

## AIRCRAFT LOG-BOOK

## 5111129 K

Book established: 9/9/05

Book inscribed and closed:

Ordinal number: .....

	Aircraft data
Registration sign	NZISKP
Aircraft type	KAPPA KP-5
Manufacturer	JIHLAVAN
Serial number	5111129K
Place and year of prod.	

Aircraft owner's (operator's) data					
Name	Since				
DAVID C. GUDSM	11/7/05				
	1. 1.5				

Airworthiness Certificate				
Number	Made out on	Issued by	Confirmation	
		9 		

912445 Engine records					
Туре	Serial number	on	Dismantled on	Run time	Signature
<u> GRULS</u>	5645-163	9.9.05	-	3	TZ
		-			
			- 1		
		· · · · · · · · ·			
					· · · · · ·
8		e La companya de la com La companya de la com		та 1 а. <sup>1</sup> л	· · · · · · · · · · · · · · · · · · ·
	i de care en c		an a sin constant and sin		
					« · · · · · · · · · · · · · · · · · · ·
jan n					· · · · · · ·
-	، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ، ،	1. M + - Y -			
с.					· · · · · · · · · · · · · · · · · · ·
					•
	1 m <sub>1</sub>	an a			

Propeller records					
Туре	Serial number	Installed on	Dismantled on	Run time	Signature
<del>WASHE</del>	528		1	-	
KLASSIC	525868	2 -10.3.05			YS
			1		
-	-				- 2 gan - 121 - 0. s
	4		a the state of the		
	1 -			gir a s	a - Caracter e e a composition de la composition
ă.				17 JF - 18	
					a. 9
	3.			и	ê çeriştere e
-		÷	n in the second		e kana sa sa sa
				· · · · · · · · · · · · · · · · · · ·	
e e e e e e e e e e e e e e e e e e e	·				, ,
L Jane			7 E		
		ж. .к			
5		· · · · ·			
					T. C.
	•	-			
					,
÷					
	9 N N 11 I		-		-
i Ali ali		-			
51.2	а. — — — — — — — — — — — — — — — — — — —	r.	an c		
					x
		- k	. X #		
			······································		

Ī		re-flight, po eplacements	st-flight, revisio s etc.)	ns,
Date	Activity	Findings - co	ndition of the plane	Signature
15.9.05	Pre-flight	see tust	posirewreld	Oh
			د روایی بید سیسیس بین در بردند کرد. افغار دو میها داده کی در به د	
	Moyer	Aviation,	Inc.	
	2800 5	ullivan Trail		
		n, PA 18040		
		258 0473		
		.moyeraviati	on.com	
10-24	-05 N215KP			
10 2 .			$\mathcal{N}$	
Reass	emble N <b>B</b> 215I	XP in accord	lance with Flight	and
	enance Manua			
	1	1 1		
Kurt I	R Singer	int .	Cert # AP 285729	90 IA
	hut	12z		
I find the	at the aircraft me	ets the requiren	nents	-
for the c	certification reque	sted and have i		-
a specia Dated:	al airworthiness c	ertificate		
The nex	t inspection is du	e10 27/05	e, S ' == 1	а Ч. те
Signed:	Janua 100	2000		
	James Willess DA	Moyer Av	iation, Inc.	
		أغديه فيتعب المربس		
		3800 Sulliv	van Trail	
<u> </u>		Easton, PA		
		(610) 258		
	htt	<u>p://www.mo</u>	yeraviation.com	
	10-28-05 N	1215KP Ta	ch/6.9 S/N 5111	129K
	Test flew a	ircraft IAW	FAR 91407 PAF	R (B)
	Operation			
	EKN			
	Edwin Mill		Cert# 208	647872
			and the second	· · · · · · · · · · · · · · · · · · ·
		× :	* 1	



Form MA 400 CRS# CDHR764C

Inspe	ctions (pre- repl	flight, p acemen	and the second	, revisio	ns,
Taken over by	and the second	Operation	and the second s		Signature
المقالد ا	see test rew	******	post-flig	ht Ok	dh
	Moyer A	viatio	<u>n, Inc.</u>	*)	
Installed G	3800 Sull Easton, I (610) 25 t <u>p://www.m</u> 1215KP Tac armin GTX g Encoder A	PA 1804 58 0473 <u>oyeravia</u> ch/6.9 S 320A S	) <u>ation.com</u> /N 51111 N 838100	29K 0. Instal	led
Gyro Horiz Icom IC-A Manufactur Service end	on GH02E- 200 Radio S es Drawings Up date Ec	00 II Sn 31 Sn 05 n 01089 s and ins quipmen	H08073. 2008. Ins 14. All w structions t list and	Installed talled ork done Return weight	
FAR 91;20' Kurt R Sing	e. Installed 7 par D insp ger	EBC 10 ection .	2A ELT ( Battery no Cert # A	ext due 1	2-07 90 IA
			mondorth	boon	
	certify that		3		
640	sted and insp				
Wit	h FAR 91-4 31-05 Sign	13 and r	AR 45 A		r
	oyer Aviatio				
	uyei Avialio	п, ше. <b>с</b>			
	<i></i>	-			

ZOART ZO.Z Dull I. Jule Son 37274   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repairs made in accordance with AC 43.13-1B, Ch 3, Section 1, Para 3.   The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.   TTAF: Tach time   Date 28 Apr. 2006 APPROVED:   MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, 0   Marcade of the following endorsement approves this aircraft part for return to service.	sions,
350 B EAST SANTA MARIA STREET, SANTA PAULA CA. A AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Fiberglas repair made on small area Le of RH wing tip, damaged area approximately 3 in Repairs made in accordance with AC43.13-1B, CA. 5, Sect. 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance wit regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 30 Nov. 2005 APPROVED: Wither T. Marple A&P 10044691A 3.20 A 9 C 7 0.7 MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 5 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength. Repairs made in accordance with AC43.13-1B, Ch. 3, Sect. 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 28 Apr. 2006 APPROVED: Walker T. Marple A&P 10044691A MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 5 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength. Repairs made in accordance with AC 43.13-1B, Ch. 3, Section 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 28 Apr. 2006 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten rith body puty and touching up paint. Repairs made in accordance with AC 43.13-1B, the he above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.	ne Signature
Date 30 Nov. 2005 APPROVED: Walter T. Marple A&P 10044691A   Walter T. Marple A&P 10044691A Walter T. Marple A&P 10044691A   3. AN 9. 4 OcuMP Lifter J. Jon 3073024   20 AN 7. 0. 7 Out I Lifter J. Jon 3274   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repairs made in accordance with AC 43.13-1B, Ch 3, Section 1, Para 3.   The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.   TIAF:   Tach time   Date 26 Apr. 2006   APPROVED:   Maller T. Marple A&P 10044691A   Maller T. Marple A&P 10044691A   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   APPROVED:   Maller T. Marple A&P 10044691A   Maller T. Marple A&P 10044691A   Maller T. Marple A&P 10044691A   Maller T.	P inches long. ith current FAA
ZOART ZO.Z Duill L.M. 3003224   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repairs made in accordance with AC 43.13-1B, Ch 3, Soction 1, Para 3.   The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.   TTAF: Tach time   Date 28 Apr. 2006   APPROVED:   Malle, T. Marple   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, the above inspections, repairs and/or modifications have been done in accordance with egulations and the following endorsement approves this aircraft part for return to service.	
ZOART ZO.Z Duill L.M. 3003224   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength.   Repairs made in accordance with AC 43.13-1B, Ch 3, Soction 1, Para 3.   The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.   TTAF: Tach time   Date 28 Apr. 2006   APPROVED:   Malle, T. Marple   MARPLE AVIATION INC.   350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9   AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP   Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, the above inspections, repairs and/or modifications have been done in accordance with egulations and the following endorsement approves this aircraft part for return to service.	· · · · · · · · · · · · · · · · · · ·
MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repairs made in accordance with AC 43.13-1B, Ch 3, Section 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 26 Apr. 2006 APPROVED: Walter T. Marple A&P 1004469IA MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, (he above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.	45 01 C14C
350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength. Repairs made in accordance with AC 43.13-1B, Ch 3, Section 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 26 Apr. 2006 APPROVED: Walter T. Marple A&P 10044691A MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, Ch above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.	
350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repair two cracks in co-pilot seat, repaired using carbon fiber for added strength. Repairs made in accordance with AC 43.13-1B, Ch 3, Section 1, Para 3. The above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service. TTAF: Tach time Date 26 Apr. 2006 APPROVED: Walter T. Marple A&P 10044691A MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, Ch above inspections, repairs and/or modifications have been done in accordance with regulations and the following endorsement approves this aircraft part for return to service.	
Walter T. Marple A&P 1004469IA MARPLE AVIATION INC. 350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, of the above inspections, repairs and/or modifications have been done in accordance with egulations and the following endorsement approves this aircraft part for return to service.	th current FAA
350 B EAST SANTA MARIA STREET, SANTA PAULA CA. 9 AIRFRAME LOG BOOK MODEL: Kappa K-5, N215KP Repaired small two inch dent in L/H wing L/E four feet outboard of butt rib by straighten with body putty and touching up paint. Repairs made in accordance with AC 43.13-1B, of the above inspections, repairs and/or modifications have been done in accordance with egulations and the following endorsement approves this aircraft part for return to service.	
TAF: Tach time	ning, filling Ch. 4, Sect. 4. th current FAA
APPROVED: Watter T. Marple	la
Walter T. Marple A&P 1004469IA	
	~ ~ }

8

ľ

Inspe	ctions (pre-flight, post-flight, revision replacements etc.)	ons,
Taken over by	Qperation failures	Signature
2050004	Dand Cifler 307 32 246 5	OILCHG
	Bg. I HR-S	
AIRFF Serviced and adjusted The above inspections regulations and the foll	s, repairs and/or modifications have been done in accordance with c lowing endorsement approves this aircraft part for return to service.	urrent FAA
	APPROVED: Walter T. Marple A&P 10044691A	<u> </u>
1. 1		
		8
		ł
		4
	· · · · · · · · · · · · · · · · · · ·	
1		
an i <sup>n</sup> i		
н. Н		
		14 A

## Aircraftsman

7000 Merrill Ave Hangar A245/Box 100 Chino, CA 91710 Chino Airport (909) 393-0884 (909) 393-0494 FAX N-Number: Model Number: Serial Number:

**Airframe** N215KP Date: 09/12/07 Kappa K-5 Tach: 99.0 5111129K

## Description of Damage:

Loss of power resulted in landing damage to this aircraft.

The engine and propeller suffered sudden stoppage, destroying the spinner and propeller and required engine disassembly for internal damage inspection. The nose cowling was destroyed including induction components and exhaust components. The landing light assembly and cowl attachment were damaged. All landing gear legs were buckled, two shock struts were damaged and the nose and right main wheel fairings were broken. Much of the hardware of the gear components were damaged.

The forward belly skin, the right hand outboard wing leading edge skin and the right hand aft lower wing skin were damaged. The right hand wing tip was crushed. The damage to the main gears transferred a load to the rear spar assemblies, damaging the rear spar lower angles of the left and right wings.

The Following Labor Items Were Conducted During Repairs:

- 1. Remove cabin interior for access to repairs.
- 2. Remove propeller and engine for inspection and repair.
- 3. Remove engine exhaust, baffling and accessories.
- 4. Shore aircraft.
- 5. Remove all damaged fairings, antennas and left hand and right hand wings.
- 6. Remove forward belly skin.
- 7. Inspect for hidden damage.

8. Fit new forward belly skin.

9. Inspect sub-assembly of forward belly skin.

10. Rivet forward belly skin.

11. Inspect installation forward belly skin.

12. Remove all landing gear from aircraft.

13. Disassemble landing gear.

14. Inspect landing gear assemblies for hidden damage.

15. Build up and install new gear assemblies with new components and hardware.

16. Install new shock assemblies.

17. Install all rebuilt gear assemblies.

18. Inspect gear installation.

b

19. Inspect wheel assemblies and brakes.

- 20. Replace right main and nose fairings and existing left fairing.
- 21. Inspect wheel fairing installation..
- 22. Disassemble damaged right hand wing outboard section.
- 23. Inspect for hidden damage.
- 24. Replace outboard leading edge on right wing.
- 25. Inspect leading edge skin installation.
- 26. Remove lower aft inboard right hand wing skin.
- 27. Remove damaged lower aft spar cap.
- 28. Inspect for hidden damage.
- 29. Replace lower spar cap.
- 30. Replace lower aft inboard wing skin.
- 31. Inspect replaced spar cap and wing skin.
- 32. Remove lower aft inboard left hand wing skin for access to spar cap replacement.
- 33. Remove damaged lower aft spar cap.
- 34. Inspect for hidden damage.
- 35. Replace lower spar cap.
- 36. Reinstall existing lower aft inboard wing skin.
- 37. Inspect replaced spar cap and wing skin.
- 38. Reinstall repaired wing assemblies.
- 39. Rig flight controls IAW KAPA Service Manual.
- 40. Repair damaged fiberglass right hand wing tip.
- 41. Inspect repairs to wing tip.
- 42. Reinstall repaired wing tip.
- 43. Inspect wing tip installation.
- 44. Re-install cabin interior and cargo door.
- 45. Inspect cabin interior and cargo door installation.
- 46. Build up prop strike inspected engine with accessories and baffling.
- 47. Reinstall inspected engine with rebuilt exhaust tailpipe.
- 48. Install Factory New propeller.
- 49. Inspect installation, all hoses and 'B' nut torques, all control terminals for large area was steel lock nuts or castle nuts with installed cotter pins, all wiring routing, appropriate sa with clamps, torque settings and application of torque stripe on all structural fasteners as secured lock tabs on engine mount bolts.
- 50. Service engine with appropriate grade of oil and new filter.
- 51. Ground run engine and set-up.
- 52. Paint all repaired areas of aircraft.
- 53. Final Inspection of completed program.
- 54. Flight test aircraft.

active and share

2 3

The F	following Parts Were Rej	placed During Repairs:	AND A
		Leg - gear main	
1	123961.1	Leg - gear main	U U
1	123961.2	Shock Absorber	
1	123964	Upper Distance Tube	<b>MILLIN</b>
1	123601	Screw - M12 X 155 (138)	
1	123602 912 018	Bearing	CAT
5	904 007	Nut M12	
1	905 007	Washer Dia 13	
1	902 042	Screw M8 X 57 (45)	
1.	123 603	Inner Distance Tube	
1	123 606	Circled Bushing	
1	912 017	Bushing 1020KU	
1	904 005	Nut M8	
1	905 004	Washer dia 8.4	
1	902 043	Screw - M8 X 59 (47)	
1	123 604	Shock Absorber Distance Tube	
1	904 005	Nut M8	
1	905 004	Washer - dia 8.4	لنسهد
. 1	123 973	Strut	
1	108 801	Fork	
1	108 806	Shock Absorber	
	108 802	Nose Leg Body	
1.	108 802	Leg - PP	
1	123-972	Fork Screw	
1		Wheel Axis	E
1	108 015	Pivot	
2	108 001	Headlight Holder	
1	00-01	Headlight	
1	979 001		
1	110 501	Lower Housing (cowling)	
2	924 401	Rudder Rim 6	
1	110 961	Suction Chamber	Contraction of the second s
1	952 102	Air filter	
1	111 402	Lower Cover	
1	111 403	Lower Cover	

days, during which time the PINK copy of this application must be carried in the aircram.

AC Form P050-1 (5/12)

1

		••
- <sup>2</sup> 1	111 942	Inlet
1	111 111.2	Lower Strap
1	111 112	Guide
1	111 113	Strap Latch
1	118 112	Spinner Pate with Spinner
1	No Part Number	Rear spar lower angle inboard right-hand
1	No Part Number	Rear spar lower angle inboard left-hand
1	No Part Number	Right-hand Main Gear Fairing
1	No Part Number	Nose Fairing
1	No Part Number	Forward Belly Skin
1	No Part Number	Right-hand outboard leading edge skin
1	No Part Number	Right-hand inboard AFT lower wing skin.

•

· ·

.

The second		the second s
		·
	A	
	need an opportunity of the second sec	
	and the second s	2 2
	and the second s	
	Lan deriver	
		1
	х.	
L		

Iı	nspections (pre-flight, post-flight, revision replacements etc.)	s,
Date	Activity Finding - condition of the plane	Signature
Tuly	1. 2011	
Tuh	130.2	· .
lach		
	· · · · · · · · · · · · · · · · · · ·	
	CAMARILLO AIRCRAFT SERVICE	14
	I certify that this Arrevert has been inspecte	d
	in accordance with a Annoal inspection	n
	and was determined to be in errorthy condition.	
	Signature 100 1 feb	-
	35215	70.70
	Luber avframe, checked to	
· · · ·	and brakes, charged man	
	battery. I certify that the	
	ELT has been tested IAW	
	FAR 91. 207D and was four	0
	to be in airworthy condition	
	Installed new ELT baffery (Sept	2013
3 y *		
July 1	2611 CAMARILLO AIRCRAFT SERVICE	-
Tach 130.	2 I certify that this Engine / Phas been inspected	
	in accordance with an Am no. inspectio	
5. 19	and was determined to be in airworthy condition.	
	Signature R. N Jel	
	2 5 2 1 5 2	TA
	Compression test: all 70/80 on better. Changed oil t filter Added 4 gts Valoline 10/30 W. and RB- C308 Filter. Repla 1/4" fuel lines with new. W engine with solvent. Added chate strips to leading pre	<u> </u>
	better. Changed ail + fill.	
	Added 4 ats Walaling 10/2000	
	and RB- (308 Filton D. 1	
	1/4" fuel lines with new 1	loch.D
	engine with solvent. A D.D.D	NEL
	chafe strips to leading pre	p bloc
	E ENDE	)

ſ

1

days, during which time the PINK copy of this application must be carried in the aircraft

Insp	ections (pre-flig replace	ht, post-fligh ments etc.)	nt, revision	ıs,
aken over by		ration failures	3	Signature
Jet 16,	2012		131.5	2.6
CAM	ARILLO AII	RCRAFT	SERV	CE
Longin	hat this Arre	The has	heen insp	ected
in accor	lance with an_	Annual	insp	ection
end was	determined to	be in airwor	thy condi	tion.
		10 10	3521	
Signa	ture / ture	1 jep	3521	
	1 1 0 0			
	Lubel airfr		entry th	- +
	and batter this FLT	1	n tested	2 IAL
	this ELT FAR 91, 207			
	to be in			Ant .
	AD's check	. then	2012-	18
rt (f	2012	Tach	131.5	
et is		1 4 6 1		
CAM	ARILLO AI	RCRAFT	SERV	ICE
		the second se		
I certify t	hat this Engine	A nas	been ins	pecied_
in accord	lance with an	My wow I	dby cone	lition
and was	determined to	De in anwo	TITY COTIC	
Ciana	ture R.P.V	teo.	352157	AI C
Signa		1 40	A11 70	(on
(	Compression or better.	Testa		
4	or better.	Cleanin	spart	510-95
	No oil cha	inge at t	his tim	د
	<b>b</b> . <b>b</b> 1	0		
	Rreplaced 1 on propella.	eading t	age le	pe

11

1

J

1------

ſ

Inspections (pre-flight, post-flight, revisions,										
replacements etc.)										
Date Activity Finding - condition of the plane Signature										
	n na star na st Na star na star n Na star na star			ter (s. 1.) Le tra						
·		ALTIMETER SCALE								
he	I CERTIFY THAT THE ALTIMETER SYSTEM AND ALTITUDE	ALTIMETER READS	PILOT		COPILOT S/N	2				
0	REPORTING EQUIPMENT HAVE BEEN TESTED AND INSPECTED AS	-1000	18	А		3				
	REQUIRED BY FAR 91.411 AND FOUND TO COMPLY WITH	0	8	D						
	APPENDIX E AND F OF PART 43	500	-2	D						
*:	NZISKP	1000	13							
	ALTIMETER TESTED TO	1500	9	Α						
		2000	16	L						
	20,000 FEET	3000	20	G						
		4000	14	E						
	DATE 05 0-1 2014	6000	21	В						
	$1 \Omega X$	8000	23	R						
	fm 1(.5 ~	10000	37	<b>A</b>						
	SIGNATURE	12000	56	L		-				
		14000	74	C						
	THE TRANSPONDER TESTS REQUIRED BY FAR 91.413 HAVE BEEN PERFORMED.	16000	42	Α		л. 				
-	TRANSPONDER(S) MEETS THE REQUIREMENTS OF FAR PART 43	18000	124	L						
	APPENDIX F.	20000	121	L						
091	DATE 05 07 2014	22000		Y						
00	DATE 0910110011	25000		941 						
<u>.</u>	/ Kall	30000								
	SIGNATURE	DATE_05	07 1	201						
	CAMARILLO AVIONICS	TESTED BY	1 6	22	h					
	RSC# 1CKR861B	INSPECTOR	An	12n						
		in an								
•										

Tach 131.5 July 10, 2014 CAMARILLO AIRCRAFT SERVICE I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Signature Renzel 3521570 IA Lubrel airframe, serviced tires & brakes installed new Werker 12V main battery I certify that this ELT has been tested IAW FAR 91.2070 and was found to be in satisfactory condition. ELT bettery due Sept 2016: Closed careframe, ran up engine, all systems check good July 10, 2014 Tach 131.5 **CAMARILLO AIRCRAFT SERVICE** I certify that this Engine / Propelles has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Signature De N flo 3521570 IA Compression test: All 70/80 or better. Inspected fuel lines, engine controls, an filter, fuel strainer, engine mounts, spinner, propeller blacks, aftaching hardware. Washed engine with solvent. Cowled. ZENDE

I

T

I

L

-----

Te

D



N215KP Rotax Model 912 ULS S/N: 5E45-163 Tach: 133.3 ETT: 133.3 Date: 15 Mar. 2018 Performed 50/100 hour/ Annual inspection IAW Rotax 912 maintenance manual Cleaned induction filter with new. Drained oil, inspected magnetic pick up. Replaced oil filter AA825706 and serviced with 3 liters of Castro GTX 10W-40 oil. Cleaned, inspected, tested and rotated spark plugs. Compressions are #1=68/80, #2=69/80, #3=70/80, #4=70/80. AD's current to revision 2018-05. Performed leak and operational checks on ground run. No defects noted at this time. I have inspected this engine IAW Rotax 912 M.M. 50/100-hour inspection and determined this engine is approved for return for service. I certify that this engine has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition ----うってちっろ Matthew Shubin A&P \$53153032 14 20 N215KP Klassic S/N: 5258683R Tach: 133.3 PTT: 133.3 Date: 15 Mar. 2018 Performed 50/150 hour/ Annual IAW Klassic propeller M.M. and FAR 43-17 appendix D checklist. Cleaned and inspected blades. Inspected prop bolts and spinner. No defects noted at this time. I have inspected this Propeller IAW a 50/150-hour inspection and determined this propeller is approved for return for service. I certify that this Propeller has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition. --normans Matthew Shubin A&P 553153032 JIHLAVAN KAPPA KP-5 N215KP S/N: 5111129K Tach: 133.3 Date: 27 April 2021 Performed a 100-hour/Annual inspection IAW FAR 43 Appendix D. Serviced and inspected brakes. Cleaned fuel screen and gasgolator. Replaced main battery with new. Lubed flight controls. Replaced ELT battery with new BP1045. Performed FAR 91.207(d) on ELT battery due 05/2023. AD's current to revision 2021-08. I have inspected this aircraft IAW a 100-hour inspection and determined this aircraft is approved for return for service. I certify that this airframe has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition. Matthew Shubin A&P 4212318 IA N215KP Rotax Model 912 ULS S/N: 5E45-163 ETT: 133.3 Date: 27 April 2021 Tach: 133.3 21 Performed 50/100 hour/ Annual inspection IAW Rotax 912 maintenance manual Cleaned induction filter with new. Drained oil, inspected magnetic pick up. Replaced oil filter AA825706 and serviced with 3 qts of AS sport plus oil. Cleaned, inspected, tested and rotated spark plugs. Compressions are #1=71/80, #2=73/80, #3=74/80, #4=72/80. AD's current to revision 2021-08. Performed leak and operational checks on ground run. No defects noted at this time. I have inspected this engine IAW Rotax 912 M.M. 50/100-hour inspection and determined this engine is approved for return for service. I certify that this engine has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition ----Matthew Shubin A&P 4212318 IA

