DATE	A. D. NUMBER	TOTAL TIME IN SERVICE		Holder Aviation, Inc. 420 Airport Road	IPLIANCE.
			Holder	Pell City, AL 35128 CRS# 9HLR596B	
			Reg. No.: N3714F Tach/Hobbs: Model: 172H Serial No.: W. O. No.: 22-0013		
			Removed defective Altimeter P/N 13-3006-1 S. Altimeter P/N 5934P-3A.83 S/N 521037. Performance system integrity check, and encoder correlation Appendix E to comply with 14CFR 91.411. Continue. Performed Transponder test I A W 14 with 14CFR 91.413. No defects noted. Altimet	ormed Altimeter check, static check I A W 14CFR43 crtified to 20,000 feet max CFR43 Appendix F to comply er P/N 5934P-3A.83 S/N	
			521037, Stratus ESG Transponder P/N 153510- The aircraft or appliance (s) identified above was in accordance with current F.A.A. Regulations an airworthy for return to service with respect to the Pertinent details of the work are on file at this age	maintained and inspected d was found to be work performed.	
			referenced work order number. Date: 1/25/2022 Signature:	and the second	

N3714F AIRFRAME VOLIL

DATE TOTAL TIME IN	as a street		INS COMPLIANCE.
Cessna 03/31/2022	172H Tach:	SER# 17255209 N3714F ⁄1	
On this date 1	nose tire was changed, Airc	raft returned to service.	
	<u>.</u>		

	LLANCE INFORMATION
N3714F TACH 1568.25 ACTT 6049.25 10/04/2022 S/N 172-55209 IAW FAR PART 43 APP D ALL AD'S COMPLIED WITH TO THIS DATE, SERVICED ALL FLUIDS. GREASED ALL POINTS. REPL AIR FILTER BA6108. ELT BATT DUE 11/2023 AND TESTED OK,C/W FAR 91-207D. REPLACED BOTH MAIN TIRES/TUBES. REPLACED R/S CALIPER O RING MS28775-224. BLEED BRAKES I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSP. IAW AN ANNUAL INSP. AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND RETURNIND TO SERVICE SCOTT A JENKINS AP 2823404 IA	REMARKS

N3714F August 27, 2023	Tach: 1610.53 Hobbs: 279.6 Aircraft TT:6091.53	
paragraph (g). Nex occurs first. 93-24-15 Panel Rheostat - Permanently complied win installation IAW SEB 92	i-33 K1 complied with by the installation of AN3-6A, I AN 380 as described in entry found bellow, per	al Equipment if Equipment d—Exchanged for Options d—Exchanged for Options al Equipment il Equipment d—Exchanged for Options id—Exchanged for Options al Equipment
paragraph A, SE77	-6 incorporated "AD 79-10-14 complied with by lent fuel filler cap prior to this entry; Cessna P/N	bl Equipment d—Exchanged for Optio d—Exchanged for Optio
72-03-03 R3 Wing Flap Actuator - Permanently comparagraph D, SE 71-22-02 Nose Fork - Permanently complied with by 71-18-01 Fuel Placard - Permanently complied with by	72-2 & SE72-2 Supplement 1 incorporated verification of nose fork P/N 0543043-498 by the verification of a "placard which shows usable	al Equipment al Equipment d—Exchanged for Optio ed—Exchanged for Optio
fuel capacity of 18 gallons le off position"	eft tank, 18 gallons right tank, 36 gallons both and an	al Equipment al Equipment
Removed and replaced right side exhaust muffler Removed and replaced pilot and co-pilot tail pipe	P/N: A0550176-59, due to a crack clamp P/N S1601-36, due to broken clamps	id—Exchanged for Option
Con	atinued	

- Removed and replaced engine throttle control attachment with a AN3-6A bolt, AN310 castellated nut, and AN380 cotter pin IAW AD86-24-07.
- 4. Repaired and stop drilled multiple cracks located on the engine baffling
- 5. Re-installed safety wire to the oil quick drain
- 6. Installed safety wire to the right main tank sump
- 7. Secured primer plunger assembly located on the pilot panel
- 8. Reattached and secured right main fuel cap chain to the airframe
- Removed and replaced "O" Rings located within the fuel valve assembly P/N: MS29513-012 (2 each), MS29513-116 (2 each), and MS29513-111 (1 each) due to a fuel leak. Reassembled with the new fuel inlet fitting P/N MC0513120-3 and no leaks were noted at this time
- 10. Removed and replaced fuel selector valve to firewall line assembly P/N 0500118-31 and left hand selector valve to union P/N 0500118-33
- 11. Removed and replaced a single upper cowling mount with Lord Cowling Mounts P/N J 7444-14
- 12. Rigged elevator trim tab IAW aircraft maintenance manual
- 13. Stop drilled multiple skin cracks on the trailing edge of the left hand flap
- 14. Replaced thirteen flap buttons P/N S1093-1
- 15. Removed and replaced left and right worn outboard flap track bolt P/N AN3-10A and nut P/N MS21044N3
- 16. Removed debris in the horizontal stabilizer, left aileron, left and right wing near the flap track assemblies
- 17. Removed and replaced two and half inch SCAT tube from distribution box to the floor outlet vents on pilot and co-pilot side.
- 18. Installed new three inch SCAT tube from forward outside air vent to the distribution box
- 19. Installed new grease felt seal P/N 154-01300 on the nose wheel assembly
- 20 Serviced main tires with 24psi and nose with 26psi
- 21. Cleaned, inspected, and packed wheel bearings
- 22. Serviced left and right hydraulic brake systems and reservoirs.
- 23. Replaced instrument air filter AAD9-14-5.

Continued

quipment quipment xchanged for Optional Exchanged for Optional

iquipment quipment ixchanged for Optional Exchanged for G

quipment quipment exchanged for Q Exchanged for Q

quipment quipment xchanged for O Exchanged for O

quipment

schanged for Of

xchanged for Op

anconameriam.		
	3. Removed and replaced engine throttle control attachment with a AN3-6A bolt, AN310 castellated nut, and AN380 cotter pin IAW AD86-24-07. 4. Repaired and stop drilled multiple cracks located on the engine baffling 5. Re-installed safety wire to the oil quick drain 6. Installed safety wire to the right main tank sump 7. Secured primer plunger assembly located on the pilot panel 8. Reattached and secured right main fuel cap chain to the airframe 9. Removed and replaced "O" Rings located within the fuel valve assembly P/N: MS29513-012 (2 each), MS29513-116 (2 each), and MS29513-111 (1 each) due to a fuel leak. Reassembled with the new fuel inlet fitting P/N MC0513120-3 and no leaks were noted at this time 10. Removed and replaced fuel selector valve to firewall line assembly P/N 0500118-31and left hand selector valve to union P/N 0500118-33 11. Removed and replaced a single unner cowling mount with 1 and Combinated Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport 13. Stop drilled multiple toracks located on the engine baffling 14. Replaced thirteen 15. Removed and replaced a single unner cowling mount with 1 and Combinated Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport Tail # N3714F Tail # N3714F Champion Flyers of Alabama—Shelby Co. Airport T	15641 flap motor assembly.
	pilot and co-pilot 18. Installed new thre 19. Installed new grea 20. Serviced main tire 21. Cleaned, inspected 22. Serviced left and r 23. Replaced instrume Continued	

- 60.2 <u>-</u> .		
nt nt sd for Optional ed for Optional	24. Lubed flight control hinge points and landing gear. 25. ELT inspected per FAR 91.207(d). Removed and replaced battery P/N BP-1045. Next main battery replacement due September 2025. I certify that this aircraft has been inspected in accordance with an Annual Inspection and found to be in an airworthy condition. Airworthiness Directives are listed in the AD Compliance Report.	
t d for Optional	Charles Mullins 3790649 A&P/IA	
	Changed oil + Silter. Installed A448108-3 filter.	
assembly.	0:1 checked normal, added Squarts 20W-50, ground run	
formation	Teak checked normal. Eac Contorno 3087400 Tech: 1682.3 61/11/2024 Front tire + tube replaced. Bearings Checked seed. 01/28/2024 Fac Contorno 3987400 700 Cm	

	and the second s
MEMORANDA	
Changed Oil + filter. Installed AA48	3108-2 filter
ground run check normal. Rachel Eth	-50
around run check normal. Rachel Eth	eredoe 413862
tach 1731.86 4/17/24	J.
100. 113.100 1111 21	
TRANSPONDER CERTIFICATION LOGBOOK ENTRY THIS TRANSPONDER WAS TESTED AS REQUIRED BY FAR PART 91.413 (a) AND	A CONTRACTOR OF THE CONTRACTOR
FOUND TO BE WITHIN THE LIMITS SPECIFIED IN FAR PART 43 APPENDIX F.	
DATE 3/13/2024 SIN 07263	
TYPE_ESGINSPECTOR Dux Fruit	
FLIGHT CONTROL SERVICES CERTIFIED REPAIR STATION #0FHR414L	
(850) 665-2130	
WO# 20775	
	. <i>'</i>



The Standard

ANTE TO CARREST TO

A5N+8A+7

	Tail # N3714F Champion Flyers of Alabama-Shelby Co. Airport (KEET) DATE: 12/20/2023 TACH: 1661.49 HOBBS: 346.5 Troubleshoot intermittent flap motor operation. Removed flap motor and jack screw. Opened gear box on jack screw and found hardened grease inside. Cleaned, lubricated, reinstalled, and tested. Ops check	Note
	good . I certify this AIRFRAME has been serviced IAW applicable FAA and/or manufacturers technical information and is airworthy at this time. Nick Owens A&P 2639932	
	No	

N3714F	-			YEA 20
1966 Cessna 172H	AFTT: 6247.66	Tach: 1766.66	SN: 172-55209	
08/30/2024	Annual Inspe	ection		
Lubricated p 2. Inspected la 3. Tested ELT 4. Replaced ig 5. Replaced a 6. Complied w	oulleys and hinges, anding gear and brake IAW FAR 91.207(D), poition switch with nevel I rudder hinge bolts with recurring ADs, see	e system components. operational test good, v 10-357200-1. PL 1 vith new AN4-11A, and e list for details.	wings. Checked cables and controls for travel battery due 09/20251.06 bushings with new MC0532104K	602 N3 ———————————————————————————————————
N3714F 1966 Cessna 172 10/22/2024 Removed Concol Operational chec Jacob Felimeth	Battery rde RG-25 battery due	Replacement e to slow cranking. Inst	SN: 172-55209 alled new Concorde RG-25 battery, s/n: 4140	08671

YEAR 20 ___ TOTAL TIME IN **Current Weight and Balance Information**

Shimkus Aviation LLC Tupelo, MS

Wayne Shimkus

6022 Westwind Dr. Tupelo, MS 38801

Date: 11/20/2024

N3714F SN:172-55209

Tach: 1779.6 TTAF:6259.6

TSMOH: 408.79

Continental: O-300-D

SN: 25243-D-8-D-R

Repaired damaged cowl, location right of propellor hub, with aluminum reinforcement plate.

Weight change negligible. Returned to service.

Wayne A. Shimkus AP3475836 IA

Description of Inspections, Tests, Repairs and Alterations TOTAL TIME IN SERVICE RECORDING Entries must be endorsed with Name, Rating and Certificate Number of Technician or TODAY'S YEAR TACH FLIGHT 20_ Shimkus Aviation LLC Tupelo, MS Wayne Shimkus Date: 02/03/2025 6022 Westwind Dr. Tupelo, MS 38801 TSMOH: 413.49 TTAF:6264.3 Tach: 1779.6 SN:172-55209 SN: 25243-D-8-D-R Continental: O-300-D On this date replaced defective landing light with Aero-Led landing light. Weight change negligible. Operational check tested okay. Returned to service.

Wayne A. Shimkus AP3475836 IA

Le Complete	Shimkus Aviation LLC Tupelo, MS	
onnician or	Wayne Shimkus 6022 Westwind Dr. Tupelo, MS 38801 N3714F SN:172-55209 Tach: 1784.3 TTAF: 6269.0 TSMOH: 428.2 Continental: O-300-D SN: 25243-D-8-D-R Installed 2 each Timken Bearings 08231-20629, 2 each Timken Bearings 08125-20629, 1 each 0742410-27 Stud, and 2 each AN310-5 Castle Nuts on landing gear, nose. Returned to service. Wayne Anthony Shimkus AP3475836 IA	