

ENGINE LOG

CONTRACTO

Engine Record General Info	rmation	
Manufacturer Lycoming	Z-⊙ZleboM	20-E1A
Borial L-5172-55 A	Type Certificat	e
This engine is currently install	ed in aircraft:	
Minimum Octane Fuel	Oil Grade Summer	Winter
Magneto Time	Point Setting	Firing Order
Spark Plug Gap		
Manufacturer's Recommended	Overhaul at hours	
	2.0	79
		4

YEAR 20 \ S Daye	RECORDING TACH TIME	TOBAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be encorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
130	トナウイン		3 HO.1	cht Or Mags our hand & Hags
				the stand. Toming the Ob. Cong cate
				Chb for trace 1 to though of unused o
				Endine word of apy for poly at
				an annual or charpetus. I FABUS 924D
1-2				

TEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterati Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entri	
		ignition sy Repaired v	stem. Chec	N: Bellanca 8KCAB S/N: 108-73 Tach Time: 1450.02 ked mag timing, tested spark plug leads, cleaned and tested all ght P-lead and positioned P-leads to correct mag position.	
	FAA regula	tions and v	with respect	cribed above were inspected in accordance with current to work performed, the aircraft and/or component was for return to service. Index work order 9625. Chad Jackowske. IMYR828C	
=		ET CENT		onsville, IN 46077 317-764-4487 CERTIFIED REPAIR STATION NO. 1MYR629C	

YEA 20 DAT

YEAR PO	MECORDING TACH TIME	TOBAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
May 28	2019 Tach	time 145	Hrs. ENG	TT: 1147 Hrs. TSMOH: 376 Hrs. Changed oil and
cleaned	il screen. C	eaned ar	d gapped sp	ark plugs. Checked compression #1 70/80, #2 78/80, #3
70/80 #	78/80. Che	cked ma	g points and	timing. Serviced engine with Aeroshell 100W Plus.
Inspecte	exhaust sy	tem. Wa	shed engine	and engine compartment, run-up and checked for oil
			his time. EN	
House, a day	norman op			Certify that this Engine
				as been inspected in accordance
				ith a 100 Hour inspection and was
				rmined to be in airworthy condition
				Robet Edwar
				A&P 2372626
Novem	ber 3, 2019	Tach tin	e 1470.1 H	rs. ENG TT: 1166.1 Hrs. TSMOH: 395.1 Hrs.
Chang	d oil and c	daned oil	screen. Ser	liced engine with Aeroshell 100W Plus, Performed run-
up and	checked fo	roil leak	OK at this	time. END Rolt Edwar A&P2372626.

rear 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
May 20,	2020 Tach	time 147	8.5 Hrs. EN	G TT: 1174.5 Hrs. TSMOH: 403.5 Hrs. Changed oil
and clea	ed oil scree	n. Clean	d and gappe	d spark plugs. Checked compression #1 78/80, #2
78/80. #	79/80, #4	8/80. CI	ecked mag	oints and timing. Serviced engine with Aeroshell
100W P	lus, Inspecte	dexhaus	system. Wa	shed engine and engine compartment, run-up and
				at this time. END.
-112-535-5				Certify that this Engine
				as been inspected in accordance
				ith a 100 Hour inspection and was
			det	rmined to be in airworthy condition
				Robet Acces
				A&P 2372626
Make: Lyco		1		Tach: 1500.2

Model: 10-320-ELA S/N: 5772-55A Real N36352

Installed Oil Filter Adapter by Casper Labs P/N CL1000 installation manual in accordance with STC SE01930NY. Installed New oil film P/N CH48108. Changed oil, added 8 qts, Aeroshell 15w-50. Ran engine and checked for leaks. Non found.

The screen, airfranc, arrestly engine, propeller or appliance identified above was repaired and inspected in accordance with current Federal Avazion Regulations and is agree for patient to service. Posttoent details of the reports) are on file at this Facility under the above referenced Work Order

Inspector: - Coo Scott Wilson 31422271A

Date: November 5, 2020

TEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alt Entries must be endorsed with Name, Rating and Certificate N Technician or Repair Facility. (See back pages for other specific	
ike Lycom odal IO-32 ii 5772-55 gil N/6352	0-E1A A	T		Tach: 1500.2 Tach: 1500.2 Tach: 1500.2 Tach: 1500.2 Tach: 1500.2	10.00
N CHARL	os. Changea ou,	anders a que c, propoliter or a la of the repair(e I coronia	ted above was repaired and inspected to acceedance with careent Federal Aviation Regulations his Pacifity under the above referenced Work Order. Inspector: Scott Wilson 3142227/A	and in opprove
Make L	ycoming Ch 320, E1 A			TTE: 1207.45	
Make 1.5 Model: B 5/H: 577 Regil N3	()-320-E1A /2-55A 16352 0 11R inspection IA			tanual & Single Engine Inspection Guide. Performed differential compression leaned and checked gap in Spark Pings. Checked and set Magneto tinting. Ind. Performed routine resintenance and servicing. Run up, ops and leak checks section IAW par. e. No leaks found. I certify that this engine has been inspected be airworthy this date.	

AR ITE	RECORDING TACH TIME	TOBAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be encorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Model: S/N: 10 Regil N	Model: Bellanca Model: 8KCAB S/N: 108-73 Reg# N36352			Trch: 1552.0 TTA: 1552.0
	A 14	Supplied motions	he or applicated	is Acroshell 15W-50. Filter P/N AA48108. identified above was repaired and respected in accordance with current Federal Assettion Regulations and is tip) are on file at this Federal worker the above reformand Work Order.
Date: 6 Tacl War cont filter Con chec	totor 24, 2031 wood on the design of the de	N363 ined oil cut Serviced w rk plugs. ck #2-70 #3-6 xchangers and. New oil	52 and inspects th 6qts Aero an gap test i9 #4-69. Ma and fuel lines	Inspector Morris Morgan (898598 3/10/22 ed filter no 100 and new torqued, ag to engine timing outed. Run-up leak s installed at this time
inst	entity this engine section and dete trong AP330155	ermined to b	e in airworth	hy condition.
-				

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	-	-		
			-	
		1		
	_			
		+-		