AlleraficLoglook

Interprite Company

Raytheon Aircraft

Beech Hawker

Model:

G36

A/C Serial Number:

E-3680

Registration Number:

N36780

EXTERIOR PAINT:

Desoto White F17865 Sherwin Williams Black Metallic R06070 Sherwin Williams Camel A07975

INTERIOR PAINT:

Wheat VO.4026

KEY NO. 2R038

STC's

This aircraft has the following STC's incorporated into the production of this unit at build:

1. SA00902WI

Replacement of original landing gear doors

2. SA00719LA

Hartzell PHC-C3YF-1R/F8468A (B, K) -6R constant speed

propeller

3. SA01033WI Replacement of original landing gear doors

AIRWORTHINESS CERTIFICATE

I have inspected this aircraft and issued a STANDARD Airworthiness Certificate Dated 02-14-2006. Time: 4.0 Landings: 7

Eugene Hainstock

For Raytheon Aircraft Company

DOA-230339-CE

01

Aircraft Model G138	Serial Number	2000	Andrew or
Reg # N367 FC	Owner's Name		
STEVENSAVIATIO	NTRIES MAY BE ON MULTIPLE		
The state of the s	LINES IF REQUIRED		
	Airframe Log Entry		
Date: June 2, 2006	Aircraft: G36	H.M./Tach:	12.4
Work Order: DAY. 26398/125	Reg. No.: N36780	Total Time:	
	Serial No.: E-3680		
1. Replaced taxi light bulb with new	v unit p/n 4596.		
This Maintenance I and I also			
Service.	Has Been Inspected In Accordance With FAA R	egulations And Is App	proved For Return
1000	0		
Signature: Danie P Can	Se		
For, Stevens Aviation, CRS VIB436	8K, Dayton Int'l Airport, Vandalia, Ohio 45377	7	10
TELENIO AL MATION			
STEVENSAVIATION	V		
STEVENSAVIATION	N		
STEVENSAVIATION			
Date: June 27, 2006	Airframe Log Entry Aircraft: Beech 36	H.M./Tach	15.9
Date: June 27, 2006	Airframe Log Entry	H.M./Tach: Total Time:	15.9
Date: June 27, 2006	Airframe Log Entry Aircraft: Beech 36		
Date: June 27, 2006 Work Order: DAY. 26442/125	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680		
Date: June 27, 2006 Work Order: DAY. 26442/125	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680		
Date: June 27, 2006 Vork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM's Adjusted all strut extensions to pro Touched up paint on nose strut as r	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH.	Total Time:	15.9
Date: June 27, 2006 Vork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH.	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH.	Total Time:	15.9
Date: June 27, 2006 Nork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice.	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. teeded. las Been Inspected In Accordance With FAA Reg	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice.	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. needed. las Been Inspected In Accordance With FAA Regular Company Compa	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice.	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. teeded. las Been Inspected In Accordance With FAA Reg	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice.	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. needed. las Been Inspected In Accordance With FAA Regular Company Compa	Total Time:	15.9
Date: June 27, 2006 Nork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice. ignature: Alegaca or, Stevens Aviation, CRS VIB4368	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. needed. las Been Inspected In Accordance With FAA Regular Company Compa	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice.	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. needed. las Been Inspected In Accordance With FAA Regular Company Compa	Total Time:	15.9
Date: June 27, 2006 Nork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice. ignature: Alegaca or, Stevens Aviation, CRS VIB4368	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. needed. las Been Inspected In Accordance With FAA Regular Company Compa	Total Time:	15.9
Date: June 27, 2006 Nork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice. ignature: Alegaca or, Stevens Aviation, CRS VIB4368	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. leeded. las Been Inspected In Accordance With FAA Reg. Douglas Duncan, Inspector K, Dayton Int'l Airport, Vandalia, Ohio 45377	Total Time:	15.9
Date: June 27, 2006 Work Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM's Adjusted all strut extensions to pro. Touched up paint on nose strut as nhis Maintenance Identified Above Hervice. Ignature: Deaglow Or, Stevens Aviation, CRS VIB4368 VENSAVIATION	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. leeded. las Been Inspected In Accordance With FAA Reg. Douglas Duncan, Inspector K, Dayton Int'l Airport, Vandalia, Ohio 45377 Airframe Log Entry	Total Time:	15.9 roved For Return 1
Date: June 27, 2006 Nork Order: DAY. 26442/125 Adjusted engine idle I/A/W TCM s Adjusted all strut extensions to pro Touched up paint on nose strut as r his Maintenance Identified Above H ervice. ignature: Alegaca or, Stevens Aviation, CRS VIB4368	Airframe Log Entry Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680 shop manual. per height I/A/W aircraft POH. leeded. las Been Inspected In Accordance With FAA Reg. Douglas Duncan, Inspector K, Dayton Int'l Airport, Vandalia, Ohio 45377	Total Time:	15.9 roved For Return 3

Removed excess sealant from around windshie
 Adjusted aft door latch strikers for better seal.

The Aircraft, Airframe, Aircraft engine, Propeller, and/or Appliance Identified Above was repaired and inspected in accordance with current Regulations of the Federal Adation Agency and is approved for return to service. Pertinent details of the repair(s) are on file at this repair station tracer work order no(s). DAY.26864/125/300

S

For, Steven Aviation, CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

1 of 1

	ES MAY BE ON MULTIPLE INES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER	- 100
STEVENSAVIATION 8/2/2006	N36780 SN E-3680	HM 33.1		
Retensioned pilot's microphone	jack's contactors. Ops checked goo	d.		
The Maintenance Identified In Approved For Return To Servic Under Work Order No. DAY.20	This Work Order Package Has Been be. Pertinent Details Of The Repair(s 6710/200.	Inspected And The Item) Are On File At This A	n(s) Are gency	티
SIGNED IN B	ATION, INC., DAYTON, OH CRS			
FOT STEVENS AVE	ATTON, INC., DAYTON, OH CRS	VIB4368K		
				_
				(=
STEVENSAVIATION				
	Airframe Log Entry			_
Date: August 8, 2006 Work Order: DAY. 26709/125	Aircraft: Beech 36 Reg. No.: N36780 Serial No.: E-3680	H.M./Tach: Total Time;	33.1 33.1	
1. Cleaned debris from right fuel quick d	rain. Leak checked satisfactory.			
2. C/W MSB 52-2693 rev 2 on cabin doc Functional checked in hangar satisfactory This Maintenance Identified Above Has I Service.	Recording to the second	Adjusted top and bottom I	atch points .	
1) 2000/11/10	(a.c.)	A Regulations And Is App	proved For Return To	
	Dayton Int'l Airport, Vandalia, Ohio 4:	5377		
or, Stevens Aviation, CRS VIB4368K, I			1 of 1	
or, Stevens Aviation, CRS VIB4368K, I				
or, Stevens Aviation, CRS VIB4368K, I				
or, Stevens Aviation, CRS VIB4368K, I				

Aircraft Model			Serial I	Number _	2		Towns of
Reg #			Owne	r's Name _			100
DATE TIME			MAY BE O	N MULTII UIRED	PLE	INSPECTOR'S SIGNATURE	LICENSE NUMBER
	P	A 980 Airpo	Ray ircraf	the t Serv	On ices	387	
	BONANZA G36 10/20/2006	S/N: FHM:	E-3680 92.6	REG. #: ACTT:	N36780 92.6	LNDGS:	
REPLACED FLAP STO CERTIFY THAT WITH RI EPAIRED AND INSPECTI ND IS APPROVED FOR R FAA CERTIFIED I UTHORIZED SIGNATURI	OP BUMPER P/N - ESPECT TO THE V ED IN ACCORDAT RETURN TO SERV REPAIR STATION E: Mark Arkins	WORK PE NCE WIT ICE. BWVR6	H NEW UNI RFORMED H CURREN 72C	T IAW BONA THIS AIRCR FFAA REGU	ANZA G36 N AFT/ENGIN LATIONS A EASA CER	ONANZA G36 M/M 33-40-4 MM 27-50-00. OPS CHECK E/PROPELLER OR APPLL ND IS IN AN AIRWORTH TIFIED REPAIR STATION	S SATISFACTORY ANCE WAS Y CONDITION
S WORK ORDER(S)	04-31342	, , ,	m · Carrey	yav_	QUALITY	ONTROL INSPECTOR	
			1				
			EXY	RyE			
				~			

DIRECTIVE LOG

STEVI	ENSAVIATION					
		AIRFRAME LO		***	a month	1000
Date:	February 12, 2007	Aircraft: (Reg. No.:			M_/Tach: tal Time:	
		Serial No.:				
This Is To	Costile An Annual (100 Hz	THE PARTY OF THE P	ab ad In Asserdance	Wish EAD 43 Anne	ndiny "D"	
1. C/W	MSB 27-3459 gust lock inspe	Inspection Has Been Accompli-	sned in Accordance	WIIII PAR 45 Appe	ildilia 15	HEER
	100 hour heater muff pressure					
	400 hour / 6 month Gill batter					
		weight check and periodic insp	ection.			
	12 month seat belt and should					
	FAR 91.207 (d) ELT inspecti	replacement p/n 35-380035-7.				
	initial wing bolt torque check					
9. Repla	ced right forward passenger s	seat shoulder harness stop p/n S	00-380050-17.			
10. Service	ced brake reservoir.					
		old pressure line and oil pressu	re dome.			
12. Repla	ced air conditioner belt p/n 6	46293-34.00.				
		and #4 cylinders p/n 35-91021	6-5.			
	ed edge sealant around prope sted rudder primary cable tens					
	sted elevator primary cable ter					
	sted elevator trim cable tensio					
	sted aileron primary cable ten					
	sted aileron trim cable tension					
Repla	ced one nose wheel bearing p	n/n 214-03300 and race p/n LN	167010.			
		r pilots seat p/n 36-555054-00	JS. Leak checked, de	ep vacuumed and so	erviced sys	stem witi
	s freon 134A. ced shimmy damper.					
This Aircra	oft Has Been Inspected In Ac	Cordance With Current FAA R	egulations Is Airwor	thy And Approved	For Return	То
Service, Pe	ertinent details are on file at t	his location under work order	no. DAY. 27596/125			
	1951					
Signature:	1 XXX					
For, Steven	ns Ayiation, CRS VIR4368K	, Dayton Int'l Airport, Vandal	ia, Ohio 45377			1 of
1						
1						
CTEV	ENSAVIATION					
SILV	LIVOAVIATION					
		Airframe Log E	ntry			
		Airrante Log E		H.M./Tach:	169.9	
Date:	March 6, 2007	Reg No.: N36	780	Total Time:		
		Serial No.: E-36	80			
Date:	March 6, 2007	Aircraft: G36 Reg. No.: N36 Serial No.: E-36	780			
		n/n C-3532-24P s/n AK-5117C	Inspected propelle	r bulkhead, no defe	cts noted.	
1. Repl	laced spinner with new unit p	III C 3332-241 SHITHE CITY				
	A Alefonna Alecraft engin	e, Propeller, and/or Appliance	Identified Above wa	as repaired and insp	ected in a	ccordan
				ervice. Pertinent det	ails of the	repair(s
	ent Regulations of the reder	work order no(s). DAY. 27738	1/125			
with curr						
are on fil	e at this repair station dides	2				
are on fil	e at this repair station under	7				

G

Ta	STEVENS
-	AVIATION

March 19, 2008

AIRFRAME LOG ENTRY

Aircraft: G36 Reg. No.: N36780 Serial No.: E-3680

H.M./Tach: 315.2 Total Time: 315.2

This Is To Certify An Annual / 100 Hr Inspection Has Been Accomplished In Accordance With FAR 43 Appendix "D". This Aircraft Has Been Inspected In Accordance With Current FAA Regulations Is Airworthy And Approved For Return To


Signature:

For, Stevens Aviation, CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

- C/W SB 27-3459 Recurring gust lock inspection. No defects noted.
- C/W Annual ELT inspection IAW FAR 91.207 (d) and remote switch function test. Operational test satisfactory,
- C/W Annual fire bottle weight/inspection.
- C/W Annual induction filter replacement P/N 35-380035-7.
- C/W Annual seat belt and shoulder harness inspection.
- C/W 100 hour heater muffler inspection.
- C/W 100 hour lubrication.
- C/W 200 hour/12 month Concorde battery load check.
- C/W 300 hour lubrication.
- 10. C/W 400 hour/6 month Gill battery load check.
- Adjusted left and right main landing gear uplock cables.
- Adjusted left and right main gear uplock roller to .010-.020 clearance.
- Installed new bushing P/N 169-420010-85 in aft cabin door stop. 13.
- Installed new seat stop pin in left hand mid passenger seat P/N BLNC3-11. 14.
- Re-connected loose BNC connector under co-pilots panel. 15.
- Removed old exterior windshield seal and applied new. 16.
- Replaced ELT battery with new P/N 452-0130. Expires July 2010.
- Replaced left hand aileron static which with new P/N 58-360032-7.
- Replaced pilot's vent window seal with new.
- Replaced passenger shoulder harness stop assembly with new on left middle passenger seat P/N 90-380050-17.
- 21. Replaced damaged nut-sert on aft baggage trim right hand outboard screw with new.
- Replaced brake reservoir clamp with new P/N 102-580011-1.
- Replaced propeller heat brush block with new P/N 3E2062-2. Operational check of propeller heat satisfactory.
- Replaced tail nav bulb with new P/N A508-28V. Operational check satisfactory.
- Replaced cabin heat duct with new P/N 35-550115-149.
- Replaced Concorde battery P/N RG-125, S/N 40101855. Installed new Concorde battery P/N RG-125, S/N 40226681.
- Replaced Gill battery P/N G-242, S/N G02223821 with new P/N G-242, S/N G02296581.
- Re-torqued jam nut on right side of throttle warning horn block.
- Serviced brake reservoir.
- 30. Serviced shimmy dampner with new o-rings as required and 5606. No leaks noted.
- 31. Recovered Freon 134a. Replaced evaporator p/n 36-380088-5 s/n 138. Serviced with 2.4 lbs freon 134a.
- Replaced air conditioner compressor drive belt p/n642759.
- 33. Inflated main struts to 3" and nose strut to 5" nitrogen.
- 34. Removed rudder inspection panels, painted and re-installed.

The Aircraft, Airframe, Aircraft engine, Propeller, and/or Appliance Identified Above was repaired and inspected in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair(s) are on file at this repair station under work order no(s). DAY, WO-7

Signature: Mart D. For, Stevens Aviation, CRS VIB430	68K, Dayton Int'l Airport, Vandalia, Ohio 45377	10
		1 10 1



Date: March 12, 2009

AIRFRAME LOG ENTRY

Aircraft: G36 Reg. No.: N36780 H.M./Tach: 451.3 Total Time: 451.3

Serial No.: E-3680

This Is To Certify An Annual / 100 Hr Inspection Has Been Accomplished In Accordance With FAR 43 Appendix "D".

This Aircraft Has Been Inspected In Accordance With Current FAA Regulations Is Airworthy And Approved For Return To

Signature: Walling to Tomber For, Stevens Aviation, CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

- C/W HBC MSB 71-3940 and Slick SB 3-08A Magneto Brush Inspection. Replaced brush ass'ys. (2) ea. p/n K3215 and distributor block ass'ys (2) ea. p/n K3823 IAW SB instructions.
- C/W SB 27-3459 Flight Control Gust Lock Inspection.
- C/W 3B 27-3459 Fight Cont.
 C/W 100 hr lubrication items.
- 4. C/W 100 hr heater muff inspection.
- 5. C/W 400 hr/6 month Gill Lead Acid Battery load check.
- C/W 500 hr heater muff inspection.
- C/W 500 hr magneto inspection.
- C/W 12 month/500 hr induction filter replacement.
- C/W 12 month seat belt shoulder harness inspection.
- 10. C/W 12 month portable fire bottle inspection.
- 11. C/W 12 month ELT inspection IAW FAR 91.207(d). Battery exp. date July 2010.
- C/W 12 month Concorde Emergency Ship's Battery Capacity Check. Battery failed and was replaced with new, (1) ea. p/n RG-125 s/n 40290405. Ops check good.
- 13. C/W 3 yr fuel cell flapper valve inspection. Leak check good.
- 14. Removed and inspected landing gear retract motor brushes. Found to be within limits. Ops check good.
- 15. Serviced brake reservoir.
- Stop drilled and patched cracked right rear engine baffle IAW King Air SRM 20-10-15.
- Removed existing sealant, cleaned and resealed windshield.
- Removed existing scarant, created and research which the second of the se
- 19. Removed and replaced tail nav light bulb (1) ea. p/n A508-28V. Ops check good.
- 20. Adjusted left nose gear door. Ops check good.
- 21. Replaced stop buttons on pilot and co-pilot's shoulder harnesses.
- 22. Replaced all cabin seats removed to facilitate inspection.

The Aircraft, Airframe, Aircraft engine, Propeller, and/or Appliance Identified Above was repaired and inspected in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair(s) are on file at this repair station under work order no(s). DAY-WO- 814.

Signature: Wolfer For Stevens Aviation CRS VIB4368K, Davion Int'l Airport, Vandalia, Ohio 45377

1 of 1



Date: July 1, 2009

Airframe Log Entry Aircraft: G36 Reg. No.: N36780

H.M./Tach: 527.6 Total Time: 527.6

Serial No.: E-3680

- Complied with SB 28-3967 by inspection of fuel line for protective insulation and clearance of electrical connectors and wiring. Found fuel line has factory covering and electrical connector has a 0.50-inch separation from fuel line and is securely fastened in place. No further action required.
- Drained oil and removed filter. Inspected oil filter, no defects noted. Installed a new CH48109-1 filter and serviced with Aeroshell 15W50.
- 3. Replaced tail and belly red beacon lights (2) ea. p/n 34-0226010-91. Ops check good.

The Aircraft, Airframe, Aircraft engine, Propeller, and/or Appliance Identified Above was repaired and inspected in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair(s) are on file at this repair station under work order no(s). DAY-WO- 1074

Signature: 2000 CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

1 of 1

Reg #	Owner's	s Name		
	ENTRIES MAY BE ON		INSPECTOR'S	LICENSE
M D HOURS	LINES IF REQU	JIRED	SIGNATURE	NOWIDER
STEVENS				
D. V. I 0.444	Airframe Lo			
Date: November 9, 2009	Aircraft: G		H.M./Tach: 527.6	
	Reg. No.: N Serial No.: E		Total Time: 527.6	
Static reported in audio system. P. Complied with engine oil change Engine ground run and leak check e Aircraft, Airframe, Aircraft engine or change with current Regulations of repair(s) are on file at this repair as	using 12 qt. of Aeroshell 1 satisfactory. , Propeller, and/or Applian the Federal Aviation Ages	5W50. Changed filter uses Identified Above wancy and is approved for	using (1) ea. p/n CH48109 as renaired and inspected	in
r, Stevens Aviation, CRS VIB4368K	, Dayton Int'l Airport, Va	andalia, Ohio 45377		1 of 1
				1
STEVENS AVIATION				
	Airframe Log E		HM (T.). (070	
te: February 2, 2010	Aircraft: G36 Reg. No.: N36 Serial No.: E-36	780	H.M./Tach: 607.9 Total Time: 607.9	
ubricated nose wheel steering linka Replaced L/H wing tip strobe flash to	ges as required. ube using (d) ea. p/n 55-02 shell 80W. Changed oil fi	lter using (1) ea. p/n C	H48109-1. Engine ground	d run and
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. lance with current Regulations of th	e Federal Aviation Agency	and is approved for re	turn to service. Pertinent	details of
eak check satisfactory.	e Federal Aviation Agency	and is approved for re	turn to service. Pertinent	details of
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. tance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	
eak check satisfactory. ircraft, Airframe, Aircraft engine, Plance with current Regulations of the pair(s) are on file at this repair station.	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	details of
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. tance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. lance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. lance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. lance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	
eak check satisfactory. ircraft, Airframe, Aircraft engine, P. lance with current Regulations of th pair(s) are on file at this repair station	e Federal Aviation Agency n under work order no(s).	and is approved for re DAY-WO- 1446.	turn to service. Pertinent	



Date: April 2, 2010

AIRFRAME LOG ENTRY

Aircraft: G36 Reg. No.: N36780 Serial No.: E-3680

H.M./Tach: 617.6 Total Time: 617.6

This Is To Certify An Annual / 100 Hr Inspection Has Been Accomplished In Accordance With FAR 43 Appendix "D".

This Aircraft Has Been Inspected In Accordance With Current FAA Regulations Is Airworthy And Approved For Return To

Signature: Willer F. Spilon

For, Stevens Aviation, CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

- C/W AD 09-15-01 (eff. 07/27/2009) Electrical Connector Wiring to Fuel Line Interference. HBC SB 28-3967 was P/C/W on 07/01/2009 at 527.6 ACTT. Verified proper tubing and standoff installation by visual inspection. No further action required.
- C/W AD 10-01-03 (eff. 01/20/2010) Contaminated Halon 1211 Gas. N/A as the portable fire extinguisher installed in this
 aircraft has not been manufactured or serviced by FFE Ltd. No further action required.
- 3. C/W SB 27-3459 Recurring Flight Control Gust Lock Inspection.
- C/W SB 32-3990 Replacement of Nose Landing Gear Retract Plunger. N/A to this aircraft by serial number and no replacement of retract plunger since aircraft manufacture. No further action required.
- 5. C/W Annual Garmin G1000 Inspection Items in accordance with HBC/Garmin MM Supplement 05-20-05.
- C/W Annual Garmin GSM-85 Clutch Torque Tests and GFC 700 Autopilot Ground Checks IAW Garmin G1000 G36 MM and HBC G36 G1000 MM Supplement.
- C/W annual Standby Attitude Indicator battery capacity check.
- C/W annual ELT functional test/inspection IAW FAR 91.207 (d). Replaced ELT battery using (1) ea. p/n 452-0130. Ops. check good, battery next due replacement August 2012.
- C/W annual Concorde RG-125 battery capacity check.
- 10. C/W annual portable fire bottle weight check/inspection.
- C/W annual induction air filter change using (1) ea. p/n 35-380035-7.
- 12. C/W 100 hr. lubrication items.
- 13. C/W 100 hr. heater muff inspection.
- 14. C/W 300 hr. lubrication items.
- 15. C/W 400 hr. /6 month Gill Lead Acid Battery inspection.
- 16. C/W 600 hr. lubrication items.
- Replaced Roll Capstan using (1) ea. p/n 011-00894-10 s/n 88005803 IAW Garmin G1000 G36 MM. Ops, checks good.
- 18. Adjusted rudder cable tension.
- 19. Replaced R/H MLG brake linings using (4) ea. p/n 066-10500.
- 20. Removed crew and cabin seats to facilitate inspection. Reinstalled crew and cabin seats.
- 21. Relamped tail beacon using (1) ea. p/n 34-0226010-91. Ops. checks good.
- 22. Replaced fuel pump cooling duct using (1) ea. p/n BE709-6-72-6.

The Aircraft, Airframe, Aircraft engine, Propeller, and/or Appliance Identified Above was repaired and inspected in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair(s) are on file at this repair station under work order no(s). DAY-WO- 1500.

Signature: William F. A. V. For, Stevens Aviation, CRS VIB4368K, Dayton Int'l Airport, Vandalia, Ohio 45377

1 of 1

ARTEX AIRCRAFT SUPPLIES, INC. 14405 Keil Rd NE Aurora, OR 97002 (503) 678-7929 800-547-8901	ARTEX ARTEX ARCANT SUPPLIES, INC. 14405 Salf Rd. NE. Auroa, OR 67002 (503) 676-7929 800-547-9935
BATTERY PACK: ELT 110-4 PART NO: 452-0130 REV: H W.0.: 0117814-11 EXP. DATE: AUG/2012 ENVCATCIADD1839000000988888 TSO C916	LOG BOOK ENTRY C4 01 200 ELT BATTERY PREPLACIMENT DATE AUGUST 2012

STEVENS			
	Airframe Log Entry		
Date: June 28, 2010	Aircraft: G36 Reg. No.: N36780		62.7 62.7
Descended windshield with v	Serial No.: E-3680		
Resealed windshield using E Replaced (1) ea. missing doo	or hinge rivet		
	ngine, Propeller, and/or Appliance Identified Al ons of the Federal Aviation Agency and is appro air station under work order no(s). DAY-WO-1		ted in tinent details of
nature: William F.X	0		
Stevens Aviation, CRS VIB4	368K, Dayton Int'l Airport, Vandalia, Ohio 45	377	1 of 1
DA	TE: 11-1-2010 Tach: 782.5 N	3678Q	
	placed nose tire with new michilen		
nev	w Goodyear 5.00x 5 tube. Jeff Leac	h AP3527139	
	AMM		
	and the same of th	-	
	Russell County A	irport	
	628 C Smith R	oad	
	Jamestown, KY Phone: 270-343-6644 Fax: 270-343-66	42629 78 Email: k24@aerotech	.net
Date: 3-7-2011	Serial # 687116	N# 36780 Eng: TSMOH NA	
Tach: 865.0	Eng. TT: 865.0 and rotated plugs. Drained oil and remove	d filter installed new AA4	8109 filter and
Serviced engine	wih A/S 100W oil. Checked all oil and fue	l screens. Removed RH e	xhaust, Welded
Lower ring and r	einstalled using all new nardware. Checke	esearched Ads through To	lata rev 2011-05 nor
apply at this time	0 #3 52/80 #4 70/80 #5 74/80 #6 73/80. A . I CERTIFY THIS ENGINE HAS BEEN ECTION AND WAS DETERMINED TO	INSPECTED IN ACCOU	RDANCE WITH AT Y CONDITION.
ANNITAL INSP	EACH AP3527139IA		
III LINDIN SLIT I	941N		
A local management of the	And the second s		the same of the same

-	-
•	•
_	_

	Date:	04/24/2012		Reg. No: N	ICE 36780 UM
	HM: TTAF:	1045.8 1045.8		Beech G36 S/N E-3680	
	2445 E.	General Aviation Dr	Horizon Avionics ive, Suite C, Alcoa, TN 37701. Te	Inc. 1: (865) 980-7858 Fax: (86	5) 980-7701
	BiWeekly	2012-06. Installed	AIRFRAME LOG ENTI espection this date IAW Hori FAR 91.207(D), batter expire I new It and rt brake disc and nd ran Acft, leak and ops ch	zon Avionics inspections AUG, 2012. Research	and ADia there
	I certify to determine Order No.	M2668.	MAINTENANCE RELEA e has been inspected IAV rworthy condition. Pertiner Cert. No: APUG For Horizon Avionics.	V an Annual Inspect t Details Are On File	Under Work
Tr			N36780 Beech	e at compressor, and	8/N E-3680 I installed &P 3030006
Sign					
Sigr	-	CF	IRISTIANSEN AVIATI 106 W PIPER DR TULSA OKLA 7413 800-331-5550		
Sign	March 1		106 W PIPER DR TULSA OKLA 7413	2	

INSTRUMENT, STATIC, AND SERVI AVIONICS CHECKS

RVICE INSTRUCTION

DIRECTIVE LOG

ATE TIME M D HOURS		/ BE ON MULTIPLE F REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER	
		Airframe Log Entry			187
06/01/13 1126.2 Tac	ch 1126.2 Aircraft	Total Time N36780	Beechcraft G36	S/N E-3680	
landing gear zirks, re battery box, cleaned new Goodyear 7.000 resealed with new o- justed nose strut cer with new P/N MS295 ery with new P/N 45	ppacked all wheel by , removed corrosion 6-6 tire & Michelin rings, and reinstall htering cam as neo 513-338. Reattache 2-0130. C/W FAR S	cleaned fuel strainer screen bearings, & serviced landing n, painted, and reinstalled. I, 7.00/8.00-6 TR20 tube. Re- ed. Bled both brakes. Servicessary and tightened nut on dd propeller control cable at 21.207 C & D on ELT, S/N 7 een inspected in accordance.	Replaced right main tire moved right master brak ced nose and main gear or od bolt. Replaced fuel forward mount. Replace 72788. Battery expiration we with an Annual Inspec	& tube with xe cylinder, r struts. Ad- cap o-rings ed ELT batt- n is 12/2015.	
I certify tha	and was dete	rmined to be in Airworthy C	ondition.		
Signature	rele (edegge	IA	# 3030006	
		//			
FOR LAUGERDAILE, FL. LOG BOOK ENTRY ELT. SATTERY REPLACEMENT DATE DEC 20	13				
	Air	frame Log Entry			
control rod ends, greased l BE709-4-23-6. Replaced le 400 respectively. Replaced on ELT, S/N 72788. Batter	ced and installed n anding gear zirks, oft main tire & tube I LH muffler with ne y expiration is 12/2	ew G-242 battery, S/N G02 as serviced brake hydraul with new Goodyear tire an ew P/N K701-04, supplied to 015.	1829303, cleaned fuel st lic fluid. Installed new bi d tube, P/N 301-063-00 by Parts Exchange. CA	attery duct, P/N 6 and P/N 302-061- N FAR 91.207 C & D	RECORD
I certify that this	aircraft has been in and was determine	nspected in accordance wit ed to be in Airworthy Condi	th an Annual Inspection tion.		
Signature / Lad	r Cha	Legge	IA# 3	3030006	

13

INSTRUMENT, STATIC, AND AVIONICS CHECKS

SERVICE BULLETIN/ SERVICE INSTRUCTION

AIRWORTHINESS DIRECTIVE LOG

DATE TIME Y M D HOURS	ENTRIES MAY BE OF LINES IF REQU		INSPECTOR'S SIGNATURE	LICEN
	Airframe Log	g Entry		
08/14/15 1213.3 Tach	1213.3 Aircraft Total Time	N36780 Beechcr	aft G36 S/N E-36	80
landing gear zirks, and se Tightened linkages on ma S/N 72788. Battery expira	riced battery, cleaned fuel stra erviced brake hydraulic fluid. I ain gear doors. Adjusted LH o ation is 12/2015. s aircraft has been inspected and was determined to be in	nstalled new inlet air duc cowl flap rod ends. C/W in accordance with an A	t, P/N 36-380098-1. FAR 91.207 C & D o	
Signature	all Ces	lyzar	IA# 30300	006
	Airframe Log Er	ntry		
Replaced air conditioner com	55.0 Aircraft Total Time I	N36780 Beechcraft (0-10067-SD6679, suppli	ied by McCain's A/C	
Replaced air conditioner com Parts. Evacuated system an ested all affected systems sa	55.0 Aircraft Total Time Inpressor with new unit, P/N 20 d serviced air conditioning with	N36780 Beechcraft (0-10067-SD6679, suppli th 2.5 lb. of Freon 134A r	ied by McCain's A/C	
Replaced air conditioner com Parts. Evacuated system an ested all affected systems sa	55.0 Aircraft Total Time Appressor with new unit, P/N 20 d serviced air conditioning with attisfactory.	N36780 Beechcraft (0-10067-SD6679, suppli th 2.5 lb. of Freon 134A r	ied by McCain's A/C refrigerant. Operation	
Replaced air conditioner com Parts. Evacuated system an tested all affected systems sa	55.0 Aircraft Total Time Inpressor with new unit, P/N 20 d serviced air conditioning will atisfactory.	N36780 Beechcraft (0-10067-SD6679, suppli th 2.5 lb. of Freon 134A r	ied by McCain's A/C refrigerant. Operation A&P 30	
Replaced air conditioner com Parts. Evacuated system an tested all affected systems so Signature Multiple 19/16/16 1259.6 Tach 1259 an electrical check, serviced by deated with zinc chromate, and (N 35-380132-101. Installed r	55.0 Aircraft Total Time spressor with new unit, P/N 20 d serviced air conditioning will atisfactory. Airframe Log Entr	N36780 Beechcraft (2) 0-10067-SD6679, suppliid the 2.5 lb. of Freon 134A in 2.5 lb. of Freon 134	A&P 30: S/N E-3680 eel bearings, greased ydraulic fluid. Cleane saker switch with new	30006
Parts. Evacuated system an tested all affected systems satisfied by the systems of the systems o	Airframe Log Entre 18.6 Aircraft Total Time No.6 Aircraft Total Time No	N36780 Beechcraft (Co. 10067-SD6679, supplied to 2.5 lb. of Freon 134A response to 2.5 lb. of Freon 134A res	A&P 30 A&P 30 S/N E-3680 eel bearings, greased ydraulic fluid. Cleane eaker switch with new ELT, S/N 72788.	30006

_	•

G

D	
Reg #	Owner's Name
The second second	
	Airframe Log Entry
03/09/17 1285.4 Tach 1285	
	en. Installed rivet in cargo door stay, as required.
Signature_ Male	Cealiza ASP 3030006
	//
	Airframe Log Entry
0/05/17 1306.0 Tach 1306.0 Air	
an electrical check, serviced batter	ry, cleaned fuel strainer screen, greased landing gear zirks, lubed control
o enos, and serviced brake hydrau 03/2019.	ulic fluid. C/W FAR 91.207 C & D on ELT, S/N 72788. Battery expiration
I certify that this aircraft ha	as been inspected in accordance with an Annual Inspection
and was	determined to be in Airworthy Condition.
	delignification of Management of the Control of the
m //.	10000000
ignature M-zll	Clilezze 1A# 3030006
m //.	10000000
m //.	10000000
m //.	Clilezze 1A# 3030006
ignature_M—ll	Airframe Log Entry
ignature_M—ll	Clilezze 1A# 3030006
ignature_M—ll	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680
ignature 128.0 Tach 1 rviced and installed new G242 pa	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378.
ignature M-ll	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378.
ignature 128.0 Tach 1 rviced and installed new G242 pa	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378.
ignature 128.0 Tach 1 rviced and installed new G242 pa	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378.
ignature M-JU /05/18 1328.0 Tach 1 rviced and installed new G242 manature M-JU gnature M-JU IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Airframe Log Entry 1328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Ludyre A&P 3030006 Airframe Log Entry
ignature	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Luly Airframe Log Entry
ignature 12-21 /05/18 1328.0 Tach 1 rviced and installed new G242 manature 12-21 11/15/18 1328.z Tach 1328 Ran electrical check, serviced b	Airframe Log Entry 1328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Lucy Airframe Log Entry
ignature 1228.0 Tach 1 //05/18 1328.0 Tach 1 rviced and installed new G242 page and	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Ludyre A&P 3030006 Airframe Log Entry Airframe Log
ignature 1228.0 Tach 1 705/18 1328.0 Tach 1 rviced and installed new G242 page of the following state of the fol	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Airframe Log Entry Airframe Log
ignature 1228.0 Tach 1 705/18 1328.0 Tach 1 rviced and installed new G242 page of the following state of the fol	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Airframe Log Entry Airframe Log
ignature 1228.0 Tach 1 705/18 1328.0 Tach 1 rviced and installed new G242 page of the following state of the fol	Airframe Log Entry 328.0 ATT N36780 Beechcraft G36 S/N E-3680 ain battery, S/N G02990378. Airframe Log Entry Airframe Log

Aircraft Model	Serial Number
Reg #	Owner's Name
	Airframe Log Entry
	1238 5 Aircraft Total Time N36780 Beechcraft G36 S/N E-3680
	ach 1338.5 Aircraft Total Time 1400700 Become and
Replaced air condition 555048. Operations	oner belt with new P/N 646293-34.00, and air conditioner belt guard with new P/N 36- ally tested affected systems satisfactorily.
	Isle Cereligge A&P 3030006
Olgridia -	
	Airframe Log Entry
2/02/20 1352 1 Tach	1352.1 Aircraft Total Time N36780 Beechcraft G36 S/N E-3680
an electrical check, ser	rviced battery, cleaned fuel strainer screen, lubed control rod ends, greased landing wheel bearings, and serviced brake hydraulic fluid. Adjusted cowl latches, as
- Ind Donlaged the	fellowing with new Reacon hulb P/N 34-0226010-91, both Wingtip liastitudes F/N
m er coost & and took	de eigenië breeker D/N 36,380132-103 Kemoved and reinstalled EL pariet, alter
enair by Air Capitol Dial	I, Inc. Replaced ELT battery with new P/N 452-0130 and C/W PAR 91.207 C & D 611
LT, S/N 72788. Battery	
I certify that th	his aircraft has been inspected in accordance with an Annual Inspection
1.	and was determined to be in Airworthy Condition.
Signature M	1A# 3030006
Signature / / DD	
	Alfano Los Feles
	Airframe Log Entry
0/09/20 1374.8 Ta	ach 1374.8 ATT N36780 Beechcraft G36 S/N E-3680
Adjusted throttle rigg	ing and gear warning horn linkage.
m_	De Ceclegral ASP 3030006
signature/_/_	ac confi
	Airframe Log Entry
10/21 1377.2 Tach 1	377.2 Aircraft Total Time N36780 Beechcraft G36 S/N E-3680 —
electrical check consid	bed and installed new G-242 battery, S/N G03111642, cleaned fuel strainer
en. lubed control rod er	nds greased landing gear zirks, and serviced brake hydraulic fluid. Serviced
G struts with Nitrogen 1	Replaced the following with new: P/N 34-0226010-91 belly strope built, P/N
1W RH wing static wick.	, P/N 653981 alternator gasket, and P/N 177 pilot's storm window seal. C/W FAR 72788. Battery expiration is 01/2022.
I certify that this	aircraft has been inspected in accordance with an Annual Inspection
. Constructions	and was determined to be in Airworthy Condition.
VVI	
ignature / / Laz	le (lieberge 1A# 3030006 -

ircraft Model	Serial Number
teg #	Owner's Name
DATE TIME M D HOURS	ENTRIES MAY BE ON MULTIPLE INSPECTOR'S LICENSE LINES IF REQUIRED SIGNATURE NUMBER
	Airframe Log Entry
	1399.5 Aircraft Total Time N36780 Beechcraft G36 S/N E-3680
Removed and reinstalled	fuel boost pump, P/N 4613-00-5, S/N 1288, after overhaul by Aeromotors, LLC., 10/27/21. Boosted fuel. Operationally tested satisfactory.
Signature_ Mad	L Circlipse A&P 3030006 _
	Airframe Log Entry
05/01/22 1414.9	Tach 1414.9 ATT N36780 Beechcraft G36 S/N E-3680
	ner belt with new P/N 646293-34.00. Operationally tested affected systems
satisfactorily.	^ ^
m	1 () - legge A&P 3030006
Signature	ell Company
	Airframe Log Entry
08/01/22 1416.8 Ta	ach 1416.8 ATT N36780 Beechcraft G36 S/N E-3680
Ran electrical check, ser	
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	cked all wheel bearings, and serviced brake hydraulic fluid. Resealed RH brake wo-rings, bled and serviced brake system with 5606. Installed new inboard snap ring otter pin at fuel selector knob, where missing. Replaced NLG tire and tube with new GL-5067B, respectively. Removed and reinstalled alternator P/N 649304, S/N ur inspection and repair by Aircraft Accessories of Oklahoma, Inc., W/O# WO51341, sed ELT battery with new P/N 452-0130 and C/W FAR 91.207 C & D on ELT, S/N in is 06/2025. This aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	cked all wheel bearings, and serviced brake hydraulic fluid. Resealed RH brake wo-rings, bled and serviced brake system with 5606. Installed new inboard snap ring otter pin at fuel selector knob, where missing. Replaced NLG tire and tube with new GL-5067B, respectively. Removed and reinstalled alternator P/N 649304, S/N ur inspection and repair by Aircraft Accessories of Oklahoma, Inc., W/O# WO51341, sed ELT battery with new P/N 452-0130 and C/W FAR 91.207 C & D on ELT, S/N in is 06/2025.
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	cked all wheel bearings, and serviced brake hydraulic fluid. Resealed RH brake wo-rings, bled and serviced brake system with 5606. Installed new inboard snap ring otter pin at fuel selector knob, where missing. Replaced NLG tire and tube with new GL-5067B, respectively. Removed and reinstalled alternator P/N 649304, S/N ur inspection and repair by Aircraft Accessories of Oklahoma, Inc., W/O# WO51341, and ELT battery with new P/N 452-0130 and C/W FAR 91.207 C & D on ELT, S/N in is 06/2025. This aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	cked all wheel bearings, and serviced brake hydraulic fluid. Resealed RH brake wo-rings, bled and serviced brake system with 5606. Installed new inboard snap ring otter pin at fuel selector knob, where missing. Replaced NLG tire and tube with new GL-5067B, respectively. Removed and reinstalled alternator P/N 649304, S/N ur inspection and repair by Aircraft Accessories of Oklahoma, Inc., W/O# WO51341, and ELT battery with new P/N 452-0130 and C/W FAR 91.207 C & D on ELT, S/N in is 06/2025. This aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.
landing gear zirks, repac master cylinder with new at LH wheel and new col P/N's 301-016-420 and 0 005JA020, after 500 hou dated 07/14/22. Replace 72788. Battery expiration	cked all wheel bearings, and serviced brake hydraulic fluid. Resealed RH brake wo-rings, bled and serviced brake system with 5606. Installed new inboard snap ring otter pin at fuel selector knob, where missing. Replaced NLG tire and tube with new GL-5067B, respectively. Removed and reinstalled alternator P/N 649304, S/N ur inspection and repair by Aircraft Accessories of Oklahoma, Inc., W/O# WO51341, and ELT battery with new P/N 452-0130 and C/W FAR 91.207 C & D on ELT, S/N in is 06/2025. This aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.

DATE TIME ENTRIES MAY BE ON MULTIPLE INSPECTOR'S SIGNATURE Page 1 3716-08-2022 (10-13-2022) MAKE Beech MAKE MAKE MAKE MAKE MAKE MAKE MAKE MAKE	Aircraft Model	Serial Number	
Note	Reg #	Owner's Name	
### PROPRIES SIGNATURE NUMBER ST16-08-2022 (10-13-2022) MAKE: Beech			
MAKE: Beech MODEL: G38 SN: E-3680 REG. NO: N36780 Airframe Install G1000 NXI Retrofit STC SA0194SWI Removed Garmin G1000 Parts: GDU1043 PN: 011-01079-00 SN: 86900372 GDU1040 PN: 011-01079-00 SN: 86900372 GDU1059 PN: 010-01308-00 SN: 494005733 GDU1055 PN: 010-01308-00 SN: 494005733 GDU1055 PN: 010-01308-00 SN: 494005735 Software Loader Card PN: 010-02699-01 Installed IAW STC SA0194SWI & Garmin Master Drawing List, P/N: 005-01474-00, Rev 2. Updated Equipment List As Required Updated Weight and Balance Replace non WAAS GPS antenna to GA35 WAAS GPS antenna Removed existing non WAAS GPS antenna No PN or SN on unit. Installed a new antenna P/N: 013-00235-00 S/N: 218872 IAW G36 SB, P/N: 34-392 Rev 1. Replace non WAAS GR5 antenna to GA35 WAAS GPS antenna Removed dexisting non WAAS GPS antenna No PN or SN on unit. Installed a new antenna P/N: 013-00235-00 S/N: 218872 IAW G36 SB, P/N: 34-392 Rev 1. Replace non WAAS GR5 antenna to GA35 WAAS GPS antenna Removed GIA63 units. PN: 011-00781-01 SN: 48101872 PN: 011-00781-01 SN: 48101849 Installed Repaired GIA63W units. PN: 011-00781-01 SN: 48101849 Installed Repaired GIA63W units. PN: 011-10105-00 SN: 685000929 PN: 011-01105-00 SN: 685000929 PN: 011-01078-01 SN: 48101849 Installed Repaired Replacement due to 'GMA1 needs service. Return unit for repair* message on G1000 display Removed GMA1347 audio panel PN: 011-00809-00 S/N: 47110648, Installed an overhauled panel P/N: 011-00809-00 S/N: 47118971 IAW G1000 NCA, PN: 190-02765-05, Rev 02. Parking Brake Cable Broken Replaced parking brake cable IAW Bonanza MM, Rev C11, Ch. 30-60.	Y M D HOURS		SIGNATURE NUMBER
Install G1000 NXI Retrofit STC SA01945WI Removed Garmin G1000 Parts: GDU1043 PIN: 011-010972-30 SIN: 88900208 Installed new Garmin G1000 NXI parts: GDU1050 PIN: 010-01308-80 SIN: 494008733 GDU1055 PIN: 010-01308-80 SIN: 494008733 Software Loader Card PIN: 010-02699-01 Installed IAW STC SA01945WI & Garmin Master Drawing List, PIN: 005-01474-00, Rev 2. Updated Equipment List As Required Updated Weight and Balance Replace non WAAS GPS antenna to GA35 WAAS GPS antenna Removed existing non WAAS GPS antenna. No PN or SN on unit. Installed a new antenna PIN: 013-00235-00 SIN: 218872 IAW G36 SB, PIN: 34-390 Rev 1. Replace non WAAS GIA63 units for WAAS GIA63W units Removed GIA63 units. PIN: 011-00781-01 SIN: 48101872 PIN: 011-00781-01 SIN: 48101849 Installed Repaired GIA63W units. PIN: 011-01105-00 SIN: 68500629 PIN: 011-01105-00 SIN: 68500629 PIN: 011-01105-00 SIN: 68500609 Work performed IAW G36 SB, PIN: 34-3926, Rev 1. Audio panel replacement due to "GIAA1 needs service. Return unit for repair" message on G1000 display Removed GMA1347 audio panel PIN: 011-00809-00 SIN: 47100648, Installed an overhauled panel PIN: 011-00809-00 SIN: 47118971 IAW G1000 IICA, PIN: 190-02765-05, Rev 02. Parking Brake Cable Broken Replaced parking brake cable IAW Bonanza MM, Rev C11, Ch. 32-40 and 20-01. Low Amp Draw on Propeller Heaf. Pantaged Punish block assessmbly PIN: 3E2062-2 Lot # N3000041 IAW Bonanza MM, Rev C11, Ch. 30-60.	MAKE: Beech MODEL: G36 S/N: E-3680	CRS#: 7OKR809N 3751 N Jabara Rd.	DATE: 10-13-2
	Install G1000 NXI Retrofit STC SA019 Removed Garmin G1000 Parts: GDU1043 PN: 011-01079-00 SN: 86: GDU1040 PN: 011-01079-00 SN: 86: Installed new Garmin G1000 NXI parts GDU1050 PN: 010-01308-00 SN: 49 GDU1055 PN: 010-01308-00 SN: 49 FS510 PN: 010-01322-00 SN: 40201 Software Loader Card PN: 010-0269 Installed IAW STC SA01945WI & Gan Updated Equipment List As Required Updated Weight and Balance Replace non WAAS GPS antenna to 0 Removed existing non WAAS GPS an Rev 1. Replace non WAAS GIA63 units for W Removed GIA63 units. PN: 011-00781-01 SN: 48101872 PN: 011-00781-01 SN: 485080929 PN: 011-01105-00 SN: 6850609 Work performed IAW G36 SB, PN: 34 Audio panel replacement due to "GM/ Removed GIA61347 audio panel PN: ICA, PN: 190-02765-05, Rev 02. Parking Brake Cable Broken Replaced parking brake cable IAW B0 Low Amp Draw on Propeller Heat Replaced Push broke assembly PN:	900372 900208 900208 900208 9135 90135 901 901 901 902 9035 9035 9035 9035 9035 9035 9035 9035	display nel P/N: 011-00809-00 S/N: 47118971 IAW G1000
WORK ORDER: 3716-08	Daric Dunn		
DATE: 10-13-2022 SIGNED: Daric Dunn Printed by EBIS (EBISClou	4037-12-2022 (01-09-2023)		Page 1/1
Daric Dunn CRS#: 70KR809N	MAKE: Beechcraft MODEL: G38 S/N: E-3680 REG. NO:: N36780 Entries - Alternator Dropping Offline Removed voltage regulator P/N: 3 battery number 2 P/N: RG-125 S/n alternator 1. All work accomplishe	CRS#: 70KR809N 3751 N Jabara Rd. Wichita, KS 67226 AVIATION Wichita, KS 67226 6-380096-1 S/N: 80755714. Installed a new regulator P/N: 40290405. Installed a new battery P/N: RG-125 S/N: 7d IAW Beechcraft G36 MM Rev C11	W/O #: 4037-12-2022 DATE: 01-09-2023 N: 36-380096-1 S/N: 80X29605. Removed 70017502. Tightened terminals on
Daric Dunn CRS#: 70KR809N 4037-12-2022 (01-09-2023) MAKE: Beechcraft MODEL: G36 SiN: E-3680 REG. NO:: N36780 Entries Alternator Dropping Offline Removed voltage regulator P/N: 36-380096-1 S/N: 80755714. Installed a new regulator P/N: 36-380096-1 S/N: 80X29605. Removed battery number 2 P.N: RG-125 SiN: 40200465.	repair station under work order numb		formationly. Pertinent details on file at the
Daric Dunn CRS#: 70KR809N 4037-12-2022 (01-09-2023) MAKE: Beechcraft MODEL: G36 SiN: E-3680 REG. NO:: N36780 Entries Alternator Dropping Offline Removed voltage regulator P/N: 36-380096-1 S/N: 80755714. Installed a new regulator P/N: 36-380096-1 S/N: 80X29605. Removed battery number 2 P/N: RG-125 S/N: 40290405. Installed a new battery P/N: RG-125 S/N: 70017502. Tightened terminals on alternator 1. All work accomplished IAW Beechcraft G36 MM, Rev C11, Ch. 24-30. I certify this aircraft has been inspected and is approved for return to service for the work performs only. Pertinent details on file at the repair station under work order number 4037-12-2022.	DATE: 01-09-2023 SIGN	11 11 /	/

INSTRUMENT, STATIC, AND AVIONICS CHECKS SERVICE INSTRUCTION

AIRWORTHINESS DIRECTIVE LOG

G

- 44		
eg #	Owner's Name	
	Airframe Log Entry	
10/05/23 1450.8 Tach	1450.8 ATT N36780 Beec	hcraft G36 S/N E-3680
landing gear zirks, repacked a RH exhaust stack P/N 35-900 by fabricating and installing a	main battery, cleaned fuel strainer screen, li Il wheel bearings, and serviced brake hydra 05-95 after repair by AWI. Repaired hole in doubler. Repaired RH engine lower bulkhea 07 C & D on ELT, S/N 395932-025. Battery o	firewall lower RH at exhaust outlet d by fabricating and installing
I certify that this airc	craft has been inspected in accordance with d was determined to be in Airworthy Condition	an Annual Inspection on.
Signature Male	Chelipa	IA# 3030006
	Airframe Log Entry	
12/01/23 1451.7 Tac	th 1451.7 ATT N36780 E	Beechcraft G36 S/N E-3680
Replaced cylinder #3 EG1	probe with new P/N 86245. Operationally	tested affected sustame satisfactorily
- m 0	. 0	tosted affected systems satisfactomy.
Signature / / Level	1 Cerdifful	A&P 303000
16Thurs 69-14-2	0024 1/08× 1468.5	G36 S/N E-3680
15TAUET) 69-14-2	2024 HOBBS 1468.5	388, cleaned fuel strainer
- n	2024 HOBBS 1468.5 MICHELIN gar Tyros / TRB	388, cleaned fuel strainer hydraulic fluid Seprend II
The state of the s	MICHELIN	388, cleaned fuel strainer
The state of the s	MICHELIN gar Tyres / TRB la 213, 18300 Pirot Serbia	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery
TI Nikole Pasid	MICHELIN gar Tyres / TRB la 213, 18300 Pirot Serbia	388, cleaned fuel strainer hydraulic fluid Seprend II
Nikole Pasit CERTIFICATE OF	MICHELIN gar Tyres / TRB la 213, 18300 Pirot Serbia	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery
Nikole Pasid CERTIFICATE OF	MICHELIN gar Tyres / TRB is 213, 18300 Pirot Serbis CONFORMANCE	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery
Nikole Pasid CERTIFICATE OF ION: SCB67-A IN 097-908-0 Tube size	MCHELIN gar Tyres / TRB a 213, 18300 Pirot Serbia CONFORMANCE 5.00-5 Production lot 51/2023	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery nnual Inspection IA# 3030006
Nkole Pasid CERTIFICATE OF ION: 5CB67-A IN 097-908-0 Tube size Iman, we hereby certify that the parts supplications according to applicable specificat	MCHELIN gar Tyres / TRB a 213, 18300 Pirot Serbia CONFORMANCE 5.00-6 Production lot 51/2023 Illed and referenced by the production lot, are ions. Substantiating documents regarding the	388, cleaned fuel strainer hydraulic fluid. Serviced List. S/N 395932-025. Battery nnual Inspection IA# 3030006 Douglas St. mit, MO. 64664 25/3996 Cell 816/588/2897
Nikole Pasid CERTIFICATE OF ION : SCB67-A IN 097 - 908 - 0 Tube size	MCHELIN gar Tyres / TRB a 213, 18300 Pirot Serbia CONFORMANCE 5.00-6 Production lot 51/2023 Illed and referenced by the production lot, are ions. Substantiating documents regarding the	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery nnual Inspection IA# 3030006
Nikele Pasks CERTIFICATE OF ION: 5CB67-A IN 097-908-0 Tube size tman, we hereby certify that the parts supparactured according to applicable specificat subject parts are on file available.	MCHELN par Tyres / TRB a 213, 18300 Pirot Serbia CONFORMANCE 5.00-5 Production lot 51/2023 Blied and referenced by the production lot, are ions. Substantiating documents regarding the e for inspection upon request.	388, cleaned fuel strainer hydraulic fluid. Serviced List. S/N 395932-025. Battery nnual Inspection IA# 3030006 Douglas St. mit, MO. 64664 25/3996 Cell 816/588/2897
Nkole Pasid CERTIFICATE OF ION: 5CB67-A IN 097-908-0 Tube size Iman, we hereby certify that the parts supplications according to applicable specificat	MCHELIN gar Tyres / TRB a 213, 18300 Pirot Serbia CONFORMANCE 5.00-6 Production lot 51/2023 Illed and referenced by the production lot, are ions. Substantiating documents regarding the	388, cleaned fuel strainer hydraulic fluid. Serviced LF S/N 395932-025. Battery nnual Inspection IA# 3030006 Douglas St. mit, MO. 64964 25/3996 Cell 816/388/2897 Airframe Total Time

