



Status Report

HAWKER 800XP

S/N 258293 N432SM

OWNER: THE MEYERS GROUP

ADDRESS: 2999 NE 191ST STREET
AVENTURA FL 33180

OFFICE:
FAX:

OPERATOR: THE MEYERS GROUP

ADDRESS: 2999 NE 191ST STREET
AVENTURA FL 33180

OFFICE:
FAX:

ANALYST: CHRISTOPHER CUTLER
EMAIL: CCUTLER@CAMPSYSTEMS.COM

+1-316-462-2451 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 258293/N432SM	MODEL: HAWKER 800XP	MANUFACTURER: TEXTRON AVIATION INC.
CERTIFICATION DATE: 06-MAR-1996		LAST ACTUALS: 8440.9 A/C HRS as of 31-MAR-2024 6827 AFL as of 31-MAR-2024 5355 APH as of 31-MAR-2024 9124 APS as of 31-MAR-2024	
APU	SERIAL/PART: P-284/3800304-1	MODEL: GTCP36-150(W)	MANUFACTURER: HONEYWELL
INSTALLED ON: 12-SEP-1999 1060 APU HRS 0 A/C HRS 1919 APUS		LAST ACTUALS: 5355 APU HRS as of 31-MAR-2024 9124 APUS as of 31-MAR-2024	
ENGINE NO. 1	SERIAL/PART: P-107136/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
INSTALLED ON: 02-FEB-2019 7401.1 ENG. HRS 0 A/C HRS 6251 ENC		LAST ACTUALS: 8128.9 ENG. HRS as of 31-MAR-2024 7107 ENC as of 31-MAR-2024	
ENGINE NO. 2	SERIAL/PART: P-107238/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
INSTALLED ON: 08-AUG-2007 3575.6 ENG. HRS 4384.4 A/C HRS 3510 ENC		LAST ACTUALS: 7631.9 ENG. HRS as of 31-MAR-2024 6063 ENC as of 31-MAR-2024	



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
000003 ^U	FCC RADIO STATION AUTHORIZATION							Service ATA:00
	MOS/MSC	06-Mar-15	DUE		06-Mar-25 (M)		276 d	
	HRS							
	AFL							
000004 ^U	AIRCRAFT REGISTRATION							Service ATA:00
	MOS/MSC	24-Nov-21	DUE		01-Sep-24 (M)		90 d	
	HRS							
	AFL							
BCXP-160901	REVIEW HAWKER 750/800XP/850XP/900XP AFMS REVISION 32 DATED SEP.16 REVISION SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF BCXP								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050001	INSPECTION PRE-FLIGHT							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 05.T01	AFL							
PROC. REF: AMS 5-20-01, AFMS 05-00-00								
050005	INSPECTION POST FLIGHT							Service ATA:05
	MOS/MSC		A/R					
	HRS							
WC#: 05.T02	AFL							
PROC. REF: AFMS 05-00-00, AMS 5-20-02								
050110	INSPECTION B1-B12 COMPLETE							Package ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)		8696.7	8736.7	255.8 (+40)	
	AFL	6498						
PROC. REF: AMS 5-21-00								
PKG:2								
050141 ^S	INSPECT AREA F1-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.203	AFL	6498						
PROC. REF: AMS 5-00-00								
PKG:2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050171 ^S	INSPECT AREA F3 ABOVE FLOOR-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.206	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050181 ^S	INSPECT AREA F4-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.207	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050191 ^S	INSPECT AREA T1-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.208	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050201 ^S	INSPECT AREA W1-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.209	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050211 ^S	INSPECT AREA W2-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.210	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050221 ^S	INSPECT AREA M1/M2-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.211	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2
050231 ^S	INSPECT AREA G-800 HOURS							Service ATA:05
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 05.212	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:2,18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050240	INSPECTION C1-C12 COMPLETE							Package ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)		9899.1	9949.1	1458.2 (+50)	
	AFL	6753						
			PROC. REF: AMS 5-22-00					PKG:3
050271 ^S	INSPECT AREA F1-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.303	AFL	6753						
			PROC. REF: AMS 5-00-00					PKG:3
050281 ^S	INSPECT AREA F2-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.304	AFL	6753						
			PROC. REF: AMS 5-00-00					PKG:3
050291 ^S	INSPECT AREA F3 UNDERFLOOR-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.305	AFL	6753						
			PROC. REF: AMS 5-00-00					PKG:3
050301 ^S	INSPECT AREA F3- ABOVE FLOOR-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.306	AFL	6753						
			PROC. REF: AMS 5-00-00					PKG:3
050311 ^S	INSPECT AREA F4-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.307	AFL	6753						
			PROC. REF: AMS 5-00-00					PKG:3
050321 ^S	INSPECT AREA T1-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.308	AFL	6753						
								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050331 ^S	INSPECT AREA W1-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.309	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:3
050341 ^S	INSPECT AREA W2-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.310	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:3
050351 ^S	INSPECT AREA M1/M2-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.311	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:3
050361 ^S	INSPECT AREA G-1600 HOURS							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 05.312	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:3
050370	INSPECTION D1-D12 COMPLETE							Package ATA:05
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)		9867.8	10017.8	1426.9 (+150)	
	AFL	5769						
				PROC. REF: AMS 5-23-00				PKG:4
050411 ^S	INSPECT AREA F2-3200 HOURS							Service ATA:05
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 05.404	AFL	5769						
				PROC. REF: AMS 5-00-00				PKG:4
050431 ^S	INSPECT AREA F3 ABOVE FLOOR-3200 HOURS							Service ATA:05
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 05.406	AFL	5769						
				PROC. REF: AMS 5-00-00				PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050441 ^S	INSPECT AREA F4-3200 HOURS							Service ATA:05
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 05.407	AFL	5769						
				PROC. REF: AMS 5-00-00				PKG:4
050491 ^S	INSPECT AREA G-3200 HOURS							Service ATA:05
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 05.412	AFL	5769						
				PROC. REF: AMS 5-00-00				PKG:4
050500	INSPECTION E1-E12 COMPLETE							Package ATA:05
	MOS	17-Nov-23	12 (+1m/-1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1						
	AFL	6799						
				PROC. REF: AMS 5-24-00				PKG:5
050571 ^S	INSPECT AREA F4-12 MONTHS							Service ATA:05
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 05.506	AFL	6799						
				PROC. REF: AMS 5-00-00				PKG:5
050630	INSPECTION F1-F12 COMPLETE							Package ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)		11-Jan-25	11-Mar-25	222 d (+59)	
	HRS	8299.1						
	AFL	6753						
				PROC. REF: AMS 5-25-00				PKG:6
050661 ^S	INSPECT AREA F1-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.603	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050671 ^S	INSPECT AREA F2-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.604	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050691 ^S	INSPECT AREA F3-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.606	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050701 ^S	INSPECT AREA F4-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.607	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050721 ^S	INSPECT AREA W1-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.609	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050731 ^S	INSPECT AREA W2-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.610	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050751 ^S	INSPECT AREA G-24 MONTHS							Service ATA:05
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 05.612	AFL	6753						
				PROC. REF: AMS 5-00-00				PKG:6
050760	INSPECTION G COMPLETE							Package ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)		04-Sep-24	04-Nov-24	93 d (+61)	
	HRS	7896.7						
	AFL	6498						
				PROC. REF: AMS 5-26-00				PKG:7
050761 ^S	INSPECT AREA F1-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.703	AFL	6498						
				PROC. REF: AMS 5-00-00				PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050762 ^S	INSPECT AREA F2-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.704	AFL	6498						
	PROC. REF: AMS 5-00-00							PKG:7
050763 ^S	INSPECT AREA F3-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.705	AFL	6498						
	PROC. REF: AMS 5-00-00							PKG:7
050764 ^S	INSPECT AREA F4-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.707	AFL	6498						
	PROC. REF: AMS 5-00-00							PKG:7
050765 ^S	INSPECT AREA T1-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.708	AFL	6498						
	PROC. REF: AMS 5-00-00							PKG:7
050766 ^S	INSPECT AREA W1/W2-48 MONTHS							Service ATA:05
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 05.709	AFL	6498						
	PROC. REF: AMS 5-00-00							PKG:7
050771	INSPECTION 400 HOUR DETAILED WALK-AROUND							Service ATA:05
	MOS	11-Jan-23						
	HRS	8299.1	400 (+40/-10)		8699.1	8739.1	258.2 (+40)	
WC#: 05.100	AFL	6753						
	PROC. REF: AMS 5-20-07							
055005	ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.710	AFL	0						
	PROC. REF: AMS 5-50-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055010	ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.711	AFL	0						
PROC. REF: AMS 5-50-02								
055015	ACCOMPLISH INSPECTIONS AFTER A LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.712	AFL	0						
PROC. REF: AMS 5-50-03								
055035	ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.713	AFL	0						
PROC. REF: AMS 5-50-06								
055040	ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.714	AFL	0						
PROC. REF: AMS 5-50-04								
055045	ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.715	AFL	0						
PROC. REF: AMS 5-50-05								
055050	ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.716	AFL	0						
PROC. REF: AMS 5-50-07								
055060	ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.717	AFL	0						
PROC. REF: AMS 5-50-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055065	ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.718	AFL	0						
PROC. REF: AMS 5-50-09								
055070	ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.719	AFL	0						
PROC. REF: AMS 5-50-10								
055075	ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
WC#: 05.720	AFL	0						
PROC. REF: AMS 5-50-11								
055080	ACCOMPLISH INSPECTIONS FOR HYDRAULIC CONTAMINATION OF THE CABIN VENTILATION SYSTEM							Service ATA:05
	MOS/MSC	06-Mar-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMS 5-50-12								
057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION							Package ATA:05
	MOS	20-Dec-22						
	HRS	7987.1	200 (+50)		(8187.1) 8499.1	8237.1	58.2 (+50)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION							Package ATA:05
	MOS	20-Dec-22						
	HRS	7490.1	200 (+50)		(7690.1) 8499.1	7740.1	58.2 (+50)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057120	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	11-Jun-21						
	HRS	7772.8	400		(8172.8) 8484.8		43.9	
	ENC	6914						
	PROC. REF: LMM 72-00-00							PKG:2
057120	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	21-Mar-23						
	HRS	7516.9	400		(7916.9) 8725.9		285	
	ENC	6001						
	PROC. REF: LMM 72-00-00							PKG:2
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	16-Jan-19						
	HRS	7401.1	800 (+50)		(8251.1) 8563.1 (M)	8301.1	122.2 (+50)	
	ENC							
	PROC. REF: LMM 72-00-00, LMM 72-00-00							PKG:4
057140	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	04-Sep-20						
	HRS	7087.8	800 (+50)		(7887.8) 8696.8	7937.8	255.9 (+50)	
	ENC	5734						
	PROC. REF: LMM 72-00-00, LMM 72-00-00							PKG:4
057160	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	16-Jan-19						
	HRS	7401.1	1200 (+200)		(8801.1) 9113.1 (M)	9001.1	672.2 (+200)	
	ENC	6651						
	PROC. REF: LMM 72-00-00, LMM 72-00-00							
057160	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	02-Mar-18						
	HRS	6635.4	1200 (+200)		(7835.4) 8644.4	8035.4	203.5 (+200)	
	ENC	5441						
	PROC. REF: LMM 72-00-00, LMM 72-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS	16-Jan-19						
	HRS	7401.1	1600 (+50)		(9051.1) 9363.1 (M)	9101.1	922.2 (+50)	
	ENC							
			PROC. REF: LMM 72-00-00, LMM 72-00-00					PKG:5
057170	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS	16-Feb-18						
	HRS	6867	1600 (+50)		(8467) 9276	8517	835.1 (+50)	
	ENC	5585						
			PROC. REF: LMM 72-00-00, LMM 72-00-00					PKG:5
T05T03 ^U	INSPECTION CRITERIA/STRUCTURAL INSPECTIONS							Service ATA:05
	MOS/MSC		O/C					
	HRS							
WC#: 05.T03	AFL							
ATA 06 - DIMENSIONS AND AREAS								
T06T01 ^U	GENERAL INSPECTION PANEL LOCATION CHARTS							Service ATA:06
	MOS/MSC		O/C					
	HRS							
WC#: 06.T01	AFL							
ATA 12 - SERVICING								
120001	LUBRICATE AREA G-200 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	200 (+40/-10)		8499.1	8539.1	58.2 (+40)	
WC#: 12.001	AFL	6753						
			PROC. REF: AMS 5-20-11					
120003	LUBRICATE AREA F1-400 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	400 (+40/-10)		8699.1	8739.1	258.2 (+40)	
WC#: 12.003	AFL	6753						
			PROC. REF: AMS 5-20-11					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
120004	LUBRICATE AREA T1-400 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	400 (+40/-10)		8699.1	8739.1	258.2 (+40)	
WC#: 12.004	AFL	6753						
PROC. REF: AMS 5-20-11								
120007	LUBRICATE AREA W1/W2-400 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	400 (+40/-10)		8699.1	8739.1	258.2 (+40)	
WC#: 12.007	AFL	6753						
PROC. REF: AMS 5-20-11								
120012 ^S	LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS							Service ATA:12
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 12.012	AFL	6498						
PROC. REF: AMS 5-20-11								PKG:2
120013 ^S	LUBRICATE AREA F4-800 HOURS							Service ATA:12
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 12.009	AFL	6498						
PROC. REF: AMS 5-20-11								PKG:2
120015 ^S	LUBRICATE AREA W1-800 HOURS							Service ATA:12
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 12.015	AFL	6498						
PROC. REF: AMS 5-20-11								PKG:2
120016 ^S	LUBRICATE AREA W2-800 HOURS							Service ATA:12
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 12.016	AFL	6498						
PROC. REF: AMS 5-20-11								PKG:2
120018 ^S	LUBRICATE AREA G-800 HOURS							Service ATA:12
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 12.018	AFL	6498						
PROC. REF: AMS 5-20-11								PKG:2,18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
120019 ^S	LUBRICATE AREA F1-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.013	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120020 ^S	LUBRICATE AREA F2-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.020	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120021 ^S	LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.021	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120022 ^S	LUBRICATE AREA F3-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.022	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120023 ^S	LUBRICATE AREA F4-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.023	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120024 ^S	LUBRICATE AREA T1-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.024	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120025 ^S	LUBRICATE AREA W1-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.025	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
120026 ^S	LUBRICATE AREA W2-1600 HOURS							Service ATA:12
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 12.026	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:3
120030 ^S	LUBRICATE AREA F2-3200 HOURS							Service ATA:12
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 12.030	AFL	5769						
PROC. REF: AMS 5-20-11								PKG:4
120049 ^S	LUBRICATE AREA F1-24 MONTHS							Service ATA:12
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 12.049	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:6
120050 ^S	LUBRICATE AREA F2-24 MONTHS							Service ATA:12
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 12.050	AFL	6753						
PROC. REF: AMS 5-20-11								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
200001 ^S	BONDING CHECK CONTROL SURFACES							Service ATA:20
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 20.010	AFL	6498						
								PKG:2
200002 ^S	FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF)							Service ATA:20
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 20.020	AFL	6498						
								PKG:2
200003 ^S	CHECK RADIO RACKING, ELECTRICAL-BONDING							Service ATA:20
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 20.030	AFL	6498						
PROC. REF: AMM NO REF-1								PKG:7
ATA 21 - AIR CONDITIONING								
210002 ^S	CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE							Service ATA:21
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 21.075	AFL	6498						
								PKG:2
210003 ^S	BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM							Service ATA:21
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 21.110	AFL	6498						
								PKG:2
210004 ^S	CHECK MANUAL CABIN ALTITUDE CONTROL VALVE							Service ATA:21
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 21.270	AFL	6498						
								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210005 ^S	CHECK COOLING TURBINE EXHAUST DUCT DRAIN							Service ATA:21
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 21.260	AFL	6498						
								PKG:2
210006	INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION							Service ATA:21
	MOS	17-Nov-23						
	HRS	8393.1	400 (+10%)		8793.1	8833.1	352.2 (+40)	
WC#: 21.221	AFL	6799						
PROC. REF: AMM 21-10-95								
210007	INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS							Service ATA:21
	MOS	17-Nov-23						
	HRS	8393.1	400 (+10%)		8793.1	8833.1	352.2 (+40)	
WC#: 21.280	AFL	6799						
PROC. REF: AMM 21-10-95								
210008 ^S	VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.118	AFL	6753						
								PKG:3
210009 ^S	CHECK PRESSURIZATION CONTROL VENTURI SCREEN							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.275	AFL	6753						
								PKG:3
210010 ^S	CLEAN PRESSURE REGULATOR FILTER SCREENS							Service ATA:21
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 21.155	AFL	6498						
PROC. REF: AMM 21-30-55								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210011 ^S	CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES							Service ATA:21
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 21.120	AFL	6498						
PROC. REF: AMM NO REF-1							PKG:7	
210012 ^S	INSPECT AIR CONDITIONING DUCTS							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.250	AFL	6753						
PROC. REF: AMM 21-10-15							PKG:3	
210013 ^S	INSPECT RAM AIR DUCT							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.255	AFL	6753						
							PKG:3	
210014 ^S	INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM)							Service ATA:21
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 21.310	AFL	6498						
							PKG:7	
210015 ^S	INSPECT SILENCER DUCT/SOUNDPROOFING							Service ATA:21
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 21.015	AFL	5769						
PROC. REF: AMM 21-10-15							PKG:4	
210016 ^S	BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH							Service ATA:21
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 21.195	AFL	5769						
PROC. REF: AMM NO REF-1							PKG:4	
210018 ^S	FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING							Service ATA:21
	MOS		48 (+2m/-2m)					
	HRS							
WC#: 21.135	AFL							
PROC. REF: AMM 21-30-70							PKG:7	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210019 ^S	INSPECT CABIN SUPPLY NON-RETURN VALVE							Service ATA:21
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 21.065	AFL	5769						
				PROC. REF: AMM 21-10-107				PKG:4
210020 ^S	FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.180	AFL	6753						
				PROC. REF: AMM 21-60-105				PKG:3
210021 ^S	INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES							Service ATA:21
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 21.030	AFL	5769						
				PROC. REF: AMM 21-10-165				PKG:4
210022	CHECK TORQUE AIR CONDITIONING DUCTS							Service ATA:21
	MOS/MSC	10-Jul-15	O/C					
	HRS	6667.8						
WC#: 21.010	AFL	5769						
				PROC. REF: AMM 21-10-15				
210024 ^S	CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER							Service ATA:21
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 21.290	AFL	6498						
				PROC. REF: AMM 21-60-61				PKG:2
210025 ^S	INSPECT PATS APU GTCP36-150W BLEED AIR SYSTEM							Service ATA:21
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 21.035	AFL	6753						
								PKG:3
211013	LEFT SWITCHES BLEED AIR OVER TEMPERATURE TEST							Service ATA:21
	MOS	02-Apr-21	60		02-Apr-26		668 d	
	HRS	8048						
WC#: 21.265	AFL	6611						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
211014	RIGHT SWITCHES BLEED AIR OVER TEMPERATURE TEST							Service ATA:21
	MOS	02-Apr-21	60		02-Apr-26		668 d	
	HRS	8048						
WC#: 21.265	AFL	6611						
211031	APU BLEED AIR NON-RETURN VALVE							Component ATA:21
PN:123190-1-1	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
212001	LEFT MAIN AIR VALVE							Component ATA:21
PN:321292-1	MOS/MSC	11-Sep-97	O/C	TSO 0				
SN:2551	HRS	623		TSO 0				
WC#: 21.040	AFL	564		TSO 0				
PROC. REF: AMM 21-10-25								
212002	RIGHT MAIN AIR VALVE							Component ATA:21
PN:HTE250072-001	MOS/MSC	06-Mar-96	O/C					
SN:793VBF106	HRS	0		TSN 0				
WC#: 21.045	AFL	0						
PROC. REF: AMM 21-10-24								
212026	NO. 1 ENGINE BLEED AIR NON-RETURN VALVE							Component ATA:21
PN:HTE4168	MOS/MSC	06-Mar-96	O/C					
SN:302VNR1195	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REF								
212027	NO. 2 ENGINE BLEED AIR NON-RETURN VALVE							Component ATA:21
PN:HTE4168	MOS/MSC	06-Mar-96	O/C					
SN:147VNR995	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REF								
212050	AUXILIARY HEATING BLEED AIR NON-RETURN VALVE							Component ATA:21
PN:123190-1-1	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.055	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212062	LEFT (HP/LP) MIXING VALVE							Component ATA:21
PN:3213788-1-1	MOS/MSC	06-Mar-96	O/C					
SN:1380	HRS	0		TSN 0				
WC#: 21.060	AFL	0						
PROC. REF: AMM 21-10-35								
212063	RIGHT (HP/LP) MIXING VALVE							Component ATA:21
PN:3213788-1-1	MOS/MSC	29-Sep-21	O/C	TSO 0				
SN:1468	HRS	8145.1		TSO 0				
WC#: 21.060	AFL	6676		TSO 0				
PROC. REF: AMM 21-10-35								
212074	MAIN SUPPLY NON-RETURN VALVE (OVERHAUL)							Component ATA:21
PN:AWE124-51-2	MOS	06-Mar-96		TSN 0				OVERHAUL
SN:212074	HRS	0	12000	TSN 0	12000		3559.1	
WC#: 21.245	AFL	0		TSN 0				
PROC. REF: AMM 21-10-107								
212082	BLEED AIR CHECK VALVE							Component ATA:21
PN:HTE4405	MOS/MSC	06-Mar-96	O/C					
SN:1182VNR113	HRS	0		TSN 0				
WC#: 21.070	AFL							
PROC. REF: GENERIC NO REF								
212086	RAM AIR NON-RETURN VALVE							Component ATA:21
PN:321262-1	MOS/MSC	06-Mar-96	O/C					
SN:1029	HRS	0		TSN 0				
WC#: 21.075	AFL	0						
212098	RAM AIR SUPPLY NON-RETURN VALVE							Component ATA:21
PN:123190-1	MOS/MSC	06-Mar-96	O/C					
SN:5923	HRS	0		TSN 0				
WC#: 21.080	AFL	0						
PROC. REF: AMM 21-10-165								
212103	TEMPERATURE DUCT SWITCH							Component ATA:21
PN:25-6MC-415	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.085	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212122	UPPER CHECK VALVE							Component ATA:21
PN:130156-2	MOS/MSC	17-Jun-04	O/C	TSN 0				
SN:54-A0325	HRS	3568		TSN 0				
WC#: 21.095	AFL	3587		TSN 0				
PROC. REF: GENERIC NO REF								
212123	LOWER CHECK VALVE							Component ATA:21
PN:130156-1	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:105-2066	HRS	0		TSN 0				
WC#: 21.095	AFL	0						
PROC. REF: GENERIC NO REF								
212146	CABIN RECIRCULATING FAN							Component ATA:21
PN:0901-2	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:0184	HRS	0		TSN 0				
WC#: 21.100	AFL	0						
PROC. REF: GENERIC NO REF								
213001	NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE							Component ATA:21
PN:B01A214128A	MOS/MSC	06-Mar-96	O/C					
SN:RK513	HRS	0		TSN 0				
WC#: 21.105	AFL	0						
PROC. REF: GENERIC NO REF								
213002	NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE							Component ATA:21
PN:B01A214128A	MOS/MSC	06-Mar-96	O/C					
SN:RK512	HRS	0		TSN 0				
WC#: 21.105	AFL	0						
PROC. REF: GENERIC NO REF								
213019	OUTFLOW/SAFETY VALVE CONTROLLER							Component ATA:21
PN:130530-4	MOS/MSC	05-Mar-03	O/C					
SN:110-444	HRS	3001						
WC#: 21.115	AFL	2875						
PROC. REF: AMM 21-30-16								
213031	LEFT OUTFLOW VALVE							Component ATA:21
PN:103278-13	MOS/MSC	06-Mar-96	O/C					
SN:95-766	HRS	0		TSN 0				
WC#: 21.120	AFL	0						
PROC. REF: AMM 21-30-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213032	RIGHT OUTFLOW VALVE							Component ATA:21
PN:103278-13	MOS/MSC	06-Mar-96	O/C					
SN:95-764	HRS	0		TSN 0				
WC#: 21.120	AFL	0						
PROC. REF: AMM 21-30-25								
213035	2" BUTTERFLY VALVE							Component ATA:21
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
213067	CABIN ALTITUDE CONTROL VALVE							Component ATA:21
PN:131004-2	MOS/MSC	06-Mar-96	O/C					
SN:104-5104	HRS	0		TSN 0				
WC#: 21.125	AFL	0						
PROC. REF: AMM 21-30-95								
213073	MECHANICAL DUMP VALVE							Component ATA:21
PN:25-8VF43-35A	MOS/MSC	06-Mar-96	O/C					
SN:NK757	HRS	0		TSN 0				
WC#: 21.130	AFL	0						
PROC. REF: AMM 21-30-136								
213097	ALTIMETER PRESSURE SWITCH							Component ATA:21
PN:214C40-2-57	MOS/MSC	06-Mar-96	O/C					
SN:T6538	HRS	0		TSN 0				
WC#: 21.135	AFL							
PROC. REF: GENERIC NO REF								
213109	VENTURI							Component ATA:21
PN:131052-1	MOS/MSC	06-Mar-96	O/C					
SN:105-3774	HRS	0		TSN 0				
WC#: 21.140	AFL	0						
PROC. REF: AMM 21-30-105								
213115	FAN OPERATED VENTURI							Component ATA:21
PN:132322-3-1	MOS/MSC	06-Mar-96	O/C					
SN:114-4349	HRS	0		TSN 0				
WC#: 21.145	AFL	0						
PROC. REF: AMM 21-30-65								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213121	LEFT PNEUMATIC VALVE							Component ATA:21
PN:107312-4-1	MOS/MSC	06-Mar-96	O/C					
SN:55-11797	HRS	0		TSN 0				
WC#: 21.150	AFL	0						
PROC. REF: AMM 21-30-35								
213122	RIGHT PNEUMATIC VALVE							Component ATA:21
PN:107312-4-1	MOS/MSC	06-Mar-96	O/C					
SN:55-11776	HRS	0		TSN 0				
WC#: 21.150	AFL	0						
PROC. REF: AMM 21-30-35								
213133	LEFT ABSOLUTE PRESSURE CONTROL							Component ATA:21
PN:102466-5	MOS/MSC	06-Mar-96	O/C					
SN:95-1930	HRS	0		TSN 0				
WC#: 21.155	AFL	0						
PROC. REF: AMM 21-30-55								
213134	RIGHT ABSOLUTE PRESSURE CONTROL							Component ATA:21
PN:102466-5	MOS/MSC	06-Mar-96	O/C					
SN:95-1940	HRS	0		TSN 0				
WC#: 21.155	AFL	0						
PROC. REF: AMM 21-30-55								
213157	JET PUMP							Component ATA:21
PN:131150-1-1	MOS/MSC	06-Mar-96	O/C					
SN:84-2733	HRS	0		TSN 0				
WC#: 21.160	AFL	0						
PROC. REF: AMM 21-30-45								
213169	CABIN DIFFERENTIAL PRESSURE INDICATOR							Component ATA:21
PN:51010-1113	MOS/MSC	06-May-96	O/C					
SN:504548	HRS	22		TSN 0				
WC#: 21.165	AFL	11						
PROC. REF: GENERIC NO REF								
213181	GROUND PRESSURE CONNECTOR							Component ATA:21
PN:WGE133-2A	MOS/MSC	06-Mar-96	O/C					
SN:L375	HRS	0		TSN 0				
WC#: 21.170	AFL	0						
PROC. REF: AMM 21-30-85								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216001	CABIN TEMPERATURE CONTROL VALVE							Component ATA:21
PN:104968	MOS/MSC	06-Mar-96	O/C					
SN:1123	HRS	0		TSN 0				
WC#: 21.175	AFL	0						
PROC. REF: AMM 21-60-57								
216025	AUXILIARY HEATING VALVE							Component ATA:21
PN:104568	MOS/MSC	06-May-96	O/C					
SN:13022	HRS	22						
WC#: 21.180	AFL	11						
PROC. REF: AMM 21-60-105								
216055	CABIN TEMPERATURE (CONTROLLER) SENSOR							Component ATA:21
PN:607148-1-1	MOS/MSC	06-Mar-96	O/C					
SN:055C-8355	HRS	0		TSN 0				
WC#: 21.185	AFL	0						
PROC. REF: MMA 21-60-05								
216073	CABIN TEMPERATURE CONTROLLER							Component ATA:21
PN:617452-3	MOS/MSC	28-Jan-97	O/C					
SN:122C-0639	HRS	243		TSN 0				
WC#: 21.190	AFL	214						
PROC. REF: AMM 21-60-67								
216097	TEMPERATURE DUCT SELECTOR							Component ATA:21
PN:25-6MC-415	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.195	AFL	0						
PROC. REF: GENERIC NO REF								
216115	COLD AIR UNIT PACK							Component ATA:21
PN:2205490-3	MOS/MSC	05-Aug-98	O/C	TSN 0				
SN:48-347	HRS	1291		TSN 0				
WC#: 21.200	AFL	1137		TSN 0				
PROC. REF: GENERIC NO REF								
216121	MODULATING VALVE							Component ATA:21
PN:978836-5-1	MOS/MSC	26-Feb-99	O/C					
SN:239	HRS	1685						
WC#: 21.210	AFL	1465						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216127	CONTROL SENSOR							Component ATA:21
PN:1150642-2	MOS/MSC	30-May-97	O/C	TSN 0				
SN:106C-10154	HRS	459		TSN 0				
WC#: 21.215	AFL	417		TSN 0				
PROC. REF: AMM 21-60-60								
217001	WATER SEPARATOR							Component ATA:21
PN:25-8VF1351-131	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:124-1113	HRS	0		TSN 0				
WC#: 21.220	AFL	0						
PROC. REF: AMM 21-10-95								
217014	CABIN TRIPLE INDICATOR							Component ATA:21
PN:720-15900-913	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.225	AFL	0						
PROC. REF: AMM 21-30-90								
217023	PRESSURE SWITCH							Component ATA:21
PN:690090	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:009FRTR37	HRS	0		TSN 0				
WC#: 21.235	AFL	0						
PROC. REF: AMM 21-10-39								
ATA 22 - AUTO FLIGHT								
221001	AFCS CONTROL PANEL							Component ATA:22
PN:7011702-915	MOS/MSC	08-Jun-05	O/C					
SN:97030644	HRS	3776.3						
WC#: 22.010	AFL	3827						
PROC. REF: GENERIC NO REF								
221007	NO. 1 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:7003974-732	MOS/MSC	07-Aug-11	O/C	TSO 0, TSR 0				
SN:86040315	HRS	5379.8		TSR 0				
WC#: 22.015	AFL	4856		TSR 0				
PROC. REF: AMM 34-22-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221008	NO. 2 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:7003974-732	MOS/MSC	30-Sep-14	O/C					
SN:86040315	HRS	6393.7						
WC#: 22.015	AFL	5624						
PROC. REF: AMM 34-22-05								
221037	AUTOPILOT ELEVATOR SERVO							Component ATA:22
PN:4006719-910	MOS/MSC	06-May-96	O/C					
SN:95098088	HRS	22		TSN 0				
WC#: 22.020	AFL	11						
221039	ELEVATOR SERVO MOUNT							Component ATA:22
PN:4005842	MOS/MSC	06-May-96	O/C					
SN:95076649	HRS	22		TSN 0				
WC#: 22.050	AFL	11						
PROC. REF: AMM 27-30-81								
221043	AUTOPILOT RUDDER SERVO							Component ATA:22
PN:4006719-913	MOS/MSC	10-Aug-16	O/C	TSO 0				
SN:99082891	HRS	7014.8		TSO 0				
WC#: 22.020	AFL	5936		TSO 0				
221045	RUDDER SERVO MOUNT							Component ATA:22
PN:400582	MOS/MSC	06-May-96	O/C					
SN:95116859	HRS	22		TSN 0				
WC#: 22.050	AFL	11						
PROC. REF: AMM 27-20-121								
221049	AUTOPILOT AILERON SERVO							Component ATA:22
PN:4006719-906	MOS/MSC	06-May-96	O/C					
SN:95118181	HRS	22		TSN 0				
WC#: 22.020	AFL	11						
221052	AILERON SERVO MOUNT							Component ATA:22
PN:4005842	MOS/MSC	06-May-96	O/C					
SN:95076632	HRS	22		TSN 0				
WC#: 22.050	AFL	11						
ATA 23 - COMMUNICATIONS								
23-16-50 ^U	ATG CTR							Component ATA:23
PN:P12083 REV P	MOS/MSC	04-Jun-15	NONE					
SN:1208310815	HRS	6639						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
	AFL	5759						
23-16-50 ^U	ATG TRANSCEIVER							Component ATA:23
PN:P15684-001 REV J	MOS/MSC	27-Sep-17	NONE					
SN:1586410422	HRS	7329.4						
	AFL	6126						
231001	NO. 1 HF COMMUNICATIONS CONTROLLER							Component ATA:23
PN:071-1274-02	MOS/MSC	03-Oct-96	O/C					
SN:3531	HRS	23		TSN 0				
WC#: 23.015	AFL	14						
				PROC. REF: AMM 23-10-10				
231004	NO. 1 HF CONTROLLER ADAPTER							Component ATA:23
PN:071-1268-01	MOS/MSC	06-May-96	O/C					
SN:2789	HRS	22		TSN 0				
WC#: 23.020	AFL	11						
				PROC. REF: GENERIC NO REF				
231011	NO. 1 HF COMMUNICATIONS POWER AMPLIFIER							Component ATA:23
PN:064-1017-02	MOS/MSC	02-Sep-13	O/C	TSR 0				
SN:13117	HRS	6080.9		TSR 0				
WC#: 23.025	AFL	5386		TSR 0				
				PROC. REF: GENERIC NO REF				
231025	NO. 1 HF RECEIVER EXCITER							Component ATA:23
PN:064-1015-01	MOS/MSC	02-Sep-13	O/C	TSR 0				
SN:33269	HRS	6080.9		TSR 0				
WC#: 23.030	AFL	5386		TSR 0				
231027	NO. 1 HF BRIDGING AMPLIFIER							Component ATA:23
PN:071-0019-00	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.035	AFL	0						
				PROC. REF: GENERIC NO REF				
231029	DUAL HF CAPACITOR							Component ATA:23
PN:071-01271-001	MOS/MSC	06-May-96	O/C					
SN:1829	HRS	22		TSN 0				
WC#: 23.040	AFL	11						
				PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231041	VHF COMMUNICATION (CTL-23D) CONTROL							Component ATA:23
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.136	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
231043	NO. 1 VHF COMMUNICATIONS TRANSCEIVER							Component ATA:23
PN:7510700-802	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.045	AFL	0						
PROC. REF: AMM NO REF-1, MMA 23-20-79, MMA 23-20-80, MMA 23-20-81								
231049	NO. 2 VHF COMMUNICATIONS TRANSCEIVER							Component ATA:23
PN:7510700-806	MOS/MSC	27-Mar-14	O/C	TSR 0				
SN:97062422	HRS	6253.1		TSR 0				
WC#: 23.045	AFL	5527		TSR 0				
PROC. REF: AMM NO REF-1, MMA 23-20-79, MMA 23-20-80, MMA 23-20-81								
231050	ATC UPPER ANTENNA							Component ATA:23
PN:S65-5366-8L	MOS/MSC	06-May-96	O/C					
SN:4806	HRS	22		TSN 0				
WC#: 23.050	AFL	11						
PROC. REF: GENERIC NO REF								
231055	NO. 1 VHF AERIAL							Component ATA:23
PN:16-21-1T	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.055	AFL	0						
PROC. REF: AMM 23-20-1626								
231056	NO. 2 VHF AERIAL							Component ATA:23
PN:16-21-1TM0D2	MOS/MSC	14-May-15	O/C	TSN 0				
SN:7749	HRS	6613.4		TSN 0				
WC#: 23.055	AFL	5749		TSN 0				
PROC. REF: AMM 23-20-1626								
231058	AUDIO TONE GENERATOR							Component ATA:23
PN:M1285AC	MOS/MSC	06-May-96	O/C					
SN:9510208	HRS	22		TSN 0				
WC#: 23.060	AFL	11						
PROC. REF: MMA 23-50-67								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231061	NO. 1 RADIO MANAGEMENT UNIT							Component ATA:23
PN:7012100-811	MOS/MSC	06-Aug-21	O/C					
SN:92020907	HRS	8125.3						
WC#: 23.065	AFL	6661						
PROC. REF: AMM 23-80-05								
231062	NO. 2 RADIO MANAGEMENT UNIT							Component ATA:23
PN:7012100-811	MOS/MSC	24-Nov-07	O/C	TSR 0				
SN:96111786	HRS	4462.8		TSR 0				
WC#: 23.065	AFL	4280		TSR 0				
PROC. REF: AMM 23-80-05								
231064	CLEARANCE DELIVERY CONTROL							Component ATA:23
PN:7513000-801	MOS/MSC	06-May-96	O/C					
SN:1276	HRS	22		TSN 0				
WC#: 23.070	AFL	11						
PROC. REF: GENERIC NO REF								
234001	MOBILE RADIO/TELEPHONE TRANSCEIVER							Component ATA:23
PN:400-10680-002	MOS/MSC	09-Mar-09	O/C					
SN:1068021597	HRS	4670						
WC#: 23.075	AFL	4415						
234007	MOBILE RADIO ANTENNA							Component ATA:23
PN:015-10306-001	MOS/MSC	09-Mar-09	O/C					
SN:8642	HRS	4670						
WC#: 23.080	AFL	4415						
234013	COCKPIT MOBILE RADIO TELEPHONE HANDSET							Component ATA:23
PN:P12198-001	MOS/MSC	09-Mar-09	O/C					
SN:1219852089	HRS	4670						
WC#: 23.085	AFL	4415						
PROC. REF: AMM 23-17-05, MMA 23-16-05, MMA 23-16-10								
234019	CABIN MOBILE RADIO TELEPHONE HANDSET							Component ATA:23
PN:P12199-002	MOS/MSC	03-May-12	O/C	TSR 0				
SN:1219942436	HRS	5599.6		TSR 0				
WC#: 23.085	AFL	4994		TSR 0				
PROC. REF: AMM 23-17-05, MMA 23-16-05, MMA 23-16-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
234041	FLITEPHONE AUXILIARY BELL							Component ATA:23
PN:300-2070-000	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.090	AFL	0						
PROC. REF: GENERIC NO REF								
235001	NO. 1 AUDIO CONTROLLER							Component ATA:23
PN:7511001-909	MOS/MSC	22-Oct-02	O/C					
SN:96102057	HRS	2851						
WC#: 23.095	AFL	2686						
PROC. REF: MMA 23-50-67								
235002	NO. 2 AUDIO CONTROLLER							Component ATA:23
PN:7511001-909	MOS/MSC	08-Sep-99	O/C	TSN 0				
SN:95121651	HRS	2139		TSN 0				
WC#: 23.095	AFL	1744		TSN 0				
PROC. REF: MMA 23-50-67								
235017	NO. 1 HANDHELD AUDIO MICROPHONE							Component ATA:23
PN:CM488T	MOS/MSC	06-May-96	O/C					
SN:76196	HRS	22		TSN 0				
WC#: 23.100	AFL	11						
PROC. REF: GENERIC NO REF								
235019	NO. 2 HANDHELD AUDIO MICROPHONE							Component ATA:23
PN:CM488T	MOS/MSC	06-May-96	O/C					
SN:76184	HRS	22		TSN 0				
WC#: 23.100	AFL	11						
PROC. REF: GENERIC NO REF								
237001	COCKPIT VOICE RECORDER							Component ATA:23
PN:1602-01-03	MOS/MSC	24-Aug-13	O/C	TSO 0				
SN:436	HRS	6078.3		TSN 6056.3, TSO 0				
WC#: 23.105	AFL			TSO 0				
PROC. REF: AMM 23-70-15, AMM 23-70-25, MMA 23-70-05, MMA 23-70-35								
237004	COCKPIT VOICE RECORDER NO.1 MICROPHONE							Component ATA:23
PN:16101-02	MOS/MSC	10-Oct-96	O/C					
SN:1416	HRS	30		TSN 0				
WC#: 23.110	AFL	16						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237005	COCKPIT VOICE RECORDER NO.2 MICROPHONE							Component ATA:23
PN:16101-02	MOS/MSC	10-Oct-96	O/C					
SN:1421	HRS	30		TSN 0				
WC#: 23.110	AFL	16						
PROC. REF: GENERIC NO REF								
237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (OVERHAUL)							Component ATA:23
PN:DK120/90	MOS	26-Feb-19	72	TSN 0	26-Feb-25		268 d	OVERHAUL
SN:AT9481	HRS	7708		TSN 0				
WC#: 23.105	AFL	6372		TSN 0				
PROC. REF: AMM 23-70-15, AMM 23-70-25, MMA 23-70-35								
237015	TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Service ATA:23
	MOS	20-Mar-23	24		20-Mar-25		290 d	
	HRS							
WC#: 23.105	AFL							
PROC. REF: AMM 23-70-15, AMM 23-70-25, MMA 23-70-05, MMA 23-70-35								
237016	CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Service ATA:23
	MOS	21-Mar-23	24		21-Mar-25		291 d	
	HRS	8325.8						
WC#: 23.105	AFL	6765						
PROC. REF: AMM 23-70-15, AMM 23-70-25, MMA 23-70-05, MMA 23-70-35								
237017	REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service ATA:23
	MOS/MSC	26-Feb-19	DUE		30-Nov-24 (M)		180 d	
	HRS	7708						
WC#: 23.105	AFL	6372						
PROC. REF: MMA 23-70-05								
237019	LEFT COCKPIT VOICE RECORDER CONTROL							Component ATA:23
PN:1614-01	MOS/MSC	06-May-96	O/C					
SN:188	HRS	22		TSN 0				
WC#: 23.125	AFL	11						
237020	RIGHT COCKPIT VOICE RECORDER CONTROL							Component ATA:23
PN:93-A151-20	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.125	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237021	VOICE RECORDER INERTIA SWITCH							Component ATA:23
PN:3L0-453-2G	MOS/MSC	06-May-96	O/C					
SN:5664	HRS	22		TSN 0				
WC#: 23.115	AFL	11						
PROC. REF: GENERIC NO REF								
237022	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Component ATA:23
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
238015	SELCAL DECODER UNIT							Component ATA:23
PN:1200008-001	MOS/MSC	10-Oct-96	O/C					
SN:146	HRS	30		TSN 0				
WC#: 23.120	AFL	16						
PROC. REF: AMM 23-20-10, MMA 23-20-05								
ATA 24 - ELECTRICAL POWER								
240001	INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR							Service ATA:24
PN:23080-064	MOS	11-Jan-23						
SN:99996	HRS	8299.1	200 (+200)		8499.1	8699.1	58.2 (+200)	
WC#: 24.045	AFL	6753						
PROC. REF: AMM 24-30-21								
240001	INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR							Service ATA:24
PN:23080-064	MOS	11-Jan-23						
SN:P2260	HRS	8299.1	200 (+200)		8499.1	8699.1	58.2 (+200)	
WC#: 24.045	AFL	6753						
PROC. REF: AMM 24-30-21								
240002 ^S	OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS							Service ATA:24
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 24.010	AFL	6498						
PKG:2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240003 ^S	FUNCTION TEST FREQUENCY WILD A.C. SYSTEM							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.030	AFL	5769						
PROC. REF: AMM 24-22-02							PKG:4	
240004 ^S	CHECK BUSBAR CONTACTOR CONTROL							Service ATA:24
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 24.145	AFL	6753						
							PKG:3	
240006 ^S	CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.070	AFL	5769						
PROC. REF: AMM 24-30-142							PKG:4	
240007 ^S	BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED).							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.110	AFL	5769						
PROC. REF: AMM 24-30-146							PKG:4	
240009 ^S	FUNCTIONAL TEST D.C. GENERATING SYSTEM							Service ATA:24
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 24.065	AFL	6498						
PROC. REF: AMM 24-30-01							PKG:2	
240010 ^S	INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA							Service ATA:24
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 24.160	AFL	6753						
PROC. REF: AMM 24-01-00							PKG:3	
240011 ^S	FUNCTIONAL TEST OF THE BUSBAR PE, PS1 AND PS2 FEEDER FUSES							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	1600 (+50/-50)					
WC#: 24.150	AFL	5769						
PROC. REF: AMM 24-01-00							PKG:3	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240012 ^U	INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS							Service ATA:24
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 24.165	AFL	6753						
								PKG:3
240013 ^S	FUNCTION TEST ALL CIRCUIT BREAKERS							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.005	AFL	5769						
								PKG:4
240014 ^S	FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.040	AFL	5769						
PROC. REF: AMM 24-30-07								PKG:4
240015 ^S	FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.040	AFL	5769						
PROC. REF: AMM 24-36-03								PKG:4
240016 ^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.235	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4
240017 ^S	INSPECT/CHECK EARTH STATIONS *16, *17, *18, AND *19							Service ATA:24
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 24.155	AFL	6498						
PROC. REF: AMM 24-01-00								PKG:7
240018 ^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.235	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240024	INSPECT/CHECK APU STARTER/GENERATOR							Service ATA:24
PN:23080-005	MOS	06-Apr-22						
SN:6174	HRS	8213.1						
WC#: 24.085	AFL	6712						
	APH	5264	500		5764		409	
PROC. REF: AMM 24-30-21								
240025 ^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.245	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4
240026 ^S	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.240	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4
240027 ^S	CHECK MAIN BATTERIES							Service ATA:24
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 24.250	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4
240028	VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M							Service ATA:24
	MOS	17-Nov-23						
	HRS	8393.1	400 (+10%)		8793.1	8833.1	352.2 (+40)	
WC#: 24.095	AFL	6799						
PROC. REF: AMM NO REF-1								
240029 ^S	VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF HEAT DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS							Service ATA:24
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 24.260	AFL	6799						
PKG:5								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242001	NO. 1 (MAIN) INVERTER							Component ATA:24
PN:ASH664-5	MOS/MSC	11-Jun-21	O/C					
SN:EK919	HRS	8083.4						
WC#: 24.015	AFL	6635						
PROC. REF: AMM 24-21-102								
242002	NO. 2 (MAIN) INVERTER							Component ATA:24
PN:140-380010-7	MOS/MSC	15-Jan-21	O/C					
SN:1237ME	HRS	8003.7						
WC#: 24.015	AFL	6577						
PROC. REF: AMM 24-21-102								
242013	NO. 3 (STANDBY) INVERTER							Component ATA:24
PN:PC250	MOS/MSC	06-Mar-96	O/C					
SN:6171	HRS	0		TSN 0				
WC#: 24.015	AFL	0						
PROC. REF: AMM 24-21-105								
242031	NO. 1 INVERTER CONTACTOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:140-380020-0001	MOS	11-Jun-10		TSN 0				
SN:CR-73112	HRS	5097.8	5000	TSN 0	10097.8		1656.9	
WC#: 24.020	AFL	4673		TSN 0				
242032	NO. 2 INVERTER CONTACTOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:140-380020-0001	MOS	21-Dec-09		TSN 0				
SN:CR-34558	HRS	4961.5	5000	TSN 0	9961.5		1520.6	
WC#: 24.020	AFL	4598		TSN 0				
242073	NO. 1 ENGINE AC GENERATOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:BA02801-1	MOS	17-Nov-23	96	TSO 0	17-Nov-31		2723 d	
SN:2600	HRS	8393.1	3000	TSO 0	11393.1		2952.2	
WC#: 24.025	AFL	6799		TSO 0				
PROC. REF: AMM 24-22-21								
242074	NO. 2 ENGINE AC GENERATOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:BA02801-1	MOS	17-Nov-23	96	TSO 0	17-Nov-31		2723 d	
SN:1359	HRS	8393.1	3000	TSO 0	11393.1		2952.2	
WC#: 24.025	AFL	6799		TSO 0				
PROC. REF: AMM 24-22-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242097	LEFT AC GENERATOR CONTROL UNIT							Component ATA:24
PN:CB02701	MOS/MSC	08-Jul-03	O/C					
SN:H1570	HRS	3147.5						
WC#: 24.035	AFL	3065						
PROC. REF: AMM 24-30-07								
242098	RIGHT AC GENERATOR CONTROL UNIT							Component ATA:24
PN:CB02701	MOS/MSC	06-Mar-96	O/C					
SN:1905	HRS	0		TSN 0				
WC#: 24.035	AFL	0						
PROC. REF: AMM 24-30-07								
243001	NO. 1 ENGINE STARTER/GENERATOR (OVERHAUL)							Component ATA:24
PN:23080-064	MOS	02-Apr-21		TSO 0				OVERHAUL
SN:99996	HRS	8048	1000	TSO 0	9048		607.1	
WC#: 24.045	AFL	6611		TSO 0				
PROC. REF: AMM 24-30-21								
243002	NO. 2 ENGINE STARTER/GENERATOR (OVERHAUL)							Component ATA:24
PN:23080-064	MOS	02-Apr-21		TSO 0				OVERHAUL
SN:P2260	HRS	8048	1000	TSO 0	9048		607.1	
WC#: 24.045	AFL	6611		TSO 0				
PROC. REF: AMM 24-30-21								
243037	NO. 1 DC GENERATOR CONTROL UNIT							Component ATA:24
PN:51539-006H	MOS/MSC	06-Mar-96	O/C					
SN:95356	HRS	0		TSN 0				
WC#: 24.050	AFL	0						
PROC. REF: AMM 24-30-07								
243038	NO. 2 DC GENERATOR CONTROL UNIT							Component ATA:24
PN:51539-006H	MOS/MSC	06-Mar-96	O/C					
SN:95358	HRS	0		TSN 0				
WC#: 24.050	AFL	0						
PROC. REF: AMM 24-30-07								
243049	H (UPPER) CONTACTOR							Component ATA:24
PN:A.703-ZS	MOS/MSC	06-Mar-96	O/C					
SN:CL-45869	HRS	0		TSN 0				
WC#: 24.055	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243050	H (LOWER) CONTACTOR							Component ATA:24
PN:A.703.ZS	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.055	AFL	0						
PROC. REF: GENERIC NO REF								
243061	G (UPPER) CONTACTOR							Component ATA:24
PN:A.703-FSS	MOS/MSC	06-Mar-96	O/C					
SN:CL-44848	HRS	0		TSN 0				
WC#: 24.060	AFL	0						
PROC. REF: GENERIC NO REF								
243062	G (LOWER) CONTACTOR							Component ATA:24
PN:A.703.FSS	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.060	AFL	0						
PROC. REF: GENERIC NO REF								
243079	DC VOLTAGE SENSING UNIT							Component ATA:24
PN:U3626-2	MOS/MSC	06-Mar-96	O/C					
SN:2062	HRS	0		TSN 0				
WC#: 24.070	AFL	0						
PROC. REF: GENERIC NO REF								
243091	GROUND SUPPLY START (E) CONTACTOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:LDG.150-Y4	MOS	02-Sep-13		TSO 0				
SN:Q35896	HRS	6080.9	6000	TSO 0	12080.9		3640	
WC#: 24.075	AFL	5386		TSO 0				
243103	APU STARTER/GENERATOR CONTROL UNIT							Component ATA:24
PN:51539-006H	MOS/MSC	20-Feb-15	O/C	TSO 0				
SN:99017	HRS	6511.2		TSO 0				
WC#: 24.080	AFL	5703		TSO 0				
PROC. REF: AMM 24-30-21, AMM 49-11-00								
243115	APU STARTER/GENERATOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:23080-005	MOS	06-Apr-22		TSO 0				
SN:6174	HRS	8213.1		TSO 0				
WC#: 24.085	AFL	6712		TSO 0				
	APH	5264	1000	TSO 0	6264		909	
PROC. REF: AMM 24-30-21, MMA 49-16-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243137	NO. 1 BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	16-Oct-20	O/C	TSN 12				
SN:41021432	HRS	7924.2		TSN 128.8				
WC#: 24.090	AFL	6522		TSN 90				
PROC. REF: AMM 24-30-104, AMM 24-30-151								
243138	NO. 2 BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	16-Oct-20	O/C	TSN 12				
SN:41021435	HRS	7924.2		TSN 128.8				
WC#: 24.090	AFL	6522		TSN 90				
PROC. REF: AMM 24-30-104, AMM 24-30-151								
243139	NO. 3 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	17-Nov-23	O/C	TSN 0				
SN:70024263	HRS	8393.1		TSN 0				
WC#: 24.210	AFL	6799		TSN 0				
PROC. REF: AMM 24-30-104, AMM 24-30-151								
243140	NO. 4 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	17-Nov-23	O/C	TSN 38				
SN:40827103	HRS	8393.1		TSN 496.4				
WC#: 24.220	AFL	6799		TSN 301				
PROC. REF: AMM 24-30-07, AMM 24-30-153, AMM 24-30-154								
243141	NO. 5 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	17-Nov-23	O/C					
SN:40827769	HRS	8393.1						
WC#: 24.230	AFL	6799						
PROC. REF: AMS 24-30-155								
243154	CAPACITY CHECK NO. 1 BATTERY							Service ATA:24
PN:RG-390E	MOS	17-Nov-23	12 (+1m/-1m)		17-Nov-24	17-Dec-24	167 d (+30)	
SN:41021432	HRS	8393.1						
WC#: 24.090	AFL	6799						
PROC. REF: GENERIC NO REF								
243155	CAPACITY CHECK NO. 2 BATTERY							Service ATA:24
PN:RG-390E	MOS	17-Nov-23	12 (+1m/-1m)		17-Nov-24	17-Dec-24	167 d (+30)	
SN:41021435	HRS	8393.1						
WC#: 24.090	AFL	6799						
PROC. REF: AMM 24-30-104, AMM 24-30-151								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243156	CAPACITY CHECK NO. 3 BATTERY							Service ATA:24
PN:RG-126	MOS	17-Nov-23	12 (+30d/-30d)		17-Nov-24	17-Dec-24	167 d (+30)	
SN:70024263	HRS	8393.1						
WC#: 24.210	AFL	6799						
PROC. REF: AMM 24-30-153, AMM 24-30-154								
243157	CAPACITY CHECK NO. 4 BATTERY							Service ATA:24
PN:RG-126	MOS	17-Nov-23	12 (+30d/-30d)		17-Nov-24	17-Dec-24	167 d (+30)	
SN:40827103	HRS	8393.1						
WC#: 24.220	AFL	6799						
PROC. REF: AMM 24-30-153, AMM 24-30-154								
243158	CAPACITY CHECK NO. 5 BATTERY							Service ATA:24
PN:RG-126	MOS	17-Nov-23	12 (+30d/-30d)		17-Nov-24	17-Dec-24	167 d (+30)	
SN:40827769	HRS	8393.1						
WC#: 24.230	AFL	6799						
PROC. REF: AMM 24-30-153, AMM 24-30-154								
243238	OVERVOLTAGE SENSOR							Component ATA:24
PN:E311TS	MOS/MSC	06-Mar-96	O/C					
SN:CM-99128	HRS	0		TSN 0				
WC#: 24.110	AFL	0						
PROC. REF: AMM 24-30-146								
243246	THERMAL SWITCH							Component ATA:24
PN:21346-6	MOS/MSC	03-Oct-96	O/C					
SN:430U	HRS	23						
WC#: 24.115	AFL	14						
PROC. REF: AMM 26-16-03								
243247	S CONTACTOR							Component ATA:24
PN:LDA-200-B18C	MOS/MSC	06-Mar-96	O/C					
SN:X3389	HRS	0		TSN 0				
WC#: 24.120	AFL	0						
PROC. REF: GENERIC NO REF								
243253	FORWARD U CONTACTOR							Component ATA:24
PN:LDA-200-B18C	MOS/MSC	06-Mar-96	O/C					
SN:X3398	HRS	0		TSN 0				
WC#: 24.120	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243259	J CONTACTOR							Component ATA:24
PN:A.700-RSS	MOS/MSC	06-Mar-96	O/C					
SN:CL-49648	HRS	0		TSN 0				
WC#: 24.125	AFL	0						
PROC. REF: GENERIC NO REF								
243265	K CONTACTOR							Component ATA:24
PN:A.700-RSS	MOS/MSC	06-Mar-96	O/C					
SN:CL-49649	HRS	0		TSN 0				
WC#: 24.125	AFL	0						
PROC. REF: GENERIC NO REF								
243271	AFT U CONTACTOR							Component ATA:24
PN:A.848-MAS	MOS/MSC	06-Mar-96	O/C					
SN:CL40849	HRS	0		TSN 0				
WC#: 24.130	AFL	0						
PROC. REF: GENERIC NO REF								
243277	L CONTACTOR							Component ATA:24
PN:9124-9290	MOS/MSC	06-Mar-96	O/C					
SN:79888	HRS	0		TSN 0				
WC#: 24.135	AFL	0						
PROC. REF: GENERIC NO REF								
243283	M CONTACTOR							Component ATA:24
PN:9124-9290	MOS/MSC	06-Mar-96	O/C					
SN:78248	HRS	0		TSN 0				
WC#: 24.135	AFL	0						
PROC. REF: GENERIC NO REF								
245001	BUS TIE (T) CONTACTOR (OVERHAUL)							Component ATA:24 OVERHAUL
PN:140-380017-0001	MOS	21-Dec-09		TSN 0				
SN:CR-22398	HRS	4961.5	5000	TSN 0	9961.5		1520.6	
WC#: 24.140	AFL	4598		TSN 0				
245043	TEMPERATURE SENSOR							Component ATA:24
PN:548408-1	MOS/MSC	06-Mar-96	O/C					
SN:075C-1698	HRS	0		TSN 0				
WC#: 24.170	AFL	0						
PROC. REF: AMM 34-48-622								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
250003 ^S	CHECK 3RD CREW MEMBERS SEAT							Service ATA:25
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 25.115	AFL	6498						
								PKG:2
250006 ^S	CHECK FIRST AID KITS							Service ATA:25
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 25.130	AFL	6799						
								PKG:5
250007 ^S	OPERATIONAL CHECK CREW SEATS							Service ATA:25
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 25.145	AFL	6498						
								PKG:2
250008 ^S	DETAILED CHECK CREW SEATS							Service ATA:25
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 25.150	AFL	5769						
PROC. REF: AMM NO REF-1								PKG:4
251000 ^U	SEAT BELTS							Component ATA:25
PN:5000B2	MOS/MSC		O/C					
SN:UNKNOW	HRS							
	AFL							
251001	NO. 1 CREW SEAT							Component ATA:25
PN:3A/026/0013/00-2	MOS/MSC	06-Mar-96	O/C					
SN:26321	HRS	0		TSN 0				
WC#: 25.010	AFL	0						
PROC. REF: AMM 25-10-14								
251002	NO. 2 CREW SEAT							Component ATA:25
PN:3A/026/0014/00-2	MOS/MSC	06-Mar-96	O/C					
SN:26325	HRS	0		TSN 0				
WC#: 25.010	AFL	0						
PROC. REF: AMM 25-10-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
251020	THROTTLE BOX							Component ATA:25
PN:25-8CX179-577A	MOS/MSC	06-Mar-96	O/C					
SN:520	HRS	0		TSN 0				
WC#: 25.020	AFL							
PROC. REF: GENERIC NO REF								
256001	EMERGENCY LOCATOR TRANSMITTER (ELT)							Component ATA:25
PN:453-5000-999	MOS/MSC	07-Dec-15	O/C					
SN:00915	HRS	6821.6						
WC#: 25.025	AFL	5853						
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15								
256005	INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT)							Service ATA:25
PN:453-5000-999	MOS	17-Nov-23	12		17-Nov-24		167 d	
SN:00915	HRS	8393.1						
WC#: 25.025	AFL	6799						
256007	REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Service ATA:25
PN:452-0133	MOS/MSC	04-Sep-20	DUE		31-Mar-25 (M)		301 d	
SN:384405-020	HRS	7896.7						
WC#: 25.025	AFL	6498						
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15								
256010	FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT)							Service ATA:25
PN:453-5000-999	MOS	17-Nov-23	12		17-Nov-24		167 d	
SN:00915	HRS	8393.1						
WC#: 25.025	AFL	6799						
PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15								
256013	INSPECT LIFE VESTS							Service ATA:25
	MOS	11-Jan-23	24		11-Jan-25		222 d	
	HRS	8299.1						
WC#: 25.040	AFL	6753						
256080 ^U	NO. 1 LIFE VEST							Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160084	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256080A ^U		RECERTIFY NO. 1 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160084	HRS	7896.7						
	AFL	6498						
256081 ^U		NO. 2 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160072	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256081A ^U		RECERTIFY NO. 2 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160072	HRS	7896.7						
	AFL	6498						
256082 ^U		NO. 3 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160014	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256082A ^U		RECERTIFY NO. 3 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160014	HRS	7896.7						
	AFL	6498						
256083 ^U		NO. 4 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160009	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256083A ^U		RECERTIFY NO. 4 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160009	HRS	7896.7						
	AFL	6498						
256084 ^U		NO. 5 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160008	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256084A ^U		RECERTIFY NO. 5 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160008	HRS	7896.7						
	AFL	6498						
256085 ^U		NO. 6 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160094	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256085A ^U		RECERTIFY NO. 6 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160094	HRS	7896.7						
	AFL	6498						
256086 ^U		NO. 7 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160065	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256086A ^U		RECERTIFY NO. 7 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160065	HRS	7896.7						
	AFL	6498						
256087 ^U		NO. 8 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160087	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256087A ^U		RECERTIFY NO. 8 LIFE VEST						Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160087	HRS	7896.7						
	AFL	6498						
256088 ^U		NO. 9 LIFE VEST						Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160033	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256088A ^U	RECERTIFY NO. 9 LIFE VEST							Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160033	HRS	7896.7						
	AFL	6498						
256089 ^U	NO. 10 LIFE VEST							Component ATA:25
PN:P01074-101W	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:20060160083	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
256089A ^U	RECERTIFY NO. 10 LIFE VEST							Service ATA:25
PN:P01074-101W	MOS	04-Sep-20	60		04-Sep-25		458 d	
SN:20060160083	HRS	7896.7						
	AFL	6498						
256301	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY							Component ATA:25
PN:452-0133	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:384405-020	HRS	7896.7		TSN 0				
	AFL	6498		TSN 0				
25R001 ^U	INSPECT E.L.T. NAV INTERFACE							Service ATA:25
	MOS	17-Nov-23	12		17-Nov-24		167 d	
	HRS	8393.1						
	AFL	6799						
ATA 26 - FIRE PROTECTION								
260000 ^U	COCKPIT AND CABIN FIRE EXTINGUISHERS							Service ATA:26
	DAYS	17-Nov-23	30		17-Dec-23		OVD	
	HRS	8393.1						
	AFL	6799						
260002 ^S	FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM							Service ATA:26
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 26.035	AFL	6498						
PROC. REF: AMM 26-10-00								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
260003 ^S	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C-352	MOS	17-Nov-23	12 (+1m/-1m)					
SN:B-10810797	HRS	8393.1						
WC#: 26.080	AFL	6799						
								PKG:5
260004 ^S	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C-352	MOS	17-Nov-23	12 (+1m/-1m)					
SN:B-10810827	HRS	8393.1						
WC#: 26.075	AFL	6799						
								PKG:5
260005 ^S	WEIGHT CHECK AFT ENGINE FIRE EXTINGUISHER							Service ATA:26
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 26.020	AFL	6799						
PROC. REF: AMM 26-20-12								PKG:5
260005 ^S	WEIGHT CHECK FORWARD ENGINE FIRE EXTINGUISHER							Service ATA:26
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 26.010	AFL	6799						
PROC. REF: AMM 26-20-12								PKG:5
260008	FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)							Service ATA:26
	MOS	17-Nov-23	6 (+10%)		17-May-24	04-Jun-24	TOL (+1 d)	
	HRS	8393.1						
WC#: 26.115	AFL	6799						
PROC. REF: MMA 26-11-00								
260010 ^S	CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER							Service ATA:26
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 26.085	AFL	6799						
PROC. REF: AMM 49-61-20, CMM 26-20-02								PKG:5
261030	APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH							Component ATA:26
PN:17343*	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.120	AFL	0		TSN 0				
PROC. REF: AMM 26-16-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261031	APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH							Component ATA:26
PN:17343*	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.125	AFL	0		TSN 0				
PROC. REF: AMM 26-16-03								
261032	APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH							Component ATA:26
PN:160275-1	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.130	AFL	0		TSN 0				
PROC. REF: AMM 26-16-03								
261033	APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH							Component ATA:26
PN:67100*	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.135	AFL	0		TSN 0				
PROC. REF: AMM 26-16-03								
261034	TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH							Service ATA:26
PN:17343*	MOS	02-Apr-21	60		02-Apr-26		668 d	
SN:UNKNOWN	HRS	8048						
WC#: 26.120	AFL	6611						
261035	TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH							Service ATA:26
PN:17343*	MOS	02-Apr-21	60		02-Apr-26		668 d	
SN:UNKNOWN	HRS	8048						
WC#: 26.125	AFL	6611						
261036	TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH							Service ATA:26
PN:160275-1	MOS	02-Apr-21	60		02-Apr-26		668 d	
SN:UNKNOWN	HRS	8048						
WC#: 26.130	AFL	6611						
261037	TEST APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH							Service ATA:26
PN:67100*	MOS	02-Apr-21	60		02-Apr-26		668 d	
SN:UNKNOWN	HRS	8048						
WC#: 26.135	AFL	6611						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261074	OVERHEAT DETECTION SWITCHES TEST							Service ATA:26
	MOS	02-Apr-21	60		02-Apr-26		668 d	
	HRS	8048						
WC#: 26.030	AFL	6611						
PROC. REF: AMM 26-20-00								
261171	NO. 1 ENGINE ZONE 1 FIRE DETECTOR							Component ATA:26
PN:3001-112-900/400-10	MOS/MSC	05-Aug-98	O/C	TSN 0				
SN:78542	HRS	1291		TSN 0				
WC#: 26.050	AFL	1137		TSN 0				
PROC. REF: AMM 26-10-12								
261172	NO. 2 ENGINE ZONE 1 FIRE DETECTOR							Component ATA:26
PN:3001-112-900/400-10	MOS/MSC	06-Mar-96	O/C					
SN:76680	HRS	0		TSN 0				
WC#: 26.055	AFL	0						
PROC. REF: AMM 26-10-12								
261183	NO. 1 ENGINE ZONE 2 FIRE DETECTOR							Component ATA:26
PN:3001-133-900/500-6	MOS/MSC	05-Aug-98	O/C	TSN 0				
SN:79057	HRS	1291		TSN 0				
WC#: 26.050	AFL	1137		TSN 0				
PROC. REF: AMM 26-10-12								
261184	NO. 2 ENGINE ZONE 2 FIRE DETECTOR							Component ATA:26
PN:3001-133-900/500-6	MOS/MSC	06-Mar-96	O/C					
SN:76703	HRS	0		TSN 0				
WC#: 26.055	AFL	0						
PROC. REF: AMM 26-10-12								
262001	ENGINE FORWARD FIRE EXTINGUISHER							Component ATA:26
PN:33200009	MOS/MSC	10-Jul-15	O/C	TSO 0				
SN:18000C1	HRS	6667.8		TSO 0				
WC#: 26.010	AFL	5769		TSO 0				
PROC. REF: AMM 26-20-12								
262002	ENGINE AFT FIRE EXTINGUISHER							Component ATA:26
PN:33200009	MOS/MSC	10-Jul-15	O/C	TSO 0				
SN:18967C1	HRS	6667.8		TSO 0				
WC#: 26.020	AFL	5769		TSO 0				
PROC. REF: AMM 26-20-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262025	HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER							Service ATA:26
PN:33200009	MOS	07-Jul-15	120		07-Jul-25		399 d	
SN:18000C1	HRS							
WC#: 26.010	AFL							
262026	HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER							Service ATA:26
PN:33200009	MOS	07-Jul-15	120		07-Jul-25		399 d	
SN:18967C1	HRS							
WC#: 26.020	AFL							
262027	FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE							Component ATA:26
PN:30900000M	MOS/MSC	10-Jul-15	O/C	TSN 0				
SN:06967	HRS	6667.8		TSN 0				
WC#: 26.015	AFL	5769		TSN 0				
PROC. REF: GENERIC NO REF								
262028	AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE							Component ATA:26
PN:30900000M	MOS/MSC	10-Jul-15	O/C	TSN 0				
SN:07032	HRS	6667.8		TSN 0				
WC#: 26.025	AFL	5769		TSN 0				
PROC. REF: GENERIC NO REF								
262029	FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE							Component ATA:26
PN:30900000M	MOS/MSC	10-Jul-15	O/C	TSN 0				
SN:06872	HRS	6667.8		TSN 0				
WC#: 26.015	AFL	5769		TSN 0				
PROC. REF: GENERIC NO REF								
262030	AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE							Component ATA:26
PN:30900000M	MOS/MSC	10-Jul-15	O/C	TSN 0				
SN:07011	HRS	6667.8		TSN 0				
WC#: 26.025	AFL	5769		TSN 0				
PROC. REF: GENERIC NO REF								
262037	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	120		07-Jul-25		399 d	LIFE LIMIT
SN:06967	HRS							
WC#: 26.015	AFL							
PROC. REF: AMM 26-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262038	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	120		07-Jul-25		399 d	LIFE LIMIT
SN:07032	HRS							
WC#: 26.025	AFL							
PROC. REF: AMM 26-20-22								
262049	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	120		07-Jul-25		399 d	LIFE LIMIT
SN:06872	HRS							
WC#: 26.015	AFL							
PROC. REF: AMM 26-20-22								
262050	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	120		07-Jul-25		399 d	LIFE LIMIT
SN:07011	HRS							
WC#: 26.025	AFL							
PROC. REF: AMM 26-20-22								
262061	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	180		07-Jul-30		2225 d	LIFE LIMIT
SN:06967	HRS							
WC#: 26.015	AFL							
PROC. REF: AMM 26-20-22								
262062	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	180		07-Jul-30		2225 d	LIFE LIMIT
SN:07032	HRS							
WC#: 26.025	AFL							
PROC. REF: AMM 26-20-22								
262073	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	180		07-Jul-30		2225 d	LIFE LIMIT
SN:06872	HRS							
WC#: 26.015	AFL							
PROC. REF: AMM 26-20-22								
262074	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30900000M	MOS	07-Jul-15	180		07-Jul-30		2225 d	LIFE LIMIT
SN:07011	HRS							
WC#: 26.025	AFL							
PROC. REF: AMM 26-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262091	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C-352	MOS/MSC	12-Dec-15	O/C	TSN 0				
SN:B-10810827	HRS	6821.6		TSN 0				
WC#: 26.075	AFL	5853		TSN 0				
262103	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C-352	MOS	12-Dec-15	144		12-Dec-27		1287 d	
SN:B-10810827	HRS							
WC#: 26.075	AFL							
262109	COCKPIT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C-352	MOS/MSC	12-Dec-15	O/C	TSN 0				
SN:B-10810797	HRS	6821.6		TSN 0				
WC#: 26.080	AFL	5853		TSN 0				
262121	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C-352	MOS	12-Dec-15	144		12-Dec-27		1287 d	
SN:B-10810797	HRS	6821.6						
WC#: 26.080	AFL	5853						
262127	APU FIRE EXTINGUISHER							Component ATA:26
PN:4190-1	MOS/MSC	02-Apr-21	O/C	TSO 0				
SN:1072	HRS	8048		TSO 0				
WC#: 26.085	AFL	6611		TSO 0				
PROC. REF: AMM 26-20-54, AMM 49-61-20, MMA 26-16-00								
262139	HYDROSTATIC TEST APU FIRE EXTINGUISHER							Service ATA:26
PN:4190-1	MOS	31-Mar-21	60		31-Mar-26		666 d	
SN:1072	HRS							
WC#: 26.085	AFL							
262143	APU FORWARD CARTRIDGE							Component ATA:26
PN:30900000M	MOS/MSC	11-Jan-23	O/C	TSN 1				
SN:3792CH	HRS	8299.1		TSN 0				
WC#: 26.060	AFL	6753		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262145	REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE)							Service ATA:26
PN:30900000M	MOS	11-Jan-23	120		11-Jan-33		3144 d	LIFE LIMIT
SN:3792CH	HRS							
WC#: 26.060	AFL							
PROC. REF: CMM 26-20-02								
262157	REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:30900000M	MOS	14-Dec-22	180		14-Dec-37		4942 d	LIFE LIMIT
SN:3792CH	HRS							
WC#: 26.060	AFL							
PROC. REF: AMM 26-20-54, CMM 26-20-02								
262190	FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED							Component ATA:26
PN:A1003(1)	MOS/MSC	11-Jan-23	O/C	TSN 9				
SN:UNKNOWN	HRS	8299.1		TSN 0				
WC#: 26.100	AFL	6753		TSN 0				
PROC. REF: GENERIC NO REF								
262195	AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED							Component ATA:26
PN:A1003(1)	MOS/MSC	11-Jan-23	O/C	TSN 9				
SN:UNKNOWN	HRS	8299.1		TSN 0				
WC#: 26.105	AFL	6753		TSN 0				
PROC. REF: GENERIC NO REF								
262199	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT)							Service ATA:26
PN:A1003(1)	MOS	29-Apr-22	48		29-Apr-26		695 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.100	AFL							
PROC. REF: AMM 26-20-41								
262200	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT)							Service ATA:26
PN:A1003(1)	MOS	29-Apr-22	48		29-Apr-26		695 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.105	AFL							
PROC. REF: AMM 26-20-41								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262201	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE)							Service ATA:26
PN:A1003(1)	MOS	11-Jan-23	36		11-Jan-26		587 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.100	AFL							
PROC. REF: AMM 26-20-41								
262202	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE)							Service ATA:26
PN:A1003(1)	MOS	11-Jan-23	36		11-Jan-26		587 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.105	AFL							
PROC. REF: AMM 26-20-41								
262301	SMOKE DETECTOR AMPLIFIER							Component ATA:26
PN:30326-7	MOS/MSC	06-May-96	O/C					
SN:1776	HRS	22		TSN 0				
WC#: 26.070	AFL	11						
262307	FORWARD BAGGAGE COMPARTMENT SMOKE DETECTOR							Component ATA:26
PN:30231-3	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.110	AFL	0						
PROC. REF: AMM 26-10-51, MMA 26-11-00								
262308	AFT BAGGAGE COMPARTMENT SMOKE DETECTOR							Component ATA:26
PN:30231-3	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.110	AFL	0						
PROC. REF: AMM 26-10-51, MMA 26-11-00								
262309	VANITY SMOKE DETECTOR							Component ATA:26
PN:473054	MOS/MSC	03-Sep-99	O/C	TSN 0				
SN:1171	HRS	2078		TSN 0				
WC#: 26.110	AFL	1818		TSN 0				
PROC. REF: MMA 26-11-00								
ATA 27 - FLIGHT CONTROLS								
270001	OPERATIONAL TEST AIRBRAKE SELECTOR LEVER BAULK							Service ATA:27
	MOS/MSC		N/R					
	HRS							
WC#: 27.265	AFL							
PROC. REF: AMS 5-20-08, AMM 27-61-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270002 ^S	INSPECT LEFT WING FLAP VANE INNER							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.490	AFL	6753						
								PKG:3
270003 ^S	INSPECT LEFT WING FLAP SCREWJACKS SCREW THREADS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.495	AFL	6498						
								PKG:2
270004 ^S	FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.120	AFL	6498						
PROC. REF: AMM 27-33-00								PKG:2
270008 ^S	FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.060	AFL	6498						
PROC. REF: AMM 27-20-00								PKG:2
270009 ^S	FUNCTIONAL TEST STALL DETECTOR UNIT (THIRD CHANNEL)							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.110	AFL	6498						
PROC. REF: AMM 27-33-14								PKG:2
270011 ^S	INSPECT GUST LOCKS/AILERONS AND ELEVATORS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.415	AFL	6498						
								PKG:2
270012 ^S	CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.450	AFL	6498						
PROC. REF: AMM 27-20-00								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270013 ^S	CHECK AND INSPECT ELEVATORS AND TRIM TABS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.485	AFL	6498						
				PROC. REF: AMM 27-30-00				PKG:2
270014 ^S	INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.420	AFL	6498						
								PKG:2
270015 ^S	OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.425	AFL	6498						
								PKG:2
270016 ^S	CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.435	AFL	6498						
								PKG:2
270017 ^S	CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.500	AFL	6498						
				PROC. REF: AMM 27-50-141				PKG:2
270018 ^S	INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.550	AFL	6498						
								PKG:2
270019 ^S	CHECK FLAP CONTROL UNIT							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.525	AFL	6498						
				PROC. REF: AMM 27-50-02				PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270020 ^S	OPERATE FLAP CONTROL UNIT							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.520	AFL	6498						
								PKG:2
270021 ^S	INSPECT LEFT FLAP DRIVE SHAFTS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.510	AFL	6498						
								PKG:2
270022 ^S	OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.425	AFL	6498						
								PKG:2
270023 ^S	CHECK AND INSPECT RIGHT AILERON SERVO TABS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.435	AFL	6498						
								PKG:2
270024 ^S	CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.500	AFL	6498						
PROC. REF: AMM 27-50-141								PKG:2
270025 ^S	INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.550	AFL	6498						
								PKG:2
270026 ^S	INSPECT RIGHT FLAP DRIVE SHAFTS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.510	AFL	6498						
								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270027 ^S	FUNCTIONAL TEST FLAP CONTROL SYSTEM							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.200	AFL	6498						
				PROC. REF: AMM 27-50-02				PKG:2,18
270028 ^S	FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.260	AFL	6498						
				PROC. REF: AMM 27-61-02				PKG:2,18
270030 ^S	CHECK ELEVATOR TRIM SERVO							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.095	AFL	6753						
								PKG:3
270032 ^S	CHECK AILERON AUTOPILOT SERVO CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.440	AFL	6753						
				PROC. REF: AMM 27-00-00				PKG:3
270033 ^S	INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.100	AFL	6753						
								PKG:3
270034 ^S	CHECK ELEVATOR PRIMARY CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.460	AFL	6753						
				PROC. REF: AMM 27-30-00				PKG:3
270035 ^S	CHECK FLAP CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.540	AFL	6753						
				PROC. REF: AMM 27-50-02				PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270036 ^S	CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.465	AFL	6753						
PROC. REF: AMM 27-30-00							PKG:3	
270037 ^S	CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.455	AFL	6753						
PROC. REF: AMM 27-20-00							PKG:3	
270038 ^S	CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.475	AFL	6753						
PROC. REF: AMM NO REF-1							PKG:3	
270039 ^S	CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.445	AFL	6753						
PROC. REF: AMM NO REF-1							PKG:3	
270040 ^S	CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.480	AFL	6753						
PROC. REF: AMM 27-30-00							PKG:3	
270041 ^S	INSPECT ELEVATOR TRIM CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.470	AFL	6753						
PROC. REF: AMM 27-30-00							PKG:3	
270042 ^S	CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.430	AFL	6753						
							PKG:3	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270043 ^S	INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.565	AFL	6753						
								PKG:3
270044 ^S	CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.535	AFL	6753						
								PKG:3
270045 ^S	CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.515	AFL	6753						
PROC. REF: AMM 27-50-02								PKG:3
270046 ^S	CHECK FLAP/AIRBRAKE BAULK BOBBIN							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.575	AFL	6753						
PROC. REF: AMM 27-50-02								PKG:3
270047 ^S	CHECK FLAP SPRING DRUM PULLEY-LEVER							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.555	AFL	6753						
								PKG:3
270048 ^S	CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.505	AFL	6753						
PROC. REF: AMM 27-50-141								PKG:3
270049 ^S	CHECK LEFT FLAP SYNCHRONIZING SYSTEM							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.530	AFL	6753						
PROC. REF: AMM 27-50-02								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270050 ^S	CHECK LEFT AIRBRAKE CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.570	AFL	6753						
PROC. REF: AMM 27-61-02							PKG:3	
270051 ^S	CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.430	AFL	6753						
							PKG:3	
270052 ^S	INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.565	AFL	6753						
							PKG:3	
270053 ^S	CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.535	AFL	6753						
							PKG:3	
270054 ^S	CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.505	AFL	6753						
PROC. REF: AMM 27-50-141							PKG:3	
270055 ^S	CHECK RIGHT FLAP SYNCHRONIZING SYSTEM							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.530	AFL	6753						
PROC. REF: AMM 27-50-02							PKG:3	
270056 ^S	CHECK RIGHT AIRBRAKE CONTROL CABLES							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.570	AFL	6753						
PROC. REF: AMM 27-61-02							PKG:3	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270057 ^S	CHECK FLAP CONTROL FORWARD SPRING STRUT							Service ATA:27
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 27.560	AFL	5769						
PROC. REF: AMM 27-50-02							PKG:4	
270058 ^S	CHECK FLAP CONTROL INPUT-CIRCUIT							Service ATA:27
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 27.210	AFL	5769						
PROC. REF: AMM 27-50-02							PKG:4	
270059 ^S	INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD							Service ATA:27
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 27.545	AFL	6799						
							PKG:5	
270060 ^S	REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER							Service ATA:27
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 27.215	AFL	5769						
PROC. REF: AMM NO REF-1							PKG:4	
270061	CHECK FLIGHT CONTROL CABLES TENSION							Service ATA:27
	MOS/MSC	18-Feb-97	O/C					
	HRS	285						
WC#: 27.010	AFL	251						
PROC. REF: AMM 27-10-00								
270064 ^S	INSPECT RIGHT WING FLAP VANE INNER							Service ATA:27
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 27.490	AFL	6753						
							PKG:3	
270065 ^S	INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.495	AFL	6498						
							PKG:2	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270066 ^S	INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.600	AFL	6498						
								PKG:2
270067 ^S	INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS							Service ATA:27
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 27.605	AFL	6498						
								PKG:2
270071 ^S	INSPECT RUDDER TRIM JACK							Service ATA:27
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
	AFL	6498						
PROC. REF: AMM 27-20-111								PKG:7
270072 ^S	INSPECT ELEVATOR TRIM JACK							Service ATA:27
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
	AFL	6498						
PROC. REF: AMM 27-30-51								PKG:7
270100	LEFT CONTROL COLUMN							Component ATA:27
PN:25-8CF53-217	MOS/MSC	06-Mar-96	O/C					
SN:PPLS/DH/1035	HRS	0		TSN 0				
WC#: 27.015	AFL	0						
PROC. REF: AMM 27-10-11								
270102	RIGHT CONTROL COLUMN							Component ATA:27
PN:25-8CF55-215	MOS/MSC	06-Mar-96	O/C					
SN:PPLS/DH/1054	HRS	0		TSN 0				
WC#: 27.015	AFL	0						
PROC. REF: AMM 27-10-11								
271001	LEFT AILERON							Component ATA:27
PN:25-9WG1-111A	MOS/MSC	06-Mar-96	O/C					
SN:DHB539	HRS	0		TSN 0				
WC#: 27.020	AFL	0						
PROC. REF: AMM 27-10-31								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271002	RIGHT AILERON							Component ATA:27
PN:25-9WG1-112A	MOS/MSC	06-Mar-96	O/C					
SN:DHB538	HRS	0		TSN 0				
WC#: 27.020	AFL	0						
PROC. REF: AMM 27-10-31								
271025	AILERON TRIM SCREWJACK							Component ATA:27
PN:25.8CW49/39A	MOS/MSC	06-Mar-96	O/C					
SN:CH/HG/352	HRS	0		TSN 0				
WC#: 27.025	AFL	0						
PROC. REF: AMM 27-10-71								
272001	RUDDER							Component ATA:27
PN:25.TR235A/L	MOS/MSC	06-Mar-96	O/C					
SN:FL/DHB/8296	HRS	0		TSN 0				
WC#: 27.045	AFL	0						
PROC. REF: AMM 27-20-23								
272019	RUDDER TRIM JACK							Component ATA:27
PN:25.CW573G	MOS/MSC	06-Mar-96	O/C					
SN:6328	HRS	0		TSN 0				
WC#: 27.050	AFL	0						
PROC. REF: AMM 27-20-111								
272020	RUDDER GEARED TAB							Component ATA:27
PN:25TR209A/F	MOS/MSC	06-Mar-96	O/C					
SN:8298	HRS	0		TSN 0				
WC#: 27.125	AFL	0						
PROC. REF: GENERIC NO REF								
272021	RUDDER TRIM TAB							Component ATA:27
PN:25TR221A/F	MOS/MSC	06-Mar-96	O/C					
SN:8287	HRS	0		TSN 0				
WC#: 27.285	AFL	0						
PROC. REF: GENERIC NO REF								
272022	LEFT RUDDER PEDAL ASSEMBLY							Component ATA:27
PN:25-CF1365A/G	MOS/MSC	06-Mar-96	O/C					
SN:CMLDHB949	HRS	0		TSN 0				
WC#: 27.065	AFL	0						
PROC. REF: AMM 27-20-35								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272023	RIGHT RUDDER PEDAL ASSEMBLY							Component ATA:27
PN:25-CF1366A/G	MOS/MSC	06-Mar-96	O/C					
SN:CMLDHB950	HRS	0		TSN 0				
WC#: 27.065	AFL	0						
PROC. REF: AMM 27-20-35								
272049	LEFT RUDDER BIAS STRUT							Component ATA:27
PN:ACA1218	MOS/MSC	06-Mar-96	O/C					
SN:3FN189	HRS	0		TSN 0				
WC#: 27.055	AFL	0						
PROC. REF: AMM 27-20-51								
272050	RIGHT RUDDER BIAS STRUT							Component ATA:27
PN:ACA1218	MOS/MSC	06-Mar-96	O/C					
SN:3AH191	HRS	0		TSN 0				
WC#: 27.055	AFL	0						
PROC. REF: AMM 27-20-51								
272066	LEFT RUDDER BIAS STRUT HEATER MUFF							Component ATA:27
PN:XC5732	MOS/MSC	06-Mar-96	O/C					
SN:642	HRS	0		TSN 0				
WC#: 27.060	AFL	0						
PROC. REF: GENERIC NO REF								
272067	RIGHT RUDDER BIAS STRUT HEATER MUFF							Component ATA:27
PN:XC5732	MOS/MSC	06-Mar-96	O/C					
SN:647	HRS	0		TSN 0				
WC#: 27.061	AFL	0						
PROC. REF: GENERIC NO REF								
272103	LEFT RUDDER BIAS PRESSURE SWITCH							Component ATA:27
PN:HTE.690011	MOS/MSC	06-Mar-96	O/C					
SN:FRTR063	HRS	0		TSN 0				
WC#: 27.290	AFL	0						
PROC. REF: GENERIC NO REF								
272105	RIGHT RUDDER BIAS PRESSURE SWITCH							Component ATA:27
PN:HTE.690011	MOS/MSC	06-Mar-96	O/C					
SN:FRTR050	HRS	0		TSN 0				
WC#: 27.290	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273001	LEFT ELEVATOR							Component ATA:27
PN:258TE1-1A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/355	HRS	0		TSN 0				
WC#: 27.070	AFL	0						
PROC. REF: AMM 27-30-22								
273002	RIGHT ELEVATOR							Component ATA:27
PN:258TE1-2A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/354	HRS	0		TSN 0				
WC#: 27.070	AFL	0						
PROC. REF: AMM 27-30-22								
273021	ELEVATOR TRIM SERVOMOTOR (OVERHAUL)							Component ATA:27
PN:622-3260-001	MOS	17-Nov-23		TSO 0				OVERHAUL
SN:152	HRS	8393.1	3500	TSO 0	11893.1		3452.2	
WC#: 27.085	AFL	6799		TSO 0				
PROC. REF: AMM 27-30-61								
273022	ELEVATOR TRIM SERVOMOTOR MOUNT ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.701	AFL	0		TSN 0				
273025	LEFT ELEVATOR TRIM JACK							Component ATA:27
PN:25.8CT29-115A	MOS/MSC	06-Mar-96	O/C					
SN:MEC/DHB/431	HRS	0		TSN 0				
WC#: 27.080	AFL	0						
PROC. REF: AMM 27-30-51								
273026	RIGHT ELEVATOR TRIM JACK							Component ATA:27
PN:25.8CT29-116A	MOS/MSC	06-Mar-96	O/C					
SN:MEC/DHB/429	HRS	0		TSN 0				
WC#: 27.080	AFL	0						
PROC. REF: AMM 27-30-51								
273040	LEFT ELEVATOR TRIM TAB							Component ATA:27
PN:258TE3-1A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/363	HRS	0		TSN 0				
WC#: 27.090	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273041	RIGHT ELEVATOR TRIM TAB							Component ATA:27
PN:25.8TE3-2A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/368	HRS	0		TSN 0				
WC#: 27.090	AFL	0						
PROC. REF: GENERIC NO REF								
273104	LEFT STICK SHAKER							Component ATA:27
PN:B1443/2	MOS/MSC	06-Mar-96	O/C					
SN:8072	HRS	0		TSN 0				
WC#: 27.140	AFL	0						
PROC. REF: AMM 27-33-20								
273105	RIGHT STICK SHAKER							Component ATA:27
PN:B1443/2	MOS/MSC	06-Mar-96	O/C					
SN:8059	HRS	0		TSN 0				
WC#: 27.140	AFL	0						
PROC. REF: AMM 27-33-20								
273110	FORWARD STALL WARNING DETECTOR							Component ATA:27
PN:10201-1	MOS/MSC	06-Mar-96	O/C					
SN:F036	HRS	0		TSN 0				
WC#: 27.145	AFL	0						
PROC. REF: GENERIC NO REF								
273111	AFT STALL WARNING DETECTOR							Component ATA:27
PN:C87706-1	MOS/MSC	06-Mar-96	O/C					
SN:136	HRS	0		TSN 0				
WC#: 27.145	AFL	0						
PROC. REF: GENERIC NO REF								
273115	NO. 1 STALL WARNING VANE							Component ATA:27
PN:1703-12MODA	MOS/MSC	06-Mar-96	O/C					
SN:1574	HRS	0		TSN 0				
WC#: 27.150	AFL	0						
PROC. REF: GENERIC NO REF								
273116	NO. 2 STALL WARNING VANE							Component ATA:27
PN:1703-12MODA	MOS/MSC	06-Mar-96	O/C					
SN:1585	HRS	0		TSN 0				
WC#: 27.150	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273121	THIRD CHANNEL STALL DETECTOR							Component ATA:27
PN:10201-1	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 27.305	AFL	0						
PROC. REF: GENERIC NO REF								
275001	LEFT FLAP							Component ATA:27
PN:25.8WF251-1A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/343	HRS	0		TSN 0				
WC#: 27.155	AFL	0						
PROC. REF: AMM 27-50-151								
275002	RIGHT FLAP							Component ATA:27
PN:25.8WF251-2A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/358	HRS	0		TSN 0				
WC#: 27.155	AFL	0						
PROC. REF: AMM 27-50-151								
275025	LEFT FLAP SCREWJACK AND REDUCTION GEARBOX (OVERHAUL)							Component ATA:27
PN:258CW159A/C	MOS	17-Jun-04		TSO 0				OVERHAUL
SN:MEC/R/DHB/488	HRS	3568		TSO 0				
WC#: 27.160	AFL	3587	4000	TSO 0	7587		760	
PROC. REF: AMM 27-50-141								
275026	RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX (OVERHAUL)							Component ATA:27
PN:25.8CW161A/C	MOS	17-Jun-04		TSO 0				OVERHAUL
SN:MEC/R/DHB/003	HRS	3568		TSO 0				
WC#: 27.160	AFL	3587	4000	TSO 0	7587		760	
PROC. REF: AMM 27-50-141								
275049	LEFT OUTBOARD FLAP VANE							Component ATA:27
PN:25.8WF13-65A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/405	HRS	0		TSN 0				
WC#: 27.165	AFL	0						
PROC. REF: GENERIC NO REF								
275050	RIGHT OUTBOARD FLAP VANE							Component ATA:27
PN:25.8WF13-66A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/388	HRS	0		TSN 0				
WC#: 27.170	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275051	LEFT INBOARD FLAP VANE							Component ATA:27
PN:25-7WF101A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/373	HRS	0		TSN 0				
WC#: 27.165	AFL	0						
PROC. REF: GENERIC NO REF								
275052	RIGHT INBOARD FLAP VANE							Component ATA:27
PN:25-7WF102A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/382	HRS	0		TSN 0				
WC#: 27.170	AFL	0						
PROC. REF: GENERIC NO REF								
275057	LEFT FLAP BEVEL SHAFT ASSEMBLY							Component ATA:27
PN:25.CF2667A/D	MOS/MSC	06-Mar-96	O/C					
SN:MEC/DHB/820	HRS	0		TSN 0				
WC#: 27.175	AFL	0						
PROC. REF: GENERIC NO REF								
275058	RIGHT FLAP BEVEL SHAFT ASSEMBLY							Component ATA:27
PN:25.CF2668A/D	MOS/MSC	06-Mar-96	O/C					
SN:MEC/DHB/817	HRS	0		TSN 0				
WC#: 27.175	AFL	0						
PROC. REF: GENERIC NO REF								
275073	FLAP CONTROL UNIT (OVERHAUL)							Component ATA:27
PN:614MK2	MOS	16-May-16		TSO 0				OVERHAUL
SN:614-M-74	HRS	6937		TSO 0				
WC#: 27.180	AFL	5906	6000	TSO 0	11906		5079	
PROC. REF: AMM 27-50-121								
275074	FLAP DESIGN UNIT ASSEMBLY							Component ATA:27
PN:25-8NW111-1A	MOS/MSC	06-Mar-96	O/C					
SN:BY5488	HRS	0		TSN 0				
WC#: 27.590	AFL	0						
PROC. REF: GENERIC NO REF								
275085	FLAP SYNCHRONIZING SYSTEM RECEIVER (OVERHAUL)							Component ATA:27
PN:CHA617-104	MOS	17-Jun-04		TSO 0				OVERHAUL
SN:N798	HRS	3568		TSO 0				
WC#: 27.185	AFL	3587	4500	TSO 0	8087		1260	
PROC. REF: AMM 27-50-162								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275091	FLAP POSITION INDICATOR							Component ATA:27
PN:2132-01-0011	MOS/MSC	06-Mar-96	O/C					
SN:BG75670	HRS	0		TSN 0				
WC#: 27.190	AFL	0						
PROC. REF: AMM NO REF-1								
275097	FLAP POSITION TRANSMITTER							Component ATA:27
PN:S132-2-21	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.195	AFL	0						
PROC. REF: AMM 27-50-181								
275145	LEFT FLAP INBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-17	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.220	AFL	4994	5000	TSN 0	9994		3167	
275146	RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-9	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.225	AFL	4994	5000	TSN 0	9994		3167	
275147	LEFT FLAP INBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-19	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.220	AFL	4994	5000	TSN 0	9994		3167	
275148	RIGHT FLAP INBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-11	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.225	AFL	4994	5000	TSN 0	9994		3167	
275149	LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-3	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.230	AFL	4994	5000	TSN 0	9994		3167	
275150	RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-13	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.235	AFL	4994	5000	TSN 0	9994		3167	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275151	LEFT FLAP OUTBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-7	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.230	AFL	4994	5000	TSN 0	9994		3167	
275152	RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE (LIFE LIMIT)							Component ATA:27
PN:25CF3225-15	MOS	03-May-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	5599.6		TSN 0				
WC#: 27.235	AFL	4994	5000	TSN 0	9994		3167	
276001	LEFT UPPER AIRBRAKE							Component ATA:27
PN:25.8WB9-1A	MOS/MSC	06-Mar-96	O/C					
SN:DHB-W-37	HRS	0		TSN 0				
WC#: 27.240	AFL	0						
PROC. REF: AMM 27-61-21								
276002	RIGHT UPPER AIRBRAKE							Component ATA:27
PN:25.8WB9-2A	MOS/MSC	06-Mar-96	O/C					
SN:DHB-W-40	HRS	0		TSN 0				
WC#: 27.245	AFL	0						
PROC. REF: AMM 27-61-21								
276003	LEFT LOWER AIRBRAKE							Component ATA:27
PN:25.7WB1A/B	MOS/MSC	06-Mar-96	O/C					
SN:35771-000	HRS	0		TSN 0				
WC#: 27.240	AFL	0						
PROC. REF: AMM 27-61-21								
276004	RIGHT LOWER AIRBRAKE							Component ATA:27
PN:25.7WB2A/B	MOS/MSC	06-Mar-96	O/C					
SN:38380-000	HRS	0		TSN 0				
WC#: 27.245	AFL	0						
PROC. REF: AMM 27-61-21								
276039	LEFT AIRBRAKE JACK ASSEMBLY							Component ATA:27
PN:AIR46520-2	MOS	01-Nov-12						OVERHAUL
SN:APB961331	HRS	5784	3000	TSO 0	8784		343.1	
WC#: 27.250	AFL							
PROC. REF: AMM 27-61-31								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276040	RIGHT AIRBRAKE JACK ASSEMBLY							Component ATA:27
PN:AIR46521-2	MOS	23-May-18		TSO 0				OVERHAUL
SN:LK0627	HRS	7503.4	3000	TSO 0	10503.4		2062.5	
WC#: 27.255	AFL	6246		TSO 0				
PROC. REF: AMM 27-61-31								
276051	LEFT AIRBRAKE JACK BODY (LIFE LIMIT)							Component ATA:27
PN:AIR111462	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.250	AFL	0	25000	TSN 0	25000		18173	
PROC. REF: AMM 27-61-31								
276052	RIGHT AIRBRAKE JACK BODY (LIFE LIMIT)							Component ATA:27
PN:AIR111463	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.255	AFL	0	25000	TSN 0	25000		18173	
PROC. REF: AMM 27-61-31								
276063	LEFT AIRBRAKE JACK EYE END							Component ATA:27
PN:AIR150338	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.250	AFL	0		TSN 0				
PROC. REF: AMM 27-61-31								
276064	RIGHT AIRBRAKE JACK EYE END							Component ATA:27
PN:AIR150339	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.255	AFL	0		TSN 0				
PROC. REF: AMM 27-61-31								
ATA 28 - FUEL								
280001 ^S	FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS							Service ATA:28
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 28.075	AFL	6498						
PKG:2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280002 ^S	CHECK FUEL VALVE CONTROL CABLES							Service ATA:28
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 28.010	AFL	6753						
								PKG:3
280003 ^S	FUNCTIONAL TEST LP VALVES							Service ATA:28
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 28.050	AFL	5769						
PROC. REF: AMM 28-20-00								PKG:4
280004 ^S	INSPECT/CLEAN OR REPLACE APU FUEL INLET FILTER ELEMENT (IF FITTED)							Service ATA:28
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 28.085	AFL	5769						
PROC. REF: AMM 28-10-00								PKG:4
280005 ^S	VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS							Service ATA:28
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 28.165	AFL	6753						
								PKG:3
280006 ^S	VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS							Service ATA:28
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 28.170	AFL	6753						
								PKG:3
280007 ^S	VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS							Service ATA:28
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 28.165	AFL	6753						
								PKG:3
280008 ^S	VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS							Service ATA:28
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 28.170	AFL	6753						
								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280010	CHECK CABLE TENSION OF FUEL CONTROL VALVES							Service ATA:28
	MOS/MSC	06-Mar-96	O/C					
	HRS	0						
WC#: 28.020	AFL	0						
PROC. REF: AMM 28-20-83								
280016 ^S	VISUAL INSPECTION LOW PRESSURE FUEL VALVE SUPPORT STRUT. PART NO. 25 PF361, 25 PF361-5A (MOD. 25G310A) AND 25 PF363							Service ATA:28
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 28.195	AFL	6498						
PKG:7								
281067	VENTRAL FUEL TANK							Component ATA:28
PN:25-8PT463.1A	MOS/MSC	06-Mar-96	O/C					
SN:SD/DH/103	HRS	0		TSN 0				
WC#: 28.015	AFL	0						
PROC. REF: AMM 28-10-15								
282001	LEFT WING HIGH LEVEL FLOAT SWITCH							Component ATA:28
PN:3515000/107	MOS/MSC	06-Mar-96	O/C					
SN:FRTR465AS	HRS	0		TSN 0				
WC#: 28.025	AFL	0						
PROC. REF: AMM 28-22-143								
282002	RIGHT WING HIGH LEVEL FLOAT SWITCH							Component ATA:28
PN:3515000/107	MOS/MSC	06-Mar-96	O/C					
SN:FRTR470AS	HRS	0		TSN 0				
WC#: 28.025	AFL	0						
PROC. REF: AMM 28-22-143								
282004	LOW PRESSURE FUEL COCK VALVE							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.191	AFL	0		TSN 0				
282005	LEFT FUEL COCK							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282006	RIGHT FUEL COCK							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282007	LEFT FUEL ACTUATOR							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.185	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282008	RIGHT FUEL ACTUATOR							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.185	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282009	LEFT FUEL NON-RETURN VALVE							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28-20-32								
282010	RIGHT FUEL NON-RETURN VALVE							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28-20-32								
282011	LEFT FUEL NON-RETURN VALVE							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.192	AFL	0		TSN 0				
PROC. REF: AMM 28-20-32								
282012	RIGHT FUEL NON-RETURN VALVE							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.193	AFL	0		TSN 0				
PROC. REF: AMM 28-20-32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282025	APU FUEL PRESSURE SWITCH							Component ATA:28
PN:TP30093	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.030	AFL							
	APH	0						
	APS	0						
PROC. REF: AMM 28-22-91								
282053	LEFT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE							Component ATA:28
PN:AWE124-13	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.035	AFL	0						
PROC. REF: AMM 28-20-32								
282054	RIGHT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE							Component ATA:28
PN:AWE124-13	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.035	AFL	0						
PROC. REF: AMM 28-20-32								
282253	LEFT HAND LP FUEL VALVE							Component ATA:28
PN:HTE1984P	MOS/MSC	06-Mar-96	O/C					
SN:M162VB695	HRS	0		TSN 0				
WC#: 28.045	AFL	0						
282254	RIGHT HAND LP FUEL VALVE							Component ATA:28
PN:HTE1984	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.045	AFL	0						
282289	FUEL 3C VALVE							Component ATA:28
PN:HTE1984X	MOS/MSC	06-Mar-96	O/C					
SN:M167VB695	HRS	0		TSN 0				
WC#: 28.055	AFL	0						
PROC. REF: AMM 28-20-61								
282295	FUEL 4S VALVE							Component ATA:28
PN:HTE1984S	MOS/MSC	06-Mar-96	O/C					
SN:M164VB695	HRS	0		TSN 0				
WC#: 28.060	AFL	0						
PROC. REF: AMM 28-20-61								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282301	VENTRAL TANK FUEL TRANSFER VALVE							Component ATA:28
PN:HTE1984F	MOS/MSC	06-Mar-96	O/C					
SN:M161VB695	HRS	0		TSN 0				
WC#: 28.065	AFL	0						
PROC. REF: AMM 28-20-78								
282343	LEFT BOOST PUMP (OVERHAUL)							Component ATA:28
PN:2C40-2	MOS/MSC	24-Oct-18	O/C	TSO 0				OVERHAUL
SN:11AN153	HRS	7636.9		TSO 0				
WC#: 28.080	AFL	6325		TSO 0				
PROC. REF: AMM 28-20-12								
282344	RIGHT BOOST PUMP (OVERHAUL)							Component ATA:28
PN:2C40-2	MOS/MSC	11-Jan-19	O/C	TSO 0				OVERHAUL
SN:8AT100	HRS	7680.3		TSO 0				
WC#: 28.080	AFL	6353		TSO 0				
PROC. REF: AMM 28-20-12								
282384	SINGLE-POINT PRESSURE CONTROL VALVE							Component ATA:28
PN:1159000-1	MOS/MSC	23-Oct-09	O/C	TSO 0				
SN:FR.083BB	HRS	4901.4		TSO 0				
WC#: 28.175	AFL	4564		TSO 0				
PROC. REF: GENERIC NO REF								
284013	LEFT NO. 1 FUEL TANK UNIT							Component ATA:28
PN:0207KTU1	MOS/MSC	06-Mar-96	O/C					
SN:TU951028	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: AMM 28-42-03								
284014	RIGHT NO.1 FUEL TANK UNIT							Component ATA:28
PN:0207KTU1	MOS/MSC	06-Mar-96	O/C					
SN:TU951026	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: AMM 28-42-03								
284015	LEFT NO.2 FUEL TANK UNIT							Component ATA:28
PN:0204KTU2	MOS/MSC	06-Mar-96	O/C					
SN:TU954283	HRS	0		TSN 0				
WC#: 28.105	AFL	0						
PROC. REF: AMM 28-42-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284016	RIGHT NO.2 FUEL TANK UNIT							Component ATA:28
PN:0204KTU2	MOS/MSC	06-Mar-96	O/C					
SN:TU954285	HRS	0		TSN 0				
WC#: 28.105	AFL	0						
PROC. REF: AMM 28-42-03								
284017	LEFT NO.3 FUEL TANK UNIT							Component ATA:28
PN:0207KTU3	MOS/MSC	06-Mar-96	O/C					
SN:TU951071	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: AMM 28-42-03								
284018	RIGHT NO.3 FUEL TANK UNIT							Component ATA:28
PN:0207KTU3	MOS/MSC	06-Mar-96	O/C					
SN:TU951072	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: AMM 28-42-03								
284019	LEFT NO.4 FUEL TANK UNIT							Component ATA:28
PN:0204KTU4	MOS/MSC	06-Mar-96	O/C					
SN:TU952147	HRS	0		TSN 0				
WC#: 28.115	AFL	0						
PROC. REF: AMM 28-42-03								
284020	RIGHT NO.4 FUEL TANK UNIT							Component ATA:28
PN:0204KTU4	MOS/MSC	06-Mar-96	O/C					
SN:TU952145	HRS	0		TSN 0				
WC#: 28.115	AFL	0						
PROC. REF: AMM 28-42-03								
284021	LEFT NO.5 FUEL TANK UNIT							Component ATA:28
PN:0204KTU5	MOS/MSC	06-Mar-96	O/C					
SN:TU942457	HRS	0		TSN 0				
WC#: 28.120	AFL	0						
PROC. REF: AMM 28-42-03								
284022	RIGHT NO.5 FUEL TANK UNIT							Component ATA:28
PN:0204KTU5	MOS/MSC	06-Mar-96	O/C					
SN:TU955815	HRS	0		TSN 0				
WC#: 28.120	AFL	0						
PROC. REF: AMM 28-42-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284023	LEFT NO.6 FUEL TANK UNIT							Component ATA:28
PN:0204KTU6	MOS/MSC	06-Mar-96	O/C					
SN:TU954277	HRS	0		TSN 0				
WC#: 28.125	AFL	0						
PROC. REF: AMM 28-42-03								
284024	RIGHT NO.6 FUEL TANK UNIT							Component ATA:28
PN:0204KTU6	MOS/MSC	06-Mar-96	O/C					
SN:TU954274	HRS	0		TSN 0				
WC#: 28.125	AFL	0						
PROC. REF: AMM 28-42-03								
284025	LEFT NO.7 FUEL TANK CONTENTS UNIT							Component ATA:28
PN:0204KTU7	MOS/MSC	06-Mar-96	O/C					
SN:TU944039	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: AMM 28-42-03								
284026	RIGHT NO.7 FUEL TANK CONTENTS UNIT							Component ATA:28
PN:0204KTU7	MOS/MSC	06-Mar-96	O/C					
SN:TU944047	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: AMM 28-42-03								
284115	LEFT FUEL QUANTITY INDICATOR							Component ATA:28
PN:WL1901KID-1	MOS/MSC	06-Mar-96	O/C					
SN:951213	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: AMM 28-42-03								
284116	RIGHT FUEL QUANTITY INDICATOR							Component ATA:28
PN:WL1901KID-1	MOS/MSC	06-Mar-96	O/C					
SN:951214	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: AMM 28-42-03								
284130	FUEL PRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.194	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284139	VENTRAL TANK LOW LEVEL FLOAT SWITCH							Component ATA:28
PN:3515000/149	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.145	AFL	0						
PROC. REF: AMM 28-20-78								
284145	VENTRAL TANK HIGH LEVEL FLOAT SWITCH							Component ATA:28
PN:3515001-105	MOS/MSC	06-Mar-96	O/C					
SN:190/AP	HRS	0		TSN 0				
WC#: 28.150	AFL	0						
PROC. REF: AMM 28-22-143								
284151	LEFT SURGE TANK FLOAT SWITCH							Component ATA:28
PN:3515000/106	MOS/MSC	06-Mar-96	O/C					
SN:FRTR434AP	HRS	0		TSN 0				
WC#: 28.155	AFL	0						
PROC. REF: AMM 28-44-43								
284152	RIGHT SURGE TANK FLOAT SWITCH							Component ATA:28
PN:3515000/106	MOS/MSC	06-Mar-96	O/C					
SN:FRTR424AP	HRS	0		TSN 0				
WC#: 28.155	AFL	0						
PROC. REF: AMM 28-44-43								
ATA 29 - HYDRAULIC POWER								
290003 ^S	REPLACE HYDRAULIC SUCTION FILTER ELEMENT							Service ATA:29
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 29.070	AFL	6498						
PROC. REF: AMM 29-10-21								
290004 ^S	FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM							Service ATA:29
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 29.075	AFL	6498						
PROC. REF: AMM 29-10-00								
PKG:2								
PKG:2,18								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
290005 ^S	OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM							Service ATA:29
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 29.115	AFL	6498						
				PROC. REF: AMM NO REF-1				PKG:2,18
290006 ^S	DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM							Service ATA:29
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 29.160	AFL	6753						
								PKG:3
290007 ^S	TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING							Service ATA:29
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 29.165	AFL	6753						
								PKG:3
290008 ^S	CHECK EMERGENCY BRAKE SYSTEM LEAK RATE							Service ATA:29
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 29.175	AFL	6753						
				PROC. REF: AMM NO REF-1				PKG:3
290009 ^S	FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM							Service ATA:29
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 29.180	AFL	6498						
				PROC. REF: AMM 29-30-00				PKG:2,18
290010 ^S	FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM							Service ATA:29
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 29.170	AFL	6753						
				PROC. REF: AMM 29-10-13				PKG:3
290011 ^S	CLEAN FULL-FLOW RELIEF VALVE							Service ATA:29
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 29.005	AFL	5769						
				PROC. REF: AMM 29-10-71				PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
290012 ^S INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM								
	MOS	10-Jul-15						Service ATA:29
	HRS	6667.8	3200 (+150/-50)					
WC#: 29.145	AFL	5769						
PROC. REF: AMM 29-30-00								
PKG:4								
291018 PRESSURE REGULATOR VALVE								
PN:PAS129-163	MOS/MSC	06-Mar-96	O/C					Component ATA:29
SN:RG724	HRS	0		TSN 0				
WC#: 29.010	AFL	0						
PROC. REF: GENERIC NO REF								
291025 NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE								
PN:AIR87240/0	MOS/MSC	06-Mar-96	O/C					Component ATA:29
SN:APB951053	HRS	0		TSN 0				
WC#: 29.015	AFL	0						
PROC. REF: GENERIC NO REF								
291026 NO. 2 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE								
PN:AIR87240/0	MOS/MSC	06-Mar-96	O/C					Component ATA:29
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.015	AFL	0						
PROC. REF: GENERIC NO REF								
291037 LEFT HYDRAULIC SUCTION VALVE								
PN:7907015E	MOS/MSC	06-Mar-96	O/C					Component ATA:29
SN:FRTR014/AS	HRS	0		TSN 0				
WC#: 29.020	AFL	0						
PROC. REF: AMM 29-10-31								
291038 RIGHT HYDRAULIC SUCTION VALVE								
PN:7907015E	MOS/MSC	06-Mar-96	O/C					Component ATA:29
SN:FRTR016/AS	HRS	0		TSN 0				
WC#: 29.020	AFL	0						
PROC. REF: AMM 29-10-31								
291049 NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE (OVERHAUL)								
PN:AIR45394-0-2	MOS	17-Jun-04		TSO 0				Component ATA:29
SN:LK8806132	HRS	3568		TSO 0				OVERHAUL
WC#: 29.025	AFL	3587	4500	TSO 0	8087		1260	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291050	NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE (OVERHAUL)							Component ATA:29
PN: AIR45394-0-2	MOS	17-Jun-04		TSO 0				OVERHAUL
SN: LK8503105	HRS	3568		TSO 0				
WC#: 29.025	AFL	3587	4500	TSO 0	8087		1260	
291073	PRESSURE MAINTAINING VALVE (OVERHAUL)							Component ATA:29
PN: AIR45474-0	MOS	03-May-12		TSO 0				OVERHAUL
SN: APB000936	HRS	5599.6		TSO 0				
WC#: 29.030	AFL	4994	5000	TSO 0	9994		3167	
291079	GROUND SERVICE HANDPUMP SUPPLY NONRETURN VALVE							Component ATA:29
PN: AIR48026-0-1	MOS/MSC	06-Mar-96	O/C					
SN: APB951118	HRS	0		TSN 0				
WC#: 29.035	AFL	0						
PROC. REF: GENERIC NO REF								
291091	MAIN HYDRAULIC RESERVOIR							Component ATA:29
PN: 25.8HC7/1A	MOS/MSC	06-Mar-96	O/C					
SN: CHO4631	HRS	0		TSN 0				
WC#: 29.040	AFL	0						
PROC. REF: AMM 29-10-13								
291096	HYDRAULIC PRESSURE GAUGE							Component ATA:29
PN: 18293201-1	MOS/MSC	06-Mar-96	O/C					
SN: 34105D	HRS	0		TSN 0				
WC#: 29.045	AFL	0						
PROC. REF: GENERIC NO REF								
291103	MAIN HYDRAULIC ACCUMULATOR							Component ATA:29
PN: AIR45574-3-4	MOS/MSC	06-Mar-96	O/C					
SN: APB951940	HRS	0		TSN 0				
WC#: 29.050	AFL	0						
PROC. REF: AMM 29-10-81								
291109	EMERGENCY BRAKE ACCUMULATOR							Component ATA:29
PN: AIR45574-3-4	MOS/MSC	06-Mar-96	O/C					
SN: APB920667	HRS	0		TSN 0				
WC#: 29.055	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291131	HYDRAULIC FILTER							Component ATA:29
PN:51143	MOS/MSC	09-Mar-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1711		TSN 0				
WC#: 29.060	AFL	1484		TSN 0				
PROC. REF: GENERIC NO REF								
291132	PRESSURE FILTER ASSEMBLY							Component ATA:29
PN:MFHA189A	MOS/MSC	09-Mar-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1711		TSN 0				
WC#: 29.065	AFL	1484		TSN 0				
PROC. REF: AMM 29-10-21								
291163	NO. 1 ENGINE HYDRAULIC PUMP							Component ATA:29
PN:42022-03	MOS/MSC	02-Feb-19	O/C	TSO 5				
SN:AH17897	HRS	7707.2		TSO 100.2				
WC#: 29.080	AFL	6370		TSO 64				
PROC. REF: AMM 29-10-54								
291164	NO. 2 ENGINE HYDRAULIC PUMP							Component ATA:29
PN:42022-03	MOS/MSC	08-Feb-15	O/C	TSO 0				
SN:AY14	HRS	6503.5		TSO 0				
WC#: 29.080	AFL	5695		TSO 0				
PROC. REF: AMM 29-10-54								
291182	GROUND SERVICING HANDPUMP							Component ATA:29
PN:AIR45424-0	MOS/MSC	06-Mar-96	O/C					
SN:APB950799	HRS	0		TSN 0				
WC#: 29.085	AFL	0						
PROC. REF: GENERIC NO REF								
291186	NO. 1 NON-RETURN TANK PRESSURE VALVE							Component ATA:29
PN:HTE4350	MOS/MSC	06-Mar-96	O/C					
SN:M106VNR295	HRS	0		TSN 0				
WC#: 29.090	AFL	0						
PROC. REF: GENERIC NO REF								
291193	NO. 2 NON-RETURN TANK PRESSURE VALVE							Component ATA:29
PN:HTE4350	MOS/MSC	06-Mar-96	O/C					
SN:M110VNR295	HRS	0		TSN 0				
WC#: 29.090	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
292001	EMERGENCY HYDRAULIC TANK							Component ATA:29
PN:25.HC161A/D	MOS/MSC	06-Mar-96	O/C					
SN:CH05943/A	HRS	0		TSN 0				
WC#: 29.095	AFL	0						
PROC. REF: GENERIC NO REF								
292003	SUCTION FILTER ASSEMBLY							Component ATA:29
PN:AIR87366-0	MOS/MSC	06-Mar-96	O/C					
SN:BF95/0105	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: AMM 29-10-21								
292007	EMERGENCY HYDRAULIC HAND PUMP							Component ATA:29
PN:AIR45448	MOS/MSC	06-Mar-96	O/C					
SN:APB95079	HRS	0		TSN 0				
WC#: 29.105	AFL	0						
PROC. REF: GENERIC NO REF								
292013	AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH							Component ATA:29
PN:3515000/76	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.110	AFL	0						
PROC. REF: AMM 29-30-00								
292031	EMERGENCY TANK ON/OFF HAND PUMP VALVE							Component ATA:29
PN:AIR45446-1-2	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.120	AFL	0						
PROC. REF: GENERIC NO REF								
292037	EMERGENCY SYSTEM CHECK VALVE							Component ATA:29
PN:AIR48026-0-1	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.125	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
293001	NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH							Component ATA:29
PN:15185/4SN1	MOS/MSC	06-Mar-96	O/C					
SN:2748	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293002	NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH							Component ATA:29
PN:15185/4SN1	MOS/MSC	06-Mar-96	O/C					
SN:2756	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: GENERIC NO REF								
293013	EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH (OVERHAUL)							Component ATA:29
PN:TP42001	MOS	21-Dec-09		TSO 0				OVERHAUL
SN:1626	HRS	4961.5	5000	TSO 0	9961.5		1520.6	
WC#: 29.135	AFL	4598		TSO 0				
293019	HYDRAULIC PRESSURE TRANSDUCER							Component ATA:29
PN:695-4-20	MOS/MSC	06-Mar-96	O/C					
SN:BY6175	HRS	0		TSN 0				
WC#: 29.140	AFL	0						
PROC. REF: GENERIC NO REF								
293024	HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH							Component ATA:29
PN:150T283	MOS/MSC	06-Mar-96	O/C					
SN:949	HRS	0		TSN 0				
WC#: 29.145	AFL	0						
PROC. REF: AMM 29-30-00								
294001	LEFT HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.183	AFL	0		TSN 0				
294002	RIGHT HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.184	AFL	0		TSN 0				
294003	NO. 1 HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.186	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
294004	NO. 2 HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.187	AFL	0		TSN 0				
294005	HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.188	AFL	0		TSN 0				
294006	HYDRAULIC RELIEF VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.189	AFL	0		TSN 0				
294007	LEFT HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.190	AFL	0		TSN 0				
PROC. REF: AMM 29-10-68								
294008	RIGHT HYDRAULIC NON-RETURN VALVE							Component ATA:29
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.191	AFL	0		TSN 0				
ATA 30 - ICE AND RAIN PROTECTION								
300001 ^S	FUNCTIONAL TEST ROTARY ICE DETECTOR							Service ATA:30
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 30.085	AFL	6498						
PROC. REF: AMM 30-80-00								PKG:2
300002 ^S	OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM							Service ATA:30
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 30.080	AFL	6753						
PROC. REF: AMM 30-41-00								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300003 ^S	REPLACE AIRFRAME DE-ICING FILTER ELEMENT							Service ATA:30
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 30.020	AFL	6498						
				PROC. REF: AMM 30-10-52				PKG:2
300004 ^S	FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS							Service ATA:30
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 30.065	AFL	6753						
				PROC. REF: AMM 30-35-15				PKG:3
300005 ^S	REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER							Service ATA:30
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 30.045	AFL	6753						
				PROC. REF: AMM 30-10-43				PKG:3
300007	PURGE ICE PROTECTION SYSTEM							Service ATA:30
	MOS/MSC	18-Dec-16	A/R					
	HRS	7107.6						
WC#: 30.090	AFL	5996						
				PROC. REF: AMM 12-30-00				
301001	TKS DE-ICER TANK							Component ATA:30
PN:08301-01	MOS/MSC	06-May-96	O/C					
SN:AST96A336	HRS	22						
WC#: 30.010	AFL	11						
				PROC. REF: AMM 30-10-35				
301007	AIRFRAME DE-ICING PUMP ASSEMBLY							Component ATA:30
PN:XA9511E009	MOS/MSC	28-Feb-97	O/C	TSN 0				
SN:AST91D267	HRS	316		TSN 0				
WC#: 30.015	AFL	285		TSN 0				
				PROC. REF: AMM 30-10-43				
301013	AIRFRAME DE-ICING FILTER ASSEMBLY							Component ATA:30
PN:F903	MOS/MSC	25-Mar-97	O/C	TSN 0				
SN:D148010	HRS	361		TSN 0				
WC#: 30.020	AFL	312		TSN 0				
				PROC. REF: AMM 30-10-52				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301025	DE-ICING VALVE ASSEMBLY							Component ATA:30
PN:FV131-1	MOS/MSC	24-Jul-97	O/C	TSN 0				
SN:AST968225	HRS	542		TSN 0				
WC#: 30.025	AFL	486		TSN 0				
PROC. REF: AMM 30-10-43								
301037	DE-ICING SYSTEM CONTENTS GAUGE							Component ATA:30
PN:S458-3-191	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:BG74836	HRS	0		TSN 0				
WC#: 30.030	AFL	0						
PROC. REF: GENERIC NO REF								
301043	DE-ICING SYSTEM CONTENTS FLOAT							Component ATA:30
PN:FRH070001	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:FR028AS	HRS	0		TSN 0				
WC#: 30.035	AFL	0						
PROC. REF: GENERIC NO REF								
301063	EMPENNAGE TKS PROPORTION UNIT							Component ATA:30
PN:PU308JT40	MOS/MSC	12-Nov-96	O/C	TSN 0				
SN:C220-86	HRS	72		TSN 0				
WC#: 30.050	AFL	72						
PROC. REF: AMM 30-10-25								
301067	TKS VENT VALVE							Component ATA:30
PN:FV141	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:AST95L231	HRS	0		TSN 0				
WC#: 30.055	AFL	0						
PROC. REF: GENERIC NO REF								
301069	TKS PRESSURE SWITCH							Component ATA:30
PN:P067D075	MOS/MSC	27-Nov-16	O/C	TSN 0				
SN:CAV116H1118	HRS	7101.2		TSN 0				
WC#: 30.060	AFL	5990		TSN 0				
PROC. REF: GENERIC NO REF								
304019	NO. 1 WINDSCREEN (A PANEL) CONTROLLER							Component ATA:30
PN:ND00752011MK22	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:L241968	HRS	0		TSN 0				
WC#: 30.070	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304020	NO. 2 WINDSCREEN (A PANEL) CONTROLLER							Component ATA:30
PN:ND00752011MK22	MOS/MSC	06-Mar-96	O/C					
SN:L243245	HRS	0		TSN 0				
WC#: 30.070	AFL	0						
PROC. REF: GENERIC NO REF								
304022	NO. 1 WINDSCREEN (B PANEL) CONTROLLER							Component ATA:30
PN:ND00752001MK20	MOS/MSC	06-Mar-96	O/C					
SN:L243595	HRS	0		TSN 0				
WC#: 30.075	AFL	0						
PROC. REF: GENERIC NO REF								
304023	NO. 2 WINDSCREEN (B PANEL) CONTROLLER							Component ATA:30
PN:ND00752001MK20	MOS/MSC	06-Mar-96	O/C					
SN:L243547	HRS	0		TSN 0				
WC#: 30.075	AFL	0						
PROC. REF: GENERIC NO REF								
308001	ROTARY ICE DETECTOR							Component ATA:30
PN:NF0075-667	MOS/MSC	16-Nov-01	O/C					
SN:L245389	HRS	2477						
WC#: 30.085	AFL	2241						
PROC. REF: AMM NO REF-1								
ATA 31 - INDICATING/RECORDING SYSTEMS								
310002	LIGHTNING SENSOR ANTENNA							Component ATA:31
PN:4057697-901	MOS/MSC	15-Oct-16	O/C	TSN 0				
SN:16052671	HRS	7057.2		TSN 0				
WC#: 31.015	AFL	5965		TSN 0				
PROC. REF: AMM 34-42-05								
310100	LIGHTNING PROCESSOR UNIT							Component ATA:31
PN:7011822-903	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.010	AFL	0						
PROC. REF: MMA 34-43-05, MMA 34-43-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
311001	TKS TIMER							Component ATA:31
PN:25-7NF1565A	MOS/MSC	06-Mar-96	O/C					
SN:7027	HRS	0		TSN 0				
WC#: 31.020	AFL	0						
PROC. REF: GENERIC NO REF								
312001	PILOT CLOCK							Component ATA:31
PN:MD93	MOS/MSC	02-Mar-18	O/C		TSN 0			
SN:UNKNOWN	HRS	7444.3		TSN 0				
WC#: 31.025	AFL	6205		TSN 0				
PROC. REF: GENERIC NO REF								
312002	COPILOT CLOCK							Component ATA:31
PN:MD93	MOS/MSC	02-Mar-18	O/C		TSN 0			
SN:UNKNOWN	HRS	7444.3		TSN 0				
WC#: 31.025	AFL	6205		TSN 0				
PROC. REF: GENERIC NO REF								
312008	O.A.T. INDICATOR							Component ATA:31
PN:2141-01-0014	MOS/MSC	06-Mar-96	O/C					
SN:BG75199	HRS	0		TSN 0				
WC#: 31.030	AFL	0						
PROC. REF: GENERIC NO REF								
312009	PITOT AMMETER							Component ATA:31
PN:2132-01-0017	MOS/MSC	06-Mar-96	O/C					
SN:BG75100	HRS	0		TSN 0				
WC#: 31.035	AFL	0						
PROC. REF: GENERIC NO REF								
313005	LEFT CURRENT LEVEL INDICATOR							Component ATA:31
PN:770-537	MOS/MSC	06-Mar-96	O/C					
SN:1096	HRS	0		TSN 0				
WC#: 31.040	AFL	0						
PROC. REF: GENERIC NO REF								
313006	RIGHT CURRENT LEVEL INDICATOR							Component ATA:31
PN:770-537	MOS/MSC	06-Mar-96	O/C					
SN:1079	HRS	0		TSN 0				
WC#: 31.040	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313007	CABIN TEMPERATURE INDICATOR							Component ATA:31
PN:2132-01-0015	MOS/MSC	06-Mar-96	O/C					
SN:BG75250	HRS	0		TSN 0				
WC#: 31.045	AFL	0						
PROC. REF: GENERIC NO REF								
313008	DC VOLTMETER							Component ATA:31
PN:2132-01-0012	MOS/MSC	08-Aug-02	O/C					
SN:BG72556	HRS	2771.2						
WC#: 31.050	AFL	2589						
PROC. REF: GENERIC NO REF								
313009	LEFT DC AMMETER							Component ATA:31
PN:2132-01-0013	MOS/MSC	06-Mar-96	O/C					
SN:BG75039	HRS	0		TSN 0				
WC#: 31.055	AFL	0						
PROC. REF: GENERIC NO REF								
313010	AC VOLTMETER							Component ATA:31
PN:2132-01-0014	MOS/MSC	06-Mar-96	O/C					
SN:BG75151	HRS	0		TSN 0				
WC#: 31.060	AFL	0						
PROC. REF: GENERIC NO REF								
313011	RIGHT DC AMMETER							Component ATA:31
PN:2132.1.13	MOS/MSC	22-Oct-01	O/C					
SN:BG78356	HRS	2452.8						
WC#: 31.065	AFL	2202						
PROC. REF: GENERIC NO REF								
313012	FLIGHT DATA ACCELEROMETER							Component ATA:31
PN:17A47102	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 31.120	AFL	0						
313014	DUCT AIR TEMPERATURE INDICATOR							Component ATA:31
PN:2132-01-0018	MOS/MSC	06-Mar-96	O/C					
SN:BG75159	HRS	0		TSN 0				
WC#: 31.070	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313015	TEMPERATURE SELECTOR							Component ATA:31
PN:25-6MC415	MOS/MSC	06-Mar-96	O/C					
SN:104C-869	HRS	0		TSN 0				
WC#: 31.075	AFL	0						
PROC. REF: GENERIC NO REF								
313020	FUEL PROCESSOR UNIT							Component ATA:31
PN:0107KPU-1	MOS/MSC	06-Mar-96	O/C					
SN:951202	HRS	0		TSN 0				
WC#: 31.080	AFL	0						
PROC. REF: GENERIC NO REF								
313101	ANGLE OF ATTACK INDICATOR COMPUTER							Component ATA:31
PN:C-82-305-4	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.095	AFL	0						
PROC. REF: AMM 31-20-05, MMA 31-20-06								
313109	NO. 1 ANGLE OF ATTACK INDEXER							Component ATA:31
PN:965-0118-008	MOS/MSC	06-May-96	O/C					
SN:1512	HRS	22		TSN 0				
WC#: 31.100	AFL	11						
PROC. REF: AMM 31-20-05, MMA 31-20-06								
313110	NO. 2 ANGLE OF ATTACK INDEXER							Component ATA:31
PN:965-0118-008	MOS/MSC	06-May-96	O/C					
SN:1510	HRS	22		TSN 0				
WC#: 31.100	AFL	11						
PROC. REF: AMM 31-20-05, MMA 31-20-06								
313201	BRAKE PRESSURE INDICATOR							Component ATA:31
PN:696-01-0013	MOS/MSC	06-Mar-96	O/C					
SN:BG75121	HRS	0		TSN 0				
WC#: 31.105	AFL	0						
PROC. REF: GENERIC NO REF								
314008	NO. 1 INCLINOMETER							Component ATA:31
PN:7005400-901	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.115	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314009	NO. 2 INCLINOMETER							Component ATA:31
PN:7005400-901	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.115	AFL	0						
PROC. REF: GENERIC NO REF								
319000 ^U	REPLACE PILOT/COPILOT MD93 CLOCK BATTERIES							Service ATA:31
	MOS	02-Apr-21	48		02-Apr-25		303 d	
	HRS	8048						
	AFL	6611						
ATA 32 - LANDING GEAR								
320001 ^S	TEST BRAKING SYSTEMS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.305	AFL	6498						
PROC. REF: AMM 32-40-00								
320002 ^S	FUNCTIONAL TEST MAXARET UNITS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.370	AFL	6498						
PROC. REF: AMM 32-40-101								
320003 ^S	CHECK NOSE GEAR LEG ASSEMBLY							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.430	AFL	6498						
PKG:2,18								
320004 ^S	CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.435	AFL	6498						
PKG:2,18								
320005 ^S	INSPECT NOSEWHEEL STEERING JACK							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.470	AFL	6498						
PROC. REF: AMM 32-50-00								
PKG:2,18								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320006 ^S	INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.450	AFL	6498						
							PKG:2,18	
320007 ^S	INSPECT NOSEWHEEL STEERING ON/OFF VALVE							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.350	AFL	6498						
							PKG:2,18	
320008 ^S	CHECK NOSE GEAR DRAG STAY ASSEMBLY							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.440	AFL	6498						
PROC. REF: AMM 32-20-21							PKG:2,18	
320009 ^S	DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.545	AFL	6498						
PROC. REF: AMM NO REF-1							PKG:2,18	
320010 ^S	CHECK MAIN GEAR LEG ASSEMBLIES							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.420	AFL	6498						
PROC. REF: AMM 12-32-00							PKG:2,18	
320011 ^S	INSPECT MAIN LANDING GEAR SIDE-STAYS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.010	AFL	6498						
PROC. REF: AMM 32-10-25							PKG:2,18	
320012 ^S	CHECK MAIN LANDING GEAR TORQUE LINKS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.015	AFL	6498						
PROC. REF: AMM 32-10-12							PKG:2,18	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320013 ^S	INSPECT MAIN LANDING GEAR DOORS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.460	AFL	6498						
							PKG:2,18	
320014 ^S	INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.425	AFL	6498						
							PKG:2,18	
320015 ^S	INSPECT REVERSING VALVES AND OPERATING MECHANISMS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.445	AFL	6498						
							PKG:2,18	
320016 ^S	CHECK STEERING SYSTEM CABLES AND CHAINS							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.475	AFL	6753						
PROC. REF: AMM 32-50-00							PKG:3	
320017 ^S	CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.180	AFL	6753						
PROC. REF: AMM 32-20-21							PKG:3	
320018 ^S	CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.350	AFL	6753						
							PKG:3	
320019 ^S	INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT							Service ATA:32
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 32.385	AFL	5769						
PROC. REF: AMM 32-30-22							PKG:4	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320020 ^S	CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)							Service ATA:32
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 32.185	AFL	5769						
PROC. REF: AMM 32-30-22							PKG:4	
320021 ^S	CLEAN RESTRICTOR VALVES							Service ATA:32
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 32.145	AFL	5769						
PROC. REF: AMM 32-30-01							PKG:4	
320022 ^S	CHECK BRAKE MASTER CYLINDERS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.465	AFL	6498						
PROC. REF: AMM 32-40-00							PKG:2	
320023 ^S	CHECK BRAKE HOSES TO MASTER CYLINDERS							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.455	AFL	6753						
							PKG:3	
320024 ^S	REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.375	AFL	6753						
PROC. REF: AMM 32-40-101							PKG:3	
320027 ^S	VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE							Service ATA:32
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 32.350	AFL	6498						
							PKG:7	
320028	INSPECT/NDT MAIN LANDING GEAR FAIRING STRUT							Service ATA:32
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 32.035	AFL	6498						
PROC. REF: NTM 32-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320029	CHECK NOSE LANDING GEAR DRAG STAY							Service ATA:32
	MOS/MSC	16-Oct-20	A/R					
	HRS	7924.2						
WC#: 32.070	AFL	6522						
PROC. REF: AMM NO REF-1								
320033 ^S	DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.095	AFL	6498						
PKG:2,18								
320034 ^S	INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.510	AFL	6498						
PKG:2,18								
320035 ^S	INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.520	AFL	6753						
PKG:3								
320036 ^S	INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK							Service ATA:32
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 32.530	AFL	6753						
PROC. REF: GENERIC NO REF								
PKG:3								
320037 ^S	CHECK NOSE LEG ASSEMBLY TORQUE LINKS							Service ATA:32
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 32.540	AFL	6498						
PROC. REF: AMM 32-20-12								
PKG:2,18								
320038	LUBRICATE MAIN LANDING GEAR SIDESTAY SHIMS							Service ATA:32
	MOS/MSC	18-Nov-15	A/R					
	HRS	6815.8						
WC#: 32.570	AFL	5849						
PROC. REF: AMS 5-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320039 ^S		INSPECTION OF LEFT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS						Service ATA:32
	MOS	06-Mar-96						
	HRS	0	800 (+40/-10)					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:2,18
320039 ^S		INSPECTION OF RIGHT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS						Service ATA:32
	MOS	06-Mar-96						
	HRS	0	800					
	AFL	0						
PROC. REF: GENERIC NO REF								PKG:2,18
321001		LEFT MAIN LEG (OVERHAUL)						Component ATA:32
PN:140-810044-17	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/8DP/398	HRS	7896.7		TSO 828.9				
WC#: 32.020	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-10-12								
321002		RIGHT MAIN LEG (OVERHAUL)						Component ATA:32
PN:140-81044-18	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/8S/417	HRS	7896.7		TSO 828.9				
WC#: 32.020	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-10-12								
321013		LEFT SIDESTAY (OVERHAUL)						Component ATA:32
PN:140-810043-11	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/8S/417	HRS	7896.7		TSO 828.9				
WC#: 32.025	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-10-25								
321014		RIGHT SIDESTAY (OVERHAUL)						Component ATA:32
PN:140-810043-12	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/8SSS/382	HRS	7896.7		TSO 828.9				
WC#: 32.030	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-10-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321015	LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM (LIFE LIMIT)							Component ATA:32
PN:140-8100125-1	MOS	08-Aug-08						LIFE LIMIT
SN:SAM 2612	HRS	4602.2						
WC#: 32.025	AFL	4370	10000	TSN 4872	9498	9498	2671	
PROC. REF: AMM 32-10-25								
321016	RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM (LIFE LIMIT)							Component ATA:32
PN:140-8100125-2	MOS	08-Aug-08						LIFE LIMIT
SN:SAM 2506	HRS	4602.2						
WC#: 32.030	AFL	4370	10000	TSN 4872	9498	9498	2671	
PROC. REF: AMM 32-10-25								
321017	LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM (LIFE LIMIT)							Component ATA:32
PN:140-810064-1	MOS	08-Aug-08						LIFE LIMIT
SN:SAM 2005	HRS	4602.2						
WC#: 32.025	AFL	4370	12000	TSN 4872	11498	11498	4671	
PROC. REF: AMM 32-10-25								
321018	RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM (LIFE LIMIT)							Component ATA:32
PN:140-810064-2	MOS	08-Aug-08						LIFE LIMIT
SN:SAM 2006	HRS	4602.2						
WC#: 32.030	AFL	4370	12000	TSN 4872	11498	11498	4671	
PROC. REF: AMM 32-10-25								
321050	LEFT MAIN LANDING GEAR UPPER CASING (LIFE LIMIT)							Component ATA:32
PN:25-8UM-69	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0	24000	TSN 0	24000		17173	
321051	RIGHT MAIN LANDING GEAR UPPER CASING (LIFE LIMIT)							Component ATA:32
PN:25-8UM-69	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0	24000	TSN 0	24000		17173	
321061	LEFT MAIN LANDING GEAR JACK PIVOT							Component ATA:32
PN:25UM1229A	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.040	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321062	RIGHT MAIN LANDING GEAR JACK PIVOT							Component ATA:32
PN:25UM1229A	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.040	AFL	0		TSN 0				
321065	LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN (LIFE LIMIT)							Component ATA:32
PN:25-8UM15-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.400	AFL	0	20000	TSN 0	20000		13173	
321066	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN (LIFE LIMIT)							Component ATA:32
PN:25-8UM15-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.400	AFL	0	20000	TSN 0	20000		13173	
321067	LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN (LIFE LIMIT)							Component ATA:32
PN:25-8UM15-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.495	AFL	0	20000	TSN 0	20000		13173	
321068	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN (LIFE LIMIT)							Component ATA:32
PN:25-8UM15-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.495	AFL	0	20000	TSN 0	20000		13173	
321071	LEFT MAIN LANDING GEAR JACK DISTANCE PIN (LIFE LIMIT)							Component ATA:32
PN:25UM423	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.045	AFL	0	24000	TSN 0	24000		17173	
321072	RIGHT MAIN LANDING GEAR JACK DISTANCE PIN (LIFE LIMIT)							Component ATA:32
PN:25UM423	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.045	AFL	0	24000	TSN 0	24000		17173	
321075	LEFT MAIN LANDING GEAR PLUNGER TUBE (LIFE LIMIT)							Component ATA:32
PN:25-8UM5,6	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0	17000	TSN 0	17000		10173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321076	RIGHT MAIN LANDING GEAR PLUNGER TUBE (LIFE LIMIT)							Component ATA:32
PN:25-8UM5,6	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0	17000	TSN 0	17000		10173	
321081	LEFT MAIN LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:PN	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0	20000	TSN 0	20000		13173	
321082	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:PN	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0	20000	TSN 0	20000		13173	
321083	LEFT MAIN LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:PN	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.555	AFL	0	20000	TSN 0	20000		13173	
321084	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:PN	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.555	AFL	0	20000	TSN 0	20000		13173	
321087	LEFT MAIN LANDING GEAR AXLE ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.571	AFL	0		TSN 0				
321088	RIGHT MAIN LANDING GEAR AXLE ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.572	AFL	0		TSN 0				
322001	NOSE LEG ASSEMBLY (OVERHAUL)							Component ATA:32
PN:25-9UN-407A	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/9N/406	HRS	7896.7		TSO 828.9				
WC#: 32.050	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-20-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322003	NOSE LANDING GEAR PIVOT PIN (LIFE LIMIT)							Component ATA:32
PN:25UN645A	MOS	06-Mar-96						LIFE LIMIT
SN:JO46277-000	HRS	0						
WC#: 32.055	AFL	0	16000	TSN 4847	11153		4326	
322007	NOSE LANDING GEAR DRAG STAY (OVERHAUL)							Component ATA:32
PN:25-8UN3-179A	MOS	04-Sep-20	144	TSO 63	04-Jun-27		1096 d	OVERHAUL
SN:SAM/DHB/8DS/385	HRS	7896.7		TSO 828.9				
WC#: 32.070	AFL	6498	5000	TSO 599	10899		4072	
PROC. REF: AMM 32-20-21								
322009	NOSE LANDING GEAR JACK LOWER PIVOT PIN (LIFE LIMIT)							Component ATA:32
PN:25UN597	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.075	AFL	0	22000	TSN 0	22000		15173	
322011	NOSE LANDING GEAR DRAG STAY BRIDGE CASTING (LIFE LIMIT)							Component ATA:32
PN:25-8UN487-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.075	AFL	0	33000	TSN 0	33000		26173	
322015	NOSE LANDING GEAR UPPER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:25-8UN267-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.080	AFL	0	32000	TSN 0	32000		25173	
322016	NOSE LANDING GEAR LOWER TORQUE LINK (LIFE LIMIT)							Component ATA:32
PN:25-8UN269-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.080	AFL	0	32000	TSN 0	32000		25173	
322017	NOSE LANDING GEAR DRAG STRUT PICK-UP (LIFE LIMIT)							Component ATA:32
PN:25-8UN265	MOS	06-Mar-96		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.560	AFL	0	13900	TSN 0	13900		7073	
322025	NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS (LIFE LIMIT)							Component ATA:32
PN:A102/28J	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.380	AFL	0	10000	TSN 0	10000		3173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322031	NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS (LIFE LIMIT)							Component ATA:32
PN:A102/21J	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.085	AFL	0	10000	TSN 0	10000		3173	
322045	NOSE LANDING GEAR PLUNGER TUBE (LIFE LIMIT)							Component ATA:32
PN:25UN649	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.075	AFL	0	20000	TSN 0	20000		13173	
323001	NOSE LANDING GEAR RETRACTION JACK (OVERHAUL)							Component ATA:32
PN:AIR45404-1	MOS	03-May-12		TSO 0				OVERHAUL
SN:LK0523	HRS	5599.6		TSO 0				
WC#: 32.090	AFL	4994	5000	TSO 0	9994		3167	
PROC. REF: AMM 32-30-28								
323007	LEFT MAIN LANDING GEAR RETRACTION JACK (OVERHAUL)							Component ATA:32
PN:AIR48502-7	MOS	08-Aug-08						OVERHAUL
SN:LK9003183	HRS	4602.2						
WC#: 32.100	AFL	4370	5000	TSO 0	9370		2543	
PROC. REF: AMM 32-30-27								
323008	RIGHT MAIN LANDING GEAR RETRACTION JACK (OVERHAUL)							Component ATA:32
PN:AIR48503-7	MOS	08-Aug-08						OVERHAUL
SN:LK0432	HRS	4602.2						
WC#: 32.100	AFL	4370	5000	TSO 0	9370		2543	
PROC. REF: AMM 32-30-27								
323019	LEFT MAIN LANDING GEAR DOOR JACK (OVERHAUL)							Component ATA:32
PN:AIR48485-3	MOS	03-May-12		TSO 0				OVERHAUL
SN:APB002986	HRS	5599.6		TSO 0				
WC#: 32.105	AFL	4994	5000	TSO 0	9994		3167	
323020	RIGHT MAIN LANDING GEAR DOOR JACK (OVERHAUL)							Component ATA:32
PN:AIR48484-3	MOS	03-May-12		TSO 0				OVERHAUL
SN:APB002616	HRS	5599.6		TSO 0				
WC#: 32.105	AFL	4994	5000	TSO 0	9994		3167	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323031	LEFT SEQUENCE VALVE							Component ATA:32
PN:AIR48540-1	MOS/MSC	16-May-16	O/C	TSO 0				
SN:APB983229	HRS	6937		TSO 0				
WC#: 32.110	AFL	5906		TSO 0				
PROC. REF: AMM 32-30-41								
323032	RIGHT SEQUENCE VALVE							Component ATA:32
PN:AIR48540-1	MOS/MSC	16-May-16	O/C	TSO 0				
SN:APB031119	HRS	6937		TSO 0				
WC#: 32.110	AFL	5906		TSO 0				
PROC. REF: AMM 32-30-41								
323043	LEFT REVERSING VALVE							Component ATA:32
PN:AIR48542-1	MOS/MSC	16-May-16	O/C	TSO 0				
SN:LK8804854	HRS	6937		TSO 0				
WC#: 32.115	AFL	5906		TSO 0				
PROC. REF: AMM 32-30-31								
323044	RIGHT REVERSING VALVE							Component ATA:32
PN:AIR48543-1-3	MOS/MSC	16-May-16	O/C	TSO 0				
SN:LK0761	HRS	6937		TSO 0				
WC#: 32.115	AFL	5906		TSO 0				
PROC. REF: AMM 32-30-31								
323079	LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE							Component ATA:32
PN:AIR48026-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951140	HRS	0		TSN 0				
WC#: 32.120	AFL	0						
PROC. REF: GENERIC NO REF								
323080	RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE							Component ATA:32
PN:AIR48026-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951141	HRS	0		TSN 0				
WC#: 32.120	AFL	0						
PROC. REF: GENERIC NO REF								
323091	MAIN LANDING GEAR CENTER NONRETURN VALVE							Component ATA:32
PN:AIR48026-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951143	HRS	0		TSN 0				
WC#: 32.125	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323097	FRAME 14 NON-RETURN VALVE							Component ATA:32
PN:AIR45420-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951692	HRS	0		TSN 0				
WC#: 32.130	AFL	0						
PROC. REF: GENERIC NO REF								
323098	FRAME 14A NONRETURN VALVE							Component ATA:32
PN:AIR45420-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951682	HRS	0		TSN 0				
WC#: 32.130	AFL	0						
PROC. REF: GENERIC NO REF								
323099	FRAME 15A NONRETURN VALVE							Component ATA:32
PN:AIR45420-0	MOS/MSC	06-Mar-96	O/C					
SN:APB951693	HRS	0		TSN 0				
WC#: 32.130	AFL	0						
PROC. REF: GENERIC NO REF								
323103	LANDING GEAR SELECTOR/DUMP VALVE							Component ATA:32
PN:AIR45406-1	MOS/MSC	06-Mar-96	O/C					
SN:APB951500	HRS	0		TSN 0				
WC#: 32.135	AFL	0						
PROC. REF: GENERIC NO REF								
323115	LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE							Component ATA:32
PN:AIR45444-0-1	MOS/MSC	06-Mar-96	O/C					
SN:APB950829	HRS	0		TSN 0				
WC#: 32.140	AFL	0						
PROC. REF: GENERIC NO REF								
323116	RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE							Component ATA:32
PN:AIR45444-0-1	MOS/MSC	06-Mar-96	O/C					
SN:APB950833	HRS	0		TSN 0				
WC#: 32.140	AFL	0						
PROC. REF: GENERIC NO REF								
323139	LEFT MAIN LANDING GEAR JACK PIVOT BOLT (LIFE LIMIT)							Component ATA:32
PN:25UM153A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.150	AFL	0	30000	TSN 0	30000		23173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323140	RIGHT MAIN LANDING GEAR JACK PIVOT BOLT (LIFE LIMIT)							Component ATA:32
PN:25UM153A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.150	AFL	0	30000	TSN 0	30000		23173	
323151	LEFT MAIN LANDING GEAR JACK CYLINDER HEAD (LIFE LIMIT)							Component ATA:32
PN:AIR48502-7	MOS	28-Sep-10	168	TSN 0	28-Sep-24		117 d	LIFE LIMIT
SN:APB981005	HRS	5178.7		TSN 0				
WC#: 32.155	AFL	4724	12000	TSN 0	16724		9897	
323152	RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD (LIFE LIMIT)							Component ATA:32
PN:AIR48503-7	MOS	28-Sep-10	168	TSN 0	28-Sep-24		117 d	LIFE LIMIT
SN:LK9300826	HRS	5178.7		TSN 0				
WC#: 32.155	AFL	4724	12000	TSN 0	16724		9897	
323163	LEFT MAIN LANDING GEAR JACK EYE END (LIFE LIMIT)							Component ATA:32
PN:AIR158922	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.160	AFL	0	10000	TSN 0	10000		3173	
323164	RIGHT MAIN LANDING GEAR JACK EYE END (LIFE LIMIT)							Component ATA:32
PN:AIR158922	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.160	AFL	0	10000	TSN 0	10000		3173	
323175	LEFT MAIN LANDING GEAR RETRACTION ARM (LIFE LIMIT)							Component ATA:32
PN:25-8UM63-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.165	AFL	0	12000	TSN 0	12000		5173	
323176	RIGHT MAIN LANDING GEAR RETRACTION ARM (LIFE LIMIT)							Component ATA:32
PN:25-8UM63-2A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.165	AFL	0	12000	TSN 0	12000		5173	
323181	LEFT MAIN LANDING GEAR RETRACTION ARM PIN (LIFE LIMIT)							Component ATA:32
PN:25UM787	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.170	AFL	0	32000	TSN 0	32000		25173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323182	RIGHT MAIN LANDING GEAR RETRACTION ARM PIN (LIFE LIMIT)							Component ATA:32
PN:25UM787	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.170	AFL	0	32000	TSN 0	32000		25173	
323187	LANDING GEAR LEVER LOCK SOLENOID							Component ATA:32
PN:D5327	MOS/MSC	06-Mar-96	O/C					
SN:X4899	HRS	0		TSN 0				
WC#: 32.175	AFL	0						
PROC. REF: AMM 32-30-21								
324001	NOSE LANDING GEAR AXLE BARREL (LIFE LIMIT)							Component ATA:32
PN:25-8UN257-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.195	AFL	0	30000	TSN 0	30000		23173	
PROC. REF: AMM 32-40-31								
324002	NOSE LANDING GEAR AXLE ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.573	AFL	0		TSN 0				
324003	LEFT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.574	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324004	RIGHT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.575	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324006	NOSE LANDING GEAR OUTER CASING							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.576	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324007	LEFT NOSE WHEEL							Component ATA:32
PN:AH52239	MOS/MSC	02-Apr-21	O/C	TSO 0				
SN:LX108	HRS	8048		TSO 0				
WC#: 32.200	AFL	6611		TSO 0				
PROC. REF: AMM 32-40-21								
324008	RIGHT NOSE WHEEL							Component ATA:32
PN:AH52339	MOS/MSC	02-Apr-21	O/C	TSO 0				
SN:HM366	HRS	8048		TSO 0				
WC#: 32.205	AFL	6611		TSO 0				
PROC. REF: AMM 32-40-21								
324009	NOSE LANDING GEAR TOP LEVER ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.577	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324010	NOSE LANDING GEAR BOTTOM LEVER ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.578	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
324019	LEFT NOSE TIRE							Component ATA:32
PN:181K63-2	MOS/MSC	02-Apr-21	T/C	TSN 0				
SN:00410686	HRS	8048		TSN 0				
WC#: 32.200	AFL	6611		TSN 0				
PROC. REF: AMM 32-40-41								
324020	RIGHT NOSE TIRE							Component ATA:32
PN:181K63-2	MOS/MSC	02-Apr-21	T/C	TSN 0				
SN:00430675	HRS	8048		TSN 0				
WC#: 32.205	AFL	6611		TSN 0				
PROC. REF: AMM 32-40-41								
324031	LEFT OUTBOARD MAIN WHEEL							Component ATA:32
PN:AHA1814	MOS/MSC	16-Jul-21	O/C	TSO 0				
SN:2590QC/029CP	HRS	8103.5		TSO 0				
WC#: 32.210	AFL	6646		TSO 0				
PROC. REF: AMM 32-40-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324032	RIGHT OUTBOARD MAIN WHEEL							Component ATA:32
PN: AHA1814	MOS/MSC	06-Apr-22	O/C	TSO 0				
SN: LT159	HRS	8213.1		TSO 0				
WC#: 32.215	AFL	6712		TSO 0				
PROC. REF: AMM 32-40-12								
324033	LEFT INBOARD MAIN WHEEL							Component ATA:32
PN: AHA1814	MOS/MSC	16-Jul-21	O/C	TSO 0				
SN: 5052JA	HRS	8103.5		TSO 0				
WC#: 32.220	AFL	6646		TSO 0				
PROC. REF: AMM 32-40-12								
324034	RIGHT INBOARD MAIN WHEEL							Component ATA:32
PN: AHA1814	MOS/MSC	06-Apr-22	O/C	TSO 0				
SN: 5058FV	HRS	8213.1		TSO 0				
WC#: 32.225	AFL	6712		TSO 0				
PROC. REF: AMM 32-40-12								
324055	LEFT OUTBOARD MAIN TIRE							Component ATA:32
PN: 237K23-2	MOS/MSC	16-Jul-21	T/C	TSN 0				
SN: 11250358	HRS	8103.5		TSN 0				
WC#: 32.210	AFL	6646		TSN 0				
PROC. REF: AMM 32-40-41								
324056	RIGHT OUTBOARD MAIN TIRE							Component ATA:32
PN: 033-504-0	MOS/MSC	06-Apr-22	T/C	TSN 0				
SN: 5139R05087	HRS	8213.1		TSN 0				
WC#: 32.215	AFL	6712		TSN 0				
PROC. REF: AMM 32-40-41								
324057	LEFT INBOARD MAIN TIRE							Component ATA:32
PN: 237K23-2	MOS/MSC	16-Jul-21	T/C	TSN 0				
SN: 11240561	HRS	8103.5		TSN 0				
WC#: 32.220	AFL	6646		TSN 0				
PROC. REF: AMM 32-40-41								
324058	RIGHT INBOARD MAIN TIRE							Component ATA:32
PN: 033-504-0	MOS/MSC	06-Apr-22	T/C	TSN 0				
SN: 7269R05122	HRS	8213.1		TSN 0				
WC#: 32.225	AFL	6712		TSN 0				
PROC. REF: AMM 32-40-41								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324065	RIGHT WHEEL WELL FILTER							Component ATA:32
PN:AIR48538	MOS/MSC	06-Mar-96	O/C					
SN:BF93/0133	HRS	0		TSN 0				
WC#: 32.230	AFL	0						
PROC. REF: AMM 32-30-22								
324066	LEFT FRAME 14A FILTER							Component ATA:32
PN:AIR48538-0	MOS/MSC	06-Mar-96	O/C					
SN:BF950095	HRS	0		TSN 0				
WC#: 32.235	AFL	0						
PROC. REF: AMM 32-30-22								
324067	RIGHT FRAME 14A FILTER							Component ATA:32
PN:AIR48538-0	MOS/MSC	06-Mar-96	O/C					
SN:BF950092	HRS	0		TSN 0				
WC#: 32.235	AFL	0						
PROC. REF: AMM 32-30-22								
324068	FRAME 15 FILTER							Component ATA:32
PN:AIR48538-0	MOS/MSC	06-Mar-96	O/C					
SN:BF950090	HRS	0		TSN 0				
WC#: 32.235	AFL	0						
PROC. REF: AMM 32-30-22								
324069	NOSE WHEEL STEERING FILTER							Component ATA:32
PN:AIR45412-0	MOS/MSC	06-Mar-96	O/C					
SN:BF93/0102	HRS	0		TSN 0				
WC#: 32.240	AFL	0						
PROC. REF: GENERIC NO REF								
324115	BRAKE CONTROL VALVE							Component ATA:32
PN:AC67732	MOS/MSC	20-Feb-22	O/C	TSO 0				
SN:YU124	HRS	8192.3		TSO 0				
WC#: 32.245	AFL	6702		TSO 0				
PROC. REF: AMM 32-40-71								
324121	BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE (LIFE LIMIT)							Component ATA:32
PN:ACO34629	MOS	20-Feb-22		TSN 0				LIFE LIMIT
SN:NSN	HRS	8192.3		TSN 0				
WC#: 32.245	AFL	6702	4500	TSN 0	11202		4375	
PROC. REF: AMM 32-40-71								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324122	BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE (LIFE LIMIT)							Component ATA:32
PN:ACO34629	MOS	20-Feb-22		TSN 0				LIFE LIMIT
SN:NSN	HRS	8192.3		TSN 0				
WC#: 32.245	AFL	6702	4500	TSN 0	11202		4375	
PROC. REF: AMM 32-40-71								
324123	BRAKE CONTROL VALVE INNER KNIFE EDGE (LIFE LIMIT)							Component ATA:32
PN:AIE48502-7	MOS	20-Feb-22		TSN 0				LIFE LIMIT
SN:NSN	HRS	8192.3		TSN 0				
WC#: 32.245	AFL	6702	4500	TSN 0	11202		4375	
PROC. REF: AMM 32-40-71								
324145	MAIN REDUCING VALVE							Component ATA:32
PN:AC61518	MOS/MSC	12-Mar-21	O/C					
SN:LF360	HRS	8039.4						
WC#: 32.250	AFL	6604						
PROC. REF: GENERIC NO REF								
324151	EMERGENCY REDUCING VALVE							Component ATA:32
PN:AC69784	MOS/MSC	27-Mar-14	O/C	TSO 0				
SN:NS378	HRS	6253.1		TSO 0				
WC#: 32.255	AFL	5527		TSO 0				
PROC. REF: AMM 32-40-51								
324157	EMERGENCY REDUCING VALVE LEFT KNIFE EDGE (LIFE LIMIT)							Component ATA:32
PN:ACO34630	MOS	27-Mar-14		TSN 0				LIFE LIMIT
SN:NSN	HRS	6253.1		TSN 0				
WC#: 32.255	AFL	5527	4500	TSN 0	10027		3200	
324158	EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE (LIFE LIMIT)							Component ATA:32
PN:ACO34620	MOS	27-Mar-14		TSN 0				LIFE LIMIT
SN:NSN	HRS	6253.1		TSN 0				
WC#: 32.255	AFL	5527	4500	TSN 0	10027		3200	
324169	EMERGENCY BRAKE PRESSURE NONRETURN VALVE							Component ATA:32
PN:AIR45420-0-1	MOS/MSC	06-Mar-96	O/C					
SN:APB950841	HRS	0		TSN 0				
WC#: 32.500	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324175	LEFT OUTBOARD BRAKE UNIT							Component ATA:32
PN: AHA1897	MOS/MSC	15-Sep-15	O/C	TSO 0				
SN: 057BX	HRS	6754.5		TSO 0				
WC#: 32.265	AFL	5813		TSO 0				
PROC. REF: AMM 32-40-114								
324176	RIGHT OUTBOARD BRAKE UNIT							Component ATA:32
PN: AHA1897	MOS/MSC	07-Jan-03	O/C	TSO 0				
SN: TT020	HRS	2943.1		TSO 0				
WC#: 32.260	AFL	2797		TSO 0				
PROC. REF: AMM 32-40-114								
324177	LEFT INBOARD BRAKE UNIT							Component ATA:32
PN: AHA1897	MOS/MSC	05-Mar-21	O/C	TSN 147				
SN: RZ020	HRS	8033.8		TSN 2165.2				
WC#: 32.265	AFL	6599		TSN 1663				
PROC. REF: AMM 32-40-114								
324178	RIGHT INBOARD BRAKE UNIT							Component ATA:32
PN: AHA1897	MOS/MSC	11-Sep-98	O/C	TSO 0				
SN: NL029	HRS	1360		TSO 0				
WC#: 32.260	AFL	1194		TSO 0				
PROC. REF: AMM 32-40-114								
324223	LEFT OUTBOARD MAXARET (OVERHAUL)							Component ATA:32
PN: AC65218	MOS	16-May-16		TSO 0				OVERHAUL
SN: KF160	HRS	6937		TSO 0				
WC#: 32.270	AFL	5906	3000	TSO 0	8906		2079	
PROC. REF: AMM 32-40-101								
324224	RIGHT OUTBOARD MAXARET (OVERHAUL)							Component ATA:32
PN: AC65216	MOS	29-Sep-21		TSO 0				OVERHAUL
SN: 2C141	HRS	8145.1		TSO 0				
WC#: 32.275	AFL	6676	3000	TSO 0	9676		2849	
PROC. REF: AMM 32-40-101								
324225	LEFT INBOARD MAXARET (OVERHAUL)							Component ATA:32
PN: AC65216	MOS	16-Apr-15		TSO 0				OVERHAUL
SN: YS026	HRS	6574.7		TSO 0				
WC#: 32.270	AFL	5734	3000	TSO 0	8734		1907	
PROC. REF: AMM 32-40-101								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324226	RIGHT INBOARD MAXARET (OVERHAUL)							Component ATA:32
PN:AC65218	MOS	16-May-16		TSO 0				OVERHAUL
SN:8DD	HRS	6937		TSO 0				
WC#: 32.275	AFL	5906	3000	TSO 0	8906		2079	
PROC. REF: AMM 32-40-101								
324260	LEFT MAIN LANDING GEAR DOOR							Component ATA:32
PN:25.8UD111-1A	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB/063	HRS	0		TSN 0				
WC#: 32.280	AFL	0						
PROC. REF: AMM 32-10-41								
324261	RIGHT MAIN LANDING GEAR DOOR							Component ATA:32
PN:25.8UD111-2A	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB/064	HRS	0		TSN 0				
WC#: 32.280	AFL	0						
PROC. REF: AMM 32-10-41								
324262	LEFT NOSE GEAR DOOR							Component ATA:32
PN:25.8UD1-103	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB131	HRS	0		TSN 0				
WC#: 32.285	AFL	0						
PROC. REF: AMM 32-20-42								
324263	RIGHT NOSE GEAR DOOR							Component ATA:32
PN:25.8UD1-104	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB126	HRS	0		TSN 0				
WC#: 32.285	AFL	0						
PROC. REF: AMM 32-20-42								
324264	NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY							Component ATA:32
PN:25.8UD63-1A	MOS/MSC	06-Mar-96	O/C					
SN:CFTWDHB126	HRS	0		TSN 0				
WC#: 32.290	AFL	0						
PROC. REF: AMM 32-20-42								
324265	LEFT MAIN LANDING GEAR FAIRING							Component ATA:32
PN:25.8UD43-115A	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB/140	HRS	0		TSN 0				
WC#: 32.295	AFL	0						
PROC. REF: AMM 32-10-32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324266	RIGHT MAIN LANDING GEAR FAIRING							Component ATA:32
PN:25.8UD43-116A	MOS/MSC	06-Mar-96	O/C					
SN:CFTW/DHB/130	HRS	0		TSN 0				
WC#: 32.295	AFL	0						
PROC. REF: AMM 32-10-32								
324271	LEFT BRAKE MODULATOR							Component ATA:32
PN:ACM22740	MOS/MSC	05-Nov-03	O/C	TSO 0				
SN:VE007	HRS	3261.8		TSO 0				
WC#: 32.300	AFL	3230		TSO 0				
PROC. REF: GENERIC NO REF								
324272	RIGHT BRAKE MODULATOR							Component ATA:32
PN:ACM22742	MOS/MSC	06-Mar-96	O/C					
SN:52030	HRS	0		TSN 0				
WC#: 32.300	AFL	0						
PROC. REF: GENERIC NO REF								
324285 ^U	LEFT MAIN LANDING GEAR DOOR ASSEMBLY							Component ATA:32
PN:S25-8UM50009A	MOS/MSC	24-May-11	O/C					
SN:HA-25	HRS	5347.4						
	AFL	4839						
324301	PILOT LEFT BRAKE MASTER CYLINDER							Component ATA:32
PN:ACM26274	MOS/MSC	06-Mar-96	O/C					
SN:NW440	HRS	0		TSN 0				
WC#: 32.310	AFL	0						
PROC. REF: GENERIC NO REF								
324302	PILOT RIGHT BRAKE MASTER CYLINDER							Component ATA:32
PN:ACM26274	MOS/MSC	06-Mar-96	O/C					
SN:RB308	HRS	0		TSN 0				
WC#: 32.310	AFL	0						
PROC. REF: GENERIC NO REF								
324303	COPILOT LEFT BRAKE MASTER CYLINDER							Component ATA:32
PN:ACM26274	MOS/MSC	06-Mar-96	O/C					
SN:NW337	HRS	0		TSN 0				
WC#: 32.315	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324304	COPILOT RIGHT BRAKE MASTER CYLINDER							Component ATA:32
PN:ACM26274	MOS/MSC	06-Mar-96	O/C					
SN:NW436	HRS	0		TSN 0				
WC#: 32.315	AFL	0						
PROC. REF: GENERIC NO REF								
324325	LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH (OVERHAUL)							Component ATA:32
PN:TP42000	MOS	21-Dec-09		TSO 0				OVERHAUL
SN:787	HRS	4961.5	5000	TSO 0	9961.5		1520.6	
WC#: 32.320	AFL	4598		TSO 0				
324326	RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH (OVERHAUL)							Component ATA:32
PN:TP42000	MOS	21-Dec-09		TSO 0				OVERHAUL
SN:3220	HRS	4961.5	5000	TSO 0	9961.5		1520.6	
WC#: 32.320	AFL	4598		TSO 0				
324337	FORWARD HIGH PRESSURE TRANSDUCER							Component ATA:32
PN:FDA695-4-21	MOS/MSC	06-Mar-96	O/C					
SN:BY6166	HRS	0		TSN 0				
WC#: 32.325	AFL	0						
PROC. REF: GENERIC NO REF								
324338	AFT HIGH PRESSURE TRANSDUCER							Component ATA:32
PN:FDA695-4-21	MOS/MSC	06-Mar-96	O/C					
SN:BY6167	HRS	0		TSN 0				
WC#: 32.325	AFL	0						
PROC. REF: GENERIC NO REF								
325001	STEERING JACK							Component ATA:32
PN:AIR45396-7	MOS/MSC	16-Jul-15	O/C	TSO 0				
SN:APB951625	HRS	6678		TSO 0				
WC#: 32.330	AFL	5773		TSO 0				
PROC. REF: AMM 32-50-11								
325003	NOSE LANDING GEAR CONNECTING ROD (LIFE LIMIT)							Component ATA:32
PN:25-8UN433-1A	MOS	06-Mar-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.335	AFL	0	20000	TSN 0	20000		13173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325007	STEERING JACK EYE END (LIFE LIMIT)							Component ATA:32
PN: AIR110646	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.340	AFL	0	14400	TSN 0	14400		7573	
325011	NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE (LIFE LIMIT)							Component ATA:32
PN: 25-8UN455/1	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.335	AFL	0	20000	TSN 0	20000		13173	
325015	NOSE LANDING GEAR STEERING PIN (LIFE LIMIT)							Component ATA:32
PN: 25UN605	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.345	AFL	0	25000	TSN 0	25000		18173	
325021	NOSE LANDING GEAR MAIN CASING BOLT (LIFE LIMIT)							Component ATA:32
PN: 25UN603	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.345	AFL	0	33000	TSN 0	33000		26173	
325025	NOSE WHEEL STEERING ON/OFF VALVE							Component ATA:32
PN: AIR45408/0	MOS/MSC	28-Oct-98	O/C	TSN 0				
SN: APB981474	HRS	1471		TSN 0				
WC#: 32.350	AFL	1275		TSN 0				
PROC. REF: GENERIC NO REF								
325031	NOSE WHEEL ANTI-SHIMMING VALVE							Component ATA:32
PN: AIR48284-1	MOS/MSC	28-Oct-98	O/C	TSN 0				
SN: APB981860	HRS	1471		TSN 0				
WC#: 32.355	AFL	1275		TSN 0				
PROC. REF: GENERIC NO REF								
325041	NOSE LANDING GEAR UPPER STEERING MAIN MEMBER (LIFE LIMIT)							Component ATA:32
PN: 25-8UN431-1A	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.360	AFL	0	35000	TSN 0	35000		28173	
325042	NOSE LANDING GEAR LOWER STEERING MAIN MEMBER (LIFE LIMIT)							Component ATA:32
PN: 25-8UN431-2A	MOS	06-Mar-96						LIFE LIMIT
SN: UNKNOWN	HRS	0						
WC#: 32.360	AFL	0	35000	TSN 0	35000		28173	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325051	NOSE LANDING GEAR STEERING JACK PICK-UP (LIFE LIMIT)							Component ATA:32
PN:25-8UN263-1A	MOS	06-Mar-96					LIFE LIMIT	
SN:UNKNOWN	HRS	0						
WC#: 32.365	AFL	0	18000	TSN 0	18000		11173	
325058	NOSE LANDING GEAR STEERING SLEEVE (LIFE LIMIT)							Component ATA:32
PN:25-8UN439-1A	MOS	06-Mar-96					LIFE LIMIT	
SN:UNKNOWN	HRS	0						
WC#: 32.365	AFL	0	20000	TSN 0	20000		13173	
ATA 33 - LIGHTS								
330003 ^S	CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM							Service ATA:33
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 33.080	AFL	6498						
PKG:2								
330007	MAIN CG ILLUMINATED LABEL							Component ATA:33
PN:JW125-1L-317	MOS/MSC	06-Mar-96	O/C					
SN:JWBA408	HRS	0		TSN 0				
WC#: 33.015	AFL	0						
PROC. REF: GENERIC NO REF								
330008	FORWARD CG ILLUMINATED LABEL							Component ATA:33
PN:JW125-1L-210	MOS/MSC	06-Mar-96	O/C					
SN:JWBA658	HRS	0		TSN 0				
WC#: 33.015	AFL	0						
PROC. REF: GENERIC NO REF								
334001	TOP ANTI COLLISION BEACON							Component ATA:33
PN:01-0790044-55	MOS/MSC	25-Jun-01	O/C					
SN:02897	HRS	2352.4						
WC#: 33.020	AFL	2050						
PROC. REF: AMM 33-40-42								
334002	BOTTOM ANTI COLLISION BEACON							Component ATA:33
PN:01-0790044-54	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:08273	HRS	7830.3		TSN 0				
WC#: 33.020	AFL	6457		TSN 0				
PROC. REF: AMM 33-40-42								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334013	LEFT WING STROBE LIGHT							Component ATA:33
PN:31-2059-11	MOS/MSC	11-Sep-15	O/C	TSN 0				
SN:NA	HRS	6754.5		TSN 0				
WC#: 33.025	AFL	5813		TSN 0				
PROC. REF: AMM NO REF-1								
334014	RIGHT WING STROBE LIGHT							Component ATA:33
PN:31-2059-11	MOS/MSC	11-Sep-15	O/C	TSN 0				
SN:NA	HRS	6754.5		TSN 0				
WC#: 33.025	AFL	5813		TSN 0				
PROC. REF: AMM NO REF-1								
334016	TEST LEFT WING STROBE LIGHT INTENSITY							Service ATA:33
PN:31-2059-11	MOS	11-Jan-23						
SN:NA	HRS	8299.1	400 (+50/-50)		8699.1	8749.1	258.2 (+50)	
WC#: 33.025	AFL	6753						
334017	TEST RIGHT WING STROBE LIGHT INTENSITY							Service ATA:33
PN:31-2059-11	MOS	11-Jan-23						
SN:NA	HRS	8299.1	400 (+50/-50)		8699.1	8749.1	258.2 (+50)	
WC#: 33.025	AFL	6753						
334032	LEFT STROBE LIGHT POWER SUPPLY							Component ATA:33
PN:60-1755-1	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: GENERIC NO REF								
334033	RIGHT STROBE LIGHT POWER SUPPLY							Component ATA:33
PN:60-1755-1	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: GENERIC NO REF								
334044	TAIL STROBE LIGHT (REPLACE)							Component ATA:33 REPLACE
PN:30-0516-1	MOS	15-Mar-18		TSO 0				
SN:7740	HRS	7449.8	1500	TSO 0	8949.8		508.9	
WC#: 33.040	AFL	6210		TSO 0				
PROC. REF: AMM NO REF-1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334045	TAIL STROBE LIGHT POWER SUPPLY							Component ATA:33
PN:60-1775-1	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.035	AFL	0						
PROC. REF: GENERIC NO REF								
334047	TEST TAIL STROBE LIGHT INTENSITY							Service ATA:33
PN:30-0516-1	MOS/MSC	15-Mar-18	O/C					
SN:7740	HRS	7449.8						
WC#: 33.040	AFL	6210						
334061	STROBE LIGHTS POWER SUPPLY							Component ATA:33
PN:701571	MOS/MSC	09-Mar-00	O/C					
SN:4442	HRS	2303						
WC#: 33.045	AFL	2002						
PROC. REF: GENERIC NO REF								
335009	FORWARD EMERGENCY LIGHTING POWER SUPPLY							Component ATA:33
PN:60-0304-51	MOS/MSC	14-Oct-15	O/C	TSO 0				
SN:29457	HRS	6775		TSO 0				
WC#: 33.090	AFL	5825		TSO 0				
PROC. REF: MMA 33-50-05								
335011	AFT EMERGENCY LIGHTING POWER SUPPLY							Component ATA:33
PN:60-0304-51	MOS/MSC	14-Oct-15	O/C	TSO 0				
SN:8066	HRS	6775		TSO 0				
WC#: 33.095	AFL	5825		TSO 0				
PROC. REF: MMA 33-50-05								
335025	NO. 1 (AA PNL) DIMMER							Component ATA:33
PN:LT-52A	MOS/MSC	06-May-96	O/C					
SN:13236	HRS	22		TSN 0				
WC#: 33.055	AFL	11						
PROC. REF: GENERIC NO REF								
335027	NO. 2 (AA PNL) DIMMER							Component ATA:33
PN:LT-52A	MOS/MSC	06-May-96	O/C					
SN:13427	HRS	22		TSN 0				
WC#: 33.055	AFL	11						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335029	NO. 1 (AB PNL) DIMMER							Component ATA:33
PN:LT-52A	MOS/MSC	06-May-96	O/C					
SN:13246	HRS	22		TSN 0				
WC#: 33.060	AFL	11						
PROC. REF: GENERIC NO REF								
335031	NO. 2 (AB PNL) DIMMER							Component ATA:33
PN:LT-52A	MOS/MSC	06-May-96	O/C					
SN:13414	HRS	22		TSN 0				
WC#: 33.060	AFL	11						
PROC. REF: GENERIC NO REF								
335200	PULSELIGHT CONTROL UNIT							Component ATA:33
PN:2400-25-44	MOS/MSC	03-Jun-05	O/C	TSO 0				
SN:K00168	HRS	3774.5		TSO 0				
WC#: 33.085	AFL	3826		TSO 0				
PROC. REF: MMA 33-40-10, MMA 33-40-15								
33R799A ^U	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (900 HRS / 1 YR)							Service ATA:33
	MOS	17-Nov-23	12 (+1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1	900 (+40)		9293.1	9333.1	852.2 (+40)	
	AFL	6799						
33R799B ^U	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (1800 HRS/ 2 YRS)							Service ATA:33
	MOS	11-Jan-23	24 (+2m)		11-Jan-25	11-Mar-25	222 d (+59)	
	HRS	8299.1	1800 (+50)		10099.1	10149.1	1658.2 (+50)	
	AFL	6753						
33R801A ^U	INSPECT LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (900 HRS/ 1 YR)							Service ATA:33
	MOS	17-Nov-23	12 (+1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1	900 (+40)		9293.1	9333.1	852.2 (+40)	
	AFL	6799						
33R801B ^U	INSPECT LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (1800 HRS/ 2 YRS)							Service ATA:33
	MOS	11-Jan-23	24 (+2m)		11-Jan-25	11-Mar-25	222 d (+59)	
	HRS	8299.1	1800 (+50)		10099.1	10149.1	1658.2 (+50)	
	AFL	6753						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340002	DRAIN PITOT/STATIC DRAIN TRAPS							Service ATA:34
	MOS	11-Jan-23	24 (+2m)		11-Jan-25	11-Mar-25	222 d (+59)	
	HRS	8299.1						
WC#: 34.025	AFL	6753						
PROC. REF: AMM 34-11-19								
340003 ^S	INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT							Service ATA:34
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 34.405	AFL	6753						
PKG:3								
340004 ^S	INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR							Service ATA:34
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 34.410	AFL	6753						
PKG:3								
340005 ^S	INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT							Service ATA:34
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 34.415	AFL	6753						
PKG:3								
340006	PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS							Service ATA:34
	MOS	16-Dec-22	24 (+2m)	Adj -103d	04-Sep-24	04-Nov-24	93 d (+61)	
	HRS	8299.1						
WC#: 34.015	AFL	6753						
PROC. REF: AMM 34-11-19								
340007	CHECK PITOT SYSTEM ISOLATION VALVES							Service ATA:34
	MOS	16-Dec-22	24 (+2m)	Adj -103d	04-Sep-24	04-Nov-24	93 d (+61)	
	HRS	8299.1						
WC#: 34.290	AFL	6753						
340008 ^S	TEST MACH TRIM SYSTEM							Service ATA:34
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 34.270	AFL	5769						
PROC. REF: AMM 34-24-00								
PKG:4								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340010 ^S	TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY							Service ATA:34
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 34.425	AFL	5769						
PROC. REF: AMM 27-30-00							PKG:4	
340011 ^S	CHECK MACH TRIM FAIL ANNUNCIATION RELAYS							Service ATA:34
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 34.420	AFL	5769						
							PKG:4	
340012	SWING CHECK NO. 1 COMPASS							Service ATA:34
	MOS	06-Apr-22	36 (+2m)	Adj -198d	20-Sep-24	20-Nov-24	109 d (+61)	
	HRS	8213.1						
WC#: 34.095	AFL	6712						
PROC. REF: AMM 34-09-111, AMM 34-20-15, AMM 34-23-61								
340012	SWING CHECK NO. 2 COMPASS							Service ATA:34
	MOS	06-Apr-22	36 (+2m)	Adj -198d	20-Sep-24	20-Nov-24	109 d (+61)	
	HRS	8213.1						
WC#: 34.095	AFL	6712						
PROC. REF: AMM 34-09-111, AMM 34-20-15, AMM 34-23-61								
340012	SWING CHECK STANDBY COMPASS							Service ATA:34
	MOS	06-Apr-22	36 (+2m)	Adj -198d	20-Sep-24	20-Nov-24	109 d (+61)	
	HRS	8213.1						
WC#: 34.095	AFL	6712						
PROC. REF: AMM 34-09-111, AMM 34-20-15, AMM 34-23-61								
340013	COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME							Service ATA:34
	MOS/MSC	27-Mar-14	A/R					
	HRS	6253.1						
WC#: 34.020	AFL	5527						
341001	LEFT PITOT PRESSURE HEAD							Component ATA:34
PN:853JF1	MOS/MSC	21-Oct-17	O/C	TSN 0				
SN:13832	HRS	7341.7		TSN 0				
WC#: 34.010	AFL	6131		TSN 0				
PROC. REF: AMM 34-11-24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341002	RIGHT PITOT PRESSURE HEAD							Component ATA:34
PN:5D853JF1	MOS/MSC	23-May-21	O/C	TSN 0				
SN:15254	HRS	8062.9		TSN 0				
WC#: 34.010	AFL	6622		TSN 0				
PROC. REF: AMM 34-11-24								
341073	LEFT ALTIMETER							Component ATA:34
PN:4016341-905	MOS/MSC	31-Mar-16	O/C					
SN:95118235	HRS	6924.4		TSN 6902.4				
WC#: 34.030	AFL	5897						
PROC. REF: AMM 34-10-05								
341074	RIGHT ALTIMETER							Component ATA:34
PN:4016341-905	MOS/MSC	31-Mar-16	O/C					
SN:96048418	HRS	6924.4						
WC#: 34.035	AFL	5897						
PROC. REF: AMM 34-10-05								
341085	TEST LEFT ALTIMETER (FAR 91.411)							Service ATA:34
PN:4016341-905	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:95118235	HRS							
WC#: 34.030	AFL							
PROC. REF: FAR FAR PART 91								
341086	TEST RIGHT ALTIMETER (FAR 91.411)							Service ATA:34
PN:4016341-905	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:96048418	HRS							
WC#: 34.035	AFL							
PROC. REF: FAR FAR PART 91								
341097	STANDBY ALTIMETER							Component ATA:34
PN:1611AM3	MOS/MSC	11-Jan-23	O/C					
SN:AF577	HRS	8299.1						
WC#: 34.040	AFL	6753						
PROC. REF: AMM NO REF								
341103	TEST STANDBY ALTIMETER (FAR 91.411)							Service ATA:34
PN:1611AM3	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:AF577	HRS							
WC#: 34.040	AFL							
PROC. REF: FAR FAR PART 91								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341109	LEFT AIRSPEED INDICATOR							Component ATA:34
PN:WL271ASI	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.050	AFL	0						
PROC. REF: AMM NO REF								
341110	RIGHT AIRSPEED INDICATOR							Component ATA:34
PN:WL271ASI	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.055	AFL	0						
PROC. REF: AMM NO REF								
341115	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:WL271ASI	MOS/MSC	06-Mar-96	O/C					
SN:AJ937	HRS	0		TSN 0				
WC#: 34.045	AFL	0						
PROC. REF: AMM NO REF								
341195	VOICE ADVISORY							Component ATA:34
PN:7001433-902(VA-100)	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.060	AFL	0						
PROC. REF: MMA 31-50-00, AMM NO REF								
341228	NO. 1 AIR DATA COMPUTER							Component ATA:34
PN:7000700-668	MOS/MSC	31-Mar-16	O/C					
SN:96017008	HRS	6924.4						
WC#: 34.065	AFL	5897						
PROC. REF: AMM 34-10-05, AMM 34-10-17								
341229	NO. 2 AIR DATA COMPUTER							Component ATA:34
PN:7000700-668	MOS/MSC	31-Mar-16	O/C					
SN:96037099	HRS	6924.4						
WC#: 34.066	AFL	5897						
PROC. REF: GENERIC NO REF								
341240	TEST NO.1 AIR DATA COMPUTER (FAA 91.411)							Service ATA:34
PN:7000700-668	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:96017008	HRS							
WC#: 34.065	AFL							
PROC. REF: AMM 34-10-05, FAR FAR PART 91								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341241	TEST NO.2 AIR DATA COMPUTER (FAA 91.411)							Service ATA:34
PN:7000700-668	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:96037099	HRS							
WC#: 34.066	AFL							
PROC. REF: AMM 34-10-05, FAR FAR PART 91								
341276	RADIO ALTIMETER UNIT							Component ATA:34
PN:7001840-912	MOS/MSC	12-Oct-96	O/C					
SN:96075895	HRS	32						
WC#: 34.070	AFL	17						
PROC. REF: AMM 34-40-05								
341279	LEFT RADIO ALTIMETER ANTENNA							Component ATA:34
PN:S67-2002	MOS/MSC	06-May-96	O/C					
SN:9381	HRS	22		TSN 0				
WC#: 34.075	AFL	11						
PROC. REF: AMM 34-40-05								
341281	RIGHT RADIO ALTIMETER ANTENNA							Component ATA:34
PN:S67-2002	MOS/MSC	06-May-96	O/C					
SN:8364	HRS	22		TSN 0				
WC#: 34.080	AFL	11						
PROC. REF: AMM 34-40-05								
342013	EMERGENCY GYRO HORIZON INDICATOR							Component ATA:34
PN:ADI-332B	MOS/MSC	06-May-96	O/C					
SN:1080	HRS	22		TSN 0				
WC#: 34.090	AFL	11						
PROC. REF: AMM NO REF								
342097	STANDBY COMPASS (E2B) INDICATOR							Component ATA:34
PN:KCA0104W	MOS/MSC	06-Mar-96	O/C					
SN:AG8011294	HRS	0		TSN 0				
WC#: 34.106	AFL	0						
PROC. REF: AMM 34-09-111								
342141	NO. 1 VLF/OMEGA SENSOR							Component ATA:34
PN:100-601200-004	MOS/MSC	06-May-96	O/C					
SN:2545	HRS	22		TSN 0				
WC#: 34.105	AFL	11						
PROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342143	H FIELD (TOP) ANTENNA							Component ATA:34
PN:418-312-001	MOS/MSC	06-May-96	O/C					
SN:DJ7077	HRS	22		TSN 0				
WC#: 34.110	AFL	11						
PROC. REF: AMM NO REF								
342145	NO. 1 DATA LOADER							Component ATA:34
PN:G7226-01	MOS/MSC	19-Jun-15	O/C	TSN 0				
SN:2616	HRS	6659.2		TSN 0				
WC#: 34.115	AFL	5767		TSN 0				
PROC. REF: AMM 34-60-05, AMM 34-60-15, AMM 34-60-25								
342220	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:7020116-1	MOS/MSC	28-Nov-20	O/C	TSN 0				
SN:N/A	HRS	7956.3		TSN 0				
WC#: 34.350	AFL	6545		TSN 0				
PROC. REF: AMM 34-60-05, AMM 34-60-15, AMM 34-60-25								
342220A ^U	REPLACE NO. 1 FLIGHT MANAGEMENT COMPUTER BATTERY							Service ATA:34
PN:7020116-1	MOS	28-Nov-20	24		28-Nov-22		OVD	
SN:N/A	HRS	7956.3						
	AFL	6545						
342221	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:7020116-1	MOS/MSC	28-Nov-20	O/C	TSN 0				
SN:N/A	HRS	7956.3		TSN 0				
WC#: 34.350	AFL	6545		TSN 0				
PROC. REF: AMM 34-60-05, AMM 34-60-15, AMM 34-60-25								
342221A ^U	REPLACE NO. 2 FLIGHT MANAGEMENT COMPUTER BATTERY							Service ATA:34
PN:7020116-1	MOS	28-Nov-20	24		28-Nov-22		OVD	
SN:N/A	HRS	7956.3						
	AFL	6545						
342225 ^U	NO. 1 FLIGHT MANAGEMENT SYSTEM(FMS) [CD820 MCDU] UNIT							Component ATA:34
PN:2888-01-1	MOS/MSC	12-Sep-02	O/C	TSR 0				
SN:058	HRS	2789.2		TSR 0				
	AFL	2608		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342226 ^U	NO. 2 FLIGHT MANAGEMENT SYSTEM(FMS) [CD820 MCDU] UNIT							Component ATA:34
PN:2888-01-1	MOS/MSC	13-Jan-20	O/C					
SN:728	HRS	7850.1						
	AFL	6472						
342253	NO. 1 COMPASS FLUX VALVE							Component ATA:34
PN:7010133	MOS/MSC	17-Sep-18	O/C					
SN:96103376	HRS	7607						
WC#: 34.120	AFL	6306						
					PROC. REF: AMM 34-20-15			
342254	NO. 2 COMPASS FLUX VALVE							Component ATA:34
PN:7010133	MOS/MSC	07-Oct-16	O/C		TSR 1			
SN:01066114	HRS	7056.8			TSR 0			
WC#: 34.120	AFL	5964			TSR 0			
					PROC. REF: AMM 34-20-15			
342265	NO. 1 AHRs COMPUTER							Component ATA:34
PN:7003360-943	MOS/MSC	11-Sep-18	O/C					
SN:01074706	HRS	7607						
WC#: 34.125	AFL	6306						
					PROC. REF: AMM 34-23-61			
342266	NO. 2 AHRs COMPUTER							Component ATA:34
PN:7003360-943	MOS/MSC	10-Oct-96	O/C					
SN:96023451	HRS	30						
WC#: 34.125	AFL	16						
					PROC. REF: AMM 34-23-61			
342289	NO. 1 AHRs CONTROLLER							Component ATA:34
PN:7004545-901	MOS/MSC	06-May-96	O/C					
SN:96031713	HRS	22			TSN 0			
WC#: 34.140	AFL	11						
					PROC. REF: AMM 34-20-15			
342290	NO. 2 AHRs CONTROLLER							Component ATA:34
PN:7004545-901	MOS/MSC	06-May-96	O/C					
SN:96021671	HRS	22			TSN 0			
WC#: 34.140	AFL	11						
					PROC. REF: AMM 34-20-15			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342501	NO. 1 MULTIFUNCTION DISPLAY							Component ATA:34
PN:7003110-901	MOS/MSC	06-May-96	O/C					
SN:96019540	HRS	22		TSN 0				
WC#: 34.130	AFL	11						
PROC. REF: AMM 34-70-05								
342502	NO. 2 MULTIFUNCTION DISPLAY							Component ATA:34
PN:7003110-901	MOS/MSC	13-Jan-20	O/C					
SN:98061220	HRS	7850.1						
WC#: 34.135	AFL	6472						
PROC. REF: AMM 34-70-05								
342513	NO. 1 PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:7003110-901	MOS/MSC	06-May-96	O/C					
SN:95109364	HRS	22		TSN 0				
WC#: 34.130	AFL	11						
PROC. REF: AMM 34-70-05								
342514	NO. 2 PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:7003110-901	MOS/MSC	17-Aug-18	O/C					
SN:89083752	HRS	7592.6						
WC#: 34.135	AFL	6295						
PROC. REF: AMM 34-70-05								
342515	EFIS MULTIFUNCTION ELECTRONIC DISPLAY							Component ATA:34
PN:7003110-901	MOS/MSC	09-Mar-09	O/C	TSR 0				
SN:83110283	HRS	4670		TSR 0				
WC#: 34.140	AFL	4415		TSR 0				
PROC. REF: MMA 34-70-13								
342516	NO. 1 REMOTE INSTRUMENT CONTROL							Component ATA:34
PN:7011345-901	MOS/MSC	20-Oct-06	O/C					
SN:98111244	HRS	4234.1						
WC#: 34.145	AFL	4124						
PROC. REF: AMM 34-70-05								
342517	NO. 2 REMOTE INSTRUMENT CONTROL							Component ATA:34
PN:7011345-911	MOS/MSC	20-Oct-06	O/C					
SN:98081212	HRS	4234.1						
WC#: 34.145	AFL	4124						
PROC. REF: AMM 34-70-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342527	NO. 1 EFIS SYMBOL GENERATOR							Component ATA:34
PN:7011674-118	MOS/MSC	30-Aug-99	O/C					
SN:96011250	HRS	2070		TSN 2070				
WC#: 34.150	AFL	1808		TSN 1808				
PROC. REF: AMM 34-70-05								
342528	NO. 2 EFIS SYMBOL GENERATOR							Component ATA:34
PN:7011674-118	MOS/MSC	30-Aug-99	O/C					
SN:95081184	HRS	2070		TSN 2070				
WC#: 34.150	AFL	1808		TSN 1808				
PROC. REF: AMM 34-70-05								
342530	MULTIFUNCTION SYMBOL GENERATOR							Component ATA:34
PN:7011675-119	MOS/MSC	27-Mar-18	O/C					
SN:00100977	HRS	7449.8						
WC#: 34.150	AFL	6210						
PROC. REF: AMM 34-70-05								
342537	NO. 1 DISPLAY CONTROL PANEL							Component ATA:34
PN:7005819-707	MOS/MSC	06-May-96	O/C					
SN:95082965	HRS	22		TSN 0				
WC#: 34.155	AFL	11						
PROC. REF: AMM 34-70-05, MMA 34-70-13								
342538	NO. 2 DISPLAY CONTROL PANEL							Component ATA:34
PN:7005819-707	MOS/MSC	06-May-96	O/C					
SN:96023105	HRS	22		TSN 0				
WC#: 34.155	AFL	11						
PROC. REF: AMM 34-70-05, MMA 34-70-13								
342539	MULTI FUNCTION EFIS CONTROL							Component ATA:34
PN:7007062-921	MOS/MSC	06-May-96	O/C					
SN:96011596	HRS	22		TSN 0				
WC#: 34.160	AFL	11						
PROC. REF: AMM 34-70-05								
342561	TCAS COMPUTER							Component ATA:34
PN:4066010-904	MOS/MSC	14-Apr-98	O/C					
SN:95082581	HRS	1079						
WC#: 34.175	AFL	955						
PROC. REF: AMM 34-45-05, MMA 34-45-06, MMA 34-45-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342562	TCAS (TOP) ANTENNA							Component ATA:34
PN:7514081-910	MOS/MSC	10-Oct-96	O/C					
SN:95095169	HRS	30		TSN 0				
WC#: 34.180	AFL	16						
PROC. REF: AMM 34-45-05, MMA 34-45-00, MMA 34-45-06, MMA 34-45-07								
342563	TCAS (BOTTOM) ANTENNA							Component ATA:34
PN:S65-5366-11L	MOS/MSC	10-Oct-96	O/C					
SN:3496	HRS	30		TSN 0				
WC#: 34.180	AFL	16						
PROC. REF: AMM 34-45-05, MMA 34-45-00, MMA 34-45-06, MMA 34-45-07								
342601	NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT							Component ATA:34
PN:7510100-731	MOS/MSC	15-Sep-05	O/C					
SN:95111656	HRS	3885.7						
WC#: 34.185	AFL							
PROC. REF: AMM 34-30-05								
342602	NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT							Component ATA:34
PN:7510100-731	MOS/MSC	06-Dec-19	O/C	TSN 0				
SN:1909C895	HRS	7830.3		TSN 0				
WC#: 34.185	AFL	6457		TSN 0				
PROC. REF: AMM 34-30-05								
342624	NO. 1 ADF ANTENNA							Component ATA:34
PN:7510300-901	MOS/MSC	06-May-96	O/C					
SN:95061657	HRS	22						
WC#: 34.190	AFL	11						
PROC. REF: AMM 34-51-05								
342625	NO. 2 ADF ANTENNA							Component ATA:34
PN:7510300-901	MOS/MSC	09-Mar-09	O/C	TSN 0				
SN:05059494	HRS	4670		TSN 0				
WC#: 34.190	AFL	4415		TSN 0				
PROC. REF: AMM 34-51-05								
343001	GLIDE SLOPE AERIAL							Component ATA:34
PN:17-21F6	MOS/MSC	06-Mar-96	O/C					
SN:771	HRS	0		TSN 0				
WC#: 34.195	AFL	0						
PROC. REF: AMM 34-32-725								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
343013	MARKER AERIAL							Component ATA:34
PN:17-5C	MOS/MSC	06-Mar-96	O/C					
SN:S/NO.113	HRS	0		TSN 0				
WC#: 34.200	AFL	0						
PROC. REF: AMM 34-33-612								
344001	NO. 1 WEATHER RADAR CONTROL PANEL							Component ATA:34
PN:7008471-803	MOS/MSC	20-Jul-99	O/C					
SN:96022356	HRS	2005		TSN 2005				
WC#: 34.205	AFL	1743		TSN 1743				
PROC. REF: AMM 34-41-05, AMM 34-41-15, MMA 34-41-29								
344002	NO. 2 WEATHER RADAR CONTROL PANEL							Component ATA:34
PN:7008471-803	MOS/MSC	20-Jul-99	O/C					
SN:85112282	HRS	2005		TSN 2005				
WC#: 34.205	AFL	1743		TSN 1743				
PROC. REF: AMM 34-41-05, AMM 34-41-15, MMA 34-41-29								
344005	WEATHER RADAR TRANSCEIVER							Component ATA:34
PN:7012640-922	MOS/MSC	11-Jul-19	O/C					
SN:95021347	HRS	7757.8						
WC#: 34.210	AFL	6405						
PROC. REF: AMM 34-41-05, AMM 34-41-15								
344016	RADAR CHECKLIST MODULE							Component ATA:34
PN:7990197-131	MOS/MSC	06-May-96	O/C					
SN:96021424	HRS	22		TSN 0				
WC#: 34.215	AFL	11						
PROC. REF: AMM NO REF								
344036	ISOLATION VALVE							Component ATA:34
PN:25-MC2175	MOS/MSC	06-Mar-96	O/C					
SN:FRTR010A	HRS	0		TSN 0				
WC#: 34.220	AFL							
PROC. REF: AMM 34-11-52								
345020	NO. 2 ADF RECEIVER							Component ATA:34
PN:7510114-901	MOS/MSC	10-Dec-97	O/C					
SN:95101520	HRS	795						
WC#: 34.310	AFL	728						
PROC. REF: MMA 34-52-01, AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345037	LEFT VOR/LOC AERIAL							Component ATA:34
PN:S65-247-12	MOS/MSC	07-Jul-99	O/C	TSN 0				
SN:3405	HRS	1985		TSN 0				
WC#: 34.230	AFL	1725		TSN 0				
PROC. REF: AMM 34-32-675								
345038	RIGHT VOR/LOC AERIAL							Component ATA:34
PN:S65-247-12	MOS/MSC	07-Jul-99	O/C	TSN 0				
SN:3404	HRS	1985		TSN 0				
WC#: 34.230	AFL	1725		TSN 0				
PROC. REF: AMM 34-32-675								
345049	NO. 1 ADF LOOP ANTENNA							Component ATA:34
PN:622-3710-001	MOS/MSC	06-Mar-96	O/C					
SN:3054	HRS	0		TSN 0				
WC#: 34.235	AFL	0						
PROC. REF: AMM NO REF								
345097	PHASING COUPLER							Component ATA:34
PN:SSPD-113-10	MOS/MSC	06-Mar-96	O/C					
SN:1321	HRS	0		TSN 0				
WC#: 34.240	AFL	0						
PROC. REF: AMM NO REF								
345098	COUPLER ANTENNA							Component ATA:34
PN:SSPD-113-13	MOS/MSC	06-Mar-96	O/C					
SN:223	HRS	0		TSN 0				
WC#: 34.245	AFL	0						
PROC. REF: AMM NO REF								
345109	NO. 1 DME AERIAL							Component ATA:34
PN:50-4-2	MOS/MSC	18-Jul-17	O/C	TSN 0				
SN:12449	HRS	7304.7		TSN 0				
WC#: 34.250	AFL	6110		TSN 0				
PROC. REF: AMM 34-42-652								
345110	NO. 2 DME AERIAL							Component ATA:34
PN:10A-1	MOS/MSC	06-Mar-96	O/C					
SN:3949	HRS	0		TSN 0				
WC#: 34.250	AFL	0						
PROC. REF: AMM 34-42-652								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345124 ^U	NO. 1 DISTANCE MEASURING EQUIPMENT (DME) INDICATOR							Component ATA:34
PN:7513006-901	MOS/MSC	12-Sep-02	O/C					
SN:117	HRS	2789.2						
	AFL	2608						
345125 ^U	NO. 2 DISTANCE MEASURING EQUIPMENT (DME) INDICATOR							Component ATA:34
PN:7513006-901	MOS/MSC	12-Sep-02	O/C					
SN:433	HRS	2789.2						
	AFL	2608						
345133	NO. 1 ATC TRANSPONDER AERIAL							Component ATA:34
PN:10A-1	MOS/MSC	06-Mar-96	O/C					
SN:3968	HRS	0		TSN 0				
WC#: 34.255	AFL	0						
				PROC. REF: AMM 34-43-742				
345134	NO. 2 ATC TRANSPONDER AERIAL							Component ATA:34
PN:10A-1	MOS/MSC	06-Mar-96	O/C					
SN:3969	HRS	0		TSN 0				
WC#: 34.255	AFL	0						
				PROC. REF: AMM 34-43-742				
345217	NO. 1 ATC TRANSPONDER							Component ATA:34
PN:7510700-806	MOS/MSC	31-Mar-16	O/C					
SN:98012698	HRS	6924.4						
WC#: 34.260	AFL	5897						
				PROC. REF: AMM 34-52-05, AMM 34-52-15, MMA 34-43-64				
345218	NO. 2 ATC TRANSPONDER							Component ATA:34
PN:7510700-806	MOS/MSC	31-Mar-16	O/C					
SN:97102575	HRS	6924.4						
WC#: 34.260	AFL	5897						
				PROC. REF: AMM 34-52-05, AMM 34-52-15, MMA 34-43-64				
345229	SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413)							Service ATA:34
PN:7510700-806	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:98012698	HRS							
WC#: 34.260	AFL							
				PROC. REF: FAR FAR PART 91				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345230	SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413)							Service ATA:34
PN:7510700-806	MOS	16-Dec-22	24		16-Dec-24		196 d	MANDATORY
SN:97102575	HRS							
WC#: 34.260	AFL							
PROC. REF: FAR FAR PART 91								
345305	MACH TRIM COMPUTER							Component ATA:34
PN:822-0872-001	MOS/MSC	06-May-96	O/C					
SN:111	HRS	22		TSN 0				
WC#: 34.270	AFL	11						
PROC. REF: AMM NO REF								
345324 ^U	LEFT STATIC PLATE							Component ATA:34
PN:E42024-1	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
345324 ^U	RIGHT STATIC PLATE							Component ATA:34
PN:E42024-2	MOS/MSC	31-Mar-16	O/C	TSN 0				
SN:4820	HRS	6924.4		TSN 0				
	AFL	5897		TSN 0				
345404	NO. 1 GPS SENSOR UNIT							Component ATA:34
PN:HG2021GD02	MOS/MSC	10-Oct-96	O/C					
SN:96061663	HRS	30		TSN 0				
WC#: 34.275	AFL	16						
PROC. REF: AMM 34-53-05								
345405	NO. 2 GPS SENSOR UNIT							Component ATA:34
PN:HG2021GD02	MOS/MSC	11-Jan-99	O/C					
SN:98023278	HRS	1581						
WC#: 34.275	AFL	1373						
PROC. REF: AMM 34-53-05								
345406	NO. 1 GPS ANTENNA							Component ATA:34
PN:S67-1575-20	MOS/MSC	10-Oct-96	O/C					
SN:2620	HRS	30		TSN 0				
WC#: 34.280	AFL	16						
PROC. REF: AMM 34-53-05, MMA 34-48-30, MMA 34-48-32, MMA 34-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345407	NO. 2 GPS ANTENNA							Component ATA:34
PN:S67-1575-20	MOS/MSC	21-Nov-18	O/C	TSN 0				
SN:10716	HRS	7659		TSN 0				
WC#: 34.280	AFL	6339		TSN 0				
PROC. REF: AMM 34-53-05, MMA 34-48-30, MMA 34-48-32, MMA 34-50-00								
345413	NO. 1 CONFIGURATION STRAPPING UNIT							Component ATA:34
PN:7014940-902	MOS/MSC	06-May-96	O/C					
SN:95100948	HRS	22		TSN 0				
WC#: 34.285	AFL	11						
PROC. REF: AMM NO REF								
345414	NO. 2 CONFIGURATION STRAPPING UNIT							Component ATA:34
PN:7014940-902	MOS/MSC	06-May-96	O/C					
SN:96031192	HRS	22		TSN 0				
WC#: 34.285	AFL	11						
PROC. REF: AMM NO REF								
346810	OBSERVERS AMPLIFER							Component ATA:34
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.601	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
349998	ADJUSTMENT/TEST COLLINS AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)							Service ATA:34
	MOS/MSC		O/C					
	HRS							
WC#: 34.T04	AFL							
PROC. REF: AMM 34-10-18								
349999	ADJUSTMENT/TEST HONEYWELL ADZ-810 AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)							Service ATA:34
	MOS/MSC		O/C					
	HRS							
WC#: 34.T05	AFL							
PROC. REF: AMM 34-10-15								
ATA 35 - OXYGEN								
350001 ^S	CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE							Service ATA:35
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 35.110	AFL	6498						

PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350002 ^S	FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE							Service ATA:35
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 35.035	AFL	5769						
				PROC. REF: AMM 35-10-141				PKG:4
350004 ^S	TEST/INSPECT PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 35.075	AFL	6799						
				PROC. REF: AMM 35-06-00, MMA 35-06-00, MMA 35-20-05				PKG:5
350005 ^S	CHECK BAROMATIC CONTROL VALVE							Service ATA:35
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 35.100	AFL	6799						
								PKG:5
350006 ^S	INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES							Service ATA:35
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 35.115	AFL	6799						
								PKG:5
350007 ^S	INSPECT PORTABLE BREATHING EQUIPMENT							Service ATA:35
	MOS	17-Nov-23	12 (+1m/-1m)					
	HRS	8393.1						
WC#: 35.120	AFL	6799						
								PKG:5
350008 ^S	INSPECT OXYGEN CYLINDERS							Service ATA:35
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 35.105	AFL	6753						
								PKG:3
351001	MASTER OXYGEN SUPPLY VALVE							Component ATA:35
PN:SDV1012	MOS/MSC	30-Nov-00	O/C					
SN:10189	HRS	2339		TSN 0				
WC#: 35.030	AFL	2040		TSN 0				
				PROC. REF: AMM 35-10-62				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351013	OXYGEN PRESSURE GAUGE							Component ATA:35
PN:18430901-1	MOS/MSC	12-Sep-02	O/C	TSN 0				
SN:006004	HRS	2789.2		TSN 0				
WC#: 35.040	AFL	2608		TSN 0				
PROC. REF: AMM 35-10-32								
351014	ALTERNATIVE OXYGEN PRESSURE GAUGE							Component ATA:35
PN:18430901-1	MOS/MSC	08-Aug-08	O/C					
SN:049010	HRS	4602.2						
WC#: 35.040	AFL	4370						
PROC. REF: AMM 35-10-33								
351015	OXYGEN CHARGING FILTER ASSEMBLY							Component ATA:35
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.215	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
351025	OXYGEN REDUCING VALVE							Component ATA:35
PN:WKA29720-2	MOS/MSC	01-Dec-00	O/C					
SN:1332	HRS	2339		TSN 0				
WC#: 35.045	AFL	2040		TSN 0				
PROC. REF: GENERIC NO REF								
351031	PILOT OXYGEN MASK (OVERHAUL)							Component ATA:35
PN:MC10-14-124	MOS	06-Apr-22	72	TSO 0	06-Apr-28		1403 d	OVERHAUL
SN:87306	HRS	8213.1		TSO 0				
WC#: 35.050	AFL	6712		TSO 0				
351032	COPILOT OXYGEN MASK (OVERHAUL)							Component ATA:35
PN:MC10-14-124	MOS	06-Apr-22	72	TSO 0	06-Apr-28		1403 d	OVERHAUL
SN:18596	HRS	8213.1		TSO 0				
WC#: 35.050	AFL	6712		TSO 0				
351035	PASSENGER OXYGEN MASKS (OVERHAUL)							Component ATA:35
PN:289-601	MOS	21-May-17	72	TSN 0	21-May-23		OVD	OVERHAUL
SN:UNKNOWN	HRS	7267.9		TSN 0				
WC#: 35.140	AFL	6086		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351043	LEFT OXYGEN OUTLET VALVE							Component ATA:35
PN:DPB181	MOS/MSC	06-Mar-96	O/C					
SN:22024	HRS	0		TSN 0				
WC#: 35.055	AFL	0						
PROC. REF: GENERIC NO REF								
351044	RIGHT OXYGEN OUTLET VALVE							Component ATA:35
PN:DPB181	MOS/MSC	06-Mar-96	O/C					
SN:22028	HRS	0		TSN 0				
WC#: 35.055	AFL	0						
PROC. REF: GENERIC NO REF								
351101	NO. 1 OXYGEN CYLINDER							Component ATA:35
PN:WKA37447	MOS/MSC	04-Sep-20	O/C					
SN:642735	HRS	7896.7						
WC#: 35.010	AFL	6498						
PROC. REF: AMM 35-10-14								
351102	NO. 2 OXYGEN CYLINDER							Component ATA:35
PN:WKA37447	MOS/MSC	04-Sep-20	O/C					
SN:1635	HRS	7896.7						
WC#: 35.015	AFL	6498						
PROC. REF: AMM 35-10-14								
351103	NO. 3 OXYGEN CYLINDER							Component ATA:35
PN:176531-35	MOS/MSC	28-Feb-19	O/C					
SN:366326/3612	HRS	7708						
WC#: 35.020	AFL	6372						
PROC. REF: AMM 35-10-14, MMA 35-06-01								
351110	HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER							Service ATA:35
PN:WKA37447	MOS	16-Jul-20	60		16-Jul-25		408 d	
SN:642735	HRS							
WC#: 35.010	AFL							
PROC. REF: GENERIC CMM								
351110	HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER							Service ATA:35
PN:WKA37447	MOS	30-Jul-20	60		30-Jul-25		422 d	
SN:1635	HRS							
WC#: 35.015	AFL							
PROC. REF: GENERIC CMM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351110	HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER							Service ATA:35
PN:176531-35	MOS	27-Feb-19	60		27-Feb-24		OVD	
SN:366326/3612	HRS							
WC#: 35.020	AFL							
PROC. REF: GENERIC CMM								
352001	ON/OFF OXYGEN VALVE							Component ATA:35
PN:SDV1012	MOS/MSC	06-Mar-96	O/C					
SN:9180	HRS	0		TSN 0				
WC#: 35.065	AFL	0						
PROC. REF: GENERIC NO REF								
352007	BAROMATIC VALVE							Component ATA:35
PN:K38002/1	MOS/MSC	03-Oct-96	O/C					
SN:528	HRS	23						
WC#: 35.070	AFL	14						
PROC. REF: AMM 35-20-42								
353001	PORTABLE OXYGEN BOTTLE							Component ATA:35
PN:176965-SMB3	MOS/MSC	04-Sep-20	O/C	TSO 0				
SN:367803	HRS	7896.7		TSO 0				
WC#: 35.080	AFL	6498		TSO 0				
PROC. REF: GENERIC NO REF								
353007	HYDROSTATIC TEST PORTABLE OXYGEN BOTTLE							Service ATA:35
PN:176965-SMB3	MOS	26-Jun-20	60		26-Jun-25		388 d	MANDATORY
SN:367803	HRS							
WC#: 35.080	AFL							
PROC. REF: GENERIC NO REF								
353031	(PBE) PROTECTIVE BREATHING EQUIPMENT (LIFE LIMIT)							Component ATA:35
PN:802300-14	MOS	11-Jun-21	120		09-Jun-31		2562 d	LIFE LIMIT
SN:E21050629	HRS	8087.8		TSN 0				
WC#: 35.085	AFL	6639		TSN 0				
Manufacture Date:: 09-Jun-21			PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
380001 ^S	INSPECT TOILET AND GALLEY WATER SYSTEMS							Service ATA:38
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 38.010	AFL	6498						
	PROC. REF: AMM 12-38-00							PKG:2
ATA 49 - AIRBORNE AUXILIARY POWER								
490001	INSPECT PATS APU GTCP36-150W							Service ATA:49
	MOS	17-Nov-23	12 (+1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1						
WC#: 49.205	AFL	6799						
	APH	5335.5	750		6085,5		730,5	
490002	REMOVE/CLEAN/INSPECT APU IGNITER PLUG							Service ATA:49
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 49.210	AFL	6498						
	APH	5053,3	750		5803,3		448,3	
490003	ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION							Service ATA:49
	MOS/MSC	26-Dec-22	N/R					
	HRS	8299.1						
WC#: 49.220	AFL	6753						
490003	ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK							Service ATA:49
	MOS	17-Nov-23	12 (+1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1						
WC#: 49.221	AFL	6799						
	APH	5335.5	750		6085,5		730,5	
490004	REMOVE AND REPLACE APU FUEL FILTER ELEMENT							Service ATA:49
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 49.230	AFL	6498						
	APH	5053,3	1000		6053,3		698,3	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490005	FLOW CHECK APU FUEL NOZZLE ASSEMBLIES							Service ATA:49
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 49.240	AFL	6498						
	APH	5053.3	4500		9553.3		4198.3	
490006	ACCOMPLISH APU DETAILED HOT SECTION INSPECTION							Service ATA:49
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 49.250	AFL	6498						
	APH	5053.3	4500		9553.3		4198.3	
490007	VISUALLY CHECK APU COMPRESSOR ROTOR							Service ATA:49
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 49.260	AFL	6498						
	APH	5053.3	4500		9553.3		4198.3	
491005	APU BLEED AIR CHECK VALVE							Component ATA:49
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
491010	APU - TURBINE ROTOR (LIFE LIMIT)							Component ATA:49
PN:3615880-1	MOS	12-Sep-99						LIFE LIMIT
SN:960134501247	HRS	1060	10000	TSN 1060	10000		4645	
WC#: 49.010	APUS	1919		TSN 1919				
PROC. REF: GENERIC NO REF								
491020	APU - COMPRESSOR ROTOR (LIFE LIMIT)							Component ATA:49
PN:3822101-1	MOS	12-Sep-99						LIFE LIMIT
SN:960350100741	HRS	1060	100000	TSN 1060	100000		94645	
WC#: 49.015	APUS	1919		TSN 1919				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
491025 ^S	APU - INSPECT COMPRESSOR ROTOR							Service ATA:49
PN:3822101-1	MOS	04-Sep-20						
SN:960350100741	HRS	5053.3	4500					
WC#: 49.020	APUS	8690						
PROC. REF: MM 49-20-00								
491030 ^S	APU - INSPECT HOT SECTION							Service ATA:49
	MOS	04-Sep-20						
	HRS	5053.3	4500					
WC#: 49.025	APUS	8690						
PROC. REF: MM 49-20-00								
493010	APU - FUEL CONTROL							Component ATA:49
PN:3882730-9	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:16409	HRS	1060		TSN 0				
WC#: 49.030	APUS	1919		TSN 0				
PROC. REF: MM 49-30-52								
493020 ^S	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:49
	MOS	04-Sep-20						
	HRS	5053.3	1000					
WC#: 49.035	APUS	8690						
PROC. REF: MM 49-30-52								
493030	APU - ORIFICE FITTING							Component ATA:49
PN:3606721-1	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.040	APUS	1919		TSN 0				
PROC. REF: MM 49-30-56								
493040	APU - FUEL SHUTOFF VALVE							Component ATA:49
PN:692545-17	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.045	APUS	1919		TSN 0				
PROC. REF: MM 49-30-54								
493050 ^S	APU - CHECK FUEL NOZZLE FLOW RATE							Service ATA:49
	MOS	04-Sep-20						
	HRS	5053.3	4500					
WC#: 49.050	APUS	8690						
PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493060	APU - CONTROLLER							Component ATA:49
PN:2118330-2	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:16-80084	HRS	1060		TSN 0				
WC#: 49.055	APUS	1919		TSN 0				
PROC. REF: MM 49-60-46								
493070	APU - LOAD CONTROL VALVE							Component ATA:49
PN:109812-9	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:2231	HRS	1060		TSN 0				
WC#: 49.060	APUS	1919		TSN 0				
PROC. REF: MM 49-50-33								
494010	APU - IGNITION UNIT							Component ATA:49
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 49.065	APUS							
PROC. REF: MM 49-40-32								
494020	APU - IGNITER PLUG							Component ATA:49
PN:3888002-2 - CH34313	MOS/MSC	08-Mar-15	O/C	TSN 0				
SN:UNKNOWN	HRS	3921.6		TSN 0				
WC#: 49.070	APUS	7293		TSN 0				
PROC. REF: MM 49-40-33								
494030 ^S	APU - REMOVE AND INSPECT IGNITER PLUG							Service ATA:49
PN:3888002-2 - CH34313	MOS	04-Sep-20						
SN:UNKNOWN	HRS	5053.3	750					
WC#: 49.075	APUS	8690						
PROC. REF: MM 49-40-33								
497010	APU - MOTION PICK UP TRANSDUCER							Component ATA:49
PN:3876104-1	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.080	APUS	1919		TSN 0				
PROC. REF: MM 49-60-43								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
497020	APU - IMMERSION THERMOCOUPLE							Component ATA:49
PN:3876003-3	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.085	APUS	1919		TSN 0				
PROC. REF: MM 49-60-45								
497030	APU - HOURMETER							Component ATA:49
PN:3888126-1	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.090	APUS	1919		TSN 0				
PROC. REF: MM 49-70-41								
499010	APU - ROTARY OIL PUMP							Component ATA:49
PN:3880225-2	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.095	APUS	1919		TSN 0				
PROC. REF: MM 49-90-51								
499020	APU - INSPECT MAGNETIC DRAIN PLUG							Service ATA:49
	MOS	17-Nov-23	12		17-Nov-24		167 d	
	HRS	5335.5	750		6085.5		730.5	
WC#: 49.100	APUS							
PROC. REF: MM 49-90-46								
499030	APU - CHANGE OIL							Service ATA:49
	MOS/MSC	26-Dec-22	O/C					
	HRS	5317.6						
WC#: 49.105	APUS							
PROC. REF: MM 49-20-00								
499040	APU - REMOVE AND REPLACE OIL FILTER ELEMENT							Service ATA:49
	MOS	17-Nov-23	12		17-Nov-24		167 d	
	HRS	5335.5	750		6085.5		730.5	
WC#: 49.110	APUS							
PROC. REF: MM 49-90-47								
499050	APU - PRESSURE REGULATOR VALVE							Component ATA:49
PN:3880021-13	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.115	APUS	1919		TSN 0				
PROC. REF: MM 49-90-52								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
499060	APU - HIGH OIL TEMPERATURE SWITCH							Component ATA:49
PN:3888030-1	MOS/MSC	12-Sep-99	O/C	TSN 0				
SN:UNKNOWN	HRS	1060		TSN 0				
WC#: 49.120	APUS	1919		TSN 0				
PROC. REF: MM 49-60-46								
499070	APU - LOW OIL PRESSURE SWITCH							Component ATA:49
PN:3876001-8	MOS/MSC	24-Oct-18	O/C	TSN 0				
SN:UNKNOWN	HRS	4863.2		TSN 0				
WC#: 49.125	APUS	8424		TSN 0				
PROC. REF: MM 49-60-43								
499110	APU - SOAP CHECK OIL							Service ATA:49
	MOS	17-Nov-23						
	HRS	5335.5	500 (+20%/-20%)		5835.5	5935.5	480.5 (+100)	
WC#: 49.130	APUS							
49APU1	APU							Component ATA:49
PN:3800304-1	MOS/MSC		E/C					
SN:P-284	HRS							
WC#: 49.APU1	AFL							
PROC. REF: AMM 49-16-00								
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
510001	INSPECT/NDT NOSE LANDING GEAR BAY SIDEWALLS							Service ATA:51
	MOS	16-May-16	144 (+3m)		16-May-28	16-Aug-28	1443 d (+92)	
	HRS	6937						
WC#: 51.100	AFL	5906	5000 (+10%)		10906	11406	4079 (+500)	
PROC. REF: NTM 53-10-10								
510002	DETAIL INSPECT FRONT PRESSURE BULKHEAD							Service ATA:51
	MOS	04-Sep-20						
	HRS	7896.7						
WC#: 51.010	AFL	6498	1000 (+10%)		7498	7598	671 (+100)	
510003	INSPECT/NDT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS							Service ATA:51
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 51.020	AFL	6498						
PROC. REF: NTM 53-10-30, NTM 53-10-35								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
510004	DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS							Service ATA:51
	MOS	14-Oct-96						
	HRS	35		TAC 35				
WC#: 51.030	AFL	20	20000 (+500)	TAC 20	20000	20500	13173 (+500)	
510005	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19							Service ATA:51
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 51.040	AFL	6498						
PROC. REF: NTM 53-10-45								
510006	DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14							Service ATA:51
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 51.050	AFL	6498						
510007	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17							Service ATA:51
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 51.060	AFL	6498						
PROC. REF: NTM 53-10-45								
510008	X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16							Service ATA:51
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 51.070	AFL	6498						
PROC. REF: NTM 53-10-45								
510009	DETAIL INSPECT ENTRY DOOR SURROUND							Service ATA:51
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 51.080	AFL	6498						
510010	INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR							Service ATA:51
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 51.090	AFL	6498						
PROC. REF: NTM 53-10-40								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
520004 ^S	CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES							Service ATA:52
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 52.025	AFL	6753						
PROC. REF: AMM NO REF-1								PKG:3
520005 ^S	CHECK ESCAPE HATCH RELEASE MECHANISM							Service ATA:52
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 52.015	AFL	6498						
PROC. REF: AMM NO REF-1								PKG:2
520006 ^S	INSPECT ESCAPE HATCH SEALS							Service ATA:52
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 52.035	AFL	6498						
								PKG:2
520007 ^S	INSPECT/CHECK ENTRY DOOR							Service ATA:52
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 52.010	AFL	6753						
PROC. REF: AMM 52-11-00								PKG:3
520008	INSPECT/NDT MAIN ENTRY DOOR							Service ATA:52
	MOS	16-May-16	96 (+3m)		16-May-24	16-Aug-24	TOL (+74 d)	
	HRS	6937						
WC#: 52.010	AFL	5906						
PROC. REF: NTM 52-80-10								
520009	DETAIL INSPECT ESCAPE HATCH							Service ATA:52
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 52.015	AFL	6498						
520010 ^S	INSPECT MAIN ENTRY DOOR - FOLDING HANDRAIL (IF FITTED)							Service ATA:52
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 52.050	AFL	6753						
PROC. REF: MMA 52-15-00								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
521001	MAIN ENTRY DOOR ASSEMBLY							Component ATA:52
PN:25.FC7905A/C	MOS/MSC	06-Mar-96	O/C					
SN:SDDH167	HRS	0		TSN 0				
WC#: 52.010	AFL	0						
PROC. REF: AMM 52-11-00								
521016	LONG RANGE TANK DOOR							Component ATA:52
PN:25.8PT111-87A	MOS/MSC	06-Mar-96	O/C					
SN:SDDH110	HRS	0		TSN 0				
WC#: 52.055	AFL	0						
PROC. REF: GENERIC NO REF								
522001	ESCAPE HATCH							Component ATA:52
PN:25.8FC461-161A	MOS/MSC	06-Mar-96	O/C					
SN:DHB048	HRS	0		TSN 0				
WC#: 52.015	AFL	0						
PROC. REF: AMM 52-20-00								
ATA 53 - FUSELAGE								
530001	DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19							Service ATA:53
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 53.115	AFL	6498						
530002	INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS							Service ATA:53
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 53.040	AFL	6498						
530003	DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).							Service ATA:53
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 53.110	AFL	6498						
530004	DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)							Service ATA:53
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 28.015	AFL	6498						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
530007	DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS							Service ATA:53
	MOS	16-May-16	96 (+3m)		16-May-24	16-Aug-24	TOL (+74 d)	
	HRS	6937						
WC#: 53.105	AFL	5906						
PROC. REF: AMM 53-40-01								
530009	INSPECT/NDT FUSELAGE LAP JOINTS							Service ATA:53
	MOS	14-Oct-96						
	HRS	35						
WC#: 53.125	AFL	20	T:27000 (+500)		27020	27520	20193 (+500)	
PROC. REF: NTM 53-10-25								
530010	DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING							Service ATA:53
	MOS/MSC		A/R					
	HRS	0						
WC#: 53.020	AFL							
530011	INSPECT LEFT-HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)							Service ATA:53
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 53.175	AFL	6498						
530012	INSPECT RIGHT- HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)							Service ATA:53
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 53.070	AFL	6498						
530013	INSPECT/NDT NO. 1 ENGINE MOUNTING PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS							Service ATA:53
	MOS	14-Oct-96						
	HRS	0	10000 (+500)	TAC 35	9965	10465	1524.1 (+500)	
WC#: 53.030	AFL	0		TAC 20				
PROC. REF: NTM 53-10-05								
530014	INSPECT/NDT REAR ENGINE MOUNT FITTINGS							Service ATA:53
	MOS	14-Oct-96						
	HRS	0	20000 (+500)	TAC 35	19965	20465	11524.1 (+500)	
WC#: 53.035	AFL	0		TAC 20				
PROC. REF: NTM 53-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
530015	INSPECT/NDT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE							Service ATA:53
	MOS	14-Oct-96						
	HRS	0	30000 (+500)	TAC 35	29965	30465	21524.1 (+500)	
WC#: 53.015	AFL	0		TAC 20				
			PROC. REF: NTM 55-30-20					
530016	DETAIL INSPECT NO. 1 ENGINE MOUNTING ENGINE BEAM							Service ATA:53
	MOS	14-Oct-96						
	HRS	0	10000 (+500)		10000	10500	1559.1 (+500)	
WC#: 53.080	AFL	0						
530017	INSPECT NO. 1 ENGINE MOUNTING BRACKETS							Service ATA:53
	MOS/MSC	02-Feb-19	E/C					PART OF MPI
	HRS	7707.2						
WC#: 53.200	AFL	6370						
530017	INSPECT NO. 2 ENGINE MOUNTING BRACKETS							Service ATA:53
	MOS/MSC	02-Sep-13	E/C					PART OF MPI
	HRS	6080.9						
WC#: 53.200	AFL	5386						
530018	DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS							Service ATA:53
	MOS	17-Nov-23						
	HRS	8393.1	2400 (+10%)		10793.1	11033.1	2352.2 (+240)	
WC#: 53.205	AFL	6799						
530019	DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE							Service ATA:53
	MOS	17-Nov-23	12 (+1m)		17-Nov-24	17-Dec-24	167 d (+30)	
	HRS	8393.1						
WC#: 53.210	AFL	6799						
530021	DETAIL INSPECT APU SUPPORT STRUCTURE							Service ATA:53
	MOS	10-Jul-15						
	HRS	6667.8						
WC#: 53.010	AFL	5769						
	APH	4016.5	3000		7016.5		1661.5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
530022	DETAIL INSPECT APU MOUNTING HARDWARE							Service ATA:53
	MOS	21-Mar-17						
	HRS	7214.7						
WC#: 53.215	AFL	6054						
	APH	4428.2	4500		8928.2		3573.2	
PROC. REF: AMS 5-20-09								
530023	DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS							Service ATA:53
	MOS	21-Mar-17						
	HRS	7214.7						
WC#: 53.220	AFL	6054						
	APH	4428.2	4500		8928.2		3573.2	
530024	FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE							Service ATA:53
	MOS							
	HRS	0						
WC#: 53.225	AFL							
	APH	0	22500		22500		17145	
PROC. REF: AMS 5-20-09								
530025	DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS							Service ATA:53
	MOS	06-Mar-96						
	HRS	0						
WC#: 53.170	AFL	0	10000 (+500)		10000	10500	3173 (+500)	
530027 ^S	VISUAL INSPECTION FUSELAGE SKIN							Service ATA:53
	MOS	04-Sep-20	48 (+2m/-2m)					
	HRS	7896.7						
WC#: 53.235	AFL	6498						
PKG:7								
531146	RADOME							Component ATA:53
PN:25.8RF13-1A	MOS/MSC	06-Mar-96	O/C					
SN:DHB336	HRS	0		TSN 0				
WC#: 53.135	AFL	0						
PROC. REF: AMM 53-50-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
531152	TAIL CONE FAIRING							Component ATA:53
PN:25.8GF/Z27-1A	MOS/MSC	06-Mar-96	O/C					
SN:FL169	HRS	0		TSN 0				
WC#: 53.140	AFL	0						
PROC. REF: AMM 53-50-16								
531154	FUSELAGE							Component ATA:53
PN:25.8FA1	MOS/MSC	06-Mar-96	O/C					
SN:258293	HRS	0		TSN 0				
WC#: 53.145	AFL	0						
PROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
550001	DETAIL INSPECT ELEVATORS AND TABS							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 27.070	AFL	6498						
550002	LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 55.075	AFL	6498						
PROC. REF: AMM 27-30-00								
550003	XRAY ELEVATORS							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 55.055	AFL	6498						
PROC. REF: NTM 55-20-10								
550004	DETAIL INSPECT RUDDER AND TAB							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 27.045	AFL	6498						
PROC. REF: AMM NO REF-1								
550005	INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 55.065	AFL	6498						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
550006	X-RAY RUDDER (IN-SITU)							Service ATA:55
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 27.045	AFL	6498						
PROC. REF: NTM 55-40-05								
550007	DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS							Service ATA:55
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 27.045	AFL	6498						
550008 ^S	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING							Service ATA:55
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 55.010	AFL	6753						
PKG:6								
550009	DETAIL INSPECT HORIZONTAL STABILIZER							Service ATA:55
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 55.040	AFL	6498						
PROC. REF: AMM 55-13-00								
550010	INSPECT/NDT VERTICAL STABILIZER							Service ATA:55
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 55.050	AFL	6498						
PROC. REF: NTM 55-30-05, NTM 55-30-10, NTM 55-30-15								
550011	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS							Service ATA:55
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 55.025	AFL	6498						
550012	INSPECT/NDT HORIZONTAL STABILIZER							Service ATA:55
	MOS	18-Sep-20	96 (+3m)		18-Sep-28	18-Dec-28	1568 d (+91)	
	HRS	7897						
WC#: 55.045	AFL	6499						
PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
550013	X-RAY HORIZONTAL STABILIZER							Service ATA:55
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7						
WC#: 55.035	AFL	6498						
PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15, NTM 55-10-20								
550014	DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER							Service ATA:55
	MOS	14-Oct-96						
	HRS	35						
WC#: 55.060	AFL	20	T:15000 (+500)		15020	15520	8193 (+500)	
550015	INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS							Service ATA:55
	MOS	11-Jan-23	24 (+2m)		11-Jan-25	11-Mar-25	222 d (+59)	
	HRS	8299.1						
WC#: 55.070	AFL	6753						
551004	UPPER VERTICAL STABILIZER							Component ATA:55
PN:25.8TF513/1A	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:FL/DHB/8298	HRS	0		TSN 0				
WC#: 55.015	AFL	0		TSN 0				
PROC. REF: AMM 55-32-00								
551006	TAILPLANE							Component ATA:55
PN:25.8TP257-1A	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:FL/DHB/8298	HRS	0		TSN 0				
WC#: 55.020	AFL	0		TSN 0				
551010	BULLET FAIRING							Component ATA:55
PN:25.8GF173-1A	MOS/MSC	06-Mar-96	O/C					
SN:087	HRS	0		TSN 0				
WC#: 55.030	AFL	0						
ATA 56 - WINDOWS								
560004 ^S	INSPECT WINDOWS DRY-AIR SYSTEM FILTER ELEMENT (IF FITTED)							Service ATA:56
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 56.065	AFL	6753						
PROC. REF: AMM 56-00-00								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
560005 ^S	CHECK PASSENGER CABIN WINDOWS							Service ATA:56
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 56.090	AFL	6498						
PROC. REF: AMM 56-00-00							PKG:2	
560006 ^S	INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER							Service ATA:56
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 56.070	AFL	6498						
							PKG:2	
560007 ^S	SCREEN HEAT CIRCUIT BREAKERS - DO A VISUAL INSPECTION FOR HEAT DISTRESS, DISCOLORATION AND DEFORMATION							Service ATA:56
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
	AFL	6753						
							PKG:6	
561001	LEFT (PANEL A) HEATED WINDSCREEN							Component ATA:56
PN:NH24016-415	MOS/MSC	04-Sep-20	O/C	TSN 0				
SN:L521100	HRS	7896.7		TSN 0				
WC#: 56.010	AFL	6498		TSN 0				
PROC. REF: AMM 56-10-11								
561002	RIGHT (PANEL A) HEATED WINDSCREEN							Component ATA:56
PN:NF24016-416	MOS/MSC	23-May-21	O/C	TSN 0				
SN:L546079	HRS	8062.9		TSN 0				
WC#: 56.010	AFL	6622		TSN 0				
PROC. REF: AMM 56-10-11								
561003	LEFT DIRECT VIEW B WINDOW							Component ATA:56
PN:NH24016-91	MOS/MSC	26-Nov-16	O/C	TSN 0				
SN:L459002	HRS	7089.5		TSN 0				
WC#: 56.015	AFL	5984		TSN 0				
PROC. REF: AMM 56-10-22								
561004	RIGHT DIRECT VIEW B WINDOW							Component ATA:56
PN:NH24016-92	MOS/MSC	03-May-12	O/C	TSN 0				
SN:L382250	HRS	5599.6		TSN 0				
WC#: 56.015	AFL	4994		TSN 0				
PROC. REF: AMM 56-10-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561005	LEFT C WINDOW							Component ATA:56
PN:25-8FN353-41A	MOS/MSC	07-Feb-03	O/C					
SN:L328519	HRS	2982.3						
WC#: 56.020	AFL	2848						
PROC. REF: AMM 56-10-31								
561006	RIGHT C WINDOW							Component ATA:56
PN:25-8FN353-44A	MOS/MSC	09-Mar-09	O/C	TSO 0				
SN:234360	HRS	4670		TSO 0				
WC#: 56.020	AFL	4415		TSO 0				
PROC. REF: AMM 56-10-31								
562001	NO. 1 LEFT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6289	HRS	0		TSN 0				
WC#: 56.025	AFL	0						
PROC. REF: AMM 56-20-11								
562002	NO. 1 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6286	HRS	0		TSN 0				
WC#: 56.025	AFL	0						
PROC. REF: AMM 56-20-11								
562003	NO. 2 LEFT CABIN WINDOW							Component ATA:56
PN:25FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6293	HRS	0		TSN 0				
WC#: 56.030	AFL	0						
PROC. REF: AMM 56-20-11								
562004	NO. 2 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6259	HRS	0		TSN 0				
WC#: 56.030	AFL	0						
PROC. REF: AMM 56-20-11								
562005	NO. 3 LEFT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6288	HRS	0		TSN 0				
WC#: 56.035	AFL	0						
PROC. REF: AMM 56-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562006	NO. 3 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6287	HRS	0		TSN 0				
WC#: 56.035	AFL	0						
PROC. REF: AMM 56-20-11								
562007	NO. 4 LEFT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6290	HRS	0		TSN 0				
WC#: 56.040	AFL	0						
PROC. REF: AMM 56-20-11								
562008	NO. 4 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6061	HRS	0		TSN 0				
WC#: 56.040	AFL	0						
PROC. REF: AMM 56-20-11								
562009	NO. 5 LEFT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6292	HRS	0		TSN 0				
WC#: 56.045	AFL	0						
PROC. REF: AMM 56-20-11								
562010	NO. 5 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6294	HRS	0		TSN 0				
WC#: 56.045	AFL	0						
PROC. REF: AMM 56-20-11								
562011	NO. 6 LEFT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6291	HRS	0		TSN 0				
WC#: 56.050	AFL	0						
PROC. REF: AMM 56-20-11								
562012	NO. 6 RIGHT CABIN WINDOW							Component ATA:56
PN:25.FC7881-41A	MOS/MSC	06-Mar-96	O/C					
SN:DHB6295	HRS	0		TSN 0				
WC#: 56.050	AFL	0						
PROC. REF: AMM 56-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570001 ^S	INSPECT LEFT FLAP HINGE FITTINGS							Service ATA:57
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 57.095	AFL	6498						
								PKG:2
570002 ^S	INSPECT RIGHT FLAP HINGE FITTINGS							Service ATA:57
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 57.095	AFL	6498						
								PKG:2
570003 ^S	DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service ATA:57
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 57.090	AFL	6753						
								PKG:6
570005 ^S	DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service ATA:57
	MOS	11-Jan-23	24 (+2m/-2m)					
	HRS	8299.1						
WC#: 57.090	AFL	6753						
								PKG:6
570007	X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 57.040	AFL	6498						
PROC. REF: NTM 57-30-05								
570008	DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 57.035	AFL	6498						
570009	DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8							Service ATA:57
	MOS	29-Sep-21						
	HRS	8145.1	1200 (+10%)	Adj -8.1	9337	9457	896.1 (+120)	
WC#: 57.070	AFL	6676						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570010	DETAIL INSPECT WING FRONT SPAR, FORWARD FACE							Service ATA:57
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7	4800 (+10%)		12696.7	13176.7	4255.8 (+480)	
WC#: 57.020	AFL	6498						
PROC. REF: MMS 57-00-00, MMS 57-00-00								
570011	INSPECT WING REAR SPAR, REAR FACE							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 57.030	AFL	6498						
570012	DETAIL INSPECT LEFT LOWER AIRBRAKE							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 27.240	AFL	6498						
570012	DETAIL INSPECT LEFT UPPER AIRBRAKE							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 27.240	AFL	6498						
570012	DETAIL INSPECT RIGHT LOWER AIRBRAKE							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 27.245	AFL	6498						
570012	DETAIL INSPECT RIGHT UPPER AIRBRAKE							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 27.245	AFL	6498						
570013	DETAIL INSPECT AILERONS							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 27.020	AFL	6498						
PROC. REF: AMM NO REF-1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570014	LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 57.145	AFL	6498						
570015	INSPECT/X RAY AILERONS							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 57.100	AFL	6498						
PROC. REF: NTM 57-50-25								
570016	INSPECT/X RAY FLAPS AND FLAP VANES							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7	2400 (+10%)		10296.7	10536.7	1855.8 (+240)	
WC#: 57.130	AFL	6498						
PROC. REF: NTM 57-50-15, NTM 57-50-20								
570017	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7							Service ATA:57
	MOS	14-Oct-96						
	HRS	0	T:24000 (+500)		24000	24500	15559.1 (+500)	
WC#: 57.055	AFL	0						
PROC. REF: MMS 57-00-00								
570018	DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP							Service ATA:57
	MOS	14-Oct-96						
	HRS	0	T:24000 (+500)		24000	24500	15559.1 (+500)	
WC#: 57.080	AFL	0						
PROC. REF: MMS 57-00-00								
570019	INSPECT/NDT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0							Service ATA:57
	MOS	14-Oct-96						
	HRS	0	T:24000 (+500)		24000	24500	15559.1 (+500)	
WC#: 57.060	AFL	0						
PROC. REF: NTM 57-30-15, MMS 57-00-00								
570020	INSPECT/NDT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)							Service ATA:57
	MOS	14-Oct-96						
	HRS	0	T:24000 (+500)		24000	24500	15559.1 (+500)	
WC#: 57.075	AFL	0						
PROC. REF: NTM 57-00-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570021	DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS.							Service ATA:57
	MOS/MSC		A/R					
	HRS	0						
WC#: 57.010	AFL							
570022	DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH							Service ATA:57
	MOS	17-Jun-04						
	HRS	3568	4800 (+10%)		8368	8848	TOL (+407.1)	
WC#: 57.050	AFL	3587						
PROC. REF: MMS 57-00-00								
570023	INSPECT/NDT AILERON HORN BALANCE WEIGHT							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 57.135	AFL	6498						
PROC. REF: NTM 57-50-25, MMS 57-00-00								
570024	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH							Service ATA:57
	MOS							
	HRS		T:12000 (+500)		12000	12500	3559.1 (+500)	
WC#: 57.065	AFL							
PROC. REF: MMS 57-00-00								
570025	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH							Service ATA:57
	MOS	17-Jun-04						
	HRS	3568	4800 (+10%)		8368	8848	TOL (+407.1)	
WC#: 57.050	AFL	3587						
PROC. REF: MMS 57-00-00								
570026	INSPECT WING LEADING EDGES							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 57.025	AFL	6498						
570027	DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP							Service ATA:57
	MOS	04-Sep-20	96 (+3m)		04-Sep-28	04-Dec-28	1554 d (+91)	
	HRS	7896.7	4800 (+10%)		12696.7	13176.7	4255.8 (+480)	
WC#: 57.045	AFL	6498						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570028	INSPECT AILERON AT OUTBOARD HINGE CASTING							Service ATA:57
	MOS	04-Sep-20	48 (+3m)		04-Sep-24	04-Dec-24	93 d (+91)	
	HRS	7896.7						
WC#: 57.125	AFL	6498						
PROC. REF: AMM 27-10-31								
571010	WING							Component ATA:57
PN:25.8WS1	MOS/MSC	05-Sep-00	O/C					
SN:DHB8292	HRS	2336.3						
WC#: 57.010	AFL	2029						
PROC. REF: GENERIC NO REF								
571109	REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS							Service ATA:57
	MOS	06-Mar-96						LIFE LIMIT
	HRS	0						
WC#: 57.150	AFL	0	14600		14600		7773	
571110	REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS							Service ATA:57
	MOS	06-Mar-96						LIFE LIMIT
	HRS	0						
WC#: 57.150	AFL	0	14600		14600		7773	
574001	LEFT LEADING EDGE ASSEMBLY							Component ATA:57
PN:25.8WS3299-3A	MOS/MSC	06-Mar-96	O/C					
SN:AST95L328	HRS	0		TSN 0				
WC#: 57.085	AFL	0						
PROC. REF: GENERIC NO REF								
574002	RIGHT LEADING EDGE ASSEMBLY							Component ATA:57
PN:25.8WS3299-4A	MOS/MSC	06-Mar-96	O/C					
SN:AST95L330	HRS	0		TSN 0				
WC#: 57.085	AFL	0						
PROC. REF: GENERIC NO REF								
ATA 71 - POWER PLANT								
710049	COMPRESSOR WASH NO. 1 ENGINE							Service ATA:71
	MOS/MSC	21-Dec-99	O/C					
	HRS	2185						
WC#: 71.025	AFL							
PROC. REF: GENERIC CMM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710050	COMPRESSOR WASH NO. 2 ENGINE							Service ATA:71
	MOS/MSC	22-Nov-97	O/C					
	HRS	776						
WC#: 71.025	AFL							
PROC. REF: GENERIC CMM								
710081	NO. 1 ENGINE INLET COWL							Component ATA:71
PN:C46B-11000-21	MOS/MSC	06-Mar-96	O/C					
SN:B-132	HRS	0		TSN 0				
WC#: 71.055	AFL	0						
PROC. REF: AMM 71-10-00								
710082	NO. 2 ENGINE INLET COWL							Component ATA:71
PN:C46B-11000-22	MOS/MSC	06-Mar-96	O/C					
SN:B-132	HRS	0		TSN 0				
WC#: 71.055	AFL	0						
PROC. REF: AMM 71-10-00								
710083	NO. 1 ENGINE UPPER FAN COWL DOOR							Component ATA:71
PN:C46B-14000-3	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.060	AFL	0						
PROC. REF: AMM 71-10-00								
710084	NO. 2 ENGINE UPPER FAN COWL DOOR							Component ATA:71
PN:C46B-14000-3	MOS/MSC	06-Mar-96	O/C					
SN:B-132	HRS	0		TSN 0				
WC#: 71.060	AFL	0						
PROC. REF: AMM 71-10-00								
710089	NO. 1 ENGINE LOWER FAN COWL DOOR							Component ATA:71
PN:C46B-15000-21	MOS/MSC	06-Mar-96	O/C					
SN:B-133	HRS	0		TSN 0				
WC#: 71.070	AFL	0						
PROC. REF: AMM 71-10-00								
710090	NO. 2 ENGINE LOWER FAN COWL DOOR							Component ATA:71
PN:C46B-15000-23	MOS/MSC	06-Mar-96	O/C					
SN:B-133	HRS	0		TSN 0				
WC#: 71.070	AFL	0						
PROC. REF: AMM 71-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712001	NO. 1 ENGINE MOUNTING							Component ATA:71
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.075	AFL	0		TSN 0				
712002	NO. 2 ENGINE MOUNTING							Component ATA:71
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.080	AFL	0		TSN 0				
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service ATA:71
	MOS	16-Jan-19						
	HRS	7401.1	800					
WC#: 71.030	ENC							
PROC. REF: GENERIC NO REF								PKG:4
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service ATA:71
	MOS	04-Sep-20						
	HRS	7087.8	800					
WC#: 71.030	ENC	5734						
PROC. REF: GENERIC NO REF								PKG:4
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service ATA:71
	MOS	16-Jan-19						
	HRS	7401.1	800					
WC#: 71.040	ENC							
PROC. REF: GENERIC NO REF								PKG:4
715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service ATA:71
	MOS	04-Sep-20						
	HRS	7087.8	800					
WC#: 71.040	ENC	5734						
PROC. REF: GENERIC NO REF								PKG:4
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3075160-4	MOS/MSC	02-Feb-19	E/C					
SN:P-107136	HRS	7707.2		TSN 7401.1				
	AFL	6370						
PROC. REF: AMM 71-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:3075160-4	MOS/MSC	08-Aug-07	E/C					
SN:P-107238	HRS	4384.4		TSN 3575.6				
	AFL	4223						
PROC. REF: AMM 71-00-01								
ATA 72 - ENGINE								
720002	INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service ATA:72
	MOS	01-Feb-19						PART OF MPI
	HRS	7707.2	2500 (+10%)		10207.2	10457.2	1766.3 (+250)	
WC#: 72.030	AFL	6370						
720002	INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service ATA:72
	MOS	02-Sep-13						PART OF MPI
	HRS	6080.9	2500 (+10%)		8580.9	8830.9	140 (+250)	
WC#: 72.030	AFL	5386						
720003	DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service ATA:72
	MOS	01-Feb-19						PART OF MPI
	HRS	7707.2	2500 (+10%)		10207.2	10457.2	1766.3 (+250)	
WC#: 72.040	AFL	6370						
720003	DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service ATA:72
	MOS	02-Sep-13						PART OF MPI
	HRS	6080.9	2500 (+10%)		8580.9	8830.9	140 (+250)	
WC#: 72.040	AFL	5386						
720120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:72
	MOS	16-Jan-19						
	HRS	7401.1	2500 (+100)		(9901.1) 10213.1	10001.1	1772.2 (+100)	
WC#: 71.010	ENC							
PROC. REF: LMM 72-00-00								
720120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:72
	MOS	03-Sep-13						
	HRS	5272	2500 (+100)		(7772) 8581	7872	140.1 (+100)	
WC#: 71.010	ENC	4625						
PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720130 ^S	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service ATA:72
	MOS	16-Jan-19						
	HRS	7401.1	800					
WC#: 71.020	ENC							
PROC. REF: LMM 72-00-00							PKG:4	
720130 ^S	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service ATA:72
	MOS	04-Sep-20						
	HRS	7087.8	800					
WC#: 71.020	ENC	5734						
PROC. REF: LMM 72-00-00							PKG:4	
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC		O/C					
	HRS							
WC#: 72.001	ENC							
PROC. REF: LMM 72-00-00								
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC	30-Jun-97	O/C					
	HRS	0		TAC 0				
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00								
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service ATA:72
	MOS/MSC		O/C					
	HRS							
WC#: 72.001	ENC							
PROC. REF: LMM 72-00-00								
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service ATA:72
	MOS/MSC	30-Jun-97	O/C					
	HRS	0		TAC 0				
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00								
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC		O/C					
	HRS							
WC#: 72.001	ENC							
PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC	30-Jun-97	O/C					
	HRS	0		TAC 0				
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00								
723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	16-Jan-19						
	HRS	7401.1	5000 (+200)		(12401.1) 12713.1	12601.1	4272.2 (+200)	
WC#: 72.010	ENC							
PROC. REF: LMM 72-00-00								
723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	30-Jul-07						
	HRS	3575.6	5000 (+200)		(8575.6) 9384.6	8775.6	943.7 (+200)	
WC#: 72.010	ENC	3510						
PROC. REF: LMM 72-00-00								
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component ATA:72
PN:3072443-5	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:5-22151-3654	HRS	0		TSN 0				
WC#: 72.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component ATA:72
PN:3072443-5	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:7-22151-4899	HRS	0		TSN 0				
WC#: 72.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service ATA:72
PN:3072443-5	MOS	16-Jan-19						
SN:5-22151-3654	HRS	7401.1	2500 (+100)		(9901.1) 10213.1	10001.1	1772.2 (+100)	
	ENC							
PROC. REF: LMM 72-40-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service ATA:72
PN:3072443-5	MOS	03-Sep-13						
SN:7-22151-4899	HRS	5272	2500 (+100)		(7772) 8581	7872	140.1 (+100)	
	ENC	4625						
PROC. REF: LMM 72-40-04								
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075446-2	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-03229-1146	HRS	0		TSN 0				
WC#: 72.040	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075446-2	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960322902907	HRS	0		TSN 0				
WC#: 72.040	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075425-1	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-03229-106	HRS	0		TSN 0				
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075425-1	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960322905519	HRS	0		TSN 0				
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075436-1	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-12172-0540	HRS	0		TSN 0				
WC#: 72.060	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075436-1	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.060	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075227-2	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-12172-0179	HRS	0		TSN 0				
WC#: 72.070	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: LMM 72-50-06								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC (LIFE LIMIT)							Component ATA:72
PN:3075227-2	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:961217200750	HRS	0		TSN 0				
WC#: 72.070	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: LMM 72-50-06								
725050	NO. 1 ENGINE - FAN DISC (LIFE LIMIT)							Component ATA:72
PN:3074621-4	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:4-03229-2483	HRS	0		TSN 0				
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - FAN DISC (LIFE LIMIT)							Component ATA:72
PN:3074621-4	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960322906858	HRS	0		TSN 0				
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072395-2	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-03160-155	HRS	0		TSN 0				
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072395-2	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:970316000700	HRS	0		TSN 0				
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072396-3	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:4-03160-3264	HRS	0		TSN 0				
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072396-3	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960316004519	HRS	0		TSN 0				
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072397-3	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:4-03229-2832	HRS	0		TSN 0				
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3072397-3	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:970316000975	HRS	0		TSN 0				
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3075326-3	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-03501-1524	HRS	0		TSN 0				
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 19720		12893	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC (LIFE LIMIT)							Component ATA:72
PN:3075326-3	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960350104202	HRS	0		TSN 0				
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 20764		13937	
PROC. REF: GENERIC NO REF								
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:5P9910	HRS	0		TSN 0				
WC#: 72.130	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10								
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	07-Jan-03	O/C	TSN 0				
SN:2P10466	HRS	2177.3		TSN 0				
WC#: 72.130	ENC	2118		TSN 0				
PROC. REF: LMM 72-30-10								
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER (LIFE LIMIT)							Component ATA:72
PN:3073398-2	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-23315-488	HRS	0		TSN 0				
WC#: 72.140	ENC	0	10000	TSN 0	(10000) 9720		2893	
PROC. REF: GENERIC NO REF								
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER (LIFE LIMIT)							Component ATA:72
PN:3073398-2	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:975332200082	HRS	0		TSN 0				
WC#: 72.140	ENC	0	10000	TSN 0	(10000) 10764		3937	
PROC. REF: GENERIC NO REF								
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT (LIFE LIMIT)							Component ATA:72
PN:3072545-1	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5P13694	HRS	0		TSN 0				
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 11720		4893	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT (LIFE LIMIT)							Component ATA:72
PN:3072545-1	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:97P11348	HRS	0		TSN 0				
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 12764		5937	
PROC. REF: GENERIC NO REF								
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE (LIFE LIMIT)							Component ATA:72
PN:3075579-1	MOS	12-Feb-96		TSN 0				LIFE LIMIT
SN:5-03160-263	HRS	0		TSN 0				
WC#: 72.160	ENC	0	30000	TSN 0	(30000) 29720		22893	
PROC. REF: GENERIC NO REF								
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE (LIFE LIMIT)							Component ATA:72
PN:3075579-1	MOS	30-Jun-97		TSN 0				LIFE LIMIT
SN:960316005011	HRS	0		TSN 0				
WC#: 72.160	ENC	0	30000	TSN 0	(30000) 30764		23937	
PROC. REF: GENERIC NO REF								
725150	NO. 1 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3074641-3	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:5P10412	HRS	0		TSN 0				
WC#: 72.170	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725150	NO. 2 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3074641-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:97P09651	HRS	0		TSN 0				
WC#: 72.170	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3074766	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.180	ENC	0		TSN 0				
PROC. REF: LMM 72-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3074766-1	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.180	ENC	0		TSN 0				
PROC. REF: LMM 72-50-05								
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3075406-6	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:4P7110	HRS	0		TSN 0				
WC#: 72.190	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3075406-6	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.190	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-9	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:4P10007	HRS	0		TSN 0				
WC#: 72.200	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-9	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:97P07911	HRS	0		TSN 0				
WC#: 72.200	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3074052-1	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:4P9176	HRS	0		TSN 0				
WC#: 72.210	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3074052-1	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:97P11091	HRS	0		TSN 0				
WC#: 72.210	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725230	NO. 1 ENGINE - FAN SPINNER							Component ATA:72
PN:3074623-3	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:5-13262-220	HRS	0		TSN 0				
WC#: 72.220	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF, LMM 72-70-01								
725230	NO. 2 ENGINE - FAN SPINNER							Component ATA:72
PN:3074623-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:971326200687	HRS	0		TSN 0				
WC#: 72.220	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF, LMM 72-70-01								
726110	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-15	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:S430	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02								
726110	NO. 2 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-15	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:S734	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02								
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-15	MOS	16-Jan-19						
SN:S430	HRS	7401.1	5000 (+200)		(12401.1) 12713.1	12601.1	4272.2 (+200)	
WC#: 72.240	ENC	6651						
PROC. REF: LMM 72-60-02								
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-15	MOS	30-Jul-07						
SN:S734	HRS	3575.6	5000 (+200)		(8575.6) 9384.6	8775.6	943.7 (+200)	
WC#: 72.240	ENC	3510						
PROC. REF: LMM 72-60-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726130	NO. 1 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:P8019	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01								
726130	NO. 2 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:P107238	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01								
727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	16-Jan-19						
	HRS	7401.1	5000 (+200)		(12401.1) 12713.1	12601.1	4272.2 (+200)	
WC#: 72.270	ENC							
PROC. REF: LMM 72-70-06								
727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	03-Sep-13						
	HRS	5272	5000 (+200)		(10272) 11081	10472	2640.1 (+200)	
WC#: 72.270	ENC	4625						
PROC. REF: LMM 72-70-06								
ATA 73 - ENGINE FUEL AND CONTROL								
730001 ^S	DRAIN PT2 PIPELINES TO FUEL COMPUTERS							Service ATA:73
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 73.050	AFL	6498						
								PKG:2
731110	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:3060710-16	MOS/MSC	16-Jan-19	O/C	TSN 275				
SN:0116	HRS	7401.1		TSN 7401.1				
WC#: 73.010	ENC	6651		TSN 6651				
PROC. REF: LMM 73-20-01, LMM 73-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731110	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:3060710-16	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:0231	HRS	0		TSN 0				
WC#: 73.010	ENC	0		TSN 0				
PROC. REF: LMM 73-20-01, LMM 73-21-02								
731120 ^S	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	11-Jun-21						
	HRS	7772.8	400					
WC#: 73.010	ENC	6914						
PROC. REF: LMM 73-21-02, LMM 73-21-02								PKG:2
731120 ^S	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	21-Mar-23						
	HRS	7516.9	400					
WC#: 73.010	ENC	6001						
PROC. REF: LMM 73-21-02, LMM 73-21-02								PKG:2
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 73.030	ENC							
PROC. REF: GENERIC NO REF								
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	01-Apr-08	O/C					
SN:P3792	HRS	3729.1						
WC#: 73.030	ENC	3612						
PROC. REF: GENERIC NO REF								
731140	NO. 1 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	03-May-12	O/C	TSR 0				
SN:22-134	HRS	5393.8		TSR 0				
WC#: 73.040	ENC	4883		TSR 0				
PROC. REF: LMM 73-10-04								
731140	NO. 2 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731150 ^S	NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)							Service ATA:73
	MOS	11-Oct-16						
	HRS	6851.3	800					
WC#: 73.050	ENC	5910						
PROC. REF: LMM 79-20-06							PKG:4	
731150 ^S	NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)							Service ATA:73
	MOS	04-Sep-20						
	HRS	7087.8	800					
WC#: 73.050	ENC	5734						
PROC. REF: LMM 79-20-06							PKG:4	
731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE							Component ATA:73
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 73.060	ENC							
PROC. REF: LMM 73-10-04								
731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE							Component ATA:73
PN:PN	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.060	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04								
732025	NO. 1 ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:73
PN:HTE690014/1	MOS/MSC	20-Dec-99	O/C					
SN:000585	HRS	2185		TSN 2078				
WC#: 73.020	AFL							
PROC. REF: AMM 73-32-11								
732026	NO. 2 ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:73
PN:HTE690014-1	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
WC#: 73.020	AFL							
PROC. REF: AMM 73-32-11								
732037	NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH							Component ATA:73
PN:HE60010	MOS/MSC	20-Dec-99	O/C					
SN:0652TW	HRS	2185		TSN 2078				
WC#: 73.025	AFL							
PROC. REF: AMM 73-33-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732038	NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH							Component ATA:73
PN:HE60010	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
WC#: 73.025	AFL							
PROC. REF: AMM 73-33-11								
732109	ENGINE FUEL SYNCHRONIZER							Component ATA:73
PN:2118756-1	MOS/MSC	17-Mar-15	O/C					
SN:15-B0085	HRS	6533.6						
WC#: 73.035	AFL	5713						
PROC. REF: GENERIC NO REF								
732110	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-26	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:12823	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: LMM 73-20-01								
732110	NO. 2 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-35	MOS/MSC	12-Aug-08	O/C					
SN:12533	HRS	3795.7						
WC#: 73.070	ENC	3659						
PROC. REF: LMM 73-20-01								
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 73.080	ENC							
PROC. REF: GENERIC NO REF								
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732160	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-127-55	MOS/MSC	12-Feb-96	O/C	TSN 0				
SN:7445	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732160	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-127-55	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
733013	NO. 1 ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:9-328-26	MOS/MSC	06-Mar-96	O/C					
SN:3236	HRS	0		TSN 0				
WC#: 73.045	AFL	0						
PROC. REF: GENERIC NO REF								
733014	NO. 2 ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:9-328-26	MOS/MSC	06-Mar-96	O/C					
SN:3238	HRS	0		TSN 0				
WC#: 73.045	AFL	0						
PROC. REF: GENERIC NO REF								
ATA 74 - IGNITION								
741110	NO. 1 ENGINE - IGNITION UNIT							Component ATA:74
PN:3073776-1	MOS/MSC	03-Feb-18	O/C	TSN 0				
SN:J17460084	HRS	7214.2		TSN 0				
WC#: 74.010	ENC	6135		TSN 0				
PROC. REF: LMM 74-00-01								
741110	NO. 2 ENGINE - IGNITION UNIT							Component ATA:74
PN:3073776-1	MOS/MSC	01-Feb-18	O/C	TSO 0				
SN:J11250016	HRS	6608.1		TSO 0				
WC#: 74.010	ENC	5421		TSO 0				
PROC. REF: LMM 74-00-01								
741120 ^S	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service ATA:74
	MOS	16-Jan-19						
	HRS	7401.1	1200 (+200)					
WC#: 74.010	ENC	6651						
PROC. REF: LMM 74-00-01								
								PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741120 ^S	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service ATA:74
	MOS	02-Mar-18						
	HRS	6635.4	1200 (+200)					
WC#: 74.010	ENC	5441						
PROC. REF: LMM 74-00-01							PKG:0	
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-1	MOS/MSC	16-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	6368.8		TSN 0				
WC#: 74.030	ENC	5679		TSN 0				
PROC. REF: LMM 74-00-01								
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-1	MOS/MSC	04-Jan-00	O/C	TSN 0				
SN:99044680	HRS	1434.2		TSN 0				
WC#: 74.030	ENC	1249		TSN 0				
PROC. REF: LMM 74-00-01								
742120 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Jan-19						
	HRS	7401.1	1600					
WC#: 74.030	ENC							
PROC. REF: LMM 74-00-01							PKG:5	
742120 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Feb-18						
	HRS	6867	1600					
WC#: 74.030	ENC	5585						
PROC. REF: LMM 74-00-01							PKG:5	
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-1	MOS/MSC	16-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	6368.8		TSN 0				
WC#: 74.050	ENC	5679		TSN 0				
PROC. REF: LMM 74-00-01								
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-1	MOS/MSC	04-Jan-00	O/C	TSN 0				
SN:99044691	HRS	1434.2		TSN 0				
WC#: 74.050	ENC	1249		TSN 0				
PROC. REF: LMM 74-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Jan-19						
	HRS	7401.1	1600					
WC#: 74.050	ENC							
PROC. REF: LMM 74-00-01							PKG:5	
742140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Feb-18						
	HRS	6867	1600					
WC#: 74.050	ENC	5585						
PROC. REF: LMM 74-00-01							PKG:5	
ATA 75 - AIR								
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component ATA:75
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 75.010	ENC							
PROC. REF: LMM 75-40-01								
750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component ATA:75
PN:PN	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 75.010	ENC	0		TSN 0				
PROC. REF: LMM 75-40-01								
751010	NO. 1 ENGINE - ANTI-ICE VALVE							Component ATA:75
PN:F10A-5-SCP-102-5	MOS/MSC	09-Aug-01	O/C	TSO 1				
SN:7080239	HRS	2287		TSO 0				
WC#: 75.020	ENC							
PROC. REF: GENERIC NO REF								
751010	NO. 2 ENGINE - ANTI-ICE VALVE							Component ATA:75
PN:F10A-5-SCP-102-5	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:1J0012	HRS	0		TSN 0				
WC#: 75.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
751013	NO. 1 ENGINE THERMAL ANTI-ICE VALVE							Component ATA:75
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 75.020	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
751014	NO. 2 ENGINE THERMAL ANTI-ICE VALVE							Component ATA:75
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 75.021	AFL	0		TSN 0				
754010	NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH							Component ATA:75
PN:HE12423	MOS/MSC	20-Dec-99	O/C					
SN:1860TW	HRS	2185		TSN 2078				
WC#: 75.015	AFL							
PROC. REF: AMM 75-40-11								
754011	NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH							Component ATA:75
PN:HE12423	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
WC#: 75.015	AFL							
PROC. REF: AMM 75-40-11								
ATA 76 - ENGINE CONTROLS								
760001 ^S	CHECK THROTTLE LEVER CONTROLS							Service ATA:76
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 76.030	AFL	6498						
PROC. REF: AMM 27-72-00								
PKG:2								
760002 ^S	CHECK ENGINE POWER CONTROL CABLES							Service ATA:76
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 76.010	AFL	6753						
PROC. REF: AMM 76-10-00								
PKG:3								
760003	CHECK POWER CONTROL CABLES							Service ATA:76
	MOS/MSC	06-Mar-96	O/C					
	HRS	0						
WC#: 76.020	AFL	0						
PROC. REF: AMM 76-10-00								
760004	LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service ATA:76
	MOS	02-Feb-19						
	HRS	7707.2	2400 (+100)		10107.2	10207.2	1666.3 (+100)	
WC#: 76.040	AFL	6370						
PROC. REF: AMS 5-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760004	LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service ATA:76
	MOS	02-Sep-13						
	HRS	6080.9	2400		8480.9		40	
WC#: 76.040	AFL	5386						
PROC. REF: AMS 5-20-11								
760110 ^U	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL							Component ATA:76
PN:2119010-8000	MOS/MSC	06-Dec-07	O/C					
SN:92A40154	HRS	4341.6						
WC#: 76.010	ENC	4184						
PROC. REF: GENERIC NO REF								
760110 ^U	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL							Component ATA:76
PN:2119010-8000	MOS/MSC	05-Dec-07	O/C					
SN:92-AY0156	HRS	3660.7						
WC#: 76.010	ENC	3572						
PROC. REF: GENERIC NO REF								
760120 ^S	NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service ATA:76
	MOS	11-Jun-21						
	HRS	7772.8	400					
WC#: 76.020	ENC	6914						
PROC. REF: LMM 76-10-03, LMM 72-00-00								
								PKG:2
760120 ^S	NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service ATA:76
	MOS	21-Mar-23						
	HRS	7516.9	400					
WC#: 76.020	ENC	6001						
PROC. REF: LMM 76-10-03, LMM 72-00-00								
								PKG:2
760130	NO. 1 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS	17-Nov-23						
	HRS	8081.1						
WC#: 76.050	ENC	7079	40 (+10)		(7119) 6839	7129	12 (+10)	
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760130	NO. 2 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS	17-Nov-23						
	HRS	7584.1						
WC#: 76.050	ENC	6035	40 (+10)		(6075) 6839	6085	12 (+10)	
PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03								
761310	NO. 1 ENGINE - SURGE BLEED VALVE							Component ATA:76
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 76.030	ENC							
PROC. REF: LMM 76-10-01								
761310	NO. 2 ENGINE - SURGE BLEED VALVE							Component ATA:76
PN:978812-5-1	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.030	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01								
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE							Component ATA:76
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 76.040	ENC							
PROC. REF: LMM 76-10-01								
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE							Component ATA:76
PN:109696-4-1	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.040	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01								
ATA 77 - ENGINE INDICATING								
771025	NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR							Component ATA:77
PN:WL717RSA-5	MOS/MSC	07-Oct-98	O/C					
SN:AH320	HRS	1435						
WC#: 77.010	AFL	1246						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771026	NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR							Component ATA:77
PN:WL717RSA-5	MOS/MSC	21-Aug-98	O/C					
SN:AL318	HRS	1326						
WC#: 77.010	AFL	1167						
PROC. REF: GENERIC NO REF								
771037	NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component ATA:77
PN:WL656RSA-7	MOS/MSC	06-Mar-96	O/C					
SN:AL181	HRS	0		TSN 0				
WC#: 77.015	AFL	0						
PROC. REF: GENERIC NO REF								
771038	NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component ATA:77
PN:WL656RSA-7	MOS/MSC	06-Mar-96	O/C					
SN:AL182	HRS	0		TSN 0				
WC#: 77.015	AFL	0						
PROC. REF: GENERIC NO REF								
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component ATA:77
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 77.010	ENC							
PROC. REF: LMM 77-10-03								
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component ATA:77
PN:3073827-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.010	ENC	0		TSN 0				
PROC. REF: LMM 77-10-03								
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 77.020	ENC							
PROC. REF: LMM 77-10-05								
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 77.030	ENC							
PROC. REF: LMM 77-20-01								
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3073605-1	MOS/MSC	07-Jan-03	O/C	TSN 0				
SN:02-20219-00234	HRS	2177.3		TSN 0				
WC#: 77.030	ENC	2118		TSN 0				
PROC. REF: LMM 77-20-01								
773005	LEFT TIME DELAY SWITCH							Component ATA:77
PN:TDA310A	MOS/MSC	06-Mar-96	O/C					
SN:2375T	HRS	0		TSN 0				
WC#: 77.025	AFL	0						
PROC. REF: GENERIC NO REF								
773006	RIGHT TIME DELAY SWITCH							Component ATA:77
PN:TDA310A	MOS/MSC	06-Mar-96	O/C					
SN:2374T	HRS	0		TSN 0				
WC#: 77.025	AFL	0						
PROC. REF: GENERIC NO REF								
774013	NO. 1 ENGINE ITT INDICATOR							Component ATA:77
PN:WL718RSA-5	MOS/MSC	06-Mar-96	O/C					
SN:AL161	HRS	0		TSN 0				
WC#: 77.030	AFL	0						
PROC. REF: GENERIC NO REF								
774014	NO. 2 ENGINE ITT INDICATOR							Component ATA:77
PN:WL718RSA-5	MOS/MSC	02-Jan-21	O/C					
SN:AL877	HRS	7987.6						
WC#: 77.030	AFL	6569						
PROC. REF: GENERIC NO REF								
ATA 78 - EXHAUST								
780001 ^S	INSPECT THRUST REVERSER LINK ARM ASSEMBLIES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.110	AFL	6498						
PROC. REF: AMM NO REF-1								

PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
780002 ^S	INSPECT REVERSER DOOR SEALS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.120	AFL	6498						
				PROC. REF: AMM 78-31-20				PKG:2
780003 ^S	TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES							Service ATA:78
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 78.130	AFL	6753						
				PROC. REF: AMM 78-34-20				PKG:3
780004 ^S	INSPECT PYLON SKIN PANELS							Service ATA:78
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 78.135	AFL	6753						
								PKG:3
780005 ^S	DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS							Service ATA:78
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 78.140	AFL	6753						
				PROC. REF: AMM 78-31-10				PKG:3
780006 ^S	CHECK THRUST REVERSER LEVER BAULK MECHANISM							Service ATA:78
	MOS	10-Jul-15						
	HRS	6667.8	3200 (+150/-50)					
WC#: 78.125	AFL	5769						
								PKG:4
780009 ^S	INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.155	AFL	6498						
								PKG:2
780010 ^S	INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.160	AFL	6498						
								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
780011 ^S	DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.165	AFL	6498						
								PKG:2
780012 ^S	INSPECT THRUST REVERSER HYDRAULIC LINES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.170	AFL	6498						
								PKG:2
780013 ^S	INSPECT THRUST REVERSER WIRE HARNESSSES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.175	AFL	6498						
								PKG:2
780014 ^S	INSPECT THRUST REVERSER FAN DUCTS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.180	AFL	6498						
								PKG:2
780015 ^S	INSPECT THRUST REVERSER LATCH BOX SPRINGS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.185	AFL	6498						
								PKG:2
780016 ^S	OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.190	AFL	6498						
PROC. REF: AMM NO REF-1								PKG:2
780017 ^S	INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.195	AFL	6498						
PROC. REF: AMM 78-31-35								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
780018 ^S	INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.200	AFL	6498						
PROC. REF: AMM NO REF-1							PKG:2	
780019 ^S	INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.205	AFL	6498						
PROC. REF: AMM NO REF-1							PKG:2	
780020 ^S	INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.210	AFL	6498						
PROC. REF: AMM NO REF-1							PKG:2	
780021 ^S	INSPECT THRUST REVERSER PYLON PLUGS							Service ATA:78
	MOS	04-Sep-20						
	HRS	7896.7	800 (+40/-10)					
WC#: 78.215	AFL	6498						
							PKG:2	
780022 ^S	CHECK DOOR LINK RODS							Service ATA:78
	MOS	11-Jan-23						
	HRS	8299.1	1600 (+50/-50)					
WC#: 78.220	AFL	6753						
PROC. REF: AMM 78-31-10							PKG:3	
781001	NO. 1 ENGINE THRUST REVERSER AFTERBODY							Component ATA:78
PN:5451101/69	MOS/MSC	06-Mar-96	O/C					
SN:019	HRS	0		TSN 0				
WC#: 78.015	AFL	0						
PROC. REF: AMM 78-33-40								
781002	NO. 2 ENGINE THRUST REVERSER AFTERBODY							Component ATA:78
PN:5451101/71	MOS/MSC	06-Mar-96	O/C					
SN:019	HRS	0		TSN 0				
WC#: 78.015	AFL	0						
PROC. REF: AMM 78-33-40								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
781013	NO. 1 ENGINE THRUST REVERSER ASSEMBLY							Component ATA:78
PN:HS7830100-3	MOS/MSC	06-Mar-96	O/C					
SN:019	HRS	0		TSN 0				
WC#: 78.010	AFL	0						
PROC. REF: AMM 78-31-00								
781014	NO. 2 ENGINE THRUST REVERSER ASSEMBLY							Component ATA:78
PN:HS7830100-4	MOS/MSC	06-Mar-96	O/C					
SN:019	HRS	0		TSN 0				
WC#: 78.011	AFL	0						
PROC. REF: AMM 78-31-00								
781026	NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR							Component ATA:78
PN:545312-19	MOS/MSC	24-Feb-06	O/C					
SN:0106	HRS	4021.8		TSO 0				
WC#: 78.020	AFL	3984						
PROC. REF: AMM 78-32-40								
781027	NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR							Component ATA:78
PN:5453512-16	MOS/MSC	03-Oct-96	O/C					
SN:DHC1028	HRS	23						
WC#: 78.020	AFL	14						
PROC. REF: AMM 78-32-40								
781028	NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR							Component ATA:78
PN:5453512-15	MOS/MSC	03-Oct-96	O/C					
SN:DHC1021	HRS	23		TSN 0				
WC#: 78.025	AFL	14						
PROC. REF: GENERIC NO REF								
781029	NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR							Component ATA:78
PN:5453512-16	MOS/MSC	06-Mar-96	O/C					
SN:050	HRS	0		TSN 0				
WC#: 78.025	AFL	0						
PROC. REF: GENERIC NO REF								
781053	NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY							Component ATA:78
PN:5453521-7	MOS/MSC	06-Mar-96	O/C					
SN:931	HRS	0		TSN 0				
WC#: 78.030	AFL	0						
PROC. REF: AMM 78-32-50								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
781054	NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY							Component ATA:78
PN:5453521-7	MOS/MSC	06-Mar-96	O/C					
SN:957	HRS	0		TSN 0				
WC#: 78.030	AFL	0						
PROC. REF: AMM 78-32-50								
781055	NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY							Component ATA:78
PN:5453521-7	MOS/MSC	06-Mar-96	O/C					
SN:933	HRS	0		TSN 0				
WC#: 78.035	AFL	0						
PROC. REF: AMM 78-32-50								
781056	NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY							Component ATA:78
PN:5453521-7	MOS/MSC	06-Mar-96	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.035	AFL	0						
PROC. REF: AMM 78-32-50								
781090	NO. 1 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY							Component ATA:78
PN:5453511-11	MOS/MSC	06-Mar-96	O/C					
SN:921	HRS	0		TSN 0				
WC#: 78.040	AFL	0						
PROC. REF: AMM 78-32-60								
781091	NO. 1 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY							Component ATA:78
PN:5453511-11	MOS/MSC	06-Mar-96	O/C					
SN:906	HRS	0		TSN 0				
WC#: 78.040	AFL	0						
PROC. REF: AMM 78-32-60								
781092	NO. 2 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY							Component ATA:78
PN:5453511	MOS/MSC	06-May-96	O/C					
SN:951	HRS	22						
WC#: 78.045	AFL	11						
PROC. REF: AMM 78-32-60								
781093	NO. 2 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY							Component ATA:78
PN:5453511-11	MOS/MSC	06-Mar-96	O/C					
SN:925	HRS	0		TSN 0				
WC#: 78.045	AFL	0						
PROC. REF: AMM 78-32-60								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
781117	NO. 1 ENGINE RETARD THROTTLE ASSEMBLY							Component ATA:78
PN:5453305/3	MOS/MSC	06-Mar-96	O/C					
SN:037	HRS	0		TSN 0				
WC#: 78.050	AFL	0						
PROC. REF: AMM 78-32-30								
781118	NO. 2 ENGINE RETARD THROTTLE ASSEMBLY							Component ATA:78
PN:5453305-3	MOS/MSC	06-Mar-96	O/C					
SN:043	HRS	0		TSN 0				
WC#: 78.050	AFL	0						
PROC. REF: AMM 78-32-30								
781129	THRUST REVERSER TIME DELAY RELAY							Component ATA:78
PN:5400619-1	MOS/MSC	06-Mar-96	O/C					
SN:140	HRS	0		TSN 0				
WC#: 78.055	AFL	0						
PROC. REF: GENERIC NO REF								
781130	CONTROL RELAY BOX							Component ATA:78
PN:5400612-1	MOS/MSC	06-Mar-96	O/C					
SN:246	HRS	0		TSN 0				
WC#: 78.060	AFL	0						
PROC. REF: AMM 78-33-20								
781136	AUXILIARY RELAY BOX							Component ATA:78
PN:5400605-1	MOS/MSC	07-Aug-98	O/C					
SN:147	HRS	1296		TSN 917				
WC#: 78.065	AFL	1140		TSN 584				
PROC. REF: AMM 78-33-30								
781142	NO. 1 ENGINE THRUST REVERSER CONTROL VALVE							Component ATA:78
PN:064135141-3	MOS/MSC	11-Jan-23	O/C					
SN:A30040056	HRS	8299.1						
WC#: 78.070	AFL	6753						
PROC. REF: AMM 78-32-20								
781143	NO. 2 ENGINE THRUST REVERSER CONTROL VALVE							Component ATA:78
PN:5400505-1	MOS/MSC	10-Jun-98	O/C					
SN:0018	HRS	1211						
WC#: 78.070	AFL	1068						
PROC. REF: AMM 78-32-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
781155	THRUST REVERSER ACCUMULATOR							Component ATA:78
PN:D5259-3	MOS/MSC	06-Mar-96	O/C					
SN:12959	HRS	0		TSN 0				
WC#: 78.075	AFL	0						
PROC. REF: AMM 78-32-10								
781156	HYDRAULIC RELIEF VALVE							Component ATA:78
PN:D63450	MOS/MSC	06-Mar-96	O/C					
SN:59456	HRS	0		TSN 0				
WC#: 78.080	AFL	0						
PROC. REF: GENERIC NO REF								
781161	THRUST REVERSER CONTROL PANEL							Component ATA:78
PN:5412600-3	MOS/MSC	06-Mar-96	O/C					
SN:171	HRS	0		TSN 0				
WC#: 78.085	AFL	0						
PROC. REF: AMM 78-33-10								
781167	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH							Component ATA:78
PN:2365-15	MOS/MSC	06-Mar-96	O/C					
SN:1503	HRS	0		TSN 0				
WC#: 78.090	AFL	0						
PROC. REF: GENERIC NO REF								
781169	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH							Component ATA:78
PN:2365-15	MOS/MSC	06-Mar-96	O/C					
SN:1504	HRS	0		TSN 0				
WC#: 78.090	AFL	0						
PROC. REF: GENERIC NO REF								
781173	THRUST REVERSER PRESSURE GAUGE							Component ATA:78
PN:5413508	MOS/MSC	06-Mar-96	O/C					
SN:93176	HRS	0		TSN 0				
WC#: 78.090	AFL	0						
PROC. REF: GENERIC NO REF								
783008	NO. 1 ENGINE LOWER THRUST REVERSER DOOR							Component ATA:78
PN:HS7832000-3	MOS/MSC	06-Mar-96	O/C					
SN:018-152	HRS	0		TSN 0				
WC#: 78.095	AFL	0						
PROC. REF: AMM 78-31-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783009	NO. 2 ENGINE LOWER THRUST REVERSER DOOR							Component ATA:78
PN:HS7832000-4	MOS/MSC	06-Mar-96	O/C					
SN:020/152	HRS	0		TSN 0				
WC#: 78.095	AFL	0						
PROC. REF: AMM 78-31-10								
783010	NO. 1 ENGINE UPPER THRUST REVERSER DOOR							Component ATA:78
PN:HS7832000-1	MOS/MSC	06-Mar-96	O/C					
SN:019-152	HRS	0		TSN 0				
WC#: 78.100	AFL	0						
PROC. REF: AMM 78-31-10								
783011	NO. 2 ENGINE UPPER THRUST REVERSER DOOR							Component ATA:78
PN:HS7832000-1	MOS/MSC	06-Mar-96	O/C					
SN:020/154	HRS	0		TSN 0				
WC#: 78.100	AFL	0						
PROC. REF: AMM 78-31-10								
783013	NO. 1 ENGINE INNER FAN DUCT ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783014	NO. 2 ENGINE INNER FAN DUCT ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	06-Mar-96	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.231	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 79 - OIL								
790111 ^S	NO. 1 ENGINE - ANALYZE OIL AND FILTER							Service ATA:79
	MOS	20-Dec-22						
	HRS	7987.1	200 (+50)					
WC#: 79.010	ENC							
PROC. REF: LMM 72-00-00								
PKG:1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790111 ^S	NO. 2 ENGINE - ANALYZE OIL AND FILTER							Service ATA:79
	MOS	20-Dec-22						
	HRS	7490.1	200 (+50)					
WC#: 79.010	ENC							
	PROC. REF: LMM 72-00-00							PKG:1
790120	NO. 1 ENGINE - CHANGE OIL							Service ATA:79
	MOS	16-Jan-19						
	HRS	7401.1	1200 (+100)		(8601.1) 8913.1	8701.1	472.2 (+100)	
WC#: 79.020	ENC							
	PROC. REF: LMM 72-00-00							
790120	NO. 2 ENGINE - CHANGE OIL							Service ATA:79
	MOS	30-Apr-17						
	HRS	6431.2	1200 (+100)		(7631.2) 8440.2	7731.2	TOL (+99.3)	
WC#: 79.020	ENC	5304						
	PROC. REF: LMM 72-00-00							
790130 ^S	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR							Service ATA:79
	MOS	20-Dec-22						
	HRS	7987.1	200 (+50)					
WC#: 79.030	ENC							
	PROC. REF: LMM 79-20-03							PKG:1
790130 ^S	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR							Service ATA:79
	MOS	20-Dec-22						
	HRS	7490.1	200 (+50)					
WC#: 79.030	ENC							
	PROC. REF: LMM 79-20-03							PKG:1
791001 ^U	OIL L ENGINE TANK							Component ATA:79
PN:3075207-1G	MOS/MSC	20-Dec-99	O/C					
SN:UNKNOWN	HRS	2185		TSN 2078				
	AFL							
791002 ^U	OIL R ENGINE TANK							Component ATA:79
PN:3075207-1G	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792110	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-11	MOS/MSC	16-Jan-19	O/C					
SN:95-140573183	HRS	7401.1						
WC#: 79.040	ENC	6651						
PROC. REF: LMM 79-20-03								
792110	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:3060785-3	MOS/MSC	03-May-12	O/C	TSO 0				
SN:061405701109	HRS	4790.7		TSO 0				
WC#: 79.040	ENC	4321		TSO 0				
PROC. REF: LMM 79-20-03								
792120	NO. 1 ENGINE - BY-PASS INDICATOR VALVE							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.050	ENC							
PROC. REF: LMM 79-30-01								
792120	NO. 2 ENGINE - BY-PASS INDICATOR VALVE							Component ATA:79
PN:PN	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.050	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01								
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.060	ENC							
PROC. REF: LMM 79-20-02								
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:PN	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.060	ENC	0		TSN 0				
PROC. REF: LMM 79-20-02								
792140	NO. 1 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.070	ENC							
PROC. REF: LMM 79-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792140	NO. 2 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09								
792144	NO. 1 ENGINE OIL LOW PRESSURE SWITCH							Component ATA:79
PN:HTE690012	MOS/MSC	20-Dec-99	O/C					
SN:FR021/AP	HRS	2185		TSN 2078				
WC#: 79.030	AFL							
PROC. REF: AMM 79-33-11								
792145	NO. 2 ENGINE OIL LOW PRESSURE SWITCH							Component ATA:79
PN:HTE690012	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
WC#: 79.030	AFL							
PROC. REF: AMM 79-33-11								
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.080	ENC							
PROC. REF: LMM 79-20-09								
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09								
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.090	ENC							
PROC. REF: LMM 79-20-09								
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR							Component ATA:79
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
WC#: 79.100	ENC							
PROC. REF: LMM 79-20-07								
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR							Component ATA:79
PN:158610-8	MOS/MSC	30-Jun-97	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07								
793001	NO. 1 ENGINE OIL PRESSURE TRANSMITTER							Component ATA:79
PN:695-4-22	MOS/MSC	20-Dec-99	O/C					
SN:BY6432	HRS	2185		TSN 2078				
WC#: 79.040	AFL							
PROC. REF: AMM 79-32-11								
793002	NO. 2 ENGINE OIL PRESSURE TRANSMITTER							Component ATA:79
PN:695-4-22	MOS/MSC	22-Nov-97	O/C					
SN:UNKNOWN	HRS	776		TSN 0				
WC#: 79.040	AFL							
PROC. REF: AMM 79-32-11								
793037	NO. 1 ENGINE OIL PRESSURE INDICATOR							Component ATA:79
PN:2121-01-0014	MOS/MSC	06-Mar-96	O/C					
SN:BG74680	HRS	0		TSN 0				
WC#: 79.045	AFL	0						
PROC. REF: GENERIC NO REF								
793038	NO. 2 ENGINE OIL PRESSURE INDICATOR							Component ATA:79
PN:2121-1-14	MOS/MSC	12-Sep-02	O/C	TSO 0				
SN:BG81865	HRS	2789.2		TSO 0				
WC#: 79.045	AFL	2608		TSO 0				
PROC. REF: GENERIC NO REF								
793049	NO. 1 ENGINE OIL TEMPERATURE INDICATOR							Component ATA:79
PN:2121-01-0013	MOS/MSC	06-Mar-96	O/C					
SN:BG74650	HRS	0		TSN 0				
WC#: 79.050	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HAWKER 800XP Serial: 258293 RegNo: N432SM HRS: 8440.9 AFL: 6827 As Of: 31-Mar-2024

03-Jun-2024 05:48 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793050	NO. 2 ENGINE OIL TEMPERATURE INDICATOR							Component ATA:79
PN:2121-01-0013	MOS/MSC	06-Mar-96	O/C					
SN:BG74651	HRS	0		TSN 0				
WC#: 79.050	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task