

#1

Las Vegas Propeller Service, Inc.

2019 S. HIGHLAND
LAS VEGAS, NEVADA 89102
TELEPHONE (702) 384-0830

Propeller Logbook

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	The aircraft component identified above was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under: SIGNATURE _____ WORK ORDER NO. <u>2110</u> DATE <u>23 Aug. 1982</u> SIGNED <u>Sarah A. Crook</u> LAS VEGAS PROPELLER SERVICE, INC. 2019 S. RICHLAND LAS VEGAS, NV 89102 (702) 304-0830 FAA REPAIR STATION NO. 455-09
23 Aug. 1982		Overhauled per manual 113B. all Service Bulletins and A.D.'s (including 77-12-06) complied with to date. Angles @ the 30° Stations 15.6° Low; 34° High. No Tach Check this date.	
5-22-19	3408.33	This log closed 3-4-88 see log # 2.	John A. Hamby A-P 505 749274

WORK ORDER

LAS VEGAS PROPELLER SERVICE, INC.
2019 S. HIGHLAND
LAS VEGAS, NEVADA 89102
384-0830

F.A.A. REPAIR STATION NO. 466-09

W.O. NO. 2110
DATE 17 Aug 1982
P.O. NO. 5085
INV. NO. 3086

CUSTOMER Las Vegas Piper
ADDRESS P.O. Box 15105
CITY Las Vegas, STATE NV.
ZIP 89114 PHONE _____

OVERHAUL ☒ REPAIR ☐ OTHER ☐

AUTHORIZED SIGNATURE _____

DESCRIPTION OF WORK COMPLETED Overhauled per manual 113B. all
Service Bulletins and A.D's (including 77-12-06) complied
with to date. No such check this date.

MANUFACTURER Hartnell HUB MODEL HC-E24R-1B7
HUB SERIAL NO. DK 1185 BLADE DESIGN 78477-4
BLADE SERIAL NO: 1. D88554 2. D93705
3. _____ 4. _____

ANGLES: LOW 15.6° HIGH 34° FEATHER _____ STATION 30"

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED
IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY
FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT
THIS AGENCY UNDER THIS WORK ORDER NUMBER AND DATE.

SIGNED Sarah A. Crook DATE 23 Aug 1982