Propelle Logboo

SB

SENSENICH PROPELLER SERVICE, INC.



McCauley

Hartzell

MT

Sensenich

Dowty

Hamilton Standard

INSTALLING AGENCY PLEASE NO Recording of Propeller Total Time Since New (TT is Required Per F.A.R. 91.

DK 1185E

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmer Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R34

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

| Propeller Model _ | | HC-EZYR-IBF | 3 | |
|-------------------|-----|-------------|---|--|
| Blade Model | | F8477-4 | | |
| Hub Serial No | | DK/185E | | |
| Blade Serial No. | 1_ | J05946 | | |
| | 2_ | J05948 | | |
| | 3_ | , | | |
| | 4 _ | | | |
| | 5 _ | | | |
| | 6_ | | | |
| | | | | |

SERVICE HISTORY

| е | Total Propeller Time | Time Since Overhaul | Description of Work | Authorized Signatures |
|----|----------------------|------------------------|------------------------------|-----------------------------|
| 15 | BROUGHT | FORWARDS | Complied with AD | 2001-23-08 As |
| | | | PER SURVICE Bullati | |
| | | | BY EDDY CURRENT | INSPECTION, NO |
| | | | DEFRETS FOUND A | |
| | | | INSPECTION PRICE | |
| | | | THIS IS NOT AN OVE | |
| _ | | | AND CANNOT BE CONSIDER | ED AS SUCH |
| _ | | | WORK ORDER 127/23 | |
| | | | | Sensenich Propeller Service |
| | | | | Repair Station #QV9R194N |
| 16 | 3367.39 | 895.39 | Prop. Thespected for see | unity and operation |
| | | | I contify that this prope | |
| | | | in accordance with an annual | |
| _ | | | to be In an Arrustly compi | |
| _ | | | (| AP 2773537F4 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

SERVICE HISTORY

| Date | Li'l Red Aero, Inc. | | | | | | | | |
|------|--|--|--|--|--|--|--|--|--|
| | Aircraft Maintenance & Repair 4975 AIRPORT ROAD KEARNEY, NEBRASKA 68847 | | | | | | | | |
| | Tail Number: N36716 Model: Piper PA32RT-300T Serial Number: 32R-7887068 | | | | | | | | |
| | Tach Time: 3408.33 Propeller Total Time: 3408.33 SMOH: 936.83 | | | | | | | | |
| | Model: Hartzell HC-E2YR-1BF Serial Number: DK 1185E | | | | | | | | |
| | This propeller has been inspected I/A/W FAR 43 Appendix D. Dressed blades, and checked spinner and bulkheads for cracks and security. OK at this time. Painted tips and face. AD's checked through | | | | | | | | |
| | 19-11 issue. AD 01-23-08 is due in 105.67 Hours. No new, applicable, or reacurring AD's due at this time. END>>> | | | | | | | | |
| | I certify that I have inspected this Aircraft Propeller in accordance with a Annual Inspection and has | | | | | | | | |
| | been found to be in an airworthy condtion. | | | | | | | | |
| | Date: 06/04/2019 Signature: John A. Hamling John G. Hamling IA: 505749274 | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |