



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442

1978 MERLIN IIIA

Serial Number T-286

Registration N505GM



AIRFRAME:

7075 Total Hours

4352 Landings

ENGINES: TPE331-10UA-511G

Left Engine Number P-54911RC

759 Hours Since Overhaul

5000 TBO

Right Serial Number P-54282C

759 Hours Since Overhaul

PROPELLERS:

Left: Serial Number BAU7708

356 Hours Since Overhaul

Right: Number BAU6596

356 Hours Since Overhaul

ADDITIONAL:

True -10 Engines (Not Converted), Variable Authority Hydraulic Nose Wheel Steering, Lead-Acid Batteries

This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442

MAINTENANCE: Enrolled and fully paid-up on Propulsion International's GMP which covers 100% of all future scheduled/unscheduled maintenance, including future ADs, Mandatory SBs, hot section inspections and overhauls. In 5/00 a Bird strike on left wing Repaired by Factory, the 1989-1993 Airframe Log Missing (All other logs present)



AVIONICS: ADS-B Out

Comms: Garmin GTN-650; Garmin GTN-750

GPS: Garmin GTN-650; Garmin GTN-750

Navs: Garmin GTN-650; Garmin GTN-750

Emergency Locator Transmitter

Garmin GPS-400W WAAS GPS Navigator

M-4D Autopilot w/ Flight Director & Yaw Damper

PS Engineering Intercom (cockpit)
SATCOM

Transponder: Dual Garmin GTX-345

Primus 300SL Radar

Landmark LG8000 TAWS-B

This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442



INTERIOR:

Executive Configuration in Light Tan Leathers, with four individual seats, a three place sofa, and hardwood cabinetry, Flushing Potty (belted) & Vanity Sink with Privacy Divider, Tinted Window Inserts

EXTERIOR:

White Upper with Beige Lower, Dark Metallic Green & Maroon Stripes White Upper with Beige Lower, Dark Metallic Green & Maroon Stripes



This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale



FLIGHT SOURCE INTERNATIONAL, INC.

Worldwide Aircraft Sales and Acquisitions

sales@flightsource.com

Sarasota, Florida, USA

Nassau, Bahamas

Phone: +1 941.355.9585 / Fax: +1 941.296.7442



AVAILABLE IMMEDIATELY, Call Maria +1 941-586-6345

maria@flightsource.com



Commented [EE1]:

This aircraft is being brokered by Flight Source International, Inc. Flight Source International, Inc. has not conducted a pre-purchase inspection of this aircraft to verify mechanical condition, airworthiness or accuracy of specifications. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Flight Source International, Inc. makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications Subject To Verification Upon Inspection. Aircraft Subject To Prior Sale