
NZ348Q R/H

ENGINE LOG BOOK



Publication ELB-01 NOV 2013

Service Information

Consult the Continental Motors web site at continentalmotors.aero for engine related news or announcements. Continental Motors Internet Service contains useful information for Continental Motors engine owners, including electronic versions of the most current engine Instructions for Continued Airworthiness and service documents that may be pertinent to your engine model.

If Internet access is not available, contact our Customer Service Department at: 1-888-826-5465 Toll free in the United States or 1-251-436-8299 International

Engine Returns

Return engines for core credit with this log book to: Continental Motors, Inc. 2039 Broad Street Mobile, AL 36615 USA

Return engines for overhaul with this log book to: Continental Motors, Inc. **Factory Service Center** 8600 County Road 32 Fairhope, Alabama 36532 USA

> USE ONLY FUEL SPECIFIED IN OPERATOR'S MANUAL OR TYPE CERTICATE DATA SHEET USE OF AUTOMOTIVE FUEL IS PROHIBITED



Continental Motors

FAA PRODUCTION CERTIFICATE NO. 508

Printed:04/02/2019

Test Date_{04/02/2019}

This engine model I0550C49B, serial number 1037315 was rebuilt by Continental Motors Inc, in accordance with approved design data and the applicable requirements of 14 CFR, Part 21 and 43 of the Federal Aviation Regulation. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Continental Motors Service Bulletins.

CONTINENTAL MOTORS, INC.

Form 6012-04 (Rev Sept 2014)



Aircraft Tail #: N2348Q RT Aircraft Serial #: TH-1848 Engine Serial #: 1037315 Hour Meter: 4333.2

> TSR: 0.0 04/30/2019 Date:

Removed R/H engine P/N: 10-550-C S/N: 1010112 and installed Rebuilt engine P/N: 10-550C49 S/N: 1037315. IAW Baron 58 AMM P/N: 55-590000-13 Rev. G12 Operational and leak check good

Serviced engine with 11 quarts of Acroshell 100 mineral oil.

Installed all new Spark plugs (12 ea) P/N: RHB32E. Operational check good.

This engine has been inspected in accordance with the Beechcraft Baron AMM chapter 5-20-00 100 hour long or Annual form inspection guide P/N: 118662R dated 04/01/2014 and is found to be airworthy.

---END---

Certificate Number

Southwest Aircraft Charter Maintenance Operations 1675 E. Ryan Road Chandler, AZ 85286



Aircraft Tail #: N2348Q RT Aircraft Serial #: TH-1848 Engine Serial #: 1037315 Hour Meter: 4367.7

TSR: 34.5 05/24/2019

Drained mineral oil, removed and replaced oil filter P/N: CH48109-1. Serviced engine with 11qts. of Aeroshell W100 engine oil. Performed after break in inspection on engine. No discrepancies found.

---END---

ertificate Number

Aircraft Serial #:

Southwest Aircraft Charter Maintenance Operations 1675 E. Ryan Road Chandler, AZ 85286



Aircrast Tail #: N2348Q RT

Engine Serial #: 1037315 Hour Meter: 4428.1 TSR: 94.9

Date: 08/05/2019

TH-1848

Performed cylinder compression test; cyl: #1 78/80, #2 78/80, #3 79/80, #4 76/80, #5 78/80, #6 78/80

Drained oil and removed and replaced oil filter P/N: CH48109-1 Serviced engine with 11qts. of Aeroshell W100 engine oil

This engine has been inspected in accordance with Beechcraft 100-hour short form inspection guide P/N: 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see engine S/N. 1037315 listing for all AD compliance.

---END---

H177777343 Certificate Number

Southwest Aircraft Charter Maintenance Operations 1675 E. Ryan Road Chandler, AZ 85286



Aircraft Tail #: N2348Q RT Aircrast Serial #: TH-1848 Engine Serial #: 1037315 Hour Meter: 4502.1

TSR: 168 9 11/06/2019 Date:

Performed cylinder compression test, cyl: #1 76/80, #2 74/80, #3 76/80, #4 77/80, #5 76/80, #6 78/80

Drained oil and removed and replaced oil filter P/N CH48109-1 Serviced engine with 11qts of Aeroshell W100 engine oil.

This engine has been inspected in accordance with Beechcraft 100-hour short form inspection guide P/N: 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see engine S/N 1037315 listing for all AD compliance.

-END-

747 2727343

Southwest Aircraft Charter Maintenance Operations 1675 E Ryan Road Chandler, AZ 85286



N2348Q RT Aircraft Tail #: TH-1848 Aircrast Serial #: 1037315 Engine Serial #: 4593.5 Hour Meter: 260.3 TSR: 03/27/2020 Date:

Performed cylinder compression test; cyl #1 76/80, #2 78/80, #3 77/80, #4 77/80, #5 77/80, #6 77/80

Drained oil and removed and replaced oil filter P/N CH48109-1 Serviced engine with 11qts of Aeroshell W100 engine oil

This engine has been inspected in accordance with the Beechcraft Baron AMM chapter 5-20-00 100 hour long or Annual form inspection guide P/N 118662R dated 04/01/2014 and is found to be airworthy

-END-

AIPZIZISHSIA

Southwest Aircraft Charter Maintenance Operations 1675 E Ryan Road Chandler, AZ 85286



Aircrast Tail #: N2348Q RT Aircrast Serial #: TH-1848 Engine Serial #: 1037315

> Hour Meter: 4689.4 TSR: 356.2

TSR: 356.2 Date: 01/22/2021

Performed cylinder compression test; cyl: #1 78/80, #2 74/80, #3 76/80, #4 76/80, #5 76/80, #6 77/80

Complied with Continental motors CSB07-01A. No discrepancies found.

- Drained oil and removed and replaced oil filter P/N: CH48109-1 Serviced engine with 11qts. of Aeroshell W100 engine oil.

This engine has been inspected in accordance Beechcraft 100 hour long / annual inspection form P/N: 11862R dated 04/01/2014 and found to be in airworthy condition. See current engine S/N: 1037315 AD listing for AD compliance.

---END---

Signature

AIP Z 7 Z 7 3 4 3 TA
Certificate Number

Southwest Aircraft Charter Maintenance Operations 1675 E. Ryan Road Chandler, AZ 85286



Aircraft Tail #: N2348Q RT Aircraft Serial #: TH-1848

Engine Serial # 1037315 Hour Meter: 49.6

> TSR. 452.3 Date: 07/26/2021

- Performed cylinder compression test; cyl: #1 72/80, #2 71/80, #3 72/80, #4 72/80, #5 73/80, #6 71/80

Complied with Continental motors CSB07-01A. No discrepancies found.

Drained oil and removed and replaced oil filter P/N: CH48109-1. Serviced engine with 11qts of Aeroshell W100 engine oil
This engine has been inspected in accordance with <u>Beecheraft 100-hour short form inspection guide P/N: 98-39097K dated 04/01/2014</u>
and is in airworthy condition.

--END--

Signature

AIP Z7Z7345
Certificate Number