



PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 172S125860 N828PK

PROPELLER MODEL AND SERIAL A170E/SH47060 ADJ23010

HUB SERIAL ADJ23010 BLADE SERIALS NA, NA, NA

D5519-2-13

INSTRUCTIONS

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.417 and/or other prevailing government regulations.

NOTE: Record Service Bulletins and Airworthiness Directives in the back of this record as well as the Airframe Maintenance Record.

Copyright © 1996

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED					AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER	
	HOURS	10THS							

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Total Engine HRS	Total Prop Hrs
172S12596	12596	N828PK	Dec 5, 2020	IDP	3.5	5	3.5	3.5

Propeller hub S/N **AOJ23010** Blade S/N #1 **NA** Blade S/N #2 **NA** Blade S/N #3 **NA**
has been installed on engine S/N **L-38550-51E** on aircraft S/N **172S12596** with TTAF **3.5** TTSN was **3.5**

Work Performed by **TEXTRON AVIATION INC.** Certificate No. **PC-4** Date **Dec 5, 2020**

*I certify that the above stated maintenance and/or inspection was performed in accordance
with the current regulations of the Federal Aviation Administration*

Work inspected by

Stephen Catlin

Certificate No. **PC-4**

Date **Dec 5, 2020**

Pertinent details of this maintenance are on file at our facility under the above Work/Service Order
Number as applicable.