N/60329



Registered Owner R	lecord			No.
Name Rick Roberts		Address		
City	State	From		
Name Austin Andersor	<u> </u>	Address 2820 Su	mmit Dr	
city Pocabllo		From		
Name Austin Anders				
City Pocalello	State ID	From 2820 Swymit	To 11151 Dearridge	
		Address		
City		From		
-	State	Address		
Name			To	
City	State			
Name		Address		
City	State	From	То	
Name		Address		
City	State	From	To	
Name		Address		
City	State	From	To	
Name		Address		
City	State	From	То	

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20	RECORDING TACH TIME	TODAY'S Flight	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE	DATE 09/ THIS ENGINE TCM OVERHAINSPECTED. T CRANKCASE, INTERNAL ST BY J&J AIRPA ALL CERTIFIE BOLTS AND N SPRING, GASE ALL LOCKING TIME. ENGINE	MODEL IG UL MANG HE FOLLO CRANKSI EEL, AND ITEMS. UTS, ALL ETS AND TABS AN WAS INS AD'S COM	D-520-BB SN JAL PN X300 DWING ITEM HAFT, CAMS OIL COOLEI CYLINDERS ENGINE WA INTERNAL I SEALS, SPA ID WASHERS TALLED WITH	TSMOH: 0 248572-R MAJOR OVERHAULED THIS DATE IN ACCORDANCE WITH 39A. ENGINE WAS DISASSEMBLED, CLEANED, AND VISUALLY IS WERE SENT OUT FOR INSPECTION AND CERTIFICATION: HAFT, CONNECTING RODS, LIFTERS, ROCKER ARMS, ALL R. CYLINDERS WERE OVERHAULED, CERTIFIED, AND ASSEMBLED WERE ASSEBLED WITH ALL NEW PARTS. SEE YELLOW TAGS ON AS ASSEMBLED WITH ALL NEW MAIN AND ROD BEARINGS, ROD HARDWARE, OIL TEMP CONTROL VALVE, OIL PRESSURE RELIEF RK PLUGS, IGNITION HARNESS, MAGNETO DRIVE BUSHINGS, AND S. AN OVERHAULED STARTER ADAPTER WAS INSTALLED AT THIS TH NEW MOUNTS AND TEST RUN WITH ALL INDICATIONS GOOD. AT THIS TIME. END.	13 Jue 2016	3356,37 3369, 9		k Conf	Technician or Repair Facility. (See back pages for other specific entries.) New Crank shaff seal in stabled due to seepage of seal done at overhaul. Reploenut seal applied fro seal crank case to outside of seal instabled retaining plates. After cure of Pro seal run up & flights no leak. When ZBlade prop was removed for crank sheft seal change and New 3 blade Houtall model PHC-C3YF-IRF/8068 as per STC SA-10135 \$ C, See proplog and 337. Frank Z. Vouk Aof 2239538 Massion check #1250 #285 #3 #50 #44 %60 % #655. Cleared and gapped plugs and new M674 gaslate instabled. New Bralett Airf: 164 BA7112
25 F 25/6	HEART OF 1 877-597-2306	** 1 a. E.	TAIRCRAI Deple CPEN 109-16	TENGINES, INC. Ited and Raplamish of City 10 CTS Extra 2000 (Doold folder found to be free of debrie. Mail [14 1451 Bell and Smith.]. Rim up check operation tel. Frank 5, Vant Art 2237538					Timing chested OK. Solkant clearlengine. Runup clearle normal no lewer noted al contify that this engine has been ingretal IAW an 100 HP inspection and was determed to be in on Airwhy condition. Frank 7. Vouk And 2239538

	YEAR 20 / L Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	20 17	RECORDING TACH TIME	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	fer 22	3411.5			Change oil " Filter Even Elet No Mord in Silk	June 18	3441.3		Enginer removed Sento Western Skyways for fear down in spection Julia L Mungu At 1744682
	15 MAR 2017	3411.99			Replaced Crankshaft seal with new SA641250 seal Proposas reinstalled + Torquet to spes. Frank E. Vork -		SM		Juhua L'Mungu Ar? 1744682
)	MAYI				Tope talled General Assisting	7-1110-11			
	<i>3</i> 0) 1	3416.0			modification, Inc GAMIjectine BKH mo GAD 13A SN 26275 IAW				
					STC# SE09217 SC PMA = PQ821SW Scc 337 form dated May 1, 2017				
	M4924	3439.24	,		No Metal IN FILLER CLEAN 350 5157				
					The Merky the Flact Clear 100 377.				

YEAR 20 / ^7 DATE	RECORDING TACH TIME		TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20/8 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
Si plut			3441,3	Engine reinstalled after Western	aug!			3557.9	Diff lin Chack no 50-79 702 80-78
				Skyways repairs. Shell mimeral 100 0: I added: Engine installed IAU Beech A-36 MM. Testran good	Total T	me SMOH	116.6	-lra	703080-79 no480-76 no5 80-79 no680-79
		<u> </u>		O: Padded, Engine installed IAN					Trag timing Check.
		ļ		Beech A-36 MM lestrangood				<u>-</u> -	
			<u> </u>	Test Plight good.	-				I certify that this Airsraft—Engine—has been in-
		<u> </u>	<u> </u>			-			spected in accordance with a 100 hour—Annual Inspection—and has been found to be in an air-
		<u> </u>	<u> </u>	certify that this Aircraft—Engine—has been in-	<u> </u>	1			worthy condition for return to service.
		<u> </u>		Inspection—and has been found to be in an air-		1			By Toshua L Munger ArP 1744682
		· · · - · ·	 	worthy condition for return to service.		26/001			Change Oil Ex Elent Justice
		-	 	Joshua L. Munger - 1744682	2ept 6	3569,90			Change Oil Ex Elent Just
20/10/2	1 7/17	a	<u> </u>		Mach 15	3590.92			through at 1 Tiller Torondal All Tille day
JULI IVIT	7916	41	+	USP NO METAL IN FILTER AT TIME	J. M.C.	/			On Good of well - Biling continue
	<u> </u>	+	-	Keei Rubert Punket Owner 390 9158					Changed oil + Filter. Inspected Dil Filter (cut open) 100 signs of metal - Oil in good conditions, Oil Change & silter trapate grenes filter NO metal vil Good has the
7/7/19	35/7	90		Claux Dil to Exam Elite 2050	July 1	3041,42	_		al clamac & silter translationers filter
1111-12	2717	1		Kit hote oune 3008(88					no metal vil god hat the
									, , , , , , , , , , , , , , , , , , ,

20 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20-20 DATE	RECORDING TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	3675,7		334.4	Spark plays Cleaned, gap, rotated DiffAircheck 18076 280-75 \$80.76	MON 13	37/9.0		3790.H	Diff Air Check No 80-77 No 280-76
				480-78 58 -75 680.78 Mag Himings					Diff Bir Check No 80-77 No 280-76
			,	Dress right reav angine leg groove					110 39 74 10 00 11 110 00 11 10 10 10
		-		t certify that this Atterest Engine—has been in- spected in accordance with a 100 hour—Annual		<u> </u>			Mag timing Check good Installed new Exhaust muller K701-04 Lett hand K701-05 Right hand Engine + Cowl
				Inspection—and has been found to be in an air- worthy condition for return to service.				_	Wash.
				By Joshua L. Munger - 1 & A 1744682					I certify that this Attenuit—Engine—has been in- specied in accordance with a 100 hour—Annual
									Inspection—and has been found to be in an air. worthy condition for return to service.
									Joshua L. Munger - 12 A 1744682
*** <u></u>		_							
						·			
							<u></u>		

YEAR 20	NG0220 Engine Logbook Entry IO-520-BB Engine S/N: 2485/2-R	18 YEAI	· ;	RECORDING TACH TIME	TODAY'S FLIGHT		Description of Inspections, Tests, Repairs and Atterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
DATI	N60329 Engine Logbook Entry 10-520-DD Engine Service S	DATI				- CENTIOL	recritician of hepair Facility. (388 back pages for other specific entiries.)
_	DCompleted an Annual inspection in accordance with FAR43 Appendix 5						
	shoot of 9 OHIGE						
	2) Drained engine oil, removed old filter cut open and inspected. Forting 12:00 oil filter P/N: CH48109-1 and serviced with 11 quarts of Phillips X/C 20W-50 oil filter P/N: CH48109-1 and serviced with 11 quarts on the bottle.						
	filter P/N: CH48103-1 and service instructions on the bottle.						
		7					
	#1 Cylinder #2 Cylinder 75/80 75/80 75/80						
	6) Washed the engine and lubed controls.						
	7) Removed Gamijectors and cleaned and reason leak check good.			-			
	7)Removed Gamijectors and cleaned and reinstance per 001. Pressurized fuel system, leak check good. 8) Performed fuel system adjustments per Continental M-O manual. Set idle to 600 rpm with unmetered fuel pressure at 10.7 psi, set full throttle metered pressure to 15.8 psi at 2700 rpm and 23.5 gpm flow.			. <u>.</u>	-		
	pressure at 10.7 psi, set full throttle metered pressure to 15.8 psi at 2700 ipin and	<u>.</u>					
	9) AD's checked thru Bi-Weekly 2022-06.	į į					
	9) AD's checked thru Bi-Weekly 2022-00. I certify that this engine has been inspected in accordance with a Annual inspection and was determined to be						
-	I certify that this engine has been inspected in description					L-	
	in airworthy condition. Avcenter, PIH	<u></u>					
	Signed: Alex Neiwert A&P3531597IA Avcenter, PIH						
	Signed. Mes : 18:11						