## **1984 Citation 650**

## 1984 Citation 650

ngg\_shortcode\_0\_placeholder

AIRFRAME STATUS

MFR YEAR: 1984

MODEL YEAR: 1984

TOTAL TIME: 9,734

TOTAL LANDINGS: 7,663

ENGINE STATUS

**NO 1 ENGINE** 

Honeywell TFE731-3C-100S S/N: P-87235

TSN: **9,557** 

CSN: 7,609

**NO 2 ENGINE** 

Honeywell TFE731-3C-100S S/N: P-87220

TSN: **9,124** 

CSN: 6,610

## APU

Hamilton Sundstrand T-62T-40C3A/3A1 TSN: 2,704

CSN: **5,671** 

AVIONICS

Single Garmin 530W & Single Garmin 430W Dual Garmin 330 Mode S Transponders w/ Traffic info system displayed on 530

Dual King KHF-950 HF with SELCAL

King ART-2000 Vertical Profile Color Radar King KDR-510 Data Link Weather System BFGoodrich WX-950 Stormescope

King KMH 980 TCAS I / EGPWS

King KMD-850 Multi-Function Display for Mapping, Weather and TCAS / EGPWS Sperry SPZ-650 Autopilot

RVSM Capable

ADS-B Out Compliant

ADDITIONAL EQUIPMENT

Fairchild GA100 CVR Pointer 3000 ELT System Freon AC & Flood Cooling

CD/DVD Player w/ Fwd & Aft Drop Down Monitors (w/ remote)

Airshow 400

Electric window shades (w/remote) LED Cabin Lighting

Dual Concorde Maintenance Free Lead Acid Batteries

All history tracked with CESCOM since 1984

EXTERIOR & INTERIOR

New Paint: January 2012

## **Interior Refurbishment: January 2015**

9 Passenger Configuration 5 Individual Club Chairs

Fwd 4-Place Divan w/ Storage Underneath Ultra Leather Sidewalls & Headliner Mini Galley w/ Microwave, Ice Drawer, Beverage Storage & Snack Storage Combination CD/DVD player

2 Ceiling Mounted, Drop Down Monitors Electric Window Shades
w/ Individual & Remote Master Controls

Enclosed Aft Lav w/ Running Water Super Soundproofing

Fully Adjustable LED Upwash & Downwash Lighting

Individual Reading Lights

MAINTENANCE STATUS

Doc 8 c/w 02/19/2021, Next Due 02/29/2024 Doc 11 c/w 02/19/2021, Next Due 02/28/2027

ngg\_shortcode\_1\_placeholderSpecifications and/or descriptions are provided as introductory information. They do not constitute representations or warranties of Northern Jet Sales, LLC. Accordingly; you should rely on your own inspection of the aircraft.