

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C3YR-1RF/F7282

PROPELLER S/N PA 1938B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position FRONT

PITCH RANGE

Propeller Model _____

High/Feather _____

Propeller S/N _____

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 _____

Aircraft Manufacturer _____

No. 2 _____

Aircraft Model _____

No. 3 _____

S/N _____



No. 4 _____

Registration _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	FINGERLAKES FLYING SERVICE	2984 BENSON ROAD	SKANEATELES N Y 13152 585-7647068
	HARTZELL	HC-C3YR-1RF/F7282	PA1938B
	5-14-21	TACH 3718.12	T.T/TSNEW 0.00
	PROPELLER INSTALLED ON PA28R-200 N87KG SER# 28R-35043 IN ACCORDANCE WITH HARTZELL STC# SA4528NM AND OWNERS MANUAL # 115N - I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.		
	 DON McANN AP37863461A		
	May 15, 2023	Tach: 3723.5	Total Time: 5.38 HC-C3YR-1RF/F7282 S/N PA1938B
	Complied with a 100-hour Inspection per FAR43 Appendix D. AD's checked through Bi-Weekly 2023-10.		
	<ul style="list-style-type: none"> Lubricated propeller with NYCO GN3058. 		
	I certify that this propeller has been inspected in accordance with a 100-hour inspection and was determined to be in airworthy condition.  Taber Robbins A&P 2738826		

HARTZELL

MODEL: HC-C3YR-1RF/F7282

S/N: PA1938B

06/06/2024

TACH: 3746.60

TSPOH: 28.48

Annual inspection performed at this time, propeller cleaned and dressed. Greased hub with Nyco GN3058.

Airworthiness Directives checked to date and entered in the aircraft permanent file. I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.


Matthew Donnelly

AP3604140IA
AP3604140IA