



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                                                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains  |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|---------------------|
| 262203F<br>FORWARD             | HYDROSTATIC TEST APU EXTINGUISHER                                                                                  |      |         | 30300015<br>37789B1           | MTH 01-Apr-2021                           |                | 60             |                | 30-Apr-2026                | 15 m 0 d            |
| 055012                         | INTERIOR CABIN/TAILCONE FLUID SPILL - GIVEN IN INTERIOR CABIN/TAILCONE FLUID SPILL                                 |      |         |                               | MTH                                       |                | A/R            |                |                            |                     |
| 055013                         | EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED - GIVEN IN EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED |      |         |                               | MTH                                       |                | A/R            |                |                            |                     |
| 5-12-01                        | INSPECTION DOCUMENT 1                                                                                              |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 12<br>400      |                | 31-Mar-2025<br>9152.5      | 2 m 1 d<br>378.6    |
| 5-12-02                        | INSPECTION DOCUMENT 2                                                                                              |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 400            |                | 9135.3                     | 361.4               |
| 5-12-03                        | INSPECTION DOCUMENT 3                                                                                              |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 12             |                | 31-Mar-2025                | 2 m 1 d             |
| B262201<br>CABIN               | FUNCTIONAL CHECK HALON EXTINGUISHER (WEIGHT CHECK) : INSPECTION DOCUMENT 3                                         |      |         | C352TS<br>74101642            | MTH 01-Mar-2024                           |                | 12             |                | 31-Mar-2025                | 2 m 1 d             |
| Weight Check Date: 01-Mar-2024 |                                                                                                                    |      |         |                               |                                           |                |                |                |                            |                     |
| B262201<br>COCKPIT             | FUNCTIONAL CHECK HALON EXTINGUISHER (WEIGHT CHECK) : INSPECTION DOCUMENT 3                                         |      |         | C352TS<br>74101641            | MTH 01-Mar-2024                           |                | 12             |                | 31-Mar-2025                | 2 m 1 d             |
| Weight Check Date: 01-Mar-2024 |                                                                                                                    |      |         |                               |                                           |                |                |                |                            |                     |
| 5-12-04                        | INSPECTION DOCUMENT 4                                                                                              |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 24<br>400      |                | 31-Mar-2026<br>9152.5      | 14 m 1 d<br>378.6   |
| 5-12-05                        | INSPECTION DOCUMENT 5                                                                                              |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 24<br>800      |                | 31-Mar-2026<br>9552.5      | 14 m 1 d<br>778.6   |
| 5-12-06                        | INSPECTION DOCUMENT 6                                                                                              |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 800            |                | 9535.3                     | 761.4               |
| 5-12-07                        | INSPECTION DOCUMENT 7                                                                                              |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 24             |                | 31-Mar-2026                | 14 m 1 d            |
| 5-12-08                        | INSPECTION DOCUMENT 8                                                                                              |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     |                | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| 5-12-09                        | INSPECTION DOCUMENT 9                                                                                              |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36             |                | 30-Jun-2024                | -7 m -1 d           |
| 5-12-11                        | INSPECTION DOCUMENT 11                                                                                             |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 72             |                | 30-Sep-2027                | 32 m 0 d            |
| D262203<br>CABIN               | EMPTY/INSPECT/RECHARGE HALON EXTINGUISHER : INSPECTION DOCUMENT 11                                                 |      |         | C352TS<br>74101642            | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 72             |                | 30-Sep-2027                | 32 m 0 d            |
| D262203<br>COCKPIT             | EMPTY/INSPECT/RECHARGE HALON EXTINGUISHER : INSPECTION DOCUMENT 11                                                 |      |         | C352TS<br>74101641            | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 72             |                | 30-Sep-2027                | 32 m 0 d            |
| 5-12-19                        | INSPECTION DOCUMENT 19                                                                                             |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 72<br>2400     |                | 30-Jun-2027<br>11135.3     | 29 m 0 d<br>2361.4  |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 5-12-20               | INSPECTION DOCUMENT 20<br>FXE                                                                           |      |         |                               | MTH 26-Mar-2019<br>HRS 8642.2<br>LDG 7130 |                | 200            |                | 8842.2                     | 68.3               |
| 5-12-21               | INSPECTION DOCUMENT 21                                                                                  |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 500            |                | 9235.3                     | 461.4              |
| B243000<br>NO. 1      | CAPACITY CHECK BATTERY LEAD ACID BATTERY: INSPECTION DOCUMENT 23                                        |      |         | S3597-4<br>41326428           | MTH 23-May-2024<br>HRS 8773.9<br>LDG 7234 |                | 4<br>200       |                | 30-Sep-2024<br>8973.9      | -4 m -1 d<br>200   |
| Over Due              |                                                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| B243000<br>NO. 2      | CAPACITY CHECK BATTERY LEAD ACID BATTERY: INSPECTION DOCUMENT 23                                        |      |         | S3597-4<br>41325862           | MTH 23-May-2024<br>HRS 8773.9<br>LDG 7234 |                | 4<br>200       |                | 30-Sep-2024<br>8973.9      | -4 m -1 d<br>200   |
| Over Due              |                                                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| 5-12-25               | INSPECTION DOCUMENT 25<br>UNK                                                                           |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | A/R            |                |                            |                    |
| 5-12-26               | INSPECTION DOCUMENT 26<br>UNK                                                                           |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 4800           |                | 13535.3                    | 4761.4             |
| 5-12-28               | INSPECTION DOCUMENT 28<br>CCS                                                                           |      |         |                               | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | 6              |                |                            |                    |
| B237001               | FUNCTIONAL CHECK COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (PINGER TEST): INSPECTION DOCUMENT 30 |      |         | DK120<br>AT131419             | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 24             |                | 31-Mar-2026                | 14 m 1 d           |
| A324101<br>NO. 1      | SPECIAL DETAILED INSPECTION MAIN WHEEL (NDI): INSPECTION DOCUMENT 40                                    | UNK  |         | 3-1399-6<br>0990#2219         | MTH                                       |                | A/R            |                |                            |                    |
| A324101<br>NO. 2      | SPECIAL DETAILED INSPECTION MAIN WHEEL (NDI): INSPECTION DOCUMENT 40                                    | FXE  |         | 3-1399-6<br>1880              | MTH                                       |                | A/R            |                |                            |                    |
| A324101<br>NO. 3      | SPECIAL DETAILED INSPECTION MAIN WHEEL (NDI): INSPECTION DOCUMENT 40                                    | FXE  |         | 3-1399-5<br>2982#3109         | MTH                                       |                | A/R            |                |                            |                    |
| A324101<br>NO. 4      | SPECIAL DETAILED INSPECTION MAIN WHEEL (NDI): INSPECTION DOCUMENT 40                                    | UNK  |         | 3-1399-5<br>2723              | MTH                                       |                | A/R            |                |                            |                    |
| A324101<br>NOSE       | SPECIAL DETAILED INSPECTION WHEEL (NDI): INSPECTION DOCUMENT 40                                         | FXE  |         | 3-1418<br>3088                | MTH                                       |                | A/R            |                |                            |                    |
| 5-12-41L              | INSPECTION DOCUMENT 41 LEFT ENGINE<br>UNK                                                               |      |         |                               | MTH 21-Oct-2011<br>HRS 7545.3<br>LDG 6400 |                | 2100           |                | 9645.3                     | 871.4              |
| 5-12-41R              | INSPECTION DOCUMENT 41 RIGHT ENGINE<br>UNK                                                              |      |         |                               | MTH 21-Oct-2011<br>HRS 7545.3<br>LDG 6400 |                | 2100           |                | 9645.3                     | 871.4              |
| 5-12-42               | INSPECTION DOCUMENT 42                                                                                  |      |         |                               | MTH 12-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | 12             |                | 31-Dec-2024                | -30 d              |
| Over Due              |                                                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| 341010                | INSPECT RVSM SKIN WAVINESS: INSPECTION DOCUMENT 43                                                      |      |         |                               | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position         | Description<br>Drawing # / Task #                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------|---------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| B341105<br>COPILOT            | CALIBRATION TEST ALTIMETER : INSPECTION DOCUMENT 43                                   |      |         | 520-15790-903<br>1059         | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| B341105<br>NO. 1              | CALIBRATION TEST AIR DATA COMPUTER : INSPECTION DOCUMENT 43                           |      |         | 7000700-665<br>03119559       | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| B341105<br>NO. 2              | CALIBRATION TEST AIR DATA COMPUTER : INSPECTION DOCUMENT 43                           |      |         | 7000700-665<br>83090293       | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| B341105<br>PILOT              | CALIBRATION TEST ALTIMETER : INSPECTION DOCUMENT 43                                   |      |         | 4016341-905<br>5071038        | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| B341105<br>STANDBY            | CALIBRATION TEST ALTIMETER : INSPECTION DOCUMENT 43                                   |      |         | 10460-11880<br>W10869         | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| B345201<br>COPILOT            | PERFORM TRANSPONDER CHECKS/INSPECTIONS REQUIRED BY FAR 91.413: INSPECTION DOCUMENT 43 |      |         | 9007000-57001<br>NXE02453     | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| B345201<br>PILOT              | PERFORM TRANSPONDER CHECKS/INSPECTIONS REQUIRED BY FAR 91.413: INSPECTION DOCUMENT 43 |      |         | 066-01143-0601<br>97032377    | MTH 08-Dec-2023                           |                | 24             |                | 31-Dec-2025                | 11 m 1 d           |
| Calibration Date: 08-Dec-2023 |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| 5-12-45                       | INSPECTION DOCUMENT 45                                                                |      |         |                               | MTH 17-Jul-2008<br>HRS 6926.2<br>LDG 5992 |                | 2000           |                | 7992                       | 758                |
| 5-12-47                       | INSPECTION DOCUMENT 47                                                                |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 12<br>800      |                | 31-Mar-2025<br>9552.5      | 2 m 1 d<br>778.6   |
| 5-12-48                       | INSPECTION DOCUMENT 48                                                                |      |         |                               | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | 24<br>1600     |                |                            |                    |
| 5-12-50                       | INSPECTION DOCUMENT 50                                                                |      |         |                               | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 6              |                | 30-Sep-2024                | -4 m -1 d          |
| Over Due                      |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| 5-12-51                       | INSPECTION DOCUMENT 51                                                                |      |         |                               | MTH 15-Sep-2015<br>HRS 8099<br>LDG 6754   |                | 1200           |                | 9299                       | 525.1              |
| 5-12-MA                       | INSPECTION DOCUMENT MA (CHAPTER 4 REQUIREMENT)                                        |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 100            |                | 8835.3                     | 61.4               |
| 5-12-MD                       | INSPECTION DOCUMENT MD (CHAPTER 4 REQUIREMENT)                                        |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 600            |                | 9335.3                     | 561.4              |
| 5-12-ME                       | INSPECTION DOCUMENT ME (CHAPTER 4 REQUIREMENT)<br>FXE                                 |      |         |                               | MTH 10-Jan-2016<br>HRS 8174<br>LDG 6797   |                | 900            |                | 9074                       | 300.1              |
| 5-12-MG                       | INSPECTION DOCUMENT MG (CHAPTER 4 REQUIREMENT)                                        |      |         |                               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 1200           |                | 9935.3                     | 1161.4             |
| 5-12-MI                       | INSPECTION DOCUMENT MI (CHAPTER 4 REQUIREMENT)                                        |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 72<br>2400     |                | 30-Jun-2027<br>11135.3     | 29 m 0 d<br>2361.4 |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                       | Description<br>Drawing # / Task #                   | City | Mod Lvl                          | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------|-----------------------------------------------------|------|----------------------------------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 5-12-ML                                     | INSPECTION DOCUMENT ML (CHAPTER 4 REQUIREMENT)      |      |                                  | MTH                           | 23-Aug-1995              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 3260                     |                | 12000          |                | 15260.2                    | 6486.3             |
| 057110<br>E1                                | 150/250 HOUR INSPECTION                             |      |                                  | MTH                           | 05-Jun-2021              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8735.3                   |                | 150            |                | (8708.4)8885.3             | 111.4              |
|                                             |                                                     |      |                                  | LDG                           | 7213                     |                |                |                |                            |                    |
| 057110<br>E2                                | 150/250 HOUR INSPECTION                             |      |                                  | MTH                           | 05-Jun-2021              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8735.3                   |                | 150            |                | (8695.6)8885.3             | 111.4              |
|                                             |                                                     |      |                                  | LDG                           | 7213                     |                |                |                |                            |                    |
| 057120<br>E1                                | 300/400 HOUR INSPECTION                             | KFXE |                                  | MTH                           | 02-Apr-2018              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8531.9                   |                | 300            |                | (8655)8831.9               | 58                 |
|                                             |                                                     |      |                                  | LDG                           | 7040                     |                |                |                |                            |                    |
| 057120<br>E2                                | 300/400 HOUR INSPECTION                             | FXE  |                                  | MTH                           | 02-Apr-2018              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8531.9                   |                | 300            |                | (8642.2)8831.9             | 58                 |
|                                             |                                                     |      |                                  | LDG                           | 7040                     |                |                |                |                            |                    |
| 057130<br>E1                                | 600/800 HOUR INSPECTION                             | FXE  |                                  | MTH                           | 14-Mar-2017              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8328.5                   |                | 800            |                | (8951.6)9128.5             | 354.6              |
|                                             |                                                     |      |                                  | LDG                           | 6901                     |                |                |                |                            |                    |
| 057130<br>E2                                | 600/800 HOUR INSPECTION                             | FXE  |                                  | MTH                           | 15-Mar-2017              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 8328.5                   |                | 800            |                | (8938.8)9128.5             | 354.6              |
|                                             |                                                     |      |                                  | LDG                           | 6901                     |                |                |                |                            |                    |
| 057140<br>E1                                | 1000/1500 HOUR INSPECTION                           | UNK  |                                  | MTH                           | 12-Oct-2011              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 7545.3                   |                | 1500           |                | (8868.4)9045.3             | 271.4              |
|                                             |                                                     |      |                                  | LDG                           | 6403                     |                |                |                |                            |                    |
| 057140<br>E2                                | 1000/1500 HOUR INSPECTION                           | UNK  |                                  | MTH                           | 11-Oct-2011              |                |                |                |                            |                    |
|                                             |                                                     |      |                                  | HRS                           | 7545.3                   |                | 1500           |                | (8855.6)9045.3             | 271.4              |
|                                             |                                                     |      |                                  | LDG                           | 6403                     |                |                |                |                            |                    |
| 12-26-00-601                                | 15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH   |      |                                  | MTH                           |                          |                | A/R            |                |                            |                    |
| 12-26-00-602                                | 45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH |      |                                  | MTH                           |                          |                | A/R            |                |                            |                    |
| 12-26-00-603                                | 90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH    |      |                                  | MTH                           |                          |                | A/R            |                |                            |                    |
| 213000                                      | PRIMARY OUTFLOW VALVE FILTER - DISCARD              |      |                                  | MTH                           | 05-Jun-2021              |                | 36             |                | 30-Jun-2024                | -7 m -1 d          |
|                                             |                                                     |      |                                  | HRS                           | 8735.3                   |                | 1200           |                | 9935.3                     | 1161.4             |
|                                             |                                                     |      |                                  | LDG                           | 7213                     |                |                |                |                            |                    |
| 256018                                      | INSPECT LIFE RAFT                                   |      |                                  | MTH                           | 31-Jul-2023              |                | 12             |                | 31-Jul-2024                | -5 m 30 d          |
|                                             |                                                     |      | 1900-1/2000-1<br>3610BDA/2516BDA |                               |                          |                |                |                |                            |                    |
| 261000<br>LEFT ENGINE                       | SERVICE LIFE EXTINGUISHER (FORWARD) CARTRIDGE       |      |                                  | MTH                           | 04-Apr-2016              |                | 120            |                | 30-Apr-2026                | 15 m 0 d           |
|                                             |                                                     |      | M30903824<br>00933               |                               |                          |                |                |                |                            |                    |
| Installation (Serv. Life) Date: 04-Apr-2016 |                                                     |      |                                  |                               |                          |                |                |                |                            |                    |
| 261002<br>LEFT ENGINE                       | SERVICE LIFE EXTINGUISHER (AFT) CARTRIDGE           |      |                                  | MTH                           | 04-Apr-2016              |                | 120            |                | 30-Apr-2026                | 15 m 0 d           |
|                                             |                                                     |      | M30903824<br>00939               |                               |                          |                |                |                |                            |                    |
| Installation (Serv. Life) Date: 04-Apr-2016 |                                                     |      |                                  |                               |                          |                |                |                |                            |                    |
| 262000<br>RIGHT ENGINE                      | SERVICE LIFE EXTINGUISHER (FORWARD) CARTRIDGE       |      |                                  | MTH                           | 30-Apr-2016              |                | 120            |                | 30-Apr-2026                | 15 m 0 d           |
|                                             |                                                     |      | M30903824<br>00936               |                               |                          |                |                |                |                            |                    |
| Installation (Serv. Life) Date: 30-Apr-2016 |                                                     |      |                                  |                               |                          |                |                |                |                            |                    |
| 262002<br>RIGHT ENGINE                      | SERVICE LIFE EXTINGUISHER (AFT) CARTRIDGE           |      |                                  | MTH                           | 30-Apr-2016              |                | 120            |                | 30-Apr-2026                | 15 m 0 d           |
|                                             |                                                     |      | M30903824<br>00937               |                               |                          |                |                |                |                            |                    |
| Installation (Serv. Life) Date: 30-Apr-2016 |                                                     |      |                                  |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                       | Description<br>Drawing # / Task #                                                                                                 | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 263000<br>APU                               | SERVICE LIFE EXTINGUISHER CARTRIDGE                                                                                               |      |         | AE30903824<br>866             | MTH 01-Mar-2024          |                | 96             |                | 31-Mar-2032                | 86 m 1 d           |
| Installation (Serv. Life) Date: 01-Mar-2024 |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| 263000F                                     | SERVICE LIFE APU FIRE EXT CARTRIDGE                                                                                               |      |         |                               | MTH 05-Jun-2021          | -30            | 96             |                | 31-Dec-2026                | 23 m 1 d           |
| 263001F                                     | TOTAL LIFE APU FIRE EXT CARTRIDGE                                                                                                 |      |         |                               | MTH 01-Dec-2016          |                | 120            |                | 31-Dec-2026                | 23 m 1 d           |
| 263005                                      | SERVICE LIFE APU EXTINGUISHER (AFT) CARTRIDGE                                                                                     |      |         | AE30903824<br>794             | MTH 01-Mar-2024          |                | 96             |                | 31-Mar-2032                | 86 m 1 d           |
| Installation (Serv. Life) Date: 01-Mar-2024 |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| D262003<br>LEFT ENGINE                      | HYDROSTATIC TEST EXTINGUISHER                                                                                                     |      |         | 9914193-1<br>05225C1          | MTH 05-Jun-2021          |                | 60             |                | 30-Jun-2026                | 17 m 0 d           |
| D262003<br>RIGHT ENGINE                     | HYDROSTATIC TEST EXTINGUISHER                                                                                                     |      |         | 32700012<br>06872C1           | MTH 05-Jun-2021          |                | 60             |                | 30-Jun-2026                | 17 m 0 d           |
| D262103<br>APU                              | HYDROSTATIC TEST EXTINGUISHER                                                                                                     |      |         | 32700012<br>11771C1           | MTH 01-Feb-2024          |                | 60             |                | 28-Feb-2029                | 48 m 29 d          |
| Hydro Check Date: 01-Feb-2024               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| D262201<br>CABIN                            | HYDROSTATIC TEST HALON EXTINGUISHER                                                                                               |      |         | C352TS<br>74101642            | MTH 20-Sep-2016          |                | 144            |                | 30-Sep-2028                | 44 m 0 d           |
| Hydro Check Date: 20-Sep-2016               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| D262201<br>COCKPIT                          | HYDROSTATIC TEST HALON EXTINGUISHER                                                                                               |      |         | C352TS<br>74101641            | MTH 20-Sep-2016          |                | 144            |                | 30-Sep-2028                | 44 m 0 d           |
| Hydro Check Date: 20-Sep-2016               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| 28-00-02-220                                | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)                                |      |         |                               |                          |                |                |                |                            |                    |
|                                             |                                                                                                                                   |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| 28-00-02-221                                | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)                                    |      |         |                               |                          |                |                |                |                            |                    |
|                                             |                                                                                                                                   |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| 324001<br>GEAR                              | EMERGENCY LANDING GEAR PNEUMATIC STORAGE BOTTLE - OVERHAUL                                                                        |      |         | 9914099-3<br>0120             | MTH 09-Mar-2017          |                | 120            |                | 31-Mar-2027                | 26 m 1 d           |
| 324010<br>EMERGENCY                         | EMERGENCY BRAKE PNEUMATIC STORAGE BOTTLE - OVERHAUL                                                                               |      |         | 9914099-4<br>0056             | MTH 30-Apr-2021          |                | 120            |                | 30-Apr-2031                | 75 m 0 d           |
| D324301<br>EMERGENCY                        | EMERGENCY BRAKE PNEUMATIC STORAGE BOTTLE - HYDROSTATIC TEST                                                                       |      |         | 9914099-4<br>0056             | MTH 30-Apr-2021          |                | 60             |                | 30-Apr-2026                | 15 m 0 d           |
| Hydro Check Date: 30-Apr-2021               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| D324301<br>GEAR                             | EMERGENCY LANDING GEAR PNEUMATIC STORAGE BOTTLE - HYDROSTATIC TEST (9914099-3, SOUTHBEND CONTROLS 20028210, FUTURECRAFT 900347-3) |      |         | 9914099-3<br>0120             | MTH 23-Sep-2021          |                | 60             |                | 30-Sep-2026                | 20 m 0 d           |
| Hydro Check Date: 23-Sep-2021               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| 340020                                      | CHECK RVSM HEIGHT MONITORING                                                                                                      |      |         |                               | MTH 21-Aug-1986          |                | A/R            |                |                            |                    |
| 350001                                      | HYDROSTATIC TEST OXYGEN CYLINDER                                                                                                  |      |         | 895-20077<br>ALT281-32980     | MTH 18-Jun-2021          |                | 60             |                | 30-Jun-2026                | 17 m 0 d           |
| Hydro Check Date: 18-Jun-2021               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |
| D350002<br>PORTABLE                         | HYDROSTATIC TEST OXYGEN CYLINDER                                                                                                  |      |         | 5500-M6W-FF23AP<br>158060     | MTH 30-Apr-2021          |                | 60             |                | 30-Apr-2026                | 15 m 0 d           |
| Hydro Check Date: 30-Apr-2021               |                                                                                                                                   |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2     | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2  | Remains<br>Remains                         |
|-----------------------|-----------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|--------------------|----------------|-----------------------------|--------------------------------------------|
| 490010<br>051335      | ACCOMPLISH 6 MONTH/125 HOUR/250 CYCLE INSPECTION    |      |         |                               | APUH 01-Mar-2024<br>APUS 2174<br>4795     |                | 6<br>125<br>250    |                | 30-Sep-2024<br>2299<br>5045 | -4 m -1 d<br>125<br>250<br><b>Over Due</b> |
| 490020<br>051336      | ACCOMPLISH 6 MONTH/250 HOUR/500 CYCLE INSPECTION    |      |         |                               | APUH 01-Mar-2024<br>APUS 2174<br>4795     |                | 6<br>250<br>500    |                | 30-Sep-2024<br>2424<br>5295 | -4 m -1 d<br>250<br>500<br><b>Over Due</b> |
| 490030<br>051337      | ACCOMPLISH 12 MONTH/500 HOUR/1000 CYCLE INSPECTION  |      |         |                               | APUH 01-Mar-2024<br>APUS 2174<br>4795     |                | 12<br>500<br>1000  |                | 31-Mar-2025<br>2674<br>5795 | 2 m 1 d<br>500<br>1000                     |
| 490040<br>051338      | ACCOMPLISH 12 MONTH/1000 HOUR/2000 CYCLE INSPECTION |      |         |                               | APUH 01-Mar-2024<br>APUS 2174<br>4795     |                | 12<br>1000<br>2000 |                | 31-Mar-2025<br>3174<br>6795 | 2 m 1 d<br>1000<br>2000                    |
| 490050<br>051339      | ACCOMPLISH 24 MONTH/1500 HOUR/3000 CYCLE INSPECTION |      |         |                               | APUH 01-Mar-2024<br>APUS 2174<br>4795     |                | 24<br>1500<br>3000 |                | 31-Mar-2026<br>3674<br>7795 | 14 m 1 d<br>1500<br>3000                   |
| 710120<br>E1          | MAJOR PERIODIC INSPECTION (MPI)<br>UNK              |      |         |                               | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 2100               |                | (9468.4)9645.3              | 871.4                                      |
| 710120<br>E2          | MAJOR PERIODIC INSPECTION (MPI)<br>UNK              |      |         |                               | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 2100               |                | (9455.6)9645.3              | 871.4                                      |
| 723110<br>E1          | COMPRESSOR ZONE INSPECTION (CZI)<br>UNK             |      |         |                               | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11568.4)11745.3            | 2971.4                                     |
| 723110<br>E2          | COMPRESSOR ZONE INSPECTION (CZI)<br>UNK             |      |         |                               | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11555.6)11745.3            | 2971.4                                     |
| 724120<br>E1          | INSPECT COMBUSTION PLENUM CASE<br>UNK               |      |         |                               | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 2100               |                | (9468.4)9645.3              | 871.4                                      |
| 724120<br>E2          | INSPECT COMBUSTION PLENUM CASE<br>UNK               |      |         |                               | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 2100               |                | (9455.6)9645.3              | 871.4                                      |
| 726120<br>E1          | INSPECT ACCESSORY GEARBOX<br>UNK                    |      |         | 3070003-11<br>SN-UNKNOWN      | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11568.4)11745.3            | 2971.4                                     |
| 726120<br>E2          | INSPECT ACCESSORY GEARBOX<br>UNK                    |      |         | 3070003-11<br>SN-UNKNOWN      | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11555.6)11745.3            | 2971.4                                     |
| 727110<br>E1          | PERIODIC INSPECT FAN SUPPORT ASSEMBLY<br>UNK        |      |         |                               | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11568.4)11745.3            | 2971.4                                     |
| 727110<br>E2          | PERIODIC INSPECT FAN SUPPORT ASSEMBLY<br>UNK        |      |         |                               | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | 4200               |                | (11555.6)11745.3            | 2971.4                                     |
| 731120<br>E1          | REMOVE AND REPLACE FUEL FILTER ELEMENT              |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 650                |                | (9208.4)9385.3              | 611.4                                      |
| 731120<br>E2          | REMOVE AND REPLACE FUEL FILTER ELEMENT              |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 650                |                | (9195.6)9385.3              | 611.4                                      |
| 790120<br>E1          | CHANGE OIL                                          |      |         |                               | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 1200               |                | (9758.4)9935.3              | 1161.4                                     |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code | Description        | Part Number |         |                | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1    | Remains |
|-----------|--------------------|-------------|---------|----------------|-----------------|--------|-------|-------|----------------|---------|
| Position  | Drawing # / Task # | City        | Mod Lvl | Part Serial No | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2    | Remains |
| 790120    | CHANGE OIL         |             |         |                | MTH 05-Jun-2021 |        |       |       |                |         |
| E2        |                    |             |         |                | HRS 8735.3      |        | 1200  |       | (9745.6)9935.3 | 1161.4  |
|           |                    |             |         |                | LDG 7213        |        |       |       |                |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 211001<br>LEFT        | SHUTOFF EMERGENCY VALVE ASSEMBLY            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 211001<br>RIGHT       | SHUTOFF EMERGENCY VALVE ASSEMBLY            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 211002                | ISOLATION BLEED AIR VALVE ASSEMBLY          |      |         | 9914121-1<br>2AP1             | MTH 17-Feb-2006<br>HRS 6310               |                | O/C            |                |                            |                    |
| 211003<br>LEFT        | VALVE PRESSURE REGULATOR                    |      |         | 9914125-2<br>237              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 211003<br>RIGHT       | VALVE PRESSURE REGULATOR<br>FXE             |      |         | 9914125-2<br>861/45           | MTH 25-May-2019<br>HRS 8643.2<br>LDG 7131 |                | O/C            |                |                            |                    |
| 211004                | BLEED AIR VALVE                             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 211005<br>NO. 1       | BLEED AIR CHECK VALVE                       |      |         | M942-1<br>SN-UNKNOWN          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 211005<br>NO. 2       | BLEED AIR CHECK VALVE                       |      |         | M942-1<br>SN-UNKNOWN          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 211006<br>NO. 1       | EMERGENCY VALVE CHECK                       |      |         | 9912078-3<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 211006<br>NO. 2       | EMERGENCY VALVE CHECK                       |      |         | 9912078-3<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 211015                | COMPRESSOR DRIVE MOTOR                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | N/A            | 0              |                            |                    |
| 211025                | VAPOR CYCLE CONDENSER FAN MOTOR             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | N/A            | 0              |                            |                    |
| 212001                | HYDRAULIC FAN<br>9914129-2                  |      |         | 738846<br>0127A               | MTH 23-Dec-2011<br>HRS 7585.2<br>LDG 6425 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 212002                | -- VALVE--THREE-WAY                         |      |         | 9914153-1<br>214              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 212041                | AVIONICS BLOWER ASSY.                       |      |         | 19A608<br>SN-UNKNOWN          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 212102                | CROSSFEED ACTUATOR ASSEMBLY                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 212301                | DEFOG BLOWER                                |      |         | 19A827<br>SN-UNKNOWN          | MTH 13-Dec-2003<br>HRS 5802               |                | O/C            |                |                            |                    |
| 212402<br>AVIONICS    | EXHAUST FAN                                 |      |         | 4124X<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 212402<br>INSTRUMENT  | EXHAUST FAN                                 |      |         | 4124X<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 213001                | CABIN PRESSURE/ALT INDICATOR<br>FXE         |      |         | 9914060-1<br>25582            | MTH 11-Aug-2017<br>HRS 8399.4<br>LDG 6952 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 213002                | CABIN RATE OF CLIMB INDICATOR               |      |         | 9914059-1<br>W14175H          | MTH 02-Sep-1998<br>HRS 4462               |                | O/C            |                |                            |                    |
| 213003                | CABIN PRESSURE SELECTOR<br>9914183-2<br>FXE |      |         | 2117598-1<br>14-179           | MTH 03-Jan-2018<br>HRS 8462.6<br>LDG 6995 |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # City Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 213004                | MANUAL PRESSURE CONTROL                        | 9914183-13<br>47379           | MTH 13-Jan-2004<br>HRS 5831               |                | O/C            | 4484           |                            |                    |
| 213005                | PRESSURIZATION CONTROLLER<br>FXE               | 2117598-1<br>14-179           | MTH 03-Jan-2018<br>HRS 8462.6<br>LDG 6995 |                | O/C            |                |                            |                    |
| 213006                | CABIN VACUUM REGULATOR                         | 9914183-8<br>157              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 213007                | PRIMARY RELIEF OUTFLOW VALVE                   | 9914183-10<br>74244           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 213008                | SECONDARY RELIEF OUTFLOW VALVE                 | 9914183-11<br>94240           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 213009                | (S402) BAROMETRIC PRESSURE SWITCH<br>UNK       | 9910095-12<br>1121947         | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 214001                | AUXILIARY HEATER ASSEMBLY                      | 6214434-52<br>SN-UNKNOWN      | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 214002                | MOTOR HEATER ASSEMBLY                          | 9910113-3<br>1327             | MTH 25-Sep-2002<br>HRS 5468               |                | O/C            |                |                            |                    |
| 214100                | BLOWER ASSY BAGGAGE HEATER                     | 9914053-2<br>1081             | MTH 16-Mar-2001                           |                | O/C            |                |                            |                    |
| 215000<br>AFT         | HAMILTON STANDARD CABIN ECU                    | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | A/R            | 0              |                            |                    |
| 215000<br>FORWARD     | HAMILTON STANDARD COCKPIT ECU                  | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | A/R            | 0              |                            |                    |
| 215000<br>LEFT        | ENVIRONMENTAL CONTROL UNIT                     | 9914128-8<br>186              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 215000<br>RIGHT       | ENVIRONMENTAL CONTROL UNIT                     | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215001<br>BOTTOM      | SUNDSTRAND COCKPIT ACM<br>SUNSTRAND FXE        | 740551<br>0130                | MTH 11-Aug-2017<br>HRS 8399.4<br>LDG 6952 |                | A/R            | 9<br>0<br>0    |                            |                    |
| 215001<br>TOP         | SUNDSTRAND CABIN ACM<br>SUNSTRAND FXE          | 740551<br>0214                | MTH 11-Aug-2017<br>HRS 8399.4<br>LDG 6952 |                | A/R            | 6<br>0<br>0    |                            |                    |
| 215002<br>BOTTOM      | REGULATING VALVE                               | 725671B<br>SN-UNKNOWN         | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 215002<br>TOP         | REGULATING VALVE                               | 725671B<br>SN-UNKNOWN         | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 215003<br>NO. 1       | WATER SEPARATOR                                | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215003<br>NO. 2       | WATER SEPARATOR                                | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215004<br>BOTTOM      | CONTROLLER BYPASS VALVE                        | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215004<br>TOP         | CONTROLLER BYPASS VALVE                        | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215005<br>BOTTOM      | BYPASS VALVE                                   | 9912069-1<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 215005<br>TOP         | BYPASS VALVE                                   | 9912069-1<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 215006<br>AFT         | AIRCONDITION EVAPORATOR                        | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 215006<br>FORWARD     | AIRCONDITION EVAPORATOR                        | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code         | Description                          | Part Number              | C/W Time 1                  | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-------------------|--------------------------------------|--------------------------|-----------------------------|--------|-------|-------|-------------|---------|
| Position          | Drawing # / Task #                   | Part Serial No           | C/W Time 2                  | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 215007<br>BOTTOM  | COALESCER                            | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 215007<br>TOP     | COALESCER                            | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 215012<br>AFT     | AIRCONDITION VALVE SOLENOID          | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 215012<br>FORWARD | AIRCONDITION VALVE SOLENOID          | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 215013            | AIRCONDITION BLOWER MOTOR            | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 215015<br>TOP     | AIR CYCLE MACHINE SWITCH             | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 216001            | ENVIROMENTAL CONTROL ALT SELECTOR    | 9914130-10<br>135        | MTH 04-May-1990<br>HRS 1462 |        | O/C   |       |             |         |
| 216002<br>BOTTOM  | TEMP CONTROL/COCKPIT VALVE           | 9914130-19<br>12AT105    | MTH 04-Apr-2006<br>HRS 6354 |        | O/C   |       |             |         |
| 216002<br>TOP     | TEMP CONTROL/CABIN VALVE             | 9914130-2<br>579D        | MTH 06-Apr-2003<br>HRS 5591 |        | O/C   | 334   |             |         |
| 216003<br>LEFT    | TEMPERATURE CONTROLLER               | 9914130-12<br>128        | MTH 30-Aug-1988<br>HRS 945  |        | O/C   |       |             |         |
| 216003<br>RIGHT   | TEMPERATURE CONTROLLER               | 9914130-12<br>106        | MTH 25-May-2006<br>HRS 6392 |        | O/C   |       |             |         |
| 216004<br>LEFT    | TEMP/CABIN SENSOR                    | 9914130-3<br>12AL91      | MTH 22-Mar-1996<br>HRS 3497 |        | O/C   |       |             |         |
| 216004<br>RIGHT   | TEMP/COCKPIT SENSOR                  | 9914130-3<br>392         | MTH 16-Jul-1991<br>HRS 1798 |        | O/C   |       |             |         |
| 216005<br>AFT     | TEMPERATURE SENSOR                   | 9914130-6<br>6AT170      | MTH 16-Nov-2004<br>HRS 6093 |        | O/C   |       |             |         |
| 216005<br>FORWARD | TEMPERATURE SENSOR                   | 9914130-6<br>261         | MTH 16-Nov-2004<br>HRS 6093 |        | O/C   |       |             |         |
| 216006<br>LEFT    | TEMP SWITCH                          | 1173T42<br>289           | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 216006<br>RIGHT   | TEMP SWITCH                          | 1173T42<br>292           | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 216007<br>NO. 1   | DUCT TEMP SENSOR                     | 9912069-14<br>SN-UNKNOWN | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 216007<br>NO. 2   | DUCT TEMP SENSOR                     | 9912069-14<br>SN-UNKNOWN | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 216008<br>LEFT    | BI LEVEL FLOW CONTROL SHUT OFF VALVE | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 216008<br>RIGHT   | BI LEVEL FLOW CONTROL SHUT OFF VALVE | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 216009<br>AFT     | TURBINE BYPASS DUCT ASSEMBLY         | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 216009<br>FORWARD | TURBINE BYPASS DUCT ASSEMBLY         | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 216010<br>AFT     | TURBINE OUTLET DUCT ASSEMBLY         | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code         | Description                                             | Part Number             | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-------------------|---------------------------------------------------------|-------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position          | Drawing # / Task # City Mod Lvl                         | Part Serial No          | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 216010<br>FORWARD | TURBINE OUTLET DUCT ASSEMBLY                            | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 216011<br>BOTTOM  | SENSOR TEMPERATURE CONTROL                              | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 216011<br>TOP     | SENSOR TEMPERATURE CONTROL                              | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 216012<br>RIGHT   | WEMC BOOST/CENTRIT BLOWER ASSY.                         | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 216012            | WEMAC BOOST BLOWER                                      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 216015            | DC FAN TEMP SENSOR                                      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 221001            | AUTO PILOT (PC 500) CONTROL<br>PC-500                   | 4018639-909<br>88083063 | MTH 11-Sep-2008<br>HRS 6943.9<br>LDG 6007 |        | O/C   |             |             |         |
| 221002            | AUTO PILOT (SP-650) COMPUTER<br>SP-650                  | 7000473-903<br>84030168 | MTH 04-Feb-2001<br>HRS 5356               |        | O/C   | 5275        |             |         |
| 221003            | AILERON SERVO A/P ACTUATOR<br>SM-200                    | 4006719-906<br>85102238 | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 221004            | RUDDER A/P--Y ACTUATOR<br>SM-200                        | 4006719-913<br>85092203 | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 221005            | ELEVATOR A/P ACTUATOR<br>SM-200                         | 4006719-906<br>85102236 | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 221006            | TRANSMITTER AILERON                                     | 13TX-0115A<br>16764     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 221007            | ROTARY(LEDEX) SWITCH                                    | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 230000            | AUDIO-VIDEO MODULE                                      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 230001<br>NO. 1   | HEAD-COMM CONTROL<br>CTL-22C                            | 822-1120-005<br>20998   | MTH 10-Oct-1999<br>HRS 4798               |        | O/C   |             |             |         |
| 230001<br>NO. 2   | HEAD-COMM CONTROL<br>CTL-22C                            | 822-1120-005<br>20997   | MTH 10-Oct-1999<br>HRS 4798               |        | O/C   |             |             |         |
| 230007            | HF ANTENNA                                              | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 230010            | COCKPIT VOICE RECORDER<br>AV-557C UNK                   | 980-6005-077<br>10084   | MTH 03-Feb-2014<br>HRS 7899<br>LDG 6649   |        | O/C   |             |             |         |
| 230012<br>LEFT    | MICROPHONE CVR MONITOR-                                 | 980-6109-007<br>2334    | MTH 27-Apr-1989<br>HRS 1195               |        | O/C   |             |             |         |
| 230012<br>RIGHT   | MICROPHONE CVR MONITOR-                                 | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 230014            | CVR CONTROLLER ASSY.                                    | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 230016            | -- SELCAL DECODER                                       | NA137-714A<br>5ALJ0029  | MTH 09-Sep-1987                           |        | O/C   |             |             |         |
| 230017            | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON<br>FXE | DK120<br>AT131419       | MTH 26-Mar-2019<br>HRS 8642.2<br>LDG 7130 |        | O/C   | 0<br>0<br>0 |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                  | Description                         | Part Number             | C/W Time 1                                | Adj.   | TBO 1                    | TSO 1            | (ENG) DUE 1 | Remains  |
|----------------------------|-------------------------------------|-------------------------|-------------------------------------------|--------|--------------------------|------------------|-------------|----------|
| Position                   | Drawing # / Task #                  | Part Serial No          | C/W Time 2                                | + or - | TBO 2                    | TSO 2            | (ENG) DUE 2 | Remains  |
| 230017A                    | CVR LOCATOR BEACON BATTERY<br>FXE   | PN<br>SN-UNKNOWN        | MTH 26-Mar-2019<br>HRS 8642.2<br>LDG 7130 |        | DUE<br>DUE<br>DUE<br>DUE | 0<br>0<br>0<br>0 | 30-Apr-2026 | 15 m 0 d |
| 230018                     | CVR INERTIA SWITCH                  | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 230019                     | CVR CONTROL SWITCH                  | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 230023                     | CVR MOUNT ASSY                      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231001                     | FONE RECEIVER/TRANSMITTER<br>RT-18D | 400-0125<br>648         | MTH 21-Aug-1986                           |        | O/C                      |                  |             |          |
| 231002<br>COCKPIT          | FLITEFONE HANDSET CONTROL           | PN-UNKNOWN<br>8821      | MTH 19-Dec-2002<br>HRS 5483               |        | O/C                      |                  |             |          |
| 231003<br>CABIN            | FLITEFONE HANDSET CONTROL           | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231004                     | FONE ANTENNA<br>AT-461              | 121-0011-000<br>294     | MTH 21-Aug-1986                           |        | O/C                      |                  |             |          |
| 231007<br>LEFT             | MICROPHONE                          | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231007<br>RIGHT            | MICROPHONE UNK<br>60837-23          | C596502-0202<br>NSN     | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C                      | 0<br>0<br>0      |             |          |
| 231011<br>NO. 1            | COMM TRANSCEIVER<br>VHF-22C         | 822-1113-001<br>38320   | MTH 10-Oct-1999<br>HRS 4798               |        | O/C                      |                  |             |          |
| 231011<br>NO. 2            | COMM TRANSCEIVER<br>VHF-22C         | 822-1113-001<br>38340   | MTH 10-Oct-1999<br>HRS 4798               |        | O/C                      |                  |             |          |
| 231012<br>LOWER<br>231012T | COMM #1 ANTENNA                     | S65-8282<br>331         | MTH 21-Aug-1986                           |        | O/C                      |                  |             |          |
| 231012<br>UPPER            | COMM #2 ANTENNA                     | S65-8282<br>402         | MTH 19-Dec-1986<br>HRS 156                |        | O/C                      |                  |             |          |
| 231014<br>NO. 1            | INTERGRATED COMMUNICATION UNIT      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231014<br>NO. 2            | INTERGRATED COMMUNICATION UNIT      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231015<br>NO. 1            | COMMUNICATION CLUSTER BOARD         | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231015<br>NO. 2            | COMMUNICATION CLUSTER BOARD         | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231021<br>LEFT             | HF CONTROLLER<br>KCU-951            | 064-1016-03<br>4375     | MTH 21-Aug-1986                           |        | O/C                      |                  |             |          |
| 231021<br>RIGHT            | HF CONTROLLER                       | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231022<br>NO. 1            | HF PA COUPLER                       | 064-01017-0001<br>11061 | MTH 19-Dec-1986<br>HRS 156                |        | O/C                      |                  |             |          |
| 231023<br>NO. 1            | HF RECEIVER<br>KTR-953              | 064-01015-0001<br>26194 | MTH 26-Apr-1988<br>HRS 749                |        | O/C                      |                  |             |          |
| 231023<br>NO. 2            | HF RECEIVER                         | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |
| 231031                     | DUAL ANTENNA ADAPTER                | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C                      | 0                |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 231032<br>NO. 1       | HF CONTROL ADAPTER                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 231032<br>NO. 2       | HF CONTROL ADAPTER                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 231039<br>NO. 1       | BUS REPEATER                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 231039<br>NO. 2       | BUS REPEATER                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 231053<br>LEFT        | CABIN MAGNASTAR HANDSET           |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233001                | D.C STEREO CONVERTER              |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233500                | PASSENGER ADVISORY CHIME          |      |         | 464-1<br>SN-UNKNOWN           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 233601                | PASSENGER BRIEFING COMPUTER       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233613                | MAGNASTAR ARTU                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233615                | MAGNASTAR DUPLEXER                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233616                | MAGNASTAR ANTENNA                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 233617                | ANALOG INTERFACE UNIT             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 235001<br>LEFT        | AUDIO CONTROL PANEL               |      |         | 9914064-57<br>333             | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 235001<br>RIGHT       | AUDIO CONTROL PANEL               |      |         | 9914064-57<br>427             | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 235002                | AUDIO AMPLIFIER                   |      |         | 9914064-10<br>112             | MTH 23-Sep-2004<br>HRS 6045 |                | O/C            |                |                            |                    |
| 236005                | AIRSHOW                           |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 236012<br>LEFT        | AIRSHOW MONITOR-                  |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 240001<br>CENTER      | 5 VOLT LIGHT DIMMER               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 240001<br>LEFT        | 5 VOLT LIGHT DIMMER               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 240001<br>RIGHT       | 5 VOLT LIGHT DIMMER               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 242101<br>LEFT        | AC STATIC INVERTER                |      |         | SPC38B<br>2126                | MTH 03-Jul-2006<br>HRS 6435 |                | O/C            |                |                            |                    |
| 242101<br>RIGHT       | AC STATIC INVERTER                |      |         | SPC38B<br>577                 | MTH 07-Jun-2008<br>HRS 6918 |                | O/C            |                |                            |                    |
| 242102                | STANDBY AC INVERTER               |      |         | PC50<br>2113                  | MTH 27-Apr-1989<br>HRS 1195 |                | O/C            |                |                            |                    |
| 243002                | DUAL BATTERY MONITOR              |      |         | 1863-1<br>201                 | MTH 11-Mar-1996<br>HRS 3487 |                | O/C            |                |                            |                    |
| 243003                | BATTERY TEMP INDICATOR            |      |         | 1864-1-1<br>199               | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 243004<br>LEFT        | BATTERY TEMP SENSOR               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 243004<br>RIGHT       | BATTERY TEMP SENSOR               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 243008<br>LEFT        | POWER RELAY                       |      |         | A703P<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 243008<br>RIGHT       | POWER RELAY                       |      |         | A703P<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 243009<br>LEFT        | BATTERY DISCONNECT RELAY          |      |         | A876K<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 243009<br>RIGHT       | BATTERY DISCONNECT RELAY          |      |         | A931F<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 243011                | (K17) EMERGENCY POWER RELAY       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 243013<br>NO. 1       | BATTERY                           |      |         | S3597-4<br>41326428           | MTH 23-May-2024<br>HRS 8773.9<br>LDG 7234 |                | O/C            |                |                            |                    |
| 243016<br>NO. 2       | BATTERY                           |      |         | S3597-4<br>41325862           | MTH 23-May-2024<br>HRS 8773.9<br>LDG 7234 |                | O/C            |                |                            |                    |
| 245003                | OVERVOLTAGE DETECTOR              |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 246002<br>LEFT        | DE-ICE TEMPERATURE CONTROL        |      |         | 9912106-1<br>U1241            | MTH 25-May-2006<br>HRS 6392               |                | O/C            | 603            |                            |                    |
| 246002<br>RIGHT       | DE-ICE TEMPERATURE CONTROL        |      |         | 9912106-1<br>U3270            | MTH 25-May-2006<br>HRS 6392               |                | O/C            | 603            |                            |                    |
| 246010                | PC BOARD                          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 250004<br>LEFT        | INTERCOM                          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 250004<br>RIGHT       | INTERCOM                          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 251098<br>NO. 1       | FUJITSU SVGA COLOR TFT LCD        |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 251099<br>NO. 2       | FUJITSU SVGA COLOR TFT LCD        |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 252008                | STATIC INVERTER                   |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 252012                | -- AIRSPEED CONVERTER             |      |         | FAA0009-001<br>208            | MTH 27-Apr-1989<br>HRS 1195               |                | O/C            |                |                            |                    |
| 252014                | COMPACT DISC PLAYER               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 252017                | HEADPHONE AMPLIFIER               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 253001<br>VANITY      | HOT WATER TANK                    |      |         | 1825-501<br>49                | MTH 23-Sep-1998<br>HRS 4475               |                | O/C            |                |                            |                    |
| 256003<br>LEFT        | ELT/BEACON ANTENNA                |      |         | 3003-1<br>6102                | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 256003<br>RIGHT       | ELT/BEACON ANTENNA                |      |         | 3003-1<br>SN-UNKNOWN          | MTH 29-Jan-1993<br>HRS 2352               |                | O/C            |                |                            |                    |
| 256004                | ELT POWER DIVIDER                 |      |         | 3004-2<br>100                 | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 256006<br>NO. 10      | LIFE JACKET                       |      |         | 63600-171<br>L258048          | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60             | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position        | Description<br>Drawing # / Task #          | City | Mod Lvl | Part Number<br>Part Serial No    | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|--------------------------------------------|------|---------|----------------------------------|-------------------------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| 256006<br>NO. 1              | LIFE JACKET                                |      |         | P01074-101<br>247952             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 9<br>0<br>0    | 09-Sep-2025                | 7 m 10 d           |
| 256006<br>NO. 2              | LIFE JACKET                                |      |         | 63600-171<br>L258014             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 3              | LIFE JACKET                                |      |         | 63600-171<br>L258042             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 4              | LIFE JACKET                                |      |         | 63600-171<br>L257986             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 5              | LIFE JACKET                                |      |         | P01074-101<br>16040590322        | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 9<br>0<br>0    | 09-Sep-2025                | 7 m 10 d           |
| 256006<br>NO. 6              | LIFE JACKET                                |      |         | 63600-171<br>L257885             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 7              | LIFE JACKET                                |      |         | 63600-171<br>L258046             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 8              | LIFE JACKET                                |      |         | 63600-171<br>L258084             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256006<br>NO. 9              | LIFE JACKET                                |      |         | 63600-171<br>L257886             | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 60                | 1<br>0<br>0    | 13-May-2026                | 15 m 13 d          |
| 256010                       | LIFE RAFT                                  |      |         | 1900-1/2000-1<br>3610BDA/2516BDA | MTH 30-Nov-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C               | 4<br>0<br>0    |                            |                    |
| 256011                       | SURVIVAL KIT                               |      |         | PN<br>SN-UNKNOWN                 | MTH 21-Aug-1986                           |                | O/C               | 0              |                            |                    |
| 256019                       | EMERGENCY LOCATOR TRANSMITTER              |      |         | 453-5000-316<br>02582            | MTH 01-Oct-2002<br>HRS 5468               |                | O/C               |                |                            |                    |
| 256025                       | EMERGENCY LOCATOR TRANSMITTER BATTERY PACK |      |         | 452-0133<br>399387-018           | MTH 12-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | DUE<br>DUE<br>DUE | 0<br>0<br>0    | 31-Mar-2028                | 38 m 1 d           |
| Expiration Date: 31-Mar-2028 |                                            |      |         |                                  |                                           |                |                   |                |                            |                    |
| 256026                       | ELT ANTENNA                                |      |         | PN<br>SN-UNKNOWN                 | MTH 21-Aug-1986                           |                | O/C               | 0              |                            |                    |
| 256035                       | REMOTE SWITCH                              |      |         | PN<br>SN-UNKNOWN                 | MTH 21-Aug-1986                           |                | O/C               | 0              |                            |                    |
| 260001<br>LEFT ENGINE        | EXTINGUISHER                               |      |         | 9914193-1<br>05225C1             | MTH 28-Feb-2011<br>HRS 7426.8<br>LDG 6325 |                | O/C               | 0<br>0<br>0    |                            |                    |
| 260002<br>RIGHT ENGINE       | EXTINGUISHER                               |      |         | 32700012<br>06872C1              | MTH 24-Nov-2010<br>HRS 7368.3<br>LDG 6295 |                | O/C               | 0<br>0<br>0    |                            |                    |
| 260003<br>APU                | EXTINGUISHER                               |      |         | 32700012<br>11771C1              | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | O/C               | 1<br>0<br>0    |                            |                    |
| 260003F<br>FORWARD           | APU EXTINGUISHER                           |      |         | 30300015<br>37789B1              | MTH 04-Nov-2021<br>HRS 8735.3<br>LDG 7213 |                | O/C               | 7<br>0<br>0    |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                     | Description                      | Part Number | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------------------|----------------------------------|-------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position                      | Drawing # / Task #               | City        | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| 261001                        | EXTINGUISHER (FORWARD) CARTRIDGE |             |            |                | MTH 22-Sep-2016 |        | 120         | 5       | 30-Apr-2026 | 15 m 0 d |
| LEFT ENGINE                   |                                  |             |            | M30903824      | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 00933          | LDG 6821        |        |             | 0       |             |          |
| Manufacture Date: 04-Apr-2016 |                                  |             |            |                |                 |        |             |         |             |          |
| 261003                        | EXTINGUISHER (AFT) CARTRIDGE     |             |            |                | MTH 22-Sep-2016 |        | 120         | 5       | 30-Apr-2026 | 15 m 0 d |
| LEFT ENGINE                   |                                  |             |            | M30903824      | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 00939          | LDG 6821        |        |             | 0       |             |          |
| Manufacture Date: 04-Apr-2016 |                                  |             |            |                |                 |        |             |         |             |          |
| 261010                        | TIME DELAY RELAY                 |             |            |                | MTH 21-Aug-1986 |        | O/C         | 0       |             |          |
| LEFT                          |                                  |             |            | PN             |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 261013                        | FIRE DETECTOR                    |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| LEFT ENGINE                   |                                  |             |            | 9914092-1      |                 |        |             |         |             |          |
|                               |                                  |             |            | 3008           |                 |        |             |         |             |          |
| 261014                        | FIRE DETECTOR                    |             |            |                | MTH 23-Aug-1995 |        | O/C         |         |             |          |
| RIGHT ENGINE                  |                                  |             |            | 9914092-1      | HRS 3260        |        |             |         |             |          |
|                               |                                  |             |            | 10795          |                 |        |             |         |             |          |
| 261101                        | FIRE DETECTOR                    |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| APU                           |                                  |             |            | 644-90003      |                 |        |             |         |             |          |
|                               |                                  |             |            | 3201           |                 |        |             |         |             |          |
| 261102                        | ENGINE FIRE DETECTOR CONTROL     |             |            |                | MTH 05-May-2001 |        | O/C         |         |             |          |
| 261002                        |                                  |             |            | 9914092-2      | HRS 5389        |        |             |         |             |          |
|                               |                                  |             |            | 306            |                 |        |             |         |             |          |
| 261201                        | SMOKE DETECTOR                   |             |            |                | MTH 28-May-1992 |        | O/C         |         |             |          |
|                               |                                  |             |            | 72-111211-102  | HRS 2147        |        |             |         |             |          |
|                               |                                  |             |            | A2197          |                 |        |             |         |             |          |
| 262001                        | EXTINGUISHER (FORWARD) CARTRIDGE |             |            |                | MTH 22-Sep-2016 |        | 120         | 5       | 30-Apr-2026 | 15 m 0 d |
| RIGHT ENGINE                  |                                  |             |            | M30903824      | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 00936          | LDG 6821        |        |             | 0       |             |          |
| Manufacture Date: 30-Apr-2016 |                                  |             |            |                |                 |        |             |         |             |          |
| 262003                        | EXTINGUISHER (AFT) CARTRIDGE     |             |            |                | MTH 22-Sep-2016 |        | 120         | 5       | 30-Apr-2026 | 15 m 0 d |
| RIGHT ENGINE                  |                                  |             |            | M30903824      | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 00937          | LDG 6821        |        |             | 0       |             |          |
| Manufacture Date: 30-Apr-2016 |                                  |             |            |                |                 |        |             |         |             |          |
| 262004                        | ENGINE FIRE TRAY ASSEMBLY        |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
|                               |                                  |             |            | 6218121-2      |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 262301                        | HALON EXTINGUISHER               |             |            |                | MTH 22-Sep-2016 |        | O/C         | 0       |             |          |
| COCKPIT                       |                                  |             |            | C352TS         | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 74101641       | LDG 6821        |        |             | 0       |             |          |
| 262302                        | HALON EXTINGUISHER               |             |            |                | MTH 22-Sep-2016 |        | O/C         | 0       |             |          |
| CABIN                         |                                  |             |            | C352TS         | HRS 8218.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 74101642       | LDG 6821        |        |             | 0       |             |          |
| 263001                        | EXTINGUISHER CARTRIDGE           |             |            |                | MTH 01-Mar-2024 | -3     | 120         | 21      | 31-Mar-2032 | 86 m 1 d |
| APU                           |                                  |             |            | AE30903824     | HRS 8752.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 866            | LDG 7224        |        |             | 0       |             |          |
| Manufacture Date: 09-Jun-2022 |                                  |             |            |                |                 |        |             |         |             |          |
| 263004                        | APU EXTINGUISHER (AFT) CARTRIDGE |             |            |                | MTH 01-Mar-2024 | -3     | 120         | 21      | 31-Mar-2032 | 86 m 1 d |
|                               |                                  |             |            | AE30903824     | HRS 8752.5      |        |             | 0       |             |          |
|                               |                                  |             |            | 794            | LDG 7224        |        |             | 0       |             |          |
| Manufacture Date: 09-Jun-2022 |                                  |             |            |                |                 |        |             |         |             |          |
| 270001                        | SPEED BRAKE                      |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| LEFT CENTER                   |                                  |             |            | 6224110-3      |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 270001                        | SPEED BRAKE                      |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| RIGHT CENTER                  |                                  |             |            | 6224110-4      |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 270002                        | SPEED BRAKE                      |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| LEFT CENTER                   |                                  |             |            | 6224110-5      |                 |        |             |         |             |          |
| OUTBOARD                      |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 270002                        | GROUND SPOILER                   |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| LEFT INBOARD                  |                                  |             |            | 6224110-5      |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |
| 270002                        | ROLL SPOILER                     |             |            |                | MTH 21-Aug-1986 |        | O/C         |         |             |          |
| LEFT OUTBOARD                 |                                  |             |            | 6224110-3      |                 |        |             |         |             |          |
|                               |                                  |             |            | SN-UNKNOWN     |                 |        |             |         |             |          |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position              | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 270002<br>RIGHT CENTER<br>OUTBOARD | SPEED BRAKE                       |      |         | 6224110-6<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 270002<br>RIGHT INBOARD            | GROUND SPOILER                    |      |         | 6224110-6<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 270002<br>RIGHT OUTBOARD           | ROLL SPOILER                      |      |         | 6224110-4<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 271000<br>LEFT HAND<br>CENTER      | FLAP ASSEMBLY                     |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986<br>HRS 0                  |                | 15000          | 0              | 15000                      | 6226.1             |
| 271001                             | AILERON ACTUATOR                  |      |         | 67800-1<br>0157               | MTH 11-Sep-2008<br>HRS 6943.9<br>LDG 6007 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 271002                             | AILERON CUT-OFF VALVE             |      |         | 67950<br>215                  | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 271010<br>LEFT HAND                | ELEVATOR HINGE ES 0.00 BOLT       |      |         | AN5C14<br>SN-UNKNOWN          | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 271020<br>LEFT HAND                | ELEVATOR HINGE ES 36.95 BOLT      |      |         | NAS6204-11D<br>SN-UNKNOWN     | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 271030<br>LEFT HAND                | ELEVATOR HINGE ES 73.21 BOLT      |      |         | NAS6204-11D<br>SN-UNKNOWN     | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 271040<br>LEFT HAND                | ELEVATOR HINGE ES 97.30 BOLT      |      |         | NAS6204-7D<br>SN-UNKNOWN      | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 271101                             | ROLL TRIM ACTUATOR                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 272000<br>RIGHT HAND<br>CENTER     | FLAP ASSEMBLY                     |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986<br>HRS 0                  |                | 15000          | 0              | 15000                      | 6226.1             |
| 272001                             | RUDDER TRIM ACTUATOR              |      |         | 6261305-3<br>SN-UNKNOWN       | MTH 20-Nov-2005<br>HRS 6255               |                | O/C            |                |                            |                    |
| 272002                             | RUDDER BIAS ACTUATOR              |      |         | 6260457-2<br>SN-UNKNOWN       | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            |                |                            |                    |
| 272003                             | RUDDER BIAS SOLENOID VALVE        |      |         | 65690-1<br>415                | MTH 02-Sep-1998<br>HRS 4462               |                | O/C            |                |                            |                    |
| 272004                             | BIAS ACTUATOR HEATER              |      |         | 9914322-1<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 272005                             | ELEVATOR/RUDDER TRIM CONTROL      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 272010<br>RIGHT HAND               | ELEVATOR HINGE ES 0.00 BOLT       |      |         | AN5C14<br>SN-UNKNOWN          | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272012                             | HTR AMTR BIAS RUDDER              |      |         | 115.1094-4<br>85100116        | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 272020<br>RIGHT HAND               | ELEVATOR HINGE ES 36.95 BOLT      |      |         | NAS6204-11D<br>SN-UNKNOWN     | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272030<br>RIGHT HAND               | ELEVATOR HINGE ES 73.21 BOLT      |      |         | NAS6204-11D<br>SN-UNKNOWN     | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272040<br>RIGHT HAND               | ELEVATOR HINGE ES 97.30 BOLT      |      |         | NAS6204-7D<br>SN-UNKNOWN      | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272550<br>RUDDER                   | HINGE WL 224.89 BOLT              |      |         | NAS6205-7D<br>SN-UNKNOWN      | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272560<br>RUDDER                   | HINGE WL 198.58 BOLT              |      |         | NAS6205-7D<br>SN-UNKNOWN      | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272570<br>RUDDER                   | HINGE WL 167.92 BOLT              |      |         | NAS6205-7D<br>SN-UNKNOWN      | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |
| 272580<br>RUDDER                   | HINGE WL 140.60 BOLT              |      |         | NAS6205-16D<br>SN-UNKNOWN     | MTH 30-Sep-1999<br>HRS 4798               |                | 5000           | 0              | 9798                       | 1024.1             |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position              | Description<br>Drawing # / Task #                                 | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------|-------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 272700<br>LEFT WING                | LEFT WING ROLL SPOILER SHUTTLE VALVE FILTER CLEANING/REPLACEMENT  |      |         | PN<br>SN-UNKNOWN              | MTH 23-Apr-2003<br>HRS 5610               |                |                | 0<br>0         | 9210                       | 436.1              |
| 272800<br>RIGHT WING               | RIGHT WING ROLL SPOILER SHUTTLE VALVE FILTER CLEANING/REPLACEMENT |      |         | PN<br>SN-UNKNOWN              | MTH 23-Apr-2003<br>HRS 5610               |                |                | 0<br>0         | 9210                       | 436.1              |
| 273201<br>LEFT                     | CONTROL COLUMN SHAKER                                             |      |         | 201<br>385                    | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 273201<br>RIGHT                    | CONTROL COLUMN SHAKER                                             |      |         | 201<br>404                    | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 274001                             | HORIZONTAL STAB ACTUATOR CONTROL                                  |      |         | 9914197-8<br>3032             | MTH 16-Aug-2007<br>HRS 6632               |                | O/C            |                |                            |                    |
| 274002                             | HORIZONTAL STAB INDICATOR                                         |      |         | 9914188-3<br>136              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 274003                             | HORIZONTAL STABILIZER TRIM ACTUATOR ASSEMBLY<br>497D100-9         |      |         | 9914056-3<br>167              | MTH 04-Nov-2021<br>HRS 8735.3<br>LDG 7213 |                | O/C            |                |                            |                    |
| 274004                             | HORIZONTAL STAB TRIM CONTROL                                      |      |         | 9914287-1<br>301              | MTH 07-Sep-1995<br>HRS 3276               |                | O/C            | 16             |                            |                    |
| 274101                             | SECONDARY TRIM MOTOR                                              |      |         | 9914257-2<br>13A              | MTH 28-Feb-1990<br>HRS 1430               |                | O/C            |                |                            |                    |
| 275001                             | FLAP-SPEED BRAKE POSITION INDICATOR                               |      |         | 9914187-3<br>040              | MTH 28-Feb-2003<br>HRS 5562               |                | O/C            | 1516           |                            |                    |
| 275004<br>LEFT                     | ANGLE GEARBOX                                                     |      |         | 9914054-55<br>274             | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            |                |                            |                    |
| 275004<br>RIGHT                    | ANGLE GEARBOX                                                     |      |         | 9914054-55<br>471             | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            |                |                            |                    |
| 275005<br>LEFT CENTER<br>INBOARD   | FLAP ACTUATOR                                                     |      |         | 9914054-37<br>308             | MTH 11-Dec-1997<br>HRS 4168               |                | O/C            |                |                            |                    |
| 275005<br>LEFT CENTER<br>OUTBOARD  | FLAP ACTUATOR                                                     |      |         | 9914054-36<br>1395            | MTH 24-Dec-1997<br>HRS 4181               |                | O/C            |                |                            |                    |
| 275005<br>LEFT INBOARD             | FLAP ACTUATOR                                                     |      |         | 9914054-56<br>1001            | MTH 11-Dec-1997<br>HRS 4168               |                | O/C            |                |                            |                    |
| 275005<br>LEFT OUTBOARD            | FLAP ACTUATOR                                                     |      |         | 9914054-39<br>165             | MTH 11-Dec-1997<br>HRS 4168               |                | O/C            |                |                            |                    |
| 275005<br>RIGHT CENTER<br>INBOARD  | FLAP ACTUATOR                                                     |      |         | 9914054-37<br>125             | MTH 24-Dec-1997<br>HRS 4181               |                | O/C            |                |                            |                    |
| 275005<br>RIGHT CENTER<br>OUTBOARD | FLAP ACTUATOR                                                     |      |         | 9914054-36<br>1410            | MTH 24-Dec-1997<br>HRS 4181               |                | O/C            |                |                            |                    |
| 275005<br>RIGHT INBOARD            | FLAP ACTUATOR                                                     |      |         | 9914054-36<br>1391            | MTH 24-Dec-1997<br>HRS 4181               |                | O/C            |                |                            |                    |
| 275005<br>RIGHT OUTBOARD           | FLAP ACTUATOR                                                     |      |         | 9914054-38<br>252             | MTH 11-Dec-1997<br>HRS 4168               |                | O/C            |                |                            |                    |
| 275006<br>LEFT                     | ASYMMETRY BRAKE                                                   |      |         | 738975<br>254                 | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position    | Description<br>Drawing # / Task #       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------|-----------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 275006<br>RIGHT          | ASYMMETRY BRAKE                         |      |         | 738977<br>199                 | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 275009<br>LEFT           | SPEEDBRAKE POTENTIOMETER<br>6208032-831 |      |         | 86784<br>SN-UNKNOWN           | MTH 16-Jul-1991<br>HRS 1798               |                | O/C            |                |                            |                    |
| 275009<br>RIGHT          | SPEEDBRAKE POTENTIOMETER<br>6208032-831 |      |         | 86784<br>SN-UNKNOWN           | MTH 16-Jul-1991<br>HRS 1798               |                | O/C            |                |                            |                    |
| 275012<br>LEFT           | RESOLVER CONVERTER                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275012<br>RIGHT          | RESOLVER CONVERTER                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275013<br>LEFT           | RESOLVER                                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275013<br>RIGHT          | RESOLVER                                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275014<br>LEFT           | FLAP POSITION SENSOR                    |      |         | 9914341-1<br>16               | MTH 24-Dec-1997<br>HRS 4181               |                | O/C            |                |                            |                    |
| 275014<br>RIGHT          | FLAP POSITION SENSOR                    |      |         | 6238405-15<br>SN-UNKNOWN      | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |
| 275015<br>LEFT           | FLAP FLEX DRIVE                         |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275015<br>RIGHT          | FLAP FLEX DRIVE                         |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275015                   | FLEX SHAFT ASSEMBLY                     |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275018                   | DC FLAP START MODULE                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 275019                   | DC POWER DRIVE UNIT                     |      |         | 9914416-1<br>275              | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |
| 275020                   | DC FLAP CONTROLLER                      |      |         | 6238400-2<br>320              | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |
| 275021                   | DC FLAP POSITION CONTROL HANDLE         |      |         | 6218460-4<br>315              | MTH 02-Dec-2010<br>HRS 7378.4<br>LDG 6301 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 276001<br>LEFT           | ROLL SPOILER ACTUATOR                   |      |         | 9914155-19<br>715             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 276001<br>RIGHT          | ROLL SPOILER ACTUATOR                   |      |         | 9914155-19<br>253             | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            |                |                            |                    |
| 276002<br>LEFT INBOARD   | SPEED BRAKE ACTUATOR                    |      |         | 9914155-18<br>248             | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            | 100            |                            |                    |
| 276002<br>LEFT OUTBOARD  | SPEED BRAKE ACTUATOR                    |      |         | 9914155-17<br>2761            | MTH 30-Nov-2004<br>HRS 6117               |                | O/C            |                |                            |                    |
| 276002<br>RIGHT INBOARD  | SPEED BRAKE ACTUATOR                    |      |         | 9914155-18<br>1030            | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 276002<br>RIGHT OUTBOARD | SPEED BRAKE ACTUATOR<br>9914155-17 FXE  |      |         | 1524800-17<br>2684            | MTH 03-Feb-2016<br>HRS 8196.2<br>LDG 6810 |                | O/C            | 0<br>0         |                            |                    |
| 276003<br>LEFT           | GROUND SPOILER ACTUATOR                 |      |         | 9914155-15<br>770             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code       | Description                          | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-----------------|--------------------------------------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position        | Drawing # / Task # City Mod Lvl      | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 276003<br>RIGHT | GROUND SPOILER ACTUATOR              | 9914155-15<br>535          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 276004<br>LEFT  | SPOILER POSITION TRANSMITER          | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276004<br>RIGHT | SPOILER POSITION TRANSMITER          | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276005          | EMERGENCY SPOILER VALVE              | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276006          | CYLINDER EMERGENCY ACTUATOR          | 57C57650<br>140            | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 276018<br>RIGHT | PRESSURE SWITCH                      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276101          | SPOILER HD 3WAY VALVE                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276102<br>LEFT  | SPOILER PRESSURE VALVE               | 9914192-1<br>227           | MTH 13-Sep-1998<br>HRS 4462               |        | O/C   |             |             |         |
| 276102<br>RIGHT | SPOILER PRESSURE VALVE<br>FXE        | 9914192-1<br>0663          | MTH 03-Feb-2016<br>HRS 8196.2<br>LDG 6810 |        | O/C   | 0<br>0      |             |         |
| 276103          | N/O SPOILER VALVE                    | 70129-1<br>SN-UNKNOWN      | MTH 21-Feb-1992<br>HRS 2034               |        | O/C   |             |             |         |
| 276104          | SPOILER ACCUMULATOR<br>9914081-2 FXE | 60000-2<br>TRS-1960        | MTH 14-Mar-2017<br>HRS 8328.5<br>LDG 6901 |        | O/C   | 1<br>0<br>0 |             |         |
| 276105          | ACCUMULATOR VALVE                    | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276107<br>LEFT  | SHUTTLE VALVE                        | 9914146-5<br>300           | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 276107<br>RIGHT | SHUTTLE VALVE                        | 9914146-5<br>267           | MTH 21-Aug-1987<br>HRS 425                |        | O/C   |             |             |         |
| 276108<br>LEFT  | PRESSURE SWITCH                      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276108<br>RIGHT | PRESSURE SWITCH                      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 276109<br>LEFT  | SPOILER EXT PROXIMITY SWITCH         | 8-405-04<br>B54034         | MTH 09-Jun-2005<br>HRS 6201               |        | O/C   |             |             |         |
| 276109<br>RIGHT | SPOILER EXT PROXIMITY SWITCH         | 8-405-04<br>B54090         | MTH 04-Jul-2005<br>HRS 6232               |        | O/C   |             |             |         |
| 276110          | SPOILER ACCUMULATOR GAUGE            | 19940906-1<br>SN-UNKNOWN   | MTH 10-Oct-1999<br>HRS 4798               |        | O/C   |             |             |         |
| 281001<br>LEFT  | FLOAT SWITCH                         | L15F-2<br>290              | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 281001<br>RIGHT | FLOAT SWITCH                         | L15F-2<br>363              | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 281002          | FUSELAGE FUEL TANK                   | 320-4-45026-101<br>8506612 | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 281003<br>LEFT  | TANK PUMP                            | 1C27-14<br>8M100           | MTH 03-Jun-2008<br>HRS 6916               |        | O/C   |             |             |         |
| 281003<br>RIGHT | TANK PUMP                            | 1C27-14<br>8M102           | MTH 21-Aug-1986                           |        | O/C   |             |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code               | Description                     | Part Number              | C/W Time 1                  | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-------------------------|---------------------------------|--------------------------|-----------------------------|--------|-------|-------|-------------|---------|
| Position                | Drawing # / Task # City Mod Lvl | Part Serial No           | C/W Time 2                  | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 281004                  | FUSELAGE TANK BOOST PUMP PANEL  | PN-UNKNOWN<br>8M24       | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281005<br>LEFT          | FUSELAGE FUEL TANK RELIEF VALVE | 81011205-105<br>327      | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281005<br>RIGHT         | FUSELAGE FUEL TANK RELIEF VALVE | 81011205-105<br>326      | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281006<br>LEFT          | CHECK VALVE                     | 7F2W080005<br>329        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281006<br>RIGHT         | CHECK VALVE                     | 7F2W080005<br>339        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281006                  | CHECK VALVE                     | 7F2W120005<br>110        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281008<br>LEFT          | ENGINE PRESSURE SWITCH          | PN<br>SN-UNKNOWN         | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 281008<br>RIGHT         | ENGINE PRESSURE SWITCH          | 9914112-3<br>1008        | MTH 07-May-1998<br>HRS 4329 |        | O/C   |       |             |         |
| 281010<br>LEFT WING     | FUEL RELIEF VALVE               | 840203-101<br>SN-UNKNOWN | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281010<br>RIGHT WING    | FUEL RELIEF VALVE               | 840203-101<br>SN-UNKNOWN | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281011                  | VALVE-PRESSURE DEFUEL FUSELAGE  | 61084-1<br>318           | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281101<br>LEFT          | VENT FLOAT VALVE                | 9914268-3<br>38          | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 281101<br>RIGHT         | VENT FLOAT VALVE                | 9914268-3<br>27          | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282000<br>LEFT          | BOOST PUMP                      | 9914102-5<br>317         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282000<br>RIGHT         | BOOST PUMP                      | 9914102-9<br>11AL157     | MTH 16-Jan-1997<br>HRS 3797 |        | O/C   | 26    |             |         |
| 282001<br>LEFT          | PRIMARY EJECTOR PUMP            | 9914084-1<br>220         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282001<br>RIGHT         | PRIMARY EJECTOR PUMP            | 9914084-1<br>234         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282002<br>FORWARD LEFT  | EJECTOR PUMP                    | 9914084-3<br>239         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282002<br>FORWARD RIGHT | EJECTOR PUMP                    | 9914084-3<br>241         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282003<br>AFT LEFT      | EJECTOR PUMP                    | 9914084-4<br>226         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282003<br>AFT RIGHT     | EJECTOR PUMP                    | 9914084-4<br>222         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282004<br>FORWARD LEFT  | SCAVENGER PUMP                  | 9914084-2<br>206         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282004<br>FORWARD RIGHT | SCAVENGER PUMP                  | 9914084-2<br>227         | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282005                  | FUEL CROSS-FEED VALVE           | 9914103-1<br>99          | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282006<br>LEFT          | FIREWALL SHUTOFF VALVE          | 9914094-1<br>1905        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282006<br>RIGHT         | FIREWALL SHUTOFF VALVE          | 9914094-1<br>1900        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282007                  | AFT TANK FUEL CONTROL VALVE     | 9914094-1<br>1885        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282100<br>LEFT          | SHUTOFF VALVE                   | 80002-51<br>122          | MTH 21-Aug-1986             |        | O/C   |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code             | Description                       | Part Number         | C/W Time 1                  | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-----------------------|-----------------------------------|---------------------|-----------------------------|--------|-------|-------|-------------|---------|
| Position              | Drawing # / Task #                | Part Serial No      | C/W Time 2                  | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 282100<br>RIGHT       | SHUTOFF VALVE                     | 80002-51<br>123     | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282101<br>AFT         | DEFUEL PRESSURE VALVE             | PN<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 282101<br>LEFT        | DEFUEL PRESSURE VALVE             | 9914107-2<br>342    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282101<br>RIGHT       | DEFUEL PRESSURE VALVE             | 9914107-2<br>210    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282102<br>LEFT        | FUSELAGE FUEL TANK SHUTOFF VALVE  | 9914107-3<br>478    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282102<br>RIGHT       | FUSELAGE FUEL TANK SHUTOFF VALVE  | 9914107-3<br>485    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282102                | FUSELAGE TANK SHUT OFF VALVE      | PN<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 282103<br>LEFT        | PILOT HIGH LEVEL VALVE            | 9914107-1<br>436    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282103<br>RIGHT       | PILOT HIGH LEVEL VALVE            | 9914107-1<br>431    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282104<br>LEFT        | PRESSURE VALVE                    | 820136-103<br>285   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282104<br>RIGHT       | PRESSURE VALVE                    | 820136-103<br>198   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282106                | -- VALVE-AFT TANK TRANSFER        | 9914094-3<br>19     | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282107                | AFT FUEL VALVE                    | 234695<br>16        | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282108                | HOUSING                           | 9914168-2<br>211    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282109                | PRECHECK VALVE                    | 9036-51-1<br>75     | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 282110                | AUX TANK PRESSURE SWITCH          | PN<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 284001                | FUEL QUANTITY INDICATOR           | PN<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 284002                | FUEL QUANTITY INDICATOR TOTALIZER | 9914095-9<br>141BAC | MTH 30-Oct-2006<br>HRS 6511 |        | O/C   |       |             |         |
| 284003<br>AFT         | SIGNAL CONDITIONER                | PN<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 284003<br>LEFT        | SIGNAL CONDITIONER                | 9914242-46<br>510   | MTH 16-Mar-2006<br>HRS 6334 |        | O/C   | 5782  |             |         |
| 284003<br>RIGHT       | SIGNAL CONDITIONER<br>9914242-46  | 9914242-46<br>517   | MTH 16-Mar-2006<br>HRS 6334 |        | O/C   |       |             |         |
| 284005<br>LEFT NO. 1  | FUEL PROBE                        | 9914242-5<br>405    | MTH 02-May-2006<br>HRS 6390 |        | O/C   | 6390  |             |         |
| 284005<br>RIGHT NO. 1 | FUEL PROBE                        | 9914242-5<br>409    | MTH 02-May-2006<br>HRS 6390 |        | O/C   | 6390  |             |         |
| 284006<br>LEFT NO. 2  | FUEL PROBE                        | 9914242-6<br>458    | MTH 02-May-2006<br>HRS 6390 |        | O/C   | 6390  |             |         |
| 284006<br>RIGHT NO. 2 | FUEL PROBE                        | 9914242-6<br>413    | MTH 02-May-2006<br>HRS 6390 |        | O/C   | 6390  |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-----------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 284007<br>LEFT NO. 3   | FUEL PROBE                        |      |         | 9914242-7<br>482              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284007<br>RIGHT NO. 3  | FUEL PROBE                        |      |         | 9914242-7<br>465              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284008<br>LEFT NO. 4   | FUEL PROBE                        |      |         | 9914242-8<br>489              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284008<br>RIGHT NO. 4  | FUEL PROBE                        |      |         | 9914242-8<br>428              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284009<br>LEFT NO. 5   | FUEL PROBE                        |      |         | 9914242-9<br>400              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284009<br>RIGHT NO. 5  | FUEL PROBE                        |      |         | 9914242-9<br>433              | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284010<br>LEFT NO. 6   | FUEL PROBE                        |      |         | 9914242-10<br>255             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284010<br>RIGHT NO. 6  | FUEL PROBE                        |      |         | 9914242-10<br>359             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284011<br>LEFT NO. 7   | FUEL PROBE                        |      |         | 9914242-11<br>381             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284011<br>RIGHT NO. 7  | FUEL PROBE                        |      |         | 9914242-11<br>386             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284012<br>LEFT NO. 8   | FUEL PROBE                        |      |         | 9914242-12<br>355             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284012<br>RIGHT NO. 8  | FUEL PROBE                        |      |         | 9914242-12<br>342             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284013<br>LEFT NO. 9   | FUEL PROBE                        |      |         | 9914242-13<br>489             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284013<br>RIGHT NO. 9  | FUEL PROBE                        |      |         | 9914242-13<br>480             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284014<br>LEFT NO. 10  | FUEL PROBE                        |      |         | 9914242-14<br>580             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284014<br>RIGHT NO. 10 | FUEL PROBE                        |      |         | 9914242-14<br>563             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284015<br>LEFT NO. 11  | FUEL PROBE                        |      |         | 9914242-15<br>248             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284015<br>RIGHT NO. 11 | FUEL PROBE                        |      |         | 9914242-15<br>263             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284016<br>LEFT NO. 12  | FUEL PROBE                        |      |         | 9914242-16<br>482             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |
| 284016<br>RIGHT NO. 12 | FUEL PROBE                        |      |         | 9914242-16<br>458             | MTH<br>HRS 6390          |                | O/C            | 6390           |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 284017<br>LEFT NO. 13  | FUEL PROBE                        |      |         | 9914242-17<br>509             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284017<br>RIGHT NO. 13 | FUEL PROBE                        |      |         | 9914242-17<br>407             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284018<br>LEFT NO. 14  | FUEL PROBE                        |      |         | 9914242-18<br>662             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284018<br>RIGHT NO. 14 | FUEL PROBE                        |      |         | 9914242-18<br>660             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284019<br>LEFT NO. 15  | FUEL PROBE                        |      |         | 9914242-19<br>426             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284019<br>RIGHT NO. 15 | FUEL PROBE                        |      |         | 9914242-19<br>422             | MTH 02-May-2006<br>HRS 6390               |                | O/C            | 6390           |                            |                    |
| 284020<br>UPPER        | FQ AFT FUSE SENSOR                |      |         | 9914242-20<br>361             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 284021<br>LOWER        | FQ AFT FUSE SENSOR                |      |         | 9914242-21<br>262             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 284201                 | FUEL TEMP INDICATOR               |      |         | 9914095-10<br>61              | MTH 07-Mar-2008<br>HRS 6805               |                | O/C            |                |                            |                    |
| 291001<br>APU          | HYDRAULIC PUMP                    |      |         | 9914075-1<br>237591AC         | MTH 25-Feb-2005                           |                | O/C            |                |                            |                    |
| 291001<br>LEFT         | HYDRAULIC PUMP                    |      |         | 9914075-1<br>221808AC         | MTH 11-Sep-2008<br>HRS 6943.9<br>LDG 6007 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 291001<br>RIGHT        | HYDRAULIC PUMP                    |      |         | 9914075-1<br>270796AC         | MTH 25-May-2006<br>HRS 6401               |                | O/C            |                |                            |                    |
| 291002                 | HYDRAULIC RESERVOIR               |      |         | 7401-3<br>9914074-5<br>201    | MTH 23-Dec-2011<br>HRS 7585.2<br>LDG 6425 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 291003                 | MAIN HYDRAULIC ACCUMULATOR        |      |         | 9914081-1<br>7911             | MTH 18-Jul-2011<br>HRS 7527.3<br>LDG 6388 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 291004                 | MAIN HYDRAULIC ACCUMULATOR GAUGE  |      |         | 19940906-1<br>10200D          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 291005<br>LEFT AFT     | HYDRAULIC SHUTOFF VALVE           |      |         | 9914094-1<br>1851             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 291005<br>RIGHT AFT    | HYDRAULIC SHUTOFF VALVE           |      |         | 9914094-1<br>1744             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 291006                 | HYDRAULIC PRESSURE DUMP VALVE     |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 291007                 | 3000PS1 RELIEF VALVE              |      |         | 9914093-1<br>109              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 291008                 | RELIEF VALVE                      |      |         | 9914154-1<br>91               | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 291009<br>LEFT         | MANUAL HYDRAULIC SHUT OFF VALVE   |      |         | 9914120-1<br>7                | MTH 16-Jul-1991<br>HRS 1798               |                | O/C            |                |                            |                    |
| 291009<br>RIGHT        | MANUAL HYDRAULIC SHUT OFF VALVE   |      |         | 9914120-1<br>239              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains  |
|-----------------------|---------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|---------------------|
| 291010                | SHUTTLE VALVE                               |      |         | 67040<br>172                  | MTH 21-Aug-1986                           |                | O/C            |                |                            |                     |
| 291011                | HYDRAULIC TEMP CONTROL BOX                  |      |         | 6218128-1<br>48               | MTH 09-Oct-1986<br>HRS 61                 |                | O/C            |                |                            |                     |
| 291012                | HYDRAULIC VALVE MANIFOLD ASSEMBLY           |      |         | 9914077-2<br>NSN              | MTH 20-Nov-2005<br>HRS 6255               |                |                | 0<br>0         |                            |                     |
| 291013<br>NO. 1       | UNLOADING VALVE                             |      |         | 9567<br>103                   | MTH 04-Aug-2006<br>HRS 6456               |                | O/C            |                |                            |                     |
| 291013<br>NO. 2       | UNLOADING VALVE                             |      |         | 9567<br>102                   | MTH 16-Dec-2004<br>HRS 6117               |                | O/C            |                |                            |                     |
| 291014                | HYDRAULIC FLUID TEMP MONITOR-               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                     |
| 291015<br>LEFT        | HYDRAULIC CHECK VALVE                       |      |         | 9914077-2<br>NSN              | MTH 20-Nov-2005<br>HRS 6255               |                |                | 0<br>0         |                            |                     |
| 291015<br>RIGHT       | HYDRAULIC CHECK VALVE                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                     |
| 291016                | APU HYDRAULIC SHUT OFF VALVE                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                     |
| 291017                | HYDRAULIC SHUTTLE VALVE                     |      |         | 9914146-2<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                     |
| 291020<br>LEFT        | LEFT HYDRAULIC PRESSURE FILTER - DISCARD    |      |         | 9914077-5<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291020<br>RIGHT       | RIGHT HYDRAULIC PRESSURE FILTER - DISCARD   |      |         | 9914077-5<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291021<br>LEFT        | LEFT HYDRAULIC RETURN FILTER - DISCARD      |      |         | 9914077-8<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291021<br>RIGHT       | RIGHT HYDRAULIC RETURN FILTER - DISCARD     |      |         | 9914077-8<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291022<br>LEFT        | LEFT HYDRAULIC CASE DRAIN FILTER - DISCARD  |      |         | 9914077-2<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291022<br>RIGHT       | RIGHT HYDRAULIC CASE DRAIN FILTER - DISCARD |      |         | 9914077-2<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291023                | HYDRAULIC AILERON BOOST FILTER - DISCARD    |      |         | 9914077-2<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 291025                | HYDRAULIC AUXILIARY PUMP FILTER - DISCARD   |      |         | 9914077-2<br>NSN              | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 36<br>1200     | 0<br>0<br>0    | 30-Jun-2024<br>9935.3      | -7 m -1 d<br>1161.4 |
| Over Due              |                                             |      |         |                               |                                           |                |                |                |                            |                     |
| 292001                | HYDRAULIC ELECTRIC MOTOR PUMP               |      |         | 9914119-3<br>124              | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            | 32             |                            |                     |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position   | Description<br>Drawing # / Task #    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------|--------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 293001                  | HYDRAULIC PRESSURE INDICATOR         |      |         | 9914190-1<br>123              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 293002                  | HYDRAULIC RES VOLUMN INDICATOR       |      |         | 9914189-1<br>135              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 293003                  | HYDRAULIC PRESSURE TRANSMITER        |      |         | 9914175-1<br>18425255         | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 293004<br>LEFT          | HYDRAULIC LOW PRESSURE SWITCH        |      |         | 9914145-2<br>169              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 293004<br>RIGHT         | HYDRAULIC LOW PRESSURE SWITCH        |      |         | 9914145-2<br>0811             | MTH 14-Sep-2004<br>HRS 6039               |                | O/C            |                |                            |                    |
| 293005<br>LEFT          | HYDRAULIC TEMP SENSOR                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 293005<br>NO. 3         | HYDRAULIC TEMP SENSOR                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 293005<br>NO. 7         | HYDRAULIC TEMP SENSOR                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 293005<br>RIGHT         | HYD TEMP SENSOR                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 293009                  | AUX HYDRAULIC LOW PRESSURE SWITCH    |      |         | 9914145-2<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 300001<br>LEFT          | ALTERNATOR<br>9914216-3              |      |         | 83556-5<br>BS630              | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 2000           | 516.8          | 10218.5                    | 1444.6             |
| 300001<br>LEFT INBOARD  | LE HEATER                            |      |         | 5E2019-1<br>U027              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 300001<br>RIGHT INBOARD | LE HEATER                            |      |         | 9914312-4<br>U002             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 300002<br>RIGHT         | ALTERNATOR                           |      |         | 85578-3<br>401                | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 2000           | 812.3          | 9923                       | 1149.1             |
| 301001<br>LEFT          | ANTI-ICE SHUT OFF VALVE              |      |         | 9914124-4<br>0325             | MTH 12-Jun-2003<br>HRS 5644               |                | O/C            |                |                            |                    |
| 301001<br>RIGHT         | ANTI-ICE SHUT OFF VALVE<br>9914124-4 |      |         | 5155-00-1<br>0554             | MTH 09-Dec-2010<br>HRS 7384.2<br>LDG 6303 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 301002<br>LEFT          | WING/FUSLAGE REGULATOR VALVE         |      |         | 9912086-6<br>124              | MTH 22-Mar-2006<br>HRS 6336               |                | O/C            |                |                            |                    |
| 301002<br>RIGHT         | WING/FUSLAGE REGULATOR VALVE         |      |         | 9912086-6<br>121B             | MTH 08-Aug-1989<br>HRS 1291               |                | O/C            |                |                            |                    |
| 301003<br>LEFT          | STABILIZER HEATED LEADING EDGE       |      |         | 9914217-5<br>CS0646           | MTH 16-Aug-2007<br>HRS 6632               |                | O/C            |                |                            |                    |
| 301003<br>RIGHT         | STABILIZER HEATED LEADING EDGE       |      |         | 9914217-208<br>CS0528         | MTH 27-Feb-2004<br>HRS 5909               |                | O/C            |                |                            |                    |
| 301004<br>BOTTOM        | HORIZONTAL STABILIZER CONTROL        |      |         | 9914143-2<br>U1074            | MTH 10-Jul-2009<br>HRS 7119.2<br>LDG 6119 |                | O/C            |                |                            |                    |
| 301004<br>TOP           | HORIZONTAL STABILIZER CONTROL        |      |         | 9914143-2<br>U1346            | MTH 07-Dec-2003<br>HRS 5795               |                | O/C            | 1997           |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code       | Description                                     | Part Number             | C/W Time 1                                | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-----------------|-------------------------------------------------|-------------------------|-------------------------------------------|--------|-------|-------|-------------|---------|
| Position        | Drawing # / Task #                              | Part Serial No          | C/W Time 2                                | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 301006<br>LEFT  | AC CONTROL UNIT                                 | 9914216-2<br>362        | MTH 12-Dec-2003<br>HRS 5802               |        | O/C   | 5802  |             |         |
| 301006<br>RIGHT | AC CONTROL UNIT<br>9914216-2                    | FXE<br>83096-2<br>0535  | MTH 11-Aug-2017<br>HRS 8399.4<br>LDG 6952 |        | O/C   |       |             |         |
| 301007<br>LEFT  | AC AMMETER                                      | 9914065-4<br>206        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 301007<br>RIGHT | AC AMMETER                                      | 9914065-4<br>215        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 301008          | AC VOLTMETER                                    | 9914065-2<br>124        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 301010<br>LEFT  | BLEED AIR OVER TEMP SWITCH                      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 301010<br>RIGHT | BLEED AIR OVER TEMP SWITCH                      | 1173T42-3<br>3376       | MTH 27-Jun-2004<br>HRS 5984               |        | O/C   |       |             |         |
| 301022<br>LEFT  | BLEED AIR FLOW CHECK VALVE                      | 6214638-7<br>SN-UNKNOWN | MTH 06-Jul-1993<br>HRS 2529               |        | O/C   |       |             |         |
| 301022<br>RIGHT | BLEED AIR FLOW CHECK VALVE                      | 6214638-7<br>SN-UNKNOWN | MTH 06-Jul-1993<br>HRS 2529               |        | O/C   |       |             |         |
| 301023<br>LEFT  | FLAPPER CHECK VALVE                             | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 301023<br>RIGHT | FLAPPER CHECK VALVE                             | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 301024<br>RIGHT | HORIZONTAL STABILIZER TEMP SENSOR               | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 302001<br>LEFT  | NACELLE PRESSURE REGULATOR VALVE                | 9912086-1<br>1018C      | MTH 21-Nov-1995<br>HRS 3382               |        | O/C   |       |             |         |
| 302001<br>RIGHT | NACELLE PRESSURE REGULATOR VALVE                | 9912086-1<br>487B       | MTH 22-Mar-1988<br>HRS 702                |        | O/C   |       |             |         |
| 302002<br>LEFT  | ENGINE ANTI-ICE TEMPERATURE SWITCH<br>7         | M1002-505<br>114322     | MTH 06-Jun-2002<br>HRS 5465               |        | O/C   |       |             |         |
| 302002<br>RIGHT | ENGINE ANTI-ICE TEMPERATURE SWITCH<br>M1002-505 | P9550-103<br>74714      | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 303002<br>LEFT  | CURRENT SENSOR                                  | UNK<br>76250-7<br>2508  | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |        | O/C   |       |             |         |
| 303002<br>RIGHT | CURRENT SENSOR                                  | 76250-7<br>SN-UNKNOWN   | MTH 27-Aug-1986<br>HRS 20                 |        | O/C   |       |             |         |
| 304001          | W/S ANTI-ICE REGULATOR VALVE                    | 9912402-8<br>2938       | MTH 19-Oct-2003<br>HRS 5749               |        | O/C   |       |             |         |
| 304002          | W/S TEMP CONTROL VALVE                          | 9912085-1<br>12M142     | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 304003          | WINDSHIELD HEAT EXCHANGER                       | 9912041-3<br>446        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 304004<br>LEFT         | TEMPERATURE SENSOR                |      |         | 9912085-3<br>10BY271          | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 304004<br>RIGHT        | TEMPERATURE SENSOR                |      |         | 9912085-3<br>10BY272          | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 304005                 | PRESSURE SWITCH                   |      |         | 1115P25<br>1243               | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 304006                 | WINDSHIELD TEMP CONTROLLER        |      |         | 9912085-4<br>3AA0006          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 304007                 | WINDSHIELD TEMP MONITOR-          |      |         | 8913<br>40                    | MTH 31-Jul-1992<br>HRS 2187               |                | O/C            |                |                            |                    |
| 304009<br>LEFT         | GENERATOR INLET HEATER            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 304009<br>RIGHT        | GENERATOR INLET HEATER            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 304010<br>LEFT         | WINDSHIELD TEMP CONTROL           |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 304010<br>RIGHT        | WINDSHIELD TEMP CONTROL           |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 304101                 | PUMP & FILTER W/S ALCOHOL         |      |         | 476411<br>SN-UNKNOWN          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 312001<br>LEFT         | 24HR DIGITAL CLOCK<br>FXE         |      |         | M877-28V<br>24802             | MTH 25-May-2019<br>HRS 8643.2<br>LDG 7131 |                | O/C            |                |                            |                    |
| 312001<br>RIGHT        | 24HR DIGITAL CLOCK                |      |         | M877A5V<br>1710               | MTH 31-Jul-1992<br>HRS 2187               |                | O/C            |                |                            |                    |
| 312002<br>LEFT         | CLOCK BATTERY                     |      |         | PN<br>SN-UNKNOWN              | MTH 10-Apr-2014<br>HRS 7917<br>LDG 6658   |                | O/C            | 0<br>0<br>0    |                            |                    |
| 312002<br>RIGHT        | CLOCK BATTERY                     |      |         | PN<br>SN-UNKNOWN              | MTH 10-Apr-2014<br>HRS 7917<br>LDG 6658   |                | O/C            | 0<br>0<br>0    |                            |                    |
| 313001                 | FLIGHT HOUR METER<br>85071        |      |         | C664503-0104<br>SN-UNKNOWN    | MTH 11-Dec-1997<br>HRS 4168               |                | O/C            |                |                            |                    |
| 313002                 | FLIGHT HOUR REMINDER              |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 313109                 | ACCELEROMETER                     |      |         | 981-3088-010<br>7286          | MTH 27-Apr-1989<br>HRS 1195               |                | O/C            |                |                            |                    |
| 315001                 | ANNUN PANEL MASTER                |      |         | 6298088-27<br>013             | MTH 08-May-2003<br>HRS 5629               |                | O/C            |                |                            |                    |
| 315002<br>LEFT         | MASTER WARNING CONTROL            |      |         | 1876-1<br>323                 | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 315002<br>RIGHT        | MASTER WARNING CONTROL            |      |         | 1876-1<br>174                 | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 321001<br>LEFT         | MAIN LANDING GEAR                 |      |         | 6241100-3<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 321001<br>LEFT FORWARD | TRUNNION ATTACH BEARING ASSEMBLY  |      |         | 6222303-11<br>SN-UNKNOWN      | MTH 21-Aug-1986<br>LDG 0                  |                | 15400          | 0              | 15400                      | 8166               |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position               | Description<br>Drawing # / Task #                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------|-----------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 321001<br>RIGHT                     | MAIN LANDING GEAR                                   |      |         | 6241100-4<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 321002<br>LEFT AFT                  | TRUNNION ATTACH BEARING ASSEMBLY                    |      |         | 6222303-9<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |                | 15400          | 0<br>0         | 15400                      | 8166               |
| 321003<br>LEFT FORWARD              | TRUNNION ATTACH PIN                                 |      |         | 6241107-10<br>SN-UNKNOWN      | MTH 21-Aug-1986<br>LDG 0                  |                | 11400          | 0<br>0         | 11400                      | 4166               |
| 321004<br>LEFT AFT                  | TRUNNION ATTACH PIN                                 |      |         | 6241107-9<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |                | 11400          | 0<br>0         | 11400                      | 4166               |
| 321005<br>LEFT MAIN<br>LANDING GEAR | LOCKING SIDE BRACE                                  |      |         | 9914169-3<br>1683             | MTH 17-Aug-2001<br>LDG 5099               |                | 15400          | 0<br>0         | 20499                      | 13265              |
| 321010<br>LEFT MAIN<br>LANDING GEAR | ACTUATOR                                            |      |         | 9914170-2<br>749              | MTH 15-May-1995<br>LDG 2993               |                | 22300          | 0<br>0         | 25293                      | 18059              |
| 321013<br>LEFT AFT                  | LOCKING SIDE BRACE (GEAR END) ATTACHMENT BOLTS      |      |         | S3461-71<br>NSN               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 15400          | 0<br>0<br>0    | 22613                      | 15379              |
| 321013<br>RIGHT AFT                 | LOCKING SIDE BRACE (GEAR END) ATTACHMENT BOLTS      |      |         | S3461-71<br>NSN               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 15400          | 0<br>0<br>0    | 22613                      | 15379              |
| 321014<br>LEFT FORWARD              | LOCKING SIDE BRACE (STRUCTURE END) ATTACHMENT BOLTS |      |         | S3461-73<br>NSN               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 15400          | 0<br>0<br>0    | 22613                      | 15379              |
| 321014<br>RIGHT FORWARD             | LOCKING SIDE BRACE (STRUCTURE END) ATTACHMENT BOLTS |      |         | S3461-73<br>NSN               | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 15400          | 0<br>0<br>0    | 22613                      | 15379              |
| 321025<br>LEFT MAIN GEAR            | LOCKING SIDE BRACE SUPPORT FITTING                  |      |         | 6221425-1<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |                | 11800          | 0<br>0         | 11800                      | 4566               |
| 321030<br>LEFT MAIN<br>LANDING GEAR | TRUNNION                                            |      |         | 6241101-9<br>SN-UNKNOWN       | MTH 23-Mar-2005<br>LDG 5482               |                | 23000          | 0<br>0         | 28482                      | 21248              |
| 321045<br>LEFT MAIN<br>LANDING GEAR | OLEO ASSEMBLY                                       | UNK  |         | 6241210-1<br>B315S            | MTH 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |                | 22400          |                |                            | ?                  |
| 321050<br>LEFT MAIN<br>LANDING GEAR | LINK AND AXLE ASSEMBLY                              |      |         | 6241118-4<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |                | 15600          | 0<br>0         | 15600                      | 8366               |
| 321055<br>LEFT                      | MAIN GEAR AXLE                                      |      |         | 6241111-2<br>SN-UNKNOWN       | MTH 05-Dec-2008<br>HRS 7011.7<br>LDG 6051 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 321060<br>LEFT MAIN<br>LANDING GEAR | ACTUATOR ATTACH FITTING                             |      |         | 6222345-21<br>SN-UNKNOWN      | MTH 21-Aug-1986<br>LDG 0                  |                | 45800          | 0<br>0         | 45800                      | 38566              |
| 321065<br>LEFT MAIN GEAR            | ACTUATOR (GEAR END) ATTACH BOLT                     |      |         | NAS6206-18D<br>NSN            | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 7100           | 0<br>0<br>0    | 14313                      | 7079               |
| 321066<br>LEFT MAIN GEAR            | ACTUATOR (STRUCTURE END) ATTACH BOLT                |      |         | NAS6206-24D<br>NSN            | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | 7100           | 0<br>0<br>0    | 14313                      | 7079               |
| 321070<br>LEFT MAIN<br>LANDING GEAR | TRUNNION/LINK BEARING                               |      |         | 5841211-1<br>SN-UNKNOWN       | MTH 05-Dec-2008<br>HRS 7011.7<br>LDG 6051 |                | 1300           | 0<br>0<br>0    | 7351                       | 117                |
| 322001<br>RIGHT FORWARD             | TRUNNION ATTACH BEARING ASSEMBLY                    |      |         | 6222303-10<br>SN-UNKNOWN      | MTH 21-Aug-1986<br>LDG 0                  |                | 15400          | 0<br>0         | 15400                      | 8166               |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                            | Description                          | Part Number                    | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|--------------------------------------|--------------------------------------|--------------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position                             | Drawing # / Task # City Mod Lvl      | Part Serial No                 | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 322002<br>RIGHT AFT                  | TRUNNION ATTACH BEARING ASSEMBLY     | 6222303-12<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |        | 15400 | 0           | 15400       | 8166    |
| 322003<br>RIGHT FOWARD               | TRUNNION ATTACH PIN                  | 6241107-9<br>SN-UNKNOWN        | MTH 21-Aug-1986<br>LDG 0                  |        | 11400 | 0           | 11400       | 4166    |
| 322004<br>RIGHT AFT                  | TRUNNION ATTACH PIN                  | 6241107-10<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |        | 11400 | 0           | 11400       | 4166    |
| 322005<br>RIGHT MAIN<br>LANDING GEAR | LOCKING SIDE BRACE                   | 9914169-3<br>1636              | MTH 17-Aug-2001<br>LDG 5099               |        | 15400 | 0           | 20499       | 13265   |
| 322010<br>RIGHT MAIN<br>LANDING GEAR | ACTUATOR                             | 9914170-2<br>724               | MTH 15-May-1995<br>LDG 2993               |        | 22300 | 0           | 25293       | 18059   |
| 322025<br>RIGHT MAIN<br>LANDING GEAR | LOCKING SIDE BRACE SUPPORT FITTING   | 6221425-2<br>SN-UNKNOWN        | MTH 21-Aug-1986<br>LDG 0                  |        | 11800 | 0           | 11800       | 4566    |
| 322030<br>RIGHT MAIN<br>LANDING GEAR | TRUNNION                             | 6241101-4<br>SN-UNKNOWN        | MTH 21-Aug-1986<br>LDG 0                  |        | 12000 | 0           | 12000       | 4766    |
| 322045<br>RIGHT MAIN<br>LANDING GEAR | OLEO ASSEMBLY                        | 6241209-2<br>B444S             | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | 22400 | 923         | 28701       | 21467   |
| 322050<br>RIGHT MAIN<br>LANDING GEAR | LINK AND AXLE ASSEMBLY               | 6241118-4<br>SN-UNKNOWN        | MTH 21-Aug-1986<br>LDG 0                  |        | 15600 | 0           | 15600       | 8366    |
| 322055<br>RIGHT                      | MAIN GEAR AXLE                       | PN<br>SN-UNKNOWN               | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 322060<br>RIGHT MAIN<br>LANDING GEAR | ACTUATOR ATTACH FITTING              | 6222345-22<br>SN-UNKNOWN       | MTH 21-Aug-1986<br>LDG 0                  |        | 45800 | 0           | 45800       | 38566   |
| 322065<br>RIGHT MAIN GEAR            | ACTUATOR (GEAR END) ATTACH BOLT      | NAS6206-18D<br>NSN             | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |        | 7100  | 0           | 14313       | 7079    |
| 322066<br>RIGHT MAIN GEAR            | ACTUATOR (STRUCTURE END) ATTACH BOLT | NAS6206-24D<br>NSN             | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |        | 7100  | 0           | 14313       | 7079    |
| 322070<br>RIGHT MAIN<br>LANDING GEAR | TRUNNION/LINK BEARING                | 5841211-1<br>SN-UNKNOWN        | MTH 28-Feb-2011<br>HRS 7426.8<br>LDG 6325 |        | 1300  | 0           | 7625        | 391     |
| 322510<br>NOSE WHEEL                 | POWER STEERING UNIT                  | PN<br>SN-UNKNOWN               | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 323001                               | NOSE LANDING GEAR UPLOCK ACTUATOR    | 9914096-1 UNK<br>4A167<br>0476 | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   | 0<br>0<br>0 |             |         |
| 323002<br>LEFT                       | MAIN GEAR UPLOCK ASSEMBLY            | 81029<br>850                   | MTH 10-Oct-1999<br>LDG 4618               |        | O/C   |             |             |         |
| 323002<br>RIGHT                      | MAIN GEAR UPLOCK ASSEMBLY            | 6217102-2<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 323006                               | LANDING GEAR CONTROL                 | 9914196-1<br>137               | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 323007<br>LEFT                       | MAIN GEAR SHUTTLE VALVE              | 9914146-3<br>195               | MTH 10-Feb-2004<br>LDG 5328               |        | O/C   |             |             |         |
| 323007<br>RIGHT                      | MAIN GEAR SHUTTLE VALVE              | 9914146-3<br>106               | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 323007                               | NOSE GEAR SHUTTLE VALVE              | 9914146-3<br>397               | MTH 21-Aug-1986                           |        | O/C   |             |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position          | Description<br>Drawing # / Task #               | City | Mod Lvl | Part Number<br>Part Serial No        | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|-------------------------------------------------|------|---------|--------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 323008                         | MAIN GEAR MANIFOLD VALVE                        |      |         | 66040-3<br>184A                      | MTH 02-Sep-1998<br>LDG 4239               |                | O/C            |                |                            |                    |
| 323010<br>NOSE                 | LANDING GEAR ASSEMBLY                           |      |         | 6242010-5<br>SN-UNKNOWN              | MTH 21-Aug-1986<br>LDG 0                  |                |                | 0<br>22000     |                            | 14766              |
| 323012                         | NOSE GEAR DOWNLOCK SWITCH                       |      |         | 1EN118-6<br>SN-UNKNOWN               | MTH 15-May-1995<br>LDG 2993               |                | O/C            |                |                            |                    |
| 323015<br>NOSE LANDING<br>GEAR | ACTUATOR                                        |      |         | 9914085-1<br>117                     | MTH 21-Aug-1986<br>LDG 0                  |                |                | 0<br>12000     |                            | 4766               |
| 323016<br>LEFT                 | TRAILING LINK SPACER                            |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323016<br>RIGHT                | TRAILING LINK SPACER                            |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323017<br>LEFT                 | TRAILING LINK NUT                               |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323017<br>RIGHT                | TRAILING LINK NUT                               |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323018<br>LEFT                 | TRAILING LINK SPACER                            |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323018<br>RIGHT                | TRAILING LINK SPACER                            |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323020<br>LEFT                 | TRUNNION NOSE LANDING GEAR SUPPORT FITTING      |      |         | 6213124-3<br>SN-UNKNOWN              | MTH 21-Aug-1986<br>LDG 0                  |                |                | 0<br>14900     |                            | 7666               |
| 323020<br>RIGHT                | TRUNNION NOSE LANDING GEAR SUPPORT FITTING      |      |         | 6213124-3<br>SN-UNKNOWN              | MTH 21-Aug-1986<br>LDG 0                  |                |                | 0<br>14900     |                            | 7666               |
| 323025<br>NOSE GEAR            | SPADE DOOR BELLCRANK (LEFT) BUSHING             |      |         | PN<br>SN-UNKNOWN                     | MTH 02-Feb-1998<br>LDG 3998               |                |                | 0<br>4000      |                            | 764                |
| 323026<br>NOSE GEAR            | SPADE DOOR BELLCRANK (RIGHT) BUSHING            |      |         | PN<br>SN-UNKNOWN                     | MTH 02-Feb-1998<br>LDG 3998               |                |                | 0<br>4000      |                            | 764                |
| 323027<br>LEFT                 | LINK PIN                                        |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 323028<br>RIGHT                | LINK PIN                                        |      |         | PN<br>SN-UNKNOWN                     | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 324000<br>GEAR                 | EMERGENCY LANDING GEAR PNEUMATIC STORAGE BOTTLE |      |         | 9914099-3<br>0120                    | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | O/C            |                |                            |                    |
| 324005<br>EMERGENCY            | EMERGENCY BRAKE PNEUMATIC STORAGE BOTTLE        |      |         | 9914099-4<br>0056                    | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213 |                | O/C            |                |                            |                    |
| 324051<br>NO. 1                | LEFT OUTBOARD BRAKE ASSY                        |      |         | 2-1502-3<br>9914136-9<br>FXE<br>0550 | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 324052<br>NO. 2                | LEFT INBOARD BRAKE ASSY                         |      |         | 2-1502-3<br>9914136-9<br>0747        | MTH 05-Dec-2008<br>HRS 7011.7<br>LDG 6051 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 324053<br>NO. 3                | RIGHT INBOARD BRAKE ASSY                        |      |         | 2-1502-3<br>9914136-9<br>FXE<br>1074 | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | O/C            | 0<br>0<br>0    |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                | Description                                                  | Part Number          | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|--------------------------|--------------------------------------------------------------|----------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position                 | Drawing # / Task # City Mod Lvl                              | Part Serial No       | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 324054<br>NO. 4          | RIGHT OUTBOARD BRAKE ASSY<br>9914136-9 FXE                   | 2-1502-3<br>1449     | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |        | O/C   | 0<br>0<br>0 |             |         |
| 324095<br>NO. 1          | MAIN TIRE                                                    | 226K08-4<br>22900820 | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 324096<br>NO. 2          | MAIN TIRE                                                    | 226K08-4<br>22420718 | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 324097<br>NO. 3          | MAIN TIRE                                                    | 226K08-4<br>22900819 | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 324098<br>NO. 4          | MAIN TIRE                                                    | 226K08-4<br>22880807 | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 324099<br>NOSE           | TIRE                                                         | 184F13-5<br>30371113 | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 324101                   | BRAKE METERING VALVE                                         | 9914263-1<br>219     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324102                   | ANTI-SKID CONTROL BOX                                        | 9914078-9<br>208     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324103<br>LEFT           | ANTI-SKID BRAKE VALVE ASSEMBLY                               | 9914078-10<br>314    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324103<br>RIGHT          | ANTI SKID BRAKE VALVE ASSEMBLY                               | 9914078-10<br>316    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324104<br>LEFT INBOARD   | ANTI-SKID TRANSDUCER                                         | 9914078-6<br>608     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324104<br>LEFT OUTBOARD  | ANTI-SKID TRANSDUCER                                         | 9914078-6<br>607     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324104<br>RIGHT INBOARD  | ANTI-SKID TRANSDUCER                                         | 9914078-6<br>602     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324104<br>RIGHT OUTBOARD | ANTI-SKID TRANSDUCER                                         | 9914078-6<br>603     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324106                   | EMERGENCY BRAKE VALVE                                        | 9914100-3<br>84      | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 324107                   | PARKING BRAKE VALVE                                          | 9914098-2<br>75      | MTH 27-Jun-2003<br>HRS 5658               |        | O/C   | 8094        |             |         |
| 324113<br>LEFT INBOARD   | SHUTTLE VALVE ASSEMBLY                                       | PN<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 324113<br>LEFT OUTBOARD  | SHUTTLE VALVE ASSEMBLY                                       | PN<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 324113<br>RIGHT INBOARD  | SHUTTLE VALVE ASSEMBLY                                       | PN<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 324113<br>RIGHT OUTBOARD | SHUTTLE VALVE ASSEMBLY                                       | PN<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 324114<br>NOSE GEAR      | ACCUM PRESSURE GAUGE                                         | PN<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 324120                   | ANTISKID SYSTEM BRAKE CONTROL VALVE FILTER DISCARD/SERVICING | 21243-4-10<br>NSN    | MTH 10-Oct-1999<br>HRS 4798               |        |       | 0<br>0      | 9598        | 824.1   |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 324121                | POWER BRAKE METERING VALVE FILTER DISCARD/SERVICING   |      |         | 20549-4-10<br>NSN             | MTH 11-Sep-2008<br>HRS 6943.9<br>LDG 6007 |                | 4800           | 0<br>0<br>0    | 11743.9                    | 2970               |
| 324122                | POWER STEERING UNIT FILTER FITTINGS DISCARD/SERVICING |      |         | PN<br>SN-UNKNOWN              | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | 4800           | 0              | 13018.5                    | 4244.6             |
| 324161<br>NO. 1       | MAIN WHEEL<br>9914136-8                               |      |         | 3-1399-6<br>0990#2219         | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 324162<br>NO. 2       | MAIN WHEEL<br>9914136-8                               |      |         | 3-1399-6<br>1880              | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 324163<br>NO. 3       | MAIN WHEEL<br>9914136-7                               |      |         | 3-1399-5<br>2982#3109         | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 324164<br>NO. 4       | MAIN WHEEL<br>9914136-7                               |      |         | 3-1399-5<br>2723              | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 324165<br>NOSE        | WHEEL<br>9914069-2                                    |      |         | 3-1418<br>3088                | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | O/C            |                |                            |                    |
| 325001                | POWER STEERING UNIT                                   |      |         | 9914080-7<br>97               | MTH 24-Feb-2006<br>HRS 6316               |                | O/C            |                |                            |                    |
| 325002                | POWER STEERING ACCUMULATOR                            |      |         | 9914081-1<br>8264             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 325003                | SOLENOID AUX POWER STEERING UNIT                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 331001<br>CENTER      | INVERTER INSTRUMENT PANEL                             |      |         | 273-1<br>0029313              | MTH 22-Apr-2005<br>HRS 6180               |                | O/C            |                |                            |                    |
| 331001<br>LEFT        | INVERTER INSTRUMENT PANEL                             |      |         | 273-1<br>3453                 | MTH 23-Aug-1995<br>HRS 3260               |                | O/C            |                |                            |                    |
| 331001<br>RIGHT       | INVERTER INSTRUMENT PANEL                             |      |         | 273-1<br>5098                 | MTH 02-Feb-2001<br>HRS 5213               |                | O/C            |                |                            |                    |
| 331002                | INVERTER EL PANEL                                     |      |         | EM2044-1<br>718               | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 332001<br>AFT RIGHT   | INDICATOR LIGHTING POWER SUPPLY                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 332001<br>CENTER      | INDICATOR LIGHTING POWER SUPPLY                       |      |         | 6900053<br>1388B              | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |
| 332001<br>L1          | INDICATOR LIGHTING POWER SUPPLY                       |      |         | 6900053<br>731                | MTH 20-Apr-1988<br>HRS 749                |                | O/C            |                |                            |                    |
| 332001<br>L2          | INDICATOR LIGHTING POWER SUPPLY                       |      |         | 6900053<br>736                | MTH 20-Apr-1988<br>HRS 749                |                | O/C            |                |                            |                    |
| 332001<br>L3          | INDICATOR LIGHTING POWER SUPPLY                       |      |         | 6900053<br>756                | MTH 20-Apr-1988<br>HRS 749                |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code         | Description                     | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-------------------|---------------------------------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position          | Drawing # / Task # City Mod Lvl | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 332001<br>L4      | INDICATOR LIGHTING POWER SUPPLY | 6900053<br>539B            | MTH 30-Jun-1998<br>HRS 4416               |        | O/C   |             |             |         |
| 332001<br>L5      | INDICATOR LIGHTING POWER SUPPLY | PW28S40CC2A<br>981         | MTH 30-Sep-1996<br>HRS 3700               |        | O/C   |             |             |         |
| 332001<br>LEFT    | INDICATOR LIGHTING POWER SUPPLY | 6900053<br>490B            | MTH 04-Feb-2003<br>HRS 5548               |        | O/C   |             |             |         |
| 332001<br>RIGHT   | INDICATOR LIGHTING POWER SUPPLY | PW28S40CC2<br>SN-UNKNOWN   | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 332001<br>VANITY  | INDICATOR LIGHTING POWER SUPPLY | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 334000<br>LEFT    | STROBE LIGHT                    | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 334000<br>RIGHT   | STROBE LIGHT                    | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 334001<br>LEFT    | ANTI-COLLISION POWER SUPPLY     | 60-3742-1<br>680           | MTH 13-Nov-2000<br>HRS 5002               |        | O/C   |             |             |         |
| 334001<br>RIGHT   | ANTI-COLLISION POWER SUPPLY     | 60-3742-1<br>133           | MTH 16-Jun-2010<br>HRS 7285.2<br>LDG 6232 |        | O/C   | 0<br>0<br>0 |             |         |
| 334002<br>LEFT    | LANDING LIGHT MOTOR             | G2905-24<br>26738          | MTH 25-Sep-2000<br>HRS 4924               |        | O/C   |             |             |         |
| 334002<br>RIGHT   | LANDING LIGHT MOTOR             | G2905-24<br>92786          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334003<br>LEFT    | LANDING LIGHT ASSEMBLY          | 45-0213-1<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334003<br>RIGHT   | LANDING LIGHT ASSEMBLY          | 45-0213-1<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334004<br>LEFT    | LANDING LIGHT LAMP              | MS25241-4553<br>SN-UNKNOWN | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334004<br>RIGHT   | LANDING LIGHT LAMP              | MS25241-4553<br>SN-UNKNOWN | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334005<br>LEFT    | TAXI LIGHT LAMP                 | LP4626<br>SN-UNKNOWN       | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 334005<br>RIGHT   | TAXI LIGHT LAMP FXE             | LP4594<br>N/A              | MTH 02-Nov-2015<br>HRS 8125<br>LDG 6767   |        | O/C   | 0<br>0      |             |         |
| 334006            | GRIMES FLASHER                  | 70-0196-1<br>1978          | MTH 01-Feb-2008<br>HRS 6784               |        | O/C   |             |             |         |
| 334007            | PULSE LITE CONTROL UNIT         | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 335001<br>AFT     | EMERGENCY LIGHTING BATTERY PACK | 016512018<br>003           | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |        | O/C   |             |             |         |
| 335001<br>FORWARD | EMERGENCY LIGHTING BATTERY PACK | 016512018<br>001           | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |        | O/C   |             |             |         |
| 340001<br>LEFT    | DME ANTENNA                     | DMNI50-2<br>29876          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340001<br>PILOT   | ALTIMETER<br>BA-141             | 4016341-905<br>5071038     | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code         | Description                       | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-------------------|-----------------------------------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position          | Drawing # / Task #                | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 340001<br>RIGHT   | DME ANTENNA                       | DMNI50-2<br>30376          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340002<br>AFT     | DORNE & MARGO TRANSPONDER ANTENNA | DMNI50-2<br>30425          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340002<br>COPILOT | ALTIMETER                         | 520-15790-903<br>1059      | MTH 27-Sep-2002<br>HRS 5468               |        | O/C   |             |             |         |
| 340002<br>FORWARD | DORNE & MARGO TRANSPONDER ANTENNA | DMNI50-2<br>29862          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340003<br>STANDBY | ALTIMETER                         | 10460-11880<br>W10869      | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   | 0<br>0<br>0 |             |         |
| 340004<br>NO. 1   | AIR DATA COMPUTER<br>AZ-810       | 7000700-665<br>03119559    | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   |             |             |         |
| 340005<br>NO. 2   | AIR DATA COMPUTER<br>AZ-810       | 7000700-665<br>83090293    | MTH 12-Apr-2003<br>HRS 5600               |        | O/C   |             |             |         |
| 340006<br>PILOT   | TRANSPONDER<br>MST-67A            | 066-01143-0601<br>97032377 | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |        | O/C   |             |             |         |
| 340007<br>COPILOT | TRANSPONDER                       | 9007000-57001<br>NXE02453  | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |        | O/C   |             |             |         |
| 340009            | VOICE ADVISORY SYSTEM             | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340010<br>LEFT    | AOA TRANSMITER                    | SLZ7272-1<br>PE2768        | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |        | O/C   |             |             |         |
| 340010<br>RIGHT   | AOA TRANSMITER FXE                | SLZ7272-1<br>PE2655A       | MTH 03-Jan-2018<br>HRS 8462.6<br>LDG 6995 |        | O/C   |             |             |         |
| 340011<br>LEFT    | TAS/SAT/TAT INDICATOR             | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340011<br>RIGHT   | TAS/SAT/TAT INDICATOR             | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340013<br>LEFT    | RADIO ALTIMETER                   | 7001840-905<br>85011486    | MTH 21-Apr-2004<br>HRS 5953               |        | O/C   | 194         |             |         |
| 340013<br>RIGHT   | RADIO ALTIMETER                   | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340015<br>RIGHT   | OAT SENSOR                        | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340015            | TEMPERATURE PROBE                 | 102DB1CY<br>67277          | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340017<br>LEFT    | RADIO ALTIMETER ANTENNA<br>AT-224 | 4010504-1<br>426           | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340017<br>RIGHT   | RADIO ALTIMETER ANTENNA<br>AT-224 | 4010504-1<br>340           | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 340018(R)         | -- RADAR ALT IND                  | 7000839-903<br>82032133    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 340019                | STALL WARNING COMPUTER<br>S3100-10 |      |         | SLZ7715<br>AC1311             | MTH 03-Jul-2006<br>HRS 6420 |                | O/C            |                |                            |                    |
| 340021<br>LEFT        | ACCELEROMETER<br>AG-222            |      |         | 7000992<br>3334               | MTH 10-Nov-1988<br>HRS 1050 |                | O/C            |                |                            |                    |
| 340021<br>RIGHT       | ACCELEROMETER<br>AG-222            |      |         | 7000992<br>4630               | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 340022                | AOA INDEXER                        |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340023                | FAN LOGIC BOX                      |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340024                | -- MARKER BEACON ANTENA            |      |         | 16D00500-2<br>SN-UNKNOWN      | MTH 27-Jan-1988<br>HRS 619  |                | O/C            |                |                            |                    |
| 340028<br>LEFT        | VLF LOOP COUPLER                   |      |         | 30490-1<br>592                | MTH 26-Apr-1988<br>HRS 749  |                | O/C            |                |                            |                    |
| 340028<br>RIGHT       | VLF LOOP COUPLER                   |      |         | 30490-1<br>380                | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 340029<br>BOTTOM      | VLF LOOP ANTENNA                   |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340029<br>TOP         | VLF LOOP ANTENNA                   |      |         | 11455-2<br>1478               | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 340038<br>LEFT        | DIRECTIONAL GYRO<br>C-14D          |      |         | 4020577-3<br>6060267          | MTH 30-Jun-1998<br>HRS 4416 |                | O/C            | 90             |                            |                    |
| 340038<br>RIGHT       | DIRECTIONAL GYRO<br>C-14D          |      |         | 4020577-3<br>79021114         | MTH 28-Aug-2007<br>HRS 6639 |                | O/C            |                |                            |                    |
| 340039<br>LEFT        | RATE GYRO                          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340039<br>RIGHT       | RATE GYRO<br>RG-204                |      |         | 7007453-903<br>96104156       | MTH 19-Dec-1996<br>HRS 3774 |                | O/C            |                |                            |                    |
| 340040<br>LEFT        | HSI REMOTE CONTROL                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340040<br>RIGHT       | HSI REMOTE CONTROL                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340041<br>LEFT        | ADF CONTROL<br>CTL-62              |      |         | 622-6522-005<br>2391          | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340041<br>RIGHT       | ADF CONTROL<br>CTL-62              |      |         | 622-6522-005<br>1748          | MTH 29-Jan-2001<br>HRS 5194 |                | O/C            |                |                            |                    |
| 340042                | TRANSPONDER CONTROL<br>CTL-92      |      |         | 622-6523-005<br>1468          | MTH 06-Jun-2002<br>HRS 5465 |                | O/C            | 5465           |                            |                    |
| 340046<br>LEFT        | SG CUE AIR DATA INDICATOR          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340046<br>RIGHT       | SG CUE AIR DATA INDICATOR          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340047<br>LEFT        | HSI                                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340047<br>RIGHT       | HSI                                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 340048<br>LEFT        | VERTICAL GYRO<br>VG-14A            |      |         | 7000622-901<br>82033975       | MTH 28-Aug-2007<br>HRS 6639 |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code        | Description                       |      | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|------------------|-----------------------------------|------|----------------------------|-------------------------------------------|--------|-------|-------|-------------|---------|
| Position         | Drawing # / Task #                | City | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 340048<br>RIGHT  | VERTICAL GYRO<br>VG-14A           | UNK  | 7000622-901<br>91056851    | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   |       |             |         |
| 340051           | DATA NAV COMPUTER                 |      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340052           | RADAR INDICATOR                   | FXE  | MI585351-1<br>1027         | MTH 15-Sep-2015<br>HRS 8099<br>LDG 6754   |        | O/C   |       |             |         |
| 340053           | DUAL REMOTE COMPENSATOR<br>CS-412 |      | 2593379-001<br>85048024    | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340054<br>BOTTOM | FLUX VALVE<br>FX-220              |      | 2594484<br>85093402        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340054<br>LEFT   | FLUX VALVE                        |      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340054<br>RIGHT  | FLUX VALVE                        |      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340054<br>TOP    | FLUX VALVE<br>FX-220              |      | 2594484<br>85093407        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340060           | GLIDE SCOPE ANTENNA               |      | RGS1048<br>9429            | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340073           | RADAR REC/TRANS ANTENNA<br>WR-800 |      | MI585350<br>1206           | MTH 09-Oct-2007<br>HRS 6680               |        | O/C   |       |             |         |
| 340075           | RADAR ANTENNA<br>WA-800           |      | MI585353<br>2460           | MTH 13-Nov-2000<br>HRS 5002               |        | O/C   |       |             |         |
| 340078<br>LEFT   | ADF ANTENNA<br>APA-80             |      | 622-2363-001<br>SN-UNKNOWN | MTH 22-Apr-1998<br>HRS 4326               |        | O/C   |       |             |         |
| 340078<br>RIGHT  | ADF ANTENNA<br>APA-80             |      | 622-2363-001<br>21939      | MTH 27-Jan-1988<br>HRS 619                |        | O/C   |       |             |         |
| 340080           | GLIDE SLOPE ANTENNA               |      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340081           | DATA NAV CONTROL                  |      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340082           | AOA INDICATOR                     |      | SLZ9987<br>CR1197C         | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340085           | DATA NAV INTERFACE                |      | 21105-2-03<br>1155         | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340086           | MEMORY MODULE                     |      | 22150-1-03<br>1129         | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340087<br>PITCH  | SERVO MOUNT<br>SB-201             |      | 4005842<br>85081170        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340087<br>ROLL   | SERVO MOUNT<br>SB-201             |      | 4005842<br>85081057        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340087<br>YAW    | SERVO MOUNT<br>SB-201             |      | 4005842<br>85081058        | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340088<br>PILOT  | ENCODING ALTIMETER                |      | 4016341-905<br>85070138    | MTH 18-Aug-1989<br>HRS 1291               |        | O/C   |       |             |         |
| 340089<br>LEFT   | FD MODE SELECTOR<br>MS-500A       | UNK  | 7004536-915<br>83070170    | MTH 03-Feb-2014<br>HRS 7899<br>LDG 6649   |        | O/C   |       |             |         |
| 340089<br>RIGHT  | FD MODE SELECTOR<br>MS-500A       |      | 7004536-915<br>85060639    | MTH 21-Aug-1986                           |        | O/C   |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code        | Description                          |      | Part Number                  |         | C/W Time 1                            | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|------------------|--------------------------------------|------|------------------------------|---------|---------------------------------------|--------|-------|-------------|-------------|---------|
| Position         | Drawing # / Task #                   | City | Part Serial No               | Mod Lvl | C/W Time 2                            | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 340090<br>LEFT   | FD COMPUTER<br>FZ-500                | UNK  | 4018369-905<br>88015566      | MTH     | 03-Feb-2014<br>HRS 7899<br>LDG 6649   |        | O/C   | 4<br>0<br>0 |             |         |
| 340090<br>RIGHT  | FD COMPUTER<br>FZ-500                | UNK  | 4018369-905<br>82013250      | MTH     | 03-Feb-2014<br>HRS 7899<br>LDG 6649   |        | O/C   | 4<br>0<br>0 |             |         |
| 340092<br>NO. 2  | AHRU COMPUTER POWER SUPPLY           |      | PN<br>SN-UNKNOWN             | MTH     | 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340092           | STANDBY GYRO POWER SUPPLY<br>PS-835C |      | 501-1228-03<br>1105          | MTH     | 01-Mar-2024<br>HRS 8752.5<br>LDG 7224 |        | O/C   |             |             |         |
| 340093           | JET STATIC CONVERTER                 |      | 501-1318-01<br>4578          | MTH     | 02-Sep-1998<br>HRS 4462               |        | O/C   |             |             |         |
| 340095<br>LEFT   | RMI INDICATOR<br>RMI-30              |      | 622-4938-004<br>4576         | MTH     | 21-Aug-1986                           |        | O/C   |             |             |         |
| 340095<br>RIGHT  | RMI INDICATOR                        | UNK  | 3337LB21C<br>1549            | MTH     | 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   |             |             |         |
| 340096<br>BOTTOM | RCVR NAV<br>VIR-32                   |      | 622-6137-001<br>5837         | MTH     | 09-May-1988<br>HRS 780                |        | O/C   |             |             |         |
| 340096<br>TOP    | RCVR NAV<br>VIR-32                   |      | 622-6137-201<br>1307         | MTH     | 10-Jun-1999<br>HRS 4753               |        | O/C   |             |             |         |
| 340098<br>LEFT   | DME RECEIVER/TRANSMITTER<br>DME-42   |      | 622-6263-001<br>1944         | MTH     | 21-Aug-1986                           |        | O/C   |             |             |         |
| 340098<br>RIGHT  | DME RECEIVER/TRANSMITTER<br>DME-42   | KFXE | 622-6263-001<br>4321         | MTH     | 13-Jul-2015<br>HRS 7940.2<br>LDG 6682 |        | O/C   | 1<br>0      |             |         |
| 340099<br>LEFT   | DME INDICATOR<br>IND-42C             |      | 622-7318-001<br>749          | MTH     | 21-Aug-1986                           |        | O/C   |             |             |         |
| 340099<br>RIGHT  | DME INDICATOR                        |      | PN<br>SN-UNKNOWN             | MTH     | 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 340100<br>LEFT   | ADF RECEIVER<br>ADF-60A              |      | 622-2362-001<br>11646        | MTH     | 10-Apr-2003<br>HRS 5600               |        | O/C   | 1258        |             |         |
| 340100<br>RIGHT  | ADF RECEIVER<br>ADF-60A              |      | 622-2362-001<br>16978        | MTH     | 12-Jun-2003<br>HRS 5644               |        | O/C   |             |             |         |
| 340103<br>LEFT   | NAV CONTROL<br>CTL-32                | UNK  | 622-6521-013<br>11493        | MTH     | 30-Nov-2011<br>HRS 7583.1<br>LDG 6423 |        | O/C   |             |             |         |
| 340103<br>RIGHT  | NAV CONTROL<br>CTL-32                |      | 622-6521-013<br>3959         | MTH     | 21-Aug-1986                           |        | O/C   |             |             |         |
| 340105           | V-NAV CONTROL DISPLAY<br>VN-800      |      | 7000472-901<br>86120615      | MTH     | 06-Jun-2002<br>HRS 5465               |        | O/C   | 4668        |             |         |
| 340106<br>LEFT   | NAV ANTENNA                          |      | CI120-200G/S-L<br>SN-UNKNOWN | MTH     | 07-May-1998<br>HRS 4329               |        | O/C   |             |             |         |
| 340106<br>RIGHT  | NAV ANTENNA                          |      | CI120-200G/S-L<br>SN-UNKNOWN | MTH     | 07-May-1998<br>HRS 4329               |        | O/C   |             |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code             | Description                     | Part Number             | C/W Time 1                                | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-----------------------|---------------------------------|-------------------------|-------------------------------------------|--------|-------|-------|-------------|---------|
| Position              | Drawing # / Task #              | Part Serial No          | C/W Time 2                                | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 340107<br>COPILOT     | AIRSPD INDICATOR                | 9914062-3<br>184        | MTH 04-Feb-2003<br>HRS 5548               |        | O/C   | 80    |             |         |
| 340108<br>CENTER      | MFD EFIS DISPLAY                | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340108<br>LEFT NO. 1  | EFIS (ADI) DISPLAY<br>ED-600    | 7003430-901<br>85080575 | MTH 02-Dec-2004<br>HRS 6117               |        | O/C   | 1947  |             |         |
| 340108<br>LEFT NO. 2  | EFIS (HSI) DISPLAY<br>ED-600    | 7003430-901<br>85100601 | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340108<br>NO. 5       | EFIS DISPLAY                    | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340108<br>RIGHT NO. 1 | EFIS (ADI) DISPLAY<br>ED-600    | 7003430-901<br>84070348 | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   |       |             |         |
| 340108<br>RIGHT NO. 2 | EFIS (HSI) DISPLAY<br>ED-600    | 7003430-901<br>92112846 | MTH 20-Oct-2014<br>HRS 7940.2<br>LDG 6682 |        | O/C   |       |             |         |
| 340109<br>NO. 1       | EFIS CONTROLLER<br>DC-800       | 7003420-905<br>85080553 | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340109<br>NO. 2       | EFIS CONTROLLER<br>DC-800       | 7003420-905<br>86020627 | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340110<br>NO. 1       | EFIS GENERATOR<br>SG-601        | 7003400-912<br>84110467 | MTH 04-Aug-2004<br>HRS 6016               |        | O/C   | 211   |             |         |
| 340110<br>NO. 2       | EFIS GENERATOR<br>SG-601        | 7003400-912<br>85030520 | MTH 04-Aug-2004<br>HRS 6016               |        | O/C   | 6016  |             |         |
| 340111<br>LEFT        | SELECT CONTROL SENSOR<br>SC-800 | 7004123-511<br>85110677 | MTH 25-Aug-1986<br>HRS 13                 |        | O/C   |       |             |         |
| 340111<br>RIGHT       | SELECT CONTROL SENSOR<br>SC-800 | 7004123-511<br>85100633 | MTH 25-Aug-2004<br>HRS 6022               |        | O/C   | 3877  |             |         |
| 340118<br>NO. 1       | COMPUTER DISPLAY UNIT           | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340118<br>NO. 2       | COMPUTER DISPLAY UNIT           | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340130                | NAV INDICATOR<br>KI-204         | 066-03034-0022<br>20376 | MTH 30-Sep-1996<br>HRS 3700               |        | O/C   | 702   |             |         |
| 340138                | MFD CONTROLLER                  | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340152                | DATA INTERFACE UNIT             | 20110-1-03<br>1155      | MTH 21-Aug-1986                           |        | O/C   |       |             |         |
| 340153<br>NO. 1       | FLIGHT GUIDANCE COMPUTER        | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340153<br>NO. 2       | FLIGHT GUIDANCE COMPUTER        | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340155                | ALTITUDE PRESELECT              | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340156                | STANDBY AIRSPEED INDICATOR      | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340161<br>NO. 1       | ALTITUDE HEADING REFERENCE UNIT | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |
| 340161<br>NO. 2       | ALTITUDE HEADING REFERENCE UNIT | PN<br>SN-UNKNOWN        | MTH 21-Aug-1986                           |        | O/C   | 0     |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 340161                | AHRS TIMER                                                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340164<br>NO. 1       | RADAR CONTROLLER                                                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340166                | RMI SERVO AMP                                                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340167                | STANDBY HSI INDICATOR                                            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340168<br>NO. 2       | RADAR CONTROLLER                                                 |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340168                | ADAPTER CONTROL<br>CAD-62                                        |      |         | 622-6590-001<br>2464          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 340169                | FGC CONTROLLER                                                   |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340184                | MFD SYMBOL GENERATOR                                             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340188                | CHECKLIST                                                        |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340310                | POWER SUPPLY (PS 835 SERIES) STANDBY                             |      |         | GYRO<br>PN<br>SN-UNKNOWN      | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340311                | POWER SUPPLY (PS 835 SERIES) IF SECOND UNIT IS INSTALLED STANDBY |      |         | GYRO<br>PN<br>SN-UNKNOWN      | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 340320                | (AI-804AN) STANDBY GYRO                                          |      |         | 501-1197-14<br>3976           | MTH 10-Feb-1997<br>HRS 3833               |                | O/C            |                |                            |                    |
| 341000<br>LEFT        | VERTICAL SPEED INDICATOR                                         |      |         | C661006-0201<br>W14385H       | MTH 06-Jun-2002<br>HRS 5465               |                | O/C            | 5465           |                            |                    |
| 341000<br>RIGHT       | VERTICAL SPEED INDICATOR                                         |      |         | C661006-0201<br>W185054H      | MTH 06-Jun-2002<br>HRS 5465               |                | O/C            | 3591           |                            |                    |
| 341001<br>LEFT        | PITOT TUBE                                                       |      |         | PH502<br>NOV99                | MTH 30-May-2000<br>HRS 4869               |                | O/C            |                |                            |                    |
| 341001<br>RIGHT       | PITOT TUBE                                                       |      |         | PH502<br>NOV99                | MTH 30-May-2000<br>HRS 4869               |                | O/C            |                |                            |                    |
| 341004<br>PILOT       | MACH AIRSPEED INDICATOR<br>SI-225S                               |      | FXE     | 7005358-902<br>87010254       | MTH 18-Apr-2017<br>HRS 8352.2<br>LDG 6920 |                | O/C            |                |                            |                    |
| 341005<br>COPILOT     | MACH AIRSPEED INDICATOR                                          |      |         | 37230-001<br>300              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 341005                | OAT INDICATOR                                                    |      |         | C668510-0501<br>119           | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 341006                | GROUND PROXIMITY WARNING COMPUTER                                |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 342001                | MAGNETIC COMPASS --                                              |      |         | C660501-0301<br>SN-UNKNOWN    | MTH 13-Jul-2015<br>HRS 7940.2<br>LDG 6682 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 344027                | STORMSCOPE PROCESSOR                                             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 344028                | STORMSCOPE DISPLAY                                               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 344029                | WX-10 STORMSCOPE ANTENNA                                         |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code | Description                                                             | Part Number             | C/W Time 1        | Adj.                          | TBO 1 | TSO 1  | (ENG) DUE 1 | Remains |
|-----------|-------------------------------------------------------------------------|-------------------------|-------------------|-------------------------------|-------|--------|-------------|---------|
| Position  | Drawing # / Task # City Mod Lvl                                         | Part Serial No          | C/W Time 2        | + or -                        | TBO 2 | TSO 2  | (ENG) DUE 2 | Remains |
| 344030    | IHAS MULTI-HAZARD AWARENESS UNIT (KMH0820) IHAS SET<br>PN<br>SN-UNKNOWN | MTH                     | 21-Aug-1986       |                               | O/C   | 0      |             |         |
| 344031    | TCAS ANTENNA<br>BOTTOM                                                  | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |
| 344031    | TCAS ANTENNA<br>TOP                                                     | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |
| 344032    | TCAS PROCESSER<br>PN<br>SN-UNKNOWN                                      | MTH                     | 21-Aug-1986       |                               | O/C   | 0      |             |         |
| 344034    | TCAS PROCESSOR UNIT<br>TPU-67A CCS                                      | 066-01146-1211<br>40492 | MTH<br>HRS<br>LDG | 25-Oct-2016<br>8218.5<br>6824 | O/C   | 0<br>0 |             |         |
| 344039    | TAWS RMI<br>PN<br>SN-UNKNOWN                                            | MTH                     | 21-Aug-1986       |                               | O/C   | 0      |             |         |
| 344044    | TCAS VSI DISPLAY<br>LEFT IVA-81D                                        | 066-01171-2804<br>22213 | MTH<br>HRS        | 10-Jun-2004<br>5977           | O/C   |        |             |         |
| 344044    | TCAS VSI DISPLAY<br>RIGHT IVA-81D                                       | 066-01171-2804<br>22181 | MTH<br>HRS        | 10-Jun-2004<br>5977           | O/C   |        |             |         |
| 345001    | FLIGHT MANAGEMENT COMPUTER<br>NO. 1                                     | 1116-41-1116<br>1706    | MTH<br>HRS<br>LDG | 08-Dec-2023<br>8752.5<br>7224 | O/C   |        |             |         |
| 345001    | FLIGHT MANAGEMENT COMPUTER<br>NO. 2                                     | 1116-41-1116<br>375     | MTH<br>HRS        | 23-Aug-2003<br>5697           | O/C   |        |             |         |
| 345002    | FMS MANAGEMENT DISPLAY UNIT<br>NO. 1                                    | 1117-21<br>2066         | MTH<br>HRS        | 28-Jun-2000<br>4869           | O/C   |        |             |         |
| 345002    | FMS MANAGEMENT DISPLAY UNIT<br>NO. 2                                    | 1117-21<br>328          | MTH<br>HRS        | 28-Jun-2000<br>4869           | O/C   |        |             |         |
| 345003    | OMEGA RPU SENSOR<br>NO. 1                                               | 30050-02-02<br>306      | MTH               | 21-Aug-1986                   | O/C   |        |             |         |
| 345003    | OMEGA RPU SENSOR<br>NO. 2                                               | 30050-02-02<br>423      | MTH<br>HRS        | 26-Apr-1988<br>749            | O/C   |        |             |         |
| 345004    | (CMU-GNSX) CONFIGURATION MODULE<br>NO. 1 CMU-GNSX                       | 31990-1<br>342          | MTH               | 21-Aug-1986                   | O/C   |        |             |         |
| 345004    | (CMU-GNSX) CONFIGURATION MODULE<br>NO. 2 CMU-GNSX                       | 31990-1<br>8028         | MTH<br>HRS        | 02-Sep-1998<br>4462           | O/C   |        |             |         |
| 345004    | (CMU-GNSX) CONFIGURATION MODULE<br>NO. 3                                | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |
| 345004    | TCAS CONFIGURATION MODULE<br>TOP                                        | 071-00097-1000<br>3513  | MTH<br>HRS        | 27-Sep-2002<br>5468           | O/C   |        |             |         |
| 345004    | EGPWC CONFIGURATION MODULE<br>PN<br>SN-UNKNOWN                          | MTH                     | 21-Aug-1986       |                               | O/C   | 0      |             |         |
| 345009    | AFIS DMU<br>NO. 1                                                       | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |
| 345010    | AFIS DTU<br>NO. 1                                                       | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |
| 345012    | AFIS ANTENNA<br>NO. 1                                                   | PN<br>SN-UNKNOWN        | MTH               | 21-Aug-1986                   | O/C   | 0      |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position         | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 345027<br>NO. 1               | GPS ANTENNA<br>ANTENNA            |      |         | 10706<br>5978                 | MTH 28-Jun-2000<br>HRS 4869               |                | O/C            |                |                            |                    |
| 345027<br>NO. 2               | GPS ANTENNA                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345031                        | DTU AFIS DISK DRIVE               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345039                        | -- DTU                            |      |         | 1406-01-1<br>339              | MTH 27-Sep-2002<br>HRS 5468               |                | O/C            |                |                            |                    |
| 345080<br>NO. 1               | GNS-XLS FMS                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345080<br>NO. 2               | GNS-XLS FMS                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345082<br>NO. 1               | UNS-1C ANTENNA                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345082<br>NO. 2               | UNS-1C ANTENNA                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 345202                        | TCAS TRANSPONDER CONTROL          |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 350002                        | OXYGEN VALVE                      |      |         | 9914067-19<br>72              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 350003                        | ALTITUDE OXYGEN SWITCH            |      |         | 9912057-5<br>221              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 350006                        | OXYGEN PRESSURE GAUGE<br>MD-98    |      |         | C668512-0201<br>6020          | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 351004<br>PASSENGER           | OXYGEN MASK                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 351005<br>PILOT               | OXYGEN MASK<br>9914067-41         |      |         | MC10-15-109<br>46947          | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 72             | 5<br>0<br>0    | 31-Jan-2027                | 24 m 1 d           |
| 351010<br>COPILOT             | OXYGEN MASK<br>9914067-41         |      |         | MC10-16-101<br>93581          | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | 72             | 3<br>0<br>0    | 31-Mar-2027                | 26 m 1 d           |
| 352000                        | OXYGEN CYLINDER                   |      |         | 895-20077<br>ALT281-32980     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | 180            | 19             | 28-Feb-2030                | 60 m 29 d          |
| Manufacture Date: 28-Feb-2015 |                                   |      |         |                               |                                           |                |                |                |                            |                    |
| 352005<br>PORTABLE            | OXYGEN CYLINDER                   |      |         | 5500-M6W-FF23AP<br>158060     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | O/C            |                |                            |                    |
| 361000<br>NO. 1               | REGULATOR                         |      |         | 9914133-2<br>SN-UNKNOWN       | MTH 10-Oct-1999<br>HRS 4798               |                | O/C            |                |                            |                    |
| 361001<br>LEFT                | PILOT VALVE                       |      |         | 9914126-4<br>618B             | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 361001<br>RIGHT               | PILOT VALVE                       |      |         | 9914126-4<br>10ABCD           | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |
| 361002<br>LEFT                | SLAVE VALVE                       | UNK  |         | 6214507-1<br>NSN              | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 361002<br>RIGHT               | SLAVE VALVE                       |      |         | 9914126-8<br>85ACD            | MTH 15-May-1995<br>HRS 3168               |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                | Description                                      | Part Number              | C/W Time 1                                         | Adj.   | TBO 1      | TSO 1       | (ENG) DUE 1           | Remains             |
|--------------------------|--------------------------------------------------|--------------------------|----------------------------------------------------|--------|------------|-------------|-----------------------|---------------------|
| Position                 | Drawing # / Task #                               | Part Serial No           | C/W Time 2                                         | + or - | TBO 2      | TSO 2       | (ENG) DUE 2           | Remains             |
| 361003<br>LEFT           | PRECOOLER<br>UNK                                 | 9914126-7<br>0625        | MTH<br>HRS<br>LDG<br>24-Oct-2011<br>7545.3<br>6400 |        | O/C        |             |                       |                     |
| 361003<br>RIGHT          | PRECOOLER                                        | 9914126-7<br>0639        | MTH<br>HRS<br>11-Sep-2006<br>6481                  |        | O/C        |             |                       |                     |
| 361004<br>LEFT           | DIFFERENTIAL PRESSURE SWITCH                     | 1163P22<br>773           | MTH<br>HRS<br>19-Dec-2002<br>5483                  |        | O/C        |             |                       |                     |
| 361004<br>RIGHT          | DIFFERENTIAL PRESSURE SWITCH                     | 1163P22-1<br>0255        | MTH<br>HRS<br>07-Jan-2003<br>5514                  |        | O/C        |             |                       |                     |
| 361005<br>LEFT           | TEMP SENSOR                                      | 9914149-2<br>197         | MTH<br>21-Aug-1986                                 |        | O/C        |             |                       |                     |
| 361005<br>RIGHT          | TEMP SENSOR                                      | PN<br>SN-UNKNOWN         | MTH<br>21-Aug-1986                                 |        | O/C        | 0           |                       |                     |
| 361006<br>LEFT AFT       | SERVICE AIR CHECK VALVE                          | 9914171-1<br>1406        | MTH<br>HRS<br>02-Sep-1998<br>4462                  |        | O/C        |             |                       |                     |
| 361006<br>RIGHT AFT      | SERVICE AIR CHECK VALVE                          | 9914171-1<br>365         | MTH<br>HRS<br>12-Nov-1986<br>101                   |        | O/C        |             |                       |                     |
| 361007<br>LEFT           | HIGH PRESSURE SHUTOFF VALVE                      | 9914124-2<br>SN-UNKNOWN  | MTH<br>21-Aug-1986                                 |        | O/C        |             |                       |                     |
| 361007<br>RIGHT          | HIGH PRESSURE SHUTOFF VALVE                      | 9914124-2<br>1301        | MTH<br>HRS<br>28-Dec-1998<br>4585                  |        | O/C        |             |                       |                     |
| 361008<br>LEFT           | LOW PRESSURE SHUTOFF VALVE                       | PN<br>SN-UNKNOWN         | MTH<br>21-Aug-1986                                 |        | O/C        | 0           |                       |                     |
| 361008<br>RIGHT          | LOW PRESSURE SHUTOFF VALVE                       | PN<br>SN-UNKNOWN         | MTH<br>21-Aug-1986                                 |        | O/C        | 0           |                       |                     |
| 361009<br>LEFT INBOARD   | TEE ASSY                                         | 6214561-19<br>SN-UNKNOWN | MTH<br>21-Aug-1986                                 |        | O/C        |             |                       |                     |
| 361009<br>RIGHT INBOARD  | TEE ASSY                                         | 6214561-20<br>SN-UNKNOWN | MTH<br>HRS<br>25-Sep-2002<br>5468                  |        | O/C        |             |                       |                     |
| 361010<br>LEFT OUTBOARD  | TEE ASSY                                         | 6214561-21<br>SN-UNKNOWN | MTH<br>21-Aug-1986                                 |        | O/C        |             |                       |                     |
| 361010<br>RIGHT OUTBOARD | TEE ASSY                                         | 6214561-22<br>SN-UNKNOWN | MTH<br>21-Aug-1986                                 |        | O/C        |             |                       |                     |
| 361011<br>LEFT           | PRESSURE BULKHEAD CHECK VALVE                    | PN<br>SN-UNKNOWN         | MTH<br>21-Aug-1986                                 |        | O/C        | 0           |                       |                     |
| 361020                   | CABIN ENTRY DOOR PNEUMATIC SEAL FILTER - DISCARD | 050-05BX<br>NSN          | MTH<br>HRS<br>LDG<br>23-Sep-2021<br>8735.3<br>7213 |        | 36<br>1200 | 0<br>0<br>0 | 30-Sep-2024<br>9935.3 | -4 m -1 d<br>1161.4 |
|                          |                                                  |                          |                                                    |        |            |             |                       | Over Due            |
| 371001                   | VAC EJECT VALVE                                  | PN<br>SN-UNKNOWN         | MTH<br>21-Aug-1986                                 |        | O/C        | 0           |                       |                     |
| 383001                   | TOILET PUMP                                      | 17000-82<br>1099         | MTH<br>HRS<br>30-Aug-1988<br>945                   |        | O/C        |             |                       |                     |
| 49APU1                   | APU<br>9914283-1                                 | 160371-200<br>867401     | MTH<br>HRS<br>LDG<br>05-Jun-2021<br>8735.3<br>7213 |        | E/C        | 2166.5      |                       |                     |
| 490004<br>APU            | FUEL PUMP-APU MOUNTD --<br>MCO                   | 104030-2<br>28732435     | 06-Aug-1996                                        |        | O/C        |             |                       |                     |
| 490035                   | APU OIL COOLER --<br>*CF                         | 8406R<br>2235            | 28-Sep-1986                                        |        | O/C        |             |                       |                     |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position   | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 490041                  | OIL TEMP SWITCH --                | LNK  |         | 160260-3<br>197007            | APUH 22-Oct-2003<br>1461                |                | O/C            | 0              |                            |                    |
| 490050<br>APU           | START FLW RESTRICTOR --           | LNK  |         | 179290-1<br>SN-UNKNOWN        | APUH 16-Mar-2012<br>APUS 1992.1<br>4224 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 490057                  | APU ACCELERATION CONTROL --       | LNK  |         | 4500873<br>119339             | APUH 22-Oct-2003<br>1461                |                | O/C            | 1460           |                            |                    |
| 491010<br>490032        | TURBINE ROTOR                     | LNK  |         | 167222-1<br>1653724C          | APUH 22-Oct-2003<br>APUS 1461<br>3668   |                | 9000           | 337            | 12331                      | 7536               |
| 491020<br>490031        | COMPRESSOR ROTOR                  | LNK  |         | 167200-1<br>V62C8679          | APUH 22-Oct-2003<br>APUS 1461<br>3668   |                | 6000           | 3287           | 6381                       | 1586               |
| 491026<br>490006        | ACTUATOR                          | MCO  |         | 114600-5<br>28                | 06-Aug-1996                             |                | O/C            |                |                            |                    |
| 491029<br>490010        | S/G CONTROL UNIT                  | LNK  |         | 51539-006D<br>3876AB          | 01-Apr-2011                             |                | O/C            |                |                            |                    |
| 491032<br>490013        | START COUNTER                     | ATW  |         | 104026-1<br>SN-UNKNOWN        | APUH 17-Oct-2003<br>1460                |                | O/C            | 1461           |                            |                    |
| 491034<br>490015        | EXHAUST FAN                       | MCO  |         | 2100904-4<br>305              | 06-Aug-1996                             |                | O/C            |                |                            |                    |
| 491055<br>494001 : BATT | BATTERY PACK                      | LNK  |         | 6238004-9<br>7089DA           | APUH 13-Apr-2017<br>APUS 2105.4<br>4698 |                | O/C            |                |                            |                    |
| 491056<br>498101        | BLOWER ASSY.<br>9910113-5         | UNK  |         | 76310-5<br>1197               | 23-May-2024                             |                | O/C            |                |                            |                    |
| 491058<br>490003        | FIRE CONTROL UNIT                 | *CF  |         | 377-02836<br>85170424         | 28-Sep-1986                             |                | O/C            |                |                            |                    |
| 491059<br>490007B       | STARTER GENERATOR BEARINGS        | MCO  |         | 03-6010-18<br>SN-UNKNOWN      | 06-Aug-1996                             |                | O/C            |                |                            |                    |
| 491060<br>490011        | DC AMMETER                        | ATW  |         | 115.179-4<br>86040084         | APUH 17-Oct-2003<br>1460                |                | O/C            | 1461           |                            |                    |
| 491061<br>490058        | COMBUSTION CHAMBER LINER          | LNK  |         | 171924-100<br>G93008          | APUH 22-Oct-2003<br>1461                |                | O/C            | 1460           |                            |                    |
| 493080<br>492800        | FUEL START NOZZLE                 | LNK  |         | 169046-1<br>NSN               | APUH 15-Jun-2016<br>2052.2              |                | O/C            | 0<br>0         |                            |                    |
| 493090<br>490036        | START BYPASS VALVE                | ATW  |         | 160360-4<br>189               | APUH 17-Oct-2003<br>1460                |                | O/C            | 1035           |                            |                    |
| 494020<br>490124        | IGNITER PLUG                      | LNK  |         | FHE159-6<br>SN-UNKNOWN        | APUH 22-Oct-2003<br>1461                |                | O/C            | 1460           |                            |                    |
| 496010<br>490009        | ELECTRONIC SEQUENCE UNIT          | LNK  |         | 161043-500<br>75840084        | APUH 29-Mar-2008<br>1790                |                | O/C            | 1325           |                            |                    |
| 497020<br>490012        | HOURLMETER                        | MCO  |         | 169096-1<br>SN-UNKNOWN        | 06-Aug-1996                             |                | O/C            |                |                            |                    |
| 521001<br>CABIN         | DOOR<br>6211266                   |      |         | 6211266-32<br>SN-UNKNOWN      | MTH 21-Aug-1986                         |                | O/C            |                |                            |                    |
| 521002                  | DOOR SEAL PRESSURE SWITCH         |      |         | P18M30<br>SN-UNKNOWN          | MTH 21-Aug-1986                         |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position    | Description<br>Drawing # / Task #       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------|-----------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 521003                   | CABIN DOOR INF SEAL                     |      |         | 9914195-4<br>NSN              | MTH 07-Mar-2008<br>HRS 6805 |                | O/C            |                |                            |                    |
| 521004                   | CABIN DOOR SECONDARY SEAL               |      |         | 9914294-2<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 521005                   | MAIN DOOR SEAL VALVE                    |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 521006                   | CABIN DOOR SEAL VALVE                   |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 522001                   | EMERGENCY DOOR<br>6211250-25            |      |         | 6211250-25<br>SN-UNKNOWN      | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 522002                   | EMERGENCY DOOR SEAL<br>6211250-10       |      |         | CM2002<br>SN-UNKNOWN          | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 522010<br>FORWARD        | SIDE UPPER CABIN DOOR PIN               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 527001<br>AFT            | CABIN DOOR LOCK SWITCH                  |      |         | BZ2R-A2<br>SN-UNKNOWN         | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527001<br>FORWARD        | CABIN DOOR LOCK SWITCH                  |      |         | BZ2R-A2<br>SN-UNKNOWN         | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527002                   | CABIN DOOR LATCH SWITCH                 |      |         | 8-405-04<br>B52654            | MTH 10-Apr-2003<br>HRS 5600 |                | O/C            |                |                            |                    |
| 527003                   | CABIN DOOR PRECATCH SWITCH              |      |         | B7070<br>SN-UNKNOWN           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527004                   | CABIN DOOR SEAL MON SWITCH              |      |         | A4-6-270<br>SN-UNKNOWN        | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527005<br>LEFT           | NOSE BAGGAGE DOOR SWITCH<br>MS24547-1   |      |         | 21SX39T<br>SN-UNKNOWN         | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527005<br>RIGHT          | NOSE BAGGAGE DOOR SWITCH<br>MS24547-1   |      |         | 21SX39T<br>SN-UNKNOWN         | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527006                   | REFUELING DOOR SWITCH                   |      |         | 602EN602-6<br>SN-UNKNOWN      | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527007                   | AFT BAGGAGE DOOR SWITCH                 |      |         | B7070<br>SN-UNKNOWN           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527008                   | TAILCONE DOOR SWITCH                    |      |         | B7070<br>SN-UNKNOWN           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 527009<br>LEFT INBOARD   | DOOR LATCH MONITOR SWITCH               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 527009<br>LEFT OUTBOARD  | DOOR LATCH MONITOR SWITCH               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 527009<br>RIGHT INBOARD  | DOOR LATCH MONITOR SWITCH               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 527009<br>RIGHT OUTBOARD | DOOR LATCH MONITOR SWITCH               |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 530000                   | RADOME                                  |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 540000<br>LEFT           | ENGINE INLET                            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 540000<br>RIGHT          | ENGINE INLET                            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 561001<br>COPILOT        | INNER WINDOW                            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 561002<br>COPILOT        | OUTER WINDOW                            |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT FORWARD   | FLIGHT COMPARTMENT WINDOW<br>9914072-17 |      |         | 9914072-17<br>85H77197        | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 561002<br>RIGHT FORWARD  | FLIGHT COMPARTMENT WINDOW<br>9914072-18 |      |         | 9914072-18<br>5H915013        | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                | Description                               | Part Number                | C/W Time 1                  | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|--------------------------|-------------------------------------------|----------------------------|-----------------------------|--------|-------|-------|-------------|---------|
| Position                 | Drawing # / Task # City Mod Lvl           | Part Serial No             | C/W Time 2                  | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 561003<br>LEFT AFT       | FLIGHT COMPARTMENT WINDOW<br>9914116-33   | 9914116-33<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 561003<br>PILOT          | FOUL WEATHER WINDOW<br>9914116-34         | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 561003<br>RIGHT AFT      | FLIGHT COMPARTMENT WINDOW<br>9914116-34   | 9914116-34<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 561004<br>PILOT          | INNER WINDOW<br>9914116-34                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 561005<br>PILOT          | OUTER WINDOW<br>9914116-34                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 561031<br>LEFT MAIN      | WINDSHIELD ASSY, (LH)<br>9914071-47       | 9914071-47<br>97357H3968   | MTH 02-Sep-1998<br>HRS 4462 |        | O/C   |       |             |         |
| 561032<br>RIGHT MAIN     | WINDSHIELD ASSY, (LH)<br>9914071-48       | 9914071-48<br>85H77113     | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562001                   | CABIN EMERGENCY DOOR WINDOW<br>9914159-12 | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 562002<br>COPILOT        | FOUL WEATHER WINDOW<br>9914159-12         | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 562003<br>NO. 1 LEFT     | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562004<br>NO. 1 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562005<br>NO. 2 LEFT     | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562006<br>NO. 2 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562007<br>NO. 3 LEFT     | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562008<br>NO. 3 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562009<br>NO. 4 LEFT     | CABIN WINDOW<br>9914159-12                | 9914159-12<br>1238         | MTH 11-Sep-2006<br>HRS 6481 |        | O/C   |       |             |         |
| 562010<br>NO. 4 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562011<br>NO. 5 LEFT     | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562012<br>NO. 5 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 562013<br>NO. 6 LEFT     | CABIN WINDOW<br>9914159-12                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 562014<br>NO. 6 RIGHT    | CABIN WINDOW<br>9914159-12                | 9914159-12<br>SN-UNKNOWN   | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 575101<br>LEFT CENTER    | FLAP ASSEMBLY<br>6225120-7                | 6225120-7<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 575101<br>LEFT OUTBOARD  | FLAP ASSEMBLY<br>6225120-8                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 575101<br>RIGHT CENTER   | FLAP ASSEMBLY<br>6225120-8                | 6225120-8<br>SN-UNKNOWN    | MTH 21-Aug-1986             |        | O/C   |       |             |         |
| 575101<br>RIGHT OUTBOARD | FLAP ASSEMBLY<br>6225120-8                | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986             |        | O/C   | 0     |             |         |
| 575110<br>L2             | LEADING EDGE<br>6214423-8469              | 6214423-8469<br>SN-UNKNOWN | MTH 02-Sep-1998<br>HRS 4462 |        | O/C   |       |             |         |
| 711000<br>LEFT ENGINE    | FORWARD MOUNT<br>6251100-7                | 6251100-7<br>SN-UNKNOWN    | MTH 21-Aug-1986<br>HRS 0    |        |       | 0     | 21000       | 12226.1 |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code                                  | Description                                         | Part Number                | C/W Time 1                                 | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains  |
|--------------------------------------------|-----------------------------------------------------|----------------------------|--------------------------------------------|--------|-------|-------|-------------|----------|
| Position                                   | Drawing # / Task # City Mod Lvl                     | Part Serial No             | C/W Time 2                                 | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains  |
| 711007<br>LEFT FORWARD                     | ENGINE MOUNT TO BEAM UPPER AND LOWER (4 EACH) BOLTS | NAS6706HU18<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 711008<br>LEFT FORWARD                     | CENTER MOUNT TO BEAM (4 EACH) BOLTS                 | NAS6706HU12<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 711009<br>LEFT BOTTOM                      | AFT MOUNT TO BEAM ATTACH BOLTS<br>LSZH              | NAS6708DU27<br>NSN         | MTH 26-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 21000 | 0     | 25549.12    | 16775.22 |
| 711009<br>LEFT ENGINE                      | AFT MOUNT (ENGINE TO MOUNT) ATTACHMENT BOLTS        | NAS6705DU10<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 711009<br>LEFT TOP                         | AFT MOUNT TO BEAM ATTACH BOLTS<br>LSZH              | NAS6708DU27<br>NSN         | MTH 26-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 21000 | 0     | 25549.12    | 16775.22 |
| 711015<br>LEFT ENGINE                      | AFT MOUNT                                           | 625-1200-8-1<br>SN-UNKNOWN | MTH 28-Nov-1998<br>HRS 4549                |        | 21000 | 0     | 25549       | 16775.1  |
| 711030<br>LEFT ENGINE                      | FORWARD UPPER ISOLATOR                              | 9914086-9<br>714           | MTH 28-Nov-1998<br>HRS 4549                |        | 5950  | 0     | 10499       | 1725.1   |
| 711035<br>LEFT ENGINE                      | FORWARD LOWER ISOLATOR                              | 9914086-10<br>794          | MTH 28-Nov-1998<br>HRS 4549                |        | 5950  | 0     | 10499       | 1725.1   |
| 711040<br>LEFT ENGINE<br>FORWARD TOP       | LEFT ENGINE FORWARD TOP ISOLATOR TENSION BOLT       | NAS6706DU38<br>SN-UNKNOWN  | MTH 28-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 5950  | 0     | 10499.12    | 1725.22  |
| 711041<br>LEFT ENGINE<br>FORWARD<br>BOTTOM | LEFT ENGINE FORWARD BOTTOM ISOLATOR TENSION BOLT    | NAS6706DU38<br>SN-UNKNOWN  | MTH 28-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 5950  | 0     | 10499.12    | 1725.22  |
| 711045<br>LEFT BOTTOM                      | AFT ISOLATOR                                        | 9914086-8<br>SN-UNKNOWN    | MTH 28-Nov-1998<br>HRS 4549                |        | O/C   |       |             |          |
| 711050<br>LEFT TOP                         | AFT ISOLATOR                                        | 9914086-7<br>SN-UNKNOWN    | MTH 28-Nov-1998<br>HRS 4549                |        | O/C   |       |             |          |
| 712000<br>RIGHT ENGINE                     | FORWARD MOUNT                                       | 6251100-7<br>SN-UNKNOWN    | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 712007<br>RIGHT FORWARD                    | ENGINE MOUNT TO BEAM UPPER AND LOWER (4 EACH) BOLTS | NAS6706HU18<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 712008<br>RIGHT FORWARD                    | CENTER MOUNT TO BEAM (4 EACH) BOLTS                 | NAS6706HU12<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 712009<br>RIGHT BOTTOM                     | AFT MOUNT TO BEAM ATTACH BOLTS<br>LSZH              | NAS6708DU27<br>NSN         | MTH 26-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 21000 | 0     | 25549.12    | 16775.22 |
| 712009<br>RIGHT ENGINE                     | AFT MOUNT (ENGINE TO MOUNT) ATTACHMENT BOLTS        | NAS6705DU10<br>SN-UNKNOWN  | MTH 21-Aug-1986<br>HRS 0                   |        | 21000 | 0     | 21000       | 12226.1  |
| 712009<br>RIGHT TOP                        | AFT MOUNT TO BEAM ATTACH BOLTS<br>LSZH              | NAS6708DU27<br>NSN         | MTH 26-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 21000 | 0     | 25549.12    | 16775.22 |
| 712015<br>RIGHT ENGINE                     | AFT MOUNT                                           | 6251200-8-1<br>SN-UNKNOWN  | MTH 28-Nov-1998<br>HRS 4549                |        | 21000 | 0     | 25549       | 16775.1  |
| 712030<br>RIGHT ENGINE                     | FORWARD UPPER ISOLATOR                              | 9914086-9<br>708           | MTH 28-Nov-1998<br>HRS 4549                |        | 5950  | 0     | 10499       | 1725.1   |
| 712035<br>RIGHT ENGINE                     | FORWARD LOWER ISOLATOR                              | 9914086-10<br>811          | MTH 28-Nov-1998<br>HRS 4549                |        | 5950  | 0     | 10499       | 1725.1   |
| 712040<br>RIGHT ENGINE<br>FORWARD TOP      | RIGHT ENGINE FORWARD TOP ISOLATOR TENSION BOLT      | NAS6706DU38<br>SN-UNKNOWN  | MTH 28-Nov-1998<br>HRS 4549.12<br>LDG 4346 |        | 5950  | 0     | 10499.12    | 1725.22  |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position                       | Description<br>Drawing # / Task #                 | City | Mod Lvl | Part Number<br>Part Serial No                | C/W Time 1<br>C/W Time 2       | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------|---------------------------------------------------|------|---------|----------------------------------------------|--------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 712041<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM | RIGHT ENGINE FORWARD BOTTOM ISOLATOR TENSION BOLT |      |         | NAS6706DU38<br>MTH<br>HRS<br>LDG             | 28-Nov-1998<br>4549.12<br>4346 |                |                | 0<br>0<br>0    | 10499.12                   | 1725.22            |
| 712045<br>RIGHT BOTTOM                      | AFT ISOLATOR                                      |      |         | 9914086-8<br>SN-UNKNOWN<br>MTH<br>HRS        | 28-Nov-1998<br>4549            |                | O/C            |                |                            |                    |
| 712050<br>RIGHT TOP                         | AFT ISOLATOR                                      |      |         | 9914086-7<br>SN-UNKNOWN<br>MTH<br>HRS        | 28-Nov-1998<br>4549            |                | O/C            |                |                            |                    |
| 71EN1<br>NO. 1                              | ENGINE                                            |      |         | 3074080-2<br>P-87323<br>MTH<br>HRS<br>LDG    | 21-Oct-2011<br>7545.3<br>6400  |                | E/C            | 7368.4         |                            |                    |
| 71EN2<br>NO. 2                              | ENGINE                                            |      |         | 3074080-2<br>P-87322<br>MTH<br>HRS<br>LDG    | 21-Oct-2011<br>7545.3<br>6400  |                | E/C            | 7355.6         |                            |                    |
| 720009A<br>E1                               | -- HP TURBIN ROTOR BLDS                           |      |         | 3074785-6<br>SN-UNKNOWN<br>MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111  |                | O/C            | 3491           |                            |                    |
| 720009A<br>E2                               | -- HP TURBIN ROTOR BLDS                           |      |         | 3074785-6<br>SN-UNKNOWN<br>MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113  |                | O/C            | 2106           |                            |                    |
| 720016<br>E1                                | -- TURBINE ASSY-LO PRES                           |      |         | 3072849-2<br>P342<br>MTH<br>HRS<br>LDG       | 25-Sep-2002<br>5466.4<br>5111  |                | O/C            | 5289.5         |                            |                    |
| 720016<br>E2                                | -- TURBINE ASSY-LO PRES                           |      |         | 3072849-2<br>P341<br>MTH<br>HRS<br>LDG       | 25-Sep-2002<br>5463.2<br>5113  |                | O/C            | 5273.5         |                            |                    |
| 720024<br>E1                                | -- VALVE                                          |      |         | 158465-6<br>544442<br>MTH<br>HRS<br>LDG      | 25-Sep-2002<br>5466.4<br>5111  |                | O/C            | 5289.5         |                            |                    |
| 720024<br>E2                                | -- VALVE                                          |      |         | 158465-6<br>1144679<br>MTH<br>HRS<br>LDG     | 25-Sep-2002<br>5463.2<br>5113  |                | O/C            | 5273.5         |                            |                    |
| 720027<br>E1                                | -- OUTER TRANS LINER                              |      |         | 3077022-5<br>SN-UNKNOWN<br>MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111  |                | O/C            | 5289.5         |                            |                    |
| 720027<br>E2                                | -- OUTER TRANS LINER                              |      |         | 3077022-5<br>SN-UNKNOWN<br>MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113  |                | O/C            | 5273.5         |                            |                    |
| 720035<br>E1                                | -- GEAR ASSY-PLANET                               |      |         | 3072178-10<br>SN-UNKNOWN<br>MTH              | 21-Aug-1986                    |                | O/C            |                |                            |                    |
| 720035<br>E2                                | -- GEAR ASSY-PLANET                               |      |         | 3072178-10<br>SN-UNKNOWN<br>MTH              | 21-Aug-1986                    |                | O/C            |                |                            |                    |
| 720037<br>E1                                | -- SHAFT & FAN HSG ASSY                           |      |         | 3072715-3<br>SN-UNKNOWN<br>MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111  |                | O/C            | 5289.5         |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code    | Description                     | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|--------------|---------------------------------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position     | Drawing # / Task # City Mod Lvl | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 720037<br>E2 | -- SHAFT & FAN HSG ASSY         | 3072715-3<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 720039<br>E1 | -- FUEL-OIL THERMOSTAT          | 157795-6<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720039<br>E2 | -- FUEL-OIL THERMOSTAT          | 157795-6<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720040<br>E1 | -- AIR-OIL THERMOSTAT           | 157231-5<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720040<br>E2 | -- AIR-OIL THERMOSTAT           | 157231-5<br>SN-UNKNOWN     | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720077<br>E1 | -- POWER SECTION                | 3073402-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720077<br>E2 | -- POWER SECTION                | 3073402-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720078<br>E1 | -- HARNESS ENGINE               | 3070994-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720078<br>E2 | -- HARNESS ENGINE               | 3070994-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720079<br>E1 | -- HARNESS COMPUTER             | 3070991-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720079<br>E2 | -- HARNESS COMPUTER             | 3070991-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720083<br>E1 | -- OIL TANK                     | 3071845-5<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5468        |             |         |
| 720083<br>E2 | -- OIL TANK                     | 3071845-5<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 720090<br>E1 | -- INLET SENSOR PT2             | 3070816-4<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720090<br>E2 | -- INLET SENSOR PT2             | 3070816-4<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720091<br>E1 | -- INSTL KIT FUEL SYS           | 3070912-1<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720091<br>E2 | -- INSTL KIT FUEL SYS           | 3070912-1<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720100<br>E1 | -- LEAD ASSY ITT UNK            | 3073950-7<br>1015027700129 | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 720100<br>E2 | -- LEAD ASSY ITT                | 3073950-2<br>SN-UNKNOWN    | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 720101<br>E1 | -- HP SHAFT AFT CPLG            | 3072834-4<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289.5      |             |         |
| 720101<br>E2 | -- HP SHAFT AFT CPLG            | 3072834-4<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 720102<br>E1 | -- V SEAL RING                  | 3000001-27<br>SN-UNKNOWN   | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289.5      |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 720102<br>E2          | -- V SEAL RING                         |      |         | 3000001-27<br>SN-UNKNOWN      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 5273.5         |                            |                    |
| 720103<br>E1          | -- COMBUSTOR                           | UNK  |         | 3073774-2<br>99P25940         | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 720103<br>E2          | -- COMBUSTOR                           | UNK  |         | 3073774-2<br>97P12507         | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 724110<br>E1          | COMBUSTION PLENUM CASE                 |      |         | 3072443-5<br>21511017         | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | O/C            | 4901           |                            |                    |
| 724110<br>E2          | COMBUSTION PLENUM CASE                 |      |         | 3072443-5<br>21511060         | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 4810           |                            |                    |
| 725010<br>E1          | STAGE 1 LOW PRESSURE TURBINE DISC      |      |         | 3074078-2<br>4032292709       | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 10000          | 1908           | (12992)13203               | 5969               |
| 725010<br>E2          | STAGE 1 LOW PRESSURE TURBINE DISC      |      |         | 3074078-2<br>4032292714       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 10000          | 1918           | (12892)13195               | 5961               |
| 725020<br>E1          | STAGE 2 LOW PRESSURE TURBINE DISC      |      |         | 3074079-2<br>4032293577       | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 10000          | 1908           | (12992)13203               | 5969               |
| 725020<br>E2          | STAGE 2 LOW PRESSURE TURBINE DISC      |      |         | 3074079-2<br>4032297738       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 10000          | 1918           | (12892)13195               | 5961               |
| 725030<br>E1          | STAGE 3 LOW PRESSURE TURBINE DISC      |      |         | 3074097-1<br>423315962        | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 7000           | 1908           | (9992)10203                | 2969               |
| 725030<br>E2          | STAGE 3 LOW PRESSURE TURBINE DISC      |      |         | 3074097-1<br>412172166        | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 7000           | 1918           | (9892)10195                | 2961               |
| 725040<br>E1          | HIGH PRESSURE TURBINE DISC             |      |         | 3074786-9<br>81217200268      | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 10000          | 756            | (14144)14355               | 7121               |
| 725040<br>E2          | HIGH PRESSURE TURBINE DISC             |      |         | 3074786-9<br>81217200169      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 10000          | 4810           | (10000)10303               | 3069               |
| 725045<br>E1          | HIGH PRESSURE ROTOR STEPPED SEAL PLATE |      |         | 3072827<br>4031601774         | MTH 21-Aug-1986<br>LDG 211                |                | 10000          | 0              | (10000)10211               | 2977               |
| 725045<br>E2          | HIGH PRESSURE ROTOR STEPPED SEAL PLATE |      |         | 3072827-3<br>4031601793       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 10000          | 0<br>0<br>4810 | (10000)10303               | 3069               |
| 725050<br>E1          | FAN ROTOR DISC                         |      |         | 3073604-1<br>20322900437      | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 10000          | 0<br>0<br>0    | (14900)15111               | 7877               |
| 725050<br>E2          | FAN ROTOR DISC                         |      |         | 3073604-1<br>10322905859      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | 10000          | 0<br>0<br>0    | (14810)15113               | 7879               |
| 725060<br>E1          | STAGE 1 LOW PRESSURE COMPRESSOR DISC   |      |         | 3070440-11<br>31602420        | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | 10000          | 4901           | (9999)10210                | 2976               |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code    | Description                                                      | Part Number       | C/W Time 1                    | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1  | Remains |
|--------------|------------------------------------------------------------------|-------------------|-------------------------------|--------|-------|-------------|--------------|---------|
| Position     | Drawing # / Task # City Mod Lvl Part Serial No                   | Part Serial No    | C/W Time 2                    | + or - | TBO 2 | TSO 2       | (ENG) DUE 2  | Remains |
| 725060<br>E2 | STAGE 1 LOW PRESSURE COMPRESSOR DISC<br>3070440-11<br>31602397   | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 10000 | 4810        | (10000)10303 | 3069    |
| 725070<br>E1 | STAGE 2 LOW PRESSURE COMPRESSOR DISC<br>3072416-10<br>4121121159 | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 10000 | 4901        | (9999)10210  | 2976    |
| 725070<br>E2 | STAGE 2 LOW PRESSURE COMPRESSOR DISC<br>3072416-10<br>4121122864 | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 10000 | 4810        | (10000)10303 | 3069    |
| 725071<br>E1 | COMBUSTION LINER<br>3073774-2<br>5P-1017                         | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | O/C   | 0<br>0<br>0 |              |         |
| 725071<br>E2 | COMBUSTION LINER<br>PN<br>SN-UNKNOWN                             | MTH               | 21-Aug-1986                   |        | O/C   | 0           |              |         |
| 725080<br>E1 | STAGE 3 LOW PRESSURE COMPRESSOR DISC<br>3072417-7<br>21121159    | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 10000 | 4901        | (9999)10210  | 2976    |
| 725080<br>E2 | STAGE 3 LOW PRESSURE COMPRESSOR DISC<br>3072417-7<br>21122864    | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 10000 | 4810        | (10000)10303 | 3069    |
| 725090<br>E1 | STAGE 4 LOW PRESSURE COMPRESSOR DISC<br>3075351-5<br>503501226   | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 20000 | 1908        | (22992)23203 | 15969   |
| 725090<br>E2 | STAGE 4 LOW PRESSURE COMPRESSOR DISC<br>3075351-5<br>5035011495  | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 20000 | 1918        | (22892)23195 | 15961   |
| 725091<br>E1 | LOW PRESSURE TIE ROD<br>3073049-1<br>5P22017                     | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | O/C   | 5289        |              |         |
| 725091<br>E2 | LOW PRESSURE TIE ROD<br>3073049-1<br>5P21994                     | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | O/C   | 5273.5      |              |         |
| 725110<br>E1 | HIGH PRESSURE IMPELLER<br>3073398-2<br>33651335                  | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 10000 | 4901        | (9999)10210  | 2976    |
| 725110<br>E2 | HIGH PRESSURE IMPELLER<br>3073398-2<br>33651380                  | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 10000 | 4810        | (10000)10303 | 3069    |
| 725120<br>E1 | ROTATING SEAL<br>3072729-1<br>SN-UNKNOWN                         | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | O/C   | 5289        |              |         |
| 725120<br>E2 | ROTATING SEAL<br>3072729-1<br>SN-UNKNOWN                         | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | O/C   | 5273.5      |              |         |
| 725130<br>E1 | HIGH PRESSURE SHOULDERED SHAFT<br>3072545-1<br>5P32120           | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 12000 | 4901        | (11999)12210 | 4976    |
| 725130<br>E2 | HIGH PRESSURE SHOULDERED SHAFT<br>3072545-1<br>5P32122           | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 12000 | 4810        | (12000)12303 | 5069    |
| 725140<br>E1 | HIGH PRESSURE ROTOR SEAL PLATE<br>3072411-1<br>SN-UNKNOWN        | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5466.4<br>5111 |        | 10000 | 4901        | (9999)10210  | 2976    |
| 725140<br>E2 | HIGH PRESSURE ROTOR SEAL PLATE<br>3072411-1<br>SN-UNKNOWN        | MTH<br>HRS<br>LDG | 25-Sep-2002<br>5463.2<br>5113 |        | 10000 | 4810        | (10000)10303 | 3069    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code    | Description                                      | Part Number                 | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains           |
|--------------|--------------------------------------------------|-----------------------------|-------------------------------------------|--------|-------|-------------|-------------|-------------------|
| Position     | Drawing # / Task #                               | Part Serial No              | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains           |
| 725150<br>E1 | FAN DRIVE SHAFT                                  | 3071607-10<br>5P24517       | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 4901        |             |                   |
| 725150<br>E2 | FAN DRIVE SHAFT                                  | 3071607-10<br>5P31992       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 4810        |             |                   |
| 725160<br>E1 | TURBINE INTERSTAGE TRANSITION DUCT<br>UNK        | 3072318-4<br>4P-1499        | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |                   |
| 725160<br>E2 | TURBINE INTERSTAGE TRANSITION DUCT<br>UNK        | 3072318-4<br>2P-35593       | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |                   |
| 725170<br>E1 | STAGE 1 LOW PRESSURE TURBINE ROTATING SEAL PLATE | 3072333-9<br>SN-UNKNOWN     | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        |       | 10000       | 4901        | (9999)10210 2976  |
| 725170<br>E2 | STAGE 1 LOW PRESSURE TURBINE ROTATING SEAL PLATE | 3072333-9<br>SN-UNKNOWN     | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        |       | 10000       | 4810        | (10000)10303 3069 |
| 725180<br>E1 | STAGE 1 LOW PRESSURE TURBINE NOZZLE              | 3072842-10<br>0013453993    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 3468        |             |                   |
| 725180<br>E2 | STAGE 1 LOW PRESSURE TURBINE NOZZLE<br>UNK       | 3072842-10<br>11-3300-01782 | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |                   |
| 725190<br>E1 | LOW PRESSURE TURBINE ROTATING AIR SEAL           | 3073765-10<br>4P19560       | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 1908        |             |                   |
| 725190<br>E2 | LOW PRESSURE TURBINE ROTATING AIR SEAL           | 3073765-10<br>4P19571       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 1918        |             |                   |
| 725191<br>E1 | LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT   | 3073764-4<br>4P20050        | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 2121        |             |                   |
| 725191<br>E2 | LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT   | 3073764-4<br>02P-00600      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 0<br>0<br>0 |             |                   |
| 726110<br>E1 | ACCESSORY GEARBOX                                | 3070003-11<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |                   |
| 726110<br>E2 | ACCESSORY GEARBOX                                | 3070003-11<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |                   |
| 726130<br>E1 | TRANSFER GEARBOX                                 | 3070093-4<br>P5580          | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |                   |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code    | Description                | Part Number             | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|--------------|----------------------------|-------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position     | Drawing # / Task #         | Part Serial No          | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 726130<br>E2 | TRANSFER GEARBOX           | 3070093-4<br>P5507      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 733001       | FUEL FLOW INDICATOR        | 9914095-3<br>142        | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 731001<br>E1 | -- CHECK VALVE-FUEL HEATER | 3073932-4<br>20404171   | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 731001<br>E2 | -- CHECK VALVE-FUEL HEATER | 3073932-4<br>SN-UNKNOWN | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 731020<br>E1 | FUEL MANIFOLD              | 3073591-2<br>9-798C     | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 731020<br>E2 | FUEL MANIFOLD              | 3073591-2<br>1-571C     | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 731110<br>E1 | ENGINE FUEL PUMP           | 3070850-48<br>MX243627  | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 731110<br>E2 | ENGINE FUEL PUMP           | 3070850-48<br>MX434593  | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 3411        |             |         |
| 731130<br>E1 | FLOW DIVIDER/DRAIN VALVE   | 394396-2<br>6290        | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 731130<br>E2 | FLOW DIVIDER/DRAIN VALVE   | 394396-2<br>6092        | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 731140<br>E1 | FUEL HEATER                | 158670-3<br>454223      | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 731140<br>E2 | FUEL HEATER                | 158670-3<br>454224      | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 731150<br>E1 | FUEL/OIL COOLER            | 158610-14<br>1145723    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 731150<br>E2 | FUEL/OIL COOLER            | 158610-14<br>1245769    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 732110<br>E1 | FUEL CONTROL UNIT          | 3070800-11<br>A8808     | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code              | Description            | City | Mod Lvl | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|------------------------|------------------------|------|---------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position               | Drawing # / Task #     |      |         | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 732110<br>E2           | FUEL CONTROL UNIT      | FXE  |         | 3070800-33<br>A10977       | MTH 05-Oct-2017<br>HRS 8401.7<br>LDG 6954 |        | O/C   | 0<br>0<br>0 |             |         |
| 732120<br>E1           | PRESSURE LIMITER VALVE |      |         | 3070685-6<br>18646         | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 732120<br>E2           | PRESSURE LIMITER VALVE |      |         | 3070685-6<br>A8651         | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 732130<br>E1           | SURGE BLEED VALVE      |      |         | 978812-5<br>5939           | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5289        |             |         |
| 732130<br>E2           | SURGE BLEED VALVE      |      |         | 978812-5<br>5935           | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 732140<br>E1           | SOLENOID CONTROL VALVE |      |         | 109696-4-1<br>5598         | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 0<br>0<br>0 |             |         |
| 732140<br>E2           | SOLENOID CONTROL VALVE |      |         | 109696-4-1<br>5592         | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 732150<br>E1           | FUEL CONTROL COMPUTER  | UNK  |         | 2119020-6000<br>114-CJ0059 | MTH 21-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   |             |             |         |
| 732150<br>E2           | FUEL CONTROL COMPUTER  | FXE  |         | 2119020-6000<br>103-CK0522 | MTH 05-Oct-2017<br>HRS 8401.7<br>LDG 6954 |        | O/C   |             |             |         |
| 732160<br>E1           | FUEL FLOW TRANSMITTER  |      |         | 9914087-1<br>31034         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 732160<br>E2           | FUEL FLOW TRANSMITTER  |      |         | 9914087-1<br>3551A         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 741110<br>E1           | IGNITION UNIT          | UNK  |         | 10-392000-2<br>90280106    | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 741110<br>E2           | IGNITION UNIT          | UNK  |         | 3073776-1<br>010218020088  | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 742110<br>E1 6 O'CLOCK | IGNITER PLUG           | UNK  |         | 3074541-4<br>NSN           | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 742110<br>E2 6 O'CLOCK | IGNITER PLUG           | UNK  |         | 3074541-4<br>NSN           | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 742130<br>E1 7 O'CLOCK | IGNITER PLUG           | UNK  |         | 3074541-4<br>NSN           | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 742130<br>E2 7 O'CLOCK | IGNITER PLUG           | UNK  |         | 3074541-4<br>NSN           | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 751010<br>E1           | ANTI-ICE SHUTOFF VALVE |      |         | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code       | Description                         | Part Number                | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-----------------|-------------------------------------|----------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position        | Drawing # / Task # City Mod Lvl     | Part Serial No             | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 751010<br>E2    | ANTI-ICE SHUTOFF VALVE              | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 760001<br>LEFT  | GEAR BOX                            | C81785-1<br>218            | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 760001<br>RIGHT | GEAR BOX                            | C81786-1<br>215            | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761001          | DEPLOY INTER LOCK                   | U183238-001<br>SN-UNKNOWN  | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761201          | ENGINE SYNCHRONIZER<br>UNK          | 2117416-2<br>23-134        | MTH 21-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   |             |             |         |
| 761202          | ENGINE SYNCHRONIZER INDICATOR       | 2101366-1<br>7218433       | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761302<br>LEFT  | 3 BRANCH CABLE                      | 9914303-3<br>64206         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761302<br>RIGHT | 5 BRANCH CABLE                      | 9914303-4<br>84221         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761303<br>LEFT  | SHORTING PLUG                       | 9914303-5<br>55246         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761303<br>RIGHT | SHORTING PLUG                       | 9914303-6<br>25246         | MTH 21-Aug-1986                           |        | O/C   |             |             |         |
| 761304          | APR CONTROLLER                      | PN<br>SN-UNKNOWN           | MTH 21-Aug-1986                           |        | O/C   | 0           |             |         |
| 771001          | FAN SPEED INDICATOR                 | 9914095-5<br>184BAC        | MTH 10-Jul-2009<br>HRS 7119.2<br>LDG 6119 |        | O/C   |             |             |         |
| 771002          | TURBINE SPEED INDICATOR<br>UNK      | 9914095-7<br>153           | MTH 24-Oct-2011<br>HRS 7545.3<br>LDG 6400 |        | O/C   |             |             |         |
| 772001          | ITT INDICATOR                       | 9914095-20<br>66A          | MTH 07-Mar-2008<br>HRS 6805               |        | O/C   |             |             |         |
| 771110<br>E1    | LOW PRESSURE (N1) TRANSDUCER<br>UNK | 3073827-4<br>NSN           | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |
| 771110<br>E2    | LOW PRESSURE (N1) TRANSDUCER        | 3073827-4<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 771120<br>E1    | HIGH PRESSURE (N2) TRANSDUCER       | 3070722-3<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   | 5468        |             |         |
| 771120<br>E2    | HIGH PRESSURE (N2) TRANSDUCER       | 3070722-3<br>SN-UNKNOWN    | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |        | O/C   | 5273.5      |             |         |
| 772110<br>E1    | ITT THERMOCOUPLE HARNESS            | 3073595-1<br>22021900250   | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |        | O/C   |             |             |         |
| 772110<br>E2    | ITT THERMOCOUPLE HARNESS<br>UNK     | 3073595-1<br>1115027700132 | MTH 11-Oct-2011<br>HRS 7545.3<br>LDG 6403 |        | O/C   | 0<br>0<br>0 |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position    | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 781001<br>LEFT           | EXHAUST NOZZLE DUCT               |      |         | 6252301-1<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 781001<br>RIGHT          | EXHAUST NOZZLE DUCT               |      |         | 6252301-2<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 781002<br>LEFT           | EXHAUST PRECOOLER<br>-            |      |         | 6214565-1<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 781002<br>RIGHT          | EXHAUST PRECOOLER<br>-            |      |         | 6214565-1<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783001<br>LEFT           | THRUST REVERSER ASSEMBLY          |      |         | 9914214-3<br>213              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783001<br>RIGHT          | THRUST REVERSER ASSEMBLY          |      |         | 9914214-4<br>214              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783002<br>UPPER LEFT     | THRUST REVERSER DOOR ASSEMBLY     |      |         | 223-0010-501<br>213           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783002<br>UPPER RIGHT    | THRUST REVERSER DOOR ASSEMBLY     |      |         | 223-0010-502<br>216           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783003<br>LOWER LEFT     | THRUST REVERSER DOOR ASSEMBLY     |      |         | 223-0011-501<br>213           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783003<br>LOWER RIGHT    | THRUST REVERSER DOOR ASSEMBLY     |      |         | 223-0011-502<br>212           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783004<br>LEFT INBOARD   | THRUST REVERSER ACTUATOR          |      |         | 57080-3<br>765R               | MTH 10-Aug-2005<br>LDG 5540 |                | O/C            |                |                            |                    |
| 783004<br>LEFT OUTBOARD  | THRUST REVERSER ACTUATOR          |      |         | 57080-3<br>1230R              | MTH 27-Jun-2003<br>LDG 5205 |                | O/C            |                |                            |                    |
| 783004<br>RIGHT INBOARD  | THRUST REVERSER ACTUATOR          |      |         | 57080-3<br>953R               | MTH 30-May-2000<br>LDG 4683 |                | O/C            |                |                            |                    |
| 783004<br>RIGHT OUTBOARD | THRUST REVERSER ACTUATOR          |      |         | 57080-3<br>556R               | MTH 30-May-2000<br>LDG 4683 |                | O/C            |                |                            |                    |
| 783005<br>LEFT INBOARD   | THRUST REVERSER STOW SWITCH       |      |         | 1EN331-8B<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783005<br>LEFT OUTBOARD  | THRUST REVERSER STOW SWITCH       |      |         | 1EN331-8B<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783005<br>RIGHT INBOARD  | THRUST REVERSER STOW SWITCH       |      |         | 1EN331-8B<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783005<br>RIGHT OUTBOARD | THRUST REVERSER STOW SWITCH       |      |         | 1EN331-8B<br>SN-UNKNOWN       | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783006<br>LEFT           | THRUST REVERSER DEPLOY SWITCH     |      |         | 65016-2<br>925                | MTH 06-Feb-2004<br>HRS 5850 |                | O/C            |                |                            |                    |
| 783006<br>RIGHT          | THRUST REVERSER DEPLOY SWITCH     |      |         | 65016<br>SN-UNKNOWN           | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783201<br>LEFT           | THRUST REVERSER SELECTOR VALVE    |      |         | 9914214-6<br>313              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783201<br>RIGHT          | THRUST REVERSER SELECTOR VALVE    |      |         | 9914214-6<br>307              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783202<br>LEFT           | THRUST REVERSER ISOLATION VALVE   |      |         | 9914214-7<br>327              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783202<br>RIGHT          | THRUST REVERSER ISOLATION VALVE   |      |         | 9914214-7<br>336              | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |
| 783203<br>LEFT           | THRUST REVERSER PRESSURE SWITCH   |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986             |                | O/C            | 0              |                            |                    |
| 783203<br>RIGHT          | THRUST REVERSER PRESSURE SWITCH   |      |         | 9914214-5<br>D4288            | MTH 21-Aug-1986             |                | O/C            |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position   | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------|-----------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 790001<br>LEFT          | OIL TEMP TRANSMITER               |      |         | MS28034-3<br>79255            | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 790001<br>RIGHT         | OIL TEMP TRANSMITER               |      |         | MS28034-3<br>34187            | MTH 10-May-1994<br>HRS 2835               |                | O/C            |                |                            |                    |
| 793001                  | OIL TEMP INDICATOR                |      |         | 9914095-1<br>131              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 793002<br>LEFT          | OIL PRESSURE TRANSMITER           |      |         | 9914089-2<br>16138            | MTH 21-Oct-1994<br>HRS 2997               |                | O/C            |                |                            |                    |
| 793002<br>RIGHT         | OIL PRESSURE TRANSMITER           |      |         | 9914089-4<br>5458614          | MTH 09-Apr-1997<br>HRS 3871               |                | O/C            |                |                            |                    |
| 793003<br>LEFT          | OIL PRESSURE LOW SWITCH           |      |         | 9914225-1<br>1205             | MTH 27-Jun-2004<br>HRS 5984               |                | O/C            |                |                            |                    |
| 793003<br>RIGHT         | OIL PRESSURE LOW SWITCH           |      |         | 9914225-1<br>1171             | MTH 13-Dec-2002<br>HRS 5477               |                | O/C            |                |                            |                    |
| 793006                  | OIL PRESSURE INDICATOR            |      |         | 9914095-2<br>121              | MTH 21-Aug-1986                           |                | O/C            |                |                            |                    |
| 792110<br>E1            | OIL PUMP                          | UNK  |         | 3060785-2<br>071405701747     | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 792110<br>E2            | OIL PUMP                          |      |         | 3071949-7<br>7576             | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 5273.5         |                            |                    |
| 792120<br>E1            | OIL FILTER BY-PASS INDICATOR      |      |         | 3075323-2<br>SN-UNKNOWN       | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | O/C            | 2208           |                            |                    |
| 792120<br>E2            | OIL FILTER BY-PASS INDICATOR      |      |         | 3071564-8<br>SN-UNKNOWN       | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 5273.5         |                            |                    |
| 792130<br>E1            | PRESSURE BREATHER VALVE ASSEMBLY  |      |         | PN<br>SN-UNKNOWN              | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 792130<br>E2            | PRESSURE BREATHER VALVE ASSEMBLY  |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                           |                | O/C            | 0              |                            |                    |
| 792140<br>E1 UPPER      | OIL COOLER                        |      |         | 158600-7<br>458338            | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | O/C            | 5289           |                            |                    |
| 792140<br>E2 UPPER      | OIL COOLER                        |      |         | 158600-7<br>458354            | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 5273.5         |                            |                    |
| 792150<br>E1 LOWER LEFT | OIL COOLER                        |      |         | 159910-3<br>255882            | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111 |                | O/C            | 0<br>0         |                            |                    |
| 792150<br>E2 LOWER LEFT | OIL COOLER                        |      |         | 159900-3<br>455958            | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113 |                | O/C            | 5273.5         |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position    | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                                 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------|-----------------------------------|------|---------|-------------------------------|----------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 792160<br>E1 LOWER RIGHT | OIL COOLER                        |      |         | 159910-3<br>556007            | MTH 25-Sep-2002<br>HRS 5466.4<br>LDG 5111                |                | O/C            | 0<br>0<br>0    |                            |                    |
| 792160<br>E2 LOWER RIGHT | OIL COOLER                        |      |         | 159910-3<br>453941            | MTH 25-Sep-2002<br>HRS 5463.2<br>LDG 5113                |                | O/C            | 5273.5         |                            |                    |
| 792170<br>E1             | OIL TEMPERATURE VALVE             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                                          |                | O/C            | 0              |                            |                    |
| 792170<br>E2             | OIL TEMPERATURE VALVE             |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                                          |                | O/C            | 0              |                            |                    |
| 801000<br>LEFT           | STARTER/GENERATOR<br>9914052-1    |      |         | 23080-003<br>92039            | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213                |                | 1000           | 636.3          | 9099                       | 325.1              |
| 801100<br>APU            | STARTER-GENERATOR<br>9914052-1    | UNK  |         | 23080-003E<br>2403            | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213<br>APUH 2166.5 |                | 1000           | 505.4          | 2661.1                     | 487.1              |
| 801102<br>LEFT           | CONTROL UNIT                      |      |         | 9914050-2<br>16080AB          | MTH 16-Jul-1991<br>HRS 1798                              |                | O/C            |                |                            |                    |
| 801102<br>RIGHT          | CONTROL UNIT                      |      |         | 9914050-2<br>3875AB           | MTH 17-Aug-1991<br>HRS 1824                              |                | O/C            | 27             |                            |                    |
| 801103<br>LEFT           | DC AMMETER                        |      |         | 115.179-7<br>85050179         | MTH 21-Aug-1986                                          |                | O/C            |                |                            |                    |
| 801103<br>RIGHT          | DC AMMETER                        |      |         | 115.179-7<br>85080197         | MTH 21-Aug-1986                                          |                | O/C            |                |                            |                    |
| 801103                   | DC VOLTMETER                      |      |         | 9914090-2<br>85080116         | MTH 21-Aug-1986                                          |                | O/C            |                |                            |                    |
| 801105<br>LEFT           | TRANSFORMER                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                                          |                | O/C            | 0              |                            |                    |
| 801105<br>RIGHT          | TRANSFORMER                       |      |         | PN<br>SN-UNKNOWN              | MTH 21-Aug-1986                                          |                | O/C            | 0              |                            |                    |
| 801106<br>LEFT           | STARTER RELAY                     |      |         | A703C<br>BS9021               | MTH 26-Jul-1995<br>HRS 3251                              |                | O/C            |                |                            |                    |
| 801106<br>RIGHT          | STARTER RELAY                     |      |         | A703C<br>CJ43848              | MTH 13-Oct-1993<br>HRS 2631                              |                | O/C            |                |                            |                    |
| 802000<br>RIGHT          | STARTER/GENERATOR<br>9914052-11   |      |         | 23080-003-1<br>96063          | MTH 23-Sep-2021<br>HRS 8735.3<br>LDG 7213                |                | 1200           | 203.4          | 9731.9                     | 958                |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position        | Description<br>Drawing # / Task #                                                                                                                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| VSBB 298113-SB-001<br>E1     | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 298113-SB-001<br>E2     | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 298113-SB-002 R01<br>E1 | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 298113-SB-002 R01<br>E2 | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 298113-SB-002<br>E1     | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 298113-SB-002<br>E2     | RETAINER NUT TORQUE AND DRILL FIXTURE ASSEMBLY - PN 298113; INTRODUCTION OF NEW .0635" DIAMETER DRILL BUSHING                                      |      |         |                               |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 3727214-SB-001<br>E1    | DISKBAL BLADE MAPPING SOFTWARE PN 3727214 - RELEASE OF DISKBAL BLADE MAPPING SOFTWARE VERSION 2.7, PN 3727214-2, WITH IMPROVED FAN BALANCE PROCESS |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| VSBB 3727214-SB-001<br>E2    | DISKBAL BLADE MAPPING SOFTWARE PN 3727214 - RELEASE OF DISKBAL BLADE MAPPING SOFTWARE VERSION 2.7, PN 3727214-2, WITH IMPROVED FAN BALANCE PROCESS |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL CIL-03-01                 | CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)                                                                                   |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL CIL-99-03 R01             | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                    |      |         | RECOMMENDED                   |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL CIL-99-04                 | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW                                                                                            |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-99-05 R07             | CESCOM PRICES (THIS SL CANCELS SL650-99-05 R6 AND PREVIOUS)                                                                                        |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-99-09                 | MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS                                                                               |      |         | INFORMATIONAL                 |                             |                | A/R            |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-99-10                 | MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION                                                                                        |      |         | INFORMATIONAL                 |                             |                | A/R            |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-03-01 R14             | CERTIFICATION REQUIREMENTS - UNITED STATES TO CANADIAN CONVERSION                                                                                  |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                                                       |      |         |                               |                             |                |                |                |                            |                    |
| SB ASL 650-05-07             | INSP OF INDIRECT LIGHTING CON                                                                                                                      |      |         |                               | MTH 28-Jun-2000<br>HRS 4869 |                | -              |                |                            | Complete           |
|                              | <b>MOC :</b>                                                                                                                                       |      |         | COMPLIED WITH                 |                             |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-05-10 R01      | NEW 650 TASK BASED INSPECTION PROGRAM                                                                                                          |      |         | MANDATORY                     | MTH 28-Aug-2008<br>HRS 6943.9<br>LDG 6007 |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-05-10 R02      | NEW 650 TASK BASED INSPECTION PROGRAM                                                                                                          |      |         | MANDATORY                     | MTH 03-Mar-2009<br>HRS 7047.8<br>LDG 6069 |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH - PREVIOUSLY</b>                                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-09-01       | RESTRICT DURNG TOWNG                                                                                                                           |      |         |                               |                                           |                | -              |                |                            |                    |
|                       | <b>MOC : - OPEN</b>                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-11-06          | BALLAST FUEL PLACARD INSTALLATION                                                                                                              |      |         | MANDATORY                     | MTH 13-Nov-1987<br>HRS 544                |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-11-07 R01      | SEAT PLACARD INSTALLATIONS                                                                                                                     |      |         | MANDATORY                     | MTH 25-Apr-1988<br>HRS 749                |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-11-08          | AIRSPED LIMITATIONS PLACARD REPLACEMENT                                                                                                        |      |         | MANDATORY                     | MTH 06-Jul-1988<br>HRS 869                |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-11-10          | AILERON DISCONNECT FORCE LINK PLACARDS                                                                                                         |      |         | RECOMMENDED                   | MTH 16-Jul-1991<br>HRS 1798               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-11-11          | MAIN LANDING GEAR OLEO PISTON PLACARD INSTALLATION                                                                                             |      |         | RECOMMENDED                   | MTH 06-Jul-1993<br>HRS 2529               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-11-04          | DATA PLATE RELOCATION                                                                                                                          |      |         | OPTIONAL                      |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL650-11-06 R1     | DC FLAP BREAKOUT BOX PLACARD                                                                                                                   |      |         |                               |                                           |                | -              |                |                            |                    |
|                       | <b>MOC : - OPEN</b>                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-01 R01      | USE OF CORROSION INHIBITING COMPOUNDS                                                                                                          |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-01 R02      | USE OF CORROSION INHIBITING COMPOUNDS                                                                                                          |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-02          | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS |      |         | RECOMMENDED                   | MTH                                       |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-20-01 R02      | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL                                                       |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-20-01 R03-CN   | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL                                                       |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-20-01 R27      | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL                                                       |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                    | City | Mod Lvl       | Part Number<br>Part Serial No                         | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------------------------------------------------------|------|---------------|-------------------------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-20-03          | STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL                                |      |               | INFORMATIONAL                                         |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-11          | HYDRAULIC FAN CASE DRAIN LINE MODIFICATION                                           |      |               | MTH 31-Oct-2008<br>RECOMMENDED HRS 6981.8<br>LDG 6036 |                          |                | -              |                |                            | N/A                |
|                       | <b>MOC :</b> NOT APPLICABLE - BY PART NUMBER N/A BY PART NUMBER INSTALLED            |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-21          | COCKPIT AIR SYSTEM IMPROVEMENT                                                       |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-22 R02      | WEMAC BOOST INSTALLATION                                                             |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-23          | CABIN SIDEWALL DUCT MODIFICATION AND ARMREST BRACKET REPLACEMENT                     |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-24          | CABIN SIDEWALL DUCT SPARES REPLACEMENT                                               |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-25 R01      | ENVIRONMENTAL CONTROL UNIT HYDRAULIC FAN LINE REPLACEMENT AND CLAMPING               |      | MANDATORY     |                                                       |                          |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-26 R01      | REMOVAL/INSTALLATION BAGGAGE COMPARTMENT HEATER CONNECTOR AND AIRFLOW SWITCH         |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-27 R01      | BAGGAGE COMPARTMENT HEATER AIRFLOW SWITCH REMOVAL                                    |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-32          | DEFOG BLOWER VOLTAGE REGULATOR CAPACITOR INSTALLATION                                |      | RECOMMENDED   | MTH 09-Nov-1990<br>HRS 1581                           |                          |                | -              |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                           |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-40          | DUCT TEMPERATURE SENSOR INSPECTION/REPLACEMENT                                       |      | RECOMMENDED   |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-42 R01      | AUXILIARY HEATER OVERHEAT SWITCH REPLACEMENT                                         |      | RECOMMENDED   |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-43          | RIGHT SIDEWALL PANEL MODIFICATION                                                    |      | OPTIONAL      |                                                       |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-44 R01      | WEMAC BLOWER DRAIN INSTALLATION                                                      |      | DISCRETIONARY |                                                       |                          |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SB 650-21-45          | CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT                                         |      | OPTIONAL      |                                                       |                          |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                         |      |               |                                                       |                          |                |                |                |                            |                    |
| SL CIL-21-02 R01      | ENVIRONMENTAL HOUR METER INSTALLATION                                                | KFXE | MANDATORY     | MTH 13-Jul-2015<br>HRS 7940.2<br>LDG 6682             |                          |                | -              |                |                            | N/A                |
|                       | <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE. AIRCRAFT NOT EQUIPT WITH VAPOR SYSTEM. |      |               |                                                       |                          |                |                |                |                            |                    |
| SB SL 650-21-02       | SERVICING THE ECU                                                                    |      |               | MTH 06-Mar-1987<br>HRS 194                            |                          |                | -              |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                           |      |               |                                                       |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                                                           | Part Number | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|-----------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                                                    | City        | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 650-21-02 R01 | SERVICING THE ENVIRONMENTAL CONTROL UNIT AIR CYCLE MACHINE                                                            |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SL 650-21-06     | INSPECTION FOR INTERFERENCE BETWEEN UPPER AIR CYCLE MACHINE (NEW STYLE P/N 740551) AND LOWER WATER SEPARATOR ASSEMBLY |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | RECOMMENDED    | MTH 06-Mar-1987 |        | -           |         |             | Complete |
|                  |                                                                                                                       |             |            |                | HRS 194         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SL 650-21-07     | SUNDSTRAND SERVICE BULLETIN NUMBER 738066-21-4 (ENVIRONMENTAL CONTROL UNIT WATER SEPARATOR MODIFICATION)              |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | RECOMMENDED    | MTH 25-Apr-1988 |        | -           |         |             | Complete |
|                  |                                                                                                                       |             |            |                | HRS 749         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SL 650-21-11     | TRANSMITTAL OF AIRBORNE SERVICE LETTER NUMBER 73, REPLACEMENT OF CONTROLLER-INVERTER.                                 |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | MANDATORY      | MTH 24-Oct-2011 |        | A/R         |         |             | Complete |
|                  |                                                                                                                       |             |            |                | HRS 7545.3      |        |             |         |             |          |
|                  |                                                                                                                       |             |            |                | LDG 6400        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH - FOUND TO BE N/A BY. P/N AND S/N INSTALLED AT THIS TIME                                          |             |            |                |                 |        |             |         |             |          |
| SB 650-22-03     | AUTOPILOT MACH HOLD WIRING IMPROVEMENT                                                                                |             |            |                |                 |        | A/R         |         |             |          |
|                  |                                                                                                                       |             |            | RECOMMENDED    |                 |        |             |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-01 R02 | STATIC BONDING IMPROVEMENT                                                                                            |             |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-03     | COMM 1 ANTENNA INSTALLATION IMPROVEMENT                                                                               |             |            |                | MTH 08-Aug-1989 |        | A/R         |         |             | Complete |
|                  |                                                                                                                       |             |            | RECOMMENDED    | HRS 1291        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-23-04 R02 | COCKPIT VOICE RECORDER INSTALLATION (FAIRCHILD GA100)                                                                 |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-06 R02 | COCKPIT VOICE RECORDER CIRCUIT BREAKER BUSSING MODIFICATION                                                           |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-07     | COCKPIT VOICE RECORDER HOT MICROPHONE ACTIVATION                                                                      |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-17 R02 | COLLINS 8.33 KHZ COMMICATION RADIO INSTALLATION                                                                       |             |            |                |                 |        | A/R         |         |             |          |
|                  |                                                                                                                       |             |            | OPTIONAL       |                 |        |             |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-23-18 R02 | VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT                                                                        |             |            |                | MTH 23-Oct-2000 |        | A/R         |         |             | Complete |
|                  |                                                                                                                       |             |            | MANDATORY      | HRS 4959        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-23-20 R02 | COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION                                                           |             |            |                |                 |        |             |         |             |          |
|                  |                                                                                                                       |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB SL 650-23-01  | AUDIO AMP MOD                                                                                                         |             |            |                | MTH 06-Mar-1987 |        | -           |         |             | Complete |
|                  |                                                                                                                       |             |            |                | HRS 194         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SB SL 650-23-09  | CVR IMPRV PWR MONTR                                                                                                   |             |            |                | MTH 07-Jul-1993 |        | -           |         |             | Complete |
|                  |                                                                                                                       |             |            |                | HRS 2529        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |
| SB SL 650-23-19  | AIRSHOW IMPROVE/SOFTWARE UPGR                                                                                         |             |            |                | MTH 15-May-2003 |        | -           |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                   |             |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                             | Part Number | C/W Time 1  | Adj.           | TBO 1       | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|-----------------------------------------------------------------------------------------|-------------|-------------|----------------|-------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                      | City        | Mod Lvl     | Part Serial No | C/W Time 2  | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 650-23-02     | AUDIO CONTROL AMPLIFIER MODIFICATION                                                    |             |             | MTH            | 28-Apr-1989 |        | -           |         |             | Complete |
|                  |                                                                                         |             | RECOMMENDED | HRS            | 1195        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SL 650-23-03     | MICROPHONE REPLACEMENT PROGRAM                                                          |             |             | MTH            | 28-Sep-1988 |        | -           |         |             | Complete |
|                  |                                                                                         |             | RECOMMENDED | HRS            | 1008        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SL 650-23-04     | STATIC DISCHARGE WICKS INSPECTION/REPLACEMENT                                           |             |             | MTH            | 04-Mar-1991 |        | A/R         |         |             | Complete |
|                  |                                                                                         |             | MANDATORY   | HRS            | 1675        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SL 650-23-12     | SUNDSTRAND MODEL AV-557C COCKPIT VOICE RECORDER SERVICE BULLETIN #25                    |             |             |                |             |        | A/R         |         |             |          |
|                  |                                                                                         |             | RECOMMENDED |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SL 650-23-17     | TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT     |             |             | MTH            | 14-May-2003 |        | -           |         |             | Complete |
|                  |                                                                                         |             | RECOMMENDED |                |             |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SL 650-23-19 R01 | AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE                      |             |             | MTH            | 16-Jun-2003 |        | -           |         |             | N/A      |
|                  |                                                                                         |             | RECOMMENDED |                |             |        |             |         |             |          |
|                  | MOC : NOT APPLICABLE - BY PART NUMBER                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-04 R03 | REMOVAL OF DUAL 22 AMPERE-HOUR BATTERIES, INSTALLATION OF DUAL 40 AMPERE-HOUR BATTERIES |             |             | MTH            | 09-Nov-1990 |        | -           |         |             | Complete |
|                  |                                                                                         |             | OPTIONAL    | HRS            | 1581        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SB 650-24-12 R03 | INSTALLATION OF SECOND 40 AMPERE-HOUR BATTERY                                           |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-18     | 40 AMPERE-HOUR BATTERY INSTALLATION CONVERSION (DUAL TO SINGLE AND SINGLE TO DUAL)      |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-24     | LEFT CIRCUIT BREAKER PANEL MODIFICATION                                                 |             |             | MTH            | 25-Apr-1988 |        | A/R         |         |             | Complete |
|                  |                                                                                         |             | MANDATORY   | HRS            | 749         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SB 650-24-26     | APU J-BOX MOUNTING MODIFICATION                                                         |             |             | MTH            | 25-Apr-1988 |        | A/R         |         |             | Complete |
|                  |                                                                                         |             | RECOMMENDED | HRS            | 749         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                     |             |             |                |             |        |             |         |             |          |
| SB 650-24-31 R02 | INTERIOR MASTER LOAD SHED SWITCH INSTALLATION                                           |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-32 R01 | MAIN LANDING GEAR WIRE BUNDLE ROUTING IMPROVEMENT                                       |             |             |                |             |        | A/R         |         |             |          |
|                  |                                                                                         |             | RECOMMENDED |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-43 R01 | ENGINE GROUND PLATE REPLACEMENT                                                         |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-44     | CONTROL COLUMN ELECTRICAL CABLE REPLACEMENT                                             |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |
| SB 650-24-47 R03 | EMERGENCY AVIONICS BUS RELAY CURRENT SURGE PROTECTION                                   |             |             |                |             |        | -           |         |             |          |
|                  |                                                                                         |             | OPTIONAL    |                |             |        |             |         |             |          |
|                  | MOC :                                                                                   |             |             |                |             |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code         | Description                                                                                                           | Part Number   | C/W Time 1 | Adj.            | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------|-----------------------------------------------------------------------------------------------------------------------|---------------|------------|-----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position          | Drawing # / Task #                                                                                                    | City          | Mod Lvl    | Part Serial No  | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-24-53 R02  | RAM AIR TEMPERATURE SWITCH GUARD INSTALLATION                                                                         |               |            |                 |                 |        | A/R         |         |             |          |
|                   |                                                                                                                       |               |            | RECOMMENDED     |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 |               |            |                 |                 |        |             |         |             |          |
| SB 650-24-54      | SWITCH PANEL SWITCH INSTALLATION IMPROVEMENT                                                                          |               |            |                 |                 |        | A/R         |         |             |          |
|                   |                                                                                                                       |               |            | OPTIONAL        |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 |               |            |                 |                 |        |             |         |             |          |
| SB 650-24-59      | CONVERSION OF NICKEL CADMIUM BATTERY INSTALLATIONS TO LEAD ACID BATTERY INSTALLATIONS TO NICKEL CADMIUM, ON AIRPLANES |               |            |                 |                 |        |             |         |             |          |
|                   | ORIGINALLY EQUIPPED WITH THE SAFT 43 AMP MARATHON 44 AMP DUAL BATTERY INSTALLATION                                    |               |            |                 |                 |        |             |         |             |          |
|                   |                                                                                                                       |               |            | OPTIONAL        |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                 |               |            |                 |                 |        |             |         |             |          |
| SB 650-24-60      | EXTERNAL POWER BOX ANCHOR INSTALLATION                                                                                |               | MTH        | 23-Jul-2003     |                 |        | A/R         |         |             | Complete |
|                   |                                                                                                                       |               |            | RECOMMENDED     | HRS 5674        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SB ASL 650-24-07  | AC POWER INVERTER                                                                                                     |               | MTH        | 27-Jan-1988     |                 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            | HRS 619         |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| ASL 650-24-07 R02 | PILOT ADVISORY - AC POWER INVERTER FAILURES                                                                           |               |            |                 |                 |        | A/R         |         |             |          |
|                   |                                                                                                                       |               |            | MANDATORY       |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 |               |            |                 |                 |        |             |         |             |          |
| ASL 650-24-14     | AVIONICS BUS RELAY OPERATIONAL CHECK AND WIRING MODIFICATION                                                          |               |            |                 |                 |        |             |         |             |          |
|                   |                                                                                                                       |               |            | MANDATORY       | MTH 10-Feb-1989 |        | A/R         |         |             | Complete |
|                   |                                                                                                                       |               |            |                 | HRS 1102        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SB SL 650-24-10   | TAIL ELE WATER PROTE                                                                                                  |               | MTH        | 10-Feb-1989     |                 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            | HRS 1102        |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-08      | REPLACEMENT OF SPC38B INVERTERS                                                                                       |               | MTH        | 06-Jul-1988     |                 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            | RECOMMENDED     | HRS 869         |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-09      | RESTORATION OF 1000 HOUR TBO TO THE 9914052-1 (23080-003) STARTER GENERATOR                                           |               |            |                 |                 |        |             |         |             |          |
|                   |                                                                                                                       |               |            | RECOMMENDED     | MTH 25-Apr-1988 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            |                 | HRS 749         |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-10 R01  | TAILCONE ELECTRICAL COMPONENTS MOISTURE PROTECTION                                                                    |               |            |                 |                 |        |             |         |             |          |
|                   |                                                                                                                       |               |            | RECOMMENDED     | MTH 21-Nov-1989 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            |                 | HRS 1370        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-12      | KGS SPC38B INVERTER UPDATE                                                                                            |               | MANDATORY  | MTH 08-Aug-1989 |                 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            |                 | HRS 1291        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-16      | GENERATOR CONTROL UNIT IMPROVEMENT                                                                                    |               |            |                 |                 |        |             |         |             |          |
|                   |                                                                                                                       |               |            | RECOMMENDED     | MTH 16-Jul-1991 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            |                 | HRS 1798        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SL 650-24-21      | DC FLAP SYSTEM SPARE ANL40 FUSE LIMITER                                                                               |               | MTH        | 22-Mar-1996     |                 |        | -           |         |             | Complete |
|                   |                                                                                                                       |               |            | RECOMMENDED     | HRS 3497        |        |             |         |             |          |
|                   | MOC :                                                                                                                 | COMPLIED WITH |            |                 |                 |        |             |         |             |          |
| SB 650-25-05 R01  | DROPPED AISLE MOD FOR CONDENSATION CONTROL                                                                            |               |            |                 |                 |        | -           |         |             |          |
|                   |                                                                                                                       |               |            | OPTIONAL        |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                 |               |            |                 |                 |        |             |         |             |          |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2   | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------------------------------------------------|------|---------|-------------------------------|----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 650-25-06          | CREW SEAT BACK MODIFICATION                                                    |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-09          | LOCATOR BEACON RESET CIRCUIT VOLTAGE LIMIT RESISTOR DELETION                   |      |         | MANDATORY                     |                            |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-11          | PASSENGER SEAT ARMREST RELEASE LEVER REPLACEMENT                               |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| ASB 650-25-12         | INTERIOR CABINETRY ELECTRICAL POWER SOURCE DISABLEMENT                         |      |         | MANDATORY                     | MTH 06-Mar-1987<br>HRS 194 |                | -              |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                     |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-13          | COCKPIT SIDE CONSOLE UPHOLSTERY PANEL QUARTER TURN FASTENER INSTALLATION       |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-15          | POINTER 3000-1 EMERGENCY LOCATOR TRANSMITTER INSTALLATION                      |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-19          | FORWARD REFRESHMENT CENTER ACCESS DOOR INSTALLATION                            |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-28          | COCKPIT OVERHEAD ASSIST HANDLE INSTALLATION                                    |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-34          | TSO C91A EMERGENCY LOCATOR TRANSMITTER INSTALLATION                            |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-38          | FLIGHT CREW SEAT PAN REINFORCEMENT                                             |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-40          | VANITY HOT WATER TANK INSPECTION/REPLACEMENT                                   |      |         | MANDATORY                     | MTH 23-Sep-1998            |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                     |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-41          | 3-FREQUENCY ELT INSTALLATION                                                   |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-46 R02      | ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)               |      |         | OPTIONAL                      |                            |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB 650-25-47 R01      | GLARESHIELD LEATHER STRIP INSTALLATION                                         |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SB SL 650-25-05       | SWITLIK LIFE VEST                                                              |      |         |                               |                            |                | A/R            |                |                            | N/A                |
|                       | <b>MOC :</b> NOT APPLICABLE                                                    |      |         |                               |                            |                |                |                |                            |                    |
| SL 650-25-02 R04      | INTERIOR CABINETRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION |      |         | MANDATORY                     |                            |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SL 650-25-04          | CABIN DIVIDER HEADER MODIFICATION                                              |      |         | OPTIONAL                      |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |
| SL 650-25-07          | AFT CLOSET/VANITY WIRING CHANGE TO CUSTOMIZED CITATION III INTERIOR MANUAL     |      |         | RECOMMENDED                   |                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                   |      |         |                               |                            |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                                                                                                        | Part Number | C/W Time 1    | Adj.                        | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------|-----------------------------|------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                                                                                                 | City        | Mod Lvl       | Part Serial No              | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 650-25-15     | TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH 20-Mar-2008<br>HRS 6829 |            |        | A/R         |         |             | N/A      |
|                  | MOC : NOT APPLICABLE                                                                                                                                               |             |               |                             |            |        |             |         |             |          |
| SL 650-25-16     | TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)            |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | DISCRETIONARY |                             |            |        | A/R         |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SB 650-26-01     | ENGINE FIRE EXTINGUISHER BOTTLES WIRING IDENTIFICATION                                                                                                             |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH 28-Sep-1988<br>HRS 1008 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |
| SB 650-26-02     | FIRE TRAY PRINTED CIRCUIT BOARD INSTALLATION IMPROVEMENT                                                                                                           |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | RECOMMENDED   | MTH 25-Apr-1989<br>HRS 1195 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |
| SB 650-26-03     | APU FIRE EXTINGUISHER BOTTLE REPLACEMENT                                                                                                                           |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH 03-Oct-1990<br>HRS 1559 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |
| SB 650-26-04     | TRANSMITTAL OF PACIFIC SCIENTIFIC SERVICE BULLETIN 26-03-35071497, INSPECTION AND REPLACMENT OF TEMPERATURE COMPENSATED PRESSURE SWITCH                            |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH 17-Jun-2003<br>HRS 5646 |            |        | A/R         |         |             | N/A      |
|                  | MOC : NOT APPLICABLE - BY PART NUMBER                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SB 650-26-05     | FIRE PROTECTION - INSTALLATION OF THE 6790604-2 BAGGAGE COMPARTMENT SMOKE DETECTOR                                                                                 |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | OPTIONAL      |                             |            |        | -           |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| ASL 650-26-02    | APU FIRE EXTINGUISHER BOTTLE INSPECTION                                                                                                                            |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH 03-Oct-1990<br>HRS 1559 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |
| SL CIL-26-01 R01 | FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING                                                                                          |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     | MTH                         |            |        | -           |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SL 650-26-01     | FIRE EXTINGUISHER CHECK TEE VALVE INSPECTION                                                                                                                       |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | MANDATORY     |                             |            |        | -           |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SL 650-26-03 R01 | ENGINE FIRE DETECTION SYSTEM INSPECTION/MODIFICATION                                                                                                               |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | RECOMMENDED   |                             |            |        | A/R         |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SB 650-24-27 R01 | MAIN POWER JUNCTION BOX PLACARD REPLACEMENT                                                                                                                        |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | RECOMMENDED   | MTH 10-Feb-1989<br>HRS 1102 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |
| SB 650-27-22 R02 | PILOT'S RUDDER PEDAL ADJUSTMENT IMPROVEMENT                                                                                                                        |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | OPTIONAL      |                             |            |        | -           |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SB 650-27-23 R02 | FLAPS ALTITUDE AND SPEEDBRAKE MONITOR SYSTEM INSTALLATION                                                                                                          |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | OPTIONAL      |                             |            |        | -           |         |             |          |
|                  | MOC :                                                                                                                                                              |             |               |                             |            |        |             |         |             |          |
| SB 650-27-24 R01 | FLAP OVERSPEED WARNING SYSTEM INSTALLATION                                                                                                                         |             |               |                             |            |        |             |         |             |          |
|                  |                                                                                                                                                                    |             | RECOMMENDED   | MTH 20-Aug-1990<br>HRS 1515 |            |        | A/R         |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                                                                                |             |               |                             |            |        |             |         |             |          |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                           | Part Number | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|---------------------------------------------------------------------------------------|-------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                    | City        | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-27-25 R01 | FLAP CONTROLLER REPLACEMENT AND ASYMMETRY BRAKE DISABLEMENT                           |             |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-26 R04 | FLAP RIGGING BREAKOUT BOX MODIFICATION                                                |             |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-27     | FLAP OVERSPEED PRINTED CIRCUIT BOARD MODIFICATION                                     |             |            | RECOMMENDED    | MTH 04-May-1990 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 1462        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-28     | FLAP CARRIAGE ROLLER BEARING BOLT REPLACEMENT                                         |             |            | RECOMMENDED    | MTH 04-Mar-1991 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 1675        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-29 R02 | SPOILER HOLD DOWN CONTROL MODIFICATION                                                |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-31 R01 | FLAP CONTROLLER REPLACEMENT AND ASYMMETRY (9914346-2) AND ASYMMETRY BRAKE DISABLEMENT |             |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-32     | SPEEDBRAKE POSITION INDICATOR POTENTIOMETER REPLACEMENT                               |             |            | RECOMMENDED    | MTH 16-Jul-1991 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 1798        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-34     | ANGLE GEARBOX ASSEMBLY MODIFICATION                                                   |             |            | RECOMMENDED    | MTH 04-Mar-1991 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 1675        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-35 R01 | FLAP SYSTEM POSITION SENSOR POTENTIOMETER REPLACEMENT BY RESOLVER                     |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-39 R01 | DC FLAP INSTALLATION                                                                  |             |            | RECOMMENDED    | MTH 15-May-1995 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 3168        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-39 R03 | CITATION III DC FLAPS SYSTEM INSTALLATION                                             |             |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-44 R01 | ELEVATOR IDLER ATTACH STIFFENER REPLACEMENT                                           |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-46     | SPEEDBRAKE POTENTIOMETER INSTALLATION IMPROVEMENT                                     |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-47 R01 | FLAP ACTUATOR GEARBOX GREASE FITTING BOLT INSTALLATION                                |             |            | RECOMMENDED    | MTH 09-Apr-1997 |        | A/R         |         |             | Complete |
|                  |                                                                                       |             |            |                | HRS 3871        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                   |             |            |                |                 |        |             |         |             |          |
| SB 650-27-48 R01 | SPEED BRAKE POTENTIOMETER SYSTEM MODIFICATION                                         |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |
| SB 650-27-49 R01 | DC FLAP RELAY BOX CAPACITOR INSPECTION/REPLACEMENT                                    |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                                 |             |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code           | Description                                                        | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|---------------------|--------------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------|---------|-------------|----------|
| Position            | Drawing # / Task #                                                 | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-27-52        | ROLL SPOILER MIXER BOX ASSEMBLY ROLL PIN INSPECTION                |             |            | RECOMMENDED    | MTH 11-Sep-2008<br>HRS 6943.9<br>LDG 6007 |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB 650-27-53        | HORIZONTAL STABILIZER TRIM ACTUATOR CONTROLLER IMPROVEMENT         |             |            | MANDATORY      | MTH 13-Jul-2004<br>HRS 6013               |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB 650-27-54 R01    | FLAP-RIGGING BREAKOUT-BOX MODIFICATION                             |             |            | OPTIONAL       |                                           |        | -           |         |             |          |
| MOC :               |                                                                    |             |            |                |                                           |        |             |         |             |          |
| ASL 650-27-20       | FLIGHT CONTROLS - ELEVATOR BALANCING                               |             |            | MANDATORY      |                                           |        | A/R         |         |             |          |
| MOC :               |                                                                    |             |            |                |                                           |        |             |         |             |          |
| ASL 650-27-23       | HORIZONTAL STABILZIER SECONDARY TRIM ACTUATOR MODIFICATION         |             |            | MANDATORY      | MTH 28-Feb-1990<br>HRS 1430               |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| ASL 650-27-30 R01   | ELEVATOR TORQUE TUBE INBOARD ATTACH FITTING INSPECTION/REPLACEMENT |             |            | MANDATORY      |                                           |        | A/R         |         |             |          |
| MOC :               |                                                                    |             |            |                |                                           |        |             |         |             |          |
| ASL 650-27-30       | ELEVATOR TORQUE TUBE INBOARD ATTACH FITTING INSPECTION/REPLACEMENT |             |            | MANDATORY      | MTH 14-Dec-1992<br>HRS 2312               |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| ASL 650-27-39       | BRAKE PUSHROD INSPECTION                                           |             |            | MANDATORY      | MTH 06-Jun-2002<br>HRS 5465               |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-11     | FLAP RIGGING/INSP                                                  |             |            |                | MTH 25-Apr-1988<br>HRS 749                |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-12     | REPL A-BRAKE SENSOR                                                |             |            |                | MTH 05-Aug-1988<br>HRS 905                |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-13     | FLAP ACT BRG BLOCK                                                 |             |            |                | MTH 25-Apr-1988<br>HRS 749                |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-19     | FLAP CARRIAGE ROLLER                                               |             |            |                | MTH 10-Feb-1989<br>HRS 1102               |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-25     | TORQUE TUBES INSP                                                  |             |            |                | MTH 06-Jul-1993<br>HRS 2529               |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |
| SB SL 650-27-32     | ELEV IDLER SUPT INSP                                               |             |            |                | MTH 06-Jul-1993<br>HRS 2529               |        | -           |         |             | Complete |
| MOC : COMPLIED WITH |                                                                    |             |            |                |                                           |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                     | Part Number   | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|---------------------------------------------------------------------------------|---------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                              | City          | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 650-27-06     | SPOILER/SPEEDBRAKE SERVO ACTUATOR THERMOSTAT VALVE ASSEMBLY REPLACEMENT         |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-10     | ROLL SPOILER BELLCRANK CABLE GUARD PIN INSPECTION                               |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    | MTH 06-Mar-1987 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 194         |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SL 650-27-11 R01 | FLAP SYSTEM INSPECTION                                                          |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-12 R01 | FLAP ASYMMETRY BRAKE MODIFICATION                                               |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-13 R01 | FLAP ACTUATOR REPLACEMENT, FLAP BEARING BLOCK AND FLAP CARRIAGE INSPECTION      |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-14 R01 | MODIFICATION OF FLAP TEXT BOX                                                   |               |            | MANDATORY      |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-15     | INCORPORATION OF "J" MODIFICATION INTO FLAP SYSTEM CONTROL UNIT                 |               |            | RECOMMENDED    | MTH 25-Apr-1988 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 749         |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SL 650-27-16     | HORIZONTAL STABILIZER PRIMARY TRIM ACTUATOR WIRE BUNDLE INSPECTION/MODIFICATION |               |            | RECOMMENDED    | MTH 05-Aug-1988 |        | A/R         |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 905         |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SL 650-27-18     | AILERON FORCE LINK DISCONNECT SWITCH FUNCTIONAL TEST                            |               |            | RECOMMENDED    | MTH 10-Feb-1989 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 1102        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SL 650-27-19 R01 | FLAP CARRIAGE ROLLER INSTALLATION                                               |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-21     | POWERED AILERON BOOST OPERATIONAL CHECK                                         |               |            | RECOMMENDED    | MTH 21-Nov-1989 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 1370        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SL 650-27-24     | MODEL 650 FLAP SYSTEM EVALUATION                                                |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-25 R01 | CONTROL COLUMN TORQUE TUBES INSPECTION AND FINISH REWORK                        |               |            | RECOMMENDED    |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-29 R03 | HORIZONTAL STABILZIER PRIMARY TRIM ACTUATOR FITTING ASSEMBLY RELOCATION         |               |            | MANDATORY      |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SL 650-27-38     | ELEVATOR ATTACH BOLT INSPECTION                                                 |               |            | MANDATORY      | MTH 22-Feb-2001 |        | -           |         |             | Complete |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-28-09     | ANTI-ICING ADDITIVE SYSTEM BLEED SHUTOFF VALVE INSTALLATION                     |               |            | MANDATORY      | MTH 27-May-1987 |        | A/R         |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 317         |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code         | Description                                                                                                                                          | Part Number | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position          | Drawing # / Task #                                                                                                                                   | City        | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-28-16 R02  | MODIFICATION TO ALLOW SINGLE POINT REFUELING DURING APU OPERATION                                                                                    |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-28-24      | WING FUEL FILLER CAP ADAPTER STATIC BONDING INSPECTION/IMPROVEMENT                                                                                   |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      | MTH 06-Mar-1987 |        | A/R         |         |             | Complete |
|                   |                                                                                                                                                      |             |            |                | HRS 194         |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| SB 650-28-25 R05  | VENT FLOAT VALVE REPLACEMENT                                                                                                                         |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-28-26 R03  | WING TANKS PRESSURE RELIEF VALVE RELOCATION AND STANDPIPE INSTALLATION                                                                               |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-28-27      | VENT LINE AND CHECK VALVE MODIFICATION AND IMPROVED VENT FLOAT VALVE INSTALLATION                                                                    |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | RECOMMENDED    | MTH 08-Aug-1989 |        | A/R         |         |             | Complete |
|                   |                                                                                                                                                      |             |            |                | HRS 1291        |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| SB 650-28-28 R02  | SCAVENGER EJECTOR PUMP ALIGNMENT PIN REMOVAL                                                                                                         |             |            |                |                 |        | A/R         |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      |                 |        |             |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-28-32 LEFT | BOOST PUMP INSTALLATION MODIFICATION                                                                                                                 |             |            |                | MTH 14-May-2003 |        | A/R         |         |             | Complete |
|                   |                                                                                                                                                      |             |            | RECOMMENDED    | HRS 5629        |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| ASL 650-28-07     | INSPECTION OF LOW FUEL PRESSURE SWITCH INSTALLATION                                                                                                  |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      | MTH 10-Mar-1987 |        | A/R         |         |             | Complete |
|                   |                                                                                                                                                      |             |            |                | HRS 202         |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| ASL 650-28-11 R01 | TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO SUPPORT INC., OVERHAUL OF AIRBORNE FUEL PUMPS |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| ASL 650-28-11 R02 | TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO SUPPORT INC., OVERHAUL OF AIRBORNE FUEL       |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      | MTH 29-Aug-1996 |        | A/R         |         |             | Complete |
|                   |                                                                                                                                                      |             |            |                | HRS 3648        |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| SL CIL-28-01      | FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS                                                                         |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | INFORMATIONAL  |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SL 650-28-08      | INSPECTION OF FUEL FILLER CAP ADAPTER                                                                                                                |             |            |                | MTH 06-Jul-1988 |        | -           |         |             | Complete |
|                   |                                                                                                                                                      |             |            | RECOMMENDED    | HRS 869         |        |             |         |             |          |
|                   | MOC : COMPLIED WITH                                                                                                                                  |             |            |                |                 |        |             |         |             |          |
| SL 650-28-09      | LOW FUEL PRESSURE SWITCH INSPECTION/REPLACEMENT                                                                                                      |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | MANDATORY      |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-24-29 R02  | NOSE AND MAIN GEAR WHEEL WELL WIRE BUNDLE REPLACEMENT                                                                                                |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | OPTIONAL       |                 |        | -           |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |
| SB 650-29-10 R04  | HYDRAULIC POWER - AUXILIARY HYDRAULIC PUMP REPLACEMENT                                                                                               |             |            |                |                 |        |             |         |             |          |
|                   |                                                                                                                                                      |             |            | OPTIONAL       |                 |        | A/R         |         |             |          |
|                   | MOC :                                                                                                                                                |             |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 650-29-11          | AUXILIARY HYDRAULIC PRESSURE DUMP VALVE REPLACEMENT                                                         |      |         | RECOMMENDED                   | MTH 08-Aug-1989<br>HRS 1291               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-12 R01      | HYDRAULIC TEMPERATURE SYSTEM MONITOR MODIFICATION                                                           |      |         | MANDATORY                     |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-12          | HYDRAULIC TEMPERATURE SYSTEM MONITOR MODIFICATION                                                           |      |         | MANDATORY                     | MTH 04-Mar-1991<br>HRS 1675               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-13 R01      | TRANSMITTAL OF ALLEN AIRCRAFT PRODUCTS, INC. SERVICE BULLETIN 6S121-29-01, SHUTTLE VALVE PISTON REPLACEMENT |      |         | RECOMMENDED                   | MTH 22-Aug-1997<br>HRS 4029               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-13          | TRANSMITTAL OF ALLEN AIRCRAFT PRODUCTS, INC. SERVICE BULLETIN 6S121-29-01, SHUTTLE VALVE PISTON REPLACEMENT |      |         | RECOMMENDED                   | MTH 22-Aug-1997<br>HRS 4029               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-14          | HYDRAULIC RESERVOIR REPLACEMENT                                                                             |      |         | OPTIONAL                      | MTH 23-Dec-2011<br>HRS 7585.2<br>LDG 6425 |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-17          | LANDING GEAR HYDRAULIC LINE RELIEF VALVE INSTALLATION                                                       |      |         | RECOMMENDED                   | MTH 05-Nov-2007<br>HRS 6701               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-29-18 R02      | LANDING GEAR HYDRAULIC LINE RELIEF VALVE INSTALLATION                                                       |      |         | RECOMMENDED                   |                                           |                | A/R            |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - BY SERIAL NUMBER N/A PER AIRCRAFT S/N</b>                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-29-01<br>R1 | F.S. 452 HYD INSP                                                                                           |      |         |                               | MTH 06-Mar-1987<br>HRS 194                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-29-01 R02      | HYDRAULIC SYSTEM PLUMBING INSPECTION                                                                        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-29-04          | HYDRAULIC SYSTEM HOSE INSPECTION                                                                            |      |         | RECOMMENDED                   | MTH 05-Aug-1988<br>HRS 905                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-29-05          | HYDRAULIC RESERVOIR REPLACEMENT                                                                             |      |         | RECOMMENDED                   | MTH 25-Apr-1988<br>HRS 749                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-29-09          | HYDRAULIC HOSE INSPECTION/REPLACEMENT                                                                       |      |         | RECOMMENDED                   | MTH 12-May-2000                           |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-30-05 R01      | WING LEADING EDGE ANTI-ICE BLEED AIR SYSTEM MODIFICATION                                                    |      |         | RECOMMENDED                   |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-30-06 R01      | SUPERSEDES SB650-30-06                                                                                      |      |         | SUPERSEDED                    |                                           |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                                                   | Part Number | C/W Time 1 | Adj.           | TBO 1                   | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|---------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|-------------------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                                            | City        | Mod Lvl    | Part Serial No | C/W Time 2              | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-30-07     | WINDSHIELD ANTI-ICE VALVE MODIFICATION                                                                        |             |            |                |                         |        | -           |         |             |          |
|                  | OPTIONAL                                                                                                      |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-30-08 R04 | WINDSHIELD OVERHEAT WARNING SYSTEM IMPROVEMENT                                                                |             |            | RECOMMENDED    | MTH 23-Jul-1996         |        | A/R         |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 3647                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SB 650-30-09     | ANTI-ICE BLEED AIR CHECK VALVE REPLACEMENT                                                                    |             |            | RECOMMENDED    | MTH 09-Nov-1990         |        | A/R         |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 1581                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SB 650-30-10     | ANTI-ICE BLEED AIR CHECK VALVE REPLACEMENT                                                                    |             |            | RECOMMENDED    | MTH 06-Jul-1993         |        | A/R         |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 2529                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SL CIL-30-01 R01 | ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES                                                    |             |            |                |                         |        | -           |         |             |          |
|                  | INFORMATIONAL                                                                                                 |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB SL 650-30-05  | 2000 HR ALT BRG CHG                                                                                           |             |            |                | MTH 25-Apr-1989         |        | -           |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 1195                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SB SL 650-30-07  | WS ANTI-ICE SHUTOFF                                                                                           |             |            |                | MTH 26-Apr-1994         |        | -           |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 2823                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SL 650-30-04     | INSTALLATION OF IMPROVED HORIZONTAL STABILIZER HEATED                                                         |             |            | RECOMMENDED    | MTH 25-Apr-1988         |        | -           |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 749                 |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SB 650-31-05 R02 | REMOVE TOILET CIRCUIT BREAKER ANNUNCIATOR AND RELOCATE TAIL                                                   |             |            | RECOMMENDED    | FLOODLIGHT POWER SOURCE |        |             | A/R     |             |          |
|                  |                                                                                                               |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-31-09     | STAB DE-ICE ANNUNCIATOR LIGHT REPLACEMENT                                                                     |             |            | MANDATORY      | MTH 04-May-1990         |        | A/R         |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 1462                |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |
| SL CIL-31-01     | INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION |             |            |                |                         |        | -           |         |             |          |
|                  | INFORMATIONAL                                                                                                 |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-32-20 R01 | WHEEL REPLACEMENT PLUMBING AND LANDING GEAR PLUMBING AND WIRE BUNDLE ROUTING MODIFICATION                     |             |            | MANDATORY      |                         |        | A/R         |         |             |          |
|                  |                                                                                                               |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-32-21     | NITROGEN BOTTLE REPLACEMENT                                                                                   |             |            | OPTIONAL       |                         |        | -           |         |             |          |
|                  |                                                                                                               |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-32-22 R02 | NOSE GEAR UPLOCK HOOK REPLACEMENT                                                                             |             |            | OPTIONAL       |                         |        | -           |         |             |          |
|                  |                                                                                                               |             |            |                |                         |        |             |         |             |          |
|                  | MOC :                                                                                                         |             |            |                |                         |        |             |         |             |          |
| SB 650-32-23     | NOSE GEAR STEERING ACCUMULATOR LINE AND PRE-CHARGE INDICATOR MODIFICATION                                     |             |            | OPTIONAL       | MTH 21-Aug-1987         |        | -           |         |             | Complete |
|                  |                                                                                                               |             |            |                | HRS 425                 |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                           |             |            |                |                         |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                                              | Part Number | C/W Time 1  | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|----------------------------------------------------------------------------------------------------------|-------------|-------------|----------------|------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                                                       | City        | Mod Lvl     | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-32-25 R01 | NOSE GEAR STEERING ACCUMULATOR BLEED VALVE INSTALLATION<br>OPTIONAL                                      |             |             |                |            |        | -           |         |             |          |
|                  | MOC :                                                                                                    |             |             |                |            |        |             |         |             |          |
| SB 650-32-27 R03 | FULL TIME NOSE WHEEL STEERING MODIFICATION<br>MANDATORY                                                  | MTH         | 28-Apr-1990 |                |            | A/R    |             |         |             | Complete |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-28 R01 | NOSE WHEEL STEERING SWITCH ANNUNCIATOR TEST WIRING MODIFICATION<br>MANDATORY                             | MTH         | 10-Feb-1989 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 1102        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-29 R02 | NOSE GEAR UPLOCK SPRING REPLACEMENT<br>RECOMMENDED                                                       | MTH         | 10-Feb-1989 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 1102        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-30 R01 | MAIN LANDING GEAR OLEO INSPECTION AND LOCK RING RETENTION<br>MANDATORY                                   | MTH         | 27-Sep-1989 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 1336        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-31     | NOSE GEAR UPLOCK EMERGENCY RELEASE CABLE REPLACEMENT<br>RECOMMENDED                                      | MTH         | 10-Feb-1989 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 1102        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-32 R03 | MAIN LANDING GEAR OLEO MODIFICATION<br>RECOMMENDED                                                       | MTH         | 29-May-1991 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 1754        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-35 R03 | MAIN LANDING GEAR TRUNNION PIN REPLACEMENT<br>RECOMMENDED                                                |             |             |                |            | A/R    |             |         |             |          |
|                  | MOC :                                                                                                    |             |             |                |            |        |             |         |             |          |
| SB 650-32-36     | MAIN LANDING GEAR EXTENSION SHUTTLE VALVE RESTRICTOR REPLACEMENT<br>OPTIONAL                             |             |             |                |            | -      |             |         |             |          |
|                  | MOC :                                                                                                    |             |             |                |            |        |             |         |             |          |
| SB 650-32-37 R01 | BRAKE HOSE CLAMP CHANGE<br>RECOMMENDED                                                                   | MTH         | 10-Feb-1995 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 3083        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-37     | BRAKE HOSE CLAMP CHANGE<br>RECOMMENDED                                                                   |             |             |                |            | A/R    |             |         |             |          |
|                  | MOC :                                                                                                    |             |             |                |            |        |             |         |             |          |
| SB 650-32-38 R01 | MAIN LANDING GEAR HYDRAULIC DYNAMIC TENSION LOAD RELIEF MODIFICATION<br>RECOMMENDED                      |             |             |                |            | A/R    |             |         |             |          |
|                  | MOC :                                                                                                    |             |             |                |            |        |             |         |             |          |
| SB 650-32-39     | MAIN LANDING GEAR ACTUATOR HOSE ASSEMBLY MODIFICATION AND ACTUATOR INSPECTION/REPLACEMENT<br>RECOMMENDED | MTH         | 15-May-1995 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 3168        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-40     | NOSE LANDING GEAR DOOR TORQUE TUBE BOLT REPLACEMENT<br>RECOMMENDED                                       | MTH         | 23-Oct-1995 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 3348        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |
| SB 650-32-41     | MAIN LANDING GEAR UP-AND-LOCK SWITCH WIRE BUNDLE INSPECTION/REPLACEMENT<br>RECOMMENDED                   | MTH         | 17-May-1996 |                |            | A/R    |             |         |             | Complete |
|                  |                                                                                                          | HRS         | 3559        |                |            |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                                                                      |             |             |                |            |        |             |         |             |          |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code          | Description                                                                            | Part Number | C/W Time 1  | Adj.           | TBO 1       | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|--------------------|----------------------------------------------------------------------------------------|-------------|-------------|----------------|-------------|--------|-------------|---------|-------------|----------|
| Position           | Drawing # / Task #                                                                     | City        | Mod Lvl     | Part Serial No | C/W Time 2  | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| ASB 650-32-42      | MAIN LANDING GEAR TIRE INSPECTION/REPLACEMENT                                          |             |             |                |             |        | -           |         |             |          |
|                    | MANDATORY                                                                              |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SB 650-32-43 R01   | MAIN LANDING GEAR BRAKE AND WHEEL MODIFICATION/REPLACEMENT                             |             |             |                |             |        | -           |         |             |          |
|                    | OPTIONAL                                                                               |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SB 650-32-44       | LANDING GEAR PNEUMATIC STORAGE BOTTLE/EMERGENCY BRAKE MANIFOLD MODIFICATION            |             |             |                |             |        | -           |         |             |          |
|                    | OPTIONAL                                                                               |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SB 650-32-46 R03   | LANDING GEAR LOGIC MODIFICATION                                                        |             | RECOMMENDED |                |             |        | A/R         |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SB 650-32-47       | MAIN LANDING GEAR LOCKING SIDEBRACE REPLACEMENT                                        |             |             |                |             |        | A/R         |         |             | Complete |
|                    | MANDATORY                                                                              |             | MTH         | 17-Aug-2001    |             |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SB ASL 650-32-42   | G TIRE INSP/REPLACE                                                                    |             |             | MTH            | 21-Nov-1995 |        | -           |         |             | Complete |
|                    |                                                                                        |             |             | HRS            | 3382        |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| ASL 650-32-19      | GOODYEAR TIRE REMOVAL                                                                  |             | MANDATORY   | MTH            | 28-Sep-1988 |        | A/R         |         |             | Complete |
|                    |                                                                                        |             |             | HRS            | 1008        |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SL CIL-32-01       | LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL                                         |             |             |                |             |        | -           |         |             |          |
|                    | INFORMATIONAL                                                                          |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SL CIL-32-04       | WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION                                  |             |             |                |             |        | -           |         |             |          |
|                    | INFORMATIONAL                                                                          |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SL CIL-32-06       | LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION            |             |             |                |             |        | -           |         |             |          |
|                    | INFORMATIONAL                                                                          |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SB SL 650-32-11    | MLG WHEEL INSPECTION                                                                   |             |             | MTH            | 06-Mar-1987 |        | -           |         |             | Complete |
|                    |                                                                                        |             |             | HRS            | 194         |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SB SL 650-32-12    | BFG SL 1370                                                                            |             |             | MTH            | 06-Mar-1987 |        | -           |         |             | Complete |
|                    |                                                                                        |             |             | HRS            | 194         |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SB SL 650-32-30 R1 | TEIJIN SEIKI NLG ACT                                                                   |             |             | MTH            | 15-May-1995 |        | -           |         |             | Complete |
|                    |                                                                                        |             |             | HRS            | 3168        |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SL 650-32-06 R03   | MAIN LANDING GEAR TIRE PRESSURE GAUGE                                                  |             |             |                |             |        | -           |         |             |          |
|                    | RECOMMENDED                                                                            |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SL 650-32-13       | LEFT-HAND BRAKE PLUMBING INSTALLATION INSPECTION AND BRAKE LINE REROUTING AND LABELING |             |             |                |             |        |             |         |             |          |
|                    | MANDATORY                                                                              |             | MTH         | 26-Mar-1987    |             |        | A/R         |         |             | Complete |
|                    |                                                                                        |             | HRS         | 231            |             |        |             |         |             |          |
|                    | MOC : COMPLIED WITH                                                                    |             |             |                |             |        |             |         |             |          |
| SL 650-32-14       | NOSE GEAR HYDRAULIC RESTRICTOR REMOVAL                                                 |             |             |                |             |        | -           |         |             |          |
|                    | OPTIONAL                                                                               |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |
| SL 650-32-20       | NOSE WHEEL STEERING MAINTENANCE AND TROUBLESHOOTING                                    |             |             |                |             |        | -           |         |             |          |
|                    | OPTIONAL                                                                               |             |             |                |             |        |             |         |             |          |
|                    | MOC :                                                                                  |             |             |                |             |        |             |         |             |          |

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                   | Description                                                                                                                                | Part Number       | C/W Time 1                    | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains  |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------------|--------|-------|-------|-------------|----------|
| Position                    | Drawing # / Task # City Mod Lvl                                                                                                            | Part Serial No    | C/W Time 2                    | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains  |
| SL 650-32-21                | MAIN LANDING GEAR OLEO RIVET INSPECTION<br>MANDATORY                                                                                       | MTH<br>HRS        | 27-Sep-1989<br>1336           |        | -     |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-27                | BLOWDOWN BOTTLE CONTROL CABLE INTERFERENCE RELIEF<br>RECOMMENDED                                                                           | MTH<br>HRS        | 18-Dec-1991<br>1956           |        | -     |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-30 R04            | TEIJIN SEIKI NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/REPLACEMENT<br>RECOMMENDED                                       |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-34                | ONE TIME MAIN LANDING GEAR TIRE PART NUMBER INSPECTION<br>RECOMMENDED                                                                      | MTH<br>HRS        | 28-Feb-1997<br>3840           |        | -     |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-35                | NOSE GEAR SPADE DOOR BELLCRANK BUSHING REPLACEMENT<br>MANDATORY                                                                            | MTH<br>LDG        | 02-Feb-1998<br>3998           |        | -     |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-41                | MAIN LANDING GEAR TIRE INSPECTION<br>RECOMMENDED                                                                                           | MTH<br>HRS        | 30-Apr-2003<br>5625           |        | -     |       |             | N/A      |
| <b>MOC : NOT APPLICABLE</b> |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-45                | EMERGENCY GEAR RELEASE INSPECTION<br>MANDATORY                                                                                             | MTH<br>HRS<br>LDG | 12-May-2011<br>7469.7<br>6349 |        | A/R   |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SL 650-32-47 R01            | TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1502-32-4, REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS<br>RECOMMENDED |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-09 R01            | INDIRECT LIGHTING POWER SUPPLY REPLACEMENT<br>RECOMMENDED                                                                                  | MTH<br>HRS        | 25-Apr-1988<br>749            |        | A/R   |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-10 R01            | EMERGENCY LIGHTING BATTERY PACK RELOCATION<br>OPTIONAL                                                                                     |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-11                | EMERGENCY LIGHTING BATTERY BOX ASSEMBLIES NUTPLATE REMOVAL<br>RECOMMENDED                                                                  | MTH<br>HRS        | 25-Apr-1988<br>749            |        | A/R   |       |             | Complete |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-12 R03            | PASSENGER SERVICE UNIT LIGHT WIRE ROUTING MODIFICATION<br>RECOMMENDED                                                                      |                   |                               |        | A/R   |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-13                | REPLACEMENT OF PW-28S-40CC-2 POWER SUPPLIES IN INTERIOR CABINTRY<br>OPTIONAL                                                               |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-16                | CENTER PANEL 5 VOLT LAMP DIMMER REPLACEMENT<br>OPTIONAL                                                                                    |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |
| SB 650-33-24 R03            | GRIMES LANDING LIGHT IMPROVEMENT<br>OPTIONAL                                                                                               |                   |                               |        | -     |       |             |          |
| <b>MOC :</b>                |                                                                                                                                            |                   |                               |        |       |       |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 650-33-25          | G-SWITCH REPLACEMENT                                                                                         |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-33-26 R01      | LANDING GEAR TAXI LIGHT REALIGNMENT                                                                          |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB SL 650-33-01       | LANDING LIGHT MOD                                                                                            |      |         |                               | MTH 09-Nov-1990<br>HRS 1581 |                | -              |                |                            | Complete           |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-33-02 R02      | LANDING LIGHT IMPROVEMENT PROGRAM                                                                            |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-05          | COPILOT ALTIMETER REPLACEMENT - MILLIBAR                                                                     |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-107 R02     | REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION                                            |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-107         | REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION                                            |      |         | OPTIONAL                      | MTH 27-Sep-2002<br>HRS 5468 |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-112         | NAVIGATION - SIGMA-TEK CONTROL PANEL INSTALLATION                                                            |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-113         | TCAS 2000 INTEFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0                                |      |         | MANDATORY                     |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-114         | TCAS 2000 SOFTWARE UPDATE TO VERSION 7.1                                                                     |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-115         | NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-25          | COLLINS PROLINE II CTL DISPLALY MANUAL DIMMING MODIFICATION                                                  |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-29 R01      | GNS-1000 E-FIELD ANTENNA INSTALLATION                                                                        |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-31          | NAV 2 COAXIAL CABLE REPLACEMENT                                                                              |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-35 R02      | FMS ROLL STEERING MODIFICATION                                                                               |      |         | RECOMMENDED                   | MTH 25-Apr-1988<br>HRS 749  |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-36 R03      | TRANSPONDER DUAL ANTENNA INSTALLATION                                                                        |      |         |                               |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-47 R03      | TRANSPONDER ANTENNA RELOCATION                                                                               |      |         | RECOMMENDED                   | MTH 08-Aug-1989<br>HRS 1291 |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                 |      |         |                               |                             |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 650-34-49 R03      | RECOGNITION LIGHT FILTER INSTALLATION AND VLF NOISE REDUCTION IMPROVEMENTS                                                                                               |      |         | RECOMMENDED                   | MTH 21-Feb-1992<br>HRS 2034 |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                               |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-52          | BAROMETRIC SWITCHES RELOCATION AND TEST PORT INSTALLATION                                                                                                                |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-55 R07      | STARTER/GENERATOR AND GCU FILTER INSTALLATION                                                                                                                            |      |         | RECOMMENDED                   |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| ASB 650-34-56 R01     | VG14A VERTICAL GYRO INSPECTION                                                                                                                                           |      |         | MANDATORY                     |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-73          | HONEYWELL RADIO ALTIMETER ANTENNA REPLACEMENT                                                                                                                            |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-80 R01      | STATIC HEATER CURRENT SENSOR REPLACEMENT                                                                                                                                 |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-85 R01      | STARTER/GENERATOR VLF FILTER CAPACITOR RELOCATION                                                                                                                        |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-34-94          | COPILOT ALTIMETER INSTALLATION - KOLLSMAN                                                                                                                                |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SB ASL 650-34-56 R1   | VG14A VERT GYRO INSP                                                                                                                                                     |      |         |                               | MTH 21-Nov-1989<br>HRS 1370 |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                               |      |         |                               |                             |                |                |                |                            |                    |
| SB ASL 650-34-56      | VG14A VERT GYRO INSP                                                                                                                                                     |      |         |                               | MTH 10-Nov-1989<br>HRS 1367 |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                               |      |         |                               |                             |                |                |                |                            |                    |
| ASL 650-34-21         | TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001                                                                                                               |      |         | MANDATORY                     | MTH 11-Apr-2003             |                | A/R            |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE</b>                                                                                                                                              |      |         |                               |                             |                |                |                |                            |                    |
| SL CIL-34-09 R01      | NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE INFORMATION LETTER FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SL CIL-34-09          | NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION           |      |         | INFORMATIONAL                 |                             |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                             |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-34-03          | COLLINS VIR-32 NAVIGATION RECEIVER SERVICE BULLETIN 14                                                                                                                   |      |         | RECOMMENDED                   | MTH 27-Jan-1988<br>HRS 619  |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                               |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-34-04          | COLLINS ANT60 ADF ANTENNA REPLACEMENT                                                                                                                                    |      |         | RECOMMENDED                   | MTH 27-Jan-1988<br>HRS 619  |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                               |      |         |                               |                             |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                                                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                   | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-34-09          | DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION                                                                                                                                                      |      |         | RECOMMENDED                   | MTH 23-Aug-1990<br>HRS 1515                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-34-22          | GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPDATE                                                                                                                                                               |      |         | RECOMMENDED                   | MTH 05-Nov-2004<br>HRS 6081                |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                      |      |         |                               |                                            |                |                |                |                            |                    |
| SL CIL-35-05          | OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001                                                                                                                                                       | CCS  |         | MANDATORY                     | DAYS 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARA INSTALADAS,PILOTO P/N:MAC 10-16-101 S/N: 92286 Y COPILOTO P/N: MC 10-15-109 S/N: 57797 POSEEMASCARAS DE ACUERDO AL SB MCF-SBN-35-001.</b> |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-35-01          | PASSENGER OXYGEN MASK INSPECTION                                                                                                                                                                                 |      |         | RECOMMENDED                   | MTH 28-Feb-1990<br>HRS 1430                |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-35-03          | EROS QUICK DONNING MASK-REGULATOR LOCK CHANGE                                                                                                                                                                    |      |         | RECOMMENDED                   |                                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                                                                     |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-35-09 R02      | OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240                                                                                                                                               |      |         | MANDATORY                     |                                            |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                                                                     |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-35-09          | OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240                                                                                                                                               |      |         | MANDATORY                     | MTH 02-Nov-2011<br>HRS 7548.3<br>LDG 6405  |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH - N/A BY S/N OF UNITS INSTALLED ON AIRCRAFT AT THIS TIME</b>                                                                                                                              |      |         |                               |                                            |                |                |                |                            |                    |
| SB 650-36-02          | SERVICE AIR SYSTEM MODIFICATION                                                                                                                                                                                  |      |         | OPTIONAL                      |                                            |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                                                                                                     |      |         |                               |                                            |                |                |                |                            |                    |
| SB SL 650-36-05       | V BND CLMPINSP/REPL                                                                                                                                                                                              |      |         |                               | MTH 29-Jan-1993<br>HRS 2352                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-36-01          | ENGINE MOUNTED HIGH PRESSURE BLEED AIR DUCT HEAT SHIELD REPLACEMENT                                                                                                                                              |      |         | RECOMMENDED                   | MTH 16-Jul-1991<br>HRS 1798                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-36-02          | SERVICE AIR SYSTEM FILTER INSPECTION                                                                                                                                                                             |      |         | RECOMMENDED                   | MTH 05-Aug-1988<br>HRS 905                 |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-36-03          | MODEL 650 LOW PRESSURE CHECK VALVE INSPECTION/REPLACEMENT                                                                                                                                                        |      |         | RECOMMENDED                   | MTH 20-Aug-1990<br>HRS 1515                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |
| SL 650-36-04          | PYLON BLEED AIR COLLECTOR ASSEMBLY INSPECTION/MODIFICATION                                                                                                                                                       |      |         | RECOMMENDED                   | MTH 16-Jul-1991<br>HRS 1798                |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                       |      |         |                               |                                            |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position    | Description<br>Drawing # / Task #                                                                                                                                                                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-38-01             | TOILET ACCESS DOOR MODIFICATION                                                                                                                                                                                                       |      |         | OPTIONAL                      |                             |                | -              |                |                            |                    |
|                          | <b>MOC :</b>                                                                                                                                                                                                                          |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-02             | TAILCONE EXHAUST DOOR MODIFICATION                                                                                                                                                                                                    |      |         |                               | MTH 29-Jan-1993             |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-12 R02         | APU RPM/TEMPERATURE INDICATOR CONNECTOR DELETION                                                                                                                                                                                      |      |         | MANDATORY                     |                             |                | A/R            |                |                            |                    |
|                          | <b>MOC :</b>                                                                                                                                                                                                                          |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-13 R01         | APU EXHAUST DUCT SEAL REPLACEMENT                                                                                                                                                                                                     |      |         | RECOMMENDED                   |                             |                | A/R            |                |                            |                    |
|                          | <b>MOC :</b>                                                                                                                                                                                                                          |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-14 R03         | INFLIGHT APU FIRE DETECTOR INSTALLATION MODIFICATION                                                                                                                                                                                  |      |         | OPTIONAL                      |                             |                | A/R            |                |                            |                    |
|                          | <b>MOC :</b>                                                                                                                                                                                                                          |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-15             | BATTERY OVERHEAT APU SHUTDOWN WIRING MODIFICATION                                                                                                                                                                                     |      |         | RECOMMENDED                   | MTH 25-Apr-1989<br>HRS 1195 |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-17             | TAILCONE EXHAUST DOOR SPRING MOUNT IMPROVEMENT                                                                                                                                                                                        |      |         | RECOMMENDED                   | MTH 08-Aug-1989<br>HRS 1291 |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-18             | BATTERY OVERHEAT APU SHUTDOWN MODULE WIRING MODIFICATION                                                                                                                                                                              |      |         | RECOMMENDED                   | MTH 25-Apr-1989<br>HRS 1195 |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-19 R03         | APU DRAIN AND VENT LINES MODIFICATION                                                                                                                                                                                                 |      |         | RECOMMENDED                   | MTH 09-Nov-1990<br>HRS 1581 |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB 650-49-29             | PATS APU ESU WIRING MODIFICATION                                                                                                                                                                                                      |      |         | RECOMMENDED                   |                             |                | A/R            |                |                            |                    |
|                          | <b>MOC :</b>                                                                                                                                                                                                                          |      |         |                               |                             |                |                |                |                            |                    |
| SB SL 650-49-17<br>(APU) | INSP FUEL MANIFOLD                                                                                                                                                                                                                    |      |         |                               | MTH 20-Sep-1990             |                | -              |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SB SL 650-49-17          | INSP FUEL MANIFOLD                                                                                                                                                                                                                    |      |         |                               | MTH 20-Sep-1990<br>HRS 1539 |                | -              |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-49-14             | INSPECTION AND REPLACEMENT OF I.M.C. MANUFACTURED FUEL SOLENOID VALVES                                                                                                                                                                |      |         | RECOMMENDED                   | MTH 02-Mar-1990             |                | A/R            |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-49-18             | REPLACEMENT OF START BYPASS VALVE MOUNTING BOLTS (CESSNA APU)                                                                                                                                                                         |      |         | RECOMMENDED                   | MTH 04-Mar-1991<br>HRS 1675 |                | -              |                |                            | Complete           |
|                          | <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                            |      |         |                               |                             |                |                |                |                            |                    |
| SL 650-49-29             | TRANSMITTAL OF ALLIEDSIGNAL SERVICE BULLETIN GTCP36-49-7540, AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - ONE TIME INSPECTION/REPLACEMENT OF THE COUPLING, PART NO. 234-511-9059, RETAINING BOLT 9FUEL CONTROL TO OIL PUMP FLANGE) |      |         | RECOMMENDED                   | MTH 23-Apr-2001<br>HRS 5374 |                | -              |                |                            | N/A                |
|                          | <b>MOC :</b> NOT APPLICABLE                                                                                                                                                                                                           |      |         |                               |                             |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position  | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                                              | Part Number<br>Part Serial No        | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-49-31           | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN GTCP 36-49-7717, GAS TURBINE ENGINE - ONE TIME INSPECTION/REPLACEMENT OF THE COUPLING CLAMP, PART NUMBER 234-511-9059, T-BOLT (FUEL CONTROL TO LUBE PUMP FLANGES) | RECOMMENDED MTH 16-Jun-2003          |                          |                | -              |                |                            | N/A                |
|                        | <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SIL APS500-523         | LIFE LIMITED COMPONENT NOTIFICATION                                                                                                                                                                         |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SIL APS500-524         | APS500 SPARE PARTS SUPPORT - NEW SPARE PARTS DISTRIBUTION RESPONSIBILITIES                                                                                                                                  |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SIL GEN-RADIAL-APU-041 | APU TECHNICAL PUBLICATIONS PREVIOUSLY SUPPORTED BY GULFSTREAM AEROSPACE CORPORATION ARE NOW AVAILABLE ON MYP&WC PORTAL AND MAY BE SUBJECT TO CHARGE                                                         |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB T-62T-49-76 R14     | REPLACEMENT OF APU LIFE-LIMITED COMPONENTS (TURBINE WHEEL AND COMPRESSOR WHEEL) CATEGORY 3                                                                                                                  |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB T-62T-49-76 R15     | REPLACEMENT OF APU LIFE-LIMITED COMPONENTS (TURBINE WHEEL AND COMPRESSOR WHEEL) CATEGORY 3                                                                                                                  |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB T-62T-49-76 R16     | REPLACEMENT OF APU LIFE-LIMITED COMPONENTS (TURBINE WHEEL AND COMPRESSOR WHEEL) CATEGORY 3                                                                                                                  |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB T-62T-49-76 R17     | REPLACEMENT OF APU LIFE-LIMITED COMPONENTS (TURBINE WHEEL AND COMPRESSOR WHEEL) CATEGORY 3                                                                                                                  |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-14 R03       | CABIN DOOR TRIM REPLACEMENT                                                                                                                                                                                 | RECOMMENDED                          |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-15 R02       | CABIN DOOR MECHANISM SEALING AND IMPROVEMENTS MANDATORY                                                                                                                                                     |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-16 R02       | CABIN, BAGGAGE, ACCESSORY, APU EXHAUST, AND TAILCONE EXHAUST DOORS WARNING SYSTEM IMPROVEMENTS                                                                                                              | RECOMMENDED MTH 21-Nov-1989 HRS 1370 |                          |                | -              |                |                            | Complete           |
|                        | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                                      |                          |                |                |                |                            |                    |
| SB 650-52-17           | CABIN DOOR LOWER FORWARD PIN SWITCH ACTUATOR REPLACEMENT                                                                                                                                                    | RECOMMENDED MTH 25-Apr-1988 HRS 749  |                          |                | -              |                |                            | Complete           |
|                        | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                                      |                          |                |                |                |                            |                    |
| SB 650-52-18           | CABIN DOOR PIN MONITOR SYSTEM INSTALLATION OPTIONAL                                                                                                                                                         |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-19 R03       | DOOR WARNING SYSTEM ANNUNCIATOR MODIFICATION AND RIGHT NOSE AVIONICS DOOR MECHANICAL LATCH INSTALLATION OPTIONAL                                                                                            |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-21 R03       | CABIN DOOR FIXED STEP INSTALLATION OPTIONAL                                                                                                                                                                 |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |
| SB 650-52-22 R01       | CABIN DOOR COUNTERBALANCE SPRING REPLACEMENT RECOMMENDED                                                                                                                                                    |                                      |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                                                                                                                |                                      |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                    | Part Number | C/W Time 1    | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|----------------------------------------------------------------|-------------|---------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                             | City        | Mod Lvl       | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-52-23     | CABIN DOOR SEAL VALVE MODIFICATION                             |             |               |                | MTH 08-Aug-1989 |        | -           |         |             | Complete |
|                  |                                                                |             | RECOMMENDED   |                | HRS 1291        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SB 650-52-25 R02 | CABIN DOOR ACTUATING MECHANISM MODIFICATION                    |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | RECOMMENDED   |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-26 R04 | CABIN DOOR SEAL SECONDARY VALVE INSTALLATION                   |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | RECOMMENDED   |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-28 R05 | CABIN DOOR SEAL FILTER INSTALLATION AND CHECK VALVE RELOCATION |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | RECOMMENDED   |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-30     | CABIN ENTRANCE DOOR RISER COVER REPLACEMENT                    |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | OPTIONAL      |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-32     | LOCK REPLACEMENT                                               |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | OPTIONAL      |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-36     | CABIN DOOR PIVOT BELLCRANK SCREW REPLACEMENT                   |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | OPTIONAL      |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-40 R02 | MAIN GEAR DOOR TO TRUNNION INTERFERENCE                        |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | DISCRETIONARY |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-52-41     | CABIN DOOR LATCH MECHANISM IMPROVEMENT                         |             |               |                | MTH 10-Feb-2004 |        | -           |         |             | Complete |
|                  |                                                                |             | RECOMMENDED   |                | HRS 5881        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SB 650-52-42 R03 | CABIN DOOR WARNING SYSTEM MODIFICATION                         |             |               |                | MTH 20-Aug-2004 |        | -           |         |             | Complete |
|                  |                                                                |             | MANDATORY     |                | HRS 6022        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SL 650-52-04     | MAIN CABIN DOOR X-RAY INSPECTION                               |             |               |                | MTH 26-Feb-1987 |        | A/R         |         |             | Complete |
|                  |                                                                |             | MANDATORY     |                | HRS 194         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SL 650-52-05     | ENTRANCE DOOR HINGE INSPECTION                                 |             |               |                | MTH 18-Dec-1991 |        | A/R         |         |             | Complete |
|                  |                                                                |             | RECOMMENDED   |                | HRS 1956        |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SB 650-53-10 R03 | TAILCONE BAGGAGE COMPARTMENT CEILING MODIFICATION              |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | OPTIONAL      |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-53-11     | AFT PRESSURE BULKHEAD RIVET INSPECTION/INSTALLATION            |             |               |                |                 |        | A/R         |         |             |          |
|                  |                                                                |             | MANDATORY     |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-53-14     | AFT AVIONICS WATER COVER INSTALLATION                          |             |               |                | MTH 05-Aug-1988 |        | A/R         |         |             | Complete |
|                  |                                                                |             | RECOMMENDED   |                | HRS 905         |        |             |         |             |          |
|                  | MOC : COMPLIED WITH                                            |             |               |                |                 |        |             |         |             |          |
| SB 650-53-15 R01 | NOSE GEAR UPLOCK HOOK AND ACTUATOR SUPPORT BRACKET REPLACEMENT |             |               |                |                 |        | -           |         |             |          |
|                  |                                                                |             | OPTIONAL      |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |
| SB 650-53-17 R01 | FS 342.00 FRAME DOUBLER INSTALLATION                           |             |               |                |                 |        | A/R         |         |             |          |
|                  |                                                                |             | MANDATORY     |                |                 |        |             |         |             |          |
|                  | MOC :                                                          |             |               |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                                                     | Part Number   | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|------------------|---------------------------------------------------------------------------------|---------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position         | Drawing # / Task #                                                              | City          | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 650-53-18 R01 | TAILCONE ACCESS DOOR OPENING FLUID DEFLECTOR INSTALLATION                       |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-19     | DROPPED AISLE FLOORBOARD INSPECTION MODIFICATION AND CARPET PADDING REPLACEMENT |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    | MTH 28-Apr-1989 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 1195        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-53-20 R01 | FLAP CONTROLLER AND GENERATOR CONTROL UNITS MOUNTING SPACERS INSTALLATION       |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-21     | CABIN DOOR FRAME DOUBLER INSPECTION AND FASTENER INSTALLATION                   |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | MANDATORY      | MTH 20-Aug-1990 |        | A/R         |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 1515        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-53-22     | RAM AIR INLET DUCT SEALING                                                      |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    | MTH 18-Dec-1991 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 1956        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-53-23     | AFT AVIONICS ENCLOSED WATER COVER INSTALLATION                                  |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-24 R01 | AFT CABIN UNDERFLOOR ACCESS IMPROVEMENT                                         |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-25 R02 | RADOME LIGHTNING DIVERTER STRIP INSTALLATION                                    |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-29     | BAGGAGE DOOR INSULATION IMPROVEMENT                                             |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    | MTH 31-Jul-1992 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 2187        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-53-33 R01 | SKID RAIL MODIFICATION                                                          |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | MANDATORY      |                 |        | A/R         |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-34     | TRIM ACTUATOR CONTROL MOISTURE COVER INSTALLATION                               |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-35     | TAILCONE ACCESS PANEL INSTALLATION                                              |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | OPTIONAL       |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-38 R01 | FS 368.00 RIVET INSPECTION/INSTALLATION                                         |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                  | MOC :                                                                           |               |            |                |                 |        |             |         |             |          |
| SB 650-53-39     | FUSLEAGE STATION 351.50 RIVET INSPECTION/INSTALLATION                           |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | MANDATORY      | MTH 15-May-1995 |        | A/R         |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 3168        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB 650-53-40 R01 | IMPROVED 'P' STATIC PROTECTION/LIGHTNING DIVERTER STRIP INSTALLATION            |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            | RECOMMENDED    | MTH 21-May-2003 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 5636        |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |
| SB SL 650-53-01  | N/G TRUNNION MOD                                                                |               |            |                |                 |        |             |         |             |          |
|                  |                                                                                 |               |            |                | MTH 25-Apr-1988 |        | -           |         |             | Complete |
|                  |                                                                                 |               |            |                | HRS 749         |        |             |         |             |          |
|                  | MOC :                                                                           | COMPLIED WITH |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code          | Description                                                                                      | Part Number                                                                 | C/W Time 1 | Adj.           | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|--------------------|--------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|------------|----------------|-----------------|--------|-------------|---------|-------------|----------|
| Position           | Drawing # / Task #                                                                               | City                                                                        | Mod Lvl    | Part Serial No | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 650-53-01 R01   | NOSE GEAR TRUNNION SUPPORT MODIFICATION                                                          |                                                                             |            |                |                 |        |             |         |             |          |
|                    |                                                                                                  |                                                                             |            | RECOMMENDED    |                 |        | -           |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SL 650-53-02       | FAIRING PANEL ASSEMBLY MODIFICATION AND FUEL QUANTITY INDICATION SYSTEM WIRING INSPECTION/REPAIR |                                                                             |            |                |                 |        |             |         |             |          |
|                    |                                                                                                  |                                                                             |            | RECOMMENDED    | MTH 05-Aug-1988 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            |                | HRS 905         |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SL 650-53-03       | CABIN BOND ASSEMBLY WINDOW OPENING INSPECTION/REPAIR                                             |                                                                             |            |                |                 |        |             |         |             |          |
|                    |                                                                                                  |                                                                             |            | MANDATORY      | MTH 29-Jan-1993 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            |                | HRS 2352        |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SL 650-53-05       | FUSELAGE - IMPROVEMENT FOR THE INSPECTION OF STRUCTURE UNDER THE TOILET FLOORBOARDS              |                                                                             |            |                |                 |        |             |         |             |          |
|                    |                                                                                                  |                                                                             |            | OPTIONAL       |                 |        | A/R         |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SB 650-54-05 R01   | COWL DOOR SUPPORT STRUT INSTALLATION                                                             |                                                                             |            |                |                 |        | -           |         |             |          |
|                    |                                                                                                  |                                                                             |            | OPTIONAL       |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SB 650-54-06       | COWL DOOR EDGES INSPECTION/REPAIR                                                                |                                                                             |            |                | MTH 08-Aug-1989 |        | A/R         |         |             | Complete |
|                    |                                                                                                  |                                                                             |            | RECOMMENDED    | HRS 1291        |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SB 650-55-06 R03   | HORIZONTAL STABILIZER CENTER SECTION REPAIR                                                      |                                                                             |            |                |                 |        | A/R         |         |             |          |
|                    |                                                                                                  |                                                                             |            | MANDATORY      |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SB 650-55-08 R03   | HORIZONTAL STABILIZER WIPER PLATE REPLACEMENT FOR IMPROVED CLOSURE                               |                                                                             |            |                |                 |        | -           |         |             |          |
|                    |                                                                                                  |                                                                             |            | OPTIONAL       |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SB 650-55-09       | HORIZONTAL STABILIZER WIPER GUIDE REPLACEMENT                                                    |                                                                             |            |                | MTH 25-Apr-1989 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            | MANDATORY      | HRS 1195        |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SB 650-55-10       | ELEVATOR CENTERING STRIP INSTALLATION                                                            |                                                                             |            |                | MTH 08-Aug-1989 |        | A/R         |         |             | Complete |
|                    |                                                                                                  |                                                                             |            | MANDATORY      | HRS 1291        |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SB 650-55-11 R02   | HORIZONTAL STABILIZER INTERSPAR RIB MODIFICATION AND SKIN DAMPENER INSTALLATION                  |                                                                             |            |                |                 |        | -           |         |             |          |
|                    |                                                                                                  |                                                                             |            | MANDATORY      |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| SB 650-55-13 R01   | ELEVATOR IDLER ATTACH STIFFENER SUPPORT RIVET REPLACEMENT                                        |                                                                             |            |                |                 |        | A/R         |         |             |          |
|                    |                                                                                                  |                                                                             |            | MANDATORY      |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| ASL 650-55-04 R01  | HORIZONTAL-STABILIZER ACTUATOR-CONTROLLER                                                        |                                                                             |            |                | MTH             |        | -           |         |             |          |
|                    |                                                                                                  |                                                                             |            | MANDATORY      |                 |        |             |         |             |          |
|                    | MOC :                                                                                            |                                                                             |            |                |                 |        |             |         |             |          |
| ASL 650-55-04 R02  | HORIZONTAL-STABILIZER ACTUATOR-CONTROLLER                                                        |                                                                             |            |                | MTH 30-Oct-2010 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            | MANDATORY      | HRS 7349.8      |        |             |         |             |          |
|                    |                                                                                                  |                                                                             |            |                | LDG 6282        |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH - PARTIALLY GENERAL -8 ACTUATOR IS NOT AVAILABLE AT THIS TIME |            |                |                 |        |             |         |             |          |
| SB SL 650-55-01    | HORZ STAB INSPECTION                                                                             |                                                                             |            |                | MTH 27-Aug-1986 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            |                | HRS 13          |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |
| SB SL 650-55-02 R1 | HORZ STAB BOLT INSP                                                                              |                                                                             |            |                | MTH 25-Apr-1988 |        | -           |         |             | Complete |
|                    |                                                                                                  |                                                                             |            |                | HRS 749         |        |             |         |             |          |
|                    | MOC :                                                                                            | COMPLIED WITH                                                               |            |                |                 |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                                 | Description                                                                                                        | Part Number | C/W Time 1 | Adj.           | TBO 1                        | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------------------------|--------|-------------|---------|-------------|----------|
| Position                                  | Drawing # / Task #                                                                                                 | City        | Mod Lvl    | Part Serial No | C/W Time 2                   | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB SL 650-55-02                           | HORZ STAB BOLT INSP                                                                                                |             |            |                | MTH 26-Apr-1988<br>HRS 749   |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-55-01 R01                          | HORIZONTAL STABILIZER UPPER CENTER SECTION FASTENER SKIN EDGE DISTANCE INSPECTION                                  |             |            |                | MTH 05-Mar-1987<br>HRS 194   |        | A/R         |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-55-02 R02                          | HORIZONTAL STABILIZER SCISSOR ATTACH PLATE BOLT INSPECTION                                                         |             |            |                |                              |        | A/R         |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-55-03                              | ELEVATOR SKIN DRAIN HOLE INSPECTION/INSTALLTION                                                                    |             |            |                | MTH 12-Aug-1997<br>HRS 4025  |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-56-04                              | OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION                                                                 |             |            |                | DAYS 30-Oct-2006<br>HRS 6511 |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-56-05                              | WINDSHIELD DELAMINATION                                                                                            |             |            | INFORMATIONAL  |                              |        | A/R         |         |             | N/A      |
| MOC : NOT APPLICABLE - BY SERIAL NUMBER - |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-57-06 R03                          | WS 88.00 INSPECTION AND MODIFICATION                                                                               |             |            |                | MTH 23-Aug-1995              |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-57-08 R05                          | FORWARD FAIRING TANK FUEL MIGRATION MODIFICATION                                                                   |             |            |                |                              |        | -           |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-57-09 R02                          | MAIN LANDING GEAR WHEEL WELL MODIFICATION                                                                          |             |            |                |                              |        | -           |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SL 650-57-02                              | AILERON DRAIN HOLE INSPECTION/INSTALLATION                                                                         |             |            |                | MTH 23-Sep-1998<br>HRS 4475  |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-02 R02                          | COWL DOOR LATCH REPLACEMENT                                                                                        |             |            | RECOMMENDED    |                              |        | A/R         |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-03 R01                          | LOWER COWL DOOR FASTENER INSTALLATION                                                                              |             |            |                |                              |        | -           |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-05 R01                          | FIRE SHIELD MODIFICATION                                                                                           |             |            | RECOMMENDED    |                              |        | -           |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-08 R02                          | ALL COMPOSITE AFT COWL MODIFICATION                                                                                |             |            |                |                              |        | -           |         |             |          |
| MOC :                                     |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-09<br>LEFT ENGINE               | HYBRID AFT COWL REINFORCEMENT                                                                                      |             |            | MANDATORY      | MTH 14-May-2003              |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |
| SB 650-71-11                              | COMPOSITE COWL AFT FIRESHIELD MODIFICATION TO ACCOMMODATE ALLIEDSIGNAL ENGINE FUEL FLEX TUBE ASSEMBLY INSTALLATION |             |            |                | MTH 23-Feb-1998<br>HRS 4245  |        | -           |         |             | Complete |
| MOC : COMPLIED WITH                       |                                                                                                                    |             |            |                |                              |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                                     | Description<br>Drawing # / Task #                                                                                                                                                                                          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 650-71-12 R01<br>LEFT ENGINE                                           | AFT COWLING MODIFICATION                                                                                                                                                                                                   |      |         | RECOMMENDED                   | MTH 31-Oct-2008<br>HRS 6981.8<br>LDG 6036 |                | -              |                |                            |                    |
| <b>MOC : DECLINED - CUSTOMER DOES NOT WISH TO ACCOMPLISH AT THIS TIME</b> |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-71-13 R01                                                          | REPLACEMENT OF COMPOSITE COWL DOORS                                                                                                                                                                                        |      |         | OPTIONAL                      |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                              |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| ASL 650-71-10<br>LEFT ENGINE                                              | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-72-A3748 ENGINE - COMPRESSOR SECTION - REPLACE SPECIFIC IDENTIFIED SECOND STAGE LOW PRESSURE COMPRESSOR (LPC2) AND THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTOR DISCS |      |         | MANDATORY                     | MTH 03-Mar-2009<br>HRS 7047.8<br>LDG 6069 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY SERIAL NUMBER</b>                            |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-71-02                                                              | INSPECTION OF NACELLE WIRE BUNDLE CONNECTORS                                                                                                                                                                               |      |         | RECOMMENDED                   | MTH 15-May-1995<br>HRS 3168               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-71-04 R01                                                          | COMPOSITE AFT COWL OUTER BYPASS DUCT INSPECTION                                                                                                                                                                            |      |         | MANDATORY                     | MTH 15-May-1995<br>HRS 3168               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-71-05                                                              | HYBRID AFT COWL INSPECTION                                                                                                                                                                                                 |      |         | MANDATORY                     | MTH 14-May-2003<br>HRS 5629               |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                               |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-71-08<br>LEFT ENGINE                                               | - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-72-3699 ENGINE - TURBINE SECTION - REMOVE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) ROTOR DISCS                                                                   |      |         | RECOMMENDED                   | MTH 06-Jun-2005<br>HRS 6199               |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                              |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-72-01 R02                                                          | ENGINE CONVERSION (-3B AND -3BR TO -3C AND -3CR)                                                                                                                                                                           |      |         | OPTIONAL                      | MTH 15-May-1995<br>HRS 3168               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-72-06                                                           | INSP FAN ROTOR ASSY                                                                                                                                                                                                        |      |         |                               | MTH 06-Jul-1993<br>HRS 2529               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-72-07                                                           | ENG IN-FLT DATA RECD                                                                                                                                                                                                       |      |         |                               | MTH 06-Jul-1993<br>HRS 2529               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-72-03                                                              | ENGINE - TURBINE SECTION - IMPROVED LP TURBINE SECONDARY COOLING AIR FLOW                                                                                                                                                  |      |         | INFORMATIONAL                 | MTH 18-Apr-1988<br>HRS 749                |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-72-22<br>LEFT ENGINE                                               | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-A72-3668, ENGINE - BY-PASS SECTION - FAN ROTOR DISC REMOVAL SCHEDULE (PLAN)                                                                                               |      |         | RECOMMENDED                   | MTH 17-Aug-2002                           |                | A/R            |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-72-24 R01<br>LEFT ENGINE                                           | TRANSMITTAL OF HONEYWELL ENGINE SERVICE BULLETIN, TFE731-72-3720, ENGINE - TURBINE SECTION INSPECT/REPLACE (IF REQUIRED) HIGH PRESSURE (HP) TURBINE ROTOR DISCS, P/N 3075772-1                                             |      |         | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                              |                                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position            | Description<br>Drawing # / Task #                                                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 650-72-24 R01<br>RIGHT ENGINE | TRANSMITTAL OF HONEYWELL ENGINE SERVICE BULLETIN, TFE731-72-3720, ENGINE - TURBINE SECTION INSPECT/REPLACE (IF REQUIRED) HIGH PRESSURE (HP) TURBINE ROTOR DISCS, P/N 3075772-1 |      |         | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                  | <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-72-24                     | TRANSMITTAL OF HONEYWELL ENGINE SERVICE BULLETIN, TFE731-72-3720, ENGINE - TURBINE SECTION INSPECT/REPLACE (IF REQUIRED) HIGH PRESSURE (HP) TURBINE ROTOR DISCS, PIN 3075772-1 |      |         | MANDATORY                     | MTH 20-Mar-2008                           |                | A/R            |                |                            | N/A                |
|                                  | <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| VSF 831708-SB-001<br>E1          | NAPOLI A5 NOZZLE ADJUSTMENT SOFTWARE PN 831708 - RELEASE OF NAPOLI A5 NOZZLE ADJUSTMENT SOFTWARE VERSION 2.04 FOR TFE731 ENGINE MODELS                                         |      |         |                               |                                           |                | -              |                |                            |                    |
|                                  | <b>MOC :</b>                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| VSF 831708-SB-001<br>E2          | NAPOLI A5 NOZZLE ADJUSTMENT SOFTWARE PN 831708 - RELEASE OF NAPOLI A5 NOZZLE ADJUSTMENT SOFTWARE VERSION 2.04 FOR TFE731 ENGINE MODELS                                         |      |         |                               |                                           |                | -              |                |                            |                    |
|                                  | <b>MOC :</b>                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3124 R08<br>E1      | ACCESSORY DRIVES - MODIFY STARTER/GENERATOR DRIVE SPUR GEARSHAFT                                                                                                               | UNK  |         | OPTIONAL                      | MTH 17-Jun-2003                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b>                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3124 R08<br>E2      | ACCESSORY DRIVES - MODIFY STARTER/GENERATOR DRIVE SPUR GEARSHAFT                                                                                                               | UNK  |         | OPTIONAL                      | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3128 R09<br>E1      | ACCESSORY DRIVES - MODIFY ALTERNATOR DRIVE SPUR GEARSHAFT                                                                                                                      | UNK  |         | CATEGORY 3                    | MTH 17-Jun-2003                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b>                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3128 R09<br>E2      | ACCESSORY DRIVES - MODIFY ALTERNATOR DRIVE SPUR GEARSHAFT                                                                                                                      | UNK  |         | CATEGORY 3                    | MTH 17-Aug-2002                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3367 R03<br>E1      | TURBINE SECTION - PERFORM ONE TIME INSPECTION OF NOZZLE THROAT (A5) OPENING FOR PROPER DIMENSION                                                                               | UNK  |         | RECOMMENDED                   | MTH 11-Jul-1991                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b>                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3367 R03<br>E2      | TURBINE SECTION - PERFORM ONE TIME INSPECTION OF NOZZLE THROAT (A5) OPENING FOR PROPER DIMENSION                                                                               | UNK  |         | RECOMMENDED                   | MTH 11-Jul-1991                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3384 R02<br>E1      | BY-PASS SECTION - INSTALL OIL DEFLECTOR OR REWORK EXISTING OIL DEFLECTOR.                                                                                                      | UNK  |         | CATEGORY 3                    | MTH 18-Aug-2002                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b>                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3384 R02<br>E2      | BY-PASS SECTION - INSTALL OIL DEFLECTOR OR REWORK EXISTING OIL DEFLECTOR.                                                                                                      | UNK  |         | CATEGORY 3                    | MTH 17-Aug-2002                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3397 R03<br>E1      | ENGINE - GENERAL - INITIATE COMPONENT MAINTENANCE/MODIFICATION RECORD CARD (CMMC)                                                                                              | UNK  |         |                               | MTH 23-Aug-1995                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b>                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3397 R03<br>E2      | ENGINE - GENERAL - INITIATE COMPONENT MAINTENANCE/MODIFICATION RECORD CARD (CMMC)                                                                                              | UNK  |         |                               | MTH 19-Sep-2011                           |                | -              |                |                            | Complete           |
|                                  | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3416 R06<br>E1                           | COMPRESSOR SECTION - INSTALL HP IMPELLER SHROUD WITH AN IMPROVED ALUMINUM ABRADABLE COATING                                                                                      | UNK  |         | CATEGORY 2                    | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3416 R06<br>E2                           | COMPRESSOR SECTION - INSTALL HP IMPELLER SHROUD WITH AN IMPROVED ALUMINUM ABRADABLE COATING                                                                                      | UNK  |         | CATEGORY 2                    | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3426 R02<br>E1                           | TURBINE SECTION - REPLACE/REWORK THIRD STAGE LP TURBINE NOZZLE, P/N 3072342-1/-2 TO 3072342-4 OR PART NO. 3070014-2/-3 TO 3070014-5                                              | UNK  |         | RECOMMENDED                   | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3426 R02<br>E2                           | TURBINE SECTION - REPLACE/REWORK THIRD STAGE LP TURBINE NOZZLE, P/N 3072342-1/-2 TO 3072342-4 OR PART NO. 3070014-2/-3 TO 3070014-5                                              | UNK  |         | RECOMMENDED                   | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3455 R03<br>E1                           | ACCESSORY DRIVES - INSTALL PACKINGS, PART NO. S9413-036, AND SEALS, PART NO. 3075506-2, ON TOWER SHAFT OIL TRANSFER TUBE                                                         | UNK  |         | CATEGORY 2                    | MTH 17-Nov-1998                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3455 R03<br>E2                           | ACCESSORY DRIVES - INSTALL PACKINGS, PART NO. S9413-036, AND SEALS, PART NO. 3075506-2, ON TOWER SHAFT OIL TRANSFER TUBE                                                         | UNK  |         | CATEGORY 2                    | MTH 19-Sep-2011                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3458 R12<br>E1                           | BY-PASS SECTION - PROVIDE EDDY CURRENT INSPECTION INSTRUCTIONS FOR THE FAN ROTOR ASSEMBLY DISC DOVETAIL SLOTS                                                                    | UNK  |         |                               | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3458 R12<br>E2                           | BY-PASS SECTION - PROVIDE EDDY CURRENT INSPECTION INSTRUCTIONS FOR THE FAN ROTOR ASSEMBLY DISC DOVETAIL SLOTS                                                                    | UNK  |         |                               | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH</b>            |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3484 R02<br>E1                           | INSTALL COMPRESSOR INLET STATOR, PN 3072429-5/-7                                                                                                                                 | UNK  |         |                               | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3484 R02<br>E2                           | INSTALL COMPRESSOR INLET STATOR, PN 3072429-5/-7                                                                                                                                 | UNK  |         |                               | MTH 23-Aug-1995                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3487 R03<br>E1                           | ENGINE - BY-PASS SECTION - INSPECT/REWORK FAN BLADE                                                                                                                              | UNK  |         | CATEGORY 2                    | MTH 18-Aug-2002                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3487 R03<br>E2                           | ENGINE - BY-PASS SECTION - INSPECT/REWORK FAN BLADE                                                                                                                              | UNK  |         | CATEGORY 2                    | MTH 17-Jun-1999                           |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-72-3494 R13<br>E1                           | TURBINE SECTION - HIGH PRESSURE (HP) AND LOW PRESSURE (LP) TURBINE BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-2, -3, -4, -5 SERIES ENGINE MODELS |      |         | CATEGORY 2                    | MTH<br>HRS                                |                | MPI<br>MPI<br>MPI |                | (9468.4)9645.3             | 871.4              |
| <b>MOC :</b>                                          |                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3494 R13<br>E2                           | TURBINE SECTION - HIGH PRESSURE (HP) AND LOW PRESSURE (LP) TURBINE BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-2, -3, -4, -5 SERIES ENGINE MODELS |      |         | CATEGORY 2                    | MTH<br>HRS               |                | MPI<br>MPI<br>MPI |                | (9455.6)9645.3             | 871.4              |
| <b>MOC :</b>                                          |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3499 R06<br>E1                           | BY-PASS SECTION - INSTALL COMPONENT PARTS TO PREVENT OIL LEAKAGE IN THE NO. 1 OIL SEAL REGION (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3613)               | UNK  |         | CANCELLED                     | MTH 19-Sep-2011          |                | -                 |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                           |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3499 R06<br>E2                           | BY-PASS SECTION - INSTALL COMPONENT PARTS TO PREVENT OIL LEAKAGE IN THE NO. 1 OIL SEAL REGION (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3613)               | UNK  |         | CANCELLED                     | MTH 19-Sep-2011          |                | -                 |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                           |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3508 R08<br>E1                           | CONVERT ENGINE MODELS TFE731-3B TO TFE731-3C AND TFE731-3BR TO TFE731-3CR                                                                                                        | UNK  |         |                               | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3508 R08<br>E2                           | CONVERT ENGINE MODELS TFE731-3B TO TFE731-3C AND TFE731-3BR TO TFE731-3CR                                                                                                        | UNK  |         |                               | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3524<br>E1                               | BY-PASS SECTION - INSTALL RETAINING (DAMPER) RING, PART NO. 3072463-2                                                                                                            | UNK  |         | RECOMMENDED                   | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3524<br>E2                               | BY-PASS SECTION - INSTALL RETAINING (DAMPER) RING, PART NO. 3072463-2                                                                                                            | UNK  |         | RECOMMENDED                   | MTH 19-Sep-2011          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3527 R04<br>E1                           | INSPECTION INTERVALS - ESTABLISHING PERIODIC INSPECTION INTERVALS                                                                                                                | UNK  |         |                               | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3527 R04<br>E2                           | INSPECTION INTERVALS - ESTABLISHING PERIODIC INSPECTION INTERVALS                                                                                                                | UNK  |         |                               | MTH 19-Sep-2011          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH            |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3533 R01<br>E1                           | INSTALL HP TURBINE SEAL PLATE AND HP TURBINE NOZZLE ASSEMBLY RETAINER AND INNER SEAL                                                                                             | UNK  |         |                               | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3533 R01<br>E2                           | INSTALL HP TURBINE SEAL PLATE AND HP TURBINE NOZZLE ASSEMBLY RETAINER AND INNER SEAL                                                                                             | UNK  |         |                               | MTH 17-Jun-1999          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3536 R03<br>E1                           | COMBUSTION SECTION - INSTALL COMBUSTION CHAMBER AND INNER TRANSITION LINER (CONTROLLED FIT/LOW SMOKE)                                                                            | UNK  |         | CATEGORY 2                    | MTH 18-Aug-2002          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3536 R03<br>E2                           | COMBUSTION SECTION - INSTALL COMBUSTION CHAMBER AND INNER TRANSITION LINER (CONTROLLED FIT/LOW SMOKE)                                                                            | UNK  |         | CATEGORY 2                    | MTH 23-Aug-1995          |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |
| SB TFE731-72-3540 R03<br>E1                           | COMPRESSOR SECTION - IMPROVED NO. 4 AND 5 BEARING SUMP SCAVENGE (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3662)                                             | UNK  |         | CANCELLED                     | MTH 19-Sep-2011          |                | -                 |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                           |                                                                                                                                                                                  |      |         |                               |                          |                |                   |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3540 R03<br>E2                           | COMPRESSOR SECTION - IMPROVED NO. 4 AND 5 BEARING SUMP SCAVENGE (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3662)                                  | UNK  |         | CANCELLED                     | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>          |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3542 R03<br>E1                           | COMPRESSOR SECTION - INSTALL LP SECOND STAGE COMPRESSOR (LPC2) ROTOR ASSEMBLY WITH FREQUENCY INSPECTED ROTOR BLADES                                                   | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3542 R03<br>E2                           | COMPRESSOR SECTION - INSTALL LP SECOND STAGE COMPRESSOR (LPC2) ROTOR ASSEMBLY WITH FREQUENCY INSPECTED ROTOR BLADES                                                   | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH</b>            |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3583 R01<br>E1                           | BY-PASS SECTION - REDESIGNED FAN ROTOR DISC                                                                                                                           | UNK  |         | CATEGORY 2                    | MTH 18-Aug-2002                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3583 R01<br>E2                           | BY-PASS SECTION - REDESIGNED FAN ROTOR DISC                                                                                                                           | UNK  |         | CATEGORY 2                    | MTH 17-Aug-2002                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3590<br>E2                               | TURBINE SECTION - PROVIDE FOR INSTALLATION OF HP TURBINE BLADE, PART NO. 3074785-8                                                                                    | UNK  |         | CATEGORY 3                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3596 R08<br>E1                           | REPLACE MAINSHAFT CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3613 AND TFE731-72-3662) | UNK  |         | CANCELLED                     | MTH 17-Nov-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3596 R08<br>E2                           | REPLACE MAINSHAFT CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS (INACTIVE FOR FURTHER ACCOMPLISHMENT) (SUPERSEDED BY TFE731-72-3613 AND TFE731-72-3662) | UNK  |         | CANCELLED                     | MTH 17-Jun-1999                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3600<br>E1                               | ENGINE - COMPRESSOR SECTION - INSTALL LP COMPRESSORSTATOR SHIM, PART NO. 3060360-1 THRU -11                                                                           | UNK  |         | CATEGORY 2                    | MTH 17-Nov-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3600<br>E2                               | ENGINE - COMPRESSOR SECTION - INSTALL LP COMPRESSORSTATOR SHIM, PART NO. 3060360-1 THRU -11                                                                           | UNK  |         | CATEGORY 2                    | MTH 17-Jun-1999                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3602<br>E1                               | PERFORM ONE TIME INSP. OF ANTI-ROTATION TANGS ON HP TURBINE NOZZLE SEGMENTS, PN 3072844-X, 3074783-X AND 3077089-X                                                    | UNK  |         | CATEGORY 3                    | MTH 17-Nov-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3602<br>E2                               | PERFORM ONE TIME INSP. OF ANTI-ROTATION TANGS ON HP TURBINE NOZZLE SEGMENTS, PN 3072844-X, 3074783-X AND 3077089-X                                                    | UNK  |         | CATEGORY 3                    | MTH 17-Jun-1999                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3604 R04<br>E1                           | ACCESSORY DRIVES - REWORK TRANSFER GEARBOX ASSEMBLY, PART NO. 3070093-X TO PART NO. 3070093-12/-14                                                                    | UNK  |         | CATEGORY 3                    | MTH 17-Nov-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2           | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|--------------------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3604 R04<br>E2                           | ACCESSORY DRIVES - REWORK TRANSFER GEARBOX ASSEMBLY, PART NO. 3070093-X TO PART NO. 3070093-12/-14                                                   | UNK  |         | CATEGORY 3                    | MTH 17-Jun-1999                           |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3605 R05<br>E1                           | ACCESSORY DRIVES - REWORK TRANSFER GEARBOX ASSEMBLY, PN 3070093-X TO PN 3070093-12, -14, ON TFE731-2, -3, -4, AND -5 MODEL ENGINES                   |      |         | CATEGORY 3                    |                                           |                | -                        |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3604 R05<br>E2                           | ACCESSORY DRIVES - REWORK TRANSFER GEARBOX ASSEMBLY, PN 3070093-X TO PN 3070093-12, -14, ON TFE731-2, -3, -4, AND -5 MODEL ENGINES                   |      |         | CATEGORY 3                    |                                           |                | -                        |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3605 R04<br>E1                           | ENGINE - ACCESSORY DRIVES - INSTALL/REWORK ACCESSORY DRIVE GEARBOX ASSEMBLY WITH AN IMPROVED AIR-OIL SEPARATOR AND A NEW AIR BREATHER VALVE ASSEMBLY | UNK  |         | CATEGORY 3                    | MTH 17-Nov-1998                           |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3605 R04<br>E2                           | ENGINE - ACCESSORY DRIVES - INSTALL/REWORK ACCESSORY DRIVE GEARBOX ASSEMBLY WITH AN IMPROVED AIR-OIL SEPARATOR AND A NEW AIR BREATHER VALVE ASSEMBLY | UNK  |         | CATEGORY 3                    | MTH 17-Jun-1999                           |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3613 R08<br>E1                           | BY-PASS SECTION - REPLACE NO. 1 AND NO. 3 CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS                                                | UNK  |         | CATEGORY 2                    | MTH 18-Aug-2002                           |                | MPI                      |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3613 R08<br>E2                           | BY-PASS SECTION - REPLACE NO. 1 AND NO. 3 CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS                                                | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | MPI<br>MPI<br>MPI<br>MPI |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3617 R02<br>E1                           | TURBINE SECTION- PROVIDE IMPROVED HIGH PRESSURE TURBINE NOZZLE SEGMENTS                                                                              | UNK  |         | CATEGORY 3                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3617 R03<br>E1                           | TURBINE SECTION - PROVIDE IMPROVED HIGH PRESSURE TURBINE NOZZLE SEGMENTS                                                                             |      |         | CATEGORY 3                    |                                           |                | -                        |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3617 R03<br>E2                           | TURBINE SECTION - PROVIDE IMPROVED HIGH PRESSURE TURBINE NOZZLE SEGMENTS                                                                             |      |         | CATEGORY 3                    |                                           |                | -                        |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3635<br>E1                               | ACCESSORY DRIVES SECTION- INSPECT/REWORK/INSTALL OIL FILTER COVER, PN 3072231-1 TO PN 3072231-4                                                      | UNK  |         | CATEGORY 3                    | MTH 18-Aug-2002                           |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3635<br>E2                               | ACCESSORY DRIVES SECTION- INSPECT/REWORK/INSTALL OIL FILTER COVER, PN 3072231-1 TO PN 3072231-4                                                      | UNK  |         | CATEGORY 3                    | MTH 17-Jun-1999                           |                | -                        |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |
| SB TFE731-72-3640 R04<br>E1                           | ENGINE - SERVICING WITH MOBIL 254 OR EXXON 2197 OIL(INACTIVE FOR FURTHER ACCOMPLISHMENT)                                                             | UNK  |         | CANCELLED                     | MTH 20-Sep-2011                           |                | -                        |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                      |      |         |                               |                                           |                |                          |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3640 R04<br>E2                           | ENGINE - SERVICING WITH MOBIL 254 OR EXXON 2197 OIL(INACTIVE FOR FURTHER ACCOMPLISHMENT)                                                                  | UNK  |         | CANCELLED                     | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3654 R01<br>E1                           | PREVENT LP THIRD STAGE TURBINE ROTOR DISC FROM RUBBING THE LP THIRD STAGE TURBINE NOZZLE                                                                  | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3654 R01<br>E2                           | PREVENT LP THIRD STAGE TURBINE ROTOR DISC FROM RUBBING THE LP THIRD STAGE TURBINE NOZZLE                                                                  | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3662 R07<br>E1                           | ENGINE - COMPRESSOR SECTION - REPLACE NO. 4 AND NO. 5 CARBON RING SEALS AND ASSOCIATED ENT/OIL SYSTEM COMPONENTS                                          | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3662 R07<br>E2                           | ENGINE - COMPRESSOR SECTION - REPLACE NO. 4 AND NO. 5 CARBON RING SEALS AND ASSOCIATED ENT/OIL SYSTEM COMPONENTS                                          | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3664<br>E1                               | ENGINE - COMPRESSOR SECTION - INSPECTION/REPLACEMENT (AS REQUIRED) OF THREADED ENDS TIE ROD, (LOW PRESSURE (LP) TIE ROD) PART NO. 3073049-1 AND 3074744-1 | UNK  |         | CATEGORY 2                    | MTH 18-Aug-2002                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3664<br>E2                               | ENGINE - COMPRESSOR SECTION - INSPECTION/REPLACEMENT (AS REQUIRED) OF THREADED ENDS TIE ROD, (LOW PRESSURE (LP) TIE ROD) PART NO. 3073049-1 AND 3074744-1 | UNK  |         | CATEGORY 2                    | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3674 R02<br>E1                           | ENGINE - COMPRESSOR SECTION - INSPECTION OF SPECIFIC IDENTIFIED MAIN SUPPORT FRAME ASSEMBLIES                                                             | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3674 R02<br>E2                           | ENGINE - COMPRESSOR SECTION - INSPECTION OF SPECIFIC IDENTIFIED MAIN SUPPORT FRAME ASSEMBLIES                                                             | UNK  |         | CATEGORY 2                    | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3685<br>E1                               | TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LP SECOND STAGE TURBINE BLADES, PART NO. 3072012-2 AND PART NO. 3074099-1                                   | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3685<br>E2                               | TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LP SECOND STAGE TURBINE BLADES, PART NO. 3072012-2 AND PART NO. 3074099-1                                   | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                | Description<br>Drawing # / Task #                                                                                                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3687<br>E1                              | ENGINE - COMPRESSOR SECTION - REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR SECOND STAGE (LPC2) DISCS                                    | UNK  |         | CATEGORY 2                    | MTH 20-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3687<br>E2                              | ENGINE - COMPRESSOR SECTION - REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR SECOND STAGE (LPC2) DISCS                                    | UNK  |         | CATEGORY 2                    | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3693 R01<br>E1                          | REPLACE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) TIE SHAFT PLAIN ROUND NUTS, PART NO. 3070151-4                              | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                           |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3693 R01<br>E2                          | REPLACE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) TIE SHAFT PLAIN ROUND NUTS, PART NO. 3070151-4                              | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b> |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3699<br>E1                              | TURBINE SECTION - REMOVE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) ROTOR DISCS                                                | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.3<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                           |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3699<br>E2                              | TURBINE SECTION - REMOVE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) ROTOR DISCS                                                | UNK  |         | CATEGORY 2                    | MTH 19-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3711 R05<br>E1                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC ON TFE731-2, -3, -4, AND -5 MODEL ENGINES |      |         | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3711 R05<br>E2                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC ON TFE731-2, -3, -4, AND -5 MODEL ENGINES |      |         | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3712 R01<br>E1                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC                                           |      |         | CATEGORY 1                    | MTH 19-Apr-2010<br>HRS 7264.8<br>LDG 6211 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3712 R01<br>E2                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC                                           |      |         | CATEGORY 1                    | MTH 19-Apr-2010<br>HRS 7261<br>LDG 6211   |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3712 R03<br>E1                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC ON TFE731-2, -3, AND -5 MODEL ENGINES     |      |         | CATEGORY 1                    | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3712 R03<br>E2                          | COMPRESSOR SECTION - INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC ON TFE731-2, -3, AND -5 MODEL ENGINES     |      |         | CATEGORY 1                    | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                | Description<br>Drawing # / Task #                                                                                                                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3720<br>E1                              | TURBINE SECTION - INSPECT/REPLACE (IF REQUIRED) SPECIFIC IDENTIFIED HIGH PRESSURE (HP) TURBINE ROTOR DISCS, PART NO. 3075772-1                      | UNK  |         | CATEGORY 1                    | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3720<br>E2                              | TURBINE SECTION - INSPECT/REPLACE (IF REQUIRED) SPECIFIC IDENTIFIED HIGH PRESSURE (HP) TURBINE ROTOR DISCS, PART NO. 3075772-1                      | UNK  |         | CATEGORY 1                    | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3739<br>E1                              | BY-PASS SECTION - INSTALL IMPROVED NO. 1 SEGMENTED CARBON SEAL, PN 3060457-1 OR-2 (AS APPLICABLE), AND/OR NO. 3 SEGMENTED CARBON SEAL, PN 3060458-1 | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                           |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3739<br>E2                              | BY-PASS SECTION - INSTALL IMPROVED NO. 1 SEGMENTED CARBON SEAL, PN 3060457-1 OR-2 (AS APPLICABLE), AND/OR NO. 3 SEGMENTED CARBON SEAL, PN 3060458-1 | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3759<br>E1                              | ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-25                                                              |      |         | CATEGORY 2                    | MTH 02-Nov-2011<br>HRS 7548.3<br>LDG 6408 |                | -              |                |                            |                    |
| <b>MOC : DECLINED - NO PARTS AVAILABLE</b>           |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3759<br>E2                              | ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-25                                                              |      |         | CATEGORY 2                    | MTH 02-Nov-2011<br>HRS 7548.3<br>LDG 6408 |                | -              |                |                            |                    |
| <b>MOC : DECLINED - NO PARTS AVAILABLE</b>           |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3764<br>E1                              | ENGINE - COMPRESSOR SECTION - REMOVE SPECIFIC IDENTIFIED THIRD STAGE AXIAL COMPRESSOR DISKS, PN 3072397-3                                           | UNK  |         | CATEGORY 2                    | MTH 20-Sep-2011                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3764<br>E2                              | ENGINE - COMPRESSOR SECTION - REMOVE SPECIFIC IDENTIFIED THIRD STAGE AXIAL COMPRESSOR DISKS, PN 3072397-3                                           | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                          |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3777 R01<br>E1                          | ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED LOW PRESSURE COMPRESSOR SECOND STAGE (LPC2) SHROUD, PN 3072403-6                                     | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                           |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3777 R01<br>E2                          | ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED LOW PRESSURE COMPRESSOR SECOND STAGE (LPC2) SHROUD, PN 3072403-6                                     | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3801<br>E1                              | COMPRESSOR SECTION - IMPROVED THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTATING SHROUD, PN 3072404-5 ON TFE731-2, -3, -4, AND -5 MODEL ENGINES    |      |         | CATEGORY 3                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                     |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                     | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                                                                         | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-72-3801<br>E2                                   | COMPRESSOR SECTION - IMPROVED THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTATING SHROUD, PN 3072404-5 ON TFE731-2, -3, -4, AND -5 MODEL ENGINES                                                                                       | CATEGORY 3                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3802<br>E1                                   | COMPRESSOR SECTION - IMPROVED THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTATING SHROUD, PN 3072404-5 ON TFE731-2, -2A, -3, AND -5 MODEL ENGINES                                                                                      | CATEGORY 3                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3802<br>E2                                   | COMPRESSOR SECTION - IMPROVED THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTATING SHROUD, PN 3072404-5 ON TFE731-2, -2A, -3, AND -5 MODEL ENGINES                                                                                      | CATEGORY 3                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3805 R01<br>E1                               | COMPRESSOR SECTION - IDENTIFY AND REPLACE SPECIFIC LOW PRESSURE COMPRESSOR 4TH STAGE (LPC4) CASE AND VANE ASSEMBLY, PN 3074555-10 OR PN 3074555-11, ON TFE731-2, -3, -4, -5 SERIES ENGINE MODELS (INACTIVE FOR FURTHER ACCOMPLISHMENT) | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3805 R01<br>E2                               | COMPRESSOR SECTION - IDENTIFY AND REPLACE SPECIFIC LOW PRESSURE COMPRESSOR 4TH STAGE (LPC4) CASE AND VANE ASSEMBLY, PN 3074555-10 OR PN 3074555-11, ON TFE731-2, -3, -4, -5 SERIES ENGINE MODELS (INACTIVE FOR FURTHER ACCOMPLISHMENT) | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3805<br>E1                                   | COMPRESSOR SECTION - IDENTIFY AND REPLACE SPECIFIC LOW PRESSURE COMPRESSOR 4TH STAGE (LPC4) CASE AND VANE ASSEMBLY PN 3074555-10 OR PN 3074555-11 ON TFE731-2 -3 -4 -5 SERIES ENGINE MODELS                                            | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| SB TFE731-72-3805<br>E2                                   | COMPRESSOR SECTION - IDENTIFY AND REPLACE SPECIFIC LOW PRESSURE COMPRESSOR 4TH STAGE (LPC4) CASE AND VANE ASSEMBLY PN 3074555-10 OR PN 3074555-11 ON TFE731-2 -3 -4 -5 SERIES ENGINE MODELS                                            | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                              |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-72-A3748<br>E1                                 | REPLACE SPECIFIC IDENTIFIED SECOND STAGE LOW PRESSURE COMPRESSOR (LPC2) AND THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTOR DISCS                                                                                                     | UNK CATEGORY 1                | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE PER DISK P/N |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-72-A3748<br>E2                                 | REPLACE SPECIFIC IDENTIFIED SECOND STAGE LOW PRESSURE COMPRESSOR (LPC2) AND THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTOR DISCS                                                                                                     | UNK CATEGORY 1                | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE PER DISK P/N |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-72-A3749<br>E1                                 | REPLACE SPECIFIC IDENTIFIED SECOND STAGE LOW PRESSURE COMPRESSOR (LPC2) AND THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTOR DISCS                                                                                                     | UNK CATEGORY 1                | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE PER DISK P/N |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-72-A3749<br>E2                                 | REPLACE SPECIFIC IDENTIFIED SECOND STAGE LOW PRESSURE COMPRESSOR (LPC2) AND THIRD STAGE LOW PRESSURE COMPRESSOR (LPC3) ROTOR DISCS                                                                                                     | UNK CATEGORY 1                | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - PARTIALLY COMPLIED WITH     |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-A72-3518<br>E1                                 | REPLACE LP FIRST STAGE TURBINE NOZZLE AIR SEAL                                                                                                                                                                                         | UNK                           | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                               |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-A72-3518<br>E2                                 | REPLACE LP FIRST STAGE TURBINE NOZZLE AIR SEAL                                                                                                                                                                                         | UNK                           | MTH 07-Aug-1995                           |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH      |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |
| ASB TFE731-A72-3641 R07<br>E1                             | PERFORM EDDY CURRENT INSPECTION OF HP COMPRESSOR (HPC) IMPELLER                                                                                                                                                                        | UNK CATEGORY 1                | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                |                                                                                                                                                                                                                                        |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| ASB TFE731-A72-3641 R07 E2                            | PERFORM EDDY CURRENT INSPECTION OF HP COMPRESSOR (HPC) IMPELLER                                                                                                                                                                                                                      | UNK  |         | CATEGORY 1                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-73-01                                          | FUEL FLOW TRANSMITTER REPLACEMENT                                                                                                                                                                                                                                                    |      |         | OPTIONAL                      |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-73-01                                       | ENG FUEL LINE CLAMP                                                                                                                                                                                                                                                                  |      |         |                               | MTH 11-Jan-1993<br>HRS 2327               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-04 LEFT ENGINE                              | TRANSMITTAL OF ALLIEDSIGNAL AEROSPACE COMPANY SERVICE BULLETIN TFE731-A73-3132, ENGINE FUEL AND CONTROL - DISTRIBUTION - INSTALL FLEX TUBE ASSEMBLY, PART NO. 3074376-2                                                                                                              |      |         | RECOMMENDED                   | MTH 20-May-1998<br>HRS 4345               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-05 R01 LEFT ENGINE                          | TRANSMITTAL OF ALLIEDSIGNAL SERVICE BULLETIN TFE731-73-3131, ENGINE FUEL AND CONTROL - CONTROLLING - ONE TIME INSPECTION FOR SPECIFIC IDENTIFIED FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOWES, PART NO. 3074139-2, AND REPLACEMENT (AS REQUIRED) OF THE METERING VALVE ASSEMBLY |      |         | RECOMMENDED                   | MTH 02-Sep-1998<br>HRS 4462               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-06 LEFT ENGINE                              | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-73-3135                                                                                                                                                                                                                             |      |         | RECOMMENDED                   | MTH 17-Aug-2002<br>HRS 5468               |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-07 LEFT ENGINE                              | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-73-3137                                                                                                                                                                                                                             |      |         | RECOMMENDED                   | MTH 17-Jun-2003<br>HRS 5646               |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>          |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-08 LEFT ENGINE                              | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-73-3142                                                                                                                                                                                                                             |      |         | RECOMMENDED                   | MTH 15-Jun-2003<br>HRS 5644               |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>          |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-73-11 LEFT ENGINE                              | TRANSMITTAL OF HONEYWELL SERVICE BULLETIN TFE731-73-3146, REPLACE MAIN TURBINE ENGINE FUEL PUMP                                                                                                                                                                                      |      |         | RECOMMENDED                   | MTH 05-Mar-2007<br>HRS 6520               |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SIL F731-90 R03 E1                                    | OPERATIONAL DIFFERENCES WITH THE N1 DEEC ON TFE731 ENGINES                                                                                                                                                                                                                           |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SIL F731-90 R03 E2                                    | OPERATIONAL DIFFERENCES WITH THE N1 DEEC ON TFE731 ENGINES                                                                                                                                                                                                                           |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3131 R02 E1                              | ONE TIME INSPECTION FOR SPECIFIC IDENTIFIED FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOWES, PART NO. 3074139-2, AND REPLACEMENT (AS REQUIRED) OF THE METERING VALVE ASSEMBLY                                                                                                      | UNK  |         | CATEGORY 2                    | MTH 17-Nov-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                       | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-73-3131 R02<br>E2                           | ONE TIME INSPECTION FOR SPECIFIC IDENTIFIED FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOW, PART NO. 3074139-2, AND REPLACEMENT (AS REQUIRED) OF THE METERING VALVE ASSEMBLY<br>UNK | CATEGORY 2                    | MTH 09-Feb-1998                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3135<br>E1                               | ENGINE FUEL AND CONTROL - DISTRIBUTION - INSPECT/REPLACE FLEX TUBE ASSEMBLY, PN 3074376-1 (399-5500-0003) OR 3074376-2 (AS APPLICABLE)<br>UNK                                        | CATEGORY 2                    | MTH 18-Aug-2008                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3135<br>E2                               | ENGINE FUEL AND CONTROL - DISTRIBUTION - INSPECT/REPLACE FLEX TUBE ASSEMBLY, PN 3074376-1 (399-5500-0003) OR 3074376-2 (AS APPLICABLE)<br>UNK                                        | CATEGORY 2                    | MTH 17-Aug-2002                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>  |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3137<br>E1                               | ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE THE FUEL HEATER CHECK VALVE, PART NO. 3073932 -5 WITH PART NO. 3073932 -6, AND CONNECTING METAL TUBE ASSEMBLIES<br>UNK              | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                            |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3137<br>E2                               | ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE THE FUEL HEATER CHECK VALVE, PART NO. 3073932 -5 WITH PART NO. 3073932 -6, AND CONNECTING METAL TUBE ASSEMBLIES<br>UNK              | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3142<br>E1                               | REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSEMBLIES HAVING A SUSPECT OVERSPEED AND/OR MANUAL MODE SOLENOID VALVE INSTALLED<br>UNK                                                    | CATEGORY 1                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3142<br>E2                               | REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSEMBLIES HAVING A SUSPECT OVERSPEED AND/OR MANUAL MODE SOLENOID VALVE INSTALLED<br>UNK                                                    | CATEGORY 1                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3146<br>E1                               | REPLACE MAIN TURBINE ENGINE FUEL PUMP (FUEL PUMP), PART NO.3060710-7<br>UNK                                                                                                          | CATEGORY 1                    | MTH 09-Mar-2006                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3146<br>E2                               | REPLACE MAIN TURBINE ENGINE FUEL PUMP (FUEL PUMP), PART NO.3060710-7<br>UNK                                                                                                          | CATEGORY 1                    | MTH 09-Mar-2006                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3147<br>E1                               | REPLACE SPECIFIC IDENTIFIED FUEL CONTROLS WITH A SUSPECT OVERSPEED GOVERNOR ASSEMBLY<br>UNK                                                                                          | CATEGORY 1                    | MTH 01-Jun-2005                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                           |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3147<br>E2                               | REPLACE SPECIFIC IDENTIFIED FUEL CONTROLS WITH A SUSPECT OVERSPEED GOVERNOR ASSEMBLY<br>UNK                                                                                          | CATEGORY 1                    | MTH 01-Jun-2005                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |
| SB TFE731-73-3149<br>E1                               | ENGINE FUEL AND CONTROL - CONTROLLING - REPLACE MAIN TURBINE ENGINE FUEL PUMP FUEL FILTER ELEMENT, PN 897513 - 1 WITH PN 897830 - 1<br>UNK                                           | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH</b> |                                                                                                                                                                                      |                               |                                           |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                                                                                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| SB TFE731-73-3149<br>E2                               | ENGINE FUEL AND CONTROL - CONTROLLING - REPLACE MAIN TURBINE ENGINE FUEL PUMP FUEL FILTER ELEMENT, PN 897513 - 1 WITH PN 897830 - 1                                                                                                                              | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3157 R01<br>E1                           | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS |      |         | CATEGORY 2                    | MTH<br>HRS                                |                | DUE<br>DUE<br>DUE |                | (9468.4)9645.3             | 871.4              |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3157 R01<br>E2                           | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS |      |         | CATEGORY 2                    | MTH<br>HRS                                |                | DUE<br>DUE<br>DUE |                | (9455.6)9645.3             | 871.4              |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3157<br>E1                               | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS  |      |         | CATEGORY 2                    |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3157<br>E2                               | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS  |      |         | CATEGORY 2                    |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3159<br>E1                               | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-52, -53, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2-2J, -2-2N, -3-1J, -2A-2A, AND -5-1J ENGINE MODELS                     |      |         | CATEGORY 2                    |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB TFE731-73-3159<br>E2                               | ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-52, -53, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2-2J, -2-2N, -3-1J, -2A-2A, AND -5-1J ENGINE MODELS                     |      |         | CATEGORY 2                    |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| ASB TFE731-A73-3132 R01<br>E1                         | INSTALL FLEX TUBE ASSEMBLY, PN 3074376-2                                                                                                                                                                                                                         | UNK  |         | CATEGORY 1                    | MTH 22-Aug-1997                           |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| ASB TFE731-A73-3132 R01<br>E2                         | INSTALL FLEX TUBE ASSEMBLY, PN 3074376-2                                                                                                                                                                                                                         | UNK  |         | CATEGORY 1                    | MTH 17-Aug-2002                           |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB 650-74-01 R02                                      | IGNITOR DIODE DELETION                                                                                                                                                                                                                                           |      |         | RECOMMENDED                   |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB 650-76-01 R06                                      | AUTOMATIC PERFORMANCE RESERVE INSTALLATION<br>OPTIONAL                                                                                                                                                                                                           |      |         |                               |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SB 650-76-02                                          | PT2 SENSING LINE SUPPORT IMPROVEMENT<br>OPTIONAL                                                                                                                                                                                                                 |      |         |                               | MTH 08-Mar-1995<br>HRS 3104               |                | -                 |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                            |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |
| SL 650-76-02                                          | PT2 LINE SUPPORT INSPECTION                                                                                                                                                                                                                                      |      |         | RECOMMENDED                   |                                           |                | -                 |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                                                                                                                                  |      |         |                               |                                           |                |                   |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                | Description<br>Drawing # / Task # City Mod Lvl                                                                                                           | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2    | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-----------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-76-3069 R02<br>E1                          | ENGINE CONTROLS - POWER CONTROL - REWORK N1 DIGITAL ELECTRONIC ENGINE CONTROL (DEEC), PN 2119020-1 TO PN 2119020-1001, FOR TFE731-2 AND -3 ENGINE MODELS | CATEGORY 2                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-76-3069 R02<br>E2                          | ENGINE CONTROLS - POWER CONTROL - REWORK N1 DIGITAL ELECTRONIC ENGINE CONTROL (DEEC), PN 2119020-1 TO PN 2119020-1001, FOR TFE731-2 AND -3 ENGINE MODELS | CATEGORY 2                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-76-3073 R02<br>E1                          | ENGINE CONTROLS - POWER CONTROL - REWORK N1 DIGITAL ELECTRONIC ENGINE CONTROL (DEEC), PN 2119020-3 TO PN 2119020-3001, ON TFE731-3 SERIES ENGINES        | CATEGORY 2                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-76-3073 R02<br>E2                          | ENGINE CONTROLS - POWER CONTROL - REWORK N1 DIGITAL ELECTRONIC ENGINE CONTROL (DEEC), PN 2119020-3 TO PN 2119020-3001, ON TFE731-3 SERIES ENGINES        | CATEGORY 2                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-77-3021 R01<br>E2                          | ENGINE INDICATING - POWER - REPLACE N1 MOTIONAL PICKUP TRANSDUCER<br>UNK                                                                                 | CATEGORY 3                    | MTH 17-Aug-2002             |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-77-3023 R01<br>E1                          | ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED DESIGN N2 TRANSDUCER, PN 3070722-10, ON TFE731-2, -3, -4, -5 SERIES ENGINE MODELS                   | CATEGORY 3                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB TFE731-77-3023 R01<br>E2                          | ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED DESIGN N2 TRANSDUCER, PN 3070722-10, ON TFE731-2, -3, -4, -5 SERIES ENGINE MODELS                   | CATEGORY 3                    |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB 650-78-05 R02                                     | THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION<br>RECOMMENDED                                                                                        |                               |                             |                | -              |                |                            |                    |
| <b>MOC :</b>                                         |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB 650-78-06                                         | THRUST REVERSER FEEDBACK CABLE ASSEMBLY MODIFICATION<br>OPTIONAL                                                                                         |                               |                             |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                          |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-03 R1                                   | T/R IDLER & DRVE LNK                                                                                                                                     |                               | MTH 21-Nov-1989             |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-04 R2                                   | T/R STANG MOD                                                                                                                                            |                               | MTH 05-Aug-1988<br>HRS 905  |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-04                                      | T/R STANG MOD                                                                                                                                            |                               | MTH 05-Aug-1988<br>HRS 905  |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-06                                      | REPL TR DR HINGE PIN                                                                                                                                     |                               | MTH 08-Aug-1989<br>HRS 1291 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-07                                      | MOD INBD STANG ASSY                                                                                                                                      |                               | MTH 04-May-1990<br>HRS 1462 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |
| SB SL 650-78-08                                      | TR OPERATIONAL TEST                                                                                                                                      |                               | MTH 20-Aug-1990<br>HRS 1515 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                           |                                                                                                                                                          |                               |                             |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB TFE731-79-3064 R03<br>E2                           | INSTALL OIL LUBE AND SCAVENGE PUMP, PN 3071949-12, THAT INCORPORATES AN IMPROVED PRESSURE REGULATOR SECTION                                    | UNK  |         | CATEGORY 3                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-79-3070 R01<br>E1                           | INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING (SUPERSEDED BY TFE731-79-3070 R02)                               | UNK  |         | CATEGORY 2                    | MTH 12-Oct-2011<br>HRS 7545.1<br>LDG 6403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-79-3070 R01<br>E2                           | INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING (SUPERSEDED BY TFE731-79-3070 R02)                               | UNK  |         | CATEGORY 2                    | MTH 11-Oct-2011<br>HRS 7356.1<br>LDG 6103 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH  |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-79-3070 R02<br>E1                           | OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-3, -4, -5 MODEL ENGINES                |      |         | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB TFE731-79-3070 R02<br>E2                           | OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-3, -4, -5 MODEL ENGINES                |      |         | CATEGORY 2                    |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-80-01                                          | STARTER GENERATOR SERVICE TEST                                                                                                                 |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB 650-80-02 R06                                      | STARTER GENERATOR REPLACEMENT AND SERVICE TEST                                                                                                 |      |         | OPTIONAL                      |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB SL 650-80-01                                       | START/GENERATOR BRGS                                                                                                                           |      |         |                               | MTH 21-Nov-1989<br>HRS 1370               |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                            |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-80-03<br>LEFT ENGINE                           | DELETE THE 500 HOUR MID-LIFE BEARING CHANGE REQUIREMENT FOR THE 9914052-1 (23080-003 MOD A) STARTER/GENERATOR                                  |      |         | RECOMMENDED                   | MTH 14-Jun-1993<br>HRS 2520               |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                            |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL 650-80-04<br>LEFT ENGINE                           | 500 HOUR MID-LIFE BEARING REPLACEMENT FOR 9914052-1 (LUCAS AEROSPACE PART NUMBER 23080-003 MOD A OR MOD B) STARTER GENERATORS                  |      |         | RECOMMENDED                   | MTH 14-Jun-1993<br>HRS 2520               |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                            |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-01 R03                                      | MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS                                                                                          |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-02 R01                                      | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-03 R02                                      | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-04 R01                                      | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW                                                                                        |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                          |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |



CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate | Hours  | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|---------------|--------|---------------------|---------------------|------------------------------|
| AIRCRAFT      | 8773.9 | 7234                | 23-May-2024         | .03                          |
| ENG 1         | 8597   | 7023                | 23-May-2024         | .03                          |
| ENG 2         | 8584.2 | 6931                | 23-May-2024         | .03                          |
| APU           | 2174   | 4795                | 23-May-2024         | .9                           |

Service Bulletins

| Item Code    | Description                                                 |      |         | Part Number    | C/W Time 1 | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|--------------|-------------------------------------------------------------|------|---------|----------------|------------|--------|-------|-------|-------------|---------|
| Position     | Drawing # / Task #                                          | City | Mod Lvl | Part Serial No | C/W Time 2 | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| SL CIL-99-05 | MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS |      |         |                |            |        |       |       |             |         |
|              | INFORMATIONAL                                               |      |         |                |            |        |       |       |             |         |
|              | MOC :                                                       |      |         |                |            |        |       |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code      | Description                                                                         | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|----------------|-------------------------------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------|---------|-------------|---------|
| Position       | Drawing # / Task #                                                                  | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| FAA 1974-20-10 | 74-20-10 EMERGENCY LOCATOR XMITTER-LEIGH SYSTEMS                                    |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1978-14-09 | 78-14-09 PREVENT FAILURE OF FIRE DETECTOR POWER LINES                               |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1979-05-02 | 79-05-02 PREVENT FIRE/EXPLOSION OF LITHIUM ELT BATTERIES. SUPERCEDED BY 79-18-05    |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1979-18-05 | 1979-18-05 PREVENT FIRE/EXPLOSION OF LITHIUM ELT BATTERIES                          |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1980-05-04 | 80-05-04 PREVENT INADVERTENT OPENING OF SEATBELT-EON MFG                            |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1980-07-13 | 80-07-13 PREVENT FAILURE OF FLOATATION DEVICE                                       |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1980-18-08 | 80-18-08 PREVENT FAILURE OF EMERGENCY ELECTRICAL POWER                              |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1981-02-03 | 81-02-03 PREVENT OXYGEN MASK LEAKAGE-PURITAN/BENNETT MFG. AD SUPERCEDED TO 81-08-04 |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1981-04-06 | 81-04-06 PREVENT DESTRUCTION OF CVR TAPE                                            |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1981-08-04 | 81-08-04 PREVENT OXYGEN MASK LEAKAGE-PURITAN/BENNETT MFG                            |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1981-21-05 | 81-21-05 REPLACE ELT BATTERY PACK                                                   |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1982-05-06 | 82-05-06 PREVENT EXCESSIVE PULL FORCE ON LIFE RAFT                                  |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1982-21-04 | 82-21-04 PREVENT FALSE EMERGENCY POWER INDICATION                                   |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1983-01-06 | APPLIANCE AD - 83-01-06 PREVENT FAILURE OF LIFE PRESERVERS/FLOAT DEVICES            |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1983-11-03 | APPLIANCE AD - 83-11-03 PREVENT RELEASE FAILURE-FLT ATTENDANT RESTRAINT             |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1984-02-08 | APPLIANCE AD - 84-02-08 PREVENT USE OF IMPROPERLY CHARGED OXYGEN CYLINDER           |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1984-18-07 | APPLIANCE AD - 84-18-07 PREVENT FAILURE OF FIRE EXTINGUISHER-WALTER KIDDE           |             |            |                |                                           |        | A/R         |         |             |         |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
| FAA 1985-03-51 | 85-03-51                                                                            | CCS         |            |                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |        | A/R         |         |             | N/A     |
|                | MOC :                                                                               |             |            |                |                                           |        |             |         |             |         |
|                | MOC : NOT APPLICABLE - NO APLICA POR SERIAL DE LA AERONAVE.                         |             |            |                |                                           |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------------------------------------------------------|------|---------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1985-22-10        | APPLIANCE AD - 85-22-10 PREVENT ERRONEOUS HSI INDICATION                                                         |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1985-26-03        | APPLIANCE AD - 85-26-03 OXYGEN FLOW CONNECTOR BLOCKAGE-SCOTT AVIATION                                            |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1986-05-02        | APPLIANCE AD - 86-05-02 PREVENT ERRONEOUS ALTITUDE READING                                                       |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1986-14-01        | APPLIANCE AD - 86-14-01 PREVENT LOSS OF ATTITUDE/HEADING INFORMATION<br>CCS                                      |      |                                       | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | A/R            |                |                            | N/A                |
|                       | <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NO TENER INSTALADO SISTEMAS DE REFERENCIA DE ACTITUD Y RUMBO (AHRs). |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-03-15        | 87-03-15                                                                                                         |      |                                       | MTH 13-Nov-1987<br>HRS 544                |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                                                       |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-04-19        | 87-04-19 PREVENT INADVERTENT OPENING OF SAFETY BELT ASSY                                                         |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-06-09        | APPLIANCE AD - 87-06-09 PREVENT LOSS OF EQUIPMENT/FIRE OR SHOCK HAZARD                                           |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-16-07        | APPLIANCE AD - 87-16-07 ELIMINATE ERRONEOUS AOA FAST/SLOW DISPLAY                                                |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-17-06        | APPLIANCE AD - 87-17-06 ELIMINATE INADVERTENT OPENING OF RESTRAINT ASSY                                          |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1987-20-06        | 87-20-05 ELIMINATE WEAK LAP BELT ASSY-PACIFIC SCIENTIFIC CO.                                                     |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1988-11-08        | APPLIANCE AD - 88-11-08 PREVENT FIRE FOR LIGHTING BALLAST-BRUCE INDUSTRIES                                       |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1988-24-16        | 88-24-16                                                                                                         |      |                                       | MTH 10-Feb-1989<br>HRS 1102               |                | A/R            |                |                            | Complete           |
|                       | <b>MOC :</b> COMPLIED WITH                                                                                       |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1988-26-05        | APPLIANCE AD - 88-26-05 ELIMINATE SIMULTANEOUS ATTITUDE/HDG DISPLAYS. AD SUPERCEDED BY 90-01-03                  |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1989-02-05        | APPLIANCE AD - 89-02-05 ELIMINATE LEAKING LIFE RAFT CYLINDERS                                                    |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1989-02-10<br>R01 | APPLIANCE AD - 89-02-10 R1 PREVENT FMS POSITION JUMP AT MERIDIAN                                                 |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1989-09-02        | APPLIANCE AD - 89-09-02 PREVENT FAILURE OF SAFETY BELT-DAVIS AIRCRAFT                                            |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |
| FAA 1989-20-06        | APPLIANCE AD - 89-20-06 PREVENT ERRONEOUS OMEGA/VLF SENSOR ERRORS                                                |      |                                       |                                           |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                     |      |                                       |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code                                                                                      | Description                                                                                        | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------|---------|-------------|---------|
| Position                                                                                       | Drawing # / Task #                                                                                 | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| FAA 1990-01-03                                                                                 | APPLIANCE AD - 90-01-03 ELIMINATE SIMULTANEOUS ATTITUDE/HDG DISPLAYS                               | CCS         |            |                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |        | A/R         |         |             | N/A     |
| MOC : NOT APPLICABLE - NO APLICA POR NO TENER SISTEMA DE REFERENCIA DE ACTITUD Y RUMBO (AHRS). |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1990-07-08 R1                                                                              | 90-07-08 R1 PREVENT SMOKE/FIRE FROM FLOURESCENT LIGHTING                                           |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1990-09-08                                                                                 | APPLIANCE AD - 90-09-08 PREVENT FAILURE OF SEAT BACK STRUCTURE                                     |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1990-14-06                                                                                 | APPLIANCE AD - 90-14-06 SUPERSEDED BY AD 95-22-01                                                  |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1991-10-05                                                                                 | APPLIANCE AD - 91-10-05 PREVENT FAILURE OF OXYGEN FLOW                                             |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1991-15-15                                                                                 | APPLIANCE AD - 91-15-15 PREVENT FAILURE OF PBE RETRIEVAL                                           |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1993-04-02                                                                                 | APPLIANCE AD - 93-04-02 PREVENT MID-AIR/NEAR-MISS SITUATION                                        |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1993-12-04                                                                                 | APPLIANCE AD - 93-12-04 PREVENT SMOKE IN COCKPIT FROM PULSELITE UNITS                              |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1994-01-06                                                                                 | APPLIANCE AD - 94-01-06 PREVENT COLLISIONS/NEAR-MISS FROM TCAS II                                  |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1994-14-03                                                                                 | APPLIANCE AD - 94-14-03 PREVENT GALLEY WATER HEATER/COFFEE MKR EXPLOSION                           |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1994-21-06                                                                                 | APPLIANCE AD - 94-21-06 PREVENT FAILURE OF SEAT BELT DURING EGRESS                                 |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1996-12-09                                                                                 | APPLIANCE AD - 96-12-09 PREVENT INJURY DURING OPERATION OF PAX SEAT                                |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1997-05-03 R1                                                                              | 97-05-03 R1 PREVENT FLIGHT PATH DEVIATION FROM GPS SYSTEM                                          |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1997-11-10                                                                                 | APPLIANCE AD - 97-11-10 PREVENT RESTRICTED PASSENGER OXYGEN FLOW                                   |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1997-16-10                                                                                 | APPLIANCE AD - 97-16-10 PREVENT FLIGHT INSTRUMENT FAILURE                                          |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1997-18-03                                                                                 | APPLIANCE AD - 97-18-03 PREVENT FAILURE OF CREW OXYGEN MASK                                        |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 1998-25-02                                                                                 | APPLIANCE AD - 98-25-02 PREVENT SKYWATCH FAILURE                                                   |             |            |                |                                           |        | A/R         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |
| FAA 2001-15-17                                                                                 | APPLIANCE AD - AD 2001-15-17 CTL TRANSPONDER CONTROL TO PREVENT ERRONEOUS ALTITUDE INTERPERTATIONS |             |            |                |                                           |        | DUE         |         |             |         |
| MOC :                                                                                          |                                                                                                    |             |            |                |                                           |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position             | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                                              | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2001-22-14                    | APPLIANCE AD - 2001-22-14 OVERLAND AVIATION SERVICES FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGES                                                                                                            |                               | MTH 06-Jun-2002                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE - BY PART NUMBER</b>                                                                                                                                                                |                               |                                           |                |                |                |                            |                    |
| FAA 2006-16-18<br>PARA(F)         | INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI)<br>PLACARD                                                                            | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                 |                               |                                           |                |                |                |                            |                    |
| FAA 2006-16-18<br>PARA(G)         | REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI)<br>AIRPLANE FLIGHT MANUAL (AFM)                                                        | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                 |                               |                                           |                |                |                |                            |                    |
| FAA 2006-16-18<br>PARA(H)         | UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI)<br>SOFTWARE                                                                            | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                 |                               |                                           |                |                |                |                            |                    |
| FAA 2006-19-04<br>PARA(F)         | REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND<br>HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM) | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                 |                               |                                           |                |                |                |                            |                    |
| FAA 2006-19-04<br>PARA(G)         | REPLACE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND<br>HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS IDENTIFICATION PLATE        | MANDATORY                     |                                           |                | A/R            |                |                            | N/A                |
|                                   | <b>MOC : NOT APPLICABLE</b>                                                                                                                                                                                 |                               |                                           |                |                |                |                            |                    |
| FAA 1995-07-02<br>1ST STAGE<br>E1 | ACCOMPLISH TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE<br>AND DAMAGE TO THE AIRCRAFT,                                                    |                               |                                           |                | A/R            |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |
| FAA 1995-07-02<br>1ST STAGE<br>E2 | ACCOMPLISH TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE<br>AND DAMAGE TO THE AIRCRAFT,                                                    |                               |                                           |                | A/R            |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |
| FAA 1995-07-02<br>2ND STAGE<br>E1 | ACCOMPLISH TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE<br>AND DAMAGE TO THE AIRCRAFT,                                                    |                               |                                           |                | A/R            |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |
| FAA 1995-07-02<br>2ND STAGE<br>E2 | ACCOMPLISH TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE<br>AND DAMAGE TO THE AIRCRAFT,                                                    |                               |                                           |                | A/R            |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |
| FAA 1974-08-09<br>R02             | LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)                                                                                                               | MANDATORY                     | MTH 28-Feb-2011<br>HRS 7426.8<br>LDG 6325 |                | -              |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |
| FAA 1986-22-10                    | APPLIANCE AD - 86-22-10 PREVENT DISPLAY OF ERRONEOUS DME-42 INFORMATION                                                                                                                                     |                               |                                           |                | A/R            |                |                            |                    |
|                                   | <b>MOC :</b>                                                                                                                                                                                                |                               |                                           |                |                |                |                            |                    |
| FAA 1987-06-02                    | APPLIANCE AD - 87-06-02 REDUCE AHRS ATTITUDE/HEADING FAILURE                                                                                                                                                |                               |                                           |                | A/R            |                |                            |                    |
|                                   | <b>MOC :</b>                                                                                                                                                                                                |                               |                                           |                |                |                |                            |                    |
| FAA 1988-23-04                    | 88-23-04                                                                                                                                                                                                    |                               |                                           |                | A/R            |                |                            |                    |
|                                   | <b>MOC :</b>                                                                                                                                                                                                |                               |                                           |                |                |                |                            |                    |
| FAA 1989-03-16                    | 89-03-16                                                                                                                                                                                                    |                               | MTH 10-Feb-1989<br>HRS 1102               |                | A/R            |                |                            | Complete           |
|                                   | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                  |                               |                                           |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position         | Description<br>Drawing # / Task #                                                                                                             | City | Part Number<br>Mod Lvl<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|------|------------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1989-06-01                | APPLIANCE AD - 89-06-01 PREVENT LIFE VEST/FLOAT DEVICE INFLATOR FAILURE                                                                       |      |                                          | MTH 25-Apr-1989<br>HRS 1195               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1990-03-02                | APPLIANCE AD - 90-03-02 SUPERSEDED BY AD 90-06-03                                                                                             |      |                                          | MTH 28-Feb-1990<br>HRS 1430               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1990-06-13                | APPLIANCE AD - 90-06-13 PREVENT ERRONEOUS ATTITUDE DISPLAY & A/P FUNCTION                                                                     |      |                                          | MTH 21-May-1990<br>HRS 1490               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1992-27-08                | 92-27-08 PREVENT POTENTIAL LOSS OF ELEVATOR CONTROL                                                                                           |      |                                          | MTH 24-Mar-1993<br>HRS 2406               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1993-05-15                | 93-05-15                                                                                                                                      |      |                                          | MTH 06-Aug-1992<br>HRS 2187               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1994-01-04                | APPLIANCE AD - 94-01-04 PREVENT COLLISIONS/NEAR-MISS FROM TCAS II                                                                             |      |                                          |                                           |                | A/R            |                |                            |                    |
|                               | <b>MOC :</b>                                                                                                                                  |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1994-19-06                | APPLIANCE AD - 94-19-06 PREVENT CREW OXYGEN STARVATION                                                                                        |      |                                          | MTH 10-Feb-1995<br>HRS 3083               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1995-22-01                | APPLIANCE AD - 95-22-01 PREVENT SMOKE/FIRE FROM FLOURESCENT LIGHTING                                                                          |      |                                          |                                           |                | A/R            |                |                            |                    |
|                               | <b>MOC :</b>                                                                                                                                  |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1997-12-01                | 97-12-01                                                                                                                                      |      |                                          | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | A/R            |                |                            | N/A                |
|                               | <b>MOC : NOT APPLICABLE - BY SN</b>                                                                                                           |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1998-25-10                | APPLIANCE AD - 98-25-10 PREVENT FAILURE OF SEAT RESTRAINT SYSTEM                                                                              |      |                                          | MTH 20-Feb-1999<br>HRS 4636               |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 1999-08-21                | APPLIANCE AD - 99-08-21 PREVENT RESTRICTED O2 FLOW TO PAX MASKS                                                                               |      |                                          | MTH 28-Jun-2000                           |                | A/R            |                |                            | N/A                |
|                               | <b>MOC : NOT APPLICABLE</b>                                                                                                                   |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2002-22-12<br>LEFT ENGINE | TITFLEX CORPORATION HIGH AND MEDIUM PRESSURE HOSE ON CITATION IIIS<br>MANDATORY                                                               |      |                                          | MTH 04-Feb-2003                           |                | A/R            |                |                            | Complete           |
|                               | <b>MOC : COMPLIED WITH</b>                                                                                                                    |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2003-04-06                | APPLIANCE AD - HONEYWELL PRIMUS II RNZ-850/-851 INTEGRATED NAVIGATION UNIT<br>SUPERSEDED                                                      |      |                                          | MTH 15-Apr-2003                           |                | A/R            |                |                            | N/A                |
|                               | <b>MOC : NOT APPLICABLE</b>                                                                                                                   |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2006-16-18                | APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR<br>(TAWS/RMI)<br>MANDATORY |      |                                          | MTH 17-Nov-2006                           |                | A/R            |                |                            | N/A                |
|                               | <b>MOC : NOT APPLICABLE</b>                                                                                                                   |      |                                          |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                              | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                                                                     | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                   | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|--------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2006-19-04                                                                                     | APPLIANCE AD - HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS;<br>AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS                                             | MANDATORY                     | MTH 01-Feb-2007                            |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                                                        |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (G)                                                                         | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)                                                       | MANDATORY                     | DAYS 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (H)                                                                         | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS                           | MANDATORY                     | DAYS 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (I) & (J)                                                                   | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213  |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (K)                                                                         | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM DEACTIVATION OF A/C SYSTEM                                                             | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213  |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (L)                                                                         | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM REACTIVATION OF A/C SYSTEM                                                             | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213  |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11<br>PARA (M)                                                                         | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS                                                | MANDATORY                     | DAYS 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2013-09-11                                                                                     | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE<br>A/C SYSTEM                                                                                        | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213  |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED, ACM SYSTEM INSTALLED</b>                           |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |
| FAA 2015-17-12<br>PARA (G)                                                                         | INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED<br>CCS                                                                                                                     | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU.</b> |                                                                                                                                                                                                                                    |                               |                                            |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                              | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                                                                                                                                          | City | Part Number<br>Mod Lvl<br>Part Serial No | C/W Time 1<br>C/W Time 2                   | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------------------------------------|--------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2015-17-12<br>PARA (H)                                                                         | DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND                                                                                                                                                                                                      | CCS  | MANDATORY                                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| FAA 2015-17-12<br>PARA (I)                                                                         | REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)                                                                                                                                                                                                                                                      | CCS  | MANDATORY                                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| FAA 2015-17-12<br>PARA (K)                                                                         | DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)                                                                                                                                                                                                                                                                                                   | CCS  | MANDATORY                                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| FAA 2015-17-12<br>PARA (L)                                                                         | IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE                                                                                                                                   | CCS  | MANDATORY                                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| FAA 2015-17-12<br>PARA (M)                                                                         | SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY                                                                                                                                                                                                                                                                                                                                                        | CCS  | MANDATORY                                | DAYS 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| FAA 2015-17-12                                                                                     | AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA | CCS  | MANDATORY                                | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA, EQUIPO NO INSTALADO EN LA AERONAVE, POSEE SISTEMA DE APU. |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| EASA 2014-0187<br>PARA (1)                                                                         | INSPECT THE SAFETY BELT ATTACHMENT BOLTS                                                                                                                                                                                                                                                                                                                                                                   |      | MANDATORY                                |                                            |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| EASA 2014-0187<br>PARA (2)                                                                         | IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.                                                                                                              |      | MANDATORY                                |                                            |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |
| EASA 2014-0187<br>PARA (3)                                                                         | FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.                                |      | MANDATORY                                |                                            |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                            |      |                                          |                                            |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code                     | Description                                                                                                                                                                                                                           | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|----------|
| Position                      | Drawing # / Task #                                                                                                                                                                                                                    | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| EASA 2014-0187<br>PARA (4)    | AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S). |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | MANDATORY  |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| EASA 2014-0187                | APPLIANCE AD - EQUIPMENT & FURNISHINGS – SAFETY BELT ATTACHMENT BOLTS – INSPECTION / REPLACEMENT                                                                                                                                      |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | MANDATORY  |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 1974-08-09<br>R03         | LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION                                                                                                                                                                              |             |            |                |            |        |             |         |             |          |
|                               | FXE                                                                                                                                                                                                                                   | MANDATORY   | MTH        | 26-Mar-2019    |            |        |             |         |             | Complete |
|                               |                                                                                                                                                                                                                                       |             | HRS        | 8642.2         |            |        | 1000        |         | 9642.2      | 868.3    |
|                               |                                                                                                                                                                                                                                       |             | LDG        | 7130           |            |        |             |         |             |          |
|                               | MOC : COMPLIED WITH                                                                                                                                                                                                                   |             |            |                |            |        |             |         |             |          |
| FAA 1993-23-01                | APPLIANCE AD - EQUIPMENT/FURNISHINGS - PERFORM ONE TIME INSPECTION TO DETERMINE WHETHER A NUPRO PRESSURE RELIEF VALVE HAVING PART NUMBER (P/N) SS-2C4-65 HAS BEEN INSTALLED                                                           |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             |            |                |            |        | A/R         |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 2015-10-02<br>PARA (G)    | GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2                                                              |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       | MANDATORY   |            |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 2015-10-02<br>PARA (H)    | CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK                                                                                                                                                                                    |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       | MANDATORY   |            |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 2015-10-02<br>PARA (I)    | REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS                                                                                         |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       | MANDATORY   |            |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 2015-10-02                | APPLIANCE/EMERGENCY AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT                                                                                                                                         |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       | MANDATORY   | MTH        |                |            |        | -           |         |             |          |
|                               | MOC :                                                                                                                                                                                                                                 |             |            |                |            |        |             |         |             |          |
| FAA 2017-16-01<br>PARA (G)    | PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS                                              |             |            |                |            |        |             |         |             |          |
|                               | FXE                                                                                                                                                                                                                                   |             | MTH        | 26-Mar-2019    |            |        | -           |         |             | N/A      |
|                               |                                                                                                                                                                                                                                       |             | HRS        | 8642.2         |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | LDG        | 7130           |            |        |             |         |             |          |
|                               | MOC : NOT APPLICABLE - APPLIES TO AMERI KING ELT'S ONLY                                                                                                                                                                               |             |            |                |            |        |             |         |             |          |
| FAA 2017-16-01<br>PARA (J)    | OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT                                                                                                                                                          |             |            |                |            |        |             |         |             |          |
|                               | FXE                                                                                                                                                                                                                                   | MANDATORY   | MTH        | 26-Mar-2019    |            |        | -           |         |             | N/A      |
|                               |                                                                                                                                                                                                                                       |             | HRS        | 8642.2         |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | LDG        | 7130           |            |        |             |         |             |          |
|                               | MOC : NOT APPLICABLE - APPLIES TO AMERI KING ELT'S ONLY                                                                                                                                                                               |             |            |                |            |        |             |         |             |          |
| FAA 2017-16-01                | APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS                                           |             |            |                |            |        |             |         |             |          |
|                               | FXE                                                                                                                                                                                                                                   | MANDATORY   | MTH        | 26-Mar-2019    |            |        | -           |         |             | N/A      |
|                               |                                                                                                                                                                                                                                       |             | HRS        | 8642.2         |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | LDG        | 7130           |            |        |             |         |             |          |
|                               | MOC : NOT APPLICABLE - APPLIES TO AMERI KING ELT'S ONLY                                                                                                                                                                               |             |            |                |            |        |             |         |             |          |
| FAA 2021-07-13<br>PARA (E)(1) | INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE                                                                                                                      |             |            |                |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       | MANDATORY   | MTH        | 05-Jun-2021    |            |        | -           |         |             | N/A      |
|                               |                                                                                                                                                                                                                                       |             | HRS        | 8735.3         |            |        |             |         |             |          |
|                               |                                                                                                                                                                                                                                       |             | LDG        | 7213           |            |        |             |         |             |          |
|                               | MOC : NOT APPLICABLE - BY P/N                                                                                                                                                                                                         |             |            |                |            |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                      | Description<br>Drawing # / Task # City Mod Lvl                                                                                                                                        | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2021-07-13<br>PARA (E)(2)                                                                              | MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY P/N</b>                                                                       |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(3)                                                                              | DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER                             | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY P/N</b>                                                                       |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13                                                                                             | APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT                                                                 | MANDATORY                     | MTH 05-Jun-2021<br>HRS 8735.3<br>LDG 7213 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - BY P/N</b>                                                                       |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2003-26-14                                                                                             | APPLIANCE AD - KIDDIE AEROSPACE (P/N) 898052 HAND-HELD FIRE EXTINGUISHERS                                                                                                             |                               |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                               |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2005-13-21                                                                                             | TO PREVENT UNCOMMANDED MOVEMENT OF THE HORIZONTAL STABILIZER                                                                                                                          | MANDATORY                     | MTH 08-Jun-2006                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                 |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 1984-08-02<br>R01                                                                                      | UNUSEABLE FUEL                                                                                                                                                                        |                               | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA POR SERIAL DE LA AERONAVE.</b>                                         |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2021-23-12                                                                                             | APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS                                                                | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                               |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2023-10-02<br>PARA (H)                                                                                 | REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)                                                                                 | MANDATORY                     | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - BY INSERTING A COPY OF FIGURE 3 AND FIGURE 4 OF THIS AD INTO THE AIRCRAFT AFM</b> |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2023-10-02<br>PARA (I)                                                                                 | REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)                                                                                   | MANDATORY                     | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - BY INSERTING A COPY OF FIGURE 3 AND FIGURE 4 OF THIS AD INTO THE AIRCRAFT AFM</b> |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2023-10-02                                                                                             | APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION                                                                                                | MANDATORY                     | MTH 08-Dec-2023<br>HRS 8752.5<br>LDG 7224 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - BY INSERTING A COPY OF FIGURE 3 AND FIGURE 4 OF THIS AD INTO THE AIRCRAFT AFM</b> |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |
| FAA 2002-14-24                                                                                             | 2002-14-24 ONE TIME INSPECTION OF MAIN LANDING GEAR SIDE BRACE                                                                                                                        |                               | MTH 25-Sep-2002                           |                | A/R            |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                 |                                                                                                                                                                                       |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                         | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|---------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 95-24-10                                                                                                                                                                                                                  | MICHELIN MLG TIRE REPLACEMENT<br>CCS                                                                                                                                                                                                                                                         |      |         |                               | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821               |                | O/C            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR MODELO DEL CAUCHO INSTALADOS, POSEE GOODYEAR P/N:220K08.                                                                                                                          |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 1990-25-06                                                                                                                                                                                                                | DME ANTENNA CABLE CONNECTORS                                                                                                                                                                                                                                                                 |      |         |                               |                                                         |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2002-06-06                                                                                                                                                                                                                | TDR-94/-94D MODE S XPNDER CK                                                                                                                                                                                                                                                                 |      |         |                               | MTH 06-Jun-2002                                         |                | O/C            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY PART NUMBER                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2003-13-08                                                                                                                                                                                                                | TAWS8000 TAWS                                                                                                                                                                                                                                                                                |      |         |                               | MTH 02-Aug-2003<br>HRS 5691                             |                | O/C            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2004-08-15                                                                                                                                                                                                                | TAWS8000 TAWS                                                                                                                                                                                                                                                                                |      |         |                               | MTH 04-May-2004<br>HRS 5955                             |                | O/C            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2006-16-18<br>R01                                                                                                                                                                                                         | APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD<br>AIRWORTHINESS                                                                                                                                                                                                                               |      |         |                               |                                                         |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2006-22-05                                                                                                                                                                                                                | APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM<br>SUPERSEDED                                                                                                                                                                                                                                 |      |         |                               | MTH 17-Nov-2006                                         |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2010-07-02                                                                                                                                                                                                                | PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER<br>MODULE (NRM)                                                                                                                                                |      |         |                               | MTH 19-Apr-2010<br>HRS 7265.5<br>LDG 6210               |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2012-02-08                                                                                                                                                                                                                | APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS)<br>UNITS                                                                                                                                                            |      |         |                               | MTH 27-Feb-2012<br>HRS 7620.7<br>LDG 6445               |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A BY P/N, AND MANUFACTURER OF UNIT INSTALLED AT THIS TIME                                                                                                                                     |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2014-18-01                                                                                                                                                                                                                | APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION                                                                                                                                                                                           |      |         |                               | MANDATORY MTH                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2015-10-51-E                                                                                                                                                                                                              | APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION<br>OF THE AFM OR AFMS.                                                                                                                                        |      |         |                               | MANDATORY MTH                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2015-10-51                                                                                                                                                                                                                | APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM<br>OR AFMS                                                                                                                                                   |      |         |                               | MANDATORY                                               |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |
| FAA 2015-08-07<br>PARA (G)                                                                                                                                                                                                    | INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS<br>INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240,<br>REVISION 7, DATED SEPTEMBER 1, 2011 |      |         |                               | CCS MANDATORY MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARAS INSTALADAS EN LA AERONAVE, POSEE MASCARA<br>PILOTO P/N: MC10-16-101 S/N: 92286 Y COPILOTO P/N:MC10-15-109 S7N: 57797 DE ACUERDO AL SB MXM-35-240. |                                                                                                                                                                                                                                                                                              |      |         |                               |                                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                      | Description<br>Drawing # / Task #                                                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                        | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2015-08-07<br>PARA (H)                                                                                                                                                                                                 | REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES                                                                                 | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821       |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARAS INSTALADAS EN LA AERONAVE, POSEE MASCARA PILOTO P/N: MC10-16-101 S/N: 92286 Y COPILOTO P/N:MC10-15-109 S7N: 57797 DE ACUERDO AL SB MXM-35-240. |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-08-07                                                                                                                                                                                                             | APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES    | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821       |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARAS INSTALADAS EN LA AERONAVE, POSEE MASCARA PILOTO P/N: MC10-16-101 S/N: 92286 Y COPILOTO P/N:MC10-15-109 S7N: 57797 DE ACUERDO AL SB MXM-35-240. |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (G)                                                                                                                                                                                                 | INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER                                                                                    | CCS  |         | MANDATORY                     | DAYS 22-Sep-2016<br>HRS 8218.5<br>LDG 6821      |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARA INSTALADAS,PILOTO P/N:MAC 10-16-101 S/N: 92286 Y COPILOTO P/N: MC 10-15-109 S/N: 57797 POSEEMASCARAS DE ACUERDO AL SB MCF-SBN-35-001.           |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (H.1)                                                                                                                                                                                               | REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).                                                                      | FXE  |         | MANDATORY                     | MTH 10-Jan-2016<br>DAYS 8174<br>HRS 6797<br>LDG |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A BY P/N INSTALLED.                                                                                                                                                                        |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (H.2.I)                                                                                                                                                                                             | REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1                                                    | CCS  |         | MANDATORY                     | DAYS 22-Sep-2016<br>HRS 8218.5<br>LDG 6821      |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARA INSTALADAS,PILOTO P/N:MAC 10-16-101 S/N: 92286 Y COPILOTO P/N: MC 10-15-109 S/N: 57797 POSEEMASCARAS DE ACUERDO AL SB MCF-SBN-35-001.           |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (H.2.II)                                                                                                                                                                                            | FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."                                                 | CCS  |         | MANDATORY                     | DAYS 22-Sep-2016<br>HRS 8218.5<br>LDG 6821      |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARA INSTALADAS,PILOTO P/N:MAC 10-16-101 S/N: 92286 Y COPILOTO P/N: MC 10-15-109 S/N: 57797 POSEEMASCARAS DE ACUERDO AL SB MCF-SBN-35-001.           |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (I)                                                                                                                                                                                                 | REGULATOR REPLACEMENT                                                                                                                                                          | FXE  |         | MANDATORY                     | MTH 10-Jan-2016<br>HRS 8174<br>LDG 6797         |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A BY P/N INSTALLED.                                                                                                                                                                        |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |
| FAA 2015-23-09                                                                                                                                                                                                             | APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821       |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DE LAS MASCARA INSTALADAS,PILOTO P/N:MAC 10-16-101 S/N: 92286 Y COPILOTO P/N: MC 10-15-109 S/N: 57797 POSEEMASCARAS DE ACUERDO AL SB MCF-SBN-35-001.           |                                                                                                                                                                                |      |         |                               |                                                 |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                      | Description<br>Drawing # / Task #                                                                                                                                                                                                 | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2016-11-20<br>PARA (G)                                                                 | PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12 |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA POR MODELO DEL PBE DE ACUERDO AL SB 119003-35-0101</b> |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2016-11-20<br>PARA (H.1)                                                               | REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12                                                                    |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA POR MODELO DEL PBE DE ACUERDO AL SB 119003-35-0101</b> |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2016-11-20<br>PARA (H.2)                                                               | REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA POR MODELO DEL PBE DE ACUERDO AL SB 119003-35-0101</b> |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2016-11-20                                                                             | OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12                                                 |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NO APLICA POR MODELO DEL PBE DE ACUERDO AL SB 119003-35-0101</b> |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (G)                                                                 | INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | FXE  |         | MANDATORY                     | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                                                |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (H)                                                                 | REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | FXE  |         | MANDATORY                     | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                                                |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (I) & (J)                                                           | INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.                          |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | FXE  |         | MANDATORY                     | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                                                |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2017-18-12                                                                             | APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES                                                     |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   | FXE  |         | MANDATORY                     | MTH 02-Apr-2018<br>HRS 8531.9<br>LDG 7040 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE</b>                                                                |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 74-08-09 R2                                                                            | WASTE RECEPTACLE INS                                                                                                                                                                                                              |      |         |                               |                                           |                |                |                |                            |                    |
|                                                                                            |                                                                                                                                                                                                                                   |      |         |                               | MTH 06-Jun-2002<br>HRS 5465               |                | O/C            |                |                            |                    |
| <b>MOC : - OPEN</b>                                                                        |                                                                                                                                                                                                                                   |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                          | Description<br>Drawing # / Task #                                                                                                       | City | Mod Lvl | Part Number<br>Part Serial No             | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 74-08-09                                                                                   | WASTE RECEPTACLE INS                                                                                                                    | CCS  |         | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                          |                | O/C            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SE VERIFICO EN LA AERONAVE Y POSEE SUS ETIQUETAS DE "NO SMOKING" |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 96-25-12                                                                                   | COMPRESSOR WHEEL/REPLACE                                                                                                                | CCS  |         | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6821 |                          |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DEL APU, VER SB-T-62T-49-120.      |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| AD 49-01                                                                                       | COMPRESSOR WHEEL/REPLACE                                                                                                                |      |         | APUS                                      |                          |                | 3292           |                | 6073                       | 1278               |
| <b>MOC :</b> - OPEN                                                                            |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1994-14-15<br>E1                                                                           | EXHAUST DUCT ATTACHMENT CLAMPS                                                                                                          |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1994-14-15<br>E2                                                                           | EXHAUST DUCT ATTACHMENT CLAMPS                                                                                                          |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1986-21-05<br>E1                                                                           | INSPECTION / REPAIR OF THE FORWARD ENGINE MOUNTS                                                                                        |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1986-21-05<br>E2                                                                           | INSPECTION / REPAIR OF THE FORWARD ENGINE MOUNTS                                                                                        |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 92-12-09                                                                                   | LP TURBINE DSK/1 STG                                                                                                                    |      |         | MTH 06-Jul-1993<br>HRS 2529               |                          |                | O/C            |                |                            |                    |
| <b>MOC :</b> - OPEN                                                                            |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1978-22-10<br>E1                                                                           | ENGINE - LOW PRESSURE ROTOR THRUST BALL BEARING PN 358736-2 - INSPECT / REPLACE                                                         |      |         | MANDATORY                                 |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1978-22-10<br>E2                                                                           | ENGINE - LOW PRESSURE ROTOR THRUST BALL BEARING PN 358736-2 - INSPECT / REPLACE                                                         |      |         | MANDATORY                                 |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1980-16-04<br>E1                                                                           | ENGINE - TIE ROD - REPLACE                                                                                                              |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1980-16-04<br>E2                                                                           | ENGINE - TIE ROD - REPLACE                                                                                                              |      |         |                                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1981-24-08<br>E1                                                                           | ENGINE - TURBINE INTERSTAGE TRANSITION DUCT - INSPECT / REPLACE                                                                         |      |         | MANDATORY                                 |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1981-24-08<br>E2                                                                           | ENGINE - TURBINE INTERSTAGE TRANSITION DUCT - INSPECT / REPLACE                                                                         |      |         | MANDATORY                                 |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1982-23-03<br>R01<br>E1                                                                    | ENGINE - HIGH PRESSURE COMPRESSOR IMPELLERS - REPLACE                                                                                   | UNK  |         | MANDATORY                                 | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE PER DISK P/N                                      |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1982-23-03<br>R01<br>E2                                                                    | ENGINE - HIGH PRESSURE COMPRESSOR IMPELLERS - REPLACE                                                                                   | UNK  |         | MANDATORY                                 | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - PARTIALLY COMPLIED WITH                                          |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |
| FAA 1986-03-01<br>E1                                                                           | ENGINE - TURBINE INTERSTAGE TRANSITION DUCTS, PART NUMBERS 3071486-3 THROUGH -10, 3072318-1 AND -3, 3072726-1 AND -2 - MODIFY / REPLACE |      |         | MANDATORY                                 |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                   |                                                                                                                                         |      |         |                                           |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position      | Description<br>Drawing # / Task #                                                                                                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1986-03-01<br>E2       | ENGINE - TURBINE INTERSTAGE TRANSITION DUCTS, PART NUMBERS 3071486-3 THROUGH -10, 3072318-1 AND -3, 3072726-1 AND -2 - MODIFY / REPLACE                      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1986-04-02<br>E1       | ENGINE - FAN ROTOR DISKS - REPLACEMENT (SUPERSEDED BY FAA AD 1986-11-05)                                                                                     |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1986-04-02<br>E2       | ENGINE - FAN ROTOR DISKS - REPLACEMENT (SUPERSEDED BY FAA AD 1986-11-05)                                                                                     |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1988-18-03<br>E1       | DETERMINE IF PART NUMBER 3072316-2 OR -3, OR 3073110-1 OR -2, HIGH PRESSURE TURBINE ROTOR (HPTR) DISC WITH ONE OF THE FOLLOWING SERIAL NUMBERS IS INSTALLED. |      |         |                               |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1988-18-03<br>E2       | DETERMINE IF PART NUMBER 3072316-2 OR -3, OR 3073110-1 OR -2, HIGH PRESSURE TURBINE ROTOR (HPTR) DISC WITH ONE OF THE FOLLOWING SERIAL NUMBERS IS INSTALLED. |      |         |                               |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1990-03-04<br>E1       | TFE731-3, -3A, -3AR, AND -3R TURBOFAN ENGINES EQUIPPED WITH HIGH PRESSURE TURBINE ROTOR (HPTR) DISCS, PART NUMBERS 3072316-2, -3, AND 3073110-1, -2.         |      |         |                               |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1990-03-04<br>E2       | TFE731-3, -3A, -3AR, AND -3R TURBOFAN ENGINES EQUIPPED WITH HIGH PRESSURE TURBINE ROTOR (HPTR) DISCS, PART NUMBERS 3072316-2, -3, AND 3073110-1, -2.         |      |         |                               |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1991-08-13<br>E1       | ENGINE - FAN ROTOR DISK DOVETAIL SLOT CRACKS - EDDY CURRENT INSPECTIONS (SUPERSEDED BY FAA 1996-05-03)                                                       |      |         | SUPERSEDED                    |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1991-08-13<br>E2       | ENGINE - FAN ROTOR DISK DOVETAIL SLOT CRACKS - EDDY CURRENT INSPECTIONS (SUPERSEDED BY FAA 1996-05-03)                                                       |      |         | SUPERSEDED                    |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1992-21-06<br>E1       | ENGINE - LPT ROTOR DISK - REPLACE                                                                                                                            |      |         | MANDATORY                     |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1992-21-06<br>E2       | ENGINE - LPT ROTOR DISK - REPLACE                                                                                                                            |      |         | MANDATORY                     |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1992-26-09<br>E1       | ENGINE - FAN DISK - INSPECT / REPLACE (SUPERSEDED BY AD FAA 1993-25-16)                                                                                      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1992-26-09<br>E2       | ENGINE - FAN DISK - INSPECT / REPLACE (SUPERSEDED BY AD FAA 1993-25-16)                                                                                      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1993-25-16<br>E1       | ENGINE - FAN DISK - INSPECT / REPLACE (SUPERSEDED BY AD FAA 1996-04-01)                                                                                      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1993-25-16<br>E2       | ENGINE - FAN DISK - INSPECT / REPLACE (SUPERSEDED BY AD FAA 1996-04-01)                                                                                      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>               |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1994-07-03<br>E1       | ENGINE - LOW PRESSURE TURBINE (LPT) DISK SEAL - REPLACEMENT / AFM - REVISE                                                                                   |      |         | MANDATORY                     | MTH 07-Jul-1993          |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b> |                                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                                                                                                                          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1994-07-03<br>E2  | ENGINE - LOW PRESSURE TURBINE (LPT) DISK SEAL - REPLACEMENT / AFM - REVISE                                                                                                                                                 |      |         | MANDATORY                     | MTH 07-Jul-1993          |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                 |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1995-07-02<br>E1  | TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE AND DAMAGE TO THE AIRCRAFT,                                                                                 |      |         |                               | MTH 26-Jul-1995          |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                 |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1995-07-02<br>E2  | TO PREVENT A LOW PRESSURE TURBINE (LPT) DISK WEB SEPARATION, WHICH MAY RESULT IN AN UNCONTAINED ENGINE FAILURE AND DAMAGE TO THE AIRCRAFT,                                                                                 |      |         |                               | MTH 26-Jul-1995          |                | A/R            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                 |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1996-04-01<br>E1  | ENGINE - FAN ROTOR ASSEMBLY - INSPECT / REPLACE                                                                                                                                                                            |      |         | MANDATORY                     | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - NOT APPLICABLE PER DISK P/N</b>                                                                                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1996-04-01<br>E2  | ENGINE - FAN ROTOR ASSEMBLY - INSPECT / REPLACE                                                                                                                                                                            |      |         | MANDATORY                     | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b>                                                                                                                                                                      |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1996-05-03<br>E1  | TO PREVENT UNCONTAINED FAILURE OF FAN ROTOR DISKS DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS, WHICH CAN RESULT IN INFLIGHT ENGINE SHUTDOWNS, SEVERE SECONDARY DAMAGE, AND FAN ROTOR ASSEMBLY SEPARATION FROM THE ENGINE |      |         |                               | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - NOT APPLICABLE PER DISK P/N</b>                                                                                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1996-05-03<br>E2  | TO PREVENT UNCONTAINED FAILURE OF FAN ROTOR DISKS DUE TO FATIGUE CRACKING IN THE DOVETAIL SLOTS, WHICH CAN RESULT IN INFLIGHT ENGINE SHUTDOWNS, SEVERE SECONDARY DAMAGE, AND FAN ROTOR ASSEMBLY SEPARATION FROM THE ENGINE |      |         |                               | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - PARTIALLY COMPLIED WITH</b>                                                                                                                                                                      |      |         |                               |                          |                |                |                |                            |                    |
| FAA 1997-04-03<br>E2  | ALLIED SIGNAL, 1 STG LPT SEAL                                                                                                                                                                                              |      |         |                               | MTH 30-Jul-2011          |                | O/C            |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                                                                       |      |         |                               |                          |                |                |                |                            |                    |
| FAA 2000-15-09<br>E1  | ENGINE - HIGH PRESSURE COMPRESSURE (HPC) IMPELLER - REPLACE                                                                                                                                                                |      |         | MANDATORY                     | MTH 12-Oct-2011          |                |                |                |                            | Complete           |
|                       |                                                                                                                                                                                                                            |      |         |                               | HRS 7545.1               |                | 4200           |                | (11568.2)11745.1           | 2971.2             |
|                       |                                                                                                                                                                                                                            |      |         |                               | LDG 6403                 |                |                |                |                            |                    |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                 |      |         |                               |                          |                |                |                |                            |                    |
| FAA 2000-15-09<br>E2  | ENGINE - HIGH PRESSURE COMPRESSURE (HPC) IMPELLER - REPLACE                                                                                                                                                                |      |         | MANDATORY                     | MTH 11-Oct-2011          |                |                |                |                            | Complete           |
|                       |                                                                                                                                                                                                                            |      |         |                               | HRS 7356.1               |                | 4200           |                | (11366.4)11556.1           | 2782.2             |
|                       |                                                                                                                                                                                                                            |      |         |                               | LDG 6103                 |                |                |                |                            |                    |
|                       | <b>MOC : COMPLIED WITH - PARTIALLY COMPLIED WITH</b>                                                                                                                                                                       |      |         |                               |                          |                |                |                |                            |                    |
| FAA 2001-23-09<br>E1  | ENGINE - FAN ROTOR DISC - REPLACE                                                                                                                                                                                          |      |         | MANDATORY                     | MTH 30-Jul-2011          |                | -              |                |                            | N/A                |
|                       | <b>MOC : NOT APPLICABLE - NOT APPLICABLE PER DISK P/N</b>                                                                                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| FAA 2001-23-09<br>E2  | ENGINE - FAN ROTOR DISC - REPLACE                                                                                                                                                                                          |      |         | MANDATORY                     | MTH 17-Nov-2006          |                | -              |                |                            | Complete           |
|                       | <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                 |      |         |                               |                          |                |                |                |                            |                    |
| FAA 2005-05-15<br>E1  | ENGINE - LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS - INSPECT / REPLACE                                                                                                                                                      |      |         | MANDATORY                     | MTH 22-Sep-2016          |                | -              |                |                            | N/A                |
|                       |                                                                                                                                                                                                                            | CCS  |         |                               | HRS 8218.5               |                |                |                |                            |                    |
|                       |                                                                                                                                                                                                                            |      |         |                               | LDG 6821                 |                |                |                |                            |                    |
|                       | <b>MOC : NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DEL LOW PRESSURE TURBINE (LPT) STAGE DISK, POSEE P/N: 3074076-2</b>                                                                                                |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                       | Description<br>Drawing # / Task #                                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2005-05-15<br>E2                                                                                                        | ENGINE - LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS - INSPECT / REPLACE                                    | CCS  |         | MANDATORY                     | MTH 22-Sep-2016<br>HRS 8218.5<br>LDG 6820 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APLICA POR NUMERO DE PARTE DEL LOW PRESSURE TURBINE (LPT) STAGE DISK, POSEE P/N: 3074076-2 |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2005-13-07<br>E1                                                                                                        | ENGINE - LOW PRESSURE (LP) 1ST AND 2ND STAGE TURBINE ROTOR DISC - REPLACE                                |      |         | MANDATORY                     | MTH 02-Nov-2011<br>HRS 7548.3<br>LDG 6408 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND TO BE N/A BY P/N S/N INSTALLED                                                          |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2005-13-07<br>E2                                                                                                        | ENGINE - LOW PRESSURE (LP) 1ST AND 2ND STAGE TURBINE ROTOR DISC - REPLACE                                |      |         | MANDATORY                     | MTH 02-Nov-2011<br>HRS 7548.3<br>LDG 6408 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND TO BE N/A BY P/N S/N INSTALLED                                                          |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2008-02-19<br>E1                                                                                                        | ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE                                        |      |         | MANDATORY                     | MTH 20-Mar-2008<br>HRS 5926.9             |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY PART NUMBER                                                                                |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2008-02-19<br>E2                                                                                                        | ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE                                        |      |         | MANDATORY                     | MTH 20-Mar-2008<br>HRS 5922.7             |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY PART NUMBER                                                                                |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2010-06-11<br>E1                                                                                                        | ENGINE - SECOND STAGE LOW-PRESSURE COMPRESSOR ROTOR (LPCR) DISCS AND/OR THIRD STAGE LPCR DISCS - REPLACE | UNK  |         | MANDATORY                     | MTH 30-Jul-2011                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE PER DISK P/N                                                                   |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2010-06-11<br>E2                                                                                                        | ENGINE - SECOND STAGE LOW-PRESSURE COMPRESSOR ROTOR (LPCR) DISCS AND/OR THIRD STAGE LPCR DISCS - REPLACE |      |         | MANDATORY                     | MTH 31-Mar-2010<br>HRS 7255.1<br>LDG 6205 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY SERIAL NUMBER                                                                              |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 1993-10-10<br>E1                                                                                                        | ENGINE FUEL AND CONTROL - FUEL LINE CLAMP ASSEMBLY (SUPERSEDED BY FAA AD 1998-17-01)                     |      |         | MANDATORY                     | MTH 11-Jan-1993<br>HRS 2326.9             |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                  |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 1993-10-10<br>E2                                                                                                        | ENGINE FUEL AND CONTROL - FUEL LINE CLAMP ASSEMBLY (SUPERSEDED BY FAA AD 1998-17-01)                     |      |         | MANDATORY                     | MTH 11-Jan-1993<br>HRS 2322.7             |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                  |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 1998-17-01<br>R01<br>E1                                                                                                 | ENGINE FUEL AND CONTROL - FLEX FUEL TUBE - INSTALL                                                       | UNK  |         | MANDATORY                     | MTH 18-Aug-2002                           |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PREVIOUSLY COMPLIED WITH PER SB                                                                |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 1998-17-01<br>R01<br>E2                                                                                                 | ENGINE FUEL AND CONTROL - FLEX FUEL TUBE - INSTALL                                                       | UNK  |         | MANDATORY                     | MTH 17-Jun-1999                           |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PARTIALLY COMPLIED WITH                                                                        |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 1998-17-01<br>E1                                                                                                        | ENGINE FUEL AND CONTROL - FLEX FUEL TUBE - INSTALL                                                       |      |         | MANDATORY                     | MTH 18-Nov-1998<br>HRS 4537.9             |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                  |                                                                                                          |      |         |                               |                                           |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **KM BRIDGE GROUP LLC**  
Aircraft Model: **650 - CITATION III**  
Aircraft Serial: **650-0104**  
Unit: Reg No: **N264GV**  
Airworthiness: **21-Aug-1986**  
Print Date: **30-Jan-2025 2:57PM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>8773.9</b> | <b>7234</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 1</b>    | <b>8597</b>   | <b>7023</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>ENG 2</b>    | <b>8584.2</b> | <b>6931</b>         | <b>23-May-2024</b>  | <b>.03</b>                   |
| <b>APU</b>      | <b>2174</b>   | <b>4795</b>         | <b>23-May-2024</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code           | Description                                                | Part Number | C/W Time 1  | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|---------------------|------------------------------------------------------------|-------------|-------------|----------------|------------|--------|-------------|---------|-------------|----------|
| Position            | Drawing # / Task #                                         | City        | Mod Lvl     | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| FAA 1998-17-01      | ENGINE FUEL AND CONTROL - FLEX FUEL TUBE - INSTALL         | MTH         | 18-Nov-1998 |                |            | -      |             |         |             | Complete |
| E2                  |                                                            |             |             | MANDATORY      | HRS        | 4533.7 |             |         |             |          |
| MOC : COMPLIED WITH |                                                            |             |             |                |            |        |             |         |             |          |
| FAA 1990-24-06      | ENGINE INDICATION - THERMOCOUPLE LEAD ASSEMBLIES - REPLACE |             |             |                |            |        |             |         |             |          |
| E1                  |                                                            |             |             | MANDATORY      |            |        | -           |         |             |          |
| MOC :               |                                                            |             |             |                |            |        |             |         |             |          |
| FAA 1990-24-06      | ENGINE INDICATION - THERMOCOUPLE LEAD ASSEMBLIES - REPLACE |             |             |                |            |        |             |         |             |          |
| E2                  |                                                            |             |             | MANDATORY      |            |        | -           |         |             |          |
| MOC :               |                                                            |             |             |                |            |        |             |         |             |          |