



Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

N Number: 4485S

Last Action Date	2023-09-02		
Airworthiness Date	1975-05-28	Expiration Date	2029-09-30
Manufacturer_Name	BEECH	Model Name	V35B
Registrant Name	FAHLE WILLIAM A JR	Street	580 PEARL CV
Registrant City	OAK POINT	Registrant State	TX
Registrant Zip Code	750682253	Country	UNITED STATES
Region	Southwestern	Registrant Type	Co-Owned
Fract Owner		Certificate Issue Date	2019-09-12
Status	N-Number Assigned and Registered		
Serial Number	D-9785	Aircraft Type	Fixed wing single engine
Mode S Code	51265555	Year Mfr	1975
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	1	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	150
Airworthiness Classification	Standard	Approved Operation Codes	Utility
Engine Manufacturer	CONT MOTOR		
Engine Model Name	IO 520 SERIES	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

----- History 1 -----

Last Action Date	2022-04-12
-------------------------	------------

Registrant Name	FAHLE WILLIAM A JR	Street	580 PEARL CV
Registrant City	OAK POINT	Registrant State	TX
Registrant Zip Code	750682253	Country	UNITED STATES
Region	Southwestern	Registrant Type	Co-Owned
Fract Owner		Certificate Issue Date	2019-09-12
Status	N-Number Assigned and Registered		

----- History 2 -----

Last Action Date	2019-09-12		
Registrant Name	FAHLE WILLIAM A JR	Street	580 PEARL CV
Registrant City	OAK POINT	Registrant State	TX
Registrant Zip Code	750682253	Country	UNITED STATES
Region	Southwestern	Registrant Type	Co-Owned
Fract Owner		Certificate Issue Date	2019-09-12
Status	First Notice for Registration Renewal		

----- History 3 -----

Last Action Date	2019-08-13		
Registrant Name	REGISTRATION PENDING	Street	580 PEARL CV
Registrant City	OAK POINT	Registrant State	TX
Registrant Zip Code	750682253	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	
Status	Registration pending		

----- History 4 -----

Last Action Date	2018-03-14		
Registrant Name	FENDER EXPLORATION & PRODUCTION CO LP	Street	PO BOX 8720
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	757118720	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership

Fract Owner	Certificate Issue Date	2015-05-18
Status	N-Number Assigned and Registered	

----- History 5 -----

Last Action Date	2015-05-18		
Registrant Name	FENDER EXPLORATION & PRODUCTION CO LP	Street	PO BOX 8720
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	757118720	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner	Certificate Issue Date	2015-05-18	
Status	First Notice for Registration Renewal		

----- History 6 -----

Last Action Date	2014-02-28		
Registrant Name	FAMILY FOUR PARTNERS LP	Street	PO BOX 8720
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	757118720	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner	Certificate Issue Date	1998-03-18	
Status	N-Number Assigned and Registered		

----- History 7 -----

Last Action Date	2013-12-30		
Registrant Name	FAMILY FOUR PARTNERS LP	Street	PO BOX 8720
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	757118720	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner	Certificate Issue Date	1998-03-18	
Status	First Notice for Registration Renewal		

----- History 8 -----

Last Action Date	2011-04-27		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	116 E FRONT ST
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	757028120	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	First Notice for Registration Renewal		

----- History 9 -----

Last Action Date	2010-03-16		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	PO BOX 449
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	75710-0449	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	Registration Expired		

----- History 10 -----

Last Action Date	2007-03-20		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	PO BOX 449
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	75710-0449	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 11 -----

Last Action Date	2004-03-16		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	PO BOX 449

Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	75710-0449	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 12 -----

Last Action Date	2001-03-20		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	PO BOX 449
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	75710-0449	Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 13 -----

Last Action Date	1998-03-18		
Registrant Name	DAVID M FENDER FAMILY PARTNERSHIP LTD	Street	PO BOX 449
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code		Country	UNITED STATES
Region	Southwestern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	1998-03-18
Status	N-Number assigned		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

----- FAA Accident/Incident 1 -----

Occurrence Date	2002-08-15	Aircraft Make	BEECH
------------------------	------------	----------------------	-------

Aircraft Model	V35B	Damage	MINOR
Document Last Modified	2012-08-08		
Narrative	(-23) ON AUGUST 15, 2002, AT APPROXIMATELY 1010 CENTRAL DAYLIGHT TIME MR. WILLIAM PENNOCK, A COMMERCIAL RATED PILOT, WAS ATTEMPTING TO LAND AT AMARILLO INTERNATIONAL AIRPORT ON RUNWAY 22. DURING THIS LANDING HE EXPERIENCED A COLLAPSE OF ALL THREE MAIN LANDING GEAR ASSEMBLIES. THE AIRCRAFT CAME TO REST 2,700 FEET FROM THE APPROACH OF RUNWAY 22. THERE WERE A TOTAL OF FOUR PASSENGERS ABOARD. IT WAS REPORTED THAT THERE WERE NO INJURIES TO THOSE INDIVIDUALS. THE AIRCRAFT SUSTAINED MINOR DAMAGE TO RIGHT AND LEFT WING TRAILING EDGE OF THE FLAPS, RIGHT MAIN LANDING GEAR OUTBOARD DOORS, BRAKE CALIPERS, DAMAGE TO THE NOSE LANDING GEAR DOORS AND A SUDDEN STOPPAGE TO THE AIRCRAFT ENGINE WHEN THE PROPELLER CAME IN CONTACT WITH THE RUNWAY. INSPECTION OF THE AIRCRAFT REVEALED THAT THE PILOT INADVERTENTLY RETRACTED THE LANDING GEAR HANDLE INSTEAD OF THE FLAP HANDLE.		

***** No NTBS Accidents Found *****

***** No NTBS Pre 1982 Accidents Found *****

***** No SDR's Found *****

[Custom Reports](#)

Copyright 2001 - 2025 AviationDB.com Corp. All Rights Reserved

[Legal](#) [Contact Us](#)