

DATE 19 _____	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate No. of Technician or Repair Facility. (See back pages for other special instructions)

N9427N PA28R-200 28R-35139 Tach 3011.9 ACTT 3011.9

*9-23-25 Annual Inspection*

- 1- AD 17-14-04 Installed type " D " oil cooler hoses ( AD no longer applies )
- 2- PCW on 3-24, AD 13-02-13, inspect elevator cables ( every 7 yrs due 3-31 )
- 3- AD 97-01-01 C/W side brace stud inspection ( every 500 hrs )
- 4- AD 15-19-07 C/W Inspected fuel injector lines and clamps. ( Every 100 Hrs )
- 5- AD 76-07-12R1, C/W Inspect and test magneto switch ( every 100Hrs )
- 6- Replaced bolts and bushings at RH main gear scissors
- 7- Replaced LH bottom scissor bolt and bushings
- 8- Replaced brake discs at both main wheels
- 9- Cleaned and packed all wheel bearings. LH, RH, Nose
- 10- Replaced nose gear steering rollers
- 11- Lubed trim drum and bushings
- 12- Removed ELT for repair, 90 days



ns  
f  
(S.)

DATE

19

- 13- ~~Removed and replaced landing gear powerpack, and serviced~~
- 14- Lubed fuel selector valve
- 15- Replaced complete exhaust system, Knisley
- 16- Replaced scat ducting at engine compartment
- 17- Replace brake cylinder orings at wheels
- 18- Bleed brakes
- 19- Replaced brake linings at LH wheel
- 20- Replaced LH fuel tank drain seal
- 21- Inspect and check main fuel screen

Installed  
original <sup>R</sup>  
powerpack.

ations  
per of  
ntries.)

I certify this aircraft has been inspected in accordance with an ANNUAL INSPECTION  
and has been found to be in an airworthy condition

Robert Clay AP 1896667 IA

9-23-25 R Clay

- 6 452-448 bushings
- 3 AN175-32 bolt
- 1 AN175-32 bolt
- 2 AN174-14 bolt

3012-5 10-4-25

Removed + Replaced nose wheel  
bearings. 08125 08231

R Clay 1896667 AP