

OWNER: GHANIMA LLC		OPERATOR: PRIVATE JETS INC.		
ADDRESS: 155 PLEASANT ST		ADDRESS: 7200 NW 63RD STREET		
NORWELL MA 02061		BETHANY OK 73008		
OFFICE:		OFFICE: 405-681-4466		
FAX:		FAX: 405-681-1661		
ANALYST:	SEAN WELLS	+1-316-928-7895 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	SWELLS@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

AIRCRAFT	SERIAL / REGNO: 45-145/N942FK	MODEL:	LEARJET 45XR	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 09-MAR-2001		LAST ACTUALS:		
		9778.1 A/C HRS as of 21-JUL-2025		
		7452 AFL as of 21-JUL-2025		
		2653.1 ACH as of 20-FEB-2025		

ENGINE NO. 1	SERIAL / PART: P-116284C/3060082-2	MODEL:	TFE731-20BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 20-JAN-2000		LAST ACTUALS:		
0	ENG. HRS	0 A/C HRS	9704	ENG. HRS as of 21-JUL-2025
0	ENC		7394	ENC as of 21-JUL-2025

ENGINE NO. 2	SERIAL / PART: P-116285C/3060084-2	MODEL:	TFE731-20BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 12-AUG-2015		LAST ACTUALS:		
6622.3	ENG. HRS	7535.1 A/C HRS	8865.3	ENG. HRS as of 21-JUL-2025
5602	ENC		7290	ENC as of 21-JUL-2025

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025
 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160527	REVIEW LEARJET AMM REVISION 66								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
CI45-181109B		REVIEW LEARJET 45/45XR AMM REVISION 71							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-190429A		REVIEW LEARJET 45/45XR AMM REV 72							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-200529		REVIEW AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM	
	HRS								
	AFL								
PROC. REF: RCF CI45PROC. REF: RCF CI45									
CI45-210120		REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	30-Mar-21	-					AUDIT SUMMARY CHANGE FORM	
	HRS	8414.4							
	AFL	6463							
PROC. REF: RCF CI45PROC. REF: RCF CI45									
EC04-180802		NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 00 - INFORMATION									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802									
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051101	PHASE A1-300 HOUR CHECKS								Package ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
WC#: 05.110	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01									
051102	PHASE A2-300 HOUR CHECKS								Package ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02									
051103	PHASE A3-300 HOUR CHECKS								Package ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03									
051104	PHASE A4-300 HOUR CHECKS								Package ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-04PROC. REF: AMM 05-10-00, AMM 05-11-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051105	PHASE A5-300 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-05PROC. REF: AMM 05-10-00, AMM 05-11-05									PKG:5
051106	PHASE A6-300 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	12		02-Aug-25		10 d		
	HRS	9525.7	325		9850.7		72.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-11-06PROC. REF: AMM 05-10-00, AMM 05-11-06									PKG:6
051201	PHASE B1 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-01PROC. REF: AMM 05-10-00, AMM 05-12-01									PKG:7
051202	PHASE B2 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-02PROC. REF: AMM 05-10-00, AMM 05-12-02									PKG:8
051203	PHASE B3 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-03PROC. REF: AMM 05-10-00, AMM 05-12-03									PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051204	PHASE B4 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-04PROC. REF: AMM 05-10-00, AMM 05-12-04									PKG:10
051205	PHASE B5 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-05PROC. REF: AMM 05-10-00, AMM 05-12-05									PKG:11
051206	PHASE B6 600 HOUR CHECKS							Package	ATA:05
	MOS	02-Aug-24	24		02-Aug-26		375 d		
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-12-06PROC. REF: AMM 05-10-00, AMM 05-12-06									PKG:12
051301	PHASE C1 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-01PROC. REF: AMM 05-10-00, AMM 05-13-01									PKG:13
051302	PHASE C2 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-02PROC. REF: AMM 05-10-00, AMM 05-13-02									PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051303	PHASE C3 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-03PROC. REF: AMM 05-10-00, AMM 05-13-03									PKG:15
051304	PHASE C4 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-04PROC. REF: AMM 05-10-00, AMM 05-13-04									PKG:16
051305	PHASE C5 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-05PROC. REF: AMM 05-10-00, AMM 05-13-05									PKG:17
051306	PHASE C6 1200 HOUR CHECKS							Package	ATA:05
	MOS	22-Jun-23	48		22-Jun-27		699 d		
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-13-06PROC. REF: AMM 05-10-00, AMM 05-13-06									PKG:18
051401	PHASE D1 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-01PROC. REF: AMM 05-10-00, AMM 05-14-01									PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051402	PHASE D2 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-02PROC. REF: AMM 05-10-00, AMM 05-14-02									PKG:20
051403	PHASE D3 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-03PROC. REF: AMM 05-10-00, AMM 05-14-03									PKG:21
051404	PHASE D4 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-04PROC. REF: AMM 05-10-00, AMM 05-14-04									PKG:22
051405	PHASE D5 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-05PROC. REF: AMM 05-10-00, AMM 05-14-05									PKG:23
051406	PHASE D6 2400 HOUR CHECKS							Package	ATA:05
	MOS	25-Nov-19	96		25-Nov-27		855 d		
	HRS	8177.7	2400		10577.7		799.6		
	AFL	6303							
PROC. REF: AMM 05-10-00, AMM 05-14-06PROC. REF: AMM 05-10-00, AMM 05-14-06									PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051500	4800 HOUR CHECKS								Package ATA:05
	MOS	22-Jun-23							
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 05-10-00, AMM 05-15-00PROC. REF: AMM 05-10-00, AMM 05-15-00									PKG:25
051600	9600 HOUR CHECKS								Package ATA:05
	MOS	02-Aug-24							
	HRS	9525.7	9600		19125.7		9347.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 05-16-00PROC. REF: AMM 05-10-00, AMM 05-16-00									PKG:26
051700	MAJOR LANDING GEAR INSPECTION								Package ATA:05
	MOS	09-Mar-01							
	HRS	0							
	AFL	0	10000		10000		2548		
PROC. REF: AMM 05-10-00, AMM 05-17-00PROC. REF: AMM 05-10-00, AMM 05-17-00									PKG:27
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	02-Aug-24							
	HRS	9451.6	250		(9701.6) 9775.7		OVD		
	ENC	7218							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	02-Aug-24							
	HRS	8612.9	250		(8862.9) 9775.7		OVD		
	ENC	7114							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	22-Jun-23	N/A						
	HRS	9184.4							
	ENC	7042							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS/MSC	18-Aug-22	N/A						
	HRS	8169.8							
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	22-Jun-23							
	HRS	9184.4	600		(9784.4) 9858.5		80.4		
	ENC	7042							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	22-Jun-23							
	HRS	8345.7	600		(8945.7) 9858.5		80.4		
	ENC	6938							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package	ATA:05
	MOS	18-Aug-22							
	HRS	9008.5	800		(9808.5) 9882.6		104.5		
	ENC	6936							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	18-Aug-22							
	HRS	8169.8	800		(8969.8) 9882.6		104.5		
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	27-Aug-21							
	HRS	8634.1	1200		(9834.1) 9908.2		130.1		
	ENC	6633							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	27-Aug-21							
	HRS	7795.4	1200		(8995.4) 9908.2		130.1		
	ENC	6529							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	22-Jun-23							
	HRS	9184.4	1600		(10784.4) 10858.5		1080.4		
	ENC	7042							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								Package ATA:05
	MOS	18-Aug-22							
	HRS	8169.8	1600		(9769.8) 10682.6		904.5		
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
5-50-00-BS		INSPECTION BIRD STRIKE						Service	ATA:05
	MOS/MSC		A/R					INSPECT	
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-50-00-EV		PERFORM ENGINE VIBRATION TEST AND INSPECTION						Service	ATA:05
	MOS/MSC		A/R						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-FD		INSPECTION FOREIGN OBJECT DAMAGE						Service	ATA:05
	MOS/MSC		O/C						
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-HL		INSPECTION HARD LANDING						Service	ATA:05
	MOS/MSC		A/R					INSPECT	
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-LS		INSPECTION LIGHTNING STRIKE						Service	ATA:05
	MOS/MSC	09-Mar-01	A/R					INSPECT	
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									
5-50-00-OW		INSPECTION OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)						Service	ATA:05
	MOS/MSC		A/R					INSPECT	
	HRS								
	AFL								
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 08 - LEVELING AND WEIGHING									
082000	REWEIGH AIRCRAFT							Service	ATA:08
	MOS	30-Dec-22	36		30-Dec-25		160 d		
	HRS	9186.7							
	AFL	7047							
PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185									
ATA 11 - PLACARDS AND MARKINGS									
112030 ^U	INSPECTION INTERNAL AND EXTERNAL PLACARD							Service	ATA:11
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
ATA 12 - SERVICING									
5-19-00-U1210004	LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND (U1210004)							Service	ATA:12
	MOS	12-Aug-15							
	HRS	7535.1	4800		12335.1		2557		
	AFL	5764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
AB1210060 ^S	MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE							Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
O1210002 ^S	FLAP ACTUATORS - CHECK OIL LEVEL							Service	ATA:12
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Q1221064	LEFT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A	Adj -28d					
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									
Q1221064	LEFT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A	Adj -28					
	HRS	8177.8							
	AFL	6304							
Q1221064	RIGHT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A	Adj -28					
	HRS	8177.8							
	AFL	6304							
Q1221064	RIGHT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)							Service	ATA:12
	MOS/MSC	05-Dec-19	N/A	Adj -28					
	HRS	8177.8							
	AFL	6304							
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02									
Y1210001 ^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210003 ^S		FLAP ACTUATOR BALLNUT - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:4
Y1210005 ^S		NOSE LANDING GEAR TRUNNION PIN - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210006 ^S		NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210007 ^S		NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5
Y1210009 ^S		NOSE GEAR DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210011 ^S		MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210012 ^S		MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210013 ^S		MAIN LANDING GEAR TORQUE LINKS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1210014 ^S		MAIN LANDING GEAR DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:5
Y1210016 ^S		PASSENGER/CREW DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210017 ^S		PASSENGER/CREW DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210018 ^S		PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210019 ^S		EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210020 ^S		EMERGENCY EXIT DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210021 ^S		BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210022	^S	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210023	^S	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:1
Y1210024	^S	TOILET SERVICING DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:4
Y1210025	^S	PRESSURE REFUELING STATION DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:2
Y1210026	^S	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1210027	^S	TAILCONE ACCESS DOOR PINS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210028	^S	TAILCONE ACCESS DOOR HINGE - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									PKG:6
Y1210029	^S	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5
Y1221037	^S	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:4
Y1221042	^S	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03									PKG:9

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 12 - SERVICING									
Y1227000 ^S		EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE						Service	ATA:12
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00									
									PKG:1

ATA 21 - AIR CONDITIONING

211001		SERVO AIR PRESSURE REGULATING VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									

211011		LEFT PLENUM CHECK VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09									

211012		RIGHT PLENUM CHECK VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09									

211017		LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									

211018		RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212001	COCKPIT AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01									
212007	AFT BLOWER MOTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									
212008	FORWARD BLOWER MOTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212011	LINEAR ELECTRO-MECHANICAL ACTUATOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212041	LEFT ENGINE OZONE CONVERTER								Component ATA:21
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0					
SN:2298	HRS	8936.8		TSN 0					
	AFL	6867		TSN 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
212041A	TEST LEFT EFFICIENCY. (Y2140001)								Service ATA:21
PN:4520000100-801	MOS	01-Apr-22							
SN:2298	HRS	8936.8	3600		12536.8		2758.7		
	AFL	6867							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212042	RIGHT ENGINE OZONE CONVERTER							Component	ATA:21
PN:4520000100-801	MOS/MSC	01-Apr-22	O/C	TSN 0					
SN:2305	HRS	8936.8		TSN 0					
	AFL	6867		TSN 0					
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12									
212042A	TEST RIGHT EFFICIENCY (Y2140001)							Service	ATA:21
PN:4520000100-801	MOS	01-Apr-22							
SN:2305	HRS	8936.8	3600		12536.8		2758.7		
	AFL	6867							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212101	NO. 1 THERMAL CONTROL ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212102	NO. 2 THERMAL CONTROL ACTUATOR							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212105	LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
212106	RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
212201	LEFT GASPER AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212202	RIGHT GASPER AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07									
212213	LEFT CABIN AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212214	RIGHT CABIN AIR CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02									
212801	AVIONICS COOLING FAN MOUNT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01									
213000	CABIN PRESSURE CONTROLLER								Component ATA:21
PN:6628408000-023 (10551B08Y09)	MOS/MSC	17-Feb-05	O/C	TSR 0					
SN:0716	HRS	3300.2		TSR 0					
	AFL	2515		TSR 0					
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:3291224-1	MOS/MSC	03-Dec-09	O/C						
SN:133	HRS	6212.8							
	AFL	4758							
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01									
213021	JET PUMP EJECTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06									
213031	PRIMARY OUTFLOW VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01									
213032	SECONDARY OUTFLOW VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02									
213055	EMERGENCY PRESSURE ANEROID SWITCH								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
213056	ABSOLUTE PRESSURE SWITCH								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213101	TAILCONE CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
213110	CABIN PRESSURIZATION CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07									
214301	FOOT WARMER (S167) THERMOSTAT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02									
214925	LEFT ECS CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04									
214926	RIGHT ECS CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215001	WATER SEPARATOR ASSEMBLY								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03									
215002	WATER SEPARATOR BYPASS VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215010	AIR CYCLE MACHINE PRECOOLER ASSEMBLY								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08									
215013	PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02									
215015	AIR CYCLE MACHINE BYPASS CHECK VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07									
215019	CABIN REFRIGERATION CONDENSER								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215030	ENVIRONMENTAL CONTROL UNIT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01									
215033	AIR CYCLE MACHINE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215036	HEAT, PRIMARY, SECONDARY EXCHANGER								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215039	AIR CYCLE MACHINE TURBINE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04									
215043	AFT EVAPORATOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09									
215044	FORWARD EVAPORATOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
215100	AIR CONDITIONING COMPRESSOR							Component	ATA:21
PN:JBS222-1	MOS/MSC	26-Jul-23	O/C	TSO 0					
SN:K18869	HRS	9278		TSO 0					
	AFL	7111		TSO 0					
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01									
215101	AIR CONDITIONING COMPRESSOR DRIVE MOTOR							Component	ATA:21
PN:MB86B-6	MOS/MSC	31-Jul-23	O/C	TSO 0					
SN:234	HRS	9282.8		TSO 0					
	AFL	7113		TSO 0					
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02									
215101A	AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM BRUSH WEAR INSPECTION - IRN L2150054							Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23							
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	600		3196.2		543.1		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
215101B	AIR CONDITIONING COMPRESSOR DRIVE MOTOR - OVERHAUL							Service	ATA:21
PN:MB86B-6	MOS	31-Jul-23						OVERHAUL	
SN:234	HRS	9282.8							
	AFL	7113							
	ACH	2596.2	1200		3796.2		1143.1		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
216001	ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER							Component	ATA:21
PN:1151830-3	MOS/MSC	04-Jan-21	O/C						
SN:1151830-00815	HRS	8361.7							
	AFL	6425							
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10									
216013	COCKPIT TEMPERATURE CONTROL VALVE							Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025
 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216014	CABIN TEMPERATURE CONTROL VALVE								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04									
216025	COCKPIT TEMPERATURE CONTROL SELECTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01									
216026	CABIN TEMPERATURE CONTROL SELECTOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01									
216036	COCKPIT DUCT OVERHEAT THERMOSTAT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09									
216037	CABIN DUCT OVERHEAT THERMOSTAT								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08									
216040	28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216047 ^U		TEMP CONTROL, COCKPIT VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
216049		CABIN DUCT OVERTEMP LIMITER						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06									
216071		LOW LIMIT TEMPERATURE CONTROL VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
216074		SERVO AIR PRESSURE REGULATING VALVE						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01									
216081		COCKPIT DUCT TEMPERATURE SENSOR						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07									
216083		COCKPIT TEMPERATURE SENSOR						Component	ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 21 - AIR CONDITIONING									
216084	CABIN LOW LIMIT TEMPERATURE SENSOR								Component ATA:21
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09									
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service ATA:21
	MOS/MSC	31-Jul-23	N/A					NOT INSTALLED	
	HRS	9282.8							
	AFL	7113							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)								Service ATA:21
	MOS/MSC	22-Jun-23	-					NOT INSTALLED	
	HRS	9258.5							
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-Y2130065	LEAK TEST CABIN PRESSURIZATION SYSTEM. (IRN # Y2130065).								Service ATA:21
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # W2141002)								Service ATA:21
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
J2160007 ^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS								Service ATA:21
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11									

PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 21 - AIR CONDITIONING

O2130001	^S	OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE						Service	ATA:21
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04									PKG:19

Y2130003	^S	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:21
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00									PKG:7

Y2141001	^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.						Service	ATA:21
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2

Y2142000	^S	BAGGAGE COMPARTMENT HEATING SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:21
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00									PKG:20

ATA 22 - AUTO FLIGHT

2210-RVSM		FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.						Service	ATA:22
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025
 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 22 - AUTO FLIGHT									
221001	AUTOPILOT FLIGHT GUIDANCE CONTROLLER								Component ATA:22
PN:7021170-901	MOS/MSC	25-Jan-19	O/C						
SN:05111601	HRS	8026.4							
	AFL	6168							
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01									
221041	AUTOPILOT ROLL SERVO								Component ATA:22
PN:PN 4006719-948	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04									
221045	AUTOPILOT ROLL SERVO BRACKET								Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05									
221051	AUTOPILOT PITCH SERVO								Component ATA:22
PN:PN 4006719-908	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02									
221055	AUTOPILOT PITCH SERVO BRACKET								Component ATA:22
PN:PN 4005842	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03									
221061	AUTOPILOT YAW SERVO								Component ATA:22
PN:PN 7012919-903	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-------	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 22 - AUTO FLIGHT

221065	AUTOPILOT YAW SERVO BRACKET							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07									

225001	YAW INTERFACE UNIT							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01									

225031	PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									

225032	COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component	ATA:22
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02									

A2210033 ^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST							Service	ATA:22
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00									
									PKG:7

ATA 23 - COMMUNICATIONS

230001	UNILINK PROCESSOR							Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
230002	CONFIGURATION MODULE								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231011	NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER								Component ATA:23
PN:064-1017-01	MOS/MSC	12-Feb-08	O/C						
SN:17280	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231012	NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT								Component ATA:23
PN:7510733-616	MOS/MSC	11-May-18	O/C						
SN:98093272	HRS	7850.8							
	AFL	6024							
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01									
231021A	TEST/INSPECT NO. 1 ATC TRANSPONDER								Service ATA:23
PN:7510733-616	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:98093272	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									
231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT								Component ATA:23
PN:7510733-616	MOS/MSC	13-Apr-17	O/C						
SN:99054063	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231022A	TEST/INSPECT NO. 2 ATC TRANSPONDER								Service ATA:23
PN:7510733-616	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:99054063	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413									
231030	NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231031	NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231032	HF SELECTIVE CALLING (SELCAL) ANTENNA								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231033	UPPER VHF ANTENNA								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									
231034	LOWER VHF ANTENNA								Component ATA:23
PN:DMC60-17-1	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:18936	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231045	NO. 1 HF CONTROL (MODEL KCU-951)								Component ATA:23
PN:064-1016-03	MOS/MSC	25-Feb-08	O/C						
SN:11903	HRS	5974.6							
	AFL	4566							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231046	NO. 2 HF CONTROL (MODEL KCU-951)								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231051	NO. 1 HF BRIDGING AMPLIFIER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231052	NO. 2 HF BRIDGING AMPLIFIER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231090	PILOT HEADSET								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231091	COPILOT HEADSET								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231300		MAGNASTAR PHONE TRANSCEIVER						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231301 ^U		ANTENNA						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
231305		MAGNASTAR ANTENNA						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231307		COCKPIT PHONE						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231308		CABIN PHONE						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231310		ARTU TRAY						Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231313	NO. 1 CABIN DISTRIBUTION BUS REPEATER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231314	NO. 2 CABIN DISTRIBUTION BUS REPEATER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231315	CALL ALERTER SWITCH (CAS)								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231320	NO. 1 CABIN IRIDIUM SATCOM HANDSET								Component ATA:23
PN:P12248-003	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231321	CABIN IRIDIUM SATCOM PHONE CRADLE								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231322	NO. 2 CABIN IRIDIUM SATCOM HANDSET								Component ATA:23
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
231323	IRIDIUM SATCOM TRANSCEIVER								Component ATA:23
PN:P12023	MOS/MSC	12-Feb-08	O/C						
SN:1202310876	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231325	IRIDIUM SATCOM SONALERT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231327	COCKPIT IRIDIUM SATCOM PHONE CRADLE								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231328	COCKPIT IRIDIUM SATCOM HANDSET								Component ATA:23
PN:P12192-002	MOS/MSC	12-Feb-08	O/C	TSN 0					
SN:UNKNOWN	HRS	5965.9		TSN 0					
	AFL	4561		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231330	FORWARD IRIDIUM SATCOM ANTENNA								Component ATA:23
PN:S67-1575-165	MOS/MSC	12-Feb-08	O/C						
SN:449-2303	HRS	5965.9							
	AFL	4561							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
231335	COCKPIT IRIDIUM SATCOM BASE UNIT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233001	FORWARD CABIN VIDEO MONITOR								Component ATA:23
PN:AL-LCD104-04-1	MOS/MSC	06-Aug-06	O/C						
SN:120000638	HRS	4725.85							
	AFL	3628							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233002	AFT CABIN VIDEO MONITOR								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233003	AUDIO DISTRIBUTION MODULE								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233005	PUBLIC ADDRESS SYSTEM AMPLIFER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02									
233010	INFRARED REMOTE RECEIVER MODULE								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233015	AUDIO/VIDEO CONTROLLER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233053	DVD PLAYER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233054	CD PLAYER CHANGER								Component ATA:23
PN:MCD-102-RU-3	MOS/MSC	21-Jun-05	O/C						
SN:060101192	HRS	3694.5							
	AFL	2785							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233055	CD PLAYER CONTROL UNIT								Component ATA:23
PN:MCD-102-CH-1	MOS/MSC	22-May-06	O/C						
SN:100000353	HRS	4507.7							
	AFL	3441							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233056	CASSETTE TAPE PLAYER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233101	LEFT FORWARD CABIN SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233102	RIGHT FORWARD CABIN SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
233103	LEFT AFT CABIN SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233104	RIGHT AFT CABIN SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01									
233105	SUBWOOFER SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
233201	PASSENGER INTERFACE UNIT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
234000	INTERPHONE JACK BOX ASSEMBLY								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
235001	NO. 1 AUDIO CONTROL UNIT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
235002	NO. 2 AUDIO CONTROL UNIT								Component ATA:23
PN:7511001-937	MOS/MSC	12-Sep-22	O/C						
SN:04049325	HRS	9101.8							
	AFL	6994							
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01									
235013	LEFT COCKPIT SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03									
235014	RIGHT COCKPIT SPEAKER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03									
236001 ^U	STATIC INVERTER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
236005	XM RADIO WEATHER RECEIVER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236010	XM RADIO WEATHER DATA PORT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
236015	XM RADIO ANTENNA								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
236096	NO. 1 NAVIGATION STRAP BOARD								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236097	NO. 2 NAVIGATION STRAP BOARD								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05									
236098	NO. 1 COMMUNICATION STRAP BOARD								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
236099	NO. 2 COMMUNICATION STRAP BOARD								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03									
237001	COCKPIT VOICE RECORDER (CVR)								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237005 COCKPIT VOICE RECORDER, UNDERWATER LOCATOR BEACON (CVR ULB)								Component	ATA:23
PN:DK120	MOS/MSC	02-Aug-24	O/C	TSN 0					
SN:NT60040	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01									
237005A FUNCTIONAL TEST / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN AA2560000)								Service	ATA:23
PN:DK120	MOS	02-Aug-24	24		02-Aug-26		375 d		
SN:NT60040	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237005B REPLACE BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001)								Service	ATA:23
PN:DK120	MOS/MSC	02-Aug-24	DUE		31-Mar-29 (M)		1347 d		
SN:NT60040	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237005C ^U RECERTIFY PER MANUFACTURER'S INSTRUCTIONS								Service	ATA:23
PN:DK120	MOS	02-Aug-24	216		02-Aug-42		6219 d		
SN:NT60040	HRS	9525.7							
	AFL	7276							
237018 COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05									
237019 COCKPIT AREA MICROPHONE								Component	ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
237030	PANEL SWITCH								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
237031	COCKPIT VOICE RECORDER PRE-AMPLIFIER								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03									
238001	NO. 1 RADIO MANAGEMENT UNIT (RMU)								Component ATA:23
PN:7013270-985	MOS/MSC	04-May-18	O/C						
SN:06125540	HRS	7849.4							
	AFL	6022							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238002	NO. 2 RADIO MANAGEMENT UNIT (RMU)								Component ATA:23
PN:7013270-985	MOS/MSC	16-Mar-18	O/C						
SN:1248264	HRS	7800.1							
	AFL	5976							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238025	CLEARANCE DELIVERY UNIT								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01									
239004	MASTER CONTROL SWITCH								Component ATA:23
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 23 - COMMUNICATIONS									
239011		LAVATORY MASTER CONTROL SWITCH						Component	ATA:23
PN:8500-000077-6767	MOS/MSC	03-Mar-06	O/C						
SN:0123	HRS	4328.77							
	AFL	3297							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A2300000 ^S		** COMMUNICATION SYSTEMS - PERFORM OPERATIONAL CHECK						Service	ATA:23
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00									
Y2360020 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									
Y2360023 ^S		AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service	ATA:23
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00									
ATA 24 - ELECTRICAL POWER									
24-30-50-005		EMERGENCY BATTERY						Component	ATA:24
PN:RG-443	MOS/MSC	02-Jun-25	H/T	TSN 21					
SN:41333681	HRS	9749		TSN 412.4					
	AFL	7427		TSN 293					
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
240109	AFT CIRCUIT BREAKER PANEL							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04									
242001	NO. 1 5KVA ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	14-Feb-24	O/C	TSO 0					
SN:651	HRS	9467.2		TSO 0					
	AFL	7246		TSO 0					
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242001A	REPLACE NO. 1 ** BEARING. (F2420000)							Service	ATA:24
PN:90278-2	MOS	14-Feb-24						AIRWORTHINESS	
SN:651	HRS	9467.2	1200		10667.2		889.1		
	AFL	7246							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242002	NO. 2 5KVA ALTERNATOR							Component	ATA:24
PN:90278-2	MOS/MSC	19-May-22	O/C	TSO 0					
SN:1488	HRS	8995.3		TSO 0					
	AFL	6902		TSO 0					
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01									
242002A	REPLACE NO. 2 ** BEARING. (F2420000)							Service	ATA:24
PN:90278-2	MOS	19-May-22						AIRWORTHINESS	
SN:1488	HRS	8995.3	1200		10195.3		417.2		
	AFL	6902							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242008	AC/DC VOLT INDICATOR							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
242050	NO. 1 REMOTE CONTROL CIRCUIT BREAKER								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242052	NO. 2 REMOTE CONTROL CIRCUIT BREAKER								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242054	NO. 3 REMOTE CONTROL CIRCUIT BREAKER								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									
242081	CABIN ELECTRICAL INVERTER								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242082	TAILCONE ELECTRICAL INVERTER								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
242083	ELECTRICAL INVERTER								Component ATA:24
PN:SS120(C)	MOS/MSC	23-Jul-13	A/R						
SN:320	HRS	7175.4							
	AFL	5474							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243001	NO. 1 STARTER/GENERATOR							Component	ATA:24
PN:23280-067	MOS/MSC	27-Aug-21	O/C	TSO 0					
SN:Y20436	HRS	8708.2		TSO 0					
	AFL	6691		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243001A	OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410)							Service	ATA:24
PN:23280-067	MOS	27-Aug-21						OVERHAUL	
SN:Y20436	HRS	8708.2	1200		9908.2		130.1		
	AFL	6691							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243001B	REPLACE NO. 1 STARTER/GENERATOR BEARING							Service	ATA:24
PN:23280-067	MOS/MSC	27-Aug-21	N/A						
SN:Y20436	HRS	8708.2							
	AFL	6691							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243002	NO. 2 STARTER/GENERATOR							Component	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	O/C	TSO 0					
SN:P1484LA	HRS	9525.7		TSO 0					
	AFL	7276		TSO 0					
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									
243002A	OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410)							Service	ATA:24
PN:23280-067	MOS	02-Aug-24						OVERHAUL	
SN:P1484LA	HRS	9525.7	1200		10725.7		947.6		
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243002B	REPLACE NO. 2 STARTER/GENERATOR BEARING							Service	ATA:24
PN:23280-067	MOS/MSC	02-Aug-24	N/A						
SN:P1484LA	HRS	9525.7							
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243003	APU STARTER/GENERATOR							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01									
243005	LEFT (GCU) GENERATOR CONTROL UNIT							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243006	RIGHT (GCU) GENERATOR CONTROL UNIT							Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
243019	NO. 1 MAIN SHIP BATTERY							Component	ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C						
SN:41180857	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									
243019A	CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)							Service	ATA:24
PN:RG-380E/40L	MOS	03-Feb-25	6	Adj -1d	02-Aug-25		10 d		
SN:41180857	HRS	9605.4	500		10105.4		327.3		
	AFL	7333							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									
243020	NO. 2 MAIN SHIP BATTERY							Component	ATA:24
PN:RG-380E/40L	MOS/MSC	02-Aug-24	O/C	TSN 34					
SN:41180858	HRS	9525.7		TSN 762.4					
	AFL	7276		TSN 532					
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
243020A		CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)						Service	ATA:24
PN:RG-380E/40L	MOS	03-Feb-25	6	Adj -1d	02-Aug-25		10 d		
SN:41180858	HRS	9605.4	500		10105.4		327.3		
	AFL	7333							
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71									
246001		LEFT FORWARD POWER DISTRIBUTION PANEL						Component	ATA:24
PN:650GC02Y03	MOS/MSC	21-Jun-18	O/C						
SN:575	HRS	7887.8							
	AFL	6051							
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246002		RIGHT FORWARD POWER DISTRIBUTION PANEL						Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02									
246003		LEFT AFT POWER DISTRIBUTION PANEL						Component	ATA:24
PN:660GC02Y07	MOS/MSC	30-Jan-11	O/C						
SN:588	HRS	6501.3							
	AFL	4977							
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246004		RIGHT AFT POWER DISTRIBUTION PANEL						Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03									
246101		LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD						Component	ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
246102	LEFT LOGIC PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD								Component ATA:24
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN Y2431005							Service	ATA:24
	MOS	02-Aug-24							
	HRS	9525.7	300		9825.7		47.6		
	AFL	7276							
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00									
AB2431062	EMERGENCY BATTERY - PERFORM CAPACITY CHECK								Service ATA:24
PN:RG-443	MOS	02-Jun-25	12		02-Jun-26 (M)		314 d		
SN:41333681	HRS	9749	1000		10749 (M)		970.9		
	AFL	7427							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
AB2431063		EMERGENCY BATTERY - REPLACE						Service	ATA:24
	MOS	09-Mar-01	48		02-Sep-28 (M)		1137 d	LIFE LIMIT	
	HRS	0			14336.6 (M)		4558.5		
	AFL	0							
AC2460002 ^S		REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.						Service	ATA:24
	MOS	09-Mar-01	96						
	HRS	0	2400						
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:19
H2450001 ^S		** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7
H2450023 ^S		** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7
O2431002		EMERGENCY BATTERY - PERFORM CAPACITY CHECK						Service	ATA:24
PN:RG-443	MOS/MSC	02-Jun-25	N/A						
SN:41333681	HRS	9749							
	AFL	7427							
PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 24 - ELECTRICAL POWER									
W2450000 ^S		** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK						Service	ATA:24
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00									PKG:7
Y2400002 ^S		ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7
Y2400025 ^S		ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:8
Y2430005 ^S		STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01									PKG:9
Y2430006 ^S		STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 24 - ELECTRICAL POWER

Y2431000	^S	BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:20

Y2431001	^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION						Service	ATA:24
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:7

ATA 25 - EQUIPMENT/FURNISHINGS

250010		RELAY MODULE						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

251003	^U	CHECK AIRCRAFT FLIGHT MANUAL STATUS						Service	ATA:25
	MOS/MSC	09-Mar-01	A/R					CUSTOMER CODE	
	HRS	0							
	AFL	0							

252000-1		NO. 1 PASSENGER SEAT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

252000-2		NO. 2 PASSENGER SEAT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

252000-3		NO. 3 PASSENGER SEAT				Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0		TSN 0			
	AFL	0		TSN 0			
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45							

252000-4		NO. 4 PASSENGER SEAT				Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0	TSN 0				
	AFL	0	TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45							

252000-5		NO. 5 PASSENGER SEAT				Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0	TSN 0				
	AFL	0	TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45							

252000-6					NO. 6 PASSENGER SEAT					Component	ATA:25
PN:PN		MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN		HRS	0		TSN 0						
		AFL	0		TSN 0						
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45											

252000-7		NO. 7 PASSENGER SEAT				Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0	TSN 0				
	AFL	0	TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45							

252000-8		NO. 8 PASSENGER SEAT				Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0	TSN 0				
	AFL	0	TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252000-9		JUMP SEAT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252001-1		NO. 1 PASSENGER SEAT PCU						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-2		NO. 2 PASSENGER SEAT PCU						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-3		NO. 3 PASSENGER SEAT PCU						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-4		NO. 4 PASSENGER SEAT PCU						Component	ATA:25
PN:SP-45-07A	MOS/MSC	05-Apr-06	O/C						
SN:020600592	HRS	4422.47							
	AFL	3369							
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-5		NO. 5 PASSENGER SEAT PCU						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252001-6	NO. 6 PASSENGER SEAT PCU								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-7	NO. 7 PASSENGER SEAT PCU								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-8	NO. 8 PASSENGER SEAT PCU								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45									
252001-9	LAVATORY PCU								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252005 ^U	AIRSHOW FLIGHT DECK CONTROLLER								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
252010	AIRSHOW COMPUTER								Component ATA:25
PN:920040	MOS/MSC	06-Mar-09	O/C						
SN:452	HRS	6115.4							
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252020	CLOSET SWITCH PANEL ASSEMBLY								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252090	NO. 1 110 VOLT POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252091	NO. 2 110 VOLT POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252092	NO. 3 110 VOLT POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252095	NO. 4 110 VOLT POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252097	NO. 1 AC POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
252098	NO. 2 AC POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
252099	NO. 3 AC POWER OUTLET								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253001	MICROWAVE OVEN								Component ATA:25
PN:255A-LH28-115	MOS/MSC	28-Jul-05	O/C						
SN:19976	HRS	3775.77							
	AFL	2849							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253075	NO. 1 HEATED WATER CONTAINER								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253076	NO. 2 HEATED WATER CONTAINER								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
253077	HEATED WATER SWITCH								Component ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
253080	GALLEY DRAIN VALVE SOLENOID							Component	ATA:25
PN:8210G94-24DC	MOS/MSC	03-Jan-06	O/C						
SN:T116684	HRS	4160.77							
	AFL	3151							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256001	PILOT CREW SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									
256002	COPILOT CREW SEAT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50									
256032	COPILOT PROTECTIVE BREATHING (PBE). (IRN A3510008) EQUIPMENT UNIT							Component	ATA:25
PN:119003	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
SN:131371	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256061	PILOT LIFE VEST							Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400026	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256061A	INSPECT PILOT LIFE VEST (IRN # E2561002)							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400026	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256062	COPILOT LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400085	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256062A	INSPECT COPILOT LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400085	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256063	NO. 1 LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400200	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256063A	INSPECT NO. 1 LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400200	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256064	NO. 2 LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400323	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256064A	INSPECT NO. 2 LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400323	HRS								
	AFL								
Inspection Date: : 09-Feb-21									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01

256065	NO. 3 LIFE VEST							Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400333	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

256065A	INSPECT NO. 3 LIFE VEST (IRN # E2561002)							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400333	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

256066	NO. 4 LIFE VEST							Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400338	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

256066A	INSPECT NO. 4 LIFE VEST (IRN # E2561002)							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400338	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

256067	NO. 5 LIFE VEST							Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400422	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256067A	INSPECT NO. 5 LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400422	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256068	NO. 6 LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400432	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256068A	INSPECT NO. 6 LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400432	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256069	NO. 7 LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400704	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256069A	INSPECT NO. 7 LIFE VEST (IRN # E2561002)								Service ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400704	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256070	NO. 8 LIFE VEST								Component ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400721	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256070A	INSPECT NO. 8 LIFE VEST (IRN # E2561002)							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400721	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256071	LAVATORY LIFE VEST							Component	ATA:25
PN:P01074-101	MOS/MSC	09-Feb-21	O/C	TSN 0					
SN:20100400737	HRS	8401.3		TSN 0					
	AFL	6458		TSN 0					
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05									
256071A	INSPECT LAVATORY LIFE VEST (IRN # E2561002)							Service	ATA:25
PN:P01074-101	MOS	09-Feb-21	60		09-Feb-26		201 d		
SN:20100400737	HRS								
	AFL								
Inspection Date: : 09-Feb-21									
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01									
256074 ^U	LIFE RAFT							Component	ATA:25
PN:1015FAUL-630-1-136	MOS/MSC	30-Nov-16	O/C	TSO 0					
SN:10UL-00997	HRS	7683.1		TSO 0					
	AFL	5878		TSO 0					
256074A ^U	INSPECT LIFE RAFT LIFE RAFT IAW MANUFACTURERS INSTRUCTIONS							Service	ATA:25
PN:1015FAUL-630-1-136	MOS	02-Aug-24	36		02-Aug-27		740 d		
SN:10UL-00997	HRS	9525.7							
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256075 ^U		LIFE RAFT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
256076		FIRST AID KIT						Component	ATA:25
PN:MSK70002	MOS/MSC	14-Jul-07	O/C						
SN:0602	HRS	5618.1							
	AFL	4293							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256077 ^U		MEDICAL KIT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
256080		INSPECT LIFE VESTS 05-19-00-E2561002						Service	ATA:25
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05									
256081 ^U		PYROTECHNIC SIGNALING FLARE GUN KIT						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0				CUSTOMER CODE	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
256109		(ELT) EMERGENCY LOCATOR TRANSMITTER						Component	ATA:25
PN:453-5000	MOS/MSC	03-Feb-25	O/C	TSN 122					
SN:210-05727	HRS	9605.4		TSN 2171.2					
	AFL	7333		TSN 1646					
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
256109A		FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER						Service	ATA:25
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		195 d		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109B		INSPECT ELT BATTERIES (IF INSTALLED)						Service	ATA:25
PN:453-5000	MOS	03-Feb-25	12		03-Feb-26		195 d		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207									
256109C		REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY						Service	ATA:25
PN:453-5000	MOS	03-Feb-25	72		03-Feb-31		2021 d		
SN:210-05727	HRS	9605.4							
	AFL	7333							
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207									
256110		EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2)						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256115		EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03									
256116		EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH						Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS									
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259072	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM NO REFPROC. REF: AMM NO REF									
259073	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
259074	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS							Component	ATA:25
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION							Service	ATA:25
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2510001 ^S	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION							Service	ATA:25
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

Y2520000	^S	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.						Service	ATA:25
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:1

Y2540000	^S	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.						Service	ATA:25
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									PKG:7

ATA 26 - FIRE PROTECTION

261010	^U	LEFT SENSING, ENGINE HOT SECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

261011	^U	RIGHT SENSING, ENGINE HOT SECTION ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

261012		NO. 1 ENGINE FIREWALL FIRE DETECT ELEMENT						Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261013	NO. 2 ENGINE FIREWALL FIRE DETECT ELEMENT								Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261014	NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT								Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261015	NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT								Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261016	NO. 1 ENGINE HOT SECTION FIRE DETECT ELEMENT								Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261017	NO. 2 ENGINE HOT SECTION FIRE DETECT ELEMENT								Component ATA:26
PN:744-12135	MOS/MSC	12-Aug-15	O/C						
SN:UNKNOWN	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02									
261057	NO. 1 FIRE DETECT CONTROL UNIT								Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
261058	NO. 2 FIRE DETECT CONTROL UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01									
261069	NO. 1 BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261070	NO. 2 BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:6626100000-003	MOS/MSC	18-Apr-12	O/C	TSN 0					
SN:2714	HRS	6879.9		TSN 0					
	AFL	5240		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261071	ANTI-ICE BLEED AIR LEAK DETECTION UNIT							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01									
261075	APU FIRE/OVERHEAT DETECTOR							Component	ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01									
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	22-Jun-23	O/C	TSO 0					
SN:59578B1	HRS	9258.5		TSO 0					
	AFL	7100		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262001A		NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)						Service	ATA:26
PN:33100021-1	MOS	31-May-23	60		31-May-28		1043 d	SCHEDULED MAINTENANCE TASKS AND INTERVALS	
SN:59578B1	HRS								
	AFL								
			HydroCheck Date: : 31-May-23						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262002		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE						Component	ATA:26
PN:33100021-1	MOS/MSC	25-Nov-20	O/C	TSO 0					
SN:72871B1	HRS	8301.3		TSO 0					
	AFL	6392		TSO 0					
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262002A		NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006)						Service	ATA:26
PN:33100021-1	MOS	31-Oct-20	60		31-Oct-25		100 d		
SN:72871B1	HRS								
	AFL								
			HydroCheck Date: : 31-Oct-20						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262013 ^U		LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB						Component	ATA:26
PN:M30903856	MOS	06-Dec-18	180		01-Jul-33		2900 d	LIFE LIMIT	
SN:02254	HRS	7976.3		TSN 0					
	AFL	6133		TSN 0					
			Manufacture Date:: 01-Jul-18						
262013A ^U		REPLACE LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).						Service	ATA:26
PN:M30903856	MOS	06-Dec-18	120		06-Dec-28		1232 d	LIFE LIMIT	
SN:02254	HRS	7976.3							
	AFL	6133							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262014 ^U		RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB						Component	ATA:26
PN:M30903859	MOS	06-Dec-18	180		01-Jul-33		2900 d	LIFE LIMIT	
SN:01619	HRS	7976.3		TSN 0					
	AFL	6133		TSN 0					
Manufacture Date:: 01-Jul-18									
262014A ^U		REPLACE RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).						Service	ATA:26
PN:M30903859	MOS	06-Dec-18	120		06-Dec-28		1232 d	LIFE LIMIT	
SN:01619	HRS	7976.3							
	AFL	6133							
262015 ^U		LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB						Component	ATA:26
PN:30903856	MOS	25-Nov-20	180		30-Nov-30		1956 d	LIFE LIMIT	
SN:1814TC	HRS	8301.3							
	AFL	6392							
Manufacture Date:: 30-Nov-15									
262015A ^U		REPLACE LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).						Service	ATA:26
PN:30903856	MOS	18-Jan-19	120		18-Jan-29		1275 d	LIFE LIMIT	
SN:1814TC	HRS								
	AFL								
Manufacture Date:: 18-Jan-19									
262016 ^U		RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB						Component	ATA:26
PN:30903859	MOS	25-Nov-20	180		30-Nov-30		1956 d	LIFE LIMIT	
SN:1119TE	HRS	8301.3							
	AFL	6392							
Manufacture Date:: 30-Nov-15									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
262016A ^U		REPLACE RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008).							Service ATA:26
PN:30903859	MOS	07-Nov-18	120		07-Nov-28		1203 d	LIFE LIMIT	
SN:1119TE	HRS								
	AFL								
Manufacture Date:: 07-Nov-18									
262040		APU FIRE WARNING HORN							Component ATA:26
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02									
262041		PILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344T	MOS/MSC	07-Dec-12	O/C						
SN:UNKNOWN	HRS	7016.8							
	AFL	5361							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262041D ^U		INSPECT PILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	DAYS	30-Jun-25	30		30-Jul-25		7 d	CUSTOMER CODE	
	HRS	9763.6							
	AFL	7441							
262042		COPILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344	MOS/MSC	18-May-16	O/C	TSN 0					
SN:B10813738	HRS	7623.3		TSN 0					
	AFL	5813		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262042D ^U		INSPECT COPILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	DAYS	30-Jun-25	30		30-Jul-25		7 d	CUSTOMER CODE	
	HRS	9763.6							
	AFL	7441							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 26 - FIRE PROTECTION										
262051		CABIN PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:C352		MOS/MSC	28-Dec-22	O/C	TSN 0					
SN:H-20651164		HRS	9186.7		TSN 0					
		AFL	7047		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
262051D ^U		INSPECT CABIN PORTABLE FIRE EXTINGUISHER							Service	ATA:26
		DAYS	30-Jun-25	30	30-Jul-25		7 d	CUSTOMER CODE		
		HRS	9763.6							
		AFL	7441							
5-19-00-O2610001-LEFT		VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE							Service	ATA:26
		MOS	21-May-18							
		HRS	7855.7	3000	Adj 1.5	10857.2	1079.1			
		AFL	6028							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
5-19-00-O2610001-RIGHT		VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE							Service	ATA:26
		MOS	12-Aug-15							
		HRS	7535.1	3000	Adj 78.9	10614	835.9			
		AFL	5764							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00										
Q2510003		COPILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service	ATA:26
PN:A344		MOS	01-Feb-16	144	01-Feb-28		923 d			
SN:B10813738		HRS								
		AFL								
			HydroCheck Date: : 01-Feb-16							
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00										
Y2610000 ^S		FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION							Service	ATA:26
		MOS	02-Aug-24	24						
		HRS	9525.7	600						
		AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 26 - FIRE PROTECTION									
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2620002 ^S		ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.						Service	ATA:26
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
									PKG:2
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y2620005 ^S		ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:26
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
									PKG:19
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									
Y2620009 ^S		COPILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344	MOS	02-Aug-24	12						
SN:B10813738	HRS	9525.7	300						
	AFL	7276							
									PKG:1
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Z2620021 ^S		NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
									PKG:2
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									
Z2620021 ^S		NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
									PKG:2
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 26 - FIRE PROTECTION

ATA 27 - FLIGHT CONTROLS

270301	TRIM SWITCH PANEL					Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0			
SN:UNKNOWN	HRS	0	TSN 0				
	AFL	0	TSN 0				
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01							

271001	LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE				Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05						

271002	RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE				Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05						

271003	LEFT AILERON CONTROL SYSTEM CABLE				Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05						

271004	RIGHT AILERON CONTROL SYSTEM CABLE				Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05						

271005	AFT AILERON CONTROL SYSTEM CABLE				Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0		
SN:UNKNOWN	HRS	0		TSN 0		
	AFL	0		TSN 0		
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271045	LEFT INBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271046	RIGHT INBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271051	LEFT FORWARD OUTBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271052	RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271053	LEFT AFT OUTBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									
271054	RIGHT AFT OUTBOARD AILERON CONTROL CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
271083	AILERON TRIM TAB ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09									
271093 ^U	PILOT ANGLE OF ATTACK (AOA) TRANSDUCER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
271094 ^U	COPILOT ANGLE OF ATTACK (AOA) TRANSDUCER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
271095	PILOT ANGLE OF ATTACK INDICATOR (AOA)								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
271096	COPILOT ANGLE OF ATTACK INDICATOR (AOA)								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
272001	FORWARD UPPER RUDDER CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272002	FORWARD LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272003	LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272004	RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272005	LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272006	RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08									
272021	RUDDER TRIM TAB ACTUATOR							Component	ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR								Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0437	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR								Component ATA:27
PN:6627208001-003 (4389596)	MOS/MSC	17-Feb-05	O/C						
SN:0431	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05									
273001	PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273002	COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273003	LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273004	RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05									
273015	LEFT ANGLE OF ATTACK VANE (AOA)								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273016	RIGHT ANGLE OF ATTACK VANE (AOA)								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04									
273022	LEFT ANGLE OF ATTACK TRANSMITTER (AOA)								Component ATA:27
PN:C-38817-1	MOS/MSC	11-Dec-23	O/C						
SN:1333	HRS	9373.9							
	AFL	7179							
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									
273023	RIGHT ANGLE OF ATTACK TRANSMITTER (AOA)								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
273051	ELEVATOR DISCONNECT ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09									
273063	PILOT STICK SHAKER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273064	COPILOT STICK SHAKER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03									
273087	STALL WARNING COMPUTER								Component ATA:27
PN:C-38806-2	MOS/MSC	14-Feb-24	O/C						
SN:132	HRS	9467.2							
	AFL	7246							
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02									
273201	ELEVATOR DISCONNECT CURRENT LIMITER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13									
273420	ELEVATOR OVERRIDE ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
274011	HORIZONTAL STABILIZER ACTUATOR								Component ATA:27
PN:6627401000-009	MOS/MSC	22-Jun-23	O/C	TSO 10					
SN:B0581	HRS	9258.5		TSO 175.9					
	AFL	7100		TSO 106					
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
274031	TRIM-IN-MOTION DETECTOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01									
274041	FORWARD INTERFACE UNIT								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04									
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03									
274052 ^U	ASSEMBLY, HORIZONTAL STAB ACTUATOR CONTROL BOX								Component ATA:27
PN:6627401000-003	MOS/MSC	28-Jan-07	O/C						
SN:D0305	HRS	5192.28							
	AFL	3977							
275020	LEFT FLAP, OUTBOARD ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275021	LEFT FLAP, INBOARD ACTUATOR								Component ATA:27
PN:6627503000-009	MOS/MSC	18-Jul-07	O/C						
SN:1743	HRS	5671.55							
	AFL	4333							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275022	RIGHT FLAP, INBOARD ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275023	RIGHT FLAP, OUTBOARD ACTUATOR								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
275057	FLAP DRIVE POWER UNIT								Component ATA:27
PN:6627503000-029	MOS/MSC	25-Feb-11	O/C						
SN:1461	HRS	6519.3							
	AFL	4991							
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08									
275058	FLAP CONTROL UNIT								Component ATA:27
PN:C144486-3-003	MOS/MSC	05-Jan-20	O/C						
SN:1343	HRS	8209.7							
	AFL	6328							
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05									
275069	FLAP POSITION INDICATOR								Component ATA:27
PN:C145159-1	MOS/MSC	09-Oct-23	O/C						
SN:135	HRS	9332.6							
	AFL	7149							
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
275080	FLAP CONTROL MODULE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02									
275081	LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									
275082	RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03									
276001	LEFT SPOILER ACTUATOR								Component ATA:27
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C						
SN:DWA392-00	HRS	4570.25							
	AFL	3497							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
276002	RIGHT SPOILER ACTUATOR								Component ATA:27
PN:6627602001-007	MOS/MSC	15-Jun-06	O/C						
SN:DAW398-00	HRS	4570.25							
	AFL	3497							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									
276005	SPOILER CONTROL MODULE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276010	SPOILERON CONTROLLER RESISTOR BOX								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10									
276013	SPOILER SHUTOFF VALVE								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07									
276020	SPOILER LOW PRESSURE SWITCH								Component ATA:27
PN:6629101004-003	MOS/MSC	11-Jun-16	O/C						
SN:535	HRS	7630.1							
	AFL	5823							
PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08									
276031	LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276032	RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									
276073	SPOILERON COMPUTER								Component ATA:27
PN:6627608500-007	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:00227	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
276076	CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER								Component ATA:27
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06									
5-19-00-K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION								Service ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION								Service ATA:27
	MOS	25-Nov-19	72		25-Nov-25		125 d	AIRWORTHINESS	
	HRS	8177.7							
	AFL	6303							
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE								Service ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE								Service ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE								Service ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
5-19-01-AA2760021-RIGHT		RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE						Service	ATA:27
	MOS	22-Jun-23							
	HRS	9258.5	1200		10458.5		680.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-R2710041		REPLACE * AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)						Service	ATA:27
	MOS	30-Mar-21	120		30-Mar-31		2076 d		
	HRS	8414.4							
	AFL	6463							
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07									
5-19-01-W2750055		* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT						Component	ATA:27
PN:159174-1	MOS/MSC	05-Dec-19	N/A	TSN 4372				NOT APPLICABLE	
SN:UNKNOWN	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06									
A2711001 ^S		** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04									
A2721001 ^S		** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
A2731002 ^S		** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00									PKG:8
A2760001 ^S		** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK						Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04									PKG:10
A2760002 ^S		** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK						Service	ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00									PKG:10
AA2700000 ^S		AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7
AA2700001 ^S		RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
AA2700002 ^S		ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:7
AD2760085 ^S		SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT						Service	ATA:27
	MOS	02-Aug-24	36						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05									PKG:10
D2740003		** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST						Service	ATA:27
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		347.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
D2740004		** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST						Service	ATA:27
PN:6627401000-009	MOS	02-Aug-24						AIRWORTHINESS	
SN:B0581	HRS	9525.7	600		10125.7		347.6		
	AFL	7276							
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02									
K2700007		* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700008		* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service	ATA:27
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	4800		14058.5		4280.4		
	AFL	7100							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									
N2740023	* HORIZONTAL STABILIZER ACTUATOR ACME SCREW - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A						
SN:B0581	HRS	9082.6							
	AFL	6994							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
N2740024	* HORIZONTAL STABILIZER ACTUATOR ACME NUT - REPLACE							Service	ATA:27
PN:6627401000-009	MOS/MSC	18-Aug-22	N/A						
SN:B0581	HRS	9082.6							
	AFL	6994							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
N2740025	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service	ATA:27
	MOS/MSC	18-Aug-22	N/A						
	HRS	9082.6							
	AFL	6994							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
P2740032	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service ATA:27
PN:6627401000-009	MOS	18-Aug-22							
SN:B0581	HRS	9082.6	1200		10282.6		504.5		
	AFL	6994							
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00									
P2740033	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION								Service ATA:27
PN:6627401000-009	MOS	18-Aug-22							
SN:B0581	HRS	9082.6	2400		11482.6		1704.5		
	AFL	6994							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION								Service ATA:27
	MOS/MSC	05-Dec-19	N/A					NOT APPLICABLE	
	HRS	8177.8							
	AFL	6304							
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02									
T2740002	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION								Service ATA:27
	MOS/MSC	18-Aug-22	N/A						
	HRS	9082.6							
	AFL	6994							
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK								Service ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09									
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR								Service ATA:27
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025
23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
W2750055		* LEFT INBOARD FLAP ACTUATOR JOINT - REPLACE						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750055		* LEFT OUTBOARD FLAP ACTUATOR JOINT - REPLACE						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750055		* RIGHT INBOARD FLAP ACTUATOR JOINT - REPLACE						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750055		* RIGHT OUTBOARD FLAP ACTUATOR JOINT - REPLACE						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750056		* LEFT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06									
W2750056		* LEFT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
W2750056		* RIGHT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
W2750056		* RIGHT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service	ATA:27
	MOS/MSC	05-Dec-19	N/A						
	HRS	8177.8							
	AFL	6304							
Y2700003 ^S		AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:10
Y2700004 ^S		RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:8
Y2700005 ^S		ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2700006 ^S		RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:9
Y2710000 ^S		AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10
Y2720000 ^S		RUDDER - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2721000 ^S		RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2
Y2730001 ^S		ELEVATORS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2730004 ^S		CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING						Service	ATA:27
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00									PKG:19
Y2730007 ^S		AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:27
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:20
Y2750000 ^S		FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10
Y2750001 ^S		FLAPS - PERFORM VISUAL INSPECTION						Service	ATA:27
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:4
Y2750053 ^S		FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 27 - FLIGHT CONTROLS									
Y2760000	^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						Service	ATA:27
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00 PROC. REF: AMM 05-10-00									

PKG:10

ATA 28 - FUEL									
281001		LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01 PROC. REF: AMM 28-12-01									

281002		RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01 PROC. REF: AMM 28-12-01									

281003		LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01 PROC. REF: AMM 28-12-01									

281004		RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01 PROC. REF: AMM 28-12-01									

281005		LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01 PROC. REF: AMM 28-12-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281006	RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281007	LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281008	RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281009	LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281010	RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01									
281031	FUEL, FUSELAGE CELL								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
281051	FUEL CROSSFLOW SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02									
281401	SURGE TANK FLOAT VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02									
281501	LEFT FLEX FUEL HOSE ASSY								Component ATA:28
PN:244224151	MOS/MSC	26-May-05	O/C						
SN:F16806-04	HRS	3623.3							
WC#: 28.015	AFL	2739							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281502	RIGHT FLEX FUEL HOSE ASSY								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
281521	LEFT FUEL TRANSFER CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									
281522	RIGHT FUEL TRANSFER CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282001	LEFT FUEL SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282003	RIGHT FUEL SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282011	SHUTOFF - REFUEL VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10									
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03									
282037	RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282038	LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06									
282041	CONTROL - REFUELING PANEL								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14									
282051	LEFT CHECK, MOTIVE FLOW VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									
282052	RIGHT CHECK, MOTIVE FLOW VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282063	PRE-CHECK, SPPR VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12									
282064	PILOT, SPPR VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11									
282075	LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282076	RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01									
282087	LEFT FUEL, STANDBY PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									
282088	RIGHT FUEL, STANDBY PUMP								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
282601	DEFUEL (B24) SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07									
282602	REFUEL CHECK VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09									
282603	SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
282815	APU FUEL SHUTOFF VALVE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04									
284001	ASSEMBLY, FUEL C1 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284002	FUEL C2 PROBE								Component ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C						
SN:0117	HRS	4507.7							
	AFL	3441							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284003	ASSEMBLY, FUEL C3 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284004	ASSEMBLY, FUEL C4 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284005	ASSEMBLY, FUEL C5 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284006	ASSEMBLY, FUEL C6 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284008	FUEL C8 PROBE								Component ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284009	ASSEMBLY, FUEL C9 PROBE								Component ATA:28
PN:10552T03Y00	MOS/MSC	22-May-06	O/C						
SN:7262	HRS	4507.7							
	AFL	3441							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284010		ASSEMBLY, FUEL C10 PROBE						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284011		ASSEMBLY, FUEL C11 PROBE						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284012		ASSEMBLY, FUEL C12 PROBE						Component	ATA:28
PN:6628408000-009	MOS/MSC	04-Jul-07	O/C						
SN:B408	HRS	5595.25							
	AFL	4268							
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284013		ASSEMBLY, FUEL C13 PROBE						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284014		ASSEMBLY, FUEL C14 PROBE						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284015		FUEL C15 PROBE						Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284016	ASSEMBLY, FUEL C16 PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284017	FUEL C17 PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284033	FUSELAGE FUEL PROBE							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05									
284035	NO. 1 FUEL, LOW PRESSURE (S21) SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01									
284036	NO. 2 FUEL, LOW PRESSURE (S21) SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01									
284041	LEFT FLOAT, FUEL (S19 & S20) SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
284042	RIGHT FLOAT, FUEL (S19 & S20) SWITCH							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02									
284045	FUEL QUANTITY SIGNAL CONDITIONER							Component	ATA:28
PN:6628408000-023	MOS/MSC	04-Jun-05	O/C						
SN:B0672	HRS	3648.97							
	AFL	2757							
PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04									
284047	LEFT FUEL, LOW LEVEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03									
284048	RIGHT FUEL, LOW LEVEL SENSOR							Component	ATA:28
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03									
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013)							Service	ATA:28
	MOS/MSC	30-Apr-06	A/R						
	HRS								
	AFL								
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									
H2840001	* DUAL FUEL FLOW CONVERTER (DFFC) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING							Service	ATA:28
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 28 - FUEL									
Y2810001	S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10
Y2810002	S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service	ATA:28
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:22
Y2820000	S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.						Service	ATA:28
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15									PKG:10
ATA 29 - HYDRAULIC POWER									
291001		HYDRAULIC RESERVOIR						Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02									
291012		L8 HYDRAULIC SHUTOFF VALVE						Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291013	L9 HYDRAULIC SHUTOFF VALVE								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05									
291033	RESERVOIR PRESSURIZATION CONTROL MODULE								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06									
291034	RESERVOIR FLUID LEVEL SENSOR								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02									
291045	NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291046	NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01									
291051	NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH								Component ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1452	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
291052	NO. 2 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR							Component	ATA:29
PN:88746-1	MOS/MSC	28-Jan-07	O/C						
SN:424	HRS	5192.28							
	AFL	3977							
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04									
291059	MAIN HYDRAULIC FILTER MANIFOLD							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
291069	THERMAL SHUTOFF VALVE							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07									
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY							Component	ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02									
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY							Component	ATA:29
PN:48-16-1	MOS/MSC	27-Feb-23	O/C	TSO 0					
SN:ELE0600A	HRS	9186.7		TSO 0					
	AFL	7047		TSO 0					
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
292012	AUXILIARY HYDRAULIC PUMP								Component ATA:29
PN:6629201000-015	MOS/MSC	11-Jun-16	O/C						
SN:K0153	HRS	7630.1							
	AFL	5823							
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01									
292013	AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR								Component ATA:29
PN:6629201000-011	MOS/MSC	11-Jun-16	O/C	TSR 0					
SN:ELE0/094	HRS	7630.1		TSR 0					
	AFL	5823		TSR 0					
PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04									
292025	AUXILIARY PRESSURE, HYDRAULIC SYSTEM (S29) SWITCH								Component ATA:29
PN:6629101004-001	MOS/MSC	11-Jun-16	O/C	TSN 0					
SN:1226	HRS	7630.1		TSN 0					
	AFL	5823		TSN 0					
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03									
292401	AUXILIARY HUDRAULIC PRESSURE CHECK VALVE								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
293001	GROUND SERVICE CONTROL BOX								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01									
293011	HYDRAULIC PRESSURE TRANSDUCER								Component ATA:29
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 29 - HYDRAULIC POWER									
5-19-01-D2910017		REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910017)						Service	ATA:29
	MOS/MSC	06-Jul-21	-						
	HRS	8631.2							
	AFL	6618							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
5-19-01-D2910018		REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910018)						Service	ATA:29
	MOS	18-Jan-24							
	HRS	9429.9	325	Adj 25	9779.9		1.8		
	AFL	7217							
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03									
5-19-01-O2910005		REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # O2910005)						Service	ATA:29
	MOS	19-May-22							
	HRS	8995.3	2400		11395.3		1617.2		
	AFL	6902							
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02									
Y2910003 ^S		HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service	ATA:29
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:19
ATA 30 - ICE AND RAIN PROTECTION									
301006		RELAY (P40) - ANTI-ICE VERTICAL STABILIZER. PANEL ASSY						Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06									
301010		LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR						Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301011	RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR							Component	ATA:30
PN:6621000000-059	MOS/MSC	03-Jun-06	O/C						
SN:UNKNOWN	HRS	4546.3							
	AFL	3481							
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05									
301051	LEFT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301052	RIGHT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02									
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01									
301065	LEFT SHUTTLE, ANTI-ICE VALVE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
301066	RIGHT SHUTTLE, ANTI-ICE VALVE								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08									
301240	ANTI-ICE MANIFOLD ASSEMBLY								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01									
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01									
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02									
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH								Component ATA:30
PN:7600020-1	MOS/MSC	27-Mar-23	O/C						
SN:5769TW	HRS	9209.1							
	AFL	7060							
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
303501	LEFT NOSE RELAY (P15) BOX								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01									
303510	RIGHT NOSE RELAY (P16) BOX								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01									
304021	WINDSHIELD ANTI-ICE CONTROLLER								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01									
304060	NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
304061	NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
304062	NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR								Component ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
304063	NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03									
308005	ICE DETECTION PROBE							Component	ATA:30
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01									
5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service	ATA:30
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									
A3030000 ^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:30
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00									
PKG:19									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
AC3010006		** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION						Service	ATA:30
	MOS	22-Jun-23							
	HRS	9258.5	600		9858.5		80.4		
	AFL	7100							
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
H3010000 ^S		** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00									
T3040000 ^S		** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM						Service	ATA:30
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00									
Y3010007 ^S		WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.						Service	ATA:30
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Z3020005		* LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.						Service	ATA:30
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	250		9775.7		OVD		
	AFL	7276							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 30 - ICE AND RAIN PROTECTION									
Z3020005	* RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service	ATA:30
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	250		9775.7		OVD		
	AFL	7276							
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00									

ATA 31 - INDICATING/RECORDING SYSTEMS

311001	PILOT CIRCUIT BREAKER PANEL ASSY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

311005	COPILOT CIRCUIT BREAKER PANEL ASSY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01									

311601	GEAR UP/DOWN S47 SWITCH							Component	ATA:31
PN:A3-1295	MOS/MSC	12-Aug-15	O/C						
SN:UNKNOWN	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02									

311805	ENGINE FUEL CONTROL (P7) PANEL ASSY							Component	ATA:31
PN:4576108500-023	MOS/MSC	20-Jan-05	O/C						
SN:MRP645048-01	HRS	3272.32							
	AFL	2494							
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05									

311806	ENGINE/FUEL CONTROL PANEL OVERLAY							Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
311906	FORWARD QUADRANT SWITCH PANEL (P6) OVERLAY								Component ATA:31
PN:7631208500-015	MOS/MSC	12-Aug-15	O/C	TSN 173					
SN:UNKNOWN	HRS	7535.1		TSN 7535.1					
	AFL	5764		TSN 5764					
PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04									
311906-1	RUDDER BOOST (DS48) SWITCH								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
312001	PILOT CLOCK								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312002	COPILOT CLOCK								Component ATA:31
PN:M850-5V-LA	MOS/MSC	14-Dec-10	O/C	TSN 0					
SN:A5231	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01									
312011	PILOTS DIGITAL CLOCK BATTERY								Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0, Adj 11d	14-Feb-26		206 d	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									
312012	COPILOTS DIGITAL CLOCK BATTERY								Component ATA:31
PN:E90	MOS	03-Feb-25	12	TSN 0, Adj 11d	14-Feb-26		206 d	LIFE LIMIT	
SN:NA	HRS	9605.4		TSN 0					
	AFL	7333		TSN 0					
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
313001	FLIGHT DATA RECORDER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313001A	DOWNLOAD FLIGHT DATA RECORDER								Service ATA:31
PN:PN	MOS/MSC	09-Mar-01	N/R					CUSTOMER CODE	
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313003	FDR ACCELEROMETER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313010	HOBBS METER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
313018	INERTIA, FDR SWITCH								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
314001	SELCAL DECODER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
314011	NO. 1 DATA ACQUISITION (DAU) UNIT								Component ATA:31
PN:7013348-931	MOS/MSC	12-Aug-15	O/C						
SN:00013220	HRS	7535.1							
	AFL	5764							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									
314012	NO. 2 DATA ACQUISITION (DAU) UNIT								Component ATA:31
PN:7013348-931	MOS/MSC	15-Nov-05	O/C						
SN:00063567	HRS	4035.07							
	AFL	3047							
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01									
314023	NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER								Component ATA:31
PN:7017000-82222	MOS/MSC	17-Dec-15	O/C						
SN:02065544	HRS	7546							
	AFL	5771							
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									
314024	NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER								Component ATA:31
PN:7017000-82222	MOS/MSC	23-Nov-21	O/C						
SN:98041571	HRS	8770.6							
	AFL	6752							
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01									
314051	NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE								Component ATA:31
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C						
SN:01080971	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									
314052	NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE								Component ATA:31
PN:7025973-04214	MOS/MSC	17-Feb-05	O/C						
SN:01080922	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
315001	CREW WARNING PANEL ASSEMBLY								Component ATA:31
PN:6631508501-001	MOS/MSC	17-Feb-05	O/C	TSN 0					
SN:357	HRS	3300.2		TSN 0					
	AFL	2515		TSN 0					
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01									
316001	NO. 1 DU870 COMPUTER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316001-1	PILOT (#1) MFD CONTROLLER BEZEL								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316002	NO. 2 DU870 COMPUTER								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316002-1	PILOT (#2) MFD CONTROLLER BEZEL								Component ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316003	NO. 3 DU870 COMPUTER								Component ATA:31
PN:7014300-901	MOS/MSC	06-Sep-22	O/C	TSO 0					
SN:0203A703	HRS	9097.5		TSO 0					
	AFL	6994		TSO 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
316003-1 COPILOT (#3) MFD CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316004 NO. 4 DU870 COMPUTER								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316004-1 COPILOT (#4) MFD CONTROLLER BEZEL								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01									
316005 PILOT EFIS DISPLAY CONTROLLER								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
316006 COPILOT EFIS DISPLAY CONTROLLER								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02									
316091 DATA TRANSFER, AFIS UNIT								Component	ATA:31
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS									
B3100000	S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:31
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00									
									PKG:7

ATA 32 - LANDING GEAR

32-10-01-104	LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component	ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:H5000	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

32-10-01-104	RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component	ATA:32
PN:200-0217-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:HER08U5014	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

32-10-01-900	LEFT MAIN LANDING GEAR AXLE BEAM							Component	ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0331	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

32-10-01-901	RIGHT MAIN LANDING GEAR AXLE BEAM							Component	ATA:32
PN:200-0203-001	MOS/MSC	08-Sep-12	H/T						
SN:H0334	HRS	6989.1							
	AFL	5335		TSN 5311					
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

32-32-20-015	LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN							Component	ATA:32
PN:200-0325-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:H2409	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
32-32-20-015 RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN								Component	ATA:32
PN:200-0325-101	MOS/MSC	24-Jun-19	H/T	TSN 0					
SN:HER08U/5030	HRS	8101.1		TSN 0					
	AFL	6233		TSN 0					
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320041 * REPLACE LEFT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) IRN N3220101								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320042 * REPLACE RIGHT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320051 * REPLACE LEFT MAIN LANDING GEAR PISTON PIN (P/N 200-0215). (IRN N3220102)								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320052 * REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
320061 * REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)								Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
320062	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)							Component	ATA:32
PN:4532101000V72-002	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:H1153	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320071	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)							Component	ATA:32
PN:4532101000V76-001	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:H0155	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320072	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)							Component	ATA:32
PN:4532101000V72-002	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:H1153	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320081	* REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)							Component	ATA:32
PN:200-0303-001	MOS	02-Aug-24		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276	2387	TSN 0	9663		2211		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320082	* REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)							Component	ATA:32
PN:200-0303-001	MOS	02-Aug-24		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276	2387	TSN 0	9663		2211		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320091	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)							Component	ATA:32
PN:200-0304-001	MOS	19-Dec-10		TSN 0				LIFE LIMIT	
SN:H1704	HRS	6457.2		TSN 0					
	AFL	4944	17000	TSN 0	21944		14492		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
320092	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)							Component	ATA:32
PN:4532101000V72-002	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:H1153	HRS	0		TSN 0					
	AFL	0	17000	TSN 0	17000		9548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
321001	LEFT * LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY							Component	ATA:32
PN:200-0200-013	MOS	30-Mar-21						LIFE LIMIT	
SN:H0584	HRS	8414.4		TSN 2110.4, TSO 0					
	AFL	6463	10000	TSN 1409, TSO 0	15054 (M)		7602		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321001A	PERFORM LEFT * LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)							Service	ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463	6600		13063		5611		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									
321002	RIGHT * RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY							Component	ATA:32
PN:200-0200-014	MOS	30-Mar-21						LIFE LIMIT	
SN:H1593	HRS	8414.4		TSN 2110.4					
	AFL	6463	10000	TSN 1409	15054		7602		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321002A	PERFORM RIGHT * RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)							Service	ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463	6600		13063		5611		
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321011	LEFT * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)							Component	ATA:32
PN:200-0201-009	MOS	30-Mar-21						LIFE LIMIT	
SN:H0727	HRS	8414.4		TSN 2110.4					
	AFL	6463	10000	TSN 1409	15054		7602		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321011A	ULTRASONIC-INSPECTION LEFT * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)							Service	ATA:32
PN:200-0201-009	MOS	27-Nov-22						AIRWORTHINESS	
SN:H0727	HRS	9163.6							
	AFL	7031	600		7631		179		
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
321012	RIGHT * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)							Component	ATA:32
PN:200-0201-010	MOS	30-Mar-21						LIFE LIMIT	
SN:H0755	HRS	8414.4		TSN 2110.4					
	AFL	6463	10000	TSN 1409	15054		7602		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321012A	ULTRASONIC-INSPECTION RIGHT * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)							Service	ATA:32
PN:200-0201-010	MOS	27-Nov-22						AIRWORTHINESS	
SN:H0755	HRS	9163.6							
	AFL	7031	600		7631		179		
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00									
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321085	LEFT FORWARD TRUNNION ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321086	RIGHT FORWARD TRUNNION ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321087	LEFT AFT TRUNNION ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321088	RIGHT AFT TRUNNION ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321101	* REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY								Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0501	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6450		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321101A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022)								Service ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
321102	* REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY								Component ATA:32
PN:200-0212-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0473	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6450		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321102A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022)								Service ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
321103	* REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY								Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0364	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6450		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321103A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022)								Service ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
321104	* REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY								Component ATA:32
PN:200-0213-103	MOS	24-Jul-12						LIFE LIMIT	
SN:H0338	HRS	6961.3		TSN 2110.4					
	AFL	5311	10000	TSN 1409	13902		6450		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321104A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022)								Service ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463							
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08									
321111	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN								Component ATA:32
PN:4532103201-001	MOS	15-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1882	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321111A	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								Service ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321112	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN								Component ATA:32
PN:4532103201-001	MOS	15-Dec-10		TSN 0				LIFE LIMIT	
SN:CM11113	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321112A		RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321113		LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN						Component	ATA:32
PN:4532103201-001	MOS	15-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1806	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321113A		LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321114		RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN						Component	ATA:32
PN:4532103201-001	MOS	15-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1710	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321114A		RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321117		LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN						Component	ATA:32
PN:4532103202-001	MOS	18-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1371	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321117A		LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118		RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN						Component	ATA:32
PN:4532103202-001	MOS	18-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1363	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321118A		RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119		LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN						Component	ATA:32
PN:4532103203-001	MOS	18-Dec-10		TSN 0				LIFE LIMIT	
SN:CM1818	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321119A		LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION						Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321120	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN							Component	ATA:32
PN:4532103203-001	MOS	18-Dec-10		TSN 0				LIFE LIMIT	
SN:CMI759	HRS	6457.2		TSN 0					
	AFL	4944	5000	TSN 0	9944		2492		
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321120A	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service	ATA:32
	MOS/MSC		N/A					NOT APPLICABLE	
	HRS								
	AFL								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
321215	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321216	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY							Component	ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
321227	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321228	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								Component ATA:32
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	10000	TSN 0	10000		2548		
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321302	LEFT MAIN LANDING GEAR INBOARD DOOR								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321303	RIGHT MAIN LANDING GEAR INBOARD DOOR								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									
321304	RIGHT MAIN LANDING GEAR OUTBOARD DOOR								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322001	^S	* REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (O3220009) (JAA E3220069)						Component	ATA:32
PN:4532230001-814	MOS	12-Feb-08		TSR 0				LIFE LIMIT	
SN:008	HRS	5965.9		TSR 0					
	AFL	4561	20000	TSN 4561, TSR 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322002		NOSE LANDING GEAR CYLINDER						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322003		NOSE LANDING GEAR PISTON						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322004		NOSE LANDING GEAR ACTUATOR BRACKET						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322005		NOSE LANDING GEAR FORK						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
322011	^S	* REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (O3220010) (JAA IRN E3220073) ASSEMBLY						Component	ATA:32
PN:6632201000-001	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:EFS210	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322041 ^U		NOSE LANDING GEAR (P/N 2342110) IRN 03220029 AXLE						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
322061 ^S		* REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN 03220029 JAA IRN E3220072) ASSEMBLY						Component	ATA:32
PN:2342110-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:R153	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322071 ^S		* REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN 03220028 JAA IRN E3220071) ASSEMBLY						Component	ATA:32
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L016	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322072 ^S		* REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN 03220028 JAA IRN E3220071) ASSEMBLY						Component	ATA:32
PN:2342108-003	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:L012	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01									
322095		LEFT NOSE LANDING GEAR DOOR						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									
322096		RIGHT NOSE LANDING GEAR DOOR						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
322111	NOSE LANDING GEAR CHASSIS ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
322121	NOSE LANDING GEAR UPLOCK MECHANISM							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02									
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE							Component	ATA:32
PN:200-0300-003	MOS	02-Aug-24						LIFE LIMIT	
SN:H0134	HRS	9525.7							
	AFL	7276	17000	TSN 7276	17000		9548		
Special Properties: RII ITEM									
323001A	INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)							Service	ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463	10000		16463		9011		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE							Component	ATA:32
PN:200-0300-004	MOS	02-Aug-24						LIFE LIMIT	
SN:H1188	HRS	9525.7							
	AFL	7276	17000	TSN 7276	17000		9548		
Special Properties: RII ITEM									
323002A	INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)							Service	ATA:32
	MOS	30-Mar-21	96	Adj -44d	14-Feb-29		1302 d		
	HRS	8414.4							
	AFL	6463	10000		16463		9011		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF										
323037		MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04										
323038		MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM							Component	ATA:32
PN:6632303004-006	MOS/MSC	08-Sep-12	O/C	TSR 31						
SN:0117	HRS	6989.1	TSR 0							
	AFL	5335	TSR 0							
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04										
323110		NOSE LANDING GEAR DOWN-LOCK (S139) SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05										
323220		DOWN AND LOCKED (S96) SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02										
323221		DOWN AND LOCKED (S100) SWITCH							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02										
323301		* REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY							Component	ATA:32
PN:6632303003-003	MOS/MSC	13-Apr-07	O/C							
SN:0779	HRS	5383.5								
	AFL	4119								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 32 - LANDING GEAR										
323302		* REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY							Component	ATA:32
PN:7469-1	MOS/MSC	25-Jul-12	O/C	TSN 136, TSR 0						
SN:0004	HRS	6961.3	TSN 6961.3, TSR 0							
	AFL	5311	TSN 5311, TSR 0							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02										
323305		LEFT MLG ACTUATOR GIMBAL ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06										
323306		RIGHT MLG ACTUATOR GIMBAL ASSEMBLY							Component	ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C							
SN:UNKNOWN	HRS	6330.6								
	AFL	4850								
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06										
323307		LEFT MLG SHAFT GIMBAL ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06										
323308		RIGHT MLG SHAFT GIMBAL ASSEMBLY							Component	ATA:32
PN:PN-UNKNOWN	MOS/MSC	25-Jul-10	O/C							
SN:UNKNOWN	HRS	6330.6								
	AFL	4850								
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06										
323309		LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0						
SN:UNKNOWN	HRS	0	TSN 0							
	AFL	0	TSN 0							
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
323310	RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06									
323735	CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01									
324001	NO. 1 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	O/C						
SN:1194	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	A/R						
SN:1194	HRS	9637.3							
	AFL	7352							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324002	NO. 2 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	O/C						
SN:0809	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	A/R						
SN:0809	HRS	9637.3							
	AFL	7352							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324003	NO. 3 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	O/C						
SN:3275	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324003A	NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	A/R						
SN:3275	HRS	9637.3							
	AFL	7352							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324004	NO. 4 MAIN LANDING GEAR WHEEL							Component	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	O/C						
SN:0831	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL							Service	ATA:32
PN:3-1545-1	MOS/MSC	21-Feb-25	A/R						
SN:0831	HRS	9637.3							
	AFL	7352							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324005	NOSE GEAR WHEEL ASSEMBLY							Component	ATA:32
PN:9544207-4	MOS/MSC	21-Feb-25	O/C						
SN:OCT07-2939	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
324021	NO. 1 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Feb-25	O/C	TSN 0					
SN:41910755	HRS	9637.3		TSN 0					
	AFL	7352		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324022	NO. 2 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Feb-25	O/C	TSN 0					
SN:41920768	HRS	9637.3		TSN 0					
	AFL	7352		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324023	NO. 3 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Feb-25	O/C	TSN 0					
SN:41670649	HRS	9637.3		TSN 0					
	AFL	7352		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324024	NO. 4 MAIN LANDING GEAR TIRE							Component	ATA:32
PN:226K08-4	MOS/MSC	21-Feb-25	O/C	TSN 0					
SN:42950939	HRS	9637.3		TSN 0					
	AFL	7352		TSN 0					
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02									
324025	NOSE LANDING GEAR TIRE							Component	ATA:32
PN:031-613-8	MOS/MSC	21-Feb-25	O/C	TSN 0					
SN:3005T00435	HRS	9637.3		TSN 0					
	AFL	7352		TSN 0					
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01									
324061	LEFT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									
324062	RIGHT ANTI-SKID CONTROL VALVE							Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324066	LEFT ANTI-SKID SHUTOFF VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324067	RIGHT ANTI-SKID SHUTOFF VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
324097	BRAKE CONTROL UNIT								Component ATA:32
PN:42-933-3	MOS/MSC	03-Jan-06	O/C						
SN:150	HRS	4160.77							
	AFL	3151							
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02									
324108	EMERGENCY PARKING BRAKE CHECK VALVE								Component ATA:32
PN:1C4124	MOS/MSC	19-Mar-05	O/C						
SN:UNKNOWN	HRS	3391.45							
	AFL	2574							
PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09									
324109	EMERGENCY/PARK BRAKE VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									
324110	PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324111	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324112	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE								Component ATA:32
PN:6632401000-002	MOS/MSC	27-Aug-21	O/C						
SN:2262	HRS	8708.2							
	AFL	6691							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324113	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE								Component ATA:32
PN:6632401000-002	MOS/MSC	25-Nov-19	O/C	TSO 0					
SN:1975	HRS	8177.7		TSO 0					
	AFL	6303		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324114	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE								Component ATA:32
PN:2-1579-2	MOS/MSC	15-Jul-11	O/C	TSO 0					
SN:0917SB	HRS	6651.4		TSO 0					
	AFL	5089		TSO 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324201	NO. 1 BRAKE SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324202	NO. 2 BRAKE SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324203	NO. 3 BRAKE SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324204	NO. 4 BRAKE SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									
324205	BRAKE SHUTTLE MODULE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04									
324305	LEFT PILOT BRAKE TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03									
324306	RIGHT PILOT BRAKE TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03									
324610-1	LEFT INBOARD BRAKE SWIVEL								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324610-2 LEFT OUTBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324611-1 RIGHT INBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324611-2 RIGHT OUTBOARD BRAKE SWIVEL								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									
324701 NO. 1 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324702 NO. 2 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324703 NO. 3 HYDRAULIC, BRAKE FUSE								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324704	NO. 4 HYDRAULIC, BRAKE FUSE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09									
324711	NO. 1 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component ATA:32
PN:140-183	MOS/MSC	17-Nov-20	O/C						
SN:3456	HRS	8301.3							
	AFL	6392							
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324712	NO. 2 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324713	NO. 3 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324714	NO. 4 WHEEL SPEED - ANTI-SKID TRANSDUCER								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10									
324721	(MT56) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
324722	(MT57) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324723	(MT58) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324724	(MT59) PRESSURE BRAKE TRANSDUCER ASSEMBLY								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08									
324801	EMERGENCY/PARK BRAKE FUSE								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07									
324805	EMER/PARK BRAKE ACCUMULATOR								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									
325007	FILTER, NOSE WHEEL STEERING (P41) BOX								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325011 NOSE WHEEL STEERING SERVO ACTUATOR								Component	ATA:32
PN:JR5208C	MOS/MSC	13-Feb-08	O/C	TSR 4					
SN:A0437	HRS	5967.8		TSR 0					
	AFL	4562		TSR 0					
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02									
325021 NOSE WHEEL STEERING GEARBOX								Component	ATA:32
PN:2W3201D	MOS/MSC	29-Oct-06	O/C						
SN:C0347	HRS	4933.32							
	AFL	3789							
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03									
325031 NOSE WHEEL STEERING COMPUTER								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01									
325035 NOSE WHEEL STEERING POWER SUPPLY								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
325041 LEFT NOSE WHEEL STEERING TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									
325042 RIGHT NOSE WHEEL STEERING TRANSDUCER								Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
325051	^S	* NOSE LANDING GEAR ACTUATOR UPPER PIN (IRN 03220011 OR JAA IRN E3220070)						Component	ATA:32
PN:4532302043-007	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:132	HRS	0		TSN 0					
	AFL	0	20000	TSN 0					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
326000		NOSE LANDING GEAR WIRE HARNESS						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
326104		NOSE LANDING GEAR SQUAT/WOW (S178) SWITCH						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09									
326105		NO. 1 MAIN GEAR SQUAT SWITCH						Component	ATA:32
PN:444EN2-R	MOS/MSC	18-Oct-22	O/C	TSN 0					
SN:UNKNOWN	HRS	9133.2		TSN 0					
	AFL	7007		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326106		NO. 2 MAIN GEAR SQUAT SWITCH						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326107		NO. 3 MAIN GEAR SQUAT SWITCH						Component	ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
326108	NO. 4 MAIN GEAR SQUAT SWITCH								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09									
326115	SQUAT SWITCH P21 RELAY BOX								Component ATA:32
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08									
5-19-00-D3260006	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THROUGH 45-114 NOT MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D326006)								Service ATA:32
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									
5-19-00-P3231020	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION								Service ATA:32
	MOS	02-Aug-24							
	HRS	9525.7							
	AFL	7276	300		7576		124		
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00									
5-19-00-P3231021	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION								Service ATA:32
	MOS	02-Aug-24							
	HRS	9525.7							
	AFL	7276	300		7576		124		
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02									
5-19-00-W3231022	MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION								Service ATA:32
	MOS	02-Aug-24							
	HRS	9525.7							
	AFL	7276	300		7576		124		
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-01-D3220046	U	REPLACE REPLACE MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY (P/N 200-300-001 & -002). (*IRN D3220046)						Service	ATA:32
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
5-19-01-F3220045		REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINC COATED)						Service	ATA:32
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01									
5-19-01-L3231024	U	REPLACE INBOARD LEFT AND RIGHT MAIN LANDING GEAR DOOR ACTUATOR (P/N 7469-1) CAP SCREWS. EFFECTIVE ON AIRCRAFT 45-005 THRU 45-276 MODIFIED PER SB 45-32-19, "MAIN LANDING GEAR DOOR ACTUATOR IMPROVEMENT/SADDLE INSTALLATION" AND 45-277 AND SUBSEQUENT. (ZONE/ACCESS 720/730 *IRN L3231024)						Service	ATA:32
	MOS	19-May-22						AIRWORTHINESS	
	HRS	8995.3	2400		11395.3		1617.2		
	AFL	6902							
5-19-01-N3220041	U	REPLACE MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103015 AND 4532103132). (ZONE/ACCESS 720/730 *IRN N3220041)						Service	ATA:32
	MOS/MSC	15-Dec-10	N/A						
	HRS	6457.2							
	AFL	4944							
5-19-01-N3220042	U	REPLACE MAIN LANDING GEAR AFT TRUNNION SHEAR PIN (P/N 4532103025 AND 4532103133). (ZONE/ACCESS 720/730 *IRN #N3220042)						Service	ATA:32
	MOS/MSC	18-Dec-10	N/A						
	HRS	6457.2							
	AFL	4944							
5-19-01-N3220043	U	REPLACE MAIN LANDING GEAR AFT LOWER TRUNNION SHEAR PIN (P/N 4532103026 AND 4532103134). (ZONE/ACCESS 720/730 *IRN N3220043)						Service	ATA:32
	MOS/MSC	18-Dec-10	N/A						
	HRS	6457.2							
	AFL	4944							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-01-N3220139	U	REPLACE MAIN LANDING GEAR FORWARD TRUNNION SHEAR PIN (P/N 4532103201) (ZONE/ACCESS 720/730) (IRN #N3220139)						Service	ATA:32
	MOS	15-Dec-10						LIFE LIMIT	
	HRS	6457.2							
	AFL	4944	5000		9944		2492		
5-19-01-N3220140	U	REPLACE MAIN LANDING GEAR AFT TRUNNION UPPER SHEAR PIN (P/N 4532203202) (ZONE/ACCESS 720/730) (IRN # N3220140)						Service	ATA:32
	MOS	18-Dec-10						LIFE LIMIT	
	HRS	6457.2							
	AFL	4944	5000		9944		2492		
5-19-01-N3220141	U	REPLACE MAIN LANDING GEAR AFT TRUNNION LOWER SHEAR PIN (P/N 4532103203) (ZONE/ACCESS 720/730) (IRN # N3220141)						Service	ATA:32
	MOS	18-Dec-10						LIFE LIMIT	
	HRS	6457.2							
	AFL	4944	5000		9944		2492		
5-19-01-O3220009	U	REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (P/N 2342100) (ZONE/ACCESS 710 *IRN # O3220009)						Service	ATA:32
	MOS	12-Feb-08						LIFE LIMIT	
	HRS	5965.9							
	AFL	4561	20000		24561		17109		
5-19-01-O3220010	U	REPLACE NOSE LANDING GEAR ACTUATOR ASSEMBLY (P/N 6632201000) (ZONE/ACCESS 710 *IRN # O3220010)						Service	ATA:32
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0							
	AFL	0	20000		20000		12548		
5-19-01-O3220011	U	REPLACE NOSE LANDING GEAR ACTUATOR UPPER PIN (P/N 4532302043) (ZONE/ACCESS 710 *IRN # O3220011)						Service	ATA:32
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0							
	AFL	0	20000		20000		12548		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
5-19-01-O3220028	U	REPLACE NOSE LANDING GEAR TRUNNION PINS (P/N 2342108) (ZONE/ACCESS 710 *IRN # O3220028)						Service	ATA:32
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0							
	AFL	0	20000		20000		12548		
5-19-01-O3220029	U	REPLACEMENT NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110). (ZONE/ACCESS 710 *IRN O3220029)						Service	ATA:32
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0							
	AFL	0	20000		20000		12548		
A3230001	S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST						Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00									PKG:11
A3240007	S	** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST						Service	ATA:32
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04									PKG:23
J3220120		* MAIN LANDING GEAR TRUNNION SHEAR PIN BUSHING - PERFORM DETAILED VISUAL INSPECTION FOR BUSHING MIGRATION						Service	ATA:32
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05									
L3220020		* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION						Service	ATA:32
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0							
	AFL	0	T:10000		10000		2548		
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
N3220036		* LEFT MAIN LANDING GEAR AXLE BEAM - REPLACE							Service ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT	
SN:H0331	HRS	6989.1							
	AFL	5335	10000	TAC 5311	10024		2572		
N3220036		* RIGHT MAIN LANDING GEAR AXLE BEAM - REPLACE							Service ATA:32
PN:200-0203-001	MOS	08-Sep-12						LIFE LIMIT	
SN:H0334	HRS	6989.1							
	AFL	5335	10000	TAC 5311	10024		2572		
T3220007		* LEFT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION							Service ATA:32
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		1106 d	AIRWORTHINESS	
SN:H0331	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220007		* RIGHT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION							Service ATA:32
PN:200-0203-001	MOS	02-Aug-24	48		02-Aug-28		1106 d	AIRWORTHINESS	
SN:H0334	HRS	9525.7							
	AFL	7276							
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01									
T3220014		* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE							Service ATA:32
	MOS	24-Jun-19	96	TAC 0	24-Jun-27		701 d	LIFE LIMIT	
	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
T3220014		* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE							Service ATA:32
	MOS	24-Jun-19	96	TAC 0	24-Jun-27		701 d	LIFE LIMIT	
	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01									
T3220038	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE							Service	ATA:32
	MOS	24-Jun-19	96	TAC 0	24-Jun-27		701 d	LIFE LIMIT	
	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					
T3220038	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE							Service	ATA:32
	MOS	24-Jun-19	96	TAC 0	24-Jun-27		701 d	LIFE LIMIT	
	HRS	8101.1		TAC 0					
	AFL	6233		TAC 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 32 - LANDING GEAR

T3220135	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:H5000	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

T3220135	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:H2409	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
PN:200-0217-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:HER08U5014	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION							Service	ATA:32
PN:200-0325-101	MOS	22-Jun-23	48		22-Jun-27		699 d	AIRWORTHINESS	
SN:HER08U/5030	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

V3240004 ^S	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.							Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01									

V3240008 ^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:32
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
									PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02									
Y3220000	S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3220001	S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3220002	S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3220003	S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
Y3220004	S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:11
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3220006	^S	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3220124	^S	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11
Y3230002	^S	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.						Service	ATA:32
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:5
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						Service	ATA:32
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04									PKG:5
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service	ATA:32
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 32 - LANDING GEAR									
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE.						Service	ATA:32
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01									PKG:5

Y3260005	^S	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service	ATA:32
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									PKG:5

ATA 33 - LIGHTS									
330000		MODIFIED PULSE CONTROLLER						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

331001		NO. 1 LIGHTING CONTROL UNIT						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									

331002		NO. 2 LIGHTING CONTROL UNIT						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06									

331010		PILOT FORWARD SWITCH PANEL OVERLAY						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331011PILOT SWITCH PANEL ASSY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331012COPILOT FORWARD SWITCH PANEL OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331013COPILOT FORWARD SWITCH PANEL ASSY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331015CENTER SWITCH (P5) PANEL ASSEMBLY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331016CENTER SWITCH PANEL (P5) OVERLAY									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331017THROTTLE QUADRANT OVERLAY PANEL									Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331018	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331019	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05									
331020	DIMMER CONTROL BOX								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10									
331023	GLARESHIELD FLOOR FLOODLIGHTS INVERTER								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331025	COCKPIT MISC RELAY BOX								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07									
331030	CENTER SWITCH PANEL DIODE (P12) BOX								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331033 GLARESHIELD FLOODLIGHT POWER SUPPLY								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331040 PILOT REVERSION PANEL (DS55) OVERLAY								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
331101 P35 FUSE PANEL ASSY								Component	ATA:33
PN:4533108552-007	MOS/MSC	17-Feb-05	O/C						
SN:MRP644283-001	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09									
331401-1 NO. 1 LEFT INVERTER (PS5009) SUPPLY PWR								Component	ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C						
SN:46634	HRS	3496.3							
	AFL	2649							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-10 INVERTER SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-11 INVERTER SUPPLY PWR								Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331401-2		NO. 1 RIGHT INVERTER (PS5003) SUPPLY PWR						Component	ATA:33
PN:AL-2000	MOS/MSC	11-Apr-05	O/C						
SN:46632	HRS	3496.3							
	AFL	2649							
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-3		NO. 2 LEFT INVERTER (PS5008) SUPPLY PWR						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-4		NO. 2 RIGHT INVERTER (PS5004) SUPPLY PWR						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-5		NO. 3 LEFT INVERTER (PS5007) SUPPLY PWR						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-6		NO. 3 RIGHT INVERTER (PS5005) SUPPLY PWR						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-7		NO. 4 LEFT INVERTER (PS5006) SUPPLY PWR						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
331401-8	NO. 4 RIGHT INVERTER (PS5010) LAV SUPPLY PWR							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
331401-9	NO. 5 LEFT INVERTER (PS5011) LAV SUPPLY PWR							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10									
332001	RH FWD LIGHTING CONTROL (A5038) UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332002	RH MID FWD LIGHTING CONTROL (A5039) UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332003	RH MID AFT LIGHTING CONTROL (A5040) UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332004	RH AFT LIGHTING CONTROL (A5041) UNIT							Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332005	L/H FWD LIGHTING CONTROL (A5045) UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332006	LH MID FWD LIGHTING CONTROL (A5044) UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332007	LH MID AFT LIGHTING CONTROL (A5043) UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332008	LH AFT LIGHTING CONTROL (A5042) UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05									
332030	LAVATORY NO SMOKING / RETURN TO SEAT SIGN (DS138) CONTROL UNIT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11									
332068	COPILOT LIGHTING CONTROL MODULE								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
332404	ENTRYWAY CONTROL LIGHT PANEL								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01									
334011	LANDING/TAXI, LEFT LIGHT								Component ATA:33
PN:GE4587	MOS/MSC	17-Feb-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8864.4		TSN 0					
	AFL	6822		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									
334012	LANDING/TAXI, RIGHT LIGHT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04									
334021	LEFT NAVIGATION (DS37) LIGHT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334022	RIGHT NAVIGATION (DS38) LIGHT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									
334023	TAIL NAVIGATION (DS39) LIGHT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
334041	COPILOT REVERSION PANEL (DS56) OVERLAY								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334175	RELAY OPTIONS PANEL ASSY								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
334332	UPPER ANTI-COLLISION LIGHT								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									
334333	LOWER ANTI-COLLISION LIGHT								Component ATA:33
PN:GE-16386-12-1	MOS/MSC	22-Dec-08	O/C						
SN:AA2591	HRS	6088.7							
	AFL	4660							
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01									
335005	FWD ELS ACTIVATION ASSEMBLY (A81) MODULE								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01									
335006	AFT ELS ACTIVATION ASSEMBLY (A82) MODULE								Component ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
335505 U		PILOT FLASHLIGHT						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
335506 U		COPILOT FLASHLIGHT						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
336001		PILOT CHART HOLDER						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
336002		COPILOT CHART HOLDER						Component	ATA:33
PN:10-62-01	MOS/MSC	17-Feb-05	O/C						
SN:3357	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
336003		PILOT MAP LIGHT						Component	ATA:33
PN:0204327-001	MOS/MSC	12-Dec-11	O/C	TSN 0					
SN:542319	HRS	6763.5		TSN 0					
	AFL	5158		TSN 0					
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01									
336004		COPILOT MAP LIGHT						Component	ATA:33
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 33 - LIGHTS									
Y3310000 ^S		FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATIONAL CHECK OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.						Service	ATA:33
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00									PKG:1
Y3340000 ^S		EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION CHECK OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.						Service	ATA:33
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00									PKG:2
Y3350003 ^S		EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK						Service	ATA:33
	MOS	22-Jun-23	48						
	HRS	9258.5	1200						
	AFL	7100							
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00									PKG:14
ATA 34 - NAVIGATION									
34-00-FAR-91.171		CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171						Service	ATA:34
	MOS/MSC	09-Mar-01	O/C						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171									
340000 ^U		INSPECTION ANNUAL AVIONICS						Service	ATA:34
	MOS/MSC	09-Mar-01	A/R					CUSTOMER CODE	
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341001	NO. 1 AIR DATA COMPUTER								Component ATA:34
PN:7014700-606	MOS/MSC	30-Apr-19	O/C						
SN:99072942	HRS	8080.6							
	AFL	6214							
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER								Service ATA:34
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:99072942	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									
341002	NO. 2 AIR DATA COMPUTER								Component ATA:34
PN:7014700-606	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:01014560	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01									
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER								Service ATA:34
PN:7014700-606	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:01014560	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E									
341013	STANDBY AIRSPEED INDICATOR								Component ATA:34
PN:6634208002-003	MOS/MSC	17-Dec-05	O/C						
SN:274205	HRS	4110.78							
	AFL	3119							
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01									
341025	STANDBY ALTIMETER								Component ATA:34
PN:7634208001-003	MOS/MSC	10-Aug-24	O/C						
SN:1722323	HRS								
	AFL								
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341025A	TEST/INSPECT STANDBY ALTIMETER								Service ATA:34
PN:7634208001-003	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:1722323	HRS								
	AFL								
Calibration Date: : 10-Aug-24									
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E									
341037	LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)								Component ATA:34
PN:0856TJ1	MOS	17-Aug-18		TSN 0				LIFE LIMIT	
SN:308640	HRS	7915.5	15000	TSN 0	22915.5		13137.4		
	AFL	6079		TSN 0					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341037A	TEST/INSPECT LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001)								Service ATA:34
PN:0856TJ1	MOS	10-Aug-24	24		10-Aug-26		383 d		
SN:308640	HRS								
	AFL								
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E									
341038	RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003)								Component ATA:34
PN:6634100000-003	MOS	09-Dec-24						LIFE LIMIT	
SN:276891	HRS	9574.3	15000	TSN 7559.6	17014.7		7236.6		
	AFL	7315		TSN 7118					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
341038A	TEST/INSPECT RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003)								Service ATA:34
PN:6634100000-003	MOS	09-Dec-24	24		09-Dec-26		504 d		
SN:276891	HRS	9574.3							
	AFL	7315							
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E									
341049	STANDBY PITOT/STATIC PROBE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
341049A		TEST/INSPECT STANDBY PITOT/STATIC PROBE						Service	ATA:34
	MOS	10-Aug-24	24		10-Aug-26		383 d		
	HRS								
	AFL								
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E									
341061		RADAR ALTIMETER RECEIVER						Component	ATA:34
PN:7001840-937	MOS/MSC	18-Oct-24	O/C						
SN:99118031	HRS	9555.2							
	AFL	7301							
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01									
341073		FORWARD RADAR ALTIMETER ANTENNA						Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C						
SN:552-14361	HRS	5618.1							
	AFL	4293							
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02									
341074		AFT RADAR ALTIMETER ANTENNA						Component	ATA:34
PN:S67-2002-4	MOS/MSC	14-Jul-07	O/C						
SN:552-13054	HRS	5618.1							
	AFL	4293							
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02									
3413-RVSM		FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.						Service	ATA:34
	MOS/MSC	09-Mar-01	N/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
341901		(TAT) TOTAL AIR TEMPERATURE PROBE						Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342001	(AHRs) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER								Component ATA:34
PN:145130-6000	MOS/MS	21-Mar-22	O/C						
SN:5001	HRS	8909							
	AFL	6851							
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342002	(AHRs) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER								Component ATA:34
PN:HG2010AC02	MOS/MS	10-Feb-09	O/C						
SN:99031032	HRS	6104.7							
	AFL								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342003	(AHRs) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN								Component ATA:34
PN:PN	MOS/MS	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342004	(AHRs) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN								Component ATA:34
PN:26012423-105	MOS/MS	10-Aug-12	O/C						
SN:10396	HRS	6975.7							
	AFL	5322							
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03									
342037	LEFT FLUX VALVE								Component ATA:34
PN:PN	MOS/MS	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									
342038	RIGHT FLUX VALVE								Component ATA:34
PN:PN	MOS/MS	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
342101	DUAL ANGLE OF ATTACK INDICATOR								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342103	STANDBY COMPASS								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01									
342103A	CALIBRATION CHECK STANDBY COMPASS								Service ATA:34
PN:PN	MOS/MSC	09-Mar-01	A/R						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
342701	LEFT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342702	RIGHT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01									
342801	STANDBY ATTITUDE INDICATOR								Component ATA:34
PN:501-1648-02	MOS/MSC	12-Sep-22	O/C						
SN:1338	HRS	9101.8							
	AFL	6994							
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
343005	MARKER BEACON ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01									
343008	UPPER GLIDESCOPE (E11) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343009	LOWER GLIDESCOPE (E12) ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02									
343030	MARKER BEACON ANTENNA SPLITTER								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03									
344111	UPPER TCAS ANTENNA								Component ATA:34
PN:071-01548-0200	MOS/MSC	15-Oct-09	O/C						
SN:587-10110	HRS	6191.1							
	AFL								
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									
344112	LOWER TCAS ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344143	TCAS PROCESSOR								Component ATA:34
PN:066-01146-1211	MOS/MSC	06-Jan-22	O/C						
SN:41568	HRS	8821.5							
	AFL	6790							
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01									
344155	TCAS RELAY BOX ASSEMBLY								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03									
344167	TCAS CONFIGURATION MODULE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344171	NO. 1 TCAS UPPER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344172	NO. 2 TCAS UPPER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344173	NO. 3 TCAS UPPER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344174	NO. 4 TCAS UPPER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344176	UPPER TCAS ADAPTER ASSEMBLY								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344177	LOWER TCAS ADAPTER ASSEMBLY								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344181	NO. 1 TCAS LOWER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344182	NO. 2 TCAS LOWER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344183	NO. 3 TCAS LOWER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344184	NO. 4 TCAS LOWER ANTENNA CABLE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA								Component ATA:34
PN:7021450-601	MOS/MSC	11-Aug-09	O/C						
SN:07067540	HRS	6169.3							
	AFL	4725							
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344207	WEATHER RADAR TRANSCEIVER								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01									
344209	WEATHER RADAR LIGHTNING SENSOR ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344221	WEATHER RADAR CONTROLLER								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02									
344223	LIGHTNING DETECTION PROCESSOR								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
344515	TAWS RELAY BOX							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345001	NO. 1 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-631	MOS/MSC	17-Feb-05	O/C						
SN:01015045	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345002	NO. 2 INTEGRATED NAVIGATION UNIT							Component	ATA:34
PN:7510100-633	MOS/MSC	17-Feb-05	O/C						
SN:99124053	HRS	3300.2							
	AFL	2515							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345011	NO. 1 NAVIGATION RECEIVER MODULE							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345012	NO. 2 NAVIGATION RECEIVER MODULE								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345013	NO. 1 ADF ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345014	NO. 2 ADF ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01									
345024	GPWS CONTROL PANEL								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345025	ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01									
345037	FORWARD ATC ANTENNA								Component ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143631	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345038	AFT ATC ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143620	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345049	AFT (NO. 1) DME ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	16-Jul-19	O/C	TSN 0					
SN:143632	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345050	FORWARD (NO. 2) DME ANTENNA							Component	ATA:34
PN:DMNI50-9-2	MOS/MSC	16-Jul-19	O/C	TSN 10					
SN:22086	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01									
345083	LEFT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21995	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									
345084	RIGHT VOR/LOCALIZER ANTENNA							Component	ATA:34
PN:DMN4-17-1/N	MOS/MSC	25-Nov-19	O/C	TSN 0					
SN:21818	HRS	8177.7		TSN 0					
	AFL	6303		TSN 0					
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02									
345201	NAV VHF (A42) DUPLEXER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
345260	PHASING COUPLER							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03									
345501	DME INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345605	LEFT UPPER MODE S ATC ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
345606	RIGHT UPPER MODE S ATC ANTENNA							Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component	ATA:34
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C						
SN:2081	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01									
346002	COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component	ATA:34
PN:3017-41-221	MOS/MSC	13-Apr-17	O/C						
SN:2082	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346021	FMS DATA (DTU) TRANSFER UNIT								Component ATA:34
PN:1408-00-1	MOS/MSC	13-Apr-17	O/C						
SN:3597	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02									
346025	NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE								Component ATA:34
PN:30171	MOS/MSC	13-Apr-17	O/C						
SN:2173	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346026	NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE								Component ATA:34
PN:30171	MOS/MSC	13-Apr-17	O/C						
SN:2174	HRS	7744.3							
	AFL	5922							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346031	NO. 1 FMS ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346032	NO. 2 FMS ANTENNA								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
346037 ^U	NO. 1 FMS CONTROL UNIT								Component ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
346038	U	NO. 2 FMS CONTROL UNIT						Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
346090		AFIS DATA MANAGEMENT UNIT						Component	ATA:34
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
347510		NO. 1 GPS ANTENNA						Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C						
SN:9815	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									
347511		NO. 2 GPS ANTENNA						Component	ATA:34
PN:10708	MOS/MSC	13-Apr-17	O/C						
SN:9814	HRS	7744.3							
	AFL	5922							
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01									
5-19-02-RVSM-L3411062	DETAILED VISUAL INSPECTION OF PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT(ZONE/ACCESS 220 IRN # L3411062)							Service	ATA:34
	MOS	10-Aug-24	24	Adj 6d	16-Aug-26		389 d	RVSM	
	HRS								
	AFL								
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052)							Service	ATA:34
	MOS	10-Aug-24	24	Adj 6d	16-Aug-26		389 d	RVSM	
	HRS								
	AFL								
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 34 - NAVIGATION									
5-19-02-RVSM-U3411060		PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060)						Service	ATA:34
	MOS	10-Aug-24	24	Adj 6d	16-Aug-26		389 d	RVSM	
	HRS								
	AFL								
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00									
A3400000 ^S		** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK						Service	ATA:34
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00									
V3420000 ^S		ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.						Service	ATA:34
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y3411000 ^S		PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS						Service	ATA:34
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01									
ATA 35 - OXYGEN									
35-02-01-005		OXYGEN CYLINDER						Component	ATA:35
PN:806385-14	MOS/MSC	28-Aug-23	H/T	TSN 15					
SN:C10050116	HRS	9307.4							
	AFL	7125							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350201	TEMP/PRESSURE TRANSDUCER							Component	ATA:35
PN:10008789	MOS/MSC	22-Jun-23	O/C						
SN:20201184	HRS	9258.5							
	AFL	7100							
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03									
350225	OXYGEN FILL (POST SB 45-12-1) VALVE							Component	ATA:35
PN:P21010	MOS/MSC	16-Jul-19	O/C	TSN 51					
SN:7488	HRS	8109		TSN 0					
	AFL	6239		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350230	REMOTE OXYGEN PRESSURE INDICATOR							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									
351001	PILOT OXYGEN MASK							Component	ATA:35
PN:MC10-15-166	MOS/MSC	28-Aug-23	O/C	TSO 0					
SN:100994	HRS	9307.4		TSO 0					
	AFL	7125		TSO 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351001A	OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006)							Service	ATA:35
PN:MC10-15-166	MOS	03-Aug-23	72		03-Aug-29		1472 d		
SN:100994	HRS								
	AFL								
OverHaul Date:: 03-Aug-23									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
351002	COPILOT OXYGEN MASK								Component ATA:35
PN:MC10-15-166	MOS/MSC	26-Aug-24	O/C	TSO 0					
SN:111581	HRS	9529		TSO 0					
	AFL	7280		TSO 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351002A	OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006)								Service ATA:35
PN:MC10-15-166	MOS	26-Aug-24	72		28-Jun-30		1801 d		
SN:111581	HRS	9529							
	AFL	7280							
OverHaul Date:: 28-Jun-24									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
351005	PILOT CREW OXYGEN OUTLET								Component ATA:35
PN:DPB181-04	MOS/MSC	24-May-07	O/C						
SN:20/06	HRS	5477.2							
	AFL	4173							
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
351006	COPILOT CREW-OXYGEN OUTLET								Component ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01									
352002	ALTITUDE COMPENSATING REGULATOR								Component ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06									
352005-1 ^U	LEFT NO. 1 PASSENGER OXYGEN ASSEMBLY MASK								Component ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352005-10 ^U		RIGHT NO.5 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-11 ^U		LAVATORY PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-12 ^U		LAVATORY PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-2 ^U		RIGHT NO. 1 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-3 ^U		LEFT NO. 2 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-4 ^U		RIGHT NO. 2 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352005-5 ^U		LEFT NO. 3 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-6 ^U		RIGHT NO.3 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-7 ^U		LEFT NO. 4 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-8 ^U		RIGHT NO. 4 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352005-9 ^U		LEFT NO.5 PASSENGER OXYGEN ASSEMBLY MASK						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352007-1 ^U		PASSENGER (#1 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025
 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352007-2	PASSENGER (#2 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352007-3	PASSENGER (#3 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352007-4	PASSENGER (#4 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352007-5	PASSENGER (#5 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352007-6	PASSENGER (#6 LEFT AND RIGHT) DUAL OXYGEN MASK BOX ASSEMBLY							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
352011	OXYGEN CONTROL VALVE							Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
352025	U	OXYGEN CYLINDER REGULATOR						Component	ATA:35
PN:806370-07	MOS/MSC	28-Aug-23	O/C	TSO 0					
SN:C10040171	HRS	9307.4		TSO 0					
	AFL	7125		TSO 0					
353001		PORTABLE OXYGEN CYLINDER						Component	ATA:35
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
355111		OXYGEN PRESSURE INDICATOR						Component	ATA:35
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05									
5-19-00-Q3510018	U	PERFORM OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. ZONE 230. IRN Q3510018						Service	ATA:35
	MOS/MSC		N/A						
	HRS								
	AFL								
5-19-00-Q3510022		OXYGEN CYLINDER REGULATOR - OVERHAUL						Service	ATA:35
	MOS	22-Jun-23	60		22-Jun-28		1065 d		
	HRS	9258.5	5000		14258.5		4480.4		
	AFL	7100							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-00-Q3510023		OXYGEN CYLINDER REGULATOR - OVERHAUL (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)						Service	ATA:35
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 35 - OXYGEN									
K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS							Service	ATA:35
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00									
N3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service	ATA:35
	MOS	30-Mar-21						AIRWORTHINESS	
	HRS	8414.4	1500		9914.4		136.3		
	AFL	6463							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
N3510019	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service	ATA:35
	MOS/MSC		N/A						
	HRS								
	AFL								
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
O3510003 ^S	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST							Service	ATA:35
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00									
O3510007	OXYGEN CYLINDER (COMPOSITE) - SCRAP							Service	ATA:35
	MOS	09-Mar-01	180		28-May-37 (M)		4327 d	LIFE LIMIT	
	HRS	0							
	AFL	0							
Q3510005	** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE.							Service	ATA:35
PN:806385-14	MOS	27-Jun-23	60		27-Jun-28		1070 d		
SN:C10050116	HRS	9307.4	5000		14307.4		4529.3		
	AFL	7125							
HydroCheck Date: : 27-Jun-23									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

Q3510018	** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Service	ATA:35
PN:806385-14	MOS	28-Aug-23	60		28-Aug-28		1132 d		
SN:C10050116	HRS	9307.4	5000		14307.4		4529.3		
	AFL	7125							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

W3510002 ^S	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service	ATA:35
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00									

PKG:7

Y3510001 ^S	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR.							Service	ATA:35
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:1

Y3510017 ^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION							Service	ATA:35
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

PKG:7

ATA 36 - PNEUMATIC

361001	LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361002	LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
361004	LEFT INBOARD HPBA MANIFOLD ASSEMBLY							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361005	RIGHT INBOARD HPBA MANIFOLD ASSEMBLY							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361016	RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07									
361020	LEFT HP OVER-TEMP SWITCH							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									
361021	RIGHT HP OVER-TEMP SWITCH							Component	ATA:36
PN:641179-4	MOS/MSC	06-Jun-05	O/C						
SN:0766	HRS	3654.87							
	AFL	2759							
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361031	ECS CONTROLLER								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01									
361040	VALVE, APU BLEED AIR CHECK REPLACE								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09									
361050	LOAD CONTROL (SHUTOFF (L5003) VALVE								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10									
361053	NO. 1 ECS SHUTOFF (L37) VALVE								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361054	NO. 2 ECS SHUTOFF (L38) VALVE								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03									
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE								Component ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:736	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE								Component ATA:36
PN:3291216-2	MOS/MSC	09-Jun-05	O/C						
SN:426	HRS	3666.35							
	AFL	2768							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									
361120	NO. 1 PRESSURE (S79) SWITCH								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									
361121	NO. 2 PRESSURE (S88) SWITCH								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06									
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE								Component ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
361215	ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361215A	BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361216	ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361216A	BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET							Service	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
361301	APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE							Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
361302 LEFT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE								Component	ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2360	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
361303 RIGHT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE								Component	ATA:36
PN:6608295-3	MOS/MSC	30-Apr-06	O/C						
SN:2308	HRS	4466.8							
	AFL	3408							
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02									
362005 LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT (S145) SWITCH								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362006 RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT (S146) SWITCH								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362007 LEFT AFT TAILCONE OVERHEAT THERMOSTAT (S147) SWITCH								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									
362008 RIGHT AFT TAILCONE OVERHEAT THERMOSTAT (S148) SWITCH								Component	ATA:36
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)							Service	ATA:36
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07									
5-19-00-P3610048	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 36-10-07.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY". (ZONE ACCESS 410/420)							Service	ATA:36
	MOS/MSC	12-Aug-15	MPI						
	HRS	7535.1							
	AFL	5764							
5-19-01-K3610012	REPLACE ENGINE SERVO AIR CHECK VALVE (6608295-3). (ZONE/ACCESS 310HL, 310JL, 310QR, 310RR IRN # K3610012)							Service	ATA:36
	MOS/MSC	30-Apr-06	A/R						
	HRS	4466.8							
	AFL	3408							
5-19-01-K3610013	REPLACE APU SERVO CHECK VALVE (6608295-3). EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (ZONE/ACCESS 310HL, 310JL, 310QR, 310RR IRN # K3610013)							Service	ATA:36
	MOS/MSC	09-Mar-01	N/A					NOT INSTALLED	
	HRS	0							
	AFL	0							
A3610000	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 36 - PNEUMATIC									
A3610001 ^S		** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST						Service	ATA:36
	MOS	02-Aug-24	24					AIRWORTHINESS	
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01									PKG:8
Y3610061 ^S		HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES						Service	ATA:36
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02									PKG:8
ATA 38 - WATER / WASTE									
380001		TOILET SERVICE PANEL						Component	ATA:38
PN:9600-102	MOS/MSC	09-Apr-06	O/C						
SN:SP1116	HRS								
	AFL								
PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05									
381009		TOILET HEATED DRAIN MAST ASSY						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
383001		TOILET						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01									
383002		TOILET TIMER						Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 38 - WATER/WASTE

PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02

383005	WATER TANK ASSEMBLY							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

383011	LAVATORY SINK SHUT OFF VALVE							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

384025	TOILET PUMP							Component	ATA:38
PN:5250-11A	MOS/MSC	12-Aug-15	O/C						
SN:P8851	HRS	7535.1							
	AFL	5764							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

384051	TOILET MACERATOR							Component	ATA:38
PN:5300-1	MOS/MSC	12-Aug-15	O/C	TSN 0					
SN:M5189	HRS	7535.1		TSN 0					
	AFL	5764		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

389050	TOILET CLEAN WATER PUMP							Component	ATA:38
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

ATA 49 - AIRBORNE AUXILIARY POWER

490060	ELECTRONIC CONTROL, APU ECU							Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04									
491011		MAINTENANCE CONTROL, APU PANEL						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02									
491020		APU, COCKPIT CONTROL PANEL						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01									
494050		IGNITION, APU UNIT						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04									
495001		COOLING, TAILCONE APU (B31) FAN						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01									
495002		TAILCONE ACCESS DOOR COOLING (B30) FAN						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
495040		APU THERMOSTAT (S175) SWITCH						Component	ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER									
495041	APU THERMOSTAT (S176) SWITCH								Component ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
495201	STRUT SUPPORT ASSEMBLY								Component ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
495202	STRUT SUPPORT ASSEMBLY								Component ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
497001	APU BITE INDICATOR								Component ATA:49
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
49APU1	NO. 1 APU								Component ATA:49
PN:PN	MOS/MSC		E/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
5-19-01-AA4900039	APU FUEL LINE (P/N 4549058032-001) REPLACE								Component ATA:49
PN:PN	MOS/MSC	EFF	N/A	TSN 0					
SN:UNKNOWN	HRS	EFF		TSN 0					
	AFL			TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
5-19-02-RVSM-M5240004 INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004)								Service	ATA:52
	MOS	10-Aug-24	24	Adj 6d	16-Aug-26		389 d	RVSM	
	HRS								
	AFL								
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01									
521001 UPPER CABIN DOOR								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									
521002 LOWER CABIN DOOR								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01									
5210053 CABIN DOOR HANDLE - REPLACE								Service	ATA:52
	MOS	06-Jul-21	144	Adj -67d	30-Apr-33		2838 d		
	HRS	8631.2							
	AFL	6618	6000		12618		5166		
PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13									
521010 LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY								Component	ATA:52
PN:SP21231-2	MOS/MSC	24-Jan-25	O/C	TSN 0					
SN:UNKNOWN	HRS	9595.4		TSN 0					
	AFL	7326		TSN 0					
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11									
521011 LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY								Component	ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
522001	EMERGENCY EXIT DOOR ASSEMBLY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01									
522010	DOOR ASSY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06									
523001	TAILCONE BAGGAGE DOOR ASSEMBLY								Component ATA:52
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
524001	TAILCONE ACCESS DOOR								Component ATA:52
PN:4552405151-009	MOS/MSC	17-Feb-05	O/C	TSN 0					
SN:0316	HRS	3300.2		TSN 0					
	AFL	2515		TSN 0					
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02									
524010	SPPR DOOR ASSY								Component ATA:52
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03									
AA5210055 ^S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE								Service ATA:52
	MOS	22-Jun-23	48						
	HRS	9258.5	1200						
	AFL	7100							
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02									
PKG:18									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
Y5210001 ^S		TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12
Y5210002 ^S		BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12
Y5210006 ^S		UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:12
Y5210008 ^S		EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. - PERFORM OPERATIONAL CHECK						Service	ATA:52
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07									PKG:12
ATA 53 - FUSELAGE									
5-19-00-M5310023 ^U		DETAILED VISUAL INSPECTION FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB45-53-27. (ZONE/ACCESS 300 IRN M5310023)						Service	ATA:53
	MOS/MSC	09-Mar-01	N/A					AIRWORTHINESS	
	HRS	0							
WC#: 53-108	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
5-19-00-M5310025 U DETAILED VISUAL INSPECTION AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30-495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL9.55 LH THRU BL 9.55 RH) OF HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-53-28. (ZONE/ACCESS 200 IRN M5310025) Service ATA:53									
	MOS/MSC	09-Mar-01	N/A					AIRWORTHINESS	
	HRS	0							
WC#: 53.102	AFL	0							
5-19-01-U5323167-LEFT * REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY Component ATA:53									
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS			TSN 0					
	AFL			TSN 0					
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04									
5-19-01-U5323167-RIGHT * REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY Component ATA:53									
PN:PN	MOS/MSC		N/A	TSN 0				NOT APPLICABLE	
SN:UNKNOWN	HRS			TSN 0					
	AFL			TSN 0					
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04									
5-19-02-RVSM-M5313001 PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001) Service ATA:53									
	MOS	10-Aug-24	24	Adj 6d	16-Aug-26		389 d	RVSM	
	HRS								
	AFL								
PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01									
530001 FUSELAGE ASSEMBLY Component ATA:53									
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
535001 RADOME Component ATA:53									
PN:6634408000-001	MOS/MSC	12-Dec-11	O/C	TSR 0					
SN:150	HRS	6763.5		TSR 0					
	AFL	5158		TSR 0					
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
535601	LEFT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
535602	RIGHT DELTA FIN							Component	ATA:53
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01									
H5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	11-Mar-25	24		11-Mar-27		596 d	AIRWORTHINESS	
	HRS	9645.6	2400		12045.6		2267.5		
	AFL	7359							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									
H5323092	* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS/MSC	30-Apr-06	N/A						
	HRS	4466.8							
	AFL	3408							
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01									
N5314000 ^S	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION							Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01									
N5323026 ^S	* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (FS 224 - FS 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/ CREW DOOR CUTOUT.							Service	ATA:53
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
T5321089 ^S SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING Service ATA:53									
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									
T5323166 * EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT). Service ATA:53									
	MOS	02-Aug-24	144		02-Aug-36		4028 d	MANDATORY	
	HRS	9525.7	9600		19125.7		9347.6		
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
V5323168 * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION Service ATA:53									
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	5000		14258.5		4480.4		
	AFL	7100							
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24									
Y5320000 ^S CENTER PEDESTAL - PERFORM VISUAL INSPECTION Service ATA:53									
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
Y5321010 ^S FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION Service ATA:53									
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 53 - FUSELAGE									
Y5321011 ^S		TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:8
Y5340007 ^S		WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:19
Y5360000 ^S		DELTA FINS - PERFORM VISUAL INSPECTION						Service	ATA:53
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:8
ATA 54 - NACELLES/PYLONS									
5-19-00-Q5450013 ^U		VISUAL INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT ASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.						Service	ATA:54
	MOS	22-Jun-23							
	HRS	9258.5	5000		14258.5		4480.4		
	AFL	7100							
5-19-00-Q5450013-LEFT ^U		FORWARD LEFT ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE						Service	ATA:54
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
5-19-00-Q5450013-RIGHT	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
5-19-01-A5450022 U REPLACEMENT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. (*IRN # A5450022)									
	MOS	26-Jul-23						LIFE LIMIT	
	HRS	9278	9600		18878		9099.9		
	AFL	7111							
5-19-01-A5450022-LEFT U LEFT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE									
PN:A5450022	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					
5-19-01-A5450022-RIGHT U RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE									
PN:A5450022	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					
5-19-01-A5450028 REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002)									
	MOS/MSC	09-Mar-01	N/A					N/A BY SERIAL NUMBER	
	HRS	0							
	AFL	0							
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02									
5-19-01-M5450027 REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/4)									
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
5-19-01-P5450020 ^U		REPLACEMENT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020						Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT	
	HRS	9278	9600		18878		9099.9		
	AFL	7111							
5-19-01-P5450020-LEFT ^U		LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACE						Component	ATA:54
PN:P5450020	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					
5-19-01-P5450020-RIGHT ^U		RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACEMENT						Component	ATA:54
PN:P5450020	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					
5-19-01-P5450023 ^U		REPLACE ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023						Service	ATA:54
	MOS	26-Jul-23						LIFE LIMIT	
	HRS	9278	9600		18878		9099.9		
	AFL	7111							
5-19-01-P5450023-LEFT ^U		LEFT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE						Component	ATA:54
PN:P5450023	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					
5-19-01-P5450023-RIGHT ^U		RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE						Component	ATA:54
PN:P5450023	MOS	26-Jul-23		TSN 0				MANDATORY	
SN:UNKNOWN	HRS	9278	9600	TSN 0	18878		9099.9		
	AFL	7111		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 54 - NACELLES/PYLONS									
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service	ATA:54
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
A5450022	* NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							
A5450022	* NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							
P5450020	* NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							
P5450020	* NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 54 - NACELLES/PYLONS

P5450023	* NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							

P5450023	* NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service	ATA:54
	MOS	09-Mar-01						LIFE LIMIT	
	HRS	0	9600		9600		OVD		
	AFL	0							

ATA 55 - STABILIZERS

5-19-00-M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION							Service	ATA:55
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

5-19-00-N5510088	U	DETAILED VISUAL INSPECTION UPPER VERTICAL STABILIZER, PIVOT FITTING STRUCTURE HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-55-15. (ZONE/ACCESS 300 IRN N5510088)						Service	ATA:55
	MOS/MSC	30-Apr-06	N/A					AIRWORTHINESS	
	HRS	4465.95							
WC#: 55.106	AFL	3406							

5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS ANDBUSHINGS - PERFORM DETAILED INSPECTION							Service	ATA:55
	MOS	16-Jul-19							
	HRS	8109	4800		12909		3130.9		
	AFL	6239							
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
551005	HORIZONTAL STABILIZER ASSEMBLY								Component ATA:55
PN:PN	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01									
552031	LEFT ELEVATOR ASSEMBLY								Component ATA:55
PN:4555201005-011	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									
552032	RIGHT ELEVATOR ASSEMBLY								Component ATA:55
PN:4555201005-012	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01									
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY								Component ATA:55
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
554005	RUDDER ASSEMBLY								Component ATA:55
PN:4555401000-023	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
M5510010	* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.							Service	ATA:55
	MOS	18-Aug-22						AIRWORTHINESS	
	HRS	9082.6	1200		10282.6		504.5		
	AFL	6994							
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03									
N5510005 ^S	* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05									
PKG:20									
N5510015 ^S	* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02									
PKG:20									
N5510016 ^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03									
PKG:20									
N5510069 ^S	* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service	ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02									
PKG:20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 55 - STABILIZERS									
N5510082	^S	* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04									
PKG:20									
W5510091		* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION							Service ATA:55
	MOS	02-Aug-24						MANDATORY	
	HRS	9525.7	625		10150.7		372.6		
	AFL	7276							
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00									
ATA 56 - WINDOWS									
561001		LEFT WINDSHIELD							Component ATA:56
PN:6656100000-001	MOS/MS	02-Aug-24	O/C						
SN:1121	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
561002		RIGHT WINDSHIELD							Component ATA:56
PN:6656100001-002	MOS/MS	02-Aug-24	O/C	TSN 152					
SN:1222	HRS	9525.7		TSN 2762.2					
	AFL	7276		TSN 2118					
Special Properties: RII ITEM									
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									
562010-1		LEFT NO.1 WINDOW CABIN							Component ATA:56
PN:PN	MOS/MS	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-10	RIGHT NO.5 WINDOW CABIN								Component ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4621	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-11	LEFT NO.6 WINDOW CABIN								Component ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-12	RIGHT NO.6 EMERGENCY EXIT WINDOW								Component ATA:56
PN:7656202000-015	MOS/MSC	19-Dec-10	O/C						
SN:5304	HRS	6457.2							
	AFL	4944							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-13	LEFT NO.7 WINDOW CABIN								Component ATA:56
PN:7656202000-015	MOS/MSC	28-Jun-16	O/C	TSN 0					
SN:6187	HRS	7635.4		TSN 0					
	AFL	5831		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-14	RIGHT NO.7 WINDOW CABIN								Component ATA:56
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C						
SN:0601	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-15	LEFT NO.8 WINDOW CABIN								Component ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-16		EMERGENCY EXIT WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	13-Dec-10	O/C	TSN 0					
SN:5304	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06									
562010-2		RIGHT NO.1 WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	21-Jun-05	O/C						
SN:1340	HRS	3694.5							
	AFL	2785							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-3		LEFT NO.2 WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4456	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-4		RIGHT NO.2 WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	17-Feb-05	O/C						
SN:0847	HRS	3300.2							
	AFL	2515							
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-5		LEFT NO.3 WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4505	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-6		RIGHT NO.3 WINDOW CABIN						Component	ATA:56
PN:7656202000-015	MOS/MSC	22-Dec-08	O/C	TSN 0					
SN:4458	HRS	6088.5		TSN 0					
	AFL	4660		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 56 - WINDOWS									
562010-7	LEFT NO.4 WINDOW CABIN							Component	ATA:56
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-8	RIGHT NO.4 WINDOW CABIN							Component	ATA:56
PN:7656202000-015	MOS/MSC	17-Dec-10	O/C	TSN 0					
SN:5310	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
562010-9	LEFT NO.5 WINDOW CABIN							Component	ATA:56
PN:7656202000-015	MOS/MSC	15-Dec-10	O/C	TSN 0					
SN:5307	HRS	6457.2		TSN 0					
	AFL	4944		TSN 0					
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01									
N5600003	* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service	ATA:56
PN:6656100000-001	MOS/MSC	02-Aug-24	N/A						
SN:1121	HRS	9525.7							
	AFL	7276							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									
N5600003	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service	ATA:56
PN:6656100001-002	MOS/MSC	02-Aug-24	N/A						
SN:1222	HRS	9525.7							
	AFL	7276							
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01									
N5600012	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service	ATA:56
PN:6656100000-001	MOS	02-Aug-24						AIRWORTHINESS	
SN:1121	HRS	9525.7	4800		14325.7		4547.6		
	AFL	7276							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 56 - WINDOWS

N5600012	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service	ATA:56
PN:6656100001-002	MOS	02-Aug-24						AIRWORTHINESS	
SN:1222	HRS	9525.7	4800		14325.7		4547.6		
	AFL	7276							
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01									

W5600002	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST							Service	ATA:56
	MOS	21-Feb-25	12	Adj 6d	27-Feb-26		219 d	AIRWORTHINESS	
	HRS	9637.3							
	AFL	7352							
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

Y5600000 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)							Service	ATA:56
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
									PKG:1
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y5600001 ^S	CABIN WINDOWS - PERFORM VISUAL INSPECTION							Service	ATA:56
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
									PKG:7
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									

Y5600013 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL							Service	ATA:56
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
									PKG:1
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01									

ATA 57 - WINGS

57-60-05-900	LEFT AILERON BOLTS (X3)							Component	ATA:57
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
	AFL	7276		TSN 0					
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
57-60-05-901	RIGHT AILERON BOLTS (X3)								Component ATA:57
PN:PN	MOS/MSC	02-Aug-24	H/T	TSN 0					
SN:UNKNOWN	HRS	9525.7		TSN 0					
	AFL	7276		TSN 0					
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
571001	WING ASSEMBLY								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								Component ATA:57
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								Component ATA:57
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0	20000	TSN 0	20000		12548		
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01									
5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.								Service ATA:57
	MOS	31-Mar-20	96	Adj -34d	26-Feb-28		948 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service	ATA:57
	MOS	31-Mar-20	96	Adj -34d	26-Feb-28		948 d		
	HRS	8253.8							
	AFL	6353							
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00									
573001	LEFT WINGLET FILLER							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573002	RIGHT WINGLET FILLER							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
573090	LEFT WING WINGLET							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
573091	LEFT WINGLET LEADING EDGE ASSEMBLY							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
573092	RIGHT WING WINGLET							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
573093	RIGHT WINGLET LEADING EDGE ASSEMBLY								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01									
574005	LEFT INBOARD LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574007	RIGHT INBOARD LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574033	LEFT CENTER LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
574035	RIGHT CENTER LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574050	LEFT OUTBOARD LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
574051	RIGHT OUTBOARD LEADING EDGE								Component ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01									
575001	LEFT FLAP ASSEMBLY								Component ATA:57
PN:4557500006-007	MOS/MSC	02-Aug-24	O/C						
SN:474598000144	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
575002	RIGHT FLAP ASSEMBLY							Component	ATA:57
PN:4557500006-008	MOS/MSC	02-Aug-24	O/C						
SN:474600100146	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01									
576001	LEFT AILERON							Component	ATA:57
PN:4557600003-001	MOS/MSC	02-Aug-24	O/C						
SN:UNKNOWN	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
576002	RIGHT AILERON							Component	ATA:57
PN:4557600003-002	MOS/MSC	02-Aug-24	O/C						
SN:00145	HRS	9525.7							
	AFL	7276							
Special Properties: RII ITEM									
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02									
577001	LEFT SPOILER							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									
577002	RIGHT SPOILER							Component	ATA:57
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01									
A5760004	* LEFT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service	ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600		19125.7		9347.6		
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
A5760004	* RIGHT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE								Service ATA:57
PN:PN	MOS	02-Aug-24						AIRWORTHINESS	
SN:UNKNOWN	HRS	9525.7	9600		19125.7		9347.6		
	AFL	7276							
E5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED								Service ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:10000		10000		221.9		
	AFL	0							
PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01									
E5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED								Service ATA:57
	MOS	22-Jun-23						AIRWORTHINESS	
	HRS	9258.5	600		9858.5		80.4		
	AFL	7100							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.								Service ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	3580		13105.7		3327.6		
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137								Service ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	2500		12025.7		2247.6		
	AFL	7276							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT								Service ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	4517		14042.7		4264.6		
	AFL	7276							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02									
N5710010		* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	960		10485.7		707.6		
	AFL	7276							
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									
N5710012		* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.						Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	3443		12968.7		3190.6		
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
N5710013		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.						Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:10000		10000		221.9		
	AFL	0							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									
N5710026		* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.						Service	ATA:57
	MOS							AIRWORTHINESS	
	HRS	0	T:10000		10000		221.9		
	AFL								
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710084 ^S		SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION						Service	ATA:57
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: NDT PART 6/57-40-01PROC. REF: NDT PART 6/57-40-01									

PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710123	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS	02-Aug-24						AIRWORTHINESS	
	HRS	9525.7	2666		12191.7		2413.6		
	AFL	7276							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01									
N5710148	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02									
N5710149	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06									
N5710150	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710151	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02									
N5710152	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710153	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03									
N5710155	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04									
N5710158	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03									
N5710159	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03									
N5710160	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710163	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A					NOT APPLICABLE	
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10									
N5710164	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02									
N5710165	* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01									
N5710168	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01									
N5710169	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									
N5710170	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
N5710171	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03									
N5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS	02-Aug-24							
	HRS	9525.7	2666		12191.7		2413.6		
	AFL	7276							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00									
N5710173	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00									
N5710174	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS	09-Mar-01						AIRWORTHINESS	
	HRS	0	T:10000		10000		221.9		
	AFL	0							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710175	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04									
N5710177	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service	ATA:57
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 57 - WINGS									
Y5700001	^S	WINGLET - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:4
Y5710180	^S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION						Service	ATA:57
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:10
Y5730013	^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION						Service	ATA:57
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01									PKG:4
Y5750067	^S	FLAP BRACKETS - PERFORM DETAILED VISUAL INSPECTION						Service	ATA:57
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:22
Y5750069	^S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service	ATA:57
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
5-19-00-Q7110004-LEFT	TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)								Service ATA:71
	MOS	02-Nov-22							
	HRS	9151.6	3000	Adj 39.5	12191.1		2413		
	AFL	7021							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
5-19-00-Q7110004-RIGHT	TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)								Service ATA:71
	MOS	12-Aug-15							
	HRS	7535.1	3000		10535.1		757		
	AFL	5764							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
5-19-00-R7100032	L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION.								Service ATA:71
	MOS/MSC	10-Nov-11	N/A					NOT APPLICABLE	
	HRS	6740.8							
	AFL	5145							
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03									
5-19-01-V7120074L	LEFT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.)								Component ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	9278		TSN 0					
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
5-19-01-V7120074R	RIGHT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001)(REFER TO 71-00-01.)								Component ATA:71
PN:4571408525-001	MOS/MSC	26-Jul-23	E/C	TSN 0				AIRWORTHINESS	
SN:UNKNOWN	HRS	9278		TSN 0					
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
710001 ^U	NO. 1 ASSEMBLY ENGINE								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
710002	NO. 2 ASSEMBLY ENGINE								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY								Component ATA:71
PN:3060757-3	MOS/MSC	06-Jul-23	O/C	TSN 0					
SN:22-129505-00163	HRS	8350.6		TSN 0					
	ENC	6943		TSN 0					
PROC. REF: LMM 72-00-02, LMM 72-00-02PROC. REF: LMM 72-00-02, LMM 72-00-02									
710130	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service ATA:71
	MOS	18-Aug-22							
	HRS	9008.5	800						
	ENC	6936							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
710130	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.								Service ATA:71
	MOS	18-Aug-22							
	HRS	8169.8	800						
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS	18-Aug-22							
	HRS	9008.5	800						
	ENC	6936							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									PKG:0
710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)							Service	ATA:71
	MOS	18-Aug-22							
	HRS	8169.8	800						
	ENC	6832							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									PKG:0
711001	NO. 1 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
711002	NO. 2 ENGINE FORWARD MOUNT							Component	ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS							Service	ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS							Service	ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120002	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120002	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	5000		14278		4499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120004		REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS						Component	ATA:71
	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
	HRS	0	15000	TSN 0	15000		5221.9		
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S		REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S		REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S		REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S		REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120004 ^S		REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING						Component	ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120004 ^S	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING								Component ATA:71
PN:PN	MOS	09-Mar-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	15000	TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Component ATA:71
PN:LM-833-SA18	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:LK2888	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
	MOS/MSC	27-Sep-06	N/A						
	HRS	4857.2							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:LM-833-SA18	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:LK288	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120005 REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC		N/A						
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005 REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120005 REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	5000	TSN 0	14278		4499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006 REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING									Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120006	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	N/A	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120069	NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	3000		12278		2499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120069	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	2500		11778		1999.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712007	NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING								Component ATA:71
PN:PN	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120070		REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:LM-833-SA18	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:LK2904	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:PN	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120070		REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING						Component	ATA:71
PN:LM-833-48	MOS	26-Jul-23		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	9278	6000	TSN 0	15278		5499.9		
	AFL	7111		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120073	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
7120073	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120073	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								Service ATA:71
	MOS	26-Jul-23							
	HRS	9278	6000		15278		5499.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120075	NO. 1 AFT ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS.								Service ATA:71
	MOS/MSC	26-Jul-23	MPI						
	HRS	9278	3600		12878		3099.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
7120075	NO. 2 AFT ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS.								Service ATA:71
	MOS/MSC	26-Jul-23	MPI						
	HRS	9278	3600		12878		3099.9		
	AFL	7111							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712008	NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:LM833-SA20-5	MOS/MSC	26-Sep-06	O/C						
SN:LK3128	HRS	4857.22							
	AFL	3730							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712009	NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
712010	NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY								Component ATA:71
PN:KM833-SA20-5	MOS/MSC	26-Sep-06	O/C						
SN:LK3185	HRS	4857.22							
	AFL	3730							
PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00									
712045	NO. 1 ENGINE AFT MOUNT								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
712046	NO. 2 ENGINE AFT MOUNT								Component ATA:71
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00									
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE								Service ATA:71
	MOS	18-Aug-22							
	HRS	9008.5	800						
	ENC	6936							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE								Service ATA:71
	MOS	18-Aug-22							
	HRS	8169.8	800						
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	18-Aug-22							
	HRS	9008.5	800						
	ENC	6936							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service	ATA:71
	MOS	18-Aug-22							
	HRS	8169.8	800						
	ENC	6832							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
716005	NO. 1 ENGINE INLET NACELLE							Component	ATA:71
PN:4572290001-801	MOS/MSC	16-Jul-19	O/C						
SN:145LH	HRS	8109							
	AFL	6239							
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
716006	NO. 2 ENGINE INLET NACELLE							Component	ATA:71
PN:2652000V24-003	MOS/MSC	02-Dec-09	O/C	TSR 0					
SN:114RH	HRS	6213.6		TSR 0					
	AFL	4758		TSR 0					
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01									
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3060082-2	MOS/MSC		E/C						
SN:P-116284C	HRS								
	AFL								
PROC. REF: AMM 71-00-01, SIL F731-88PROC. REF: AMM 71-00-01, SIL F731-88									
71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3060084-2	MOS/MSC	12-Aug-15	E/C						
SN:P-116285C	HRS	7535.1		TSN 6622.3					
	AFL	5764							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
PROC. REF: AMM 71-00-01, SIL F731-88PROC. REF: AMM 71-00-01, SIL F731-88									
Y7100002 ^S		LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING						Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9
Y7110000 ^S		ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.						Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9
Y7110001 ^S		ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION						Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9
Y7110002 ^S		ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION						Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9
Y7110003 ^S		ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION						Service	ATA:71
	MOS	02-Aug-24	24						
	HRS	9525.7	600						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 71 - POWER PLANT									
Y7120000	S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION							Service ATA:71
	MOS	02-Aug-24	12						
	HRS	9525.7	300						
	AFL	7276							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									
ATA 72 - ENGINE									
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	06-Dec-17							
	HRS	7696.2	3000		(10696.2) 10770.3		992.2		
	ENC	5895							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	20-Jul-15							
	HRS	6622.3	3000		(9622.3) 10535.1		757		
	ENC	5602							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720006	S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	06-Dec-17							
	HRS	7696.2	3000						
	ENC	5895							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-AS-720006	S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	20-Jul-15							
	HRS	6622.3	3000						
	ENC	5602							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS								Service ATA:72
	MOS	30-Oct-06							
	HRS	4857.2	6000		(10857.2) 10931.3		1153.2		
	ENC	3730							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS								Service ATA:72
	MOS	28-Jun-06							
	HRS	3701.2	6000		(9701.2) 10614		835.9		
	ENC	2811							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720008 ^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service ATA:72
	MOS	25-Oct-06							
	HRS	4857.2	6000						
	ENC	3730							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
72-AS-720008 ^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS								Service ATA:72
	MOS	05-Jun-06							
	HRS	3701.2	6000						
	ENC	3369							
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02									
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)								Service ATA:72
	MOS/MSC	05-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)								Service ATA:72
	MOS/MSC	20-Jan-16	A/R						
	HRS	6674							
	ENC	5628							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)								Service ATA:72
	MOS/MSC	05-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)								Service ATA:72
	MOS/MSC	15-Jan-00	A/R						
	HRS	0							
	ENC	0							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
720110	NO. 1 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3060827-2	MOS/MSC	25-Oct-06	O/C						
SN:S986	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									
720110	NO. 2 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02									
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3071383-2	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:13-150211-00260	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060150-3	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:061936801086	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060150-3	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:061936800093	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723010 ^S		NO. 1 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
PKG:0									
723010 ^S		NO. 2 ENGINE - CHECK CARBON SEAL HEALTH						Service	ATA:72
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00									
PKG:0									
723011		NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER						Component	ATA:72
PN:3075639-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141803634	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723011		NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER						Component	ATA:72
PN:3075639-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:052141802327	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723012		NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:3074573-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060515861210	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723012		NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY						Component	ATA:72
PN:3074573-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:060515847790	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR

Serial: 45-145

RegNo: N942FK

HRS: 9778.1

AFL: 7452

As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER								Component ATA:72
PN:3075633-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:062141802473	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER								Component ATA:72
PN:3075633-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:052141806990	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074574-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060515859035	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3074574-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:060515849488	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY								Component ATA:72
PN:3060840-3	MOS/MSC	25-Oct-06	A/R	TSN 0					
SN:UNKNOWN	HRS	4857.2		TSN 0					
WC#: 72.500	ENC	3730		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	A/R	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 72.500	ENC	0		TSN 0					
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060129-7	MOS	25-Oct-06						LIFE LIMIT	
SN:00P21077	HRS	4857.2							
	ENC	3730	12000	TSN 3730	(12000) 12058		4606		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060625-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:990322904089	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12162		4710		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060611-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322903502	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12058		4606		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060611-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322903437	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12162		4710		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900149	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12058		4606		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								Component ATA:72
PN:3060671-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322900152	HRS	0		TSN 0					
	ENC	0	12000	TSN 0	(12000) 12162		4710		
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060555-5	MOS	25-Oct-06						LIFE LIMIT	
SN:061217200024	HRS	4857.2							
	ENC	3730	10000	TSN 0	(13730) 13788		6336		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								Component ATA:72
PN:3060841-1	MOS	20-Jul-15						LIFE LIMIT	
SN:041217200360	HRS	6622.3		TSN 4043.4					
	ENC	5602	10000	TSN 3645	(11957) 12119		4667		
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
725050	NO. 1 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:030322901250	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20058		12606		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725050	NO. 2 ENGINE - FAN DISC								Component ATA:72
PN:3060287-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:010322905809	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20162		12710		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002316	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10058		2606		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060372-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002319	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10162		2710		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060608-3	MOS	25-Oct-06						LIFE LIMIT	
SN:000322903502	HRS	4857.2							
	ENC	3730	10000	TSN 3730	(10000) 10058		2606		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060373-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000316001852	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10162		2710		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725071	NO. 1 ENGINE - COMBUSTION LINER								Component ATA:72
PN:3060766-1	MOS/MSC	28-Nov-17	O/C	TSO 0					
SN:08P16345	HRS	7696.2		TSO 0					
	ENC	5895		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725071	NO. 2 ENGINE - COMBUSTION LINER								Component ATA:72
PN:3060766-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:06P00417	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3060374-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000316002539	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10058		2606		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3072417-12	MOS	05-Jun-06		TSR 0				LIFE LIMIT	
SN:000316002937	HRS	3701.2		TSR 0					
	ENC	3369	10000	TSN 3369, TSR 0	(10000) 10162		2710		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725081	NO. 1 ENGINE - OUTER TRANSITION LINER								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725081	NO. 2 ENGINE - OUTER TRANSITION LINER								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-03, LMM 72-40-03PROC. REF: LMM 72-40-03, LMM 72-40-03									
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075326-5	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:001365107764	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20058		12606		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								Component ATA:72
PN:3075351-12	MOS	05-Jun-06						LIFE LIMIT	
SN:050350107807	HRS	3701.2							
	ENC	3369	20000	TSN 0	(23369) 23531		16079		
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04									
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10									
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component ATA:72
PN:3060371-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:005332200378	HRS	0		TSN 0					
	ENC	0	8000	TSN 0	(8000) 8058		606		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER								Component ATA:72
PN:3060371-1	MOS	05-Jun-06						LIFE LIMIT	
SN:060322902406	HRS	3701.2							
	ENC	3369	8000	TSN 0	(11369) 11531		4079		
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06									
725130	NO. 1 ENGINE - FAN SPINNER								Component ATA:72
PN:3060156-2	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000312	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20058		12606		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									
725130	NO. 2 ENGINE - FAN SPINNER								Component ATA:72
PN:3060156-2	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:002428000311	HRS	0		TSN 0					
	ENC	0	20000	TSN 0	(20000) 20162		12710		
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725140	NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725140	NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3067021-1	MOS/MSC	23-May-07	O/C						
SN:970339000246	HRS	4564.4							
	ENC	4010							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS	28-Nov-17		TSN 0				LIFE LIMIT	
SN:16-162246-03040	HRS	7696.2		TSN 0					
	ENC	5895	7000	TSN 0	(12895) 12953		5501		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL								Component ATA:72
PN:3060698-1	MOS	20-Jul-15		TSN 0				LIFE LIMIT	
SN:14-162246-04706	HRS	6622.3		TSN 0					
	ENC	5602	7000	TSN 0	(12602) 12764		5312		
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03									
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3060534-4	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P24979	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04									
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	05-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905164	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10058		2606		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE								Component ATA:72
PN:3060514-1	MOS	15-Jan-00		TSN 0				LIFE LIMIT	
SN:000322905162	HRS	0		TSN 0					
	ENC	0	10000	TSN 0	(10000) 10162		2710		
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	25-Oct-06	O/C						
SN:97P23086	HRS	4857.2							
	ENC	3730							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3060694-6	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:02P01906	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT								Component ATA:72
PN:3060693-1	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28158	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY								Component ATA:72
PN:3060666-7	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29069	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04									
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING								Component ATA:72
PN:3060502-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P26421	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING								Component ATA:72
PN:3060599-2	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P28573	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL								Component ATA:72
PN:3073765-12	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:00P29032	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY								Component ATA:72
PN:3070093-16	MOS/MSC	25-Oct-06	O/C						
SN:P10020	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-60-03, LMM 72-60-03PROC. REF: LMM 72-60-03, LMM 72-60-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727001	NO. 1 ENGINE - BYPASS FAN STATOR								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									
727001	NO. 2 ENGINE - BYPASS FAN STATOR								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05									
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	27-Aug-21							
	HRS	8634.1	1200						
	ENC	6633							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									
727010 ^S	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.								Service ATA:72
	MOS	27-Aug-21							
	HRS	7795.4	1200						
	ENC	6529							
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060457-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:17-152826-59105	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY								Component ATA:72
PN:3060457-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-152826-73404	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER								Component ATA:72
PN:3075657-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:14-162397-04157	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727105	NO. 1 ENGINE - HELICAL RING GEAR								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727105	NO. 2 ENGINE - HELICAL RING GEAR								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
727203	NO. 1 ENGINE - NO. 3 BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727203	NO. 2 ENGINE - NO. 3 BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-30-01, LMM 72-30-01PROC. REF: LMM 72-30-01, LMM 72-30-01									
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727210-1		NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-1		NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-2		NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-2		NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-3		NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-3		NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY						Component	ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 72-72-03, LMM 72-72-03PROC. REF: LMM 72-72-03, LMM 72-72-03									
ATA 73 - ENGINE FUEL AND CONTROL									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-37	MOS/MSC	25-Oct-06	O/C						
SN:16529	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-47	MOS/MSC	27-Feb-23	O/C	TSO 0					
SN:19179	HRS	8273.9		TSO 0					
	ENC	6885		TSO 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
730120 ^S		NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73
	MOS	22-Jun-23							
	HRS	9184.4	600						
	ENC	7042							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									PKG:0
730120 ^S		NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT						Service	ATA:73
	MOS	22-Jun-23							
	HRS	8345.7	600						
	ENC	6938							
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02									PKG:0
730130		NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060760-3	MOS/MSC	25-Oct-06	O/C						
SN:0942	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
730130		NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY						Component	ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01, LMM 73-20-01, LMM 73-20-01									
731001		NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	25-Oct-06	O/C						
SN:0457	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									
731001		NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY						Component	ATA:73
PN:3060759-1	MOS/MSC	18-Dec-13	O/C	TSO 0					
SN:0671	HRS	6312.5		TSO 0					
	ENC	5360		TSO 0					
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-1		NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-430	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-1		NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:020137100424	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10		NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-1025	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-10		NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401375	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11		NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101056	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-11		NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:010137103143	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-12		NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-400	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-12		NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401374	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-2		NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:010137102472	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-2		NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401378	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-3		NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-398	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-3		NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:032923401169	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-4		NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-572	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-4		NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:032923401065	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-5		NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101033	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-5		NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:072923400480	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-6		NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:990137101059	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-6		NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923400974	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731005-7		NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-542	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-7		NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052623401379	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-8		NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:022923401439	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-8		NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:052923401376	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-9		NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	25-Oct-06	O/C						
SN:97-01371-562	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									
731005-9		NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY						Component	ATA:73
PN:3060540-2	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:000137102869	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 73-10-01, LMM 73-10-01PROC. REF: LMM 73-10-01, LMM 73-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR								Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR								Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE								Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE								Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01									
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
732102	NO. 1 ENGINE - RELIEF VALVE								Component ATA:73
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732102	NO. 2 ENGINE - RELIEF VALVE								Component ATA:73
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE								Service ATA:73
	MOS	22-Jun-23							
	HRS	9184.4	600						
	ENC	7042							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
732120 ^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE								Service ATA:73
	MOS	22-Jun-23							
	HRS	8345.7	600						
	ENC	6938							
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04									
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER								Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER								Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
733013	DUAL FUEL FLOW CONVERTER (DFFC)								Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02									
733031	LEFT ENGINE FUEL TEMPERATURE BULB								Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
733032	RIGHT ENGINE FUEL TEMPERATURE BULB								Component ATA:73
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
ATA 74 - IGNITION									
740110	NO. 1 ENGINE - IGNITION UNIT								Component ATA:74
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740110	NO. 2 ENGINE - IGNITION UNIT								Component ATA:74
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD								Service ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
740140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD								Service ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PKG:0									
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:UNKNOWN	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	18-Aug-22	O/C	TSN 0					
SN:UNKNOWN	HRS	8169.8		TSN 0					
	ENC	6832		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
740160 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD								Service ATA:74
	MOS	22-Jun-23							
	HRS	9184.4	1600						
	ENC	7042							
PKG:0									
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
740160 ^S		NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						Service	ATA:74
	MOS	18-Aug-22							
	HRS	8169.8	1600						
	ENC	6832							
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01									
742011		NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:3060722-11	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S23100003	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742011		NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742012		NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:3060722-12	MOS/MSC	22-Jun-23	O/C	TSN 0					
SN:S22500007	HRS	9184.4		TSN 0					
	ENC	7042		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
742012		NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD						Component	ATA:74
PN:9043913	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:UNKNOWN	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 74-00-01, LMM 74-00-01PROC. REF: LMM 74-00-01, LMM 74-00-01									
743001		TAIL CONE RELAY (P13) PANEL						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
743001-1		EMERGENCY LIGHTING (P-51) RELAY						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
743005-1		K22 RELAY						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
743005-2		K61 RELAY						Component	ATA:74
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
ATA 75 - AIR									
754210		NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR						Component	ATA:75
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01									
754210		NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR						Component	ATA:75
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01, LMM 75-40-01									
ATA 76 - ENGINE CONTROLS									
761013		THROTTLE CONTROL MODULE						Component	ATA:76
PN:69011-17	MOS/MSC	16-Jul-20	O/C						
SN:640	HRS	8284.1							
	AFL	6376							
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761201	AFT LEFT THROTTLE CABLE								Component ATA:76
PN:71825-6	MOS/MSC	12-Oct-12	O/C						
SN:UNKNOWN	HRS	6996.3							
	AFL	5340							
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761202	AFT RIGHT THROTTLE CABLE								Component ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761203	LEFT FORWARD THROTTLE CABLE								Component ATA:76
PN:71845-10	MOS/MSC	12-Oct-12	O/C						
SN:UNKNOWN	HRS	6996.3							
	AFL	5340							
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761204	RIGHT FORWARD THROTTLE CABLE								Component ATA:76
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01									
761310	NO. 1 ENGINE - SURGE BLEED VALVE								Component ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761310	NO. 2 ENGINE - SURGE BLEED VALVE								Component ATA:76
PN:978812-6-1	MOS/MSC	20-Jul-15	O/C	TSO 0					
SN:10962	HRS	6622.3		TSO 0					
	ENC	5602		TSO 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 76 - ENGINE CONTROLS									
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE								Component ATA:76
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE								Component ATA:76
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01, LMM 76-10-01									
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER								Component ATA:76
PN:2118882-1008	MOS/MSC	25-Oct-06	O/C						
SN:15-AW0059	HRS	4857.2							
	ENC	3730							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER								Component ATA:76
PN:2118882-1008	MOS/MSC	27-Jun-06	O/C						
SN:124-AW0057	HRS	4614							
	ENC	3532							
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02									
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM								Service ATA:76
PN:2118882-1008	MOS	30-Jun-25						CUSTOMER CODE	
SN:15-AW0059	HRS	9689.5							
	ENC	7383	40		(7423) 7481		29		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM								Service ATA:76
PN:2118882-1008	MOS	30-Jun-25						CUSTOMER CODE	
SN:124-AW0057	HRS	8850.8							
	ENC	7279	40		(7319) 7481		29		
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
5-19-00-F7720002	U	PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM ITT MARGIN CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 **IRN # F7720002)						Service	ATA:77
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
5-19-00-F7720003	U	PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM HARDWARE VALIDATION CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 IRN # F7720003)						Service	ATA:77
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
770101	NO. 1 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									
770101	NO. 2 ENGINE - N1 MONOPOLE							Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-02PROC. REF: LMM 77-10-02									
771210	NO. 1 ENGINE - N1 COMPENSATOR							Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03									
771210	NO. 2 ENGINE - N1 COMPENSATOR							Component	ATA:77
PN:3060735-7	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:011309700526	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03, LMM 77-10-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 77 - ENGINE INDICATING									
771220		NO. 1 ENGINE - N2 MONOPOLE						Component	ATA:77
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05									
771220		NO. 2 ENGINE - N2 MONOPOLE						Component	ATA:77
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05, LMM 77-10-05									
772210		NO. 1 ENGINE - ITT HARNESS ASSEMBLY						Component	ATA:77
PN:3060730-1	MOS/MSC	28-Nov-17	O/C	TSN 0					
SN:1716901702429	HRS	7696.2		TSN 0					
	ENC	5895		TSN 0					
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01									
772210		NO. 2 ENGINE - ITT HARNESS ASSEMBLY						Component	ATA:77
PN:3060763-1	MOS/MSC	20-Jul-15	O/C	TSN 0					
SN:1516901702268	HRS	6622.3		TSN 0					
	ENC	5602		TSN 0					
PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01PROC. REF: LMM 77-20-01, LMM 77-20-01, LMM 77-20-01, LMM 77-20-01									
774001		ENGINE VIBRATION MONITOR BOX						Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01									
774010		P36 RELAY BOX						Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 77 - ENGINE INDICATING

774011	LEFT ENGINE VIBRATION ACCELEROMETER							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02									

774012	RIGHT ENGINE VIBRATION ACCELEROMETER							Component	ATA:77
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02									

Y7741000 ^S	ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST							Service	ATA:77
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
									PKG:21
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00									

ATA 78 - EXHAUST

5-19-00-R7830007	PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST							Service	ATA:78
	MOS/MSC	09-Mar-01	N/A						
	HRS	0							
	AFL	0							
PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01									

783001	LEFT LOWER THRUST REVERSER							Component	ATA:78
PN:LJ7830101-5	MOS/MSC	26-Jul-23	O/C						
SN:00046	HRS	9278							
	AFL	7111							
Special Properties: RII ITEM									
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783002 RIGHT LOWER THRUST REVERSER								Component	ATA:78
PN:LJ7830101-6	MOS/MSC	26-Jul-23	O/C						
SN:00052	HRS	9278							
	AFL	7111							
Special Properties: RII ITEM									
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00									
783025 TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT								Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783037 NO. 1 GPM HYDRAULIC CONTROL VALVE								Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783038 NO. 2 GPM HYDRAULIC CONTROL VALVE								Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783051 LEFT OUTBOARD THRUST REVERSER ACTUATOR								Component	ATA:78
PN:LJ7833100-3	MOS/MSC	26-Jan-14	O/C	TSO 0					
SN:A30040652	HRS	7249.8		TSO 0					
	AFL	5528		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783052 LEFT INBOARD THRUST REVERSER ACTUATOR								Component	ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:LJ7833100-4	MOS/MSC	12-Dec-11	O/C	TSO 0					
SN:A30040459	HRS	6763.5		TSO 0					
	AFL	5158		TSO 0					
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20									
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10									
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30									
783210	LEFT THRUST REVERSER CONTROL VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783211	RIGHT THRUST REVERSER CONTROL VALVE								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
783301	LEFT THRUST REVERSER CONTROL BOX								Component ATA:78
PN:LJ7836706-3	MOS/MSC	23-Aug-22	O/C						
SN:00046	HRS	9089.4							
	AFL	6994							
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10									
783302	RIGHT THRUST REVERSER CONTROL BOX								Component ATA:78
PN:LJ7836706-3	MOS/MSC	18-Jun-07	O/C						
SN:00059	HRS	5562.1							
	AFL	4242							
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10									
783320	LEFT OUTBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783321	LEFT INBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783322	RIGHT INBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									
783323	RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	09-Mar-01	C/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20									

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C / W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 78 - EXHAUST									
D7830078 ^S		** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK						Service	ATA:78
	MOS	25-Nov-19	96					AIRWORTHINESS	
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40									PKG:21
Y7830000 ^S		EXHAUST NOZZLE - PERFORM VISUAL INSPECTION						Service	ATA:78
	MOS	25-Nov-19	96						
	HRS	8177.7	2400						
	AFL	6303							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00									PKG:21
ATA 79 - OIL									
790110		NO. 1 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:061405700614	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
790110		NO. 2 ENGINE - OIL PUMP						Component	ATA:79
PN:3060785-2	MOS/MSC	05-Jun-06	O/C	TSN 0					
SN:061405700076	HRS	3701.2		TSN 0					
	ENC	3369		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
790130 ^S		NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	02-Aug-24							
	HRS	9451.6	150						
	ENC	7218							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790130	^S	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)						Service	ATA:79
	MOS	02-Aug-24							
	HRS	8612.9	150						
	ENC	7114							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790140	^S	NO. 1 ENGINE - PERFORM OIL CHANGE						Service	ATA:79
	MOS	27-Aug-21							
	HRS	8634.1	1200						
	ENC	6633							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790140	^S	NO. 2 ENGINE - PERFORM OIL CHANGE						Service	ATA:79
	MOS	27-Aug-21							
	HRS	7795.4	1200						
	ENC	6529							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00									PKG:0
790150	^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK						Service	ATA:79
	MOS	22-Jun-23							
	HRS	9184.4	600						
	ENC	7042							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
790150	^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK						Service	ATA:79
	MOS	22-Jun-23							
	HRS	8345.7	600						
	ENC	6938							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
790160 ^S		NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						Service	ATA:79
	MOS	02-Aug-24							
	HRS	9451.6	150						
	ENC	7218							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
790160 ^S		NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						Service	ATA:79
	MOS	02-Aug-24							
	HRS	8612.9	150						
	ENC	7114							
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01									PKG:0
791001		NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR						Component	ATA:79
PN:277-5501-9002	MOS/MSC	18-May-13	O/C						
SN:N/A	HRS	7075.3							
	ENC	5383							
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01									
791001		NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR						Component	ATA:79
PN:277-5501-9004	MOS/MSC	18-May-13	O/C						
SN:N/A	HRS	6239							
	ENC	5281							
PROC. REF: LMM 79-10-01, LMM 79-10-01PROC. REF: LMM 79-10-01, LMM 79-10-01									
792008		NO. 1 ENGINE - OIL FLOW REDUCTION VALVE						Component	ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									
792008		NO. 2 ENGINE - OIL FLOW REDUCTION VALVE						Component	ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08									

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792011	NO. 1 ENGINE - FUEL/OIL VALVE								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792011	NO. 2 ENGINE - FUEL/OIL VALVE								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03									
792037	NO. 1 OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									
792038	NO. 2 OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY								Component ATA:79
PN:160554-5	MOS/MSC	05-Jun-06	O/C						
SN:76-247	HRS	3701.2							
	ENC	3369							
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY								Component ATA:79
PN:160552-3	MOS/MSC	05-Jun-06	O/C						
SN:47-274	HRS	3701.2							
	ENC	3369							
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY								Component ATA:79
PN:160554-6	MOS/MSC	05-Jun-06	O/C						
SN:1068	HRS	3701.2							
	ENC	3369							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
Serial: 45-145
RegNo: N942FK
HRS: 9778.1
AFL: 7452
As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02									
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE								Component ATA:79
PN:3075323-3	MOS/MSC	16-Feb-11	O/C						
SN:000814506520	HRS	5602							
	ENC	4823							
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02									
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01									
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR
 Serial: 45-145
 RegNo: N942FK
 HRS: 9778.1
 AFL: 7452
 As Of: 21-Jul-2025

23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 79 - OIL									
793011	LEFT TEMPERATURE OIL BULB								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793012	RIGHT TEMPERATURE OIL BULB								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793013	APU TEMPERATURE OIL BULB								Component ATA:79
PN:PN	MOS/MSC	09-Mar-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03									
793064	NO. 1 ENGINE - TEMP BULB								Component ATA:79
PN:PN	MOS/MSC	05-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793064	NO. 2 ENGINE - TEMP BULB								Component ATA:79
PN:PN	MOS/MSC	15-Jan-00	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE								Component ATA:79
PN:3060782-2	MOS/MSC	25-Oct-06	O/C	TSN 0					
SN:060645105349	HRS	4857.2		TSN 0					
	ENC	3730		TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45XR Serial: 45-145 RegNo: N942FK HRS: 9778.1 AFL: 7452 As Of: 21-Jul-2025 23-Jul-2025 08:06 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 79 - OIL									
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE								Component ATA:79
PN:3060782-2	MOS/MSC	25-Nov-20	O/C	TSO 0					
SN:K15538	HRS	7388.5		TSO 0					
	ENC	6230		TSO 0					

793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service ATA:79
	MOS	22-Jun-23							
	HRS	9184.4	600						
	ENC	7042							
PKG:0									

793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								Service ATA:79
	MOS	22-Jun-23							
	HRS	8345.7	600						
	ENC	6938							
PKG:0									

793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component ATA:79
PN:160506-4	MOS/MSC	30-Nov-16	O/C	TSO 4					
SN:47-486	HRS	7607.6		TSO 0					
	ENC	5820		TSO 0					
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									

793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY								Component ATA:79
PN:3060709-4	MOS/MSC	05-Jun-06	O/C						
SN:16-240	HRS	3701.2							
	ENC	3369							
PROC. REF: LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-07, LMM 79-20-07									

ATA 85 - FUEL CELL SYSTEMS

859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK								Service ATA:85
	MOS/MSC	09-Mar-01	A/R						
	HRS	0							
	AFL	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task