

LOG BOOK #3

Aircraft Record General Information

Manufacturer BEECH Model 58P
Serial TJ-294 Registration Number N399TC
Date of Manufacture _____

Engine(s) currently installed:

Manufacturer _____ Model _____ Serial _____
Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer _____ Model _____
HUB Model _____ Serial _____ Serial _____
Blade Model _____ Serial _____ Serial _____ Serial _____
Blade Model _____ Serial _____ Serial _____ Serial _____

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-------	---------------------------	------------------	-----------------------------	---

DATE

American Aviation Inc.

Wilkes County Airport (UKF)

Date:	05-24-2007	Hobbs:	3152.4
Aircraft Reg.	N399TC	ACTT:	
Manufacture:	Beech	ACTC:	
Model No.:	58P	TSN:	
Serial No.:	TJ-294	CSN:	

Performed annual Inspection Per. FAR 43 Appendix "D" Scope & Detail, With Reference To 58P Baron Inspection Guide. Performed Retraction Check Of Landing Gear System (Normal & Emergency). Installed Same Removed Hydro Inspected Oxygen Bottle Assembly. Installed New Left & Right Wheel Brake Disc's P/N: 164-20806 And Linings P/N: 066-09700. Resealed Right Main Gear Wheel Brake Caliper. Installed New Left & Right Pneumatic Air Filters P/N: D9-14-5 And AA1J4-7. Installed New Right Elevator Bushing P/N: 105740X-ZM0290 And New Left & Right Elevator Bolts P/N: NAS464P4-8. Installed New Left And Right Elevator Trim Horn Bolts P/N: NAS1104-6D. Installed Overhauled Propeller Deice Timer P/N: 3E1150-10. Serviced Aircraft IAW 58P Baron Shop Manual As Needed. Setup LT & Rt Engine Fuel Systems IAW Continental SID 97-3E.

Checked ELT For Condition & Operation Per. FAR 91.207 Para. "d". Installed New ELT Battery, Next Due Date (08-2009).
C'd/W AD2004-21-05 Janitrol Heater Pressure Decay Test Per. Overhaul Manual.

I certify that this aircraft has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition.

Signature, *Robert A. Wislick*

Robert A. Wislick IA 171549879

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT
-------	---------------------------	------------------

DATE

American Av

Wilkes County A

Installed Two (2) N
Installed New Nose

Signature, *Rob*

with Name, Rating and Certificate Number of
ity. (See back pages for other specific entries.)

4-2007	Hobbs:	3152.4
9TC	ACTT:	
ch	ACTC:	
	TSN:	
94	CSN:	

cope & Detail, With Reference
Check Of Landing Gear System
Inspected Oxygen Bottle
P/N: 164-20806 And Linings
Caliper. Installed New Left &
Installed New Right Elevator
Elevator Bolts P/N: NAS464P4-8
P/N: NAS1104-6D. Installed
Replaced Aircraft IAW 58P Baron
Systems IAW Continental SID 97-

Para. "d". Installed New ELT

st Per. Overhaul Manual.

with an annual inspection and

t A. Wislick IA 171549879

[illegible]

ns, Tests, Repairs and Alterations

Name, Rating and Certificate Number of
See back pages for other specific entries.)

N399TC**SN TJ-294**

ater KC295 (sn 5419). Ground
er FAR 91.411.

nspected in accordance
etails see work order 50278

CE Avionics, Inc.**CRS 0E4R411M**

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				

American Aviation Inc.**Wilkes County Airport (UKF)**

Date:	07-11-2008	Hobbs:	3200.5
Aircraft Reg.	N399TC	ACTT:	4334.5
Manufacture:	Beech	ACTC:	
Model No.:	58P	TSN:	
Serial No.:	TJ-294	CSN:	

Performed annual inspection Per. FAR 43 Appendix "D" Scope & Detail, With Reference To 58P Baron Inspection Guide. Replaced Left & Right Main Wheel Tires (021-335-1). Serviced All Wheel Bearings. Performed Retraction Check Of Landing Gear System (normal & Emergency). Replaced Two (2) Wheel Brake Pins (177-00300) Left Position. Replaced Left Wing Root Seal (115092-14400). Replaced Left & Right Engine Induction Air Filters (P12-8219) Checked ELT For Condition & Operation Per. FAR 91.207 Para. "d". Battery Due Date (Oct-2011).

I certify that this aircraft has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition.

Signature.

Robert A. Wislick

Robert A. Wislick IA 171549879

tion of Inspections, Tests, Repairs and Alterations

must be endorsed with Name, Rating and Certificate Number of
an or Repair Facility. (See back pages for other specific entries.)

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
DATE				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

American Aviation Inc.

Wilkes County Airport (UKF)

Date:	07-30-2009	Hobbs:	3252.3
Aircraft Reg.	N399TC	ACTT:	4386.3
Manufacture:	Beech	ACTC:	
Model No.:	58P	TSN:	
Serial No.:	TJ-294	CSN:	

Performed annual inspection Per. FAR 43 Appendix "D" Scope & Detail, With Reference To 58P Baron Inspection Guide. Performed Retraction Check Of Landing Gear System (Normal & Emergency). Replaced Lt Main Wheel Bearing Sets (2) (214-00100, 13889). Replaced Nose Wheel Bearing Sets (2) (08125, 08231). Replaced Main Wheel Bearing Grease Seals (4) (154-03000). Replaced A/C Compressor Drive Belt (646293-34.00). Replaced Left Engine Dry Air Pump (442CW-4). Replaced Left Propeller Deice Brush (1) (RA-2111U). Replaced Manifold Sleeves (3) (628672) Left & Right Engines. Adjusted Cabin Heater Air Pressure Switch, Per. Janitrol Overhaul Manual. Checked ELT For Condition & Operation Per. FAR 91.207 Para. "d". Battery Due Date (Oct-2011).

C'd/W AD2004-21-05 (Janitrol Heater Pressure Decay Check), Per. Janitrol Overhaul Manual (Heater Hobbs 763.3)

C'd/W AD2008-13-17 (Circuit Breaker Switches), By AMOC L115W-09-665, Dated July 30, 2009. Installation Of Williams Air Parts Inc. Circuit Breaker Switches.

I certify that this aircraft has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition.

Signature.

Robert A. Wislick

Robert A. Wislick IA 171549879

American Aviation Inc.

Wilkes County Airport (UKF)

Installed New Fuel Flow Transmitter Part No. 102-389012-11, Serial No 172388 On
Right Engine.

Signature,

Robert A Wislick

Robert A. Wislick A/P 171549879

Date: 07-09-2010
Aircraft Reg: N399TC
Manufacture: Beech
Model No.: 58P Baron
Serial No.: TJ-294

Hobbs: 3283.5
ACTT:
ACTC:
TSO:
CSO:

erations
umber of
entries.)

6 MAR 12 N399TC Hobbs 3303.2
installed Two new G2S
Batteries G02713410 and
G02704934 in Act.
C. ~~W~~ Andy Apr 1920074

YEAR:

RECORDING
TACH
TIME

TODAYS
FLIGHT

TOTAL
TIME IN
SERVICE

DATE

American Aviation

Wilkes County Airport

Performed annual Inspection
To 58P Baron Inspection
(Normal & Emergency). F
13889). Replaced Nose V
(08125, 08231). Replace
Transducer (102-389012-
Continental SID 97-3E.

Checked ELT For Condition
(Oct-2011).

I certify that this aircraft has
has been determined to be
Signature, *Robert A*

07-09-2010 Hobbs: 3283.5
N399TC ACTT:
Beech ACTC:
58P Baron TSO:
TJ-294 CSO:

89012-11, Serial No 172388 On

Operations

Number of
entries.)

Robert A. Wislick A/P 171549879

N399TC Hobbs 3303.2
new G25
3410 and
in Act.
by AWP 1920074

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
				American Aviation Inc.
				Wilkes County Airport (UKF)
				Date: 10-28-2010 Hobbs: 3302.1 Aircraft Reg. N399TC ACTT: 4436.1 Manufacture: Beech ACTC: Model No.: 58P TSN: 444 Serial No.: TJ-294 CSN:
				Performed annual Inspection Per. FAR 43 Appendix "D" Scope & Detail, With Reference To 58P Baron Inspection Guide. Performed Retraction Check Of Landing Gear System (Normal & Emergency). Replaced RT Main Wheel Outboard Bearing Set (214-00100, 13889). Replaced Nose Wheel Assembly (40-87A), Tire (071-312-0), Bearing Sets (2) (08125, 08231). Replaced RT Main Tire (19.5x6.75). Installed New Fuel Flow Transducer (102-389012-11) Left Engine. Setup LT & Rt Engine Fuel Systems IAW Continental SID 97-3E.
				Checked ELT For Condition & Operation Per. FAR 91.207 Para. "d". Battery Due Date (Oct-2011).
				I certify that this aircraft has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition. Signature, <i>Robert A. Wislick</i> Robert A. Wislick IA 171549879

