

HARTZELL

PROPELLER LOGBOOK

AirMart.com
AIRCRAFT SALES & BROKERAGE

PROPELLER MODEL DHC-J34P-1RF/F7693DEFB

PROPELLER S/N FP3942B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE _____

Propeller Model AK-J37F-1RF/F7693DFB

High/Feather _____

Propeller S/N FP3942B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 K24033

No. 2 K24032

No. 3 K24047

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Aircraft Manufacturer Cirrus



Aircraft Model SR22

S/N 1568

Registration N411HZ

AirMart.com
AIRCRAFT SALES & BROKERAGE

Page 1

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
<p>LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC.  d/b/a MILLION AIR - RICHMOND</p>				
MANUFACTURER Hartzell		Reg #:	N411HZ	
Model:	PHC-J3YF-1RF	Date	9/24/2007	
S/N:	FP3942B	W.O.:	M070928	
TTP:	506.5	ACTT:	506.5	
PROPELLER LOGBOOK INSERT				
<p>The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.</p>				
<p>The Hartzell PHC-23YF-1RF S/N: FP3942B propeller was inspected I/A/W current maintenance rules of the Federal Aviation Regulation for a 100 hour inspection using the Cirrus Design SR22 current inspection guide and is approved for return to service.</p>				
<p>Signed:  Print: John T. Gardner Certificate # AP226987565IA for COMMONWEALTH AVIATION SERVICE, INC.</p>				

AirMart.com
AIRCRAFT SALES & BROKERAGE

DLK 2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 10750 15-August-2008 WO# 8447
N411HZ S/N 1568 CIRBUS SR22
HOBBS 586.1
TTPROP 586.1
AVIATION, INC.

Pg 1

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED PROPELLERS. I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

MAINTENANCE RELEASE.


THIS AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF THE FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE FOR WORK PERFORMED UNDER WO#8447 AT REPAIR STATION DK7R795J. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.


Signed DK7R795J FOR DLK AVIATION, INC.

L&M AIRCRAFT INC. ROME, GA 30165

N411HZ Hartzell PHC-J3YF-1RF s/n FP3942B September 4, 2009 Hobbs 628.2
Total Time 628.8 I certify that this propeller has been inspected IAW an annual inspection and was determined to be in an airworthy condition.

Larry A. Owen
A&P 2050165 IA



Page 2

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p align="center">L&M AIRCRAFT INC. ROME, GA 30165</p> <p>N411HZ Hartzell PHC-J3YF-1RF s/n FP3942B October 15, 2010 Hobbs 685.7 Total Time 685.7 I certify that this propeller has been inspected IAW an annual inspection and was determined to be in an airworthy condition. Larry A. Owen A&P 2050165 IA</p> <p align="right"><i>Larry A. Owen</i></p>
				<p align="center">L&M AIRCRAFT INC. ROME, GA 30165</p> <p>N411HZ Hartzell PHC-J3YF-1RF s/n FP3942B November 8, 2011 Hobbs 713.1 Total Time 713.1 Inspected prop and dressed leading edge. Serviced prop with grease. This propeller has been inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Alton P. Owen A&P 2922063 IA</p> <p align="right"><i>Alton P. Owen</i></p>

AirMart.com
AIRCRAFT SALES & BROKERAGE

SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022
205-426-7022
REPAIR STATION #S6PR302X

DISASSEMBLED, CLEANED & VISUALLY INSPECTED. REPAIRED AS NECESSARY.
DRESSED BLADES & PAINTED. REASSEMBLED & GREASED, SET ANGLES,
TRACKED AND BALANCED. THIS WAS THE ONLY WORK PERFORMED.

WORK ORDER # SR-11912
MODEL # PHC-J3YF-1RF
BLADE MODEL # F7693DFB
HUB SERIAL# FP3942B
DATE: 11/16/2017

J. M. Gaither
JAMES M GAITHER,
GENERAL MANAGER

				<p align="center">L&M AIRCRAFT INC. ROME, GA 30165</p> <p>N411HZ Hartzell PHC-J3YF-1RF s/n FP3942B December 1, 2017 Hobbs 713.1 Total Time 713.1 Prop installed after reseal by South Coast Propeller Service on work order SR-11912 dated November 16, 2017. Run checks and leak checks good. This propeller has been inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Larry A. Owen A&P 2050165 IA</p> <p align="right"><i>Larry A. Owen</i></p>

