



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
E680-170619 E1	REVIEW PW306C EMM REV 34.0				MTH		-			
E680-170619 E2	REVIEW PW306C EMM REV 34.0				MTH		-			
E680-221107 E1	REVIEW PW306C EMM REV 46.0				MTH		-			
E680-221107 E2	REVIEW PW306C EMM REV 46.0				MTH		-			
4-12-MC	INSPECTION DOCUMENT MC SZB				MTH 14-Apr-2025 HRS 2742.3 LDG 2088	23.7	400		3166	410.7
4-12-MD	INSPECTION DOCUMENT MD SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800			
21-31-01-7100	OUTFLOW VALVES, ALTITUDE LIMITER AND DELTA P LIMITER OPERATIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
21-61-00-7100	COCKPIT AND CABIN MANUAL TEMPERATURE CONTROL OPERATIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
32-00-00-7100	MAIN LANDING SYSTEM UPLOCK SWITCHES OPERATIONAL CHECK (AIRPLANES -0001 THRU -0500) SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
32-42-00-7201	EMERGENCY BRAKE SYSTEM FUNCTIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
35-20-00-7100	PASSENGER OXYGEN SYSTEM OPERATIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
35-20-00-7101	PASSENGER OXYGEN SYSTEM OPERATIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
35-20-00-7200	PASSENGER OXYGEN SYSTEM FUNCTIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
35-20-00-7201	PASSENGER OXYGEN SYSTEM FUNCTIONAL CHECK SZB				MTH 07-Jan-2021 HRS 2373 LDG 1745		800		3173	417.7
4-12-MF	INSPECTION DOCUMENT MF SZB				MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544		1600			
32-00-00-7200	LANDING GEAR EXTENSION AND RETRACTION SYSTEM FUNCTIONAL AND OPERATIONAL CHECK SZB				MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544		1600		3218	462.7
32-30-20-7100	LANDING GEAR CONTROL VALVE AND LANDING GEAR RETURN CHECK VALVE TEE FUNCTIONAL CHECK (AIRPLANES -0007 AND ON, AND AIRPLANES -0001 THRU -0006 INCORPORATING SB680-32-01) SZB				MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544		1600		3218	462.7



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-42-00-7100	ANTI-SKID CONTROLLER OPERATIONAL CHECK			MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544			1600		3218	462.7
32-50-00-7200	NOSE WHEEL STEERING FUNCTIONAL CHECK			MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544			1600		3218	462.7
4-12-MG	INSPECTION DOCUMENT MG SZB			MTH 10-Jan-2017 HRS 1618 LDG 1082 APUH 1602.6 APUS 1544			1600		3218	462.7
4-12-MH	INSPECTION DOCUMENT MH			MTH 01-Dec-2010 HRS 0			6450		6450	3694.7
4-12-MJ	INSPECTION DOCUMENT MJ SZB			MTH 28-Oct-2020 HRS 2352.1 LDG 1719		-7.1	1200		3545	789.7
4-12-MK	INSPECTION DOCUMENT MK			HRS			6000		6000	3244.7
4-12-ML	INSPECTION DOCUMENT ML			HRS			12900		12900	10144.7
4-12-MM	INSPECTION DOCUMENT MM			HRS			15000		15000	12244.7
4-12-MO	INSPECTION DOCUMENT MO			HRS			13500		13500	10744.7
4-12-MQ	INSPECTION DOCUMENT MQ			MTH 01-Dec-2010 HRS 0			7500		7500	4744.7
4-12-MR	INSPECTION DOCUMENT MR			HRS			12100		12100	9344.7
53-50-00-2105	TAILCONE SKINS AND SPLICES INSPECTION			MTH 01-Dec-2010 HRS 0			14200		14200	11444.7
53-30-00-2503	CABIN ENTRY DOOR SUPPORT STRUCTURE SKINS INSPECTION			MTH 01-Dec-2010 HRS 0			13700		13700	10944.7
4-12-MX	INSPECTION DOCUMENT MX			MTH 01-Dec-2010 HRS 0			16200		16200	13444.7
4-12-MY	INSPECTION DOCUMENT MY			MTH 01-Dec-2010 HRS 0			18100		18100	15344.7
4-12-MZ	INSPECTION DOCUMENT MZ			MTH 01-Dec-2010 HRS 0			19500		19500	16744.7
4-12-NC	INSPECTION DOCUMENT NC			MTH 01-Dec-2010 HRS 0			25000		25000	22244.7
4-12-NF	INSPECTION DOCUMENT NF			MTH 01-Dec-2010 HRS 0 LDG 0			11800			
57-10-00-2500 045707A	REAR SPAR LOWER SPLICE STRAP AREA (WS 26.30) EDDY CURRENT INSPECTION (AIRPLANES -0001 THRU -0500)			MTH 01-Dec-2010 HRS 0			11800		11800	9044.7
4-12-NH	INSPECTION DOCUMENT NH			MTH 01-Dec-2010 HRS 0			13400		13400	10644.7
53-30-00-2502	CABIN ENTRY DOOR SUPPORT STRUCTURE THRESHOLD INSPECTION			MTH 01-Dec-2010 HRS 0			13400		13400	10644.7
4-12-NJ	INSPECTION DOCUMENT NJ			MTH 01-Dec-2010 HRS 0			13550		13550	10794.7



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
4-12-NK	INSPECTION DOCUMENT NK			MTH	01-Dec-2010					
				HRS	0		13700		13700	10944.7
4-12-NM	INSPECTION DOCUMENT NM			MTH	01-Dec-2010					
				HRS	0		14200		14200	11444.7
4-12-NN	INSPECTION DOCUMENT NN			MTH	01-Dec-2010					
				HRS	0		14650		14650	11894.7
53-30-00-2501	CABIN ENTRY DOOR SUPPORT STRUCTURE LINTEL INSPECTION			MTH	01-Dec-2010					
				HRS	0		14650		14650	11894.7
4-12-NY	INSPECTION DOCUMENT NY			MTH	01-Dec-2010					
				HRS	0		25000		25000	22244.7
4-12-OC	INSPECTION DOCUMENT OC			MTH	01-Dec-2010					
				HRS	0		25000		25000	22244.7
4-12-OF	INSPECTION DOCUMENT OF 4-12-OF (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH	01-Dec-2010		N/A			
				HRS	0					
				LDG	0					
29-10-11-9600	9914673-12 AUXILIARY PUMP PRESSURE RELIEF HYDRAULIC MANIFOLD DISCARD (AIRPLANES -0001 THRU -0040)			MTH	01-Dec-2010		N/A			
				AEC45770						
				0327						
4-12-OG	INSPECTION DOCUMENT OG			MTH						
				HRS			25000		25000	22244.7
050016	BIRD NEST INSPECTION RH & LH ELEVATOR			MTH	02-Apr-2025		3		31-Jul-2025	1 m 21 d
	SZB			HRS	2742.3					
				LDG	2088					
050030	INSPECTION -AILERON POSITION SENSOR, ITS ATTACHMENT BRACKETS AND SURROUNDING STRUCTURE (RH WING ACCESS PANEL 660AB)			MTH	03-Apr-2025		12		30-Apr-2026	10 m 20 d
	SZB			HRS	2742.3					
				LDG	2088					
050050	INSPECT THE FUEL TANK EVERY 24 MONTHS FOR MICROBIAL GROWTH AND CORROSION			MTH	31-May-2024		24		31-May-2026	11 m 21 d
	SZB			HRS	2706.5					
				LDG	2037					
052020	INSPECT RVSM AGHM FLIGHT			MTH	07-Jan-2025		24		31-Jan-2027	19 m 21 d
	SZB			HRS	2725.6		1000		3725.6	970.3
				LDG	2061					
055001	ACCOMPLISH CHECK HARD OR OVERWEIGHT LANDINGS			MTH	01-Dec-2010		A/R			
055002	ACCOMPLISH CHECK AIRPLANE OVERSPEED EXCEEDING PLACARD SPEED LIMITS OR FLAPS AND/OR LANDING GEAR/ OR EXCEEDING DESIGN SPEEDS			MTH	01-Dec-2010		A/R			
055003	ACCOMPLISH CHECK DANGEROUS AIR TURBULENCE OR UNAPPROVED MANEUVERS			MTH	01-Dec-2010		A/R			
055004	ACCOMPLISH CHECK ACCIDENTAL THRUST REVERSER DEPLOYMENT			MTH	01-Dec-2010		A/R			
055006	ACCOMPLISH CHECK FOREIGN OBJECT DAMAGE			MTH	01-Dec-2010		A/R			
055008	LANDING GEAR TIRE BURST CHECKS			MTH	01-Dec-2010		A/R			
055009	ACCOMPLISH CHECK ENGINE AND/OR AUXILLARY POWER UNIT FIRE EXTINGUISHER ACCIDENTAL DISCHARGE			MTH	01-Dec-2010		A/R			
055033	ACCOMPLISH CHECK LIGHTNING STRIKE			MTH	01-Dec-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-01	INSPECTION DOCUMENT 1 SZB			MTH HRS LDG	25-Oct-2024 2725.6 2061	-53	12		30-Sep-2025	3 m 20 d
5-12-02	INSPECTION DOCUMENT 2 SZB			MTH HRS LDG	02-Feb-2021 2384.1 1753		800		3184.1	428.8
5-12-03	INSPECTION DOCUMENT 3 SZB			MTH HRS LDG	27-Jan-2025 2725.6 2061	-50	24		31-Dec-2026	18 m 21 d
5-12-04	INSPECTION DOCUMENT 4			MTH HRS			1600		3164	408.7
5-12-05	INSPECTION DOCUMENT 5 SZB			MTH HRS LDG	07-Feb-2023 2575 1904	-28	36		31-Jan-2026	7 m 21 d
5-12-06	INSPECTION DOCUMENT 6 SZB			MTH HRS LDG	31-Dec-2022 2558.4 1888	-57	48		30-Nov-2026	17 m 20 d
5-12-07	INSPECTION DOCUMENT 7 SZB			MTH HRS LDG	20-Feb-2025 2732 2071	1	24 800		28-Feb-2027 3532	20 m 18 d 776.7
5-12-08	INSPECTION DOCUMENT 8			MTH HRS LDG	04-Nov-2014 1145 706		2400		3545	789.7
5-12-09	INSPECTION DOCUMENT 9 SZB			MTH HRS LDG	13-May-2024 2706.5 2037	-3	24 1600		31-May-2026 4306.5	11 m 21 d 1551.2
5-12-10	INSPECTION DOCUMENT 10 SZB			MTH HRS LDG	19-Jun-2022 2467.8 1814		48 1600		30-Jun-2026 4067.8	12 m 20 d 1312.5
5-12-11	INSPECTION DOCUMENT 11 SZB			MTH HRS LDG	19-Dec-2024 2724 2059	-86	24		30-Sep-2026	15 m 20 d
5-12-12	INSPECTION DOCUMENT 12 SZB			MTH HRS LDG	10-Feb-2023 2575 1904	-98	48 3200		30-Nov-2026 5775	17 m 20 d 3019.7
5-12-13	INSPECTION DOCUMENT 13 SZB			MTH HRS LDG	31-Dec-2022 2558.4 1888	-36	72		30-Nov-2028	41 m 20 d
5-12-14	INSPECTION DOCUMENT 14 SZB			MTH HRS LDG APUH	14-Aug-2024 2724 2059 2553	8	48 1600		31-Aug-2028 4153	38 m 21 d 1520.8
5-12-15	INSPECTION DOCUMENT 15 (AIRPLANES -0001 THRU -0545) SZB			MTH HRS LDG	24-Mar-2025 2735.6 2077	-22	6		30-Sep-2025	3 m 20 d
5-12-16	INSPECTION DOCUMENT 16 SZB			MTH HRS LDG	19-Dec-2018 1986 1390	-18	96		31-Dec-2026	18 m 21 d
5-12-17	INSPECTION DOCUMENT 17			HRS			5600			
27-12-00-9600	6960231-7, 6960231-9, OR 6960231-11 ROLL SPOILER MIXER BOX ASSEMBLY RESTORATION			6960231-7 309	MTH HRS	01-Dec-2010 0	5600		5600	2844.7
5-12-18	INSPECTION DOCUMENT 18 SZB			MTH HRS LDG	12-Jul-2018 1884 1306		96 6400		31-Jul-2026 8284	13 m 21 d 5528.7
5-12-19	INSPECTION DOCUMENT 19 SZB			MTH HRS LDG	03-Jan-2023 2558.4 1888	-33	144		31-Dec-2034	114 m 21 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-20	INSPECTION DOCUMENT 20	SZB			MTH 06-May-2025 HRS 2746.6 LDG 2091		12 150		31-May-2026 2896.6	11 m 21 d 141.3
24-31-00-7200 LEFT	LEFT MARATHON NI-CAD BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK	SZB		9914058-6 12201581	MTH 06-May-2025 HRS 2746.6 LDG 2091		12 150		31-May-2026 2896.6	11 m 21 d 141.3
24-31-00-7200 RIGHT	RIGHT MARATHON NI-CAD BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK	SZB		9914058-6 12201582	MTH 06-May-2025 HRS 2746.6 LDG 2091		12 150		31-May-2026 2896.6	11 m 21 d 141.3
5-12-25	INSPECTION DOCUMENT 25				MTH 01-Dec-2010 HRS 0					
055150 E1	FUEL CONTAMINATION WITH DEF (DIESEL EXHAUST FLUID)				MTH		A/R			
055150 E2	FUEL CONTAMINATION WITH DEF (DIESEL EXHAUST FLUID)				MTH		A/R			
055155 E1	AC GENERATOR FAIL INDICATION				MTH 01-Dec-2010		A/R			
055155 E2	AC GENERATOR FAIL INDICATION				MTH 01-Dec-2010		A/R			
057101 E1	MINOR INSPECTION	SZB			MTH 29-Apr-2020 HRS 2249.27 LDG 1628		800		(3049.27)3049.27	293.97
057101 E2	MINOR INSPECTION	SZB			MTH 29-Apr-2020 HRS 2249.27 LDG 1628		800		(3049.27)3049.27	293.97
057120 E1	INSPECTION LOW UTILIZATION	SZB			MTH 10-Jan-2025 HRS 2725.6 LDG 2061		24		31-Jan-2027	19 m 21 d
057120 E2	INSPECTION LOW UTILIZATION	SZB			MTH 10-Jan-2025 HRS 2725.6 LDG 2061		24		31-Jan-2027	19 m 21 d
499000	OIL PHYSICAL LEVEL CHECK	SZB			APUH 06-May-2025 APUS 2613.1 3102		4		30-Sep-2025	3 m 20 d
12-26-00-6001	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH						A/R			
12-26-00-6002	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH						A/R			
12-26-00-6003	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH						A/R			
24-32-00-9600 STANDBY	100-2410-04 SECURAPLANE STANDBY BATTERY DISCARD	SZB		100-2410-04 1194489	MTH 19-Feb-2024 HRS 2683 LDG 2011		48	1	31-Jan-2028	31 m 21 d
25-60-00-2201	KANNAD EMERGENCY LOCATOR TRANSMITTER (ELT) DETAILED INSPECTION AND OPERATIONAL CHECK (AIRPLANES -0001 THRU -0324)	SZB		S1821502-02 2620493-0036	MTH 08-Jan-2025 HRS 2725.6 LDG 2061	-26	12		31-Dec-2025	6 m 21 d
256021	FIRE CONTAINMENT BAG ANNUAL INSPECTION	SZB			MTH 08-Jan-2025 HRS 2725.6 LDG 2061		12		31-Jan-2026	7 m 21 d



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
26-20-00-7100 AFT	ENGINE FIRE BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK - AFT	SZB		30700009-12 C8372D1	MTH 07-Feb-2025 HRS 2732 LDG 2071		60		28-Feb-2030	56 m 18 d
26-20-00-7100 FORWARD	ENGINE FIRE BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK - FORWARD	SZB		30700009-12 85057D1	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		60		31-Jan-2030	55 m 21 d
26-20-00-9600.1 AFT/FWD	AFT ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD FWD SQUIB (SERVICE LIFE)	SZB		30903824-1 ESD23M356-001	MTH 07-Feb-2025 HRS 2732 LDG 2071		72		28-Feb-2031	68 m 18 d
26-20-00-9600.1 AFT REAR	AFT ENGINE BOTTLE CARTRIDGE SQUIB DISCARD AFT SQUIB (SERVICE LIFE)	SZB		30903824-1 ESD23M356-001	MTH 07-Feb-2025 HRS 2732 LDG 2071		72		28-Feb-2031	68 m 18 d
26-20-00-9600.1 FORWARD/AFT	FWD ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD AFT SQUIB (SERVICE LIFE)	SZB		30903824-1 ESD23M356-001	MTH 05-Jun-2024 HRS 2709.2 LDG 2041		72		30-Jun-2030	60 m 20 d
26-20-00-9600.1 FORWARD/FORWARD	FWD ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD FWD SQUIB (SERVICE LIFE)	SZB		30903824-1 ESD23M356-001	MTH 05-Jun-2024 HRS 2709.2 LDG 2041		72		30-Jun-2030	60 m 20 d
26-20-00-9601 AFT	FUNCTIONAL CHECK ENGINE FIRE BOTTLE (HYDROSTATIC)	SZB		30700009-12 C8372D1	MTH 07-Feb-2025 HRS 2732 LDG 2071		60		30-Nov-2029	53 m 20 d
Hydro Check Date: 13-Nov-2024										
26-20-00-9601 FORWARD	FUNCTIONAL CHECK ENGINE FIRE BOTTLE (HYDROSTATIC)	SZB		30700009-12 85057D1	MTH 25-Mar-2024 HRS 2709.2 LDG 2041		60		31-Mar-2029	45 m 21 d
Hydro Check Date: 25-Mar-2024										
26-20-20-7500 CABIN	RESTORATION PORTABLE FIRE EXTINGUISHER	SZB		C352CS F-75057071	MTH 22-Aug-2019 HRS 2109 LDG 1509		72		31-Aug-2025	2 m 21 d
26-20-20-7500 COCKPIT	RESTORATION PORTABLE FIRE EXTINGUISHER	SZB		C352CS I-33915949	MTH 08-Jan-2025 HRS 2725.6 LDG 2061		72		31-Jan-2031	67 m 21 d
26-20-20-9600 CABIN	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER	SZB		C352CS F-75057071	MTH 16-Aug-2019		144		31-Aug-2031	74 m 21 d
Hydro Check Date: 16-Aug-2019										
26-20-20-9600 COCKPIT	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER	SZB		C352CS I-33915949	MTH 08-Jan-2025 HRS 2725.6 LDG 2061		144		31-Dec-2036	138 m 21 d
Hydro Check Date: 27-Dec-2024										
26-20-30-9600.1 APU	REPLACE APU FIRE BOTTLE FIRE EXT SQUIB (SERVICE LIFE)	SZB		30903943 0454YL	MTH 06-May-2024 HRS 2706.5 LDG 2037		120		31-May-2034	107 m 21 d
26-20-30-9600.1 COMBO	REPLACE COMBO APU FIRE BOTTLE BAG FIRE EXT SQUIB (SERVICE LIFE)	SZB		30903937 0547YL	MTH 06-May-2024 HRS 2706.5 LDG 2037		120		31-May-2034	107 m 21 d
26-20-30-9600.1 LOWER	REPLACE LOWER NOSE COMPARTMENT FIRE BOTTLE FIRE EXT SQUIB (SERVICE LIFE)	SZB		30903937 1911DD	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		120		31-Jan-2035	115 m 21 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
26-20-30-9600.1 UPPER FWD	REPLACE UPPER FORWARD NOSE COMPARTMENT FIRE BOTTLE FIRE EXT SQUIB (SERVICE LIFE)	SZB		30903938 2574DC	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		120		31-Jan-2035	115 m 21 d
26-20-30-9601 APU	RESTORATION FIRE BOTTLE (HYDROSTATIC TEST) AUXILIARY POWER UNIT/BAGGAGE FIRE BOTTLE	SZB		33100328-2 80274B1	MTH 10-Mar-2024 HRS 2706.5 LDG 2037		60		31-Mar-2029	45 m 21 d
Hydro Check Date: 10-Mar-2024										
26-20-30-9602 NOSE COMPARTMENT	RESTORATION BAGGAGE (UN002) FIRE BOTTLE (HYDROSTATIC TEST)	SZB		34750005-1 10923H1	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		60		31-Jan-2030	55 m 21 d
Hydro Check Date: 01-Jan-2025										
261010 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - SENSOR, FIRE AND OVERHEAT			30B5702-01 133542	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
261010 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - SENSOR, FIRE AND OVERHEAT			30B5702-01 133886	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
28-00-10-2200	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 01-Dec-2010		A/R			
28-00-10-2201	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)	SZB			MTH 06-Jul-2021 HRS 2401.5 LDG 1767		A/R			
32-10-00-9600 LEFT	LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD			6941020-1 EMI317	MTH LDG		14950		14950	12847
32-10-00-9600 RIGHT	RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD			6941020-2 EMI335	MTH LDG		14950		14950	12847
32-10-00-9601 LEFT	LEFT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD			6941030-2 561	MTH LDG		14950		14950	12847
32-10-00-9601 RIGHT	RIGHT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD			6941030-2 564	MTH LDG		14950		14950	12847
32-10-00-9602 LEFT	LEFT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD			6941031-2 562	MTH LDG		14950		14950	12847
32-10-00-9602 RIGHT	RIGHT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD			6941031-2 565	MTH LDG		14950		14950	12847
32-10-00-9603 LEFT	LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD			6941050-3 157	MTH 10-Feb-2023 HRS 2575 LDG 1904		12000	1072	12832	10729
32-10-00-9603 RIGHT	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD			6941050-3 152	MTH 10-Feb-2023 HRS 2575 LDG 1904		12000	1880	12024	9921
32-10-00-9604 LEFT	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			2-8126-2 0652	MTH 01-Dec-2010 LDG 0		12000		12000	9897
32-10-00-9604 RIGHT	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			2-8126-2 0546	MTH 01-Dec-2010 LDG 0		12000		12014	9911
32-20-00-9600 NOSE	NOSE LANDING GEAR ASSEMBLY DISCARD			6994004-1 23	MTH 01-Dec-2010 LDG 0		20000		20000	17897

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
32-20-00-9601 NOSE	NOSE LANDING GEAR ACTUATOR DISCARD			2-8172-3 0328	MTH 01-Dec-2010 LDG 0		20000		21044	18941
32-30-70-9600 LANDING GEAR	EMERGENCY GEAR EXTENSION PNEUMATIC STORAGE BOTTLE (HYDROSTATIC) RESTORATION	SZB		40005369-2 8330	MTH 01-Apr-2024 HRS 2712 LDG 2046		36		30-Apr-2027	22 m 20 d
Hydro Check Date: 01-Apr-2024										
32-41-00-2200 LEFT INBOARD	LEFT INBOARD MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	SZB			MTH 25-Sep-2023 HRS 2647.2 LDG 1983		24 T/C		30-Sep-2025	3 m 20 d
32-41-00-2200 LEFT OUTBOARD	LEFT OUTBOARD MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	SZB			MTH 19-Nov-2023 HRS 2663.2 LDG 1995		24 T/C		30-Nov-2025	5 m 20 d
32-41-00-2200 RIGHT INBOARD	RIGHT INBOARD MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	SZB			MTH 25-Sep-2023 HRS 2647.2 LDG 1983	-23	24 T/C		30-Sep-2025	3 m 20 d
32-41-00-2200 RIGHT OUTBOARD	RIGHT OUTBOARD MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	SZB			MTH 13-Dec-2023 HRS 2673.9 LDG 2002		24 T/C		31-Dec-2025	6 m 21 d
32-41-00-2800 LEFT	LEFT NOSE LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1538-1 1919	MTH 23-Jan-2019 HRS 2013 LDG 1419		T/C			
32-41-00-2800 RIGHT	RIGHT NOSE LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1538-1 1921	MTH 23-Jan-2019 HRS 2013 LDG 1419		T/C			
32-41-00-2801 LEFT INBOARD	LEFT INBOARD MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1621 2412	MTH 28-Mar-2019 HRS 2063 LDG 1463		T/C			
32-41-00-2801 LEFT OUTBOARD	LEFT OUTBOARD MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1621 2439	MTH 23-May-2018 HRS 1907 LDG 1322		T/C			
32-41-00-2801 RIGHT INBOARD	RIGHT INBOARD MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1621 2141	MTH 10-Jan-2019 HRS 2013 LDG 1419		T/C			
32-41-00-2801 RIGHT OUTBOARD	RIGHT OUTBOARD MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDT)	SZB		3-1621 2454	MTH 16-May-2018 HRS 1840 LDG 1265		T/C			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-42-00-2200 LEFT INBD	LEFT INBOARD BRAKE ASSEMBLIES (WEAR PIN) DETAILED INSPECTION	SZB			MTH 17-Aug-2017 HRS 1739 LDG 1175 APUH 1715.6 APUS 1707		WHL/C WHL/C WHL/C WHL/C WHL/C WHL/C			
32-42-00-2200 LEFT OUTBOARD	LEFT OUTBOARD BRAKE ASSEMBLIES (WEAR PIN) DETAILED INSPECTION				MTH 01-Dec-2010		WHL/C WHL/C			
32-42-00-2200 RIGHT INBOARD	RIGHT INBOARD BRAKE ASSEMBLIES (WEAR PIN) DETAILED INSPECTION				MTH 01-Dec-2010		WHL/C WHL/C			
32-42-00-2200 RIGHT OUTBOARD	RIGHT OUTBOARD BRAKE ASSEMBLIES (WEAR PIN) DETAILED INSPECTION				MTH 01-Dec-2010		WHL/C WHL/C			
32-43-00-9600	EMERGENCY BRAKE PNEUMATIC BOTTLE(HYDROSTATIC) RESTORATION	SZB		40005370-1 9504	MTH 31-Jan-2024 HRS 2712 LDG 2046		36		31-Jan-2027	19 m 21 d
Hydro Check Date: 31-Jan-2024										
323010	INSPECTION FOR INTERNAL LEAKAGE ON ALL 4 BRAKE SHUTTLE VALVE ASSEMBLIES (REFERENCE: GOODRICH CORPORATION CMM PART NUMBER 2 -1675 32-45-52 PG. 1005)	SZB			MTH 08-Apr-2025 HRS 2742.3 LDG 2088		6		08-Oct-2025	3 m 28 d
33-50-00-9600 NO. 1	NO. 1 EMERGENCY LIGHTING BATTERY PACK RESTORATION	SZB		CBS28-1 1733M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		24		31-Mar-2027	21 m 21 d
33-50-00-9600 NO. 2	NO. 2 EMERGENCY LIGHTING BATTERY PACK RESTORATION	SZB		CBS28-1 3685M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		24		31-Mar-2027	21 m 21 d
33-50-00-9600 NO. 3	NO. 3 EMERGENCY LIGHTING BATTERY PACK RESTORATION	SZB		CBS28-1 3777M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		24		31-Mar-2027	21 m 21 d
33-50-00-9600 NO. 4	NO. 4 EMERGENCY LIGHTING BATTERY PACK RESTORATION	SZB		CBS28-1 4057M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		24		31-Mar-2027	21 m 21 d
34-11-00-7200 NO. 1	CALIBRATION TEST AIR DATA MODULE (FAR 91.411)	WSSL		HG1153CA04 11084889	MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-11	24		31-Dec-2026	18 m 21 d
Calibration Date: 27-Dec-2024										
34-11-00-7200 NO. 2	CALIBRATION TEST AIR DATA MODULE (FAR 91.411)	WSSL		HG1153CA04 10054260	MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-11	24		31-Dec-2026	18 m 21 d
Calibration Date: 27-Dec-2024										
34-11-00-7200 RVSM	FUNCTIONAL CHECK PITOT STATIC SYSTEM (FAR 91.411)	WSSL			MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-11	24		31-Dec-2026	18 m 21 d
34-11-00-7200 STANDBY	CALIBRATION TEST AIR DATA MODULE (FAR 91.411)	WSSL		501-1881-05 2471	MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-11	24		31-Dec-2026	18 m 21 d
Calibration Date: 27-Dec-2024										
34-53-00-7200 NO. 1	FUNCTIONAL CHECK HONEYWELL XS-857A/858B TRANSPONDER SYSTEM (FAR 91.413) (AIRPLANES -0001 THRU -0500)	WSSL			MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-11	24		31-Dec-2026	18 m 21 d
Calibration Date: 27-Dec-2024										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
34-53-00-7200 NO. 2	FUNCTIONAL CHECK HONEYWELL XS-857A/858B TRANSPONDER SYSTEM (FAR 91.413) (AIRPLANES -0001 THRU -0500)	WSSL			MTH 27-Dec-2024 HRS 2724.8 LDG 2060	-23	24		31-Dec-2026	18 m 21 d
Calibration Date: 27-Dec-2024										
35-00-20-9601 LEFT	EXTENDED RANGE OXYGEN BOTTLE(HYDROSTATIC) RESTORATION	SZB		804822-14 C130702223B	MTH 31-Oct-2023		60		31-Oct-2028	40 m 21 d
Hydro Check Date: 31-Oct-2023										
35-00-30-9601 RIGHT	STANDARD OXYGEN BOTTLE (HYDROSTATIC) RESTORATION	SZB		804822-14 C11060410	MTH 31-Oct-2023		60		31-Oct-2028	40 m 21 d
Hydro Check Date: 31-Oct-2023										
35-00-30-9602	EMERGENCY OXYGEN BOTTLE (HYDROSTATIC) RESTORATION	SZB		5500-M6W-FF23AN P20081199	MTH 06-Jun-2025 HRS 2755.3 LDG 2103		60		28-Feb-2030	56 m 18 d
Hydro Check Date: 01-Feb-2025										
35-10-00-9600 COPILOT	CREW OXYGEN MASK (ELASTOMER PARTS DETAILED INSPECTION AND REGULATOR FUNCTIONAL CHECK) RESTORATION - COPILOT	SZB		MLC20-505 122244	MTH 31-Oct-2022 HRS 2531.7 LDG 1867		72		31-Oct-2028	40 m 21 d
35-10-00-9600 PILOT	PILOT MC10 OR MLD20 SERIES CREWOXYGEN MASK (ELASTOMER PARTSDETAILED INSPECTION AND REGULATORFUNCTIONAL CHECK)	SZB		MLC20-505 B117572	MTH 31-Oct-2022 HRS 2531.7 LDG 1867		72		31-Oct-2028	40 m 21 d
A353000	PORTABLE EMER OXYGEN BOTTLE -- PORTABLE EMER OXYGEN BOTTLE HYDROSTATIC TEST			9914067-47 P19043251	MTH 07-Mar-2024 HRS 2692 LDG 2020		60	4	30-Nov-2028	41 m 20 d
49-00-00-2100	AUXILIARY POWER UNIT GENERAL VISUAL INSPECTION	SZB			MTH 15-Jul-2024 HRS 2712 LDG 2046 APUH 2528.8	-7	24		31-Jul-2026	13 m 21 d
490019	REMOVE IGNITER PLUG CLEAN, EXAMINE AND INSTALL	SZB		304634-2 N/A	APUH 22-Jul-2024 APUS 2528.8 3019		24	900	31-Jul-2026 3428.8	13 m 21 d 796.6
499010	INSPECT MAGNETIC CHIP DETECTOR	SZB			APUH 22-Jul-2024 APUS 2528.8 3019		12	450	31-Jul-2025 2978.8	1 m 21 d 346.6
499030	DRAIN AND DISCARD APU OIL	SZB			APUH 22-Jul-2024 APUS 2528.8 3019	-21	24	900	31-Jul-2026 3428.8	13 m 21 d 796.6
499040	OIL AND FILTER SERVICING	SZB			APUH 22-Jul-2024 APUS 2528.8 3019	-21	24	900	31-Jul-2026 3428.8	13 m 21 d 796.6
499050	REMOVE AND REPLACE FUEL FILTER ELEMENT	SZB			APUH 15-Jul-2024 APUS 2528.8 3019		24	900	31-Jul-2026 3428.8	13 m 21 d 796.6
499110	SOAP CHECK OIL				01-Dec-2010		O/C			
53-10-00-9600 LEFT	LEFT NOSE LANDING GEAR TRUNNION ATTACH SUPPORT ASSEMBLY DISCARD			6913052-2 306	MTH 01-Dec-2010 LDG 0			20000	20000	17897
53-10-00-9600 RIGHT	RIGHT NOSE LANDING GEAR TRUNNION ATTACH SUPPORT ASSEMBLY DISCARD			6913052-2 306	MTH 01-Dec-2010 LDG 0			20000	20000	17897
53-10-00-9601	NOSE LANDING GEAR ACTUATOR FITTING ASSEMBLY DISCARD			6711060-49 306	MTH LDG			20000	20000	17897

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
57-00-00-9600 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR SIDE BRACE FITTING ASSEMBLY DISCARD			6922428-1 306	MTH 01-Dec-2010 LDG 0		21600		21600	19497
57-00-00-9600 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR SIDE BRACE FITTING ASSEMBLY DISCARD			6922428-2 306	MTH 01-Dec-2010 LDG 0		21600		21600	19497
57-20-00-9600 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR REAR SPAR TRUNNION SUPPORT DISCARD			6922439-1 306	MTH 01-Dec-2010 LDG 0		12000		12000	9897
57-20-00-9600 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR REAR SPAR TRUNNION SUPPORT DISCARD			6922439-2 306	MTH 01-Dec-2010 LDG 0		12000		12000	9897
57-20-00-9601 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR CENTER SPAR TRUNNION FITTING DISCARD			6922429-1 306	MTH 01-Dec-2010 LDG 0		12000		12000	9897
57-20-00-9601 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR CENTER SPAR TRUNNION FITTING DISCARD			6922429-2 306	MTH 01-Dec-2010 LDG 0		12000		12000	9897
710000 E1	COMPRESSOR DESALINATION WASH				MTH 01-Dec-2010		A/R			
710000 E2	COMPRESSOR DESALINATION WASH				MTH 01-Dec-2010		A/R			
710005 E1	COMPRESSOR PERFORMANCE RECOVERY WASH				MTH 01-Dec-2010		A/R			
710005 E2	COMPRESSOR PERFORMANCE RECOVERY WASH SZB				MTH 10-Jan-2025 HRS 2725.6 LDG 2061		A/R			
720025 E1	OVERHAUL ENGINE				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
720025 E2	OVERHAUL ENGINE				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
720030 E1	HOT SECTION INSPECTION				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720030 E2	HOT SECTION INSPECTION				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720071 E1	BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES 30B6501-01 -				MTH 01-Dec-2010 HRS 0 LDG 0		3000 3000		(3000)3000 (3000)3000	244.7 897
720071 E2	BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES 30B6501-01 -				MTH 01-Dec-2010 HRS 0 LDG 0		3000 3000		(3000)3000 (3000)3000	244.7 897
720076 E1	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE HP TURBINE BLADE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720076 E2	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE HP TURBINE BLADE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720115 E1	SPECIAL DETAILED INSPECTION - ENGINE COMBUSTION COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE TURBINE VANE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720115 E2	SPECIAL DETAILED INSPECTION - ENGINE COMBUSTION COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE TURBINE VANE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
720120 E1	BORESCOPE FIRST-STAGE HP TURBINE VANE				MTH 01-Dec-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720120 E2	BOREScope FIRST-STAGE HP TURBINE VANE		MTH	01-Dec-2010		A/R			
720125 E1	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE HP TURBINE SHROUD SEGMENT		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720125 E2	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF FIRST-STAGE HP TURBINE SHROUD SEGMENT		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720130 E1	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE SHROUD SEGMENT		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720130 E2	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE SHROUD SEGMENT		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720135 E1	BOREScope INSPECTION SECOND-STAGE HP TURBINE BLADES WITH SPECIAL ATTENTION TO INSIDE OF THE COOLING HOLES		MTH	01-Dec-2010					
			HRS	0		4000		(4000)4000	1244.7
			LDG	0		4000		(4000)4000	1897
720135 E2	BOREScope INSPECTION SECOND-STAGE HP TURBINE BLADES WITH SPECIAL ATTENTION TO INSIDE OF THE COOLING HOLES		MTH	01-Dec-2010					
			HRS	0		4000		(4000)4000	1244.7
			LDG	0		4000		(4000)4000	1897
720136 E1	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE VANE		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720136 E2	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE VANE		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720140 E1	BOREScope THIRD-STAGE LP TURBINE VANE		MTH	01-Dec-2010		A/R			
720140 E2	BOREScope THIRD-STAGE LP TURBINE VANE		MTH	01-Dec-2010		A/R			
720145 E1	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE BLADE		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720145 E2	SPECIAL DETAILED INSPECTION - ENGINE HP TURBINE COMPONENTS - DO A BORESCOPE INSPECTION OF SECOND-STAGE HP TURBINE BLADE		MTH	01-Dec-2010					
			HRS	0		3000		(3000)3000	244.7
720150 E1	BOREScope THIRD-STAGE LP TURBINE BLADES		MTH	01-Dec-2010		A/R			
720150 E2	BOREScope THIRD-STAGE LP TURBINE BLADES		MTH	01-Dec-2010		A/R			
720160 E1	BOREScope FIFTH-STAGE LP TURBINE BLADES		MTH	01-Dec-2010		A/R			
720160 E2	BOREScope FIFTH-STAGE LP TURBINE BLADES		MTH	01-Dec-2010		A/R			
720170 E1	BOREScope FIFTH-STAGE LP TURBINE VANE		MTH	01-Dec-2010		A/R			
720170 E2	BOREScope FIFTH-STAGE LP TURBINE VANE		MTH	01-Dec-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720180 E1	BOREScope INSPECTION HP TURBINE L SEAL HP TURBINE L SEAL			PN SN-UNKNOWN	MTH 01-Dec-2010		A/R			
720180 E2	BOREScope INSPECTION HP TURBINE L SEAL HP TURBINE L SEAL			PN SN-UNKNOWN	MTH 01-Dec-2010		A/R			
721045 E1	REGULAR OPERATION AS ALTERNATE TO PRESERVATION OF INACTIVE ENGINES			MTH	01-Dec-2010		A/R			
721045 E2	REGULAR OPERATION AS ALTERNATE TO PRESERVATION OF INACTIVE ENGINES			MTH	01-Dec-2010		A/R			
724020 E1	SPECIAL DETAILED INSPECTION - ENGINE COMBUSTION COMPONENTS - DO A BORESCOPE INSPECTION OF COMBUSTION CHAMBER			MTH HRS 0	01-Dec-2010		3000		(3000)3000	244.7
724020 E2	SPECIAL DETAILED INSPECTION - ENGINE COMBUSTION COMPONENTS - DO A BORESCOPE INSPECTION OF COMBUSTION CHAMBER			MTH HRS 0	01-Dec-2010		3000		(3000)3000	244.7
724030 E1	BOREScope COMBUSTION CHAMBER LINER			MTH	01-Dec-2010		A/R			
724030 E2	BOREScope COMBUSTION CHAMBER LINER			MTH	01-Dec-2010		A/R			
726020 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - AC GENERATOR (PMA)			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
726020 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - AC GENERATOR (PMA)			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
057310 E1	FUEL FILTER BYPASS SWITCH-OIL CONTAMINATION INSPECTION FUEL FILTER IMPENDING BYPASS SWITCH (PN: 30B3500-02)	SZB		MTH HRS 2746.6 LDG 2091	07-May-2025		1		30-Jun-2025	20 d
057310 E2	FUEL FILTER BYPASS SWITCH-OIL CONTAMINATION INSPECTION FUEL FILTER IMPENDING BYPASS SWITCH (PN: 30B3500-02)	SZB		MTH HRS 2746.6 LDG 2091	07-May-2025		1		30-Jun-2025	20 d
731005 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - FUEL START VALVE			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
731005 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - FUEL START VALVE			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
731006 E1	OVERHAUL - FUEL NOZZLE			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
731006 E2	OVERHAUL - FUEL NOZZLE			MTH HRS 0	01-Dec-2010		6000		(6000)6000	3244.7
731007 E1	OVERHAUL - VALVE FUEL SHUTOFF			PN SN-UNKNOWN	MTH HRS 0		6000		(6000)6000	3244.7
731007 E2	OVERHAUL - VALVE FUEL SHUTOFF			PN SN-UNKNOWN	MTH HRS 0		6000		(6000)6000	3244.7
731009 E1	OVERHAUL/DISCARD - FUEL PUMP			PN SN-UNKNOWN	MTH HRS 0		6000		(6000)6000	3244.7
731009 E2	OVERHAUL/DISCARD - FUEL PUMP			PN SN-UNKNOWN	MTH HRS 0		6000		(6000)6000	3244.7
731015 E1	GENERAL VISUAL INSPECTION - FUEL FILTER - REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE	SZB		31B3702-01 N/A	MTH HRS 2725.6 LDG 2061		800		(3525.6)3525.6	770.3

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731015 E2	GENERAL VISUAL INSPECTION - FUEL FILTER - REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE	SZB		31B3702-01 N/A	MTH 10-Jan-2025 HRS 2725.6 LDG 2061		800		(3525.6)3525.6	770.3
731020 E1	GENERAL VISUAL INSPECTION - EMERGENCY FSOV LINKAGE - EXAMINE THE LINKAGE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
731020 E2	GENERAL VISUAL INSPECTION - EMERGENCY FSOV LINKAGE - EXAMINE THE LINKAGE				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
731021 E1	EMERGENCY FSOV ASSEMBLY - DO THE RIGGING PROCEDURE				MTH HRS		3000		(3000)3000	244.7
731021 E2	EMERGENCY FSOV ASSEMBLY - DO THE RIGGING PROCEDURE				MTH HRS		3000		(3000)3000	244.7
731022 E1	EMERGENCY FSOV ASSEMBLY - DO THE DIMENSIONAL INSPECTION				MTH HRS		3000		(3000)3000	244.7
731022 E2	EMERGENCY FSOV ASSEMBLY - DO THE DIMENSIONAL INSPECTION				MTH HRS		3000		(3000)3000	244.7
731025 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - FUEL FILTER BYPASS SWITCH			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
731025 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - FUEL FILTER BYPASS SWITCH			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
731030 E1	CLEAN/INSPECT PRIMARY FUEL NOZZLES				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
731030 E2	CLEAN/INSPECT PRIMARY FUEL NOZZLES				MTH 01-Dec-2010 HRS 0		3000		(3000)3000	244.7
731040 E1	BORESCOPE FUEL NOZZLES				MTH 01-Dec-2010		A/R			
731040 E2	BORESCOPE FUEL NOZZLES				MTH 01-Dec-2010		A/R			
732007 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - EEC			822822-4-005 07115289	MTH 22-Dec-2022 HRS 2548.3 LDG 1881		6000	2548.3	(6000)6000	3244.7
732007 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - EEC			822822-4-005 10050016	MTH 22-Dec-2022 HRS 2548.3 LDG 1881		6000	2548.3	(6000)6000	3244.7
732008 E1 OUTER	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - WIRING HARNESS (OUTER, INNER FRONT AND REAR)			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
732008 E2 OUTER	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - WIRING HARNESS (OUTER, INNER FRONT AND REAR)			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
732020 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST/DISCARD - MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
732020 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST/DISCARD - MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
751020 E1	OVERHAUL - ANTI-ICING VALVE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
751020 E2	OVERHAUL - ANTI-ICING VALVE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
753001 E1	OVERHAUL - COMPRESSOR BLEED VALVES			MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753001 E2	OVERHAUL - COMPRESSOR BLEED VALVES			MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753002 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - COMPRESSOR BOV SOLENOID			30B6399-02 KFA485 MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753002 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - COMPRESSOR BOV SOLENOID			30B6399-02 KFA486 MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753004 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - LINEAR STATOR VANE ACTUATOR			2600-1 SAU10009 MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753004 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - LINEAR STATOR VANE ACTUATOR			2600-1 SAU10002 MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
753010 E1	DETAILED INSPECTION - ENGINE COMPRESSOR P2.5 AND P2.8 BLEED VALVES - REMOVAL AND INSPECTION FOR GENERAL CONDITION AND WEAR AND OPERATIONAL CHECK			MTH HRS	01-Dec-2010 0		3000		(3000)3000	244.7
753010 E2	DETAILED INSPECTION - ENGINE COMPRESSOR P2.5 AND P2.8 BLEED VALVES - REMOVAL AND INSPECTION FOR GENERAL CONDITION AND WEAR AND OPERATIONAL CHECK			MTH HRS	01-Dec-2010 0		3000		(3000)3000	244.7
753020 E1	GENERAL VISUAL INSPECTION - BOV SOLENOID FILTER - INSPECTION OF BLEED VALVE CONTROL UNIT FILTER			MTH	01-Dec-2010		N/A			
753020 E2	GENERAL VISUAL INSPECTION - BOV SOLENOID FILTER - INSPECTION OF BLEED VALVE CONTROL UNIT FILTER			MTH	01-Dec-2010		N/A			
753030 E1	DISCARD BOV SOLENOID FILTER - REMOVE AND DISCARD THE BOV SOLENOID FILTER (REGARDLESS OF CONDITION)			MTH HRS	01-Dec-2010 0		3000		(3000)3000	244.7
753030 E2	DISCARD BOV SOLENOID FILTER - REMOVE AND DISCARD THE BOV SOLENOID FILTER (REGARDLESS OF CONDITION)			MTH HRS	01-Dec-2010 0		3000		(3000)3000	244.7
754001 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - P3 TRANSDUCER			MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
754001 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - P3 TRANSDUCER			MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
057740 E1	ECTM DATA DOWNLOAD	SZB		MTH HRS LDG	20-May-2025 2746.6 2091		1		20-Jun-2025	10 d
057740 E2	ECTM DATA DOWNLOAD	SZB		MTH HRS LDG	20-May-2025 2746.6 2091		1		20-Jun-2025	10 d
771011 E1 CHANNEL A	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N1 CHANNEL A SPEED SENSORS			PN SN-UNKNOWN MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
771011 E2 CHANNEL A	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N1 CHANNEL A SPEED SENSORS			PN SN-UNKNOWN MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7
771022 E1 CHANNEL B	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N1 CHANNEL B SPEED SENSORS			PN SN-UNKNOWN MTH HRS	01-Dec-2010 0		6000		(6000)6000	3244.7



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
771022 E2 CHANNEL B	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N1 CHANNEL B SPEED SENSORS			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
771030 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - WIRING HARNESS SPEED SENSOR				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
771030 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - WIRING HARNESS SPEED SENSOR				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
771040 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N2 SPEED SENSORS				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
771040 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - N2 SPEED SENSORS				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772010 E1	EXAMINE AND DO A FUNCTIONAL CHECK - T4.5 HARNESS AND T4.5 TERMINAL BOX				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772010 E2	EXAMINE AND DO A FUNCTIONAL CHECK - T4.5 HARNESS AND T4.5 TERMINAL BOX				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772020 E1 INBOARD	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - INBOARD P1/T1 SENSORS			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772020 E2 INBOARD	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - INBOARD P1/T1 SENSORS			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772025 E1 OUTBOARD	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OUTBOARD P1/T1 SENSORS			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
772025 E2 OUTBOARD	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OUTBOARD P1/T1 SENSORS			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
774001 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - ENGINE DIAGNOSTIC UNIT			822492-2-006 10070010	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
774001 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - ENGINE DIAGNOSTIC UNIT			822492-2-006 10060015	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
78-30-00-9600 LEFT INBOARD	LEFT INBOARD THRUST REVERSER ACTUATOR DISCARD			07ND78401-8 01624	MTH 01-Dec-2010		N/A			
78-30-00-9600 LEFT OUTBOARD	LEFT OUTBOARD THRUST REVERSER ACTUATOR DISCARD			07ND78401-7 01599	MTH 01-Dec-2010		N/A			
78-30-00-9600 RIGHT INBOARD	RIGHT INBOARD THRUST REVERSER ACTUATOR DISCARD			07ND78401-7 01622	MTH 01-Dec-2010		N/A			
78-30-00-9600 RIGHT OUTBOARD	RIGHT OUTBOARD THRUST REVERSER ACTUATOR DISCARD			07ND78401-8 01623	MTH 01-Dec-2010		N/A			
057910 E1	ENGINE OIL QTY CONNECTOR-OIL CONTAMINATION INSPECTION (PN:30B3851-03)	SZB			MTH 07-May-2025 HRS 2746.6 LDG 2091		1		30-Jun-2025	20 d
057910 E2	ENGINE OIL QTY CONNECTOR-OIL CONTAMINATION INSPECTION (PN:30B3851-03)	SZB			MTH 07-May-2025 HRS 2746.6 LDG 2091		1		30-Jun-2025	20 d



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
057920 E1	OIL ANALYSIS TECHNOLOGY (OAT)				MTH 31-May-2024 HRS 2079.2 LDG 2041		12		31-Dec-2025	6 m 21 d
057920 E2	OIL ANALYSIS TECHNOLOGY (OAT)				MTH 31-May-2024 HRS 2709.2 LDG 2041		12		31-Dec-2025	6 m 21 d
792015 E1	DETAILED INSPECTION - ENGINE OIL FILTER - EXAMINE OIL FILTER ELEMENT	SZB		30B6652-01 N/A	MTH 09-May-2025 HRS 2746.6 LDG 2091		800		(3546.6)3546.6	791.3
792015 E2	DETAILED INSPECTION - ENGINE OIL FILTER - EXAMINE OIL FILTER ELEMENT	SZB		30B6652-01 N/A	MTH 09-May-2025 HRS 2746.6 LDG 2091		800		(3546.6)3546.6	791.3
792020 E1	GENERAL VISUAL INSPECTION - NO. 3 BRG SCAVENGE OIL TUBE - VISUAL CHECK FOR LEAKAGE	SZB			MTH 29-Apr-2020 HRS 2249.27 LDG 1628		1200		(3449.27)3449.27	693.97
792020 E2	GENERAL VISUAL INSPECTION - NO. 3 BRG SCAVENGE OIL TUBE - VISUAL CHECK FOR LEAKAGE	SZB			MTH 29-Apr-2020 HRS 2249.27 LDG 1628		1200		(3449.27)3449.27	693.97
792030 E1	CHANGE OIL	SZB			MTH 09-May-2025 HRS 2746.6 LDG 2091		12 1200		31-May-2026 (3946.6)3946.6	11 m 21 d 1191.3
792030 E2	CHANGE OIL	SZB			MTH 09-May-2025 HRS 2746.6 LDG 2091		12 1200		31-May-2026 (3946.6)3946.6	11 m 21 d 1191.3
792040 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL FILTER BYPASS SWITCH				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
792040 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL FILTER BYPASS SWITCH				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793001 E1	DISCARD - CHIP DETECTOR				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793001 E2	DISCARD - CHIP DETECTOR				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793002 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - LOW OIL PRESSURE SWITCH				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793002 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - LOW OIL PRESSURE SWITCH				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793003 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL TANK FILLER CAP				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793003 E2	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL TANK FILLER CAP				MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7
793020 E1	DETAILED INSPECTION ENGINE CHIP DETECTOR - FUNCTIONAL ELECTRICAL AND MAGNETIC INSPECTION	SZB			MTH 10-Jan-2025 HRS 2725.6 LDG 2061		800		(3525.6)3525.6	770.3
793020 E2	DETAILED INSPECTION ENGINE CHIP DETECTOR - FUNCTIONAL ELECTRICAL AND MAGNETIC INSPECTION	SZB			MTH 10-Jan-2025 HRS 2725.6 LDG 2061		800		(3525.6)3525.6	770.3
793030 E1	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL LEVEL SENSOR			30B3851-03 NSN	MTH 01-Dec-2010 HRS 0		6000		(6000)6000	3244.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Maintenance Inspections

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
793030	GENERAL VISUAL INSPECTION/FUNCTIONAL TEST - OIL LEVEL SENSOR									
E2				30B3851-03	MTH	01-Dec-2010				
				NSN	HRS	0	6000		(6000)6000	3244.7



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211001 LEFT	BUTTERFLY VALVE			1406-8 1050	MTH 01-Dec-2010		O/C	0		
211001 RIGHT	BUTTERFLY VALVE			1406-8 1048	MTH 01-Dec-2010		O/C	0		
211002 LEFT	OZONE CONVERTER ASSEMBLY 9914523-4			31A435-1 1277	MTH 01-Dec-2010		O/C	0		
211002 RIGHT	OZONE CONVERTER ASSEMBLY 9914523-4			31A435-1 1279	MTH 01-Dec-2010		O/C	0		
211003	PNEUMATIC SHUTOFF VALVE			2601-31 0255	MTH 01-Dec-2010		O/C	0		
211005 CABIN	RECIRCULATING FAN 9919039-1			AE0907B00 L0412	MTH 01-Dec-2010		O/C	0		
211005 EMERGENCY	PRESSURE FLOW VALVE			4713-19 1215	MTH 01-Dec-2010		O/C	0		
211005 LEFT	COCKPIT RECIRCULATING FAN 9919039-2	*CF		AE0606A00 L0723	MTH 27-Nov-2010		O/C	0		
211005 RIGHT	COCKPIT RECIRCULATING FAN 9919039-2	*CF		AE0606A00 L0718	MTH 27-Nov-2010		O/C	0		
211006 CABIN	RATE OF CLIMB INDICATOR 9914059-1			37060-1113 366837	MTH 01-Dec-2010		O/C	0		
212200 LOWER	BAGGAGE HEAT TEMPERATURE SENSOR			MS28034-3 157885	MTH 01-Dec-2010		O/C	0		
212200 UPPER	BAGGAGE HEAT TEMPERATURE SENSOR			MS28034-3 157938	MTH 01-Dec-2010		O/C	0		
213001 CABIN	ALTITUDE/DIFFERENTIAL PRESSURE INDICATOR 9914060-1			3003J17 24761	MTH 01-Dec-2010		O/C	0		
213002	VACUUM EJECTOR JET 9914135-1			2002-1 0711	MTH 01-Dec-2010		O/C	0		
213003	PRESSURE CONTROLLER 9914487-11			2119862-3 50FA359	MTH 01-Dec-2010		O/C	0		
213004 LEFT	BI LEVEL VALVE 9912492-3			5391-00-3 0655	MTH 01-Dec-2010		O/C	0		
213004 RIGHT	BI LEVEL VALVE 9912492-3			5391-00-3 0664	MTH 01-Dec-2010		O/C	0		
213005	MANUAL CONTROL VALVE 9914183-12			131400-4 2967F	MTH 01-Dec-2010		O/C	0		
213006	CABIN PRESSURE SELECTOR 9914487-13			2119886-3 29F0048	MTH 01-Dec-2010		O/C	0		
213007	PRIMARY OUTFLOW (VC003) VALVE 9914183-14			103678-3 59A0633	MTH 01-Dec-2010		O/C	0		
213008	SECONDARY OUTFLOW (VF002) VALVE 9914183-15			103676-3 19A0627	MTH 01-Dec-2010		O/C	0		
213009	PRESSURE VACUUM REGULATOR 9914183-8			131402-1 462D	MTH 01-Dec-2010		O/C	0		
213010	ENVIRONMENTAL CONTROL UNIT 9912493-8			2215460-3 1033	MTH 01-Dec-2010		O/C	0		
213011 NO. 1	CABIN TEMPERATURE SENSOR 9914130-3			1E47-1 3BE65	MTH 01-Dec-2010		O/C	0		
213011 NO. 2	CABIN TEMPERATURE SENSOR 9914130-3			1E47-1 IBE4	MTH 01-Dec-2010		O/C	0		
213012	WATER SPRAY ECU ASPIRATOR 9912493-3			2215605-1 NSN	MTH 01-Dec-2010		O/C	0		
213013	ACM OVERTEMPERATURE SWITCH HNL			927223-2-3 0082	MTH 18-Dec-2010 HRS 18.6 LDG 8		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
213014	WATER SEPARATOR 9912493-7	2341316-2 1235	MTH 01-Dec-2010		O/C	0		
213015	COOLING TURBINE	2206610-1 SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
213016	ZONE TEMPERATURE SENSOR CABIN UPPER 9914130-6	1E46-1 6BD281	MTH 01-Dec-2010		O/C	0		
213016	ZONE TEMPERATURE SENSOR COCKPIT UPPER 9914130-6	1E46-1 12BG77	MTH 04-Jun-2012 HRS 416 LDG 230		O/C	0		
213018	ACM DUCT TEMPERATURE SENSOR 9914130-20	1E62-1 9BG31	MTH 04-Jun-2012 HRS 416 LDG 230		O/C	0		
213019	TEMPERATURE VALVE CABIN 9912518-2	27241287-14 7AY114F	MTH 06-Jul-2021 HRS 2401.5 LDG 1767		O/C	4 198		
213019	TEMPERATURE VALVE COCKPIT 9912518-2	27241287-14 5BF14F	MTH 01-Dec-2010		O/C	0		
213019	ECU TEMPERATURE CONTROL VALVE 9912518-2	27241287-14 6BF49F	MTH 01-Dec-2010		O/C	0		
215000	ACM COOLING TURBINE	2206610-1 1044	MTH 01-Dec-2010		O/C	0		
215001	HEAT EXCHANGER LEFT 9914522-2	8915-1 S4883T0653	MTH 01-Dec-2010		O/C	0		
215001	HEAT EXCHANGER RIGHT 9914522-2	8915-1 S4883T0673	MTH 01-Dec-2010		O/C	0		
216002	TEMPERATURE CONTROLLER CABIN 9912518-5	1E64-2 1BD16	MTH 01-Dec-2010		O/C	0		
21FO06	IN DEGREES CELSIUS TEMP CONTROL DISPLAY	06C FO	MTH 01-Dec-2010		O/C	0		
221001	FLIGHT GUIDANCE CONTROL PANEL GP-400	7022010-909 09050991	MTH 01-Dec-2010		O/C	0		
221010	SERVO AILERON	6256-166 1223	MTH 01-Dec-2010		O/C	0		
221010	SERVO ELEVATOR	6256-166 1248	MTH 01-Dec-2010		O/C	0		
221010	SERVO RUDDER	6256-166 1242	MTH 01-Dec-2010		O/C	0		
223001	REPLACE AUTOTHROTTLE (AIRPLANES -0501 THRU -0534)	PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
23-70-00-9600	810-2007/K OR 810-2008/K L3COCKPIT VOICE RECORDER UNDERWATERLOCATOR BEACON BATTERY DISCARD BATTERY							
COCKPIT	SZB	810-2008/K	MTH 07-Jul-2022		DUE	3	30-Apr-2028	34 m 20 d
237004A		NSN	HRS 2491.9 LDG 1828		DUE DUE DUE	0		
Expiration Date: 30-Apr-2028								
231002	HF RECEIVER/EXCITER NO. 1 KRX-1053	064-01073-0101 4913	MTH 01-Dec-2010		O/C	0		
231003	HF ANTENNA COUPLER NO. 1 KAC-1052	064-01074-0101 4478	MTH 01-Dec-2010		O/C	0		
231004	POWER AMPLIFIER HF COUPLER NO. 1 SZB	064-01072-0101 3829	MTH 10-Feb-2014 HRS 960 LDG 581		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231504 CABIN	HANDSET	P12199-002 1219954018	MTH 19-Oct-2017 HRS 1739 LDG 1175		O/C			
232001 NO. 1	COMMUNICATION ANTENNA	S65-8280-18 3121510	MTH 01-Dec-2010		O/C	0		
232001 NO. 2	COMMUNICATION ANTENNA	S65-8280-18 3121507	MTH 01-Dec-2010		O/C	0		
232009	SELCAL DECODER	1200008-000 6429	MTH 01-Dec-2010		O/C	0		
232010	TELEPHONE TRANSCEIVER AIRCELL SZB	400-10680-002 1068027088	MTH 04-Jun-2015 HRS 1290 LDG 813		O/C	0 0		
232011 LEFT	COMMUNICATION RADIO MODULE SZB	7026201-801 03070281	MTH 03-May-2024 HRS 2706.5 LDG 2037		O/C	1		
232011 RIGHT	COMMUNICATION RADIO MODULE SZB	7026201-801 B,D,J,K,M- U 1303A152	MTH 26-Dec-2024 HRS 2724.8 LDG 2060		O/C	0 0		
232013	AIRCELL AXCESS ROUTER	P14126 NSN	MTH 01-Dec-2010		O/C	0		
232015	ATG-4000 AIRCELL	P13989 NSN	MTH 01-Dec-2010		O/C	0		
235002 NO. 1	AUDIO CONTROL PANEL	7511001-915 0811D315	MTH 01-Dec-2010		O/C	0		
235002 NO. 2	AUDIO CONTROL PANEL	7511001-915 0902D469	MTH 01-Dec-2010		O/C	0		
235004 LEFT	TONE AUDIO WARNING SZB	9915001-1 001000780	MTH 23-May-2016 HRS 1472 LDG 958		O/C			
235004 RIGHT	TONE AUDIO WARNING	9915001-1 001001093	MTH 01-Dec-2010		O/C	0		
237001 COCKPIT	VOICE RECORDER	2100-1020-02 000662210	MTH 01-Dec-2010		O/C	0		
237002	COCKPIT VOICE RECORDER CONTROL HEAD	S261-1120-00 000538962	MTH 01-Dec-2010		O/C	0		
237003	COCKPIT VOICE RECORDER IMPACT SWITCH	6895D2X5-5 8296	MTH 01-Dec-2010		O/C	0		
237004 COCKPIT	VOICE RECORDER UNDERWATER LOCATOR BEACON	DK120 SC77846	MTH 01-Dec-2010		O/C	0		
240001 LEFT	POWER CONTROL UNIT 9914216-6 SZB	91479-1 1995	MTH 09-Oct-2020 HRS 2352.1 LDG 1719		O/C	2 288		
240001 RIGHT	POWER CONTROL UNIT 9914216-6	91479-1 2320	MTH 01-Dec-2010		O/C	0		
240002 CABIN	LOGIC BOX	9610005-1 NSN	MTH 01-Dec-2010		O/C	0		
242050 LEFT	AC GENERATOR 9914435-9	92589-2 193	MTH 19-Feb-2013 HRS 667 LDG 397		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
242050 RIGHT	AC GENERATOR 9914435-9	SZB		92589-2 550B	MTH 23-Apr-2013 HRS 684 LDG 414		O/C	0 0		
243001 NO. 1	28VDC TO 16VDC - CONVERTER --			PN SN-UNKNOWN			O/C			
243001 NO. 2	28VDC TO 16VDC - CONVERTER -- SZB			RHB40 159	MTH 27-Sep-2013 HRS 882 LDG 530		O/C	0 0		
243003 APU	GENERATOR CONTROL			51525-001F P5143	MTH 01-Dec-2010		O/C	0		
243003 LEFT	GENERATOR CONTROL			51525-001F P5144	MTH 01-Dec-2010		O/C	0		
243003 RIGHT	GENERATOR CONTROL SZB			51525-001F P3602	MTH 25-Sep-2013 HRS 861 LDG 517		O/C			
243007 LEFT	MAIN BATTERY 30978-002	SZB		9914058-6 12201581	MTH 24-Aug-2023 HRS 2619.5 LDG 1961		O/C			
243007 RIGHT	MAIN BATTERY 30978-002	SZB		9914058-6 12201582	MTH 24-Aug-2023 HRS 2619.5 LDG 1961		O/C			
243015 STANDBY	BATTERY PACK	SZB		100-2410-04 1194489	MTH 19-Feb-2024 HRS 2683 LDG 2011		O/C	1 0		
245000 LEFT	DOOR MONITOR NC105 PCB ASSY			6918606-11 0417	MTH 01-Dec-2010		O/C	0		
245001 R1	LANDING GEAR CONTROL NF205 PCB ASSY			6918604-11 0737	MTH 01-Dec-2010		O/C	0		
245001 R2	LANDING GEAR CONTROL NF207 PCB ASSY			6918604-11 0736	MTH 01-Dec-2010		O/C	0		
245002 LEFT	LIGHTING CONTROL NC103 PCB ASSY			6918605-31 0713	MTH 01-Dec-2010		O/C	0		
245002 RIGHT	LIGHTING CONTROL NF203 PCB ASSY SZB			6918605-31 0746	MTH 04-Aug-2011 HRS 213 LDG 101		O/C	0 0 0		
245003 LEFT	ROLL RATIO NC104 PCB ASSY			6918612-11 0417	MTH 01-Dec-2010		O/C	0		
245004 LEFT	ANTI-ICE NC111 PCB ASSY			6918610-16 0754	MTH 01-Dec-2010		O/C	0		
245004 RIGHT	ANTI-ICE NF211 PCB ASSY SZB			6918610-16 0772	MTH 25-Apr-2011 HRS 136 LDG 54		O/C	0 0 0		
245005 LEFT	SQUAT SWITCH NC106 PCB ASSY SZB			6918611-16 1341	MTH 10-Aug-2018 HRS 1907 LDG 1322		O/C	0 0		
245005 LEFT AFT	SQUAT SWITCH NZ106 PCB ASSY			6918611-16 1339	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245005 RIGHT	SQUAT SWITCH NF206 PCB ASSY SZB			6918611-16 1340	MTH 10-Aug-2018 HRS 1907 LDG 1322		O/C	0 0		
245005 RIGHT AFT	SQUAT SWITCH NZ206 PCB ASSY			6918611-16 1338	MTH 01-Dec-2010		O/C	0		
245006 LEFT	B/A CONTROL NC110 PCB ASSY			6918613-36 0740	MTH 01-Dec-2010		O/C	0		
245006 RIGHT	B/A CONTROL NF210 PCB ASSY			6918613-36 0738	MTH 01-Dec-2010		O/C	0		
245007 LEFT	STABILIZER TRIM 1 NZ105 PCB ASSY SZB			6918617-26 0427	MTH 21-Feb-2012 HRS 352 LDG 192		O/C	0 0		
245007 RIGHT	STABILIZER TRIM 2 NZ205 PCB ASSY			6918623-21 0407	MTH 01-Dec-2010		O/C	0		
245008 LEFT AFT	CB MONITOR NZ110 PCB ASSY			6918620-16 0699	MTH 01-Dec-2010		O/C	0		
245008 RIGHT AFT	CB MONITOR NZ210 PCB ASSY			6918620-16 0700	MTH 01-Dec-2010		O/C	0		
245009 LEFT AFT	RUDDER BIAS NZ111 PCB ASSY			6918624-6 0426	MTH 01-Dec-2010		O/C	0		
245009 RIGHT AFT	APU CONTROL NZ204 PCB ASSY SZB			6968012-7 0204	MTH 23-Sep-2011 HRS 213 LDG 101		O/C	0 0 0		
245012 LEFT	B/A MONITOR NC108 PCB ASSY *CF			6918625-26 0698	MTH 27-Nov-2010		O/C	0		
245012 RIGHT	B/A MONITOR NF208 PCB ASSY *CF			6918625-26 0722	MTH 27-Nov-2010		O/C	0		
245013 LEFT	ARINC DECODER NZ106 PCB ASSY			6918626-6 0717	MTH 01-Dec-2010		O/C	0		
245013 RIGHT	ARINC DECODER NZ206 PCB ASSY SZB			6918626-6 0763	MTH 16-Jul-2014 HRS 1051 LDG 642		O/C	0 0		
245014 LEFT	DIAGNOSTIC-NC101 PCB ASSY			6918627-1 1330	MTH 01-Dec-2010		O/C	0		
245014 LEFT AFT	DIAGNOSTIC-NZ101 PCB ASSY			6918627-1 1329	MTH 01-Dec-2010		O/C	0		
245014 RIGHT	DIAGNOSTIC-NF201 PCB ASSY			6918627-1 1328	MTH 01-Dec-2010		O/C	0		
245014 RIGHT AFT	DIAGNOSTIC-NZ201 PCB ASSY			6918627-1 1327	MTH 01-Dec-2010		O/C	0		
245015 LEFT AFT	AUX DIST NZ104 PCB ASSY			6918601-61 0431	MTH 01-Dec-2010		O/C	0		
245016 LEFT AFT	FUEL CONTROL NZ107 PCB ASSY			6918602-11 0715	MTH 01-Dec-2010		O/C	0		
245016 RIGHT AFT	FUEL CONTROL NZ207 PCB ASSY			6918602-11 0713	MTH 01-Dec-2010		O/C	0		
245017 RIGHT AFT	MACH TRIM NZ211 PCB ASSY			6918628-31 0395	MTH 01-Dec-2010		O/C	0		
245018 LEFT AFT	FIRE/SMOKE NZ108 PCB ASSY			6918622-51 0161	MTH 01-Dec-2010		O/C	0		
245018 RIGHT AFT	FIRE/SMOKE NZ208 PCB ASSY			6918622-51 0159	MTH 01-Dec-2010		O/C	0		
245019 LEFT AFT	START CONTROL NZ103 PCB ASSY			6918629-85 0192	MTH 01-Dec-2010		O/C	0		
245019 RIGHT AFT	START CONTROL NZ203 PCB ASSY			6918629-85 0193	MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245020 LEFT AFT	THRUST REVERSER CONTROL NZ102 PCB ASSY	SZB		6918631-33 0783	MTH 25-May-2018 HRS 1840 LDG 1265		O/C			
245020 RIGHT AFT	THRUST REVERSER CONTROL NZ202 PCB ASSY	SZB		6918631-33 0515	MTH 25-May-2018 HRS 1840 LDG 1265		O/C			
245021 NOSE	PCB ASSY			8955004-1 0127	MTH 01-Dec-2010		O/C	0		
25-60-00-9601 256003	S1820506-01 KANNAD EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY PACK DISCARD (AIRPLANES -0001 THRU -0324)	SZB		S1820516-99 TM0000236657	MTH 15-Dec-2022 HRS 2548.3 LDG 1881		DUE DUE DUE	3 0 0	30-Sep-2028	39 m 20 d
250001	WASTE DRAIN VALVE			332-0068-01 0356	MTH 01-Dec-2010		O/C	0		
251401	HEATED LIQUID CONTAINER --	SZB		81366-0721-1200 298	MTH 26-Jul-2011 HRS 182 LDG 86		O/C	0 0 0		
253001	AUTO CONFIGURATION MODULE			104001-1 NSN	MTH 01-Dec-2010		O/C	0		
254002	PUMP MOTOR ASSEMBLY	SZB		L21995 861869002	MTH 21-Mar-2014 HRS 986 LDG 601		O/C	0 0 0		
256001	ELT ANTENNA			S65-8282-406 4011799	MTH 01-Dec-2010		O/C	0		
256002	EMERGENCY LOCATOR TRANSMITTER KANNAD 406AF	SZB		S1821502-02 2620493-0036	MTH 15-Dec-2022 HRS 2548.3 LDG 1881		O/C			
256004 INFANT	SMALL CHILD LIFE JACKET			216200-0 238479	MTH 17-Jul-2023		120	2	31-May-2033	95 m 21 d
256004 NO. 10	LIFE JACKET	SZB		P01074-207 20040800170	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 11	LIFE JACKET			PN SN-UNKNOWN	MTH 07-Jul-2020		120	0	31-Jul-2030	61 m 21 d
256004 NO. 1	LIFE JACKET	SZB		P01074-207 20040800161	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 2	LIFE JACKET	SZB		P01074-207 20040800162	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 3	LIFE JACKET	SZB		P01074-207 20040800163	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 4	LIFE JACKET	SZB		P01074-207 20040800164	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 5	LIFE JACKET	SZB		P01074-207 20040800165	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 6	LIFE JACKET	SZB		P01074-207 20040800166	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256004 NO. 7	LIFE JACKET	SZB		P01074-207 20040800167	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 8	LIFE JACKET	SZB		P01074-207 20040800168	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256004 NO. 9	LIFE JACKET	SZB		P01074-207 20040800169	MTH 07-Jul-2020 HRS 2273 LDG 1664	-6	120	0	31-Jul-2030	61 m 21 d
256005 NO. 1	LIFE RAFT	SZB		69FASA-632-1-705 6UL-01379	MTH 22-Mar-2023 HRS 2579 LDG 1912		36	0	31-Mar-2026	9 m 21 d
256005 NO. 2	LIFE RAFT	SZB		69FASA-632-1-705 6UL-01380	MTH 10-Jan-2023 HRS 2558.4 LDG 1888		36	1 0 0	31-Dec-2025	6 m 21 d
256011	AIRSHOW DATA INTERFACE UNIT			920040 NSN	MTH 01-Dec-2010		O/C	0		
256020	FIRE CONTAINMENT BAG -- SZB			FP-CON-LG-HD 41015	MTH 21-Oct-2022 HRS 2531.7 LDG 1867		144	0	31-Oct-2034	112 m 21 d
259002	DEFIBRILLATOR BATTERY PACK -- SZB			M5070A 82476P	MTH 17-Jul-2024 HRS 2712 LDG 2046		48	0	31-Jul-2028	37 m 21 d
259004	DEFIBRILLATOR PADS -- SZB			989803139261 230113-0953	MTH 23-Oct-2023 HRS 2654.9 LDG 1989		24	0	13-Jun-2025	3 d
26-20-00-9600 AFT/FWD 262010	AFT ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD FWD SQUIB (MAX LIFE)	SZB		30903824-1 ESD23M356-001	MTH 07-Feb-2025 HRS 2732 LDG 2071		108	14	31-Dec-2032	90 m 21 d
Manufacture Date: 01-Dec-2023										
26-20-00-9600 AFT REAR 262012	AFT ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD AFT SQUIB (MAX LIFE)	SZB		30903824-1 ESD23M356-001	MTH 07-Feb-2025 HRS 2732 LDG 2071		108	14	31-Dec-2032	90 m 21 d
Manufacture Date: 01-Dec-2023										
26-20-00-9600 FORWARD/AFT 262008	FWD ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD AFT SQUIB (MAX LIFE)	SZB		30903824-1 ESD23M356-001	MTH 05-Jun-2024 HRS 2709.2 LDG 2041		108	6	31-Dec-2032	90 m 21 d
Manufacture Date: 01-Dec-2023										
26-20-00-9600 FORWARD/FORW ARD 262006	FWD ENGINE FIRE BOTTLE CARTRIDGE SQUIB DISCARD FWD SQUIB (MAX LIFE)	SZB		30903824-1 ESD23M356-001	MTH 05-Jun-2024 HRS 2709.2 LDG 2041		108	6	31-Dec-2032	90 m 21 d
Manufacture Date: 01-Dec-2023										
26-20-30-9600 APU 262003	REPLACE APU FIRE BOTTLE FIRE EXT SQUIB (MAX LIFE)	SZB		30903937 0454YL	MTH 06-May-2024 HRS 2706.5 LDG 2037		180	51	28-Feb-2035	116 m 18 d
Manufacture Date: 01-Feb-2020										
26-20-30-9600 COMBO 262003	COMBO APU FIRE BOTTLE BAG (MAX LIFE) FIRE EXT SQUIB	SZB		30903937 0547YL	MTH 06-May-2024 HRS 2706.5 LDG 2037		180	51	28-Feb-2035	116 m 18 d
Manufacture Date: 01-Feb-2020										
26-20-30-9600 LOWER 262003	LOWER NOSE COMPARTMENT FIRE BOTTLE (MAX LIFE) FIRE EXT SQUIB	SZB		30903937 1911DD	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		180	21	30-Apr-2038	154 m 20 d
Manufacture Date: 01-Apr-2023										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
26-20-30-9600 UPPER FWD 262003	UPPER FWD NOSE COMPARTMENT FIRE BOTTLE (MAX LIFE) FIRE EXT SQUIB									
		SZB		30903938 2574DC	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		180	11	28-Feb-2039	164 m 18 d
Manufacture Date: 01-Feb-2024										
261002 LEFT	BLEED AIR CONTROL UNIT			35009-20 D6011	MTH 01-Dec-2010		O/C	0		
261002 RIGHT	BLEED AIR CONTROL UNIT			35009-20 D5970	MTH 01-Dec-2010		O/C	0		
261003 LEFT	ANTI-ICE CONTROL UNIT			35009-20 D5703	MTH 01-Dec-2010		O/C	0		
261003 RIGHT	ANTI-ICE CONTROL UNIT		SZB	35009-20 D6022	MTH 25-May-2011 HRS 163 LDG 73		O/C			
261004 AFT	TAILCONE CONTROL UNIT		SZB	35009-20 D5230	MTH 05-Jan-2012 HRS 352 LDG 192		O/C			
261004 FORWARD	STABILIZER CONTROL UNIT		SZB	35009-20 D6009	MTH 05-Jan-2012 HRS 352 LDG 192		O/C	352		
261030 NO. 1	FIRE DETECTOR 9914512-1			3101-21-1050/450-35 202846	MTH 01-Dec-2010		O/C	0		
261030 NO. 2	FIRE DETECTOR 9914512-1			3101-21-1050/450-35 202848	MTH 01-Dec-2010		O/C	0		
261200 NO. 1	SMOKE DETECTOR		SZB	473597-17 SEA1705	MTH 04-Jan-2023 HRS 2558.4 LDG 1888		O/C			
261200 NO. 2	SMOKE DETECTOR			473597-17 2094	MTH 01-Dec-2010		O/C	0		
262001 AFT	ENGINE FIRE BOTTLE 9914513-6		SZB	30700009-12 C8372D1	MTH 07-Feb-2025 HRS 2732 LDG 2071		O/C			
262001 APU	FIRE BOTTLE		SZB	33100328-2 80274B1	MTH 06-May-2024 HRS 2706.5 LDG 2037		O/C	1 0		
262001 FORWARD	ENGINE FIRE BOTTLE 9914513-6		SZB	30700009-12 85057D1	MTH 05-Jun-2024 HRS 2709.2 LDG 2041		O/C	6 0		
262002 CABIN	PORTABLE FIRE EXTINGUISHER		SZB	C352CS F-75057071	MTH 22-Aug-2019 HRS 2109 LDG 1509		O/C	0 0		
262002 COCKPIT	PORTABLE FIRE EXTINGUISHER		SZB	C352CS I-33915949	MTH 08-Jan-2025 HRS 2725.6 LDG 2061		O/C	0 0		
262004 NOSE COMPARTMENT	BAGGAGE (UN002) FIRE BOTTLE 9914712-6		SZB	34750005-1 10923H1	MTH 22-Jan-2025 HRS 2725.6 LDG 2061		O/C			
270001	THROTTLE QUADRANT ASSEMBLY			6965200-2 HAMISOV311	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
270002	PNEUMATIC BIAS ACTUATOR SZB			6960561-86 055	MTH 24-Mar-2014 HRS 986 LDG 601		O/C	0 0		
272001	RUDDER ASSEMBLY			6933000-36 647978	MTH 01-Dec-2010		O/C	0		
273007 LEFT	ELEVATOR ASSEMBLY			6934000-29 617233	MTH 26-Mar-2018 HRS 1808 LDG 1233		O/C			
274001	STABILIZER TRIM MOTOR 9914257-4			EM440-2 001	MTH 01-Dec-2010		O/C	0		
274002	LINEAR SERVO ACTUATOR 9914558-8			EM4070-8 446	MTH 01-Dec-2010		O/C	0		
275001	MIXER BOX ASSEMBLY			6960231-7 309	MTH 01-Dec-2010		H/T H/T	0		
275002	FLAP HANDLE			6965250-2 0435	MTH 01-Dec-2010		O/C	0		
275003 LEFT NO. 1	FLAP ACTUATOR			C160250-1 1622	MTH 01-Dec-2010		O/C	0		
275003 RIGHT NO. 1	FLAP ACTUATOR			C160250-1 1640	MTH 01-Dec-2010		O/C	0		
275004 LEFT NO. 2	FLAP ACTUATOR 9914669-2			C154898-1 1621	MTH 01-Dec-2010		O/C	0		
275004 RIGHT NO. 2	FLAP ACTUATOR 9914669-2			C154898-1 1624	MTH 01-Dec-2010		O/C	0		
275005 LEFT NO. 3	FLAP ACTUATOR 9914669-3			C154899-1 1468	MTH 01-Dec-2010		O/C	0		
275005 RIGHT NO. 3	FLAP ACTUATOR 9914669-3			C154899-1 1560	MTH 01-Dec-2010		O/C	0		
275006 LEFT NO. 4	FLAP ACTUATOR 9914669-4			C154900-1 1562	MTH 01-Dec-2010		O/C	0		
275006 RIGHT NO. 4	FLAP ACTUATOR 9914669-4			C154900-1 1621	MTH 01-Dec-2010		O/C	0		
275007 LEFT NO. 5	FLAP ACTUATOR 9914669-5			C154901-1 1553	MTH 01-Dec-2010		O/C	0		
275007 RIGHT NO. 5	FLAP ACTUATOR 9914669-5			C154901-1 1616	MTH 01-Dec-2010		O/C	0		
275008 LEFT NO. 6	FLAP ACTUATOR 9914669-7			C155127-1 1310	MTH 01-Dec-2010		O/C	0		
275008 RIGHT NO. 6	FLAP ACTUATOR 9914669-8			C155128-1 1311	MTH 01-Dec-2010		O/C	0		
275009 LEFT	CONTROL COLUMN SHAKER			201 8468	MTH 01-Dec-2010		O/C	0		
275009 RIGHT	CONTROL COLUMN SHAKER			201 8490	MTH 01-Dec-2010		O/C	0		
275010 LEFT	AILERON TRIM ACTUATOR 9914667-6			2A7211D D0136	MTH 01-Dec-2010		O/C	0		
275010 RIGHT	AILERON TRIM ACTUATOR 9914667-6			2A7211D D0594	MTH 01-Dec-2010		O/C	0		
275011	RUDDER TRIM ACTUATOR 9914667-7			2A7212D D0298	MTH 01-Dec-2010		O/C	0		
275012	HORIZONTAL TRIM ACTUATOR CONTROL UNIT 9914197-6			103000 454	MTH 01-Dec-2010		O/C	0		
275013	HORIZONTAL TRIM ACTUATOR 9914056-13			6361B0001-04 0211	MTH 01-Dec-2010		O/C	0		
275015	FLAP POWER DRIVE UNIT 9914615-3			MP50G-4 709B	MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
275016	FLAP CONTROLLER			6918320-5 432	MTH 01-Dec-2010		O/C	0		
275018	SOFT START MODULE ASSEMBLY			6238405-34 0406	MTH 01-Dec-2010		O/C	0		
275019 LEFT INBOARD	SPEEDBRAKE ACTUATOR 9914668-2			2-8129-2 1223	MTH 01-Dec-2010		O/C	0		
275019 LEFT OUTBOARD	SPEEDBRAKE ACTUATOR 9914668-2			2-8129-2 1216	MTH 01-Dec-2010		O/C	0		
275019 RIGHT INBOARD	SPEEDBRAKE ACTUATOR 9914668-2			2-8129-2 1119	MTH 01-Dec-2010		O/C	0		
275019 RIGHT OUTBOARD	SPEEDBRAKE ACTUATOR 9914668-2			2-8129-2 1122	MTH 01-Dec-2010		O/C	0		
275020	SPEEDBRAKE CONTROL VALVE 9914680-1			3363 0320	MTH 01-Dec-2010		O/C	0		
275023 NO. 1	POSITION FLAP SENSOR 9914510-4			3E5514A A1048	MTH 01-Dec-2010		O/C	0		
275023 NO. 2	POSITION FLAP SENSOR 9914510-4			3E5514A A0822	MTH 01-Dec-2010		O/C	0		
275025	RUDDER BIAS ACTUATOR 9914749-3			2A5202D D0607	MTH 01-Dec-2010		O/C	0		
275026	AILERON ROLL ACTUATOR 9914749-3			2A5202D D0658	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 1	FLEX SHAFT 9914344-57			140527-5700 0233	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 2	FLEX SHAFT 9914344-53			140527-5300 0622	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 3	FLEX SHAFT 9914344-54			140527-5400 0650	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 4	FLEX SHAFT 9914344-55			140527-5500 0215	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 5	FLEX SHAFT 9914344-54			140527-5400 0241	MTH 01-Dec-2010		O/C	0		
275201 LEFT NO. 6	FLEX SHAFT 9914344-56			140527-5600 0128	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 1	FLEX SHAFT 9914344-58			140527-5800 0283	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 2	FLEX SHAFT 9914344-53			140527-5300 0633	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 3	FLEX SHAFT 9914344-54			140527-5400 0640	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 4	FLEX SHAFT 9914344-55			140527-5500 0263	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 5	FLEX SHAFT 9914344-54			140527-5400 0205	MTH 01-Dec-2010		O/C	0		
275201 RIGHT NO. 6	FLEX SHAFT 9914344-56			140527-5600 0107	MTH 01-Dec-2010		O/C	0		
276001 NO. 2	SENSOR-RVDT POSITION SPDBK LH SENSOR 9914584-1			CU91093026 0893	MTH 01-Dec-2010		O/C	0		
276001 NO. 3	-RVDT POSITION SPDBK-LH SENSOR 9914584-1			CU91093026 0927	MTH 01-Dec-2010		O/C	0		
276002 LEFT CENTER	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1646	MTH 01-Dec-2010		O/C	0		
276002 LEFT INBOARD	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1417	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
 Aircraft Model: **680 - CITATION SOVEREIGN**
 Aircraft Serial: **680-0306**
 Unit: Reg No: **N3099**
 Airworthiness: **01-Dec-2010**
 Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
276002 LEFT OUTBOARD	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1858	MTH 01-Dec-2010		O/C	0		
276002 RIGHT CENTER	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1835	MTH 01-Dec-2010		O/C	0		
276002 RIGHT INBOARD	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1834	MTH 01-Dec-2010		O/C	0		
276002 RIGHT OUTBOARD	ROLL SPOILER POWER CONTROL UNIT 9914651-3			1560800-5 1852	MTH 01-Dec-2010		O/C	0		
280001 LEFT	REFUEL PILOT VALVE 9914107-1			61087 5583	MTH 01-Dec-2010		O/C	0		
280001 RIGHT	REFUEL PILOT VALVE 9914107-1			61087 5582	MTH 01-Dec-2010		O/C	0		
280002	REFUEL/DEFUEL VALVE			9036-351-2 1750	MTH 01-Dec-2010		O/C	0		
280007 LEFT	FUEL VENT FLOAT VALVE 9914505-3			2990006-102 1453	MTH 01-Dec-2010		O/C	0		
280007 RIGHT	FUEL VENT FLOAT VALVE 9914505-3			2990006-102 1474	MTH 01-Dec-2010		O/C	0		
280008 LEFT	FUEL FLOAT SWITCH			L16H-14 1288	MTH 01-Dec-2010		O/C	0		
280008 LEFT LOWER	FUEL SHUTOFF ACTUATOR MA20A1029-1	SZB		9914423-2 AA348881	MTH 17-Jun-2013 HRS 765 LDG 458		O/C	0 0		
280008 LEFT UPPER	FUEL SHUTOFF ACTUATOR 9914423-2			MA20A1029-1 AA235388	MTH 01-Dec-2010		O/C	0		
280008 RIGHT	FUEL FLOAT SWITCH			L16H-14 1288	MTH 01-Dec-2010		O/C	0		
280008 RIGHT LOWER	FUEL SHUTOFF ACTUATOR 9914423-2			MA20A1029-1 AA235391	MTH 01-Dec-2010		O/C	0		
280008 RIGHT UPPER	FUEL SHUTOFF ACTUATOR 9914423-2			MA20A1029-1 AA235401	MTH 01-Dec-2010		O/C	0		
280009 LEFT	REFUEL VALVE 9914107-3			61086 3975	MTH 01-Dec-2010		O/C	0		
280009 RIGHT	REFUEL VALVE 9914107-3			61086 3956	MTH 01-Dec-2010		O/C	0		
280010 LEFT	FUEL BOOST PUMP 9914688-1			3C7-1 5BE32	MTH 01-Dec-2010		O/C	0		
280010 RIGHT	FUEL BOOST PUMP 9914688-1			3C7-1 2BE12	MTH 01-Dec-2010		O/C	0		
280011 LEFT	FUEL BOOST PUMP CARTRIDGE 9914688-1			3C27-1 5BE32	MTH 01-Dec-2010		O/C	0		
280011 RIGHT	FUEL BOOST PUMP CARTRIDGE 9914688-1			3C27-1 2BE12	MTH 01-Dec-2010		O/C	0		
280012 LEFT OUTBOARD	POSITIVE/NEGATIVE RELIEF FUEL VALVE 9912501-2			840203-105 6012XP	MTH 01-Dec-2010		O/C	0		
280012 RIGHT OUTBOARD	POSITIVE/NEGATIVE RELIEF FUEL VALVE 9912501-2			840203-105 5937XP	MTH 01-Dec-2010		O/C	0		
280014 LEFT	DEFUEL VALVE			61084-2 1992	MTH 01-Dec-2010		O/C	0		
280014 RIGHT	DEFUEL VALVE	WSSL		61084-2 2745	MTH 15-Mar-2022 HRS 2438.3 LDG 1790		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
280016 LEFT	FUEL QUANTITY W2 PROBE 9914666-3	10674T02Y00 MN25110	MTH 01-Dec-2010		O/C	0		
280016 RIGHT	FUEL QUANTITY W2 PROBE 9914666-3	10674T02Y00 MN23658	MTH 01-Dec-2010		O/C	0		
280017 LEFT	FUEL QUANTITY W3 PROBE 9914666-4	10674T03Y00 MN17657	MTH 01-Dec-2010		O/C	0		
280017 RIGHT	FUEL QUANTITY W3 PROBE 9914666-4	10674T03Y00 MN16448	MTH 01-Dec-2010		O/C	0		
280018 LEFT	FUEL QUANTITY W4 PROBE 9914666-5	10674T04Y00 MN23433	MTH 01-Dec-2010		O/C	0		
280018 RIGHT	FUEL QUANTITY W4 PROBE 9914666-5	10674T04Y00 MN23432	MTH 01-Dec-2010		O/C	0		
280020 LEFT	FUEL QUANTITY W5 PROBE 9914666-6	10674T05Y00 MN24810	MTH 01-Dec-2010		O/C	0		
280020 RIGHT	FUEL QUANTITY W5 PROBE 9914666-6	10674T05Y00 MN17219	MTH 01-Dec-2010		O/C	0		
280021 LEFT	FUEL QUANTITY W6 PROBE 9914666-7	10674T06Y00 MN24909	MTH 01-Dec-2010		O/C	0		
280021 RIGHT	FUEL QUANTITY W6 PROBE 9914666-7	10674T06Y00 MN24969	MTH 01-Dec-2010		O/C	0		
280022 LEFT	FUEL QUANTITY W7 PROBE 9914666-8	10674T07Y00 MN23734	MTH 01-Dec-2010		O/C	0		
280022 RIGHT	FUEL QUANTITY W7 PROBE 9914666-8	10674T07Y00 MN20847	MTH 01-Dec-2010		O/C	0		
280023 LEFT	FUEL QUANTITY W1 PROBE 9914666-5	10674T04Y00 MN23435	MTH 01-Dec-2010		O/C	0		
280023 RIGHT	FUEL QUANTITY W1 PROBE 9914666-5	10674T04Y00 MN23437	MTH 01-Dec-2010		O/C	0		
280026 LEFT INBOARD	FUEL DRAIN VALVE SZB	100-0151-03 5482	MTH 31-May-2024 HRS 2706.5 LDG 2037		O/C	0 0		
280026 LEFT OUTBOARD	FUEL DRAIN VALVE SZB	100-0151-03 2065	MTH 31-May-2024 HRS 2706.5 LDG 2037		O/C	0 0		
280026 RIGHT INBOARD	FUEL DRAIN VALVE SZB	100-0151-03 2723	MTH 31-May-2024 HRS 2706.5 LDG 2037		O/C	0 0		
280026 RIGHT OUTBOARD	FUEL DRAIN VALVE SZB	100-0151-03 5491	MTH 31-May-2024 HRS 2706.5 LDG 2037		O/C	0 0		
280027 LEFT LOWER	BALL VALVE 9914423-4	125838AV AA236670	MTH 01-Dec-2010		O/C	0		
280027 LEFT UPPER	BALL VALVE 9914423-4	125838AV AA236669	MTH 01-Dec-2010		O/C	0		
280027 RIGHT LOWER	BALL VALVE 9914423-4	125838AV AA236673	MTH 01-Dec-2010		O/C	0		
280027 RIGHT UPPER	BALL VALVE 9914423-4	125838AV AA236671	MTH 01-Dec-2010		O/C	0		
280028 LEFT	MOTIVE FLOW PRESSURE SWITCH 9914488-3	GPP1250-47 0849450	MTH 01-Dec-2010		O/C	0		
280028 RIGHT	MOTIVE FLOW PRESSURE SWITCH 9914488-3	GPP1250-47 0816328	MTH 01-Dec-2010		O/C	0		
282001	HOUSING ASSEMBLY 9914168-2	61088 2116	MTH 01-Dec-2010		O/C	0		
282002 LEFT	PRIMARY EJECTOR PUMP 9914682-1	2000002-101 0662	MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282002 RIGHT	PRIMARY EJECTOR PUMP 9914682-1	2000002-101 0667	MTH 01-Dec-2010		O/C	0		
282003 LEFT AFT	EJECTOR PUMP 9914682-2	2000003-101 1844	MTH 01-Dec-2010		O/C	0		
282003 LEFT FORWARD	EJECTOR PUMP 9914682-2	2000003-101 1876	MTH 01-Dec-2010		O/C	0		
282003 LEFT MIDDLE	EJECTOR PUMP 9914682-3	2000003-102 1912	MTH 01-Dec-2010		O/C	0		
282003 RIGHT AFT	EJECTOR PUMP 9914682-2	2000003-101 1877	MTH 01-Dec-2010		O/C	0		
282003 RIGHT FORWARD	EJECTOR PUMP 9914682-2	2000003-101 1882	MTH 01-Dec-2010		O/C	0		
282003 RIGHT MIDDLE	EJECTOR PUMP 9914682-3	2000003-102 1913	MTH 01-Dec-2010		O/C	0		
284001	FUEL QUANTITY SIGNAL CONDITIONER 9914666-1 SZB	10673B01Y01 0115	MTH 16-Feb-2015 HRS 1205 LDG 757		O/C	0 0		
29-10-09-7100	AUXILIARY PUMP PRESSURE RELIEF HYDRAULIC MANIFOLD 9914673-13	AEC45770 0327	MTH 01-Dec-2010		O/C	0		
290004	AUXILIARY ELECTRIC PUMP 9914647-3 SZB	51176-02 K0165	MTH 21-Jun-2019 HRS 2090 LDG 1488		O/C			
290006	MAIN SYSTEM ACCUMULATOR 9912644-4	7550-4 0194	MTH 01-Dec-2010		O/C	0		
290007	NWS ACCUMULATOR 9912644-3	7550-3 0190	MTH 01-Dec-2010		O/C	0		
291000	HYDRAULIC PRESSURE SWITCH GPP1250-78 1001397		MTH 01-Dec-2010		O/C	0		
291001 LEFT	MOTOR-OPERATED HYDRAULIC SHUTOFF VALVE 9914681-2	72146-1 0632	MTH 01-Dec-2010		O/C	0		
291001 RIGHT	MOTOR-OPERATED HYDRAULIC SHUTOFF VALVE 9914681-2	72146-1 0641	MTH 01-Dec-2010		O/C	0		
291002 LEFT	ENGINE DRIVEN HYDRAULIC PUMP 9914643-3 *CF	51171-02 K0712	MTH 21-Nov-2010		O/C	0		
291002 RIGHT	ENGINE DRIVEN HYDRAULIC PUMP 9914643-3 SZB	51171-02 K0109AB	MTH 26-May-2023 HRS 2597 LDG 1933		O/C	1 0 0		
291003 LEFT	HYDRAULIC PUMP LOW PRESSURE SWITCH 9914646-4	ACC4271D4 NSN	MTH 01-Dec-2010		O/C	0		
291003 RIGHT	HYDRAULIC PUMP LOW PRESSURE SWITCH 9914646-4	ACC4271D4 NSN	MTH 01-Dec-2010		O/C	0		
291005	HYDRAULIC BOOTSTP 700 CI RESERVOIR 9914648-7	7520-3 0240	MTH 01-Dec-2010		O/C	0		
291006 LEFT	SHUTTLE VALVE 9914689-1	5128-5 0688	MTH 01-Dec-2010		O/C	0		
291006 RIGHT	SHUTTLE VALVE 9914689-1	5128-5 0704	MTH 01-Dec-2010		O/C	0		
291008 BRAKE	HYDRAULIC PRESSURE GAUGE 19940931-1 032352		MTH 01-Dec-2010		O/C	0		
291008 STEERING	HYDRAULIC PRESSURE GAUGE 19940931-1 032348		MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291010	RESERVIOR VOLUME INDICATOR 9914648-5			9611-1 0270	MTH 01-Dec-2010		O/C	0		
291011	HYDRAULIC MANIFOLD 9914672-6			AEC45520 0332	MTH 01-Dec-2010		O/C	0		
301002 LEFT	WINDSHIELD TEMPERATURE CONTROLLER 9914411-2			856-1-3 3RM0C	MTH 01-Dec-2010		O/C	0		
301002 RIGHT	WINDSHIELD TEMPERATURE CONTROLLER 9914411-2			856-1-3 3RPOD	MTH 01-Dec-2010		O/C	0		
301004	ISOLATION SHUTOFF VALVE 9912403-2			2602-36 2093	MTH 01-Dec-2010		O/C	0		
301005 LEFT	ENGINE INLET ANTI ICE VALVE 9914521-6			5199-00-6 1016	MTH 01-Dec-2010		O/C	0		
301005 RIGHT	ENGINE INLET ANTI ICE VALVE 9914521-6			5199-00-6 0872	MTH 01-Dec-2010		O/C	0		
301006	RAIN REMOVAL FAN			011598-501 C08190016	MTH 01-Dec-2010		O/C	0		
301007	SERVICE AIR REGULATOR VALVE 9914133-2			38E109-25B N085145	MTH 01-Dec-2010		O/C	0		
301011 LEFT	PRESSURE REGULATOR VALVE 9914710-2			1H144-2 8BF15	MTH 01-Dec-2010		O/C	0		
301011 RIGHT	PRESSURE REGULATOR VALVE 9914710-2			1H144-2 5BF6	MTH 01-Dec-2010		O/C	0		
301101 LEFT	ANTI ICE PRESSURE REGULATOR SHUTOFF VALVE 9912495-6			1962-00-11 4754	MTH 01-Dec-2010		O/C	0		
301101 RIGHT	ANTI ICE PRESSURE REGULATOR SHUTOFF VALVE 9912495-6			1962-00-11 4577	MTH 01-Dec-2010		O/C	0		
301103 L/H	ANTI-ICE CHECK VALVE			7C2W-200000 3290	MTH 01-Dec-2010		O/C	0		
301103 R/H	ANTI-ICE CHECK VALVE			7C2W-200000 3374	MTH 01-Dec-2010		O/C	0		
302001 LEFT	DIFFERENTIAL PRESSURE SWITCH			1153P0104 0672	MTH 01-Dec-2010		O/C	0		
302001 RIGHT	DIFFERENTIAL PRESSURE SWITCH			1153P0104 0667	MTH 01-Dec-2010		O/C	0		
302002 LEFT	ANTI ICING VALVE SOLENOID			30B5553-01 AL3044	MTH 01-Dec-2010		O/C	0		
302002 RIGHT	ANTI ICING VALVE SOLENOID			30B5553-01 AL3045	MTH 01-Dec-2010		O/C	0		
303001 LEFT	PITOT TUBE			0851JL1 275690	MTH 01-Dec-2010		O/C	0		
303001 RIGHT	PITOT TUBE			0851JL1 276394	MTH 01-Dec-2010		O/C	0		
303001 STANDBY	PITOT TUBE			0851JL1 263495	MTH 01-Dec-2010		O/C	0		
313002	FLIGHT HOUR RECORDER 85071			C664503-0104 NSN	MTH 01-Dec-2010		O/C	0		
313100	FLIGHT DATA RECORDER ACCELEROMETER			3001-01-111 15981	MTH 01-Dec-2010		O/C	0		
313101 LEFT AILERON	LEFT HAND AILERON FDR POSITION SENSOR			3A1322A 0498	MTH 01-Dec-2010		O/C	0		
313101 LEFT ELEVATOR	LEFT HAND ELEVATOR FDR POSITION SENSOR			3A1322A A0917	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
313101 RUDDER	RUDDER FDR POSITION SENSOR	3A1322A A0353	MTH 01-Dec-2010		O/C	0		
313102	FDR IMPACT SWITCH	6895D2X5-5 8476	MTH 01-Dec-2010		O/C	0		
313201	ARES RECORDER	6918231-1 1187	MTH 01-Dec-2010		O/C	0		
32-30-70-9601 LANDING GEAR 324001	EMERGENCY GEAR EXTENSION PNEUMATIC STORAGE BOTTLE DISCARD 9914678-3 SZB	40005369-2 8330	MTH 12-Jul-2024 HRS 2712 LDG 2046		288	123	30-Apr-2038	154 m 20 d
Manufacture Date: 30-Apr-2014								
32-43-00-9601 324013	EMERGENCY BRAKE PNEUMATIC BOTTLE DISCARD BOTTLE 9914678-2 SZB	40005370-1 9504	MTH 12-Jul-2024 HRS 2712 LDG 2046		288	81	31-Oct-2041	196 m 21 d
Manufacture Date: 31-Oct-2017								
32-50-00-9600 CENTER	NOSE WHEEL STEERING HOSES (CENTERING HOSE) - DISCARD PN	SN-UNKNOWN	MTH HRS		5000		5000	2244.7
32-50-00-9600 PRESS	NOSE WHEEL STEERING HOSES (PRESSURE HOSE) - DISCARD PN	SN-UNKNOWN	MTH HRS		5000		5000	2244.7
32-50-00-9600 RETRACT	NOSE WHEEL STEERING HOSES (RETRACT HOSE) - DISCARD PN	SN-UNKNOWN	MTH HRS		5000		5000	2244.7
32-50-00-9600 RETURN	NOSE WHEEL STEERING HOSES (RETURN HOSE) - DISCARD PN	SN-UNKNOWN	MTH HRS		5000		5000	2244.7
320014 LEFT	NOSE WHEEL 9914473-2	3-1538-1 1919	MTH 01-Dec-2010		O/C	0		
320014 RIGHT	NOSE WHEEL 9914473-2	3-1538-1 1921	MTH 01-Dec-2010		O/C	0		
320023 AFT	SOLENOID VALVE	67020-3 1584	MTH 01-Dec-2010		O/C	0		
320023 FORWARD	SOLENOID VALVE	67020-3 1051	MTH 01-Dec-2010		O/C	0		
320026 NOSE GEAR	POWER STEERING SYSTEM VALVE 72118-2 SZB	9914650-2 0285	MTH 13-Jun-2016 HRS 1506 LDG 987 APUH 1194 APUS 1458		O/C	0 0		
320027	NOSE WHEEL STEERING GEARBOX 9914757-2	2102610-001 474	MTH 01-Dec-2010		O/C	0		
321001 LEFT	MAIN LANDING GEAR ASSEMBLY	6941010-9 69	MTH 01-Dec-2010		O/C	0		
321001 RIGHT	MAIN LANDING GEAR ASSEMBLY	6941010-10 71	MTH 01-Dec-2010		O/C	0		
321002 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY	6941020-1 EMI317	MTH 01-Dec-2010		H/T H/T	0		
321002 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY	6941020-2 EMI335	MTH 01-Dec-2010		H/T H/T	0		
321007 LEFT	MAIN LANDING GEAR TRAILING LINK	6941030-2 561	MTH 01-Dec-2010		H/T H/T	0		
321007 RIGHT	MAIN LANDING GEAR TRAILING LINK	6941030-2 564	MTH 01-Dec-2010		H/T H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321009 LEFT	MAIN LANDING GEAR TRAILING LINK SPACER			6941031-2 562	MTH 01-Dec-2010		H/T H/T	0		
321009 RIGHT	MAIN LANDING GEAR TRAILING LINK SPACER			6941031-2 565	MTH 01-Dec-2010		H/T H/T	0		
321011 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY SZB			6941050-3 157	MTH 10-Feb-2023 HRS 2575 LDG 1904		H/T H/T H/T H/T	1072		
321011 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY SZB			6941050-3 152	MTH 10-Feb-2023 HRS 2575 LDG 1904		H/T H/T H/T H/T	1880		
322001 NOSE	LANDING GEAR			6994004-1 23	MTH 01-Dec-2010		H/T H/T	0		
322004 NOSE GEAR	TRUNNION ASSEMBLY			6742020-5 424	MTH 01-Dec-2010		O/C	0		
322005 NOSE GEAR	LOWER BARREL ASSEMBLY SZB			6742170-6 365	MTH 25-Nov-2015 HRS 1361 LDG 871 APUH 1056 APUS 1303		O/C			
322006 NOSE GEAR	UPPER BARREL ASSEMBLY SZB			6742180-2 375	MTH 25-Nov-2015 HRS 1361 LDG 871 APUH 1056 APUS 1303		O/C			
323001 LEFT MAIN GEAR	HYDRAULIC UPLOCK ACTUATOR NO DRAWING NO. AT THIS TIME.			6947010-3 662	MTH 01-Dec-2010		O/C	0		
323001 NOSE GEAR	HYDRAULIC UPLOCK ACTUATOR NO DRAWING NO. AT THIS TIME.			6947030-2 272	MTH 01-Dec-2010		O/C	0		
323001 RIGHT MAIN GEAR	HYDRAULIC UPLOCK ACTUATOR NO DRAWING NO. AT THIS TIME.			6947010-3 666	MTH 01-Dec-2010		O/C	0		
323002 NOSE	LANDING GEAR ACTUATOR 9914676-3 SZB			2-8172-3 0328	MTH 25-Nov-2016 HRS 1566 LDG 1044 APUH 1561.6 APUS 1490		H/T H/T H/T H/T H/T	0		
323003 LEFT	MAIN LANDING GEAR ACTUATOR ASSEMBLY 9914674-2			2-8126-2 0652	MTH 01-Dec-2010		H/T H/T	0		
323003 RIGHT	MAIN LANDING GEAR ACTUATOR ASSEMBLY 9914674-2 SZB			2-8126-2 0546	MTH 23-Jul-2021 HRS 2401.5 LDG 1767		H/T H/T H/T H/T	1753		
323007	LANDING GEAR CONTROL 9912550-1			049801-001 T5548	MTH 01-Dec-2010		O/C	0		
323009 LEFT MAIN GEAR	HYDRAULIC SHUTTLE VALVE			98312 1985A	MTH 01-Dec-2010		O/C	0		
323009 NOSE GEAR	HYDRAULIC SHUTTLE VALVE			98312 1956A	MTH 01-Dec-2010		O/C	0		
323009 RIGHT MAIN GEAR	HYDRAULIC SHUTTLE VALVE			98312 1961A	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324002 LEFT INBOARD	SPEED TRANSDUCER 140-179 SZB	9914450-2 2643	MTH 10-Dec-2012 HRS 619 LDG 362		O/C			
324002 LEFT OUTBOARD	SPEED TRANSDUCER 140-179 SZB	9914450-2 2236	MTH 10-Dec-2012 HRS 619 LDG 362		O/C			
324002 RIGHT INBOARD	SPEED TRANSDUCER 9914450-2	140-179 2296	MTH 01-Dec-2010		O/C	0		
324002 RIGHT OUTBOARD	SPEED TRANSDUCER 9914450-2	140-179 2640	MTH 01-Dec-2010		O/C	0		
324003 LEFT INBOARD	MAIN LANDING GEAR BRAKE 9914655-3	2-1675-1 1275	MTH 01-Dec-2010		O/C	0		
324003 LEFT OUTBOARD	MAIN LANDING GEAR BRAKE 9914655-3	2-1675-1 1365	MTH 01-Dec-2010		O/C	0		
324004 RIGHT INBOARD	MAIN LANDING GEAR BRAKE 9914655-3	2-1675-1 1345	MTH 01-Dec-2010		O/C	0		
324004 RIGHT OUTBOARD	MAIN LANDING GEAR BRAKE 9914655-3	2-1675-1 1287	MTH 01-Dec-2010		O/C	0		
324005 LEFT	NOSE WHEEL TIRE 9914718-1 SZB	M15601 6015S224	MTH 20-Mar-2023 HRS 2579 LDG 1912		T/C	0 0		
324005 RIGHT	NOSE WHEEL TIRE 9914718-1 SZB	M15601 8223S246	MTH 03-Dec-2022 HRS 2539.3 LDG 1872		T/C	0 0 0		
324006 EMERGENCY	BRAKE VALVE 9914478-3	72106 0319	MTH 01-Dec-2010		O/C	0		
324007 LEFT	ANTI-SKID CONTROL VALVE 9914652-2 SZB	39-865 755	MTH 30-Mar-2023 HRS 2579 LDG 1912		O/C	172 2098		
324007 RIGHT	ANTI-SKID CONTROL VALVE 9914652-2 SZB	39-865 752	MTH 30-Mar-2023 HRS 2579 LDG 1912		O/C	172 2098		
324008	ANTI-SKID CONTROLLER 9914652-3	142-073 426A	MTH 01-Dec-2010		O/C	0		
324009 LEFT INBOARD	MAIN LANDING GEAR WHEEL 9914655-1 SZB	3-1621 2412	MTH 08-Jun-2012 HRS 476 LDG 270		O/C			
324009 LEFT OUTBOARD	MAIN LANDING GEAR WHEEL 9914655-1	3-1621 2439	MTH 01-Dec-2010		O/C	0		
324009 RIGHT INBOARD	MAIN LANDING GEAR WHEEL 9914655-1	3-1621 2141	MTH 01-Dec-2010		O/C	0		
324009 RIGHT OUTBOARD	MAIN LANDING GEAR WHEEL 9914655-1 SZB	3-1621 2454	MTH 08-Jun-2012 HRS 476 LDG 270		O/C			
324010 LEFT INBOARD	MAIN LANDING GEAR TIRE 9914661-1 S00	M14401 2088K110	MTH 12-May-2023 HRS 2597 LDG 1933		T/C	0 0		
324010 LEFT OUTBOARD	MAIN LANDING GEAR TIRE 9914661-1 SZB	M14401 3004K116	MTH 19-Nov-2023 HRS 2663.2 LDG 1995		T/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324010	MAIN LANDING GEAR TIRE	M14401	MTH 18-Feb-2023		T/C	0		
RIGHT INBOARD	9914661-1	4077J105	HRS 2575			0		
			LDG 1904			0		
324010	MAIN LANDING GEAR TIRE	M14401	MTH 13-Dec-2023		T/C	0		
RIGHT OUTBOARD	9914661-1	3005K107	HRS 2673.9			0		
			LDG 2002					
324011	BRAKE FUSE	6411	MTH 01-Dec-2010		O/C	0		
LEFT INBOARD		0840						
324011	BRAKE FUSE	6411	MTH 01-Dec-2010		O/C	0		
LEFT OUTBOARD		0917						
324011	BRAKE FUSE	6411	MTH 01-Dec-2010		O/C	0		
RIGHT INBOARD		0963						
324011	BRAKE FUSE	6411	MTH 01-Dec-2010		O/C	0		
RIGHT OUTBOARD		0965						
324014	BRAKE SHUTTLE VALVE	211-124	MTH 08-Apr-2025		O/C			
LEFT INBOARD		3714	HRS 2742.3					
			LDG 2088					
324014	BRAKE SHUTTLE VALVE	211-124	MTH 08-Apr-2025		O/C			
LEFT OUTBOARD		586	HRS 2742.3					
			LDG 2088					
324014	BRAKE SHUTTLE VALVE	211-124	MTH 08-Apr-2025		O/C			
RIGHT INBOARD		3769	HRS 2742.3					
			LDG 2088					
324014	BRAKE SHUTTLE VALVE	211-124	MTH 08-Apr-2025		O/C			
RIGHT OUTBOARD		3964	HRS 2742.3					
			LDG 2088					
324020	PARKING BRAKE VALVE	9912388-9	MTH 04-Oct-2022		O/C			
	98340-9	0609	HRS 2531.7					
			LDG 1867					
324207	PARKING BRAKE PRESSURE SWITCH	GPP1250-80	MTH 07-May-2012		O/C	0		
		0907301	HRS 386			0		
			LDG 215					
325001	LANDING GEAR CONTROL MANIFOLD ASSEMBLY		MTH 01-Dec-2010		O/C	0		
	9914649-5	V10000A012						
		0721						
325010	HYDRAULIC PRESSURE GAUGE	19940931-1	MTH 01-Dec-2010		O/C	0		
SYSTEM		032351						
325020	HYDRAULIC PRESSURE GAUGE	19940931-1	MTH 01-Dec-2010		O/C	0		
LANDING GEAR		032600						
325030	BRAKE METERING VALVE	32-089-2	MTH 29-Nov-2022		O/C			
	9914652-6	756	HRS 2539.3					
			LDG 1872					
33-42-00-9600	LEFT AFT LED WING-TIP NAVIGATION LIGHT ASSEMBLY DISCARD							
LEFT AFT		30-2900-3	MTH 01-Dec-2010			0		
334009		2742	HRS 0		3000	0	3000	244.7
33-42-00-9600	LEFT FORWARD LED WING-TIP NAVIGATION LIGHT ASSEMBLY DISCARD							
LEFT FORWARD		30-2900-3	MTH 01-Dec-2010			0		
334009		2738	HRS 0		3000	0	3000	244.7
33-42-00-9600	RIGHT AFT LED WING-TIP NAVIGATION LIGHT ASSEMBLY DISCARD							
RIGHT AFT		30-2900-4	MTH 01-Dec-2010			0		
334010		2820	HRS 0		3000	0	3000	244.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
33-42-00-9600 RIGHT FORWARD 334010	RIGHT FORWARD LED WING-TIP NAVIGATION LIGHT ASSEMBLY DISCARD			30-2900-4 2766	MTH 01-Dec-2010 HRS 0			0 0		244.7
330001	ELECTRICAL PANEL INVERTER			EM2044-1 6053A	MTH 01-Dec-2010		O/C	0		
330003	PULSE LIGHT CONTROLLER			2401C TR01882	MTH 01-Dec-2010		O/C	0		
330004 LEFT	ANTI-COLLISION LIGHT			GE16846-1 1495048	MTH 01-Dec-2010		O/C	0		
330004 RIGHT	ANTI-COLLISION LIGHT			GE16846-1 1495050	MTH 01-Dec-2010		O/C	0		
330005 NO. 1	EMERGENCY LIGHTING (UF004) BATTERY PACK	SZB		CBS28-1 1733M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		O/C			
330005 NO. 2	EMERGENCY LIGHTING (UC003) BATTERY PACK	SZB		CBS28-1 3685M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		O/C			
330005 NO. 3	EMERGENCY LIGHTING (UF006) BATTERY PACK	SZB		CBS28-1 3777M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		O/C			
330005 NO. 4	EMERGENCY LIGHTING (UF008) BATTERY PACK	SZB		CBS28-1 4057M	MTH 06-Mar-2025 HRS 2735.6 LDG 2077		O/C			
330006 NO. 1	CABIN INDIRECT LIGHTING CONTROL			CLC500-01 3677	MTH 01-Dec-2010		O/C	0		
330006 NO. 2	CABIN INDIRECT LIGHTING CONTROL			CLC500-01 3639	MTH 01-Dec-2010		O/C	0		
330006 NO. 3	CABIN INDIRECT LIGHTING CONTROL			CLC500-01 3640	MTH 01-Dec-2010		O/C	0		
331001	DIMMER			273-1 32TYK	MTH 01-Dec-2010		O/C	0		
334005 TAIL	LIGHT ASSEMBLY			01-0770966-00 03556A	MTH 01-Dec-2010		O/C	0		
334006	GROUND RECOGNITION LIGHT ASSEMBLY			01-0790044-37 06890	MTH 01-Dec-2010		O/C	0		
340001 LEFT UPPER	TRANSPONDER ANTENNA			DMNI50-2-2 118951	MTH 01-Dec-2010		O/C	0		
340001 RIGHT UPPER	TRANSPONDER ANTENNA			DMNI50-2-2 119111	MTH 01-Dec-2010		O/C	0		
340005	EGPWS MODULE			7028419-1905 09022762	MTH 01-Dec-2010		O/C	0		
340006 STANDBY	HORIZONTAL SITUATION INDICATOR	SZB		501-1879-0101 1013	MTH 31-May-2024 HRS 2709.2 LDG 2041		O/C			
340008 LEFT	AOA/STALL WARNING TRANSMITTER			0863A1-2 784	MTH 01-Dec-2010		O/C	0		
340008 RIGHT	AOA/STALL WARNING TRANSMITTER	SZB		0863A1-2 459	MTH 07-Jun-2011 HRS 163 LDG 73		O/C			
340011 LEFT	MCDU DISPLAY MC-850	SZB		7033700-910 07080152	MTH 19-Dec-2012 HRS 653 LDG 383		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
340011 RIGHT	MCDU DISPLAY MC-850	7033700-910 08090595	MTH 27-May-2015 HRS 1246 LDG 785		O/C			
340016 LEFT	CABINET W/ADF RADIO MODULE MRC-855	7517959-902 09062255	MTH 01-Dec-2010		O/C	0		
340016 RIGHT	CABINET W/ADF RADIO MODULE MRC-855	7517959-902 10067383	MTH 01-Dec-2010		O/C	0		
340017 LEFT	NTWK INTERFACE MODULE NI-900	7517964-802 08044180	MTH 26-Dec-2024 HRS 2724.8 LDG 2060		O/C			
340017 RIGHT	NTWK INTERFACE MODULE NI-900	7517964-802 10067180	MTH 26-Dec-2024 HRS 2724.8 LDG 2060		O/C			
340018 NO. 1	MAU POWER SUPPLY MODULE PWR-902	7024440-1901 1005I516	MTH 01-Dec-2010		O/C	0		
340018 NO. 2	MAU POWER SUPPLY MODULE PWR-902	7024440-1901 1005I517	MTH 01-Dec-2010		O/C	0		
340018 NO. 3	MAU POWER SUPPLY MODULE PWR-902	7024440-1901 1005I518	MTH 01-Dec-2010		O/C	0		
340018 NO. 4	MAU POWER SUPPLY MODULE PWR-902	7024440-1901 1005I519	MTH 01-Dec-2010		O/C	0		
340019 L1	GENERIC I/O MODULE	7025364-1901 10055782	MTH 01-Dec-2010		O/C	0		
340019 L2	GENERIC I/O MODULE	7025364-1901 10055784	MTH 01-Dec-2010		O/C	0		
340019 R1	GENERIC I/O MODULE	7025364-1901 10065818	MTH 18-Nov-2010		O/C	0		
340019 R2	GENERIC I/O MODULE	7025364-1901 10055799	MTH 01-Dec-2010		O/C	0		
340020 LEFT	CUSTOM I/O MODULE	7029685-1901 09030739	MTH 05-Feb-2012 HRS 352 LDG 192		O/C			
340020 RIGHT	CUSTOM I/O MODULE	7029685-1901 09030741	MTH 05-Feb-2012 HRS 352 LDG 192		O/C			
340021 NO. 1	DATA BASE MODULE DBM-901	7026532-1903 10055314	MTH 01-Dec-2010		O/C	0		
340022 NO. 2	CONTROL I/O MODULE	7026534-1902 09075430	MTH 08-Jan-2020 HRS 2197 LDG 1582		O/C	0		
340022 NO. 3	CONTROL I/O MODULE	7026534-1902 07103043	MTH 14-May-2025 HRS 2746.6 LDG 2091		O/C			
340023 NO. 1	DUAL NIC PROCESSOR NIC-901	7026542-1901 1006G571	MTH 01-Dec-2010		O/C	0		
340023 NO. 2	DUAL NIC PROCESSOR NIC-901	7026542-1901 1006G666	MTH 01-Dec-2010		O/C	0		
340023 NO. 3	DUAL NIC PROCESSOR NIC-901	7026542-1901 1006G675	MTH 01-Dec-2010		O/C	0		
340023 NO. 4	DUAL NIC PROCESSOR NIC-901	7026542-1901 1006G696	MTH 01-Dec-2010		O/C	0		
340024	CMC MODULE	7026548-1901 09123262	MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
340025 L1	I/O MODULE DUAL SERV ACTUATOR	SZB		7028432-1901 07074802	MTH 10-Jun-2019 HRS 2090 LDG 1488		O/C			
340025 L2	I/O MODULE DUAL SERV ACTUATOR	SZB		7028432-1901 07074799	MTH 10-Jun-2019 HRS 2090 LDG 1488		O/C			
340025 R1	I/O MODULE DUAL SERV ACTUATOR			7028432-1901 1005B729	MTH 01-Dec-2010		O/C	0		
340025 R2	I/O MODULE DUAL SERV ACTUATOR			7028432-1901 1005B770	MTH 01-Dec-2010		O/C	0		
340027 LEFT	CURSOR CONTROLLER CC-950			7028610-903 09040765	MTH 01-Dec-2010		O/C	0		
340027 RIGHT	CURSOR CONTROLLER CC-950			7028610-903 09050766	MTH 01-Dec-2010		O/C	0		
340033 NO. 1	AIR DATA MODULE	SZB		HG1153CA04 11084889	MTH 30-Jun-2015 HRS 1290 LDG 813		O/C			
340033 NO. 2	AIR DATA MODULE	SZB		HG1153CA04 10054260	MTH 22-Sep-2011 HRS 244 LDG 127		O/C	0 0 0		
340034	ANGLE OF ATTACK INDEXER			0031AM 339	MTH 01-Dec-2010		O/C	0		
340037	MAGNETOMETER MAG-3000			501-1826-01 3981	MTH 01-Dec-2010		O/C	0		
340039	ROTARY SOLENOID			70R10461-2 0371	MTH 01-Dec-2010		O/C	0		
340040 LEFT	AHRS COMPUTER AHC-3000			822-1110-002 3WFXL	MTH 01-Dec-2010		O/C	0		
340040 RIGHT	AHRS COMPUTER AHC-3000			822-1110-002 3WIFYK	MTH 01-Dec-2010		O/C	0		
340042 LOWER	FLUX DETECTOR			822-1193-001 300024	MTH 01-Dec-2010		O/C	0		
340042 UPPER	FLUX DETECTOR			822-1193-001 300030	MTH 01-Dec-2010		O/C	0		
340045	GLIDESLOPE ANTENNA			RGS10-48 15071	MTH 01-Dec-2010		O/C	0		
340046	GLIDESLOPE ANTENNA COUPLER			CI503 119876	MTH 01-Dec-2010		O/C	0		
340049 LEFT	CONFIGURATION MODULE IM-950			7519272-901 3086280	MTH 01-Dec-2010		O/C	0		
340049 RIGHT	CONFIGURATION MODULE IM-950			7519272-901 3608621	MTH 01-Dec-2010		O/C	0		
340050 NO. 1	ATC TRANSPONDER	WSSL		7517402-970 0703C406	MTH 13-Jul-2017 HRS 1726 LDG 1160		O/C	0 0		
340050 NO. 2	ATC TRANSPONDER	SZB		7517402-970 0707C948	MTH 04-Jan-2023 HRS 2558.4 LDG 1888		O/C			
340051 LEFT	GPS MODULE	SZB		245-604067-100 07062274	MTH 23-Nov-2023 HRS 2663.2 LDG 1995		O/C	73 0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
340051 RIGHT	GPS MODULE	SZB		245-604067-100 03110225	MTH 03-Mar-2020 HRS 2243 LDG 1623		O/C			
340052 NO. 1	IRIDIUM/GPS ANTENNA	WSSL		S67-1575-135 818-7238	MTH 13-Jul-2017 HRS 1726 LDG 1160		O/C	0 0		
340052 NO. 2	IRIDIUM/GPS ANTENNA	WSSL		S67-1575-135 818-2477	MTH 13-Jul-2017 HRS 1726 LDG 1160		O/C	0 0		
340053	DETACHABLE CONFIGURATION MODULE *CF			501-1803-84 3416	MTH 21-Nov-2010		O/C	0		
340055 NO. 1 UPPER	TCAS ANTENNA			7514081-910 ANE34850	MTH 01-Dec-2010		O/C	0		
340055 NO. 2 LOWER	TCAS ANTENNA			7514081-910 ANE34726	MTH 01-Dec-2010		O/C	0		
340061	RADAR RECEIVER/TRANSMITTER ANTENNA WU-880	SZB		7021450-801 97100348	MTH 09-May-2025 HRS 2746.6 LDG 2091		O/C	108 891		
340062	MARKER BEACON ANTENNA			CI165 277446	MTH 01-Dec-2010		O/C	0		
340065	ADVANCED GRAPHIC MODULE AFGS	SZB		7036410-1901 11077940	MTH 14-Nov-2019 HRS 2163 LDG 1553		O/C			
341000	SECONDARY FLIGHT DISPLAY GH-3000			501-1741-2104 2509B	MTH 01-Dec-2010		O/C	0		
341002 STANDBY	AIR DATA MODULE	SZB		501-1881-05 2471	MTH 16-Feb-2019 HRS 2013 LDG 1419		O/C			
341200 NO. 1	RADIO ALTIMETER ANTENNA			S67-2002-4 55215777	MTH 01-Dec-2010		O/C	0		
341200 NO. 2	RADIO ALTIMETER ANTENNA			S67-2002-4 55215776	MTH 01-Dec-2010		O/C	0		
341700 NO. 1	MAU CABINET-9 SLOT --			7031631-1950 NSN	MTH 01-Dec-2010		O/C	0		
341700 NO. 2	MAU CABINET-9 SLOT --			7031631-1950 NSN	MTH 01-Dec-2010		O/C	0		
341700 NO. 3	MAU CABINET-5 SLOT TAILCONE --			7031631-1951 NSN	MTH 01-Dec-2010		O/C	0		
341700 NO. 4	MAU CABINET-5 SLOT TAILCONE --			7031631-1951 NSN	MTH 01-Dec-2010		O/C	0		
342001 LEFT	EXTERNAL COMPENSATION UNIT			822-1200-005 3WFFG	MTH 01-Dec-2010		O/C	0		
342001 RIGHT	EXTERNAL COMPENSATION UNIT			822-1200-005 3WFFH	MTH 01-Dec-2010		O/C	0		
344001	RADIO ALTIMETER			7001840-936 0904F747	MTH 01-Dec-2010		O/C	0		
344100	WEATHER RADAR CONTROL WC 880 CONTROLLER			7008471-415 05048289	MTH 01-Dec-2010		O/C	0		
345000	DATA MANAGEMENT UNIT ICT			7031051-904 08121916	MTH 11-Nov-2010		O/C	0		
345001 NO. 1	ADF RECEIVER MODULE DF-855			7510114-855 1005E597	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345002 NO. 1	REVERSIONARY CONTROLLER			8914001-16 NSN	MTH 01-Dec-2010		O/C	0		
345002 NO. 2	REVERSIONARY CONTROLLER			8914001-16 NSN	MTH 01-Dec-2010		O/C	0		
345003 NO. 1	DME MODULE DM-855			7510184-855 1005G007	MTH 01-Dec-2010		O/C	0		
345003 NO. 2	DME MODULE DM-855			7510184-855 1006G023	MTH 01-Dec-2010		O/C	0		
345004 NO. 1	ADF ANTENNA S3100-17			7510300-901 0811F288	MTH 01-Dec-2010		O/C	0		
345005 NO. 1	NAV RADIO MODULE			7026202-805 10055682	MTH 01-Dec-2010		O/C	0		
345005 NO. 2	NAV RADIO MODULE	SZB		7026202-805 08063549	MTH 15-Jan-2024 HRS 2683 LDG 2011		O/C			
345006 NO. 1	MULTI FUNCTION DISPLAY DU-1080	SZB	A-C, G, J	7037620-811 09089270	MTH 26-Dec-2024 HRS 2724.8 LDG 2060		O/C	0 0		
345006 NO. 2	MULTI FUNCTION DISPLAY DU-1080	SZB		7037620-811 07115212	MTH 14-Sep-2023 HRS 2647.2 LDG 1983		O/C			
345006 NO. 3	MULTI FUNCTION DISPLAY DU-1080	SZB		7037620-811 1105A917	MTH 16-Oct-2018 HRS 1954 LDG 1366		O/C			
345006 NO. 4	MULTI FUNCTION DISPLAY DU-1080	SZB		7037620-811 1102A662	MTH 31-Jan-2024 HRS 2683 LDG 2011		O/C	1 0		
345007 LEFT	NAV ANTENNA			CI120-200G/S-L 326229	MTH 01-Dec-2010		O/C	0		
345007 RIGHT	NAV ANTENNA			CI120-200G/S-L 326230	MTH 01-Dec-2010		O/C	0		
345007	NAV ANTENNA COUPLER			CI120-5 326264	MTH 01-Dec-2010		O/C	0		
345008 LEFT	DME ANTENNA			DMNI50-2-2 119058	MTH 01-Dec-2010		O/C	0		
345008 RIGHT	DME ANTENNA			DMNI50-2-2 119050	MTH 01-Dec-2010		O/C	0		
345009 NO. 1 LOWER	TRANSPONDER ANTENNA 85226			DMNI50-2-2 119100	MTH 01-Dec-2010		O/C	0		
345009 NO. 2 LOWER	TRANSPONDER ANTENNA			DMNI50-2-2 118936	MTH 01-Dec-2010		O/C	0		
346000	TCAS PROCESSOR	SZB		7517900-55020 99112914	MTH 18-May-2016 HRS 1472 LDG 958		O/C	0 0		
346001 NO. 1	DISPLAY CONTROLLER DC-840			7016683-971 10054686	MTH 01-Dec-2010		O/C	0		
346001 NO. 2	DISPLAY CONTROLLER DC-840			7016683-971 10054687	MTH 01-Dec-2010		O/C	0		
35-00-20-9600 LEFT 350001	EXTENDED RANGE OXYGEN BOTTLE DISCARD ASSEMBLY	SZB		804822-14 C130702223B	MTH 03-May-2024 HRS 2694.5 LDG 2023		180	132	31-May-2028	35 m 21 d

Manufacture Date: 31-May-2013



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
35-00-30-9600 RIGHT 350001	STANDARD OXYGEN BOTTLE DISCARD ASSEMBLY SZB	804822-14 C11060410	MTH HRS LDG	03-May-2024 2694.5 2023		180	13	30-Apr-2038	154 m 20 d	
Manufacture Date: 30-Apr-2023										
35-30-00-9600 353005	802300-14 PROTECTIVE BREATHINGEQUIPMENT DISCARD EQUIPMENT	- -				N/A				
350002 AFT	OXYGEN PRESSURE GAUGE MD-97	C668512-0101 F1010528	MTH	01-Dec-2010		O/C	0			
350002 FORWARD	OXYGEN PRESSURE GAUGE MD-97	C668512-0101 F1010529	MTH	01-Dec-2010		O/C	0			
350002 LEFT	INSIDE OXYGEN PRESSURE GAUGE MD-97	C668512-0101 F1010521	MTH	01-Dec-2010		O/C	0			
350002 RIGHT	INSIDE OXYGEN PRESSURE GAUGE MD-97	C668512-0101 F1010525	MTH	01-Dec-2010		O/C	0			
350003 COPILOT	OXYGEN MASK SZB	MLC20-505 122244	MTH HRS LDG	31-Oct-2022 2531.7 1867		O/C	0 0 0			
350003 PILOT	OXYGEN MASK SZB	MLC20-505 B117572	MTH HRS LDG	31-Oct-2022 2531.7 1867		O/C	0 0 0			
350004	CABIN PRESSURE CONTROL VALVE 9914067-19	P21006 3170	MTH	01-Dec-2010		O/C	0			
350005 EXTERNAL	CHARGE VALVE 9912057-13	P21010 5950	MTH	01-Dec-2010		O/C	0			
350005	CHARGE VALVE 9912057-13	P21010 5928	MTH	01-Dec-2010		O/C	0			
350006 NO. 1	OXYGEN REGULATOR SZB	P21087-1 1309	MTH HRS LDG	20-Sep-2019 2119 1514		O/C	4 0			
353000	PORTABLE EMER OXYGEN BOTTLE -- SZB	9914067-47 P19043251	MTH HRS LDG	07-Mar-2024 2692 2020		O/C	4 0			
353001	EMERGENCY OXYGEN BOTTLE SZB	5500-M6W-FF23AN P20081199	MTH HRS LDG	06-Jun-2025 2755.3 2103		O/C	1 0			
360001 LEFT ENGINE	LOW PRESSURE BLEED AIR CHECK VALVE	4011-18 0729	MTH	01-Dec-2010		O/C	0			
360001 RIGHT ENGINE	LOW PRESSURE BLEED AIR CHECK VALVE	4011-18 0731	MTH	01-Dec-2010		O/C	0			
360004 LEFT	RAM DOOR ACTUATOR SZB	1E50-3 9BA66	MTH HRS LDG	31-Jul-2013 778 468		O/C	0 0			
360004 RIGHT	RAM DOOR ACTUATOR SZB	1E50-3 6AW17	MTH HRS LDG	29-Sep-2021 2406 1771		O/C				
360008 CENTER	APU VALVE 9914171-1	8C210 8753	MTH	01-Dec-2010		O/C	0			
360008 LEFT	VALVE 9914171-1	8C210 8773	MTH	01-Dec-2010		O/C	0			



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
360008 RIGHT	VALVE 9914171-2			8C210-1 8782	MTH 01-Dec-2010		O/C	0		
360009	SERVICE AIR VALVE			38E109-15 N081143	MTH 01-Dec-2010		O/C	0		
360012 LEFT INBOARD	HP BLEED REGULATOR VALVE 9914520-2			C144873-2 2923	MTH 01-Dec-2010		O/C	0		
360012 LEFT OUTBOARD	HP BLEED REGULATOR VALVE 9914520-2			C144873-2 2924	MTH 01-Dec-2010		O/C	0		
360012 RIGHT INBOARD	HP BLEED REGULATOR VALVE 9914520-2			C144873-2 2944	MTH 01-Dec-2010		O/C	0		
360012 RIGHT OUTBOARD	HP BLEED REGULATOR VALVE 9914520-2			C144873-2 2959	MTH 01-Dec-2010		O/C	0		
360013 CENTER	ENGINE BLEED SHUTOFF VALVE 9914552-3			2602-48 1014C	MTH 01-Dec-2010		O/C	0		
360013 LEFT	ENGINE BLEED SHUTOFF VALVE 9914552-1			2602-33 2121	MTH 01-Dec-2010		O/C	0		
360013 RIGHT	ENGINE BLEED SHUTOFF VALVE 9914552-1			2602-33 2194	MTH 01-Dec-2010		O/C	0		
361000	SOLENOID ENGINE VALVE			5035-00-1 1627	MTH 01-Dec-2010		O/C	0		
361102 LEFT	BLEED AIR OVERHEAT TEMPERATURE SENSOR 9914519-2			1E51-1 7BF14	MTH 01-Dec-2010		O/C	0		
361102 RIGHT	BLEED AIR OVERHEAT TEMPERATURE SENSOR 9914519-2			1E51-1 7BF34	MTH 01-Dec-2010		O/C	0		
361103 LEFT	PRE-COOLER TEMPERATURE CONTROL SENSOR 9914519-2			1E51-1 7BF35	MTH 01-Dec-2010		O/C	0		
361103 RIGHT	PRE-COOLER TEMPERATURE CONTROL SENSOR 9914519-2			1E51-1 7BF36	MTH 01-Dec-2010		O/C	0		
370001	VACUUM CHECK VALVE 9914487-2			130158-1 704773	MTH 01-Dec-2010		O/C	0		
49APU1	APU 9914657-1			3800785-1 P-502	MTH 22-Aug-2016 HRS 1530 LDG 1012		E/C	1198.9		
490001	APU FLOW CONTROL SHUTOFF VALVE SZB			1413-19 0577	APUH 21-Feb-2012 APUS 260 362		O/C			
490002	APU FIRE DETECTION ELEMENT 9912416-1			3001-212-1004/455-9 210982	01-Dec-2010		O/C	0		
490003	APU ELECTRONIC CONTROL UNIT 9914657-2			2119552-3 108L0430	01-Dec-2010		O/C	0		
490004	APU INDICATOR 9914715-2			MD680-4 G1010028	01-Dec-2010		O/C	0		
490005	APU AMMETER S3439-5			MD144-5 C1010538	01-Dec-2010		O/C	0		
490006	APU IGNITION EXCITER 9049300-2			3888000-7 080218092517	01-Dec-2010		O/C	0		
490007	APU PUMP ASSEMBLY			3881825-1 P-1584	01-Dec-2010		O/C	0		
490008	APU FUEL CONTROL			3883900-1 0601525	01-Dec-2010		O/C	0		
490009	APU OIL TEMP SENSOR			102-00002 NSN	01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
490010	COMPRESSOR ROTOR	SZB		3822523-003 15-162053-15850	APUH 05-Sep-2016 APUS 1239 1472		36000	0 0 0	37472	34354
490011	TURBINE ROTOR	SZB		3842340-2 08-01345-11362	APUH 05-Sep-2016 APUS 1239 1472		12000	1472	12000	8882
490012	IGNITER PLUG	SZB		304634-2 N/A	APUH 22-Jul-2024 APUS 2528.8 3019		O/C	0 0		
490013	APU LOW OIL LEVEL SWITCH			3876318-2 NSN	01-Dec-2010		O/C	0		
490014	APU LOW OIL PRESSURE SWITCH			3876351-1 NSN	01-Dec-2010		O/C	0		
490016	APU HOURMETER			C664503-0104 NSN	01-Dec-2010		O/C	0		
490017	FLOW DIVIDER			3883921-2 NSN	01-Dec-2010		O/C	0		
490022	ENGINE BRANCHED WIRING HARNESS (LEFT FORWARD)			PN SN-UNKNOWN	01-Dec-2010		O/C	0		
520001 AFT	LOWER AFT ACOUSTIC DOOR SEAL 9919042-2			9678-2 NSN	MTH 01-Dec-2010		O/C	0		
520001 FORWARD	LOWER FORWARD ACOUSTIC DOOR SEAL 9919042-2			9678-2 NSN	MTH 01-Dec-2010		O/C	0		
520001 UPPER	TOP ACOUSTIC DOOR SEAL 9919042-1	SZB		9678-1 0330	MTH 25-Mar-2025 HRS 2735.6 LDG 2077		O/C	0 0		
520003 LEFT	INTERFACE CARD SENSOR			80-060-01 A213	MTH 01-Dec-2010		O/C	0		
520005	ESCAPE HATCH SEAL 9914713-1			G04046-4 NSN	MTH 01-Dec-2010		O/C	0		
525001	CABIN DOOR SEAL 9914684-1			CG040443 NSN	MTH 01-Dec-2010		O/C	0		
531001 LEFT	NOSE LANDING GEAR TRUNNION ATTACH SUPPORT ASSEMBLY			6913052-2 306	MTH 01-Dec-2010		H/T H/T	0		
531001 RIGHT	NOSE LANDING GEAR TRUNNION ATTACH SUPPORT ASSEMBLY			6913052-2 306	MTH 01-Dec-2010		H/T H/T	0		
531002	NOSE LANDING GEAR ACTUATOR FITTING ASSEMBLY			6711060-49 306	MTH 01-Dec-2010		H/T H/T	0		
561302 LEFT FORWARD	WINDOW 9914379-7			NP139722-7 10152H7798	MTH 01-Dec-2010		O/C	0		
561302 RIGHT FORWARD	WINDOW 9914379-8			NP139722-8 10155H8159	MTH 01-Dec-2010		O/C	0		
561303 LEFT	WINDSHIELD ASSY, (LH) NP139731-1	SZB		9914380-13 24337H9023	MTH 03-Jan-2025 HRS 2725.6 LDG 2061		O/C	0 0		
561303 RIGHT	WINDSHIELD ASSY, (RH) NP139731-2	SZB		9914380-14 24254H0991	MTH 26-Dec-2024 HRS 2724.8 LDG 2060		O/C	0 0		
561304 LEFT NO. 1	CABIN WINDOW 6711139-3			6711139-3 4915	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561304 LEFT NO. 2	CABIN WINDOW 6711139-3			6711139-3 4982	MTH 01-Dec-2010		O/C	0		
561304 LEFT NO. 3	CABIN WINDOW 6711139-3			6711139-3 4922	MTH 01-Dec-2010		O/C	0		
561304 LEFT NO. 4	CABIN WINDOW 6711139-3			6711139-3 5006	MTH 01-Dec-2010		O/C	0		
561304 LEFT NO. 5	CABIN WINDOW 6711139-3			6711139-3 5015	MTH 01-Dec-2010		O/C	0		
561304 LEFT NO. 6	CABIN WINDOW 6711139-3			6711139-3 4980	MTH 01-Dec-2010		O/C	0		
561304 LEFT NO. 7	CABIN WINDOW 6711139-3			6711139-3 5638	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 11	CABIN WINDOW 6711139-3			6711139-3 5235	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 1	CABIN WINDOW 6711139-3			6711139-3 5646	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 2	CABIN WINDOW 6711139-3			6711139-3 5650	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 3	CABIN WINDOW 6711139-3			6711139-3 5651	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 4	CABIN WINDOW 6711139-3			6711139-3 5637	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 5	CABIN WINDOW 6711139-3			6711139-3 5634	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 6	CABIN WINDOW 6711139-3			6711139-3 5643	MTH 01-Dec-2010		O/C	0		
561304 RIGHT NO. 7	CABIN WINDOW 6711139-3			6711139-3 5641	MTH 01-Dec-2010		O/C	0		
561305 LEFT AFT	FOUL WEATHER WINDOW 9914116-33			93102-33 2761	MTH 01-Dec-2010		O/C	0		
561305 RIGHT AFT	FOUL WEATHER WINDOW 9914116-34			93102-34 2896	MTH 01-Dec-2010		O/C	0		
571001 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR REAR SPAR TRUNNION SUPPORT 6922439-1			306	MTH 01-Dec-2010		H/T H/T	0		
571001 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR REAR SPAR TRUNNION SUPPORT 6922439-2			306	MTH 01-Dec-2010		H/T H/T	0		
571002 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR CENTER SPAR TRUNNION FITTING 6922429-1			306	MTH 01-Dec-2010		H/T H/T	0		
571002 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR CENTER SPAR TRUNNION FITTING 6922429-2			306	MTH 01-Dec-2010		H/T H/T	0		
571003 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR SIDE BRACE FITTING ASSEMBLY 6922428-1			306	MTH 01-Dec-2010		H/T H/T	0		
571003 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR SIDE BRACE FITTING ASSEMBLY 6922428-2			306	MTH 01-Dec-2010		H/T H/T	0		
712001 LEFT	ENGINE AFT ISOLATOR 9914656-15			LM-463-SA5 LK0299	MTH 01-Dec-2010		O/C	0		
712001 RIGHT	ENGINE AFT ISOLATOR 9914656-14			LM-463-SA6 LK0326	MTH 01-Dec-2010		O/C	0		
712002 LEFT BOTTOM	ENGINE FWD ISOLATOR 9914656-21			LM-463-13 LK1430	MTH 01-Dec-2010		O/C	0		
712002 LEFT TOP	ENGINE FWD ISOLATOR 9914656-21			LM-463-13 LK1447	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
712002 RIGHT BOTTOM	ENGINE FWD ISOLATOR 9914656-21	LM-463-13 LK1427	MTH 01-Dec-2010		O/C	0		
712002 RIGHT TOP	ENGINE FWD ISOLATOR 9914656-21	LM-463-13 LK1289	MTH 01-Dec-2010		O/C	0		
712005	ENGINE VIBRATION MONITOR- 9912519-2	2789 080841	MTH 01-Dec-2010		O/C	0		
71EN1 NO. 1	ENGINE PW306C	30B4258-01 PCE-CG0627			E/C			
71EN2 NO. 2	ENGINE PW306C	30B4258-01 PCE-CG0626			E/C			
722001 E1 3RD-STAGE	LP TURBINE DISK	30A2323 MAA60610	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722001 E2 3RD-STAGE	LP TURBINE DISK	30A2323 MAA60650	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722002 E1 4TH-STAGE	LP TURBINE DISK	30A2324 MAA48588	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722002 E2 4TH-STAGE	LP TURBINE DISK	30A2344 ABT01430	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722003 E1 5TH-STAGE	LP TURBINE DISK	30A2305 MAA49909	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722003 E2 5TH-STAGE	LP TURBINE DISK	30A2345 ABT01632	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(12000)12000	9897 12371
722004 E1	LP COMPRESSOR SHAFT	30B3897-01 DDAA008A633	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(22058)22058	19955 27139
722004 E2	LP COMPRESSOR SHAFT	30B3897-01 DDAA008A624	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(22058)22058	19955 27139
722005 E1	HP COMPRESSOR (1ST-STAGE) ROTOR	30B4811-01 A002R6D4	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(15000)15000	12897 12897
722005 E2	HP COMPRESSOR (1ST-STAGE) ROTOR	30B4811-01 A002RFNF	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(15000)15000	12897 12897
722006 E1	(2ND-STAGE) HP COMPRESSOR ROTOR	30B6082-01 A002R4K3	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(15000)15000	12897 12897
722006 E2	(2ND-STAGE) HP COMPRESSOR ROTOR	30B6082-01 A002RT88	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(15000)15000	12897 12897
722007 E1	(3RD-STAGE) HP COMPRESSOR ROTOR	30B3933-01 TXA1C0137	MTH 01-Dec-2010 LDG 0 ACCC YC			0 0	(15000)15000	12897 12897

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
722007 E2	(3RD-STAGE) HP COMPRESSOR ROTOR	30B3933-01 TXA1B7826	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722008 E1	(4TH-STAGE) HP COMPRESSOR ROTOR	30B3934-01 TXA1C0045	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722008 E2	(4TH-STAGE) HP COMPRESSOR ROTOR	30B3934-01 TXA1B8315	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722009 E1	HP TURBINE ROTOR REAR COVER	30B5619-01 A002RL9A	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722009 E2	HP TURBINE ROTOR REAR COVER	30B5619-01 A002RL9B	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722010 E1	HP COMPRESSOR TIE SHAFT	30B4054-01 A002HX4P	MTH 01-Dec-2010		O/C	0		
722010 E2	HP COMPRESSOR TIE SHAFT	30B4054-01 A002HX6C	MTH 01-Dec-2010		O/C	0		
722011 E1	FAN HUB	30B6767-01 A002R47R	MTH 01-Dec-2010 LDG 0 ACCC YC		14000	0 0	(10000)10000	7897 11055
722011 E2	FAN HUB	30B6767-01 A002RMN7	MTH 01-Dec-2010 LDG 0 ACCC YC		14000	0 0	(10000)10000	7897 11055
722012 E1	HP TURBINE ROTOR FRONT COVER	30B6202-01 A002RWLA	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722012 E2	HP TURBINE ROTOR FRONT COVER	30B6202-01 A002R4E8	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722013 E1 1ST-STAGE	HP TURBINE DISK	30B6351-01 A002R283	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722013 E2 1ST-STAGE	HP TURBINE DISK	30B6351-01 A002R284	MTH 01-Dec-2010 LDG 0 ACCC YC		15000	0 0	(15000)15000	12897 12897
722014 E1 2ND-STAGE	HP TURBINE DISK	30B4642-01 A002RLLC	MTH 01-Dec-2010 LDG 0 ACCC YC		10000	0 0	(10000)10000	7897 7897
722014 E2 2ND-STAGE	HP TURBINE DISK	30B4642-01 A002T3H3	MTH 01-Dec-2010 LDG 0 ACCC YC		10000	0 0	(10000)10000	7897 7897
722015 E1	HP COMPRESSOR SHAFT	30B4697-01 EAAC000A738	MTH 01-Dec-2010		O/C	0		
722015 E2	HP COMPRESSOR SHAFT	30B4697-01 EAAC000A331	MTH 01-Dec-2010		O/C	0		
722016 E1	STUB COMPRESSOR ROTOR SHAFT	30B4737-01 EAAC000C106	MTH 01-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
722016 E2	STUB COMPRESSOR ROTOR SHAFT			30B4737-01 EAAC000C101	MTH 01-Dec-2010		O/C	0		
722017 E1	CENTRIFUGAL IMPELLER			30B4796-01 A002RW4X	MTH 01-Dec-2010 LDG 0			0	(6593)6593	4490
				ACCC YC			6000			4086
722017 E2	CENTRIFUGAL IMPELLER			30B4796-01 A002RN0P	MTH 01-Dec-2010 LDG 0			0	(6593)6593	4490
				ACCC YC			6000			4086
722019 E1	FIRST STAGE HP TURBINE BLADES			30B6501-01 -	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
					LDG 0		6000	0	(6000)6000	3897
722019 E2	FIRST STAGE HP TURBINE BLADES			30B6501-01 -	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
					LDG 0		6000	0	(6000)6000	3897
722020 E1	2ND STAGE HIGH TURBINE BLADES			30B4934-01 SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
					LDG 0		6000	0	(6000)6000	3897
722020 E2	2ND STAGE HIGH TURBINE BLADES			30B4934-01 SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
					LDG 0		6000	0	(6000)6000	3897
722021 E1	HP TURBINE ROTOR AIR SEAL			31B6205-01 AWE012744	MTH 01-Dec-2010 LDG 0			0	(15000)15000	12897
				ACCC YC			15000			12897
722021 E2	HP TURBINE ROTOR AIR SEAL			31B6205-01 AWE013182	MTH 01-Dec-2010 LDG 0			0	(15000)15000	12897
				ACCC YC			15000			12897
722023 E1 INBOARD	P1/T1 SENSOR			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
722023 E1 OUTBOARD	P1/T1 SENSOR			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
722023 E2 INBOARD	P1/T1 SENSOR			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
722023 E2 OUTBOARD	P1/T1 SENSOR			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
726010 E1	AGB STARTER PAD SEAL SZB			30B5898-01 N/A	MTH 06-Mar-2023 HRS 2579		400	0	(2979)2979	223.7
					LDG 1912					
726010 E2	AGB STARTER PAD SEAL SZB			30B5898-01 N/A	MTH 09-May-2023 HRS 2597		400	0	(2997)2997	241.7
					LDG 1933					
726012 E1	ALTERNATOR PAD SEAL SZB			30B5899-01 N/A	MTH 06-Mar-2023 HRS 2579		400	0	(2979)2979	223.7
					LDG 1912					
726012 E2	ALTERNATOR PAD SEAL SZB			30B5899-01 N/A	MTH 30-Jun-2023 HRS 2606.9		400	0	(3006.9)3006.9	251.6
					LDG 1943					
731002 LEFT	FUEL PRESSURE SWITCH 9914488-2			SPDG6435 0811329	MTH 01-Dec-2010		O/C	0		
731002 RIGHT	FUEL PRESSURE SWITCH 9914488-2			SPDG6435 0806285	MTH 01-Dec-2010		O/C	0		
730001 E1	FUEL FLOW TRANSMITTER 9914515-2			9-127-96 105998687	MTH 01-Dec-2010		O/C	0		
730001 E2	FUEL FLOW TRANSMITTER 9914515-2			9-127-96 105998652	MTH 01-Dec-2010		O/C	0		
731008 E1	FUEL SHUTOFF CABLE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731008 E2	FUEL SHUTOFF CABLE			PN SN-UNKNOWN	MTH 01-Dec-2010 HRS 0			0	(6000)6000	3244.7
731010 E1	FUEL FILTER	SZB		31B3702-01 N/A	MTH 06-Apr-2022 HRS 2438.3 LDG 1790		6000 1200	0	(3638.3)3638.3	883
731010 E2	FUEL FILTER	SZB		31B3702-01 N/A	MTH 06-Apr-2022 HRS 2438.3 LDG 1790		1200	0	(3638.3)3638.3	883
731060 E1	FUEL WASTE EJECTOR			30B6023-05 20227	MTH 01-Dec-2010		O/C	0		
731060 E2	FUEL WASTE EJECTOR			30B6023-05 20084	MTH 01-Dec-2010		O/C	0		
731090 E1	VALVE FUEL SHUTOFF			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
731090 E2	VALVE FUEL SHUTOFF			PN SN-UNKNOWN	MTH 01-Dec-2010		O/C	0		
732001 E1	ENGINE ELECTRONIC CONTROL 30B4982-05	SZB		822822-4-005 07115289	MTH 22-Dec-2022 HRS 2548.3 LDG 1881		O/C	0		
732001 E2	ENGINE ELECTRONIC CONTROL 30B4982-05	SZB		822822-4-005 10050016	MTH 22-Dec-2022 HRS 2548.3 LDG 1881		O/C	0		
732002 E1	HYDRO MECH FUEL CONTROL	SZB		30B5449-05 15058923	MTH 02-Mar-2023 HRS 2579 LDG 1912		O/C	3 0		
732002 E2	HYDRO MECH FUEL CONTROL			30B5449-05 16954124	MTH 01-Dec-2010		O/C	0		
732004 E1	FUEL, START & DUMP VALVE 31B5131-01			26240-5 9959517175	MTH 01-Dec-2010		O/C	0		
732004 E2	FUEL, START & DUMP VALVE 31B5131-01			26240-5 9959517174	MTH 01-Dec-2010		O/C	0		
741001I E1 UPPER	IGNITION EXCITER 31B4636-02			9047980-21 NNA10190073	MTH 01-Dec-2010		O/C	0		
741001I E2 UPPER	IGNITION EXCITER 31B4636-02			9047980-21 NNA10190072	MTH 01-Dec-2010		O/C	0		
741001O E1 LOWER	IGNITION EXCITER 31B4636-02			9047980-21 NNA10200211	MTH 01-Dec-2010		O/C	0		
741001O E2 LOWER	IGNITION EXCITER 31B4636-02			9047980-21 NNA10200212	MTH 01-Dec-2010		O/C	0		
742001 E1 INBOARD	UPPER IGNITOR PLUG 31B5168-01			CH34682 NSN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
742001 E2 INBOARD	UPPER IGNITOR PLUG 31B5168-01			CH34682 NSN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
742002 E1 OUTBOARD	LOWER IGNITOR PLUG 31B5168-01			CH34682 NSN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
742002 E2 OUTBOARD	LOWER IGNITOR PLUG 31B5168-01			CH34682 NSN	MTH 01-Dec-2010 HRS 0		6000	0	(6000)6000	3244.7
742003 E1 UPPER	TOP IGNITOR LEAD 31B3615-02			CH53238-1 NSN	MTH 01-Dec-2010		O/C	0		
742003 E2 UPPER	TOP IGNITOR LEAD 31B3615-02			CH53238-1 NSN	MTH 01-Dec-2010		O/C	0		
742004 E1 LOWER	BOTTOM IGNITOR LEAD 31B3615-02			CH53238-1 NSN	MTH 01-Dec-2010		O/C	0		
742004 E2 LOWER	BOTTOM IGNITOR LEAD 31B3615-02			CH53238-1 NSN	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
75-30-03.5 E2	P3 TRANSDUCER	SZB		30B3033-03A KL19056372	MTH 16-Aug-2024 HRS 2724 LDG 2059		O/C	0 0 0		
751001 E1	SOLENOID, CPRSR BLEED VALVE			30B6399-02 KFA485	MTH 01-Dec-2010		O/C	0		
751001 E2	SOLENOID, CPRSR BLEED VALVE			30B6399-02 KFA486	MTH 01-Dec-2010		O/C	0		
751002 E1	LINEAR ACTUATOR 31B5255-01			2600-1 SAU10009	MTH 01-Dec-2010		O/C	0		
751002 E2	LINEAR ACTUATOR 31B5255-01			2600-1 SAU10002	MTH 01-Dec-2010		O/C	0		
751005 E1 LEFT	P2.5 BLEED VALVE			31B5759-01 AHX016464	MTH 01-Dec-2010		O/C	0		
751005 E2 LEFT	P2.5 BLEED VALVE			31B5759-01 AHX016492	MTH 01-Dec-2010		O/C	0		
751006 E1 RIGHT	P2.5 BLEED VALVE			31B5759-01 AHX016465	MTH 01-Dec-2010		O/C	0		
751006 E2 RIGHT	P2.5 BLEED VALVE			31B5759-01 AHX016605	MTH 01-Dec-2010		O/C	0		
751007 E1 TOP	P2.8 BLEED VALVE			31B5756-01 AHX016249	MTH 01-Dec-2010		O/C	0		
751007 E2 TOP	P2.8 BLEED VALVE			31B5756-01 AHX016338	MTH 01-Dec-2010		O/C	0		
751008 E1 BOTTOM	P2.8 BLEED VALVE			31B5756-01 AHX016392	MTH 01-Dec-2010		O/C	0		
751008 E2 BOTTOM	P2.8 BLEED VALVE			31B5756-01 AHX016485	MTH 01-Dec-2010		O/C	0		
761001 E1	ENGINE DIAGNOSTIC UNIT 30B5287-06			822492-2-006 10070010	MTH 01-Dec-2010		O/C	0		
761001 E2	ENGINE DIAGNOSTIC UNIT 30B5287-06			822492-2-006 10060015	MTH 01-Dec-2010		O/C	0		
770001	STANDBY ENGINE INDICATOR			10677N03M01 0532	MTH 01-Dec-2010		O/C	0		
771001 L1	SPEED N1 SENSOR			30B3623-06 CH2307	MTH 01-Dec-2010		O/C	0		
771001 L2	SPEED N1 SENSOR			30B3623-06 CH2318	MTH 01-Dec-2010		O/C	0		
771001 R1	SPEED N1 SENSOR			30B3623-06 CH2302	MTH 01-Dec-2010		O/C	0		
771001 R2	SPEED N1 SENSOR			30B3623-06 CH2309	MTH 01-Dec-2010		O/C	0		
773001 LEFT	ENGINE ACCELEROMETER			6222SM15 21891	MTH 01-Dec-2010		O/C	0		
773001 RIGHT	ENGINE ACCELEROMETER			6222SM15 21894	MTH 01-Dec-2010		O/C	0		
771002 E1	FIRE AND OVERHEAT SENSOR			30B5702-01 133542	MTH 01-Dec-2010		O/C	0		
771002 E2	FIRE AND OVERHEAT SENSOR			30B5702-01 133886	MTH 01-Dec-2010		O/C	0		
780002 LEFT	THRUST REVERSER			07ND78001-1 SVN6197	MTH 01-Dec-2010		O/C	0		
780002 RIGHT	THRUST REVERSER			07ND78001-2 SVN618	MTH 01-Dec-2010		O/C	0		
780003 LEFT	THRUST REVERSER CONTROL VALVE			07ND78016-9 444	MTH 01-Dec-2010		O/C	0		
780003 RIGHT	THRUST REVERSER CONTROL VALVE			07ND78016-9 0427	MTH 01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
780004 LEFT INBOARD	THRUST REVERSER ACTUATOR 07ND78401-8 01624	MTH	01-Dec-2010		O/C	0		
780004 LEFT OUTBOARD	THRUST REVERSER ACTUATOR 07ND78401-7 01599	MTH	01-Dec-2010		O/C	0		
780004 RIGHT INBOARD	THRUST REVERSER ACTUATOR 07ND78401-7 01622	MTH	01-Dec-2010		O/C	0		
780004 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 07ND78401-8 01623	MTH	01-Dec-2010		O/C	0		
780005 LEFT	THRUST REVERSER MANIFOLD 9914646-10 0803	MTH	01-Dec-2010		O/C	0		
780005 RIGHT	THRUST REVERSER MANIFOLD 9914646-10 0921	MTH	01-Dec-2010		O/C	0		
780006 LEFT	THRUST REVERSER WIRING HARNESS 07ND78303-3 SVN60487	MTH	01-Dec-2010		O/C	0		
780006 RIGHT	THRUST REVERSER WIRING HARNESS 07ND78303-3 SVN59985	MTH	01-Dec-2010		O/C	0		
783102 LEFT	DEPLOY LIMIT S4 SWITCH 07ND78311-3 NSN	MTH	01-Dec-2010		O/C	0		
783102 RIGHT	DEPLOY LIMIT S4 SWITCH 07ND78311-3 NSN	MTH	01-Dec-2010		O/C	0		
783103 LEFT INBOARD	LATCH ACTUATOR S5 SWITCH 07ND78311-1 NSN	MTH	01-Dec-2010		O/C	0		
783103 LEFT OUTBOARD	LATCH ACTUATOR S3 SWITCH 07ND78311-1 NSN	MTH	01-Dec-2010		O/C	0		
783103 RIGHT INBOARD	LATCH ACTUATOR S5 SWITCH 07ND78311-1 NSN	MTH	01-Dec-2010		O/C	0		
783103 RIGHT OUTBOARD	LATCH ACTUATOR S3 SWITCH 07ND78311-1 NSN	MTH	01-Dec-2010		O/C	0		
783104 LEFT INBOARD	UPPER UNLOCK S1 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783104 LEFT OUTBOARD	UPPER UNLOCK S2 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783104 RIGHT INBOARD	UPPER UNLOCK S1 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783104 RIGHT OUTBOARD	UPPER UNLOCK S2 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783105 LEFT INBOARD	LOWER UNLOCK S6 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783105 LEFT OUTBOARD	LOWER UNLOCK S7 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783105 RIGHT INBOARD	LOWER UNLOCK S6 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
783105 RIGHT OUTBOARD	LOWER UNLOCK S7 SWITCH 07ND78311-7 NSN	MTH	01-Dec-2010		O/C	0		
793100 LEFT	ENGINE OIL PRESSURE TRANSMITTER 9912464-1 APTE-237C-1000-250D 780711161	MTH	01-Dec-2010		O/C	0		
793100 RIGHT	ENGINE OIL PRESSURE TRANSMITTER 9912464-1 APTE-237C-1000-250D 780711147	MTH	01-Dec-2010		O/C	0		
793101 LEFT	OIL TEMPERATURE SENSOR 102-00083 07309	MTH	01-Dec-2010		O/C	0		
793101 RIGHT	OIL TEMPERATURE SENSOR 102-00083 07433	MTH	01-Dec-2010		O/C	0		
791001 E1	HEAT FUEL OIL EXCHANGER 31B5790-02 2785	MTH	01-Dec-2010		O/C	0		
791001 E2	HEAT FUEL OIL EXCHANGER 31B5790-02 2788	MTH	01-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
791002 E1	OIL LEVEL SENSOR			30B3851-03 NSN	MTH 01-Dec-2010		O/C	0		
791002 E2	OIL LEVEL SENSOR			30B3851-03 NSN	MTH 01-Dec-2010		O/C	0		
792010 E1	OIL FILTER ELEMENT	SZB		30B6652-01 N/A	MTH 10-Apr-2019 HRS 2063 LDG 1463		1200	0	(3263)3263	507.7
792010 E2	OIL FILTER ELEMENT	SZB		30B6652-01 N/A	MTH 10-Apr-2019 HRS 2063 LDG 1463		1200	0	(3263)3263	507.7
792018 E1	OIL PUMP ASSY			30B6793-01 22A795	MTH 01-Dec-2010		O/C	0		
792018 E2	OIL PUMP ASSY			30B6793-01 22A794	MTH 01-Dec-2010		O/C	0		
80-10-00-9601 LEFT ENGINE 801000	LEFT ENGINE STARTER GENERATOR (REPLACE BEARINGS AND ARMATURE FUNCTIONAL CHECK) RESTORATION - AIRPLANES -0310 AND ON AND AIRPLANES -0001 THRU -0170 INCORPORATING SB680-24-08 AND SB680-49-09 AND AIRPLANES -0171 THRU -0309 INCORPORATING SB680-49-09				MTH 08-Aug-2018					
	9914685-1	SZB		23291-005 P1594	HRS 1907 LDG 1322		1000	0	2907	151.7
80-10-00-9601 RIGHT ENGINE 801000	RIGHT ENGINE STARTER GENERATOR (REPLACE BEARINGS AND ARMATURE FUNCTIONAL CHECK) RESTORATION - AIRPLANES -0310 AND ON AND AIRPLANES -0001 THRU -0170 INCORPORATING SB680-24-08 AND SB680-49-09 AND AIRPLANES -0171 THRU -0309 INCORPORATING SB680-49-09				MTH 20-Jul-2022					
	23291-005	SZB		9914685-1 P1893	HRS 2491.9 LDG 1828		1000	0	3491.9	736.6
80-10-00-9603 APU 801100	AUXILIARY POWER UNIT STARTER GENERATOR (REPLACE BEARINGS AND ARMATURE FUNCTIONAL CHECK) RESTORATION - AIRPLANES -0310 AND ON AND AIRPLANES -0001 THRU -0170 INCORPORATING SB680-24-08 AND SB680-49-09 AND AIRPLANES -0171 THRU -0309 INCORPORATING SB680-49-09				MTH 01-Jun-2022					
	23291-005	SZB		9914685-1 P2139	HRS 2460.8 LDG 1807 APUH 2155.3	-12.3	1200	0	3343	710.8



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 680-02-01	AIRPORT NOISE ABATEMENT INFORMATION			INFORMATIONAL			A/R			
	MOC :									
SL 680-99-01 R03	CESCOM PRICES (THIS SL CANCELS SL680-99-01 R2 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 680-99-02 R01	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 680-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 680-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 680-05-01	CORROSIVE ENVIRONMENT INSPECTION			INFORMATIONAL			O/C			
	MOC :									
SL 680-05-02 R01	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT (SUPERSEDED BY SL680-05-02 R02)			INFORMATIONAL			-			
	MOC :									
SL 680-05-02 R02	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT			INFORMATIONAL			-			
	MOC :									
SL 680-05-02	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT (SUPERSEDED BY SL680-05-02 R01)			INFORMATIONAL			-			
	MOC :									
SL 680-05-03	TIME LIMITS/MAINTENANCE CHECKS - NEW INSPECTION TASK 53-30-00-2500 AND INSPECTION DOCUMENT 25 IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
SL 680-05-04	TIME LIMITS/MAINTENANCE CHECKS - NEW NOSEWHEEL STEERING HOSE REPLACEMENT INTERVAL IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			CANCELLED			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 680-20-01 R01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01 R02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01 R03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01 R04	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01 R05	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01 R06	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 680-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 680-21-08	AIR CONDITIONING - DUCT IMPROVEMENT	SZB	RECOMMENDED	MTH 20-Jul-2016 HRS 1509 LDG 991 APUH 1473.5 APUS 1458			-			Complete
	MOC :			COMPLIED WITH - SB680-21-08 C/OUT I.A.W. SB680-21-08 AND CE680 MM 21-21-03 REV.47.FOUND SATIS.2. TAIL CONE PLUMBING LEAK TEST C/OUT I.A.W. CE680 MM 21-30-00 REV.47. FOUND SATIS.3. FAA FORM 8130-3 NO.4979866 REFERS.						
SL CIL-21-03 R01	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION			INFORMATIONAL			-			
	MOC :									
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION			INFORMATIONAL			-			
	MOC :									
COM MC 680-003	AFM AUTOTHROTTLE LIMITATION G5000 AIRCRAFT			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 680-23-08	COMMUNICATIONS - AIRCELL ATG ANTENNA BONDING IMPROVEMENT			RECOMMENDED			-			
	MOC :									
SB 680-23-10 R03	COMMUNICATIONS - INSTALLATION OF GARMIN IRIDIUM DATALINK EQUIPMENT AND SOFTWARE			OPTIONAL			-			
	MOC :									
SL 680-23-02	ARINC DIRECT SERVICE FOR CMF			OPTIONAL			A/R			
	MOC :									
SL 680-23-05 R01	COMMUNICATIONS - ATG-4000 SOFTWARE UPDATE			RECOMMENDED	MTH		-			
	MOC :									
SL 680-23-05	COMMUNICATIONS - ATG-4000 SOFTWARE UPDATE			RECOMMENDED			-			
	MOC :									
SL 680-23-06	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SL 680-23-07	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
	MOC :									
SL 680-25-12	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR			RECOMMENDED			-			
	MOC :									
SL 680-25-13	EQUIPMENT/FURNISHINGS - BAGGAGE COMPARTMENT FOAM BLOCK REPLACEMENT	SZB		MANDATORY	MTH 28-Jul-2016 HRS 1509 LDG 991 APUH 1473.5 APUS 1458		-			Complete
	MOC :									
	COMPLIED WITH - BAGGAGE COMPARTMENT FOAM BLOCK REPLACEMENT C/OUT I.A.W. SL680-25-13 AND CE680 MM 25-50-00 REV.47.SECURITY CHECK SATIS.2. FAA FORM 8130-3 NO.5172425 REFERS.									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	SZB		MANDATORY	MTH 29-Sep-2016 HRS 1555 LDG 1034 APUH 1543.6 APUS 1470		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
	MOC :									
SB 680-27-12 R01	FLIGHT CONTROLS - RUDDER BIAS ACTUATOR IMPROVEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB 680-27-12	RUDDER BIAS ACTUATOR IMPROVEMENT	SZB		RECOMMENDED	MTH 24-Mar-2014 HRS 986 LDG 601		-			Complete
	MOC :									
	COMPLIED WITH									
SB 680-27-13	FLAP HANDLE ASSEMBLY SCREW IMPROVEMENT	SZB		RECOMMENDED	MTH 04-Dec-2012 HRS 619 LDG 362		-			Complete
	MOC :									
	COMPLIED WITH - 1.CARRIED OUT SB680-27-13 FLAP HANDLE ASSEMBLY SCREW IMPROVEMENT I.A.W. SB680-27-13. FOUND SATIS.2.SECURITY CHECK AND OPS CHECK CARRIED OUT FOUND SATIS.									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 680-27-14	FLIGHT CONTROLS - ELEVATOR TRIM ACTUATOR PIN IMPROVEMENT			RECOMMENDED			-			
	MOC :									
SB 680-27-15 R01	FLIGHT CONTROLS - MACH TRIP PCB IMPROVEMENT (CANCELLED)			DISCRETIONARY			-			
	MOC :									
SB 680-27-15 R02	FLIGHT CONTROLS - MACH TRIP PCB IMPROVEMENT (CANCELLED)			CANCELLED			-			
	MOC :									
SB 680-27-16 R01	FLIGHT CONTROLS - MACH TRIM PCB IMPROVEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB 680-27-16	FLIGHT CONTROLS - MACH TRIM PCB IMPROVEMENT			RECOMMENDED			-			
	MOC :									
SB 680-27-17	FLIGHT CONTROLS - HORIZONTAL STABILIZER CONTROLLER WATER SHIELD INSTALLATION			RECOMMENDED	MTH		-			
	MOC :									
ASL 680-27-03 R01	RUDDER LOWER RIB CRACK INSPECTION			MANDATORY	MTH		A/R			
	MOC :									
ASL 680-27-03 R02	RUDDER LOWER RIB CRACK INSPECTION	SZB		MANDATORY	MTH 23-May-2011 HRS 136 LDG 54		A/R			Complete
	MOC :									
	COMPLIED WITH - INSPECTION ON RUDDER LOWER RIB CRACK CARRIED OUT IAW ASL 680-27-03 R2. NO CRACK OR CORROSION FOUND ON THE RUDDER LOWER RIB.									
ASL 680-27-03	RUDDER LOWER RIB CRACK INSPECTION			MANDATORY			A/R			
	MOC :									
COM MC 680-004	NEW FLEXIBLE COUPLING P/N: 99040-6-6			INFORMATIONAL			-			
	MOC :									
SL 680-27-07 R01	CABLE FAIRLEAD REPLACEMENT	SZB		MANDATORY	MTH 26-Nov-2014 HRS 1145 LDG 706		-			Complete
	MOC :									
	COMPLIED WITH - 1.BOTH LH AND RH CABLE FAIRLEAD REPLACED AS PER CE680 SL680-27-07 R1.									
SL 680-27-07	CABLE FAIRLEAD REPLACEMENT			MANDATORY	MTH		-			
	MOC :									
SB 680-28-02	PRIMARY EJECTOR PUMP CLAMPING IMPROVEMENT	SZB		RECOMMENDED	MTH 09-Dec-2013 HRS 933 LDG 558		-			Complete
	MOC :									
	COMPLIED WITH									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
	MOC :									
SB 680-29-06 R01	HYDRAULIC POWER - AUXILIARY PUMP MANIFOLD OR AUXILIARY PUMP MANIFOLD PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 680-29-06	HYDRAULIC POWER - AUXILIARY PUMP MANIFOLD TRANSDUCER REPLACEMENT			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 680-29-04 R01	HYDRAULIC POWER - MISSING SEALS ON HYDRAULIC RESERVOIR SHROUD INSTALLATION	SZB	MANDATORY	MTH 24-Oct-2017 HRS 1739 LDG 1175 APUH 1715.6 APUS 1707		-				Complete
MOC : COMPLIED WITH - JOB NO : 21460TASK :TO C/OUT SL680-29-04 R01.ACTION :1.INSPECTION FOUND R581462 RUBBER SEAL NOT INSTALLED ON THE END PLATE.2.R581462 RUBBER SEAL INSTALLED I.A.W. SL680-29-04 R01. SECURITY CHECK SATIS.3.FAA FORM 8130-3 NO.5852281 REFERS										
SL 680-29-04	HYDRAULIC POWER - MISSING SEALS ON HYDRAULIC RESERVOIR SHROUD INSTALLATION		MANDATORY	MTH		-				
MOC :										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-				
MOC :										
SL 680-30-03 R01	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			A/R				
MOC :										
SL 680-30-03 R02	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			A/R				
MOC :										
SL 680-30-03 R03	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-				
MOC :										
SL 680-30-03 R04	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			A/R				
MOC :										
SL 680-30-03 R05	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			A/R				
MOC :										
SL 680-30-03	APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			A/R				
MOC :										
SL 680-30-09 R01	ICE AND RAIN PROTECTION - ADD SEALANT BETWEEN PICCOLO TUBES AND LANDING LIGHT BOX FASTENERS TO PREVENT CHAFING		DISCRETIONARY			-				
MOC :										
SL 680-30-09	ICE AND RAIN PROTECTION - ADD SEALANT BETWEEN PICCOLO TUBES AND LANDING LIGHT BOX FASTENERS TO PREVENT CHAFING		DISCRETIONARY			-				
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION		INFORMATIONAL			-				
MOC :										
SL 680-31-02	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001	SZB	MANDATORY	MTH 23-Oct-2012 HRS 542 LDG 312		A/R				Complete
MOC : COMPLIED WITH - 1. INSPECTION C/OUT I.A.W. BULLETIN NO. CESSNA SB 001 SECTION II FOUND FA2100 CVR P/N AND S/N INSTALLED AFFECTED.2. C/OUT CSMU HARDWARE REPLACEMENT I.A.W. BULLETIN NO. CESSNA SB 001 SECTION III.3. CVR RESTORED AND SECURED.4. C/OUT OPS CHECK ON BOARD FOUND SATIS.										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 680-32-05 R01	MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION SZB			MANDATORY	MTH 22-Sep-2016 HRS 1555 LDG 1034 APUH 1543.6 APUS 1470		-			Complete
MOC : COMPLIED WITH - SB680-32-05 R1 CARRIED OUT I.A.W. CE680 MM 32-30-40 REV.47 AND SB680-32-05 R1.										
SB 680-32-05 R02	LANDING GEAR - MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION MANDATORY			MTH			-			
MOC :										
SB 680-32-05 R03	LANDING GEAR - MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION MANDATORY			MTH			-			
MOC :										
SB 680-32-05	MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION MANDATORY						-			
MOC :										
SB 680-32-06	NOSE LANDING GEAR ISOLATOR-PIN REPLACEMENT MANDATORY						-			
MOC :										
SB 680-32-08	LANDING GEAR - INSTALLATION OF THE AEROMOTION NOSE LANDING GEAR ACTUATOR OPTIONAL						-			
MOC :										
SL 680-32-05	MAIN LANDING GEAR SIMULATOR TEST BOX INFORMATIONAL						A/R			
MOC :										
SL 680-32-10	NOSE WHEEL STEERING CABLE INSPECTION SZB			RECOMMENDED	MTH 22-Apr-2014 HRS 1007 LDG 614		-			Complete
MOC : COMPLIED WITH										
SL 680-32-12	LANDING GEAR - BRAKE ANTISKID CONTROL VALVE WIRE BUNDLE INSPECTION AND PLUG SECURITY SZB			RECOMMENDED	MTH 03-Aug-2016 HRS 1530 LDG 1012 APUH 1503.5 APUS 1459		-			Complete
MOC : COMPLIED WITH - 1. SL680-32-12 C/OUT I.A.W. SL680-32-12.FOUND SATIS.2. INSPECTION FOUND ELECTRICAL CONNECTORS ARE PROPERLY LABELED AND CONNECTED TO THE CORRECT BRAKE ANTI SKID CONTROL SYSTEM.3. PY018 AND PY019 CONNECTORS FOUND TO BE SECURED SATISFACTORILY.NIL ADJUSTMENT REQUIRED.										
SL 680-32-14	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION SZB			MANDATORY	DAYS 20-Apr-2017 HRS 1670 LDG 1122 APUH 1645.6 APUS 1617		-			N/A
MOC : NOT APPLICABLE - JOB NO.170420TASKTO CARRY OUT SL680-32-14 LANDING GEAR-MAIN LANDING GEAR BRAKE VERIFICATIONACTIONS680-32-14 SERIAL NUMBER NOT APPLICABLE.										
SL 680-32-15	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1675-32-2 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY SZB			MANDATORY	DAYS 26-Jul-2017 HRS 1726 LDG 1160 APUH 1690.6 APUS 1676		-			N/A
MOC : NOT APPLICABLE - JOB NO :170726-2TASK :TO C/OUT SL680-32-15.ACTION :1.SL680-32-15 C/OUT WITH REFERENCE TO SL680-32-15.FOUND SERVICE LETTER NOT APPLICABLE.										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 680-34-19	WEATHER UPLINK SOFTWARE INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB 680-34-20 R01	EPIC PHASE 5.2 SOFTWARE UPGRADE	SZB		MANDATORY	MTH 23-Jul-2012 HRS 476 LDG 270		-			Complete
	MOC :									
	COMPLIED WITH - CARRY OUT EPIC PHASE 5.2 SOFTWARE UPGRADE SERVICE BULLETIN AS PER CE680 SB680-34-20 REV 1.									
SB 680-34-27	WIDE AREA AUGMENTATION SYSTEM (WAAS) INSTALLATION			OPTIONAL	MTH 13-Jul-2017 HRS 1726 LDG 1160		A/R			Complete
	MOC :									
	COMPLIED WITH - COMPLIED AND COMPLETED THE SB680-34-27 FROM STEPS 1 TO 18 FULLY INCORPORATED AND FOUND SATISFACTORY.									
SB 680-34-29 R01	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0			MANDATORY	MTH		-			
	MOC :									
SB 680-34-29 R02	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0	SZB		MANDATORY	MTH 19-May-2016 HRS 1472 LDG 958		-			Complete
	MOC :									
	COMPLIED WITH - TCAS 2000 COMPUTER UNIT REPLACED, SECURED AND OPS. CHECK CARRIED OUT I.A.W. SB680-34-29 R2. FOUND SATISFACTORY.									
SB 680-34-29	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE			MANDATORY			-			
	MOC :									
SB 680-34-30 R01	NAVIGATION - TCAS 2000 SOFTWARE UPDATE TO VERSION 7.1			OPTIONAL			-			
	MOC :									
SB 680-34-30	TCAS 2000 SOFTWARE UPDATE TO VERSION 7.1			OPTIONAL			-			
	MOC :									
SB 680-34-32	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SB 680-34-33 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 680-34-33 R02)			OPTIONAL			-			
	MOC :									
SB 680-34-33 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	WSSL		OPTIONAL	MTH 13-Jul-2017 HRS 1726 LDG 1160		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED AND COMPLETED THE SB680-34-33 FROM STEPS 1 TO 12, FULLY INCORPORATED AND FOUND SATISFACTORY.									
SB 680-34-33 R03	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
	MOC :									
SB 680-34-33 R04	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
	MOC :									
SB 680-34-39 R01	NAVIGATION - GARMIN G5000 SOFTWARE UPDATE TO GARMIN 4.8, VERSION A2 (SUPERSEDED BY SB 680-34-43)			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 680-34-40 R01	NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) - 1/A+ INSTALLATION OPTIONAL						-			
	MOC :									
SB 680-34-42 R01	NAVIGATION - INSTALLATION OF AIRCRAFT COMMUNICATIONS ADDRESS AND REPORTING SYSTEM (ACARS) SOFTWARE OPTIONAL						-			
	MOC :									
SL CIL-34-06 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE						-			
	INFORMATIONAL									
	MOC :									
SL CIL-34-06	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE						-			
	INFORMATIONAL									
	MOC :									
COM MC 680-002	TRAFFIC COLLISION AND AVOIDANCE SYSTEM ANTENNAS INFORMATIONAL						-			
	MOC :									
SL 680-34-12 R01	SERVICE INFORMATION FROM HONEYWELL INFORMATIONAL						-			
	MOC :									
SL 680-34-13	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE INFORMATION LETTER D2012050000067, EQUIPMENT RESET UPON DATE/TIME INITIALIZATION ON CMA-4024-1 SPACED BASED AUGMENTATION SYSTEM INFORMATIONAL						-			
	MOC :									
SL 680-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG AND SERVICE ADVISORY 1822 DME/DME NAVIGATION INFORMATIONAL						-			
	MOC :									
SL CIL-35-02	OXYGEN - TRANSMITTAL OF ZODIAC AEROTECHNICS SERVICE BULLETIN MC10-35-274 SZB MANDATORY MTH 23-Dec-2015 HRS 1364 LDG 873						-			N/A
	MOC : NOT APPLICABLE - FOUND PART NUMBER NOT AFFECTED BY ZODIAC AEROTECHNICS SERVICE BULLETIN MC10-35-274 REV. 1									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 SZB MANDATORY MTH 18-Jan-2016 DAYS 1369 HRS 879 LDG						-			N/A
	MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. SL CIL-35-05.2. FOUND BOTH FLIGHT CREWS OXYGEN MASK REGULATOR PART NUMBER AND SERIAL NUMBER ARE NOT AFFECTED BY SL CIL-35-05.3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS P/N MLD20-505									
SL 680-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 MANDATORY						-			
	MOC :									
SL 680-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 SZB MANDATORY MTH 08-Feb-2013 HRS 667 LDG 397						-			Complete
	MOC : COMPLIED WITH - 1. CARRRIED OUT SL680-35-02 REV.2 I.A.W. INTERTECHNIQUE SERVICE BULLETIN MXH-35-240.2. FOUND RH CREW OXYGEN MASK AFFECTED IN EFFECTIVITY LIST OF SB.3. REPLACEMENT OF THE AFFECTED CREW OXYGEN MASK CARRIED OUT I.A.W. CE680 35-10-00 REV. 34.4. SECURITY CHECK, OPS CHECK AND LEAK CHECK CARRIED OUT. FOUND SATIS.5. FAA FORM 8130-3 NO. IN975702 REFERS.6. SL680-35-02 REV. 2 COMPLIED WITH.									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 680-35-02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
	MOC :									
SB 680-36-05	PNEUMATIC - SERVICE AIR VACUUM EJECTOR SYSTEM MODIFICATION	SZB		RECOMMENDED	MTH 05-Feb-2012 HRS 352 LDG 192		A/R			Complete
	MOC : COMPLIED WITH - 1. SB680-36-05 CARRIED OUT2. OPERATIONAL CHECK FOUND SATISFACTORY.3.FAA FORM 8130-3 JBO11011 REFERS.									
SB 680-38-01	TOILET OVERRIDE RELAY INSTALLATION			OPTIONAL			-			
	MOC :									
SB 680-49-09 R01	APU GENERATOR CONTROL PCB IMPROVEMENT	SZB		RECOMMENDED	MTH 18-Jun-2013 HRS 765 LDG 458		-			N/A
	MOC : NOT APPLICABLE - 1. AIRPLANE PREVIOUSLY MODIFIED BY SERVICE BULLETIN ORIGINAL REVISION ARE NOT AFFECTED BY REVISION 1.									
SB 680-49-09	AUXILIARY POWER - APU GENERATOR CONTROL PCB IMPROVEMENT	SZB		RECOMMENDED	MTH 08-Dec-2021 HRS 2437 LDG 1789		-			Complete
	MOC : COMPLIED WITH - JOB CARD NO: 191519TASK:TO CARRY OUT SB680-49-09 OF REPLACEMENT OF APU STARTER GENERATOR CONTROL PCB ASSEMBLY.ACTION:FOUND CURRENT APU INSTALLED WITH IMPROVED APU STARTER GENERATOR CONTROL PCB ASSEMBLY AS PER SB680-49-09 (P/N: 6968012-7). NIL REPLACEMENT REQUIRED.									
SL 680-49-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-7992 AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			DISCRETIONARY			A/R			
	MOC :									
SL 680-49-04 R01	AUXILIARY POWER - APU FUEL LINE INSPECTION			MANDATORY	MTH		-			
	MOC :									
SL 680-49-04	APU FUEL LINE INSPECTION	SZB		MANDATORY	MTH 10-Apr-2014 HRS 1007 LDG 614		-			Complete
	MOC : COMPLIED WITH									
SL 680-49-05	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8221 INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON RE100[CS] APUS	SZB		RECOMMENDED	MTH 18-Aug-2016 HRS 1530 LDG 1012 APUH 1503.5 APUS 1459		-			N/A
	MOC : NOT APPLICABLE - SL680-49-05 C/OUT I.A.W SL680-49-05.2. INSPECTION FOUND SL680-49-05 IS NOT APPLICABLE TO THIS UNIT.3. FSOV IDENTIFICATION NUMBER # 03882									
SL 680-49-08	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8250 AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU)			INFORMATIONAL			-			
	MOC :									
SL 680-49-10	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8365 GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 3615880-49-8149 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS	RECOMMENDED			-			
	MOC :							
SB 3615880-49-8149 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS	RECOMMENDED			-			
	MOC :							
SB 3822101-49-8148 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS	RECOMMENDED			-			
	MOC :							
SB 3822101-49-8148 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS	RECOMMENDED			-			
	MOC :							
SB 3883900-49-7976 R02	AIRBORNE AUXILIARY POWER - MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1, ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT AUXILIARY POWER UNIT (APU) SHOP VISIT	RECOMMENDED			ESV			
	MOC :							
SB 3883900-49-8297	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL SEAL, PN 3883905-1, WITH PN 70722907-1 ON THE FUEL CONTROL UNIT (FCU), PN 3883900-1 FOR THE RE100 APU	RECOMMENDED			-			
	MOC :							
SB 49-7933 R01	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R2)	RECOMMENDED			-			
	MOC :							
SB 49-7933 R02	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R3)	RECOMMENDED			-			
	MOC :							
SB 49-7933 R03	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS	SUPERSEDED			-			
	MOC :							
SB 49-7933 R04	AIRBORNE AUXILIARY POWER UNIT (APU) OIL - GENERAL - APPROVED OILS				-			
	MOC :							
SB 49-7933 R05	AIRBORNE AUXILIARY POWER UNIT (APU) OIL - GENERAL - APPROVED OILS				-			
	MOC :							
SB 49-7933 R06	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R7)				-			
	MOC :							
SB 49-7933 R07	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R08)				-			
	MOC :							
SB 49-7933 R08	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS	SUPERSEDED			-			
	MOC :							
SB 49-7933	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R1)				-			
	MOC :							
SB 49-7997 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
	MOC :							
SB 49-7997 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
	MOC :							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 49-7997 R03	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 49-7997 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 49-7997 R05	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 49-7997	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 70721598-49-8168 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED						
	MOC :									
SB 70721598-49-8168 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED						
	MOC :									
SB 70721725-49-8152 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED						
	MOC :									
SB 70721725-49-8152 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED						
	MOC :									
SIL APU-49 R10	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED						
	MOC :									
SIL APU-49 R11	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED						
	MOC :									
SIL APU-49 R12	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED						
	MOC :									
SIL APU-49 R13	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED						
	MOC :									
SIL APU-49 R14	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			A/R			
	MOC :									
SB RE100-49-7787	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL LEVEL SWITCH, PART NO. 3876318-1 WITH PART NO. 3876318-2			OPTIONAL						
	MOC :									
SB RE100-49-7855	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL LEVEL SWITCH, PART NO. 3876318-1 OR PART NO. 3876318-2 WITH PART NO. 3876318-3			OPTIONAL						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB RE100-49-7897	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK AND CAP, PN 361-530-9355			OPTIONAL			-			
	MOC :									
SB RE100-49-7933	APPROVED OILS			RECOMMENDED			-			
	MOC :									
SB RE100-49-7937	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PART NUMBER 361-530-9354, WITH OIL FILLER NECK AND CAP, PART NUMBER 361-530-9355			OPTIONAL			-			
	MOC :									
SB RE100-49-7986	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE WIRING HARNESS, PN 3888487-1 WITH PN 3888487-2			OPTIONAL			-			
	MOC :									
SB RE100-49-7992 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
	MOC :									
SB RE100-49-7992	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
	MOC :									
SB RE100-49-7994	AIRBORNE AUXILIARY POWER - GAS TURBINE EINGE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
	MOC :									
SB RE100-49-8139	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU			RECOMMENDED			-			
	MOC :									
SB RE100-49-8221	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON RE100[CS] APUS			RECOMMENDED	APUH 19-May-2016		-			N/A
		SZB			APUS 1165					
					1433					
	MOC :	NOT APPLICABLE - INSPECTION FOUND SB RE 100-49-8221 IS NOT APPLICABLE TO THIS UNIT.								
SB RE100-49-8250 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN3881825-2, FOR THE RE100[CS] AND RE100 [XL] AUXILIARY POWER UNIT (APU)			ATTRITION			-			
	MOC :									
SB RE100-49-8250 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100 [XL] AUXILIARY POWER UNIT (APU)			ATTRITION			-			
	MOC :									
SB RE100-49-8303 R03	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
	MOC :									
SB RE100-49-8303 R04	GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
	MOC :									
SB RE100-49-8303	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB RE100-49-8360 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS									
		CATEGORY 2							-	
MOC :										
SB RE100-49-8360 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON RE100 ENGINE MODELS									
		CATEGORY 2							-	
MOC :										
SB RE100-49-8360	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS									
		CATEGORY 2							-	
MOC :										
SB RE100-49-8363 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE INLET HOUSING PN 3810880-1/-2 WITH PN 70724596-1 OR PN 70724596-2, GEARBOX HOUSING PN 3863409-6 WITH PN 70724597-1, GEARBOX HOUSING PN 3863409-5 WITH PN 70724597-2 AND GEARBOX HOUSING PN 3863409-4 WITH PN 70724597-3 ON THE RE100 AUXILIARY POWER UNIT (APU)									
		OPTIONAL							-	
MOC :										
SB RE100-49-8365 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU)									
		CATEGORY 3							ESV	
MOC :										
SB RE100-49-8365	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU)									
		CATEGORY 3							-	
MOC :										
SB 680-52-04	MAIN CABIN DOOR REPAIR		DISCRETIONARY		MTH		-			
MOC :										
SB 680-52-05	DOORS - CABIN DOOR SUPPORT STRUT FITTING MODIFICATION									
		RECOMMENDED							-	
MOC :										
SB 680-52-06	DOORS - EMERGENCY EXIT DOOR INNER HANDLE HARDWARE REPLACEMENT									
		SZB	MANDATORY		DAYS 10-Jan-2020		-			
				HRS 2197						
				LDG 1582						
MOC : COMPLIED WITH - JOB CARD NO: 190854TASK:TO CARRY OUT EMERGENCY EXIT DOOR INNER HANDLE HARDWARE REPLACEMENT DUE TO SB680-52-06.ACTION:1. CARRIED OUT EMERGENCY EXIT DOOR INNER HANDLE HARDWARE REPLACEMENT AS PER SB680-52-06. SECURITY CHECK CARRIED OUT SATISFACTORY.2. FAA FORM 8130-3 NO.7076652 REFER.										
SB 680-52-07	DOORS - LAVATORY SERVICE DOOR PANEL PAN FLUID SEAL INSTALLATION									
		OPTIONAL							-	
MOC :										
SL 680-52-05	MAIN CABIN DOOR INSPECTION		MANDATORY		MTH 23-Oct-2013		-			
		SZB			HRS 882					
				LDG 530						
MOC : COMPLIED WITH										
SL 680-52-08	DOORS - INSPECTION OF THE NOSE LANDING GEAR (NLG) DOOR ACTUATION SYSTEM									
		SZB	RECOMMENDED		MTH 27-Sep-2021		-			
				HRS 2437						
				LDG 1789						
MOC : COMPLIED WITH - JOB NO.191517TASK:TO CARRY OUT SERVICE LETTER SL680-52-08 INSPECTION OF THE NOSE LANDING GEAR (NLG) DOOR ACTUATION SYSTEM.ACTION:1. CARRIED OUT SL680-52-08 INSPECTION OF THE NOSE LANDING GEAR (NLG) DOOR ACTUATION SYSTEM DATED 13 JUN 2019 FOUND SATIS WITH APPROXIMATELY 1.50 INCHES CLEARANCE BETWEEN LEFT AND RIGHT NLG DOORS AND COMPLIED WITH THE REQUIREMENT OF NOT LESS THAN 0.50 INCHES CLEARANCE.										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 680-52-09	DOORS - INSPECT AND TORQUE THE INNER EMERGENCY EXIT DOOR HANDLE BOLT AND NUT	SZB		MANDATORY	DAYS 19-Dec-2019 HRS 2174 LDG 1564		-			Complete
MOC : COMPLIED WITH - JOB CARD NO: 172291 TASK: TO INSPECT AND TORQUE THE INNER EMERGENCY EXIT DOOR HANDLE BOLT AND NUT AS PER SL680-52-09. ACTION: CARRIED OUT INSPECTION AND TORQUE THE INNER EMERGENCY EXIT DOOR HANDLE BOLT AND NUT AS PER SL680-52-09 AND CE680 SPM 20-10-65 REV. 2 DATED 01 AUG 2019. SECURITY CHECK CARRIED OUT FOUND SATISFACTORY.										
SB 680-53-02	APU INLET SCREEN IMPROVEMENT			RECOMMENDED			A/R			
MOC :										
SB 680-53-05 R01	NOSE DRIP CAP BOND INSPECTION			MANDATORY			-			
MOC :										
SB 680-53-06 R01	STINGER DRAIN IMPROVEMENT	SZB		MANDATORY	MTH 17-May-2016 HRS 1472 LDG 958		-			Complete
MOC : COMPLIED WITH - SB680-53-06 R1 COMPLIED AS PER SERVICE BULLETIN FOUND SATISFACTORY										
SB 680-53-06	STINGER DRAIN IMPROVEMENT	SZB		RECOMMENDED	MTH 12-Dec-2012 HRS 619 LDG 362		-			Complete
MOC : COMPLIED WITH - 1. SB680-53-06 CARRIED OUT FOUND SATIS. 2. WORK CARRIED OUT I.A.W. SB680-53-06.										
SB 680-53-07	STINGER DRAIN TUBE INSTALLATION	SZB		MANDATORY	MTH 16-May-2016 HRS 1472 LDG 958		-			Complete
MOC : COMPLIED WITH - SB680-53-07 CARRIED OUT AS PER SERVICE BULLETIN AND FOUND SATISFACTORY. FAA FORM 8130-3 (2181877) REFERS.										
SB 680-53-08 R01	FUSELAGE - AFT CANTED BULKHEAD MODIFICATION			MANDATORY			-			
MOC :										
SB 680-53-08 R02	FUSELAGE - AFT CANTED BULKHEAD MODIFICATION	XSP		MANDATORY	MTH 04-Jul-2019 HRS 2102.8 LDG 1503		-			Complete
MOC : COMPLIED WITH - SB 680-53-08 R02 COMPLIED WITH										
SB 680-53-08	FUSELAGE - AFT CANTED BULKHEAD MODIFICATION			MANDATORY			-			
MOC :										
SL 680-53-05 R02	FUSELAGE - AFT CANTED BULKHEAD INSPECTION	SZB		MANDATORY	MTH 18-Aug-2020 HRS 2293.1 LDG 1677		-			Complete
MOC : COMPLIED WITH - JOB CARD NO: 190258 TASK: TO COMPLY WITH SL680-53-05 R02 AFT CANTED BULKHEAD INSPECTION ACTION: 1. SL680-53-05 R02 DATED 30 SEP 2015 AFT CANTED BULKHEAD INSPECTION COMPLIED WITH IN CONJUNCTION OF COMPLETION OF SB680-53-08 R02 DATED 2 NOV 2016										
SB 680-54-01	NACELLES/PYLONS - VORTEX GENERATOR INSTALLATION ON PYLONS AND NACELLES			RECOMMENDED			-			
MOC :										
SB 680-55-02 R01	STABILIZERS - VERTICAL FIN DRAIN MODIFICATION			DISCRETIONARY			-			
MOC :										
SL 680-56-02	WINDSHIELD DELAMINATION			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 680-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION									
			MANDATORY	MTH			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0068 THRU -0289, -0291 THRU -0293 ONLY.										
SB 680-71-06 R01	POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF THE LEFT AND RIGHT ALUMINUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN THE LEFT AND RIGHT ENGINE BAY									
		SZB	RECOMMENDED	MTH	22-Jan-2024		-			Complete
				HRS	2683					
				LDG	2011					
MOC : COMPLIED WITH - JOBCARD NUMBER: 193991, 193992, 193993, 194132TASK: TO CARRY OUT POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF ALUMINIUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN ENGINE BAY DUE TO SB680-71-06. ACTION: 1. CARRIED OUT POWER PLANT REPLACEMENT OF ALUMINIUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN LH AND RH ENGINE AS PER SB680-71-06 DATED 07 AUG 2023. FOUND SATIS. FINAL TORQUE : 25 IN LBTJA032C DUE : 09 MAR 2024SECURITY CHECK CARRIED OUT, FOUND SATIS.2. REFER JOBCARD NUMBER 193043 FOR RIGHT HYDRAULIC PRESSURE TUBE REPLACEMENT ON 03 MAY 2023.										
SB 680-71-06	POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF ALUMINUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN ENGINE BAY									
		SZB	RECOMMENDED	MTH	22-Jan-2024		-			Complete
				HRS	2683					
				LDG	2011					
MOC : COMPLIED WITH - JOBCARD NUMBER: 193991, 193992, 193993, 194132TASK: TO CARRY OUT POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF ALUMINIUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN ENGINE BAY DUE TO SB680-71-06. ACTION: 1. CARRIED OUT POWER PLANT REPLACEMENT OF ALUMINIUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN LH AND RH ENGINE AS PER SB680-71-06 DATED 07 AUG 2023. FOUND SATIS. FINAL TORQUE : 25 IN LBTJA032C DUE : 09 MAR 2024SECURITY CHECK CARRIED OUT, FOUND SATIS.2. REFER JOBCARD NUMBER 193043 FOR RIGHT HYDRAULIC PRESSURE TUBE REPLACEMENT ON 03 MAY 2023. 3. FAA FROM 8130.3 NO. 8982855, 8940730, 9056964 REFERS.										
SL 680-71-04	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE INFORMATION LETTER NUMBER PW300-091, PW306C REPORTED LOSS OF THRUST CONTROL DURING LANDINGINCIDENT									
			INFORMATIONAL				A/R			
MOC :										
SL 680-71-06	TRANSMITTAL OF P&WC SERVICE BULLETIN 25353 - TURBOFAN ENGINE ALTERNATOR AND STARTER SEALS - REPLACEMENT OF									
			RECOMMENDED				A/R			
MOC :										
SL 680-71-07 NO. 1 ENGINE	PRATT & WHITNEY CANADA TURBOFAN ENGINE (P&WC SERVICE BULLETIN72-25380 REV 1) REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC)									
		SZB	MANDATORY	MTH	10-Jun-2013		-			Complete
				HRS	778					
				LDG	468					
MOC : COMPLIED WITH - TASK ACCOMPLISHED BY P&WC FIELD SERVICE REP, MR DANISH LAU.SL 680-71-07 CARRIED OUT I.A.W. PWC 306C SL 680-71-07 FOUND SATISFACTORY.										
SL 680-71-07 NO. 2 ENGINE	PRATT & WHITNEY CANADA TURBOFAN ENGINE (P&WC SERVICE BULLETIN 72-25380 REV 1) REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC)									
		SZB	MANDATORY	MTH	10-Jun-2013		-			Complete
				HRS	778					
				LDG	468					
MOC : COMPLIED WITH - TASK ACCOMPLISHED BY P&WC FIELD SERVICE REP, MR DANISH LAU.SL 680-71-07 CARRIED OUT I.A.W. PWC 306C SL 680-71-07 FOUND SATISFACTORY.										
SL 680-71-08	FUEL AND HYDRAULIC HOSE REPLACEMENT									
		SZB	MANDATORY	MTH	08-Jun-2016		-			Complete
				HRS	1506					
				LDG	987					
				APUH	1194					
				APUS	1458					
MOC : COMPLIED WITH - SL680-71-08 C/OUT I.A.W. CESSNA SL680-71-08 ON ENGINE NO.1 AND ENGINE NO.2. SECURITY, LEAK AND OPS CHECK SATIS.										
SL 680-71-10	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY OF CANADA SERVICE INFORMATION LETTER PW300-219									
			INFORMATIONAL				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW100-72-25428 E1	INTRODUCTION OF SELF-LOCKING NUT (IC) OPTION CATEGORY 9						-			
	MOC :									
SB PW100-72-25428 E2	INTRODUCTION OF SELF-LOCKING NUT (IC) OPTION CATEGORY 9						-			
	MOC :									
SB PW300-72-25189 E1	MODIFICATION OF MAIN DATA PLATE CATEGORY 3			MTH 01-Dec-2010			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25189 E2	MODIFICATION OF MAIN DATA PLATE CATEGORY 3			MTH 01-Dec-2010			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25229 R05 E1	REPLACEMENT/MODIFICATION OF HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72-25229 R05 E2	REPLACEMENT/MODIFICATION OF HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72-25234 R04 E1	HIGH PRESSURE TURBINE (HPT) VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF CATEGORY 6						-			
	MOC :									
SB PW300-72-25234 R04 E2	HIGH PRESSURE TURBINE (HPT) VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF CATEGORY 6						-			
	MOC :									
SB PW300-72-25249 R02 E1	MODIFICATION /REPLACEMENT OF FUEL NOZZLES CATEGORY 5						-			
	MOC :									
SB PW300-72-25249 R02 E2	MODIFICATION /REPLACEMENT OF FUEL NOZZLES CATEGORY 5						-			
	MOC :									
SB PW300-72-25265 R01 E1	WORKSCOPE FOR LOW UTILIZATION INSPECTION CATEGORY 10						-			
	MOC :									
SB PW300-72-25265 R01 E2	WORKSCOPE FOR LOW UTILIZATION INSPECTION CATEGORY 10						-			
	MOC :									
SB PW300-72-25268 E1	REPLACEMENT/MODIFICATION OF ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25268 R01) CATEGORY 3			MTH 01-Dec-2010			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25268 E2	REPLACEMENT/MODIFICATION OF ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25268 R01) CATEGORY 3			MTH 01-Dec-2010			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25269 E1	MODIFICATION/REPLACEMENT OF HPT DISK BALANCING ASSEMBLY CATEGORY 7			MTH 01-Dec-2010			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25269 E2	MODIFICATION/REPLACEMENT OF HPT DISK BALANCING ASSEMBLY CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25270 R01 E1	INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE CATEGORY 7						-			
MOC :										
SB PW300-72-25270 R01 E2	INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE CATEGORY 7						-			
MOC :										
SB PW300-72-25270 R02 E1	INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE CATEGORY 7						-			
MOC :										
SB PW300-72-25270 R02 E2	INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE CATEGORY 7						-			
MOC :										
SB PW300-72-25274 R02 E1	REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET CATEGORY 7						-			
MOC :										
SB PW300-72-25274 R02 E2	REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET CATEGORY 7						-			
MOC :										
SB PW300-72-25274 E1	REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES (SUPERSEDED BY PW300-72-25274 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25274 E2	REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES (SUPERSEDED BY PW300-72-25274 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25284 R03 E1	REPLACEMENT OF MAGNETIC SEAL ASSEMBLIES CATEGORY 7						-			
MOC :										
SB PW300-72-25284 R03 E2	REPLACEMENT OF MAGNETIC SEAL ASSEMBLIES CATEGORY 7						-			
MOC :										
SB PW300-72-25296 E1	REPLACEMENT OF OIL VENT TUBE RETAINING BOLT CATEGORY 6			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25296 E2	REPLACEMENT OF OIL VENT TUBE RETAINING BOLT CATEGORY 6			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25298 E1	REPLACEMENT OF OIL FILLER NECK ASSEMBLY (SUPERSEDED BY PW300-72-25298 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25298 E2	REPLACEMENT OF OIL FILLER NECK ASSEMBLY (SUPERSEDED BY PW300-72-25298 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25299 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25299 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25301 E1	REPLACEMENT OF NO. 1 BEARING HOUSING ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25301 E2	REPLACEMENT OF NO. 1 BEARING HOUSING ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25304 E1	INTRODUCTION OF NEW OIL TANK VENT TUBE GASKET CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25304 E2	INTRODUCTION OF NEW OIL TANK VENT TUBE GASKET CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25305 E1	REPLACEMENT OF COMPRESSOR ROTOR BALANCING ASSEMBLY FLANGE BOLTS CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25305 E2	REPLACEMENT OF COMPRESSOR ROTOR BALANCING ASSEMBLY FLANGE BOLTS CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25306 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR (HPC) TIE SHAFT RETAINING NUT CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25306 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR (HPC) TIE SHAFT RETAINING NUT CATEGORY 6	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25308 E1	INTRODUCTION OF NEW HIGH PRESSURE TURBINE (HPT) REAR COVER (SUPERSEDED BY PW300-72-25308 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25308 E2	INTRODUCTION OF NEW HIGH PRESSURE TURBINE (HPT) REAR COVER (SUPERSEDED BY PW300-72-25308 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25309 R04 E1	REPLACEMENT OF PRIMARY FUEL NOZZLE CATEGORY 6			-				
MOC :								
SB PW300-72-25309 R04 E2	REPLACEMENT OF PRIMARY FUEL NOZZLE CATEGORY 6			-				
MOC :								
SB PW300-72-25309 E1	REPLACEMENT OF PRIMARY FUEL NOZZLE (SUPERSEDED BY PW300-72-25309 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25309 E2	REPLACEMENT OF PRIMARY FUEL NOZZLE (SUPERSEDED BY PW300-72-25309 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25311 R01 E1	REPLACEMENT/MODIFICATION OF PRIMARY FUEL NOZZLE ASSEMBLY CATEGORY 7			-				
MOC :								
SB PW300-72-25311 R01 E2	REPLACEMENT/MODIFICATION OF PRIMARY FUEL NOZZLE ASSEMBLY CATEGORY 7			-				
MOC :								
SB PW300-72-25312 R02 E1	CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R02 E2	CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 PART A E1	ACCOMPLISH REPLACEMENT OF IDENTIFICATION PLATE (A NEW ENGINE BUILD SPECIFICATION (BS1241) FOR THE PW306A AND BUILD SPECIFICATION (BS1240) FOR THE PW306C, ARE INTRODUCED TO DISTINGUISH ENGINES ELIGIBLE FOR ENROLLMENT INTO THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 PART A E2	ACCOMPLISH REPLACEMENT OF IDENTIFICATION PLATE (A NEW ENGINE BUILD SPECIFICATION (BS1241) FOR THE PW306A AND BUILD SPECIFICATION (BS1240) FOR THE PW306C, ARE INTRODUCED TO DISTINGUISH ENGINES ELIGIBLE FOR ENROLLMENT INTO THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 PART B E1	ACCOMPLISH REPLACEMENT OF IDENTIFICATION PLATE (FOR ENGINES THAT ARE NO LONGER INCLUDED WITHIN THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM, THE POST-SB25312 REFERENCE DATA PLATE WITH ENGINE BUILD SPECIFICATION (BS1241 FOR THE PW306A OR BS1240 FOR THE PW306C) IS REMOVED AND REPLACED WITH A NEW DATA PLATE REFERENCING THE ORIGINAL ENGINE BUILD SPECIFICATION (BS853 FOR THE PW306A OR BS1026 FOR THE PW306C)) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 PART B E2	ACCOMPLISH REPLACEMENT OF IDENTIFICATION PLATE (FOR ENGINES THAT ARE NO LONGER INCLUDED WITHIN THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM, THE POST-SB25312 REFERENCE DATA PLATE WITH ENGINE BUILD SPECIFICATION (BS1241 FOR THE PW306A OR BS1240 FOR THE PW306C) IS REMOVED AND REPLACED WITH A NEW DATA PLATE REFERENCING THE ORIGINAL ENGINE BUILD SPECIFICATION (BS853 FOR THE PW306A OR BS1026 FOR THE PW306C)) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 E1	CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25312 R03 E2	CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) CATEGORY 8			-				
MOC :								
SB PW300-72-25314 E1	REPLACEMENT/MODIFICATION OF UPPER AND LOWER BYPASS DUCT FAIRINGS CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25314 E2	REPLACEMENT/MODIFICATION OF UPPER AND LOWER BYPASS DUCT FAIRINGS CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25317 E1	REPLACEMENT OF TAIL FAIRING BOLTS			CATEGORY 6	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25317 E2	REPLACEMENT OF TAIL FAIRING BOLTS			CATEGORY 6	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25318 E1	INTRODUCTION OF NEW FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW300-72-25318 R01)			CATEGORY 5	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25318 E2	INTRODUCTION OF NEW FUEL/OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW300-72-25318 R01)			CATEGORY 5	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25319 E1	INTRODUCTION OF ALTERNATE SOURCE FOR THE 3RD, 4TH AND 5TH STAGE LOW PRESSURE TURBINE DISKS			CATEGORY 9	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25319 E2	INTRODUCTION OF ALTERNATE SOURCE FOR THE 3RD, 4TH AND 5TH STAGE LOW PRESSURE TURBINE DISKS			CATEGORY 9	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25321 E1	MODIFICATION/REPLACEMENT OF ALTERNATOR SPUR GEARSHAFT ASYO - SUPERSEDED (SUPERSEDED BY PW300-72-25321 R01)			CATEGORY 6	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25321 E2	MODIFICATION/REPLACEMENT OF ALTERNATOR SPUR GEARSHAFT ASYO - SUPERSEDED (SUPERSEDED BY PW300-72-25321 R01)			CATEGORY 6	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25323 E1	HIGH PRESSURE TURBINE SHROUD AIR SEAL - REPLACEMENT OF			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25323 E2	HIGH PRESSURE TURBINE SHROUD AIR SEAL - REPLACEMENT OF			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25324 E1	REPLACEMENT/MODIFICATION NO. 3 AND 4 SCAVENGE OIL PUMP WOODRUFF KEY			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25324 E2	REPLACEMENT/MODIFICATION NO. 3 AND 4 SCAVENGE OIL PUMP WOODRUFF KEY			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25325 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR BOLTS (SUPERSEDED BY PW300-72-25325 R01)			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25325 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR BOLTS (SUPERSEDED BY PW300-72-25325 R01)			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25326 R01 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25326 R01 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW300-72-25326 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY (SUPERSEDED BY PW300-72-25326 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25326 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY (SUPERSEDED BY PW300-72-25326 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25327 E1	REPLACEMENT/ MODIFICATION OF ACCESSORY GEARBOX GEARSHAFTS (SUPERSEDED BY PW300-72-25327 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25327 E2	REPLACEMENT/ MODIFICATION OF ACCESSORY GEARBOX GEARSHAFTS (SUPERSEDED BY PW300-72-25327 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25330 E1	INTRODUCTION OF LOW PRESSURE TURBINE TRIM BALANCE WEIGHT CATEGORY 8	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25330 E2	INTRODUCTION OF LOW PRESSURE TURBINE TRIM BALANCE WEIGHT CATEGORY 8	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25331 R01 E1	REPLACEMENT OF FAN HUB SET CATEGORY 7				-			
MOC :								
SB PW300-72-25331 R01 E2	REPLACEMENT OF FAN HUB SET CATEGORY 7				-			
MOC :								
SB PW300-72-25331 E1	REPLACEMENT OF FAN HUB SET (SUPERSEDED BY PW300-72-25331 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25331 E2	REPLACEMENT OF FAN HUB SET (SUPERSEDED BY PW300-72-25331 R01) CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25333 E1	REPLACEMENT / MODIFICATION OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25333 E2	REPLACEMENT / MODIFICATION OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25337 E1	INTRODUCTION OF LPT ROTOR & STATOR ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25337 E2	INTRODUCTION OF LPT ROTOR & STATOR ASSEMBLY CATEGORY 7	MTH	01-Dec-2010	-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25338 E1	REPLACEMENT OF FUEL WASTE EJECTOR CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25338 E2	REPLACEMENT OF FUEL WASTE EJECTOR CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25339 E1	REPLACEMENT/INTRODUCTION OF SELF-LOCKING NUTS AND CAP SCREWS CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25339 E2	REPLACEMENT/INTRODUCTION OF SELF-LOCKING NUTS AND CAP SCREWS CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25340 E1	REPLACEMENT OF P2.8 AND P3 AIR TUBE ASSEMBLY CATEGORY 6			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25340 E2	REPLACEMENT OF P2.8 AND P3 AIR TUBE ASSEMBLY CATEGORY 6			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25341 E1	REPLACEMENT/MODIFICATION OF HIGH PRESSURE TURBINE DISK ASSEMBLY CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25341 E2	REPLACEMENT/MODIFICATION OF HIGH PRESSURE TURBINE DISK ASSEMBLY CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25342 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 3			MTH	01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25342 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 3			MTH	01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25344 E1	REPLACEMENT OF N1 SPEED SENSOR CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25344 E2	REPLACEMENT OF N1 SPEED SENSOR CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25345 R01 E1	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER CATEGORY 7						-			
	MOC :									
SB PW300-72-25345 R01 E2	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER CATEGORY 7						-			
	MOC :									
SB PW300-72-25345 E1	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER CATEGORY 7			MTH	01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25345 E2	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25346 R01 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREATHING TUBE ADAPTER GASKET CATEGORY 7						-			
MOC :										
SB PW300-72-25346 R01 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREATHING TUBE ADAPTER GASKET CATEGORY 7						-			
MOC :										
SB PW300-72-25346 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREATHING TUBE ADAPTER GASKET (SUPERSEDED BY PW300-72-25346 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25346 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREATHING TUBE ADAPTER GASKET (SUPERSEDED BY PW300-72-25346 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25347 R02 E1	REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT CATEGORY 6						-			
MOC :										
SB PW300-72-25347 R02 E2	REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT CATEGORY 6						-			
MOC :										
SB PW300-72-25347 E1	REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT (SUPERSEDED BY PW300-72-25347 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25347 E2	REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT (SUPERSEDED BY PW300-72-25347 R01) CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25348 R01 E1	REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72-25348 R01 E2	REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72-25348 E1	REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25348 E2	REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY CATEGORY 7			MTH	01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72-25352 R01 E1	SB PW300-72-25352 R01 - REPLACEMENT OF PREFORMED PACKINGS CATEGORY 6						-			
MOC :										
SB PW300-72-25352 R01 E2	SB PW300-72-25352 R01 - REPLACEMENT OF PREFORMED PACKINGS CATEGORY 6						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25352 E1	REPLACEMENT OF PREFORMED PACKINGS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25352 E2	REPLACEMENT OF PREFORMED PACKINGS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25353 R04 E1	REPLACEMENT OF ALTERNATOR AND STARTER SEALS(SUPERSEDED BY PW300-72-25353 R05)			CATEGORY 5			A/R			
	MOC :									
SB PW300-72-25353 R04 E2	REPLACEMENT OF ALTERNATOR AND STARTER SEALS(SUPERSEDED BY PW300-72-25353 R05)			CATEGORY 5			A/R			
	MOC :									
SB PW300-72-25353 R05 E1	REPLACEMENT OF ALTERNATOR AND STARTER SEALS			CATEGORY 5			-			
	MOC :									
SB PW300-72-25353 R05 E2	REPLACEMENT OF ALTERNATOR AND STARTER SEALS			CATEGORY 5			-			
	MOC :									
SB PW300-72-25355 E1	REPLACEMENT OF HIGH PRESSURE TURBINE SHROUD SEALS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25355 E2	REPLACEMENT OF HIGH PRESSURE TURBINE SHROUD SEALS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25356 E1	REPLACEMENT OF NO.1 BEARING COVER AND HOUSING ASSEMBLY			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25356 E2	REPLACEMENT OF NO.1 BEARING COVER AND HOUSING ASSEMBLY			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25357 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) MOUNTING PLATES AND ENGINE MOUNT PAD COVER BOLTS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25357 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) MOUNTING PLATES AND ENGINE MOUNT PAD COVER BOLTS			CATEGORY 7	MTH 01-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25359 R02 E1	REPLACEMENT OF - VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25359 R02 E2	REPLACEMENT OF - VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25359 E1	REPLACEMENT OF VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS (SUPERSEDED BY PW300-72-25359 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25359 E2	REPLACEMENT OF VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS (SUPERSEDED BY PW300-72-25359 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25360 E1	REPLACEMENT OF FUEL WASTE EJECTOR (SUPERSEDED BY PW300-72-25360 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25360 E2	REPLACEMENT OF FUEL WASTE EJECTOR (SUPERSEDED BY PW300-72-25360 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25361 R01 E1	AIR TRANSFER TUBES - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25361 R01 E2	AIR TRANSFER TUBES - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25361 E1	AIR TRANSFER TUBES - REPLACEMENT OF (SUPERSEDED BY PW300-72-25361 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25361 E2	AIR TRANSFER TUBES - REPLACEMENT OF (SUPERSEDED BY PW300-72-25361 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25362 E1	REPLACEMENT OF COMPRESSOR BLEED SOLENOID VALVE			CATEGORY 8	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25362 E2	REPLACEMENT OF COMPRESSOR BLEED SOLENOID VALVE			CATEGORY 8	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25363 E1	REPLACEMENT/MODIFICATION OF LOWER HALF BY-PASS DUCT ASSEMBLY			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25363 E2	REPLACEMENT/MODIFICATION OF LOWER HALF BY-PASS DUCT ASSEMBLY			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25368 R01 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R02)						A/R			
	MOC :									
SB PW300-72-25368 R01 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R02)						A/R			
	MOC :									
SB PW300-72-25368 R02 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT			CATEGORY 7			-			
	MOC :									
SB PW300-72-25368 R02 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25368 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25368 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R01)			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25370 R01 E1	REPLACEMENT / MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW300-72-25370 R01 E2	REPLACEMENT / MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW300-72-25370 E1	REPLACEMENT/MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY (SUPERSEDED BY PW300-72-25370 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25370 E2	REPLACEMENT/MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY (SUPERSEDED BY PW300-72-25370 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW300-72-25371 E1	INTERSHAFT OIL SEALS - REPLACEMENT OF			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25371 E2	INTERSHAFT OIL SEALS - REPLACEMENT OF			CATEGORY 7	MTH 01-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW300-72-25374 R01 E1	REPLACEMENT/MODIFICATION OF FUEL NOZZLES			CATEGORY 7			-			
	MOC :									
SB PW300-72-25374 R01 E2	REPLACEMENT/MODIFICATION OF FUEL NOZZLES			CATEGORY 7			-			
	MOC :									
SB PW300-72-25374 E1	REPLACEMENT/MODIFICATION OF FUEL NOZZLES (SUPERSEDED BY PW300-72-25374 R01)						A/R			
	MOC :									
SB PW300-72-25374 E2	REPLACEMENT/MODIFICATION OF FUEL NOZZLES (SUPERSEDED BY PW300-72-25374 R01)						A/R			
	MOC :									
SB PW300-72-25375 E1	REPLACEMENT OF SAFETY WIRE			CATEGORY 8			A/R			
	MOC :									
SB PW300-72-25375 E2	REPLACEMENT OF SAFETY WIRE			CATEGORY 8			A/R			
	MOC :									
SB PW300-72-25376 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED SOLENOID VALVE			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25376 E2	REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED SOLENOID VALVE			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25377 E1	INSPECTION OF DAMPER SEAL INSTALLATION ON TURBINE ROTOR AIR SEAL			CATEGORY 5			A/R			
MOC :										
SB PW300-72-25377 E2	INSPECTION OF DAMPER SEAL INSTALLATION ON TURBINE ROTOR AIR SEAL			CATEGORY 5			A/R			
MOC :										
SB PW300-72-25378 R01 E1	REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW300-72-25378 R01 E2	REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW300-72-25378 E1	REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW300-72-25378 R01)			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25378 E2	REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW300-72-25378 R01)			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25379 E1	REPLACEMENT OF OUTER UPPER AND LOWER HALF BYPASS DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25379 E2	REPLACEMENT OF OUTER UPPER AND LOWER HALF BYPASS DUCT ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25380 R01 E1	REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW300-72-25380 R02)	SZB		CATEGORY 3	MTH 10-Jun-2013 HRS 765 LDG 458		-			Complete
MOC : COMPLIED WITH - 1. P&WC S.B NO. 25380R1 - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) ON ENGINE NO 1 ACCOMPLISHED BY P&WC FIELD SERVICE REP, MR.DANISH LAU.2. WORK CARRIED OUT I.A.W P&WC S.B NO. 25380R1.3. HIGH POWER RUN CARRIED OUT, FOUND SATIS.										
SB PW300-72-25380 R01 E2	REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW300-72-25380 R02)	SZB		CATEGORY 3	MTH 10-Jun-2013 HRS 765 LDG 458		-			Complete
MOC : COMPLIED WITH - 1. P&WC S.B NO. 25380R1 - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) ON ENGINE NO 2 ACCOMPLISHED BY P&WC FIELD SERVICE REP, MR.DANISH LAU.2. WORK CARRIED OUT I.A.W P&WC S.B NO. 25380R1.3. HIGH POWER RUN CARRIED OUT, FOUND SATIS.										
SB PW300-72-25380 R02 E1	REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC)	SZB		CATEGORY 3	MTH 23-Oct-2017 HRS 1739 LDG 1175		-			Complete
MOC : COMPLIED WITH - JOBCARD NO 21457TASK:TO CARRY OUT SB PW300-72-25380 ON ENGINE NO.1 -REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC).ACTION:1. WITH REFER TO P&WC SB PW300-72-25380 REV 2 REVISION TRANSMITTAL SHEET FOUND NONE EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT.										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25380 R02 E2	REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC)	SZB		CATEGORY 3	MTH 23-Oct-2017 HRS 1739 LDG 1175		-			Complete
MOC : COMPLIED WITH - JOBCARD NO 21457 TASK: TO CARRY OUT SB PW300-72-25380 ON ENGINE NO.2 -REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC). ACTION: 1. WITH REFER TO P&WC SB PW300-72-25380 REV 2 REVISION TRANSMITTAL SHEET FOUND NONE EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT.										
SB PW300-72-25381 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX COVER ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW300-72-25381 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX COVER ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW300-72-25383 E1	REPLACEMENT OF REAR LOWER BY-PASS DUCT FAIRING			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25383 E2	REPLACEMENT OF REAR LOWER BY-PASS DUCT FAIRING			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25384 E1	REPLACEMENT OF BY-PASS DUCT SEGMENTS			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25384 E2	REPLACEMENT OF BY-PASS DUCT SEGMENTS			CATEGORY 7			A/R			
MOC :										
SB PW300-72-25385 E1	REPLACEMENT OF BY-PASS DUCT FAIRINGS			CATEGORY 7			-			
MOC :										
SB PW300-72-25385 E2	REPLACEMENT OF BY-PASS DUCT FAIRINGS			CATEGORY 7			-			
MOC :										
SB PW300-72-25386 E1	REPLACEMENT OF FIRST STAGE VANE ACTUATOR RING SET			CATEGORY 7			-			
MOC :										
SB PW300-72-25386 E2	REPLACEMENT OF FIRST STAGE VANE ACTUATOR RING SET			CATEGORY 7			-			
MOC :										
SB PW300-72-25387 R01 E1	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7			-			
MOC :										
SB PW300-72-25387 R01 E2	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7			-			
MOC :										
SB PW300-72-25387 E1	REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY PW300-72-25387 R01)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25387 E2	REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY PW300-72-25387 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25388 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25388 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25389 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW300-72-25389 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW300-72-25390 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE			CATEGORY 7			-			
	MOC :									
SB PW300-72-25390 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE			CATEGORY 7			-			
	MOC :									
SB PW300-72-25391 E1	REPLACEMENT OF SPEED SENSOR WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25391 E2	REPLACEMENT OF SPEED SENSOR WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25395 R01 E1	REPLACEMENT OF ALTERNATOR AND STARTER SEALS						-			
	MOC :									
SB PW300-72-25395 R01 E2	REPLACEMENT OF ALTERNATOR AND STARTER SEALS						-			
	MOC :									
SB PW300-72-25395 R02 E1	REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY SB PW300-72-25395 R02)			CATEGORY 10			-			
	MOC :									
SB PW300-72-25395 R02 E2	REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY SB PW300-72-25395 R02)			CATEGORY 10			-			
	MOC :									
SB PW300-72-25395 E1	REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25395 R01)						-			
	MOC :									
SB PW300-72-25395 E2	REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25395 R01)						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25397 E1	REPAIR/MODIFICATION OF ENGINE ELECTRONIC CONTROL (EEC) CATEGORY 5						-			
MOC :										
SB PW300-72-25397 E2	REPAIR/MODIFICATION OF ENGINE ELECTRONIC CONTROL (EEC) CATEGORY 5						-			
MOC :										
SB PW300-72-25398 E1	REPLACEMENT OF NO. 2 BEARING REAR CARBON SEAL CATEGORY 6						-			
MOC :										
SB PW300-72-25398 E2	REPLACEMENT OF NO. 2 BEARING REAR CARBON SEAL CATEGORY 6						-			
MOC :										
SB PW300-72-25403 R01 E1	INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD CATEGORY 6						-			
MOC :										
SB PW300-72-25403 R01 E2	INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD CATEGORY 6						-			
MOC :										
SB PW300-72-25403 E1	INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD (SUPERSEDED BY PW300-72-25403 R01) CATEGORY 6						-			
MOC :										
SB PW300-72-25403 E2	INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD (SUPERSEDED BY PW300-72-25403 R01) CATEGORY 6						-			
MOC :										
SB PW300-72-25406 E1	REPLACEMENT OF PROTECTIVE CAPS FOR ENGINE SHIPPING CONTAINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72-25406 E2	REPLACEMENT OF PROTECTIVE CAPS FOR ENGINE SHIPPING CONTAINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72-25408 R01 E1	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R02) CATEGORY 6						-			
MOC :										
SB PW300-72-25408 R01 E2	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R02) CATEGORY 6						-			
MOC :										
SB PW300-72-25408 R02 E1	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS CATEGORY 6						-			
MOC :										
SB PW300-72-25408 R02 E2	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS CATEGORY 6						-			
MOC :										
SB PW300-72-25408 E1	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R01) CATEGORY 6						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25408 E2	REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R01)			CATEGORY 6			-			
	MOC :									
SB PW300-72-25409 E1	RELOCATION OF OIL FILLER NECK VENT TUBE SUPPORT BRACKET			CATEGORY 6			-			
	MOC :									
SB PW300-72-25409 E2	RELOCATION OF OIL FILLER NECK VENT TUBE SUPPORT BRACKET			CATEGORY 6			-			
	MOC :									
SB PW300-72-25410 R01 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7			-			
	MOC :									
SB PW300-72-25410 R01 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7			-			
	MOC :									
SB PW300-72-25410 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT (SUPERSEDED BY PW300-72-25410 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25410 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT (SUPERSEDED BY PW300-72-25410 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25411 R01 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
	MOC :									
SB PW300-72-25411 R01 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
	MOC :									
SB PW300-72-25411 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY PW300-72-25411 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25411 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY PW300-72-25411 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25412 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R02)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25412 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R02)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25412 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R03)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25412 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R03)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25412 R03 E1	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R04) CATEGORY 7									
	MOC :									
SB PW300-72-25412 R03 E2	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R04) CATEGORY 7									
	MOC :									
SB PW300-72-25412 R04 E1	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 7									
	MOC :									
SB PW300-72-25412 R04 E2	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 7									
	MOC :									
SB PW300-72-25412 R05 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 7									
	MOC :									
SB PW300-72-25412 R05 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT CATEGORY 7									
	MOC :									
SB PW300-72-25412 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R01) CATEGORY 7									
	MOC :									
SB PW300-72-25412 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R01) CATEGORY 7									
	MOC :									
SB PW300-72-25413 R01 E1	REPLACEMENT OF FIFTH STAGE LOW PRESSURE TURBINE DISK CATEGORY 9									
	MOC :									
SB PW300-72-25413 R01 E2	REPLACEMENT OF FIFTH STAGE LOW PRESSURE TURBINE DISK CATEGORY 9									
	MOC :									
SB PW300-72-25415 E1	REPLACEMENT OF NO. 2 BEARING OIL NOZZLE CATEGORY 7									
	MOC :									
SB PW300-72-25415 E2	REPLACEMENT OF NO. 2 BEARING OIL NOZZLE CATEGORY 7									
	MOC :									
SB PW300-72-25417 E1	REPLACEMENT OF HIGH PRESSURE TURBINE VANE INNER SUPPORT CATEGORY 7									
	MOC :									
SB PW300-72-25417 E2	REPLACEMENT OF HIGH PRESSURE TURBINE VANE INNER SUPPORT CATEGORY 7									
	MOC :									
SB PW300-72-25420 R01 E1	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION CATEGORY 8									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25420 R01 E2	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION	CATEGORY 8			-			
	MOC :							
SB PW300-72-25420 R02 E1	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION	CATEGORY 8			-			
	MOC :							
SB PW300-72-25420 R02 E2	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION	CATEGORY 8			-			
	MOC :							
SB PW300-72-25420 E1	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION	CATEGORY 8			-			
	MOC :							
SB PW300-72-25420 E2	CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION	CATEGORY 8			-			
	MOC :							
SB PW300-72-25421 E1	REPLACEMENT OF NO. 1 BEARING CARBON AIR SEAL	CATEGORY 9			-			
	MOC :							
SB PW300-72-25421 E2	REPLACEMENT OF NO. 1 BEARING CARBON AIR SEAL	CATEGORY 9			-			
	MOC :							
SB PW300-72-25425 R01 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY	CATEGORY 6			-			
	MOC :							
SB PW300-72-25425 R01 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY	CATEGORY 6			-			
	MOC :							
SB PW300-72-25425 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY (SUPERSEDED BY PW300-72-25425 R01)	CATEGORY 6			-			
	MOC :							
SB PW300-72-25425 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY (SUPERSEDED BY PW300-72-25425 R01)	CATEGORY 6			-			
	MOC :							
SB PW300-72-25431 R01 E1	INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING	CATEGORY 9			-			
	MOC :							
SB PW300-72-25431 R01 E2	INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING	CATEGORY 9			-			
	MOC :							
SB PW300-72-25431 E1	INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING (SUPERSEDED BY PW300-72-25431 R01)	CATEGORY 9			-			
	MOC :							
SB PW300-72-25431 E2	INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING (SUPERSEDED BY PW300-72-25431 R01)	CATEGORY 9			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25433 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25433 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25433 R02 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25433 R02 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25433 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25433 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25433 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25433 R01)			CATEGORY 7			-			
	MOC :									
SB PW300-72-25434 R01 E1	INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING			CATEGORY 3			-			
	MOC :									
SB PW300-72-25434 R01 E2	INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING			CATEGORY 3			-			
	MOC :									
SB PW300-72-25434 E1	INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING			CATEGORY 3			-			
	MOC :									
SB PW300-72-25434 E2	INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING			CATEGORY 3			-			
	MOC :									
SB PW300-72-25435 R01 E1	REPLACEMENT OF PRESSURE AND TEMPERATURE SENSORS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25435 R01 E2	REPLACEMENT OF PRESSURE AND TEMPERATURE SENSORS			CATEGORY 7			-			
	MOC :									
SB PW300-72-25436 R01 E1	INTRODUCTION OF ADD SEALANT			CATEGORY 6			-			
	MOC :									
SB PW300-72-25436 R01 E2	INTRODUCTION OF ADD SEALANT			CATEGORY 6			-			
	MOC :									
SB PW300-72-25436 E1	INTRODUCTION OF ADD SEALANT			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25436 E2	INTRODUCTION OF ADD SEALANT			CATEGORY 6			-			
	MOC :									
SB PW300-72-25440 E1	REPLACEMENT OF WIRING HARNESS PREFORMED PACKING			CATEGORY 9			-			
	MOC :									
SB PW300-72-25440 E2	REPLACEMENT OF WIRING HARNESS PREFORMED PACKING			CATEGORY 9			-			
	MOC :									
SB PW300-72-25441 E1	INTRODUCTION OF TURBINE EXHAUST CASE ASSEMBLY OPTION (IC)			CATEGORY 9			-			
	MOC :									
SB PW300-72-25441 E2	INTRODUCTION OF TURBINE EXHAUST CASE ASSEMBLY OPTION (IC)			CATEGORY 9			-			
	MOC :									
SB PW300-72-25444 R01 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 R01 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 R02 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 R02 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW300-72-25444 R01)			CATEGORY 8			-			
	MOC :									
SB PW300-72-25444 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW300-72-25444 R01)			CATEGORY 8			-			
	MOC :									
SB PW300-72-25446 R01 E1	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW300-72-25446 R01 E2	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25446 R02 E1	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R02 E2	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R03 E1	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R03 E2	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R04 E1	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R04 E2	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R05 E1	REPLACEMENT / MODIFICATION OF LOWER-HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 R05 E2	REPLACEMENT / MODIFICATION OF LOWER-HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 E1	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25446 E2	REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW300-72- 25447 R01 E1	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R01 E2	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R02 E1	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R02 E2	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R03 E1	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25447 R03 E2	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R04 E1	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 R04 E2	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 E1	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25447 E2	REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 R01 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 R01 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 R02 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 R02 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25450 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7						-			
	MOC :									
SB PW300-72- 25451 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
	MOC :									
SB PW300-72- 25451 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
	MOC :									
SB PW300-72- 25451 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
	MOC :									
SB PW300-72- 25451 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25451 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
MOC :										
SB PW300-72- 25451 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R01 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R01 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R02 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R02 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R03 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R03 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R04 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R04 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R05 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R05 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R06 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R06 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW300-72- 25452 R07 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25452 R07 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25452 R08 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25452 R08 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25452 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25452 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25453 E1	REPLACEMENT OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25453 E2	REPLACEMENT OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72- 25457 E1	REPLACEMENT OF FIRE DETECTOR BRACKET HINGED CLAMP CATEGORY 9						-			
	MOC :									
SB PW300-72- 25457 E2	REPLACEMENT OF FIRE DETECTOR BRACKET HINGED CLAMP CATEGORY 9						-			
	MOC :									
SB PW300-72- 25459 R02 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS CATEGORY 7						-			
	MOC :									
SB PW300-72- 25459 R02 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS CATEGORY 7						-			
	MOC :									
SB PW300-72- 25459 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS CATEGORY 7						-			
	MOC :									
SB PW300-72- 25459 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS CATEGORY 7						-			
	MOC :									
SB PW300-72- 25459 E1	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS						-			
	MOC :									
SB PW300-72- 25459 E2	REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25460 R01 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R01 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R02 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R02 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R03 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R03 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R04 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R04 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R05 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R05 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R06 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R06 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R07 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R07 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW300-72-25460 R08 E1	SB PW300-72-25460 R08 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25460 R08 E2	SB PW300-72-25460 R08 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25460 R09 E1	SB PW300-72-25460 R09 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25460 R09 E2	SB PW300-72-25460 R09 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25460 R10 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 6				-			
	MOC :							
SB PW300-72-25460 R10 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY CATEGORY 6				-			
	MOC :							
SB PW300-72-25462 R01 E1	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-72-25462 R01 E2	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-72-25462 E1	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-72-25462 E2	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-72-25463 E1	REPLACEMENT OF TIE ROD RETAINING NUT CATEGORY 7				-			
	MOC :							
SB PW300-72-25463 E2	REPLACEMENT OF TIE ROD RETAINING NUT CATEGORY 7				-			
	MOC :							
SB PW300-72-25465 E1	INSPECTION OF DUPLEX FUEL NOZZLE CATEGORY 6				-			
	MOC :							
SB PW300-72-25465 E2	INSPECTION OF DUPLEX FUEL NOZZLE CATEGORY 6				-			
	MOC :							
SB PW300-72-25466 R01 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 R01 E2	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72-25466 R02 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 R02 E2	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 R03 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 R03 E2	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 E1	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25466 E2	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-72-25467 E1	REPLACEMENT OF DUPLEX FUEL NOZZLE CATEGORY 7				-			
	MOC :							
SB PW300-72-25467 E2	REPLACEMENT OF DUPLEX FUEL NOZZLE CATEGORY 7				-			
	MOC :							
SB PW300-72-25471 R01 E1	SB PW300-72-25471 R01 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY CATEGORY 6				-			
	MOC :							
SB PW300-72-25471 R01 E2	SB PW300-72-25471 R01 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY CATEGORY 6				-			
	MOC :							
SB PW300-72-25471 E1	SB PW300-72-25471 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY CATEGORY 6				-			
	MOC :							
SB PW300-72-25471 E2	SB PW300-72-25471 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY CATEGORY 6				-			
	MOC :							
SB PW300-72-25475 R01 E1	REPLACEMENT OF INLET GUIDE VANE SHROUD SET CATEGORY 7				-			
	MOC :							
SB PW300-72-25475 R01 E2	REPLACEMENT OF INLET GUIDE VANE SHROUD SET CATEGORY 7				-			
	MOC :							
SB PW300-72-25475 E1	REPLACEMENT OF INLET GUIDE VANE SHROUD SET CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25475 E2	REPLACEMENT OF INLET GUIDE VANE SHROUD SET CATEGORY 7						-			
MOC :										
SB PW300-72- 25478 R01 E1	REPLACEMENT OF FIRST-STAGE HIGH-PRESSURE-TURBINE BLADES CATEGORY 7						-			
MOC :										
SB PW300-72- 25478 R01 E2	REPLACEMENT OF FIRST-STAGE HIGH-PRESSURE-TURBINE BLADES CATEGORY 7						-			
MOC :										
SB PW300-72- 25478 E1	REPLACEMENT OF FIRST-STAGE HIGH-PRESSURE-TURBINE BLADES CATEGORY 7						-			
MOC :										
SB PW300-72- 25478 E2	REPLACEMENT OF FIRST-STAGE HIGH-PRESSURE-TURBINE BLADES CATEGORY 7						-			
MOC :										
SB PW300-72- 25480 E1	REPLACEMENT OF ACTUATOR SUPPORT-BRACKET CATEGORY 7						-			
MOC :										
SB PW300-72- 25480 E2	REPLACEMENT OF ACTUATOR SUPPORT-BRACKET CATEGORY 7						-			
MOC :										
ASB PW300-72- A25358 R01 E1	INSPECTION /REPLACEMENT OF ALTERNATOR AND STARTER MAGNETIC SEAL ASSEMBLIES CATEGORY 3						-			
MOC :										
ASB PW300-72- A25358 R01 E2	INSPECTION /REPLACEMENT OF ALTERNATOR AND STARTER MAGNETIC SEAL ASSEMBLIES CATEGORY 3						-			
MOC :										
SB PW300-72- 25264 R01 E1	IMPENDING FUEL FILTER BYPASS SWITCH - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW300-72- 25264 R01 E2	IMPENDING FUEL FILTER BYPASS SWITCH - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW300-72- 25320 E1	MODIFICATION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT (HMU) CATEGORY 7				MTH 01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72- 25320 E2	MODIFICATION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT (HMU) CATEGORY 7				MTH 01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72- 25332 E1	REPLACEMENT/MODIFICATION OF FUEL START AND DUMP VALVE CATEGORY 6				MTH 01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW300-72- 25332 E2	REPLACEMENT/MODIFICATION OF FUEL START AND DUMP VALVE CATEGORY 6				MTH 01-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-72- 25450 R03 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7				-			
	MOC :							
SB PW300-72- 25450 R03 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7				-			
	MOC :							
SB PW300-72- 25450 R04 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7				-			
	MOC :							
SB PW300-72- 25450 R04 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR CATEGORY 7				-			
	MOC :							
SB PW300-73- 25462 R02 E1	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-73- 25462 R02 E2	INSPECTION OF OUTER ELECTRICAL WIRING HARNESS CATEGORY 4				-			
	MOC :							
SB PW300-75- 25454 R01 E1	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-75- 25454 R01 E2	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-75- 25454 R02 E1	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-75- 25454 R02 E2	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-75- 25454 E1	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW300-75- 25454 E2	REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 680-76-02	ENGINE CONTROLS - MODIFICATION OF LEFT AND RIGHT FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) WIRE HARNESS ASSEMBLY CLAMPING SZB	RECOMMENDED	MTH 22-Jan-2024 HRS 2683 LDG 2011		-			Complete
MOC : COMPLIED WITH - JOBCARD NUMBER: 193989, 193990, 194130, 194131 TASK: TO CARRY OUT ENGINE CONTROLS - MODIFICATION OF LEFT AND RIGHT FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) WIRE HARNESS ASSEMBLY CLAMPING DUE TO SB680-76-02 COMPLIANCE. ACTION: 1. CARRIED OUT RIGHT AND LEFT LOWER ENGINE COWLING REMOVAL AS PER MODEL 680 MM (REV 33) 71-10-00 (REV 26) DATED 01 NOV 2023. FOUND SATIS. 2. CARRIED OUT RIGHT ELECTRONIC ENGINE CONTROL (EEC) REMOVAL AS PER MODEL PW306C MM (MANUAL PART NO. 30B4422, ISSUE NO. 48.0) 73-20-02 DATED 06 NOV 2023. FOUND SATIS. 3. CARRIED OUT ENGINE CONTROLS - MODIFICATION OF RIGHT AND LEFT FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) WIRE HARNESS ASSEMBLY CLAMPING AS PER SB680-76-02 DATED 15 NOV 2019. TORQUE CHECK CARRIED OUT. FOUND SATIS. FINAL TORQUE: 25 IN LBSTJA023C DUE : 09 MAR 2024. 4. CARRIED OUT RIGHT ELECTRONIC ENGINE CONTROL (EEC) RESTORATION AS PER MODEL PW306C MM (MANUAL PART NO. 30B4422, ISSUE NO. 48.0) 73-20-02 DATED 06 NOV 2023. TORQUE CHECK CARRIED OUT. FOUND SATIS. FINAL TORQUE : 36 LBF IN TJA032C DUE: 09 MAR 2024. FINAL TORQUE : 90 LBF IN AND 42 LBF INTJA 025C DUE : 26 JUN 2024. 5. CARRIED OUT LEFT AND RIGHT LOWER ENGINE COWLING RESTORATION AS PER MODEL 680 MM (REV 33) DATED 01 NOV 2023. FOUND SATIS. 6. FAA FORM 8130-3 NO. 8940730 REFERS.								
SL CIL-76-01	ENGINE CONTROLS - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25462, TURBOFAN ENGINE INSPECTION OF OUTER ELECTRICAL HARNESS INFORMATIONAL				-			
MOC :								
SL 680-76-02 NO. 1 ENGINE	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25412, TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTICS UNIT - REPLACEMENT/MODIFICATION INFORMATIONAL				-			
MOC :								
SL 680-76-02 NO. 2 ENGINE	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25412, TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTICS UNIT - REPLACEMENT/MODIFICATION INFORMATIONAL				-			
MOC :								
SB PW300-72-25369 E1	REPLACEMENT OF SPEED SENSOR WIRING HARNESS CATEGORY 7	MTH	01-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-72-25369 E2	REPLACEMENT OF SPEED SENSOR WIRING HARNESS CATEGORY 7	MTH	01-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW300-77-25474 R01 E1	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77-25474 R01 E2	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77-25474 R02 E1	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77-25474 R02 E2	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77-25474 R03 E1	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77-25474 R03 E2	REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW300-77- 25474 E1	REPLACEMENT / RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW300-77- 25474 E2	REPLACEMENT / RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS CATEGORY 7				-			
MOC :								
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SB PW300-72- 25258 R02 E1	OIL FILTER IMPENDING BYPASS SWITCH - REPLACEMENT OF CATEGORY 7				A/R			
MOC :								
SB PW300-72- 25258 R02 E2	OIL FILTER IMPENDING BYPASS SWITCH - REPLACEMENT OF CATEGORY 7				A/R			
MOC :								
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS CANCELLED				-			
MOC :								
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Service Bulletins

Item Code	Description	Part Number			C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
	CANCELLED						-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
	CANCELLED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)	KICT		MANDATORY	MTH 01-Dec-2010 HRS 6.7 LDG 4		-			Complete
MOC : COMPLIED WITH - AD74-08-09REV2; TRANSPORT CATRGORY AIRPLANES: COMPLIED WITH THE REQUIREMENTS AS DEFINED IN PARAGRAPHS (A)(1), (A)(2), AND (C).										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	SZB		MANDATORY	MTH 22-Mar-2019 HRS 2040 LDG 1443		1000		3040	Complete 284.7
MOC : COMPLIED WITH - JOBCARD NO: 170778TASK:TO CARRY OUT AD 1974-08-09 R03 LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION PLACARD INSTALLATION.ACTION:1.AD CARRIED OUT AS PER AD 1974-08-09 R03.FOUND SATISFACTORY2. REFER FORM 8130-3 6607627										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
MOC :										
FAA 2015-10-02	EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	SZB			MTH 23-Oct-2017 HRS 1739 LDG 1175 APUH 1715.6 APUS 1707		-			N/A
MOC : NOT APPLICABLE - JOBCARD NO. 21456TASK:TO CARRY OUT FAA 2017-16-01 PARA (G).ACTION:1. FAA 2017-16-01 PARA (G) FOUND NOT APPLICABLE WITH AIRCRAFT.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2021-23-12	INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	SZB		MANDATORY	MTH 23-Dec-2021 HRS 2437 LDG 1789		-			Complete
MOC : COMPLIED WITH - JOB CARD NO: 191520TASK:TO COMPLY WITH FAA AD 2021-23-12 (5G INTERFERENCE ON RADIO ALTIMER) ACTION:AIRCRAFT CURRENTLY HAVING MAINTENANCE IN CESSNA SINGAPORE. A COPY OF FAA AD 2021-23-12 HAS BEEN PREPARED FOR TH AFM REVISION AND HANDED TO PILOT IN CHARGE WHEN PICKING UP CE680 - 0306. ALSO NOTIFIED CHIEF PILOT TO INSERT A COPY OF FAA AD 2021-23-12 ONCE THE AIRCRAFT MAINTENANCE IS COMPLETED PRIOR TO NEXT FLIGHT (XSP-SZB)										
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)			MANDATORY			-			
MOC :										
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	SZB		MANDATORY	MTH 04-Aug-2023 HRS 2619.5 LDG 1961		-			Complete
MOC : COMPLIED WITH - JOB NO.193086TASK:REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H).ACTION:1. REVISED THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H).										
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION			MANDATORY			-			
MOC :										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	SZB		MANDATORY	DAYS 09-Aug-2018 HRS 1907 LDG 1322		-			N/A
MOC : NOT APPLICABLE - JOB CARD NO: 171839TASKTO C/OUT FAA 2018-07-13 LANDING GEAR- INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH.ACTIONFAA 2018-07-13 LANDING GEAR -INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH C/OUT AS PER AD FAA 2018-07-13 DATED 15MAY 2018 NOT APPLICABLE TO CE 680-0306.										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	SZB		MANDATORY	MTH 19-May-2016 HRS 1472 LDG 958		-			Complete
MOC : COMPLIED WITH - TCAS 2000 REPLACED I.A.W. FAA AD 2012-08FOUND SATISFACTORY.										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION									
				MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51-E	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.									
				MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS									
				MANDATORY			-			
MOC :										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011									
	SZB		MANDATORY	MTH	10-Jun-2015		-			Complete
				HRS	1290					
				LDG	813					
MOC : COMPLIED WITH - 1. FAA 2015-08-07 PARA (G) AD CARRIED OUT IAW FAA 2015-08-07 AD AND ZODIAC AEROSPACE SB MXH-35-240 REV. 7.2. FOUND BOTH PILOT AND CO-PILOT'S MASKS COMPLIED WITH AD.										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES									
	SZB		MANDATORY	MTH	10-Jun-2015		-			Complete
				HRS	1290					
				LDG	813					
MOC : COMPLIED WITH - 1. FAA 2015-08-07 PARA (H) AD CARRIED OUT IAW FAA 2015-08-07 AD AND ZODIAC AEROSPACE SB MXH-35-240 REV. 7.2. FOUND BOTH PILOT AND CO-PILOT'S MASKS COMPLIED WITH AD.3. NO REPLACEMENT REQUIRED.										
FAA 2015-08-07	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES									
				MANDATORY			-			
MOC :										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER									
	SZB		MANDATORY	MTH	18-Jan-2016		-			N/A
				DAYS	1369					
				HRS	879					
				LDG						
MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. FAA AD 2015-23-09 PARA (G).2. FOUND BOTH FLIGHT CREWS OXYGEN MASK PART NUMBER ARE NOT AFFECTED BY FAA AD 2015-23-09 PARA(G).3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS.4. PILOT : P/N MLD20-505 ; S/N 121836CO-PILOT : P/N MLD20-505 ; S/N SE64337										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).									
	SZB		MANDATORY	MTH	18-Jan-2016		-			N/A
				DAYS	1369					
				HRS	879					
				LDG						
MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. FAA AD 2015-23-09.2. FOUND BOTH FLIGHT CREWS OXYGEN MASK PART NUMBER AND SERIAL NUMBER ARE NOT AFFECTED BY FAA AD 2015-23-09 PARA(G).3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS.4. PILOT : P/N MLD20-505 ; S/N 121836CO-PILOT : P/N MLD20-505 ; S/N SE64337										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1									
	SZB		MANDATORY	MTH	18-Jan-2016		-			N/A
				DAYS	1369					
				HRS	879					
				LDG						
MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. FAA AD 2015-23-09.2. FOUND BOTH FLIGHT CREWS OXYGEN MASK REGULATOR PART NUMBER AND SERIAL NUMBER ARE NOT AFFECTED BY FAA AD 2015-23-09 PARA(G).3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS.4. PILOT : P/N MLD20-505 ; S/N 121836CO-PILOT : P/N MLD20-505 ; S/N SE64337										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	SZB		MANDATORY	MTH 18-Jan-2016 DAYS 1369 HRS 879 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. FAA AD 2015-23-09.2. FOUND BOTH FLIGHT CREWS OXYGEN MASK REGULATOR PART NUMBER AND SERIAL NUMBER ARE NOT AFFECTED BY FAA AD 2015-23-09 PARA(G).3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS.4. PILOT : P/N MLD20-505 ; S/N 121836CO-PILOT : P/N MLD20-505 ; S/N SE64337										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	SZB		MANDATORY	MTH 18-Jan-2016 HRS 1369 LDG 879		-			N/A
MOC : NOT APPLICABLE - INSPECTION CARRIED OUT I.A.W. FAA AD 2015-23-09.2. FOUND BOTH FLIGHT CREWS OXYGEN MASK REGULATOR PART NUMBER AND SERIAL NUMBER ARE NOT AFFECTED BY FAA AD 2015-23-09 PARA(G).3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS.4. PILOT : P/N MLD20-505 ; S/N 121836CO-PILOT : P/N MLD20-505 ; S/N SE643375. REGULATOR REPLACEMENT NOT APPLICABLE.										
FAA 2015-23-09	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	SZB		MANDATORY	MTH 18-Jan-2016 HRS 1369 LDG 879		-			N/A
MOC : NOT APPLICABLE - ACTION1. FLIGHT CREW OXYGEN MASK REGULATOR PILOT AND CO-PILOT INSPECTED I.A.W. FAA 2015-23-09 AD.2. FOUND P/ART NUMBER AND SERIAL NUMBER OF FLIGHT CREW OXYGEN MASK REGULATOR ARE NOT AFFECTED BY FAA 2015-23-09 APPLIANCE AD.3. CE680-0306 IS FITTED WITH OXYGEN MASK FROM INTERTECHNIQUE EROS AND P/N MLD20-505.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	SZB		MANDATORY	MTH 20-Jun-2016 HRS 1506 LDG 987 APUH 1194 APUS 1458		-			N/A
MOC : NOT APPLICABLE - FOUND FAA 2016-11-20 PARA (G) AD NOT APPLICABLE WITH AIRCRAFT.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY			-			
MOC :										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	SZB		MANDATORY	MTH 20-Jun-2016 HRS 1506 LDG 987 APUH 1194 APUS 1458		-			N/A
MOC : NOT APPLICABLE - FOUND FAA 2016-11-20 PARA (H)(2) AD NOT APPLICABLE WITH AIRCRAFT.										
FAA 2016-11-20	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	SZB		MANDATORY	MTH 20-Jun-2016 HRS 1506 LDG 987 APUH 1194 APUS 1458		-			N/A
MOC : NOT APPLICABLE - FOUND FAA 2016-11-20 AD NOT APPLICABLE WITH AIRCRAFT.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED MANDATORY				-			
MOC :								
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT. SZB MANDATORY	MTH 23-Oct-2017 HRS 1739 LDG 1175 APUH 1715.6 APUS 1707			-			N/A
MOC : NOT APPLICABLE - JOBCARD NO. 21455TASK:TO CARRY OUT FAA 2017-18-12 PARA (I) AND (J).ACTION:FAA 2017-18-12 PARA (I) AND (J) IS NOT APPLICABLE ON THIS AIRCRAFT DUE TO NO PBE ONBOARD.								
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES MANDATORY				-			
MOC :								
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS SZB MANDATORY	MTH 14-Jul-2021			-			N/A
MOC : NOT APPLICABLE								
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD SZB MANDATORY	MTH 14-Jul-2021			-			N/A
MOC : NOT APPLICABLE								
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT SZB MANDATORY	MTH 14-Jul-2021 HRS 2401.5 LDG 1767			-			N/A
MOC : NOT APPLICABLE - JOBCARD NO.: 191409TASK:TO CARRY OUT APPLIANCE AD FAA 2018-21-14 - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES INSPECTION / REPLACEMENT.ACTION:1. CARRIED OUT INSPECTION ON BOTH FLIGHT CREW DONNING MASK HARNESS AS PER AIRWORTHINESS DIRECTIVE FAA 2018-21-14 PARA (G). FOUND THAT PART NUMBERS AND DMF CODES NOT APPLICABLE AND AFFECTED BY THIS AD.2. PILOT AND CO-PILOT MASK PART NO.: MLD20-505.3. PILOT MASK DMF CODE: 1142-S.4. CO-PILOT DMF CODE: 0707-S.								
FAA 2017-06-13 PARA (G) (H)	PERFORM A GENERAL VISUAL INSPECTION FOR DISBONDING AND PAINT CRACKING AROUND THE EDGES OF THE STIFFENERS ON THE AFT CANTED BULKHEAD. IF ANY DISBONDING OR CRACKING PAINT IS FOUND OBTAIN AND ACCOMPLISH REPAIR INSTRUCTIONS. MANDATORY	MTH 01-Dec-2010 HRS 0			7000		7000	4244.7
MOC :								
FAA 2017-06-13 PARA (I)	MODIFY THE AIRPLANE BY INSTALLING ADDITIONAL STIFFENERS ON THE AFT CANTED BULKHEAD XSP MANDATORY	MTH 04-Jul-2019 HRS 2102.8 LDG 1503			-			Complete
MOC : COMPLIED WITH - FAA 2017-06-13 PARA (I) COMPLIED WITH								
FAA 2017-06-13	PREVENTION OF DISBONDING OF THE HORIZONTAL AND VERTICAL STIFFENERS ON THE AFT CANTED BULKHEAD MANDATORY				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **JADEBLUE CONNECTION SDN BHD**
Aircraft Model: **680 - CITATION SOVEREIGN**
Aircraft Serial: **680-0306**
Unit: Reg No: **N3099**
Airworthiness: **01-Dec-2010**
Print Date: **10-Jun-2025 5:29AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2755.3	2103	06-Jun-2025	.2
ENG 1	2755.3	2103	06-Jun-2025	.2
ENG 2	2755.3	2103	06-Jun-2025	.2
APU	2632.2	3118	06-Jun-2025	.42

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
00FO908C	KIT FOR VERTICAL FIN SCREW MOD FACTORY OPTION			908C FO	MTH 01-Dec-2010		-	0		
00FO908F	KIT FOR TAILCONE SCREW MOD FACTORY OPTION			908F FO	MTH 01-Dec-2010		-	0		
00FO908G	KIT FOR PYLON SCREW MOD FACTORY OPTION			908G FO	MTH 01-Dec-2010		-	0		
23FO632B	HF-1050 - HONEYWELL FACTORY OPTION			632B FO	MTH 01-Dec-2010		-	0		
23FO632F	CSD-714 SELCAL - COLTECH FACTORY OPTION			632F FO	MTH 01-Dec-2010		-	0		
23FO807N	KIT FOR AIRCELL ST-3100 SATELLITE TELEPHONE SYS FACTORY OPTION			807N FO	MTH 01-Dec-2010		-	0		
25FO-08	LIFE RAFT MOORING RING FACTORY OPTION			90B FO	MTH 01-Dec-2010		-	0		
25FO-15	GEN ACCESS MF20 EROS MAGIC MSK FACTORY OPTION			66L FO	MTH 01-Dec-2010		-	0		
25FO908A	KIT STAINLESS STEEL FSTNR ALL UNSEALED INSP ACC DOORS FACTORY OPTION			908A FO	MTH 01-Dec-2010		-	0		
25FO908D	KIT FOR BGGAGE DOOR THRESHOLD STAINLESS STEEL COVER FACTORY OPTION			908D FO	MTH 01-Dec-2010		-	0		
28FO500	BRITISH PETROLEUM TURBO OIL 2380 FACTORY OPTION			500 FO	MTH 01-Dec-2010		-	0		
31FO634U	FA-2100 FLT DATA RECRD (PROVIS ONLY) - L3 COMMUNICATIONS FACTORY OPTION			634U FO	MTH 01-Dec-2010		-	0		
34FO-08	MODE-S XPDR W/ENHANCED SURVLNC FACTORY OPTION			612C FO	MTH 01-Dec-2010		-	0		
34FO697N	FMS PERFORMANCE DATABASE HONEYWELL FACTORY OPTION			697N FO	MTH 01-Dec-2010		-	0		
34FO697S	DATA MANAGEMENT UNIT (LH CLOSET) HONEYWELL FACTORY OPTION			697S FO	MTH 01-Dec-2010		-	0		
35FO-01	EXTENDED RANGE OXY SYSTEM FACTORY OPTION			66K FO	MTH 01-Dec-2010		-	0		