


January 18, 2024 N9427N Tach: 2969.0 SPOH: 00.0

This propeller, Hartzell HC-C2YK-1B, s/n CH42861B, overhauled by First Flight Propeller, LLC, was installed on Piper PA-28R-200, N9427N; aircraft was run up, operational & leak check satisfactory; I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition; all AD's currently up to date, see maint. release.

Andy von Gleich A&P 3464926 IA



HC-C2YK- CH1565

Tach 3011.9

TSMOH

42.9

9.23-25

1- Saftied prop hub bolts with applicable roll pins.

2- Removed hub bolt spacers add washers, Retorque 22 ft lbs

I certify this propeller has been inspected in accordance with a 100HR INSPECTION and has been found to be in an airworthy condition

Robert Clay AP 1896667 IA

9.23-25

