

PROPELLER ASSEMBLY LOG

PAGE NUMBER

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
1-13-25	<i>0</i>	X S/n	3GFR34C703-B 240954	THIS PROPELLER WAS MANUFACTURED NEW AT McCauley Propeller Systems, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE	617 

02/27/2025 N950PA Hobbs: 1664.9 ACTT: 21676.5
 3GFR34C703 S/N: 240954 TT: 0.0 TSO: N/A

This new Propeller installed on N950PA, SN: 208B1063 and PT6A-114A, SN: PCE-PC0940. Completed an Annual Inspection. Ops check and leak check good. See Southern Airways Work Order SA-4291 for further inspection details. I certify this propeller has been inspected in accordance with an Annual inspection per FAR Part 43 Appendix D and determined to be in an airworthy condition.

Tom Leverich 
 Southern Airways Express

AP3328084IA