Aircraft Record General Information

Aircraft Record General Information

Manufacturer: Horsefly Aviation LLC

Model: CCX-2000

Serial Number: CCX-2000-0028

Registration Number: N849W

Date of Manufacture: _

Engine Installed: Aero Sport Power

Model Number: CC363i

Serial Number: CC363i-1033

Propeller Installed: Hartzell

Model Number: HC-C2YR-1NW/NG8301W

Serial Number: NS3765B

Serial Number: CCX2000-0028

This aircraft has been painted according to the following paint specifications:

Paint Theme: Standard	N# Location: E1		
Main Color: PPG# 80502	Yellow		
Base Color: PPG# 80502	Yellow		
Base Color 2: Black	Black		
Trim Color 1: TBD	0		

EAR	TOTAL TIME IN	Current Weight and Balance Information							
ATE	SERVICE	Empty Weight	Empty CG	Useful Load	Remarks				
			-						
	accord Details	ance with Part 43 Ar	pendix F. re on file under W	ork Order # <u>0015</u> 0	13 has been performed in 17 el: CTX, 345 P 3 EN 475 238 4 CC (Le)(6C)				
	Cut	Crafters Avionics, LL 1920 S. 16 th Avenue	c CUB	CRAFTERS	Certified Repair Station 4CCR016C				

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Regist	ration Nu	mber:	N849W	Serial Number: CCX-2000-0028
		d thic	aircraft (from plans and material supplied by Cub Crafters, Inc.,
install	ed a Cub	Crafte	rs Experi	imental Engine Model: CC36i-1033 and Experimental
install Hartze	ed a Cub (Crafter er Mod	rs Experi lel: HC-C	imental Engine Model: CC36i-1033 and Experimental C2YR-1NW / NG8301W. This aircraft has been ground
install Hartze tested,	ed a Cub (el Propello inspecte	Crafter er Mod d and f	rs Experi lel: HC-C found to	imental Engine Model: CC36i-1033 and Experimental C2YR-1NW / NG8301W. This aircraft has been ground be in condition for safe operation within the scope and
install Hartze tested,	ed a Cub (Crafter er Mod d and f	rs Experi lel: HC-C found to	imental Engine Model: CC36i-1033 and Experimental C2YR-1NW / NG8301W. This aircraft has been ground be in condition for safe operation within the scope and
install Hartze tested,	ed a Cub el Propello inspecte of 14 CFR	Crafter er Mod d and f	rs Experi lel: HC-C found to	imental Engine Model: CC36i-1033 and Experimental C2YR-1NW / NG8301W. This aircraft has been ground be in condition for safe operation within the scope and adix D.
installe Hartze tested, detaile	ed a Cub el Propello inspecte of 14 CFR	Crafter er Mod d and f	rs Experi lel: HC-C found to	imental Engine Model: CC36i-1033 and Experimental C2YR-1NW / NG8301W. This aircraft has been ground be in condition for safe operation within the scope and adix D. $7-26-8$

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Regist	ration N	umber	: N849V	V Serial Number: CCX-2000-0028
I find t	this airci an Expe	raft me	ets the r tal, Ama	requirements for the certificate requested and have teur Built Airworthiness Certificate.
Next C	ondition	Inspe	ction is	due: 27 July 2019
Signed	:A	end		84326261 Date: 27 July 2018
-				

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Altera Entries must be endorsed with Name, Rating and Certificate Nu Repair Facility. (See back pages for other specific entries.)	ations amber of Technician or
DATE		Model: S/N: C Engine Draine	npion filter P/N:	TAC-AERO TacAero 3650 Airport Drive Date: 8/4/2018 Hood River, OR 97031 Tach: 10.1	
<u> </u>					

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries mu		th Name, Rating	pairs and Alteration and Certificate Number cific entries.)	
			N#:84		S/N:CCX-2	000-0028		
			comple normal execute	range of spe ed, has no ha	Tach: 37,4 hat the prescribed fli- ircraft is controllable eds and throughout a zardous operating ch for operation.	e throughout its	ign	
			Name/	Byce Ana	elson Pilot Li	cense # 3 / 1 / 5°	16	
						F - 1 - 1 - 1	Y	
	+				Carson Aviation Services			-
				2640 E. College Pi	kwy, Carson city, NV 89706 AIRFRAME	PH.775-841-0400		8
	4-	DATE: 5-Jur TACH: 107.7	•	EG: N849W AF: 107.7	MAKE: Horsethy Avisition LLC.	MODEL: CCX-2000	SN: CCX-2000-0028	-
	wires	s, control boxes a	nd cables Gradind rup	engine and check fo	Services 100 ht/ Annual inspects YIO-360-EXP 128, CC3631-2011. It r proper operation. Annual inspection and was dete	nstalled new baffling. Replace	all ignition components, Plug	

YEAR 20 <u>79</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
19 Jun	117,9			Replaced alt air brocket on #1 expost take
				Replaced alt air bracket on #1 sylpust toke Shimmed tank covers, replaced front power plus
-				installed new stick covers, installed boot coul
				doubler, Stanlastrong IA56790669
CUBCRA	FTERS 19	20 South 10	6 th Ave - Yak	ima, WA 98903 (KYKM) Phone: (509) 248-1025 Fax: (509) 853-2783

09-05-2019

Cub Crafters Cub Crafters

CCX-2000 CC363i

SN CCX-2000-0028 SN CC363i-2011

N849W

Tach: 148.1

TT: 148 0

TT: 40.3

Removed Garmin GDU 465, PN 010-01057-19, SN unknown Installed new Garmin GDU 465, PN 010-01057-19, SN 3997861610. Performed operational check and configuration swing. No discrepancies noted. I certify that the work specified above was carried out in accordance with FAA airworthiness regulations and with respect the work performed, this aircraft is approved for return to service.

Todd Hildebrand A&P 3089718 IA

YEAR 20 DATE	RECORDING TACH TIME	G TODAY'S FLIGHT	TIME IN SERVICE	Entries must be ei		s, Repairs and Alt Rating and Certificate ner specific entries.)	t erations e Number of Technician o
	Date: 02/11/	2020 R	eg# N849W	SN#	Tach 233.	5 Hobbs	TT
-	Run leak chec I certify that a is in airworthy	k operation bove work v condition, v	normal vas accomplishe vith respect to th	ed in accordance e work accomplis	with the corrent PA	(filter screen, Fuel programmer and the April 13 has been performer)	aircraft identify above 2806567
	acc	ordance wit	h Part 43. Annei	ndix F	Order #_ <i>O 0/6</i>	The state of the s	ed in
	Dat		17.200		Transponder Mod Transponder S/N:	el: <u>G</u> TX345 3EH42020 YCCR0160	28
		ubCrafters 1920 S. 1	Avionics, LLC 6 th Avenue	CUBC	AFTERS	Certified Repair S 4CCR016C	

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	-			
CUBC	RAFTERS	920 South	16 th Ave - Yak	kima, WA 98903 (KYKM) Phone: (509) 248-1025 Fax: (509) 853-2783
03/19/20)		rsefly Aviation	n CCX-2000 SN CCX-2000-0028 N849W Tach: 224.0 TT: 224.0 CC363i SN CC363i-2011 TT: 224.0
Replace Adjuste ELT ba checked	ed the followi ed flight contr attery due 11/2 d. No discrep	ing items v rol cable te 2024. Trai pancies not	with new: ind ension. Inspension. Inspension Center of the constant of the con	on in accordance with Cub Crafters, Aircraft Maintenance Manual, Appendix A. duction filter PC54108-001, back up battery SP91001-201. Lubricated flight controls. ected and tested ELT in accordance with 14 CFR 91.207(d). No discrepancies noted. ert due 03/2022. Federal Registration due 04/2021. Aircraft ground run and leak that this aircraft has been inspected in accordance with the manufacturer's maintenant was found to be in a condition for safe flight.
Toll				
Todd H	lildebrand A&	εP 308971	C IA	