

PRIVATE JETS INC

COMPUTERIZED MAINTENANCE TRACKING

N393PJ

S/N 501-0303

Cessna Citation Model 501
Unit 0551

MFG Date Jul-80

Date **12/1/20**

L/H Engine

Aircraft Total Time 8507.1

Pratt & Whitney JT15D-1A

S/N PCE-76713

Aircraft Total Landings 7420

Hobbs 2547.8

TTSN	7396.1 Eng Hrs
TCSN	6407 Cycles
TTSN	1535.3 Eng Hrs
TCSN	1328 Cycles
TTS O/H	1535.3 Eng Hrs
TCS O/H	1328 Cycles

R/H Engine

Pratt & Whitney JT15D-1A

S/N PCE-77181

TTSN	8437.1 Eng Hrs
TCSN	7191 Cycles
TTSN	958.3 Eng Hrs
TCSN	847 Cycles
TTS O/H	2704.7 Eng Hrs
TCS O/H	2657 Cycles

Note* As a Model 500 S/N was 500-0397 Unit 551 SB11-4r5 changed the S/N to 501-0303 Unit 551

PHASE INSPECTION PROGRAM

Ref: Model 500 Maintenance Manual Chapter 5-10-00

Ref	Phase	INTERVAL	C/W	DUE	REMAINING	
B		150	8477.1	8627.1	120 AFTT HRS	
1	Method 3	300	8485.4	8785.4	278.3 AFTT HRS	
	Phases 1-4 are combined	24 mo	5/26/20	5/26/22	541 DAYS	
2		300	8485.4	8785.4	278.3 AFTT HRS	
		24 mo	5/26/20	5/26/22	541 DAYS	
3		300	8485.4	8785.4	278.3 AFTT HRS	
		24 mo	5/26/20	5/26/22	541 DAYS	
4		300	8485.4	8785.4	278.3 AFTT HRS	
		24 mo	5/26/20	5/26/22	541 DAYS	
5		1200	8475.9	9675.9	1168.8 AFTT HRS	
		36 mo	8/20/19	8/19/22	626 DAYS	
6	N/A Aircraft is not based in a corrosive environment					
7	N/A Drag chute not installed					
8	Oil change L/H Engine	Oil change is on condition per Pratt & Whitney M/M 72-00-00 pg 608				
8	Oil change R/H Engine	Oil change is on condition per Pratt & Whitney M/M 72-00-00 pg 608				
9	N/A No inspection critiera listed in maintenance manual for this phase					
10	N/A Foreign registered A/C only Gill sealed lead acid battery installed P/N G6381ES Inspected per Gill M/M see below					
11	N/A Aircraft registered in the Netherlands only					
12	ACM oil change	600	8245.5	8845.5	338.4 AFTT HRS	
		600	7176	7776	356 LANDINGS	
13	Emergency power supply PS-823 Nicad	Not installed				
14	Emergency power supply PS-835 Lead acid	Not installed				
15	Horiz & vertical fwd & aft spar	10000	0	10000	1492.9 AFTT HRS	One time then 15000 hrs
		15000				One time then 1000 hrs
		1000				Every 1000 hrs
16	Engine support structure &	10000	0	10000	1492.9 AFTT HRS	One time then 15000 hrs
		15000				One time then 1000 hrs
		3000				Every 3000 hrs
17	Horizontal stab attach fittings &	10000	0	10000	1492.9 AFTT HRS	

18	Inspect Toilet,life vests,oxy masks, emerg equip	1 yr	5/26/20	5/26/21	176	Days
----	--	------	---------	---------	-----	------

PHASE INSPECTION PROGRAM

CONTINUED

Ref: Model 500 Maintenance Manual Chapter 5-10-00

Ref	Phase	INTERVAL	C/W	DUE	REMAINING			
per SL 35-06	19	N/A	No inspection critiera listed in maintenance manual for this phase					
	20	91.411 & 91.413 & RVSM Certification	2 yrs	8/22/19	8/21/21	263	DAYS	
	21	Underwater locator beacon	2 yrs	N/A	Equipment not installed	See log date 6/2/09		
	22	Hydro test Oxygen & Gear bottle						
		Puritan Oxygen Bottle	3 yrs	9/7/18	9/6/21	279	DAYS	
		HTL Emergency Gear Bottle	3 yrs	9/7/18	9/6/21	279	DAYS	
	23	Elevator rate limiter (CAA requirement)	5 yrs	N/A	Aircraft is r			
8/22/08 7/30/99	24	Inspect Bulkhead,Spar, Etc	10000	0.0	10000.0	1492.9	AFTT HRS	
			3000				AFTT HRS	
							One time inspect then every 3000hrs thereafter	
	25	Engine Hot Section Inspection L/H	1750	Per rev 35 Phase 25 not used. See below component time limits				76713
		Engine Hot Section Inspection R/H	1750	Per rev 35 Phase 25 not used. See below component time limits				77181
	26	N/A	Hydro test performed on Phase 22					
	27 thru 33	N/A	No inspection critiera listed in maintenance manual for these phases					
	34	Inspect portable fire extinguisher, etc	6 mo	11/19/20	5/20/21	171	DAYS	
	35 & 36	N/A	No inspection critiera listed in maintenance manual for these phases					
	37	Structure inspection	5000	5006.5	10006.5	1499.4	AFTT HRS	
38	N/A	No inspection critiera listed in maintenance manual for this phase						
39	N/A	For aircraft with Camara pod & Nav sight installed						
40	Inspect Cabin Door Fuselage Frame	10000	Per Revision 35 This inspection is not currently used					
41	N/A	For aircraft registered in the Netherlands or France only						
42 thru 46	N/A	No inspection critiera listed in maintenance manual for this phase						
47	Hydro Test Portable Fire Extinguishers	12 yrs	11/19/19	11/16/31	4002	DAYS		
48	Inspect Portable Fire extinguishers	6 yrs	6/8/18	6/6/24	1283	DAYS		
49	Inspect Windshields,Windows,Skin Seam	3 yrs	5/29/20	5/29/23	909	DAYS		
		1200	8249.5	9449.5	942.4	AFTT HRS		
50	Inspect Front Carry-Thru to Wing Spar Lugs	3 yrs	Not currently used					
		1200	Not currently used					
51	N/A	for aircraft not incorporating SB 28-10						
52	Forward & Aft bulkhead inspection	5000	6871.1					
		2000	6871.1	8871.1	364	AFTT HRS		
							One time inspect then every 2000hrs thereafter	

PHASE INSPECTION PROGRAM

CONTINUED

Ref: Model 500 Maintenance Manual Chapter 5-10-00

Ref	Phase	INTERVAL	C/W	DUE	REMAINING	
53	ELT inspect & test FAR 91.207 (d)	12 mo	9/18/20	9/18/21	291 DAYS	
MA	Inspect NLG Fork	12000 1000	0	12000	4580 Landings	One time inspect then every 1000 lds after
MC	Inspect NLG Fork British Certified Aircraft Only		Per Revision 35		Inspection currently not used	
MD	Inspect MLG side brace fitting	5000	4530	9530	2110 Landings	
ME	N/A British certified aircraft only		Per Revision 35		Inspection currently not used	
MF	Inspect brake L/H	200	7334	7534	114 Landings	
MF	Inspect brake R/H	200	7334	7534	114 Landings	
MG	Inspect brakes		For aircraft with T/R's installed only			
!yr	Reweigh Aircraft	3 yr	9/21/20	9/21/23	1024 Days	
	Gill Sealed Lead Acid Batteries					
		Initial Inspection	800		AFTT HRS	One time inspect then
		Initial Inspection	1 yr		DAYS	400hrs or 6 mo
	GILL P/N 7638-44	400	8463.2	8863.2	356.1 AFTT HRS	
P & W	Borescope engine L/H	300	4170.9	SB 7288 installed	This insp no longer required	
P & W	Borescope engine R/H	300	7024.8	SB 7288 installed	This insp no longer required	
P & W	Inspect Oil Filter L/H		C/W during the Phase 2 & 4			
P & W	Inspect Oil Filter R/H		C/W during the Phase 2 & 4			
P & W	Engine Minor Inspection Phase 4 L/H	300	8395.4	8695.4	188.3 AFTT HRS	
P & W	Engine Minor Inspection Phase 4 R/H	300	8395.4	8695.4	188.3 AFTT HRS	

RVSM

Instruction for Continued Airworthiness Document IC2703-34254

Ref	Description	INTERVAL	C/W	DUE	REMAINING	P/N	S/N
AAIP	RVSM inspection guide	24 mo	8/22/19	8/21/21	263 DAYS		

PORTABLE FIRE EXTINGUISHER INSPECTIONS

NFPA No. 10

Ref	Description	INTERVAL	C/W	DUE	REMAINING	P/N	S/N
-----	-------------	----------	-----	-----	-----------	-----	-----

	Inspect portable fire extinguisher	Cockpit	30 day	12/1/20	12/31/20	30	Days	
Phase 34	Inspect portable fire extinguisher	Cockpit	1 yr	9/21/20	9/21/21	294	Days	
Phase 48	Inspect portable fire extinguisher	Cockpit Internal	6 yr	6/8/18	6/6/24	1283	Days	
Phase 47	Inspect portable fire extinguisher	Cockpit Hydro	12 yr	6/8/18	6/5/30	3473	Days	
	Inspect portable fire extinguisher	Cabin	30 day	12/1/20	12/31/20	30	Days	X-481504
Phase 34	Inspect portable fire extinguisher	Cabin	1 yr	9/21/20	9/21/21	294	Days	
Phase 48	Inspect portable fire extinguisher	Cabin Internal	6 yr	6/8/18	6/6/24	1283	Days	
Phase 47	Inspect portable fire extinguisher	Cabin Hydro	12 yr	6/8/18	6/5/30	3473	Days	

COMPONENT TIME LIMITS

Ref: Model 500 Maintenance Manual Chapter 5-11-00

Ref	Description		INTERVAL	C/W	DUE	REMAINING	P/N	S/N
O/H	Environment Control Unit (Hamilton Standard)							
	Air cycle machine		5000	Cessna Refrigeration unit installed		P/N 9912069-21		
O/H	Overhead Cabin Fan	Blower assy	1200	8414.2	9614.2	1107.1	AFTT HRS BC61A-901-2	629A
	Engine Fire Extinguisher Cartridges							
	Forward bottle							
	Log entry 6/8/18	Total life (MFG Date)	10 yrs	10/15/17	10/13/27	2507 DAYS	M13083-5	
	Log entry 6/8/18	Total life (MFG Date)	10 yrs	10/15/17	10/13/27	2507 DAYS	M13083-5	

COMPONENT TIME LIMITS

Ref: Model 500 Maintenance Manual Chapter 5-11-00

Ref	Description		INTERVAL	C/W	DUE	REMAINING	P/N	S/N
	Aft Bottle	Service life (installed)	4 yrs					
	Log engty 6/8/18	Total life (MFG Date)	10 yrs	10/15/17	10/13/27	2507 DAYS	M13083-5	
		Service life (installed)	4 yrs					
	Log engty 6/8/18	Total life (MFG Date)	10 yrs	10/15/17	10/13/27	2507 DAYS	M13085-5	
	Engine Fire Bottle Fwd	Hydro	5yrs	6/7/17	6/6/22	552 Days		B13588
	Engine Fire Bottle Aft	Hydro	5yrs	6/7/17	6/6/22	552 Days		B13576
	Flap Gear Box	L/H	3000	6798.1	9798.1	1291.0	AFTT HRS 5565175-38	120796
		R/H	3000	6798.1	9798.1	1291.0	AFTT HRS 5565175-38	120193
	Brake Assyembly Goodrich	L/H	749	7125	7874	454 Landings	2-1530-4	3275

	R/H	749	7125	7874	454 Landings	2-1530-4	2969
Main Landing Gear							
Trunnion Attach Pin	L/H	28600	0	28600	21180 Landings	5541205-3	
	R/H	28600	0	28600	21180 Landings	5541205-4	
Actuator assembly	L/H	37500	0	37500	30080 Landings	9912053-13	DA1145
	R/H	37500	0	37500	30080 Landings	9912053-12	DA767
Actuator Attach Pin	L/H	28600	4895	33495	26075 Landings	6527213-2	
	R/H	28600	0	28600	21180 Landings	6527213-2	

COMPONENT TIME LIMITS

Ref: Model 500 Maintenance Manual Chapter 5-11-00

Ref	Description	P/N	INTERVAL	C/W	DUE	REMAINING	P/N	S/N
Main Landing Gear Assembly		P/N	5541000-11 & 5541000-12					
Actuator Attach Stud	L/H		28600	0	28600	21180 Landings	6541204-2	
	R/H		28600	0	28600	21180 Landings	6541204-2	
Trunnion	L/H		28600	0	28600	21180 Landings	5541306-3	
	R/H		28600	0	28600	21180 Landings	5541306-3	
Cylinder Assembly	L/H		16100	0	16100	8680 Landings	5541109-5	
	R/H		16100	0	16100	8680 Landings	5541109-6	
Piston Weld Assembly	L/H		15000	0	15000	7580 Landings	5541108-5	
	R/H		15000	0	15000	7580 Landings	5541108-6	
Axle	L/H		28600	0	28600	21180 Landings	6541200-1	
	R/H		28600	0	28600	21180 Landings	6541200-1	
Upper Piston Bearing	L/H		28600	0	28600	21180 Landings	5541310-3	
	R/H		28600	0	28600	21180 Landings	5541310-3	
Upper Torque Link Assembly	L/H		28600	0	28600	21180 Landings	5541304-9	
	R/H		28600	0	28600	21180 Landings	5541304-10	
Lower Torque Link Assembly	L/H		28600	0	28600	21180 Landings	5541304-11	
	R/H		41600	0	41600	34180 Landings	5541304-6	
Torque Link Shaft	L/H		28600	0	28600	21180 Landings	6541212-2	
	R/H		28600	0	28600	21180 Landings	6541212-2	

Torque Link Bolt	L/H	41600	0	41600	34180 Landings	5541220-2
	R/H	41600	0	41600	34180 Landings	5541220-2
Torque Link Nut	L/H	28600	0	28600	21180 Landings	MS17825-8
	R/H	28600	0	28600	21180 Landings	MS17825-8
Forward Trunnion Fitting Assy	L/H	20000	0	20000	12580 Landings	552270-1
	R/H	20000	0	20000	12580 Landings	5522700-2
Aft Trunnion Fitting Assembly	L/H	41600	0	41600	34180 Landings	5522710-1
	R/H	41600	0	41600	34180 Landings	5522710-2

COMPONENT TIME LIMITS

Ref: Model 500 Maintenance Manual Chapter 5-11-00

Ref	Description	INTERVAL	C/W	DUE	REMAINING	P/N	S/N
	Nose Landing Gear	Parts included with gear					
	Nose Landing Gear Assy	41000	0	41000	33580 Landings		
	Trunion Pins	41000	0	41000	33580 Landings		
	Actuator Support Fitting	41000	0	41000	33580 Landings		
	Actuator Attach Bolt	41000	0	41000	33580 Landings		
	Piston Weld Assembly	41000	0	41000	33580 Landings		
	Fork	41000	0	41000	33580 Landings		
	Cylinder Braze Assembly	N/A	For P/N 9912063-3 P/N installed 9912063-13				
	Upper Torque Link	41000	0	41000	33580 Landings		
	Lower Torque Link	41000	0	41000	33580 Landings		
	Axle Shaft	41000	0	41000	33580 Landings		
	Axle Bucket	41000	0	41000	33580 Landings		
	Exceptions						
	Trunion Assembly	22500	0	22500	15080 Landings	5542301-5	
	Actuator Assembly	32600	0	32600	25180 Landings	9912063-13	
	Axle Spacer	22500	0	22500	15080 Landings	5542223-1	
	Torque Link Shaft	22500	0	22500	15080 Landings	5542208-3	
	Trunnion Support Fitting	L/H 22500	5395	27895	20475 Landings	5513056-5	
		R/H 22500	0	22500	15080 Landings	5513056-6	
	Pneumatic Blowdown / Emergency Brake Bottle						

ReplaceHTL / Pacific Scientific24 yrs10/15/0210/9/262138 DAYS
Locator Beacon Battery Pack (ELT)Log 6/8/183yr4/15/184/14/21134 DAYS
ELT110-4Artex
P/N 452-0130

COMPONENT TIME LIMITS

Ref: Model 500 Maintenance Manual Chapter 5-11-00

Ref	Description				INTERVAL	C/W	DUE	REMAINING	P/N	S/N
Replace	Oxygen Bottle				24 yrs	3/1/06	3/1/30	3377 DAYS	176176-64	547657
	3HT1850									
	Oxygen Masks									
	Pilot	Log entry	11/11/16	12 Yr	11/9/16	11/6/28	2897 DAYS	MC10-16-101	39469I	
	Co-Pilot	Log entry	11/11/16	12 yr	11/9/16	11/6/28	2897 DAYS	MC10-16-101	54377I	
	Passenger Oxygen Masks									
	Fwd	Box 1	Mask 1	Log entry 1/12/15	8 yr	8/5/14	8/3/22	610 DAYS	C351-2000-205	
			Mask 2		8 yr	3/11/13	3/9/21	98 DAYS	or	
		Box 2	Mask 3		8 yr	8/5/15	8/3/23	975 DAYS	Customer P/N	
		Box 3	Mask 4		8 yr	8/5/14	8/3/22	610 DAYS	174505-01	
			Mask 5		8 yr	3/11/13	3/9/21	98 DAYS		
		Box 4	Mask 6		8 yr	8/5/14	8/3/22	610 DAYS		
			Mask 7		8 yr	8/5/14	8/3/22	610 DAYS		
		Box 5	Mask 8		8 yr	8/5/14	8/3/22	610 DAYS		
	Power Plants									
	L/H	Engine Mounts		Aft	3500	6970.8	10470.8	1963.7 AFTT HRS	9912455-2	2293
				Fwd Top	3500	6970.8	10470.8	1963.7 AFTT HRS	9912455-1	3138
				Fwd Bottom	3500	6970.8	10470.8	1963.7 AFTT HRS	9912455-1	3133
	R/H	Engine Mounts		Aft	3500	5698.2	9198.2	691.1 AFTT HRS		
				Fwd Top	3500	5698.2	9198.2	691.1 AFTT HRS		
				Fwd Bottom	3500	5698.2	9198.2	691.1 AFTT HRS		
	L/H	Engine Overhaul	8/22/08	5079	3500	5860.8	9360.8	1964.7 Eng Hrs	JT15D-1A	76713
	R/H	Engine Overhaul	7/30/99		3500	5732.4	9232.4	795.3 Eng Hrs	JT15D-1A	77181
Phase 25	L/H	Engine Hot Section	Cycles HSI	5079	1750	5860.8	7610.8	214.7 Eng Hrs	JT15D-1A	76713
Phase 25	R/H	Engine Hot Section	Cycles HSI	6344	1750	7478.8	9228.8	791.7 Eng Hrs	JT15D-1A	77181
	Starter / Generators									
	L/H	Engine			1000	8455.9	9455.9	948.8 AFTT HRS	23080-001-1	1108
	R/H	Engine			1000	8414.2	9414.2	907.1 AFTT HRS	23080-001-1	2614

JT15D-1A**S/N 77181**

Ref: Life Limit Items in SB P&WC 72-7002 &

Disk Time Record Sheet from Overhaul Dated 9/22/89

At Overhaul	7/20/99	TTSN	5732.4	Last Overhaul	9/22/89	TTSN	3503.9
		TCSN	4534			TCSN	2511

At Install

Description	P/N S/N	Life Limit Cycles	Total Cycles Date	Total Cycles on Part	Remaining Cycles
Hub Low Compressor	3018018T 4D065	27500	5022 9/22/89	9702	17798 Cycles
Note: Hub Low Compressor has a Flight Count Factor =2				Total FCF Cycles	19404
Total Flights = Number of Flights x flight Count Factor				Remaining Cycles	8096

Impeller	3031577 6A621	8400	2511 9/22/89	7191	1209 Cycles
High Turbine Disk	3023411 7D327	14000	6344 10/24/12	7191	6809 Cycles
Second Turbine Disk	3022212R 8D723	14000	2511 9/22/89	7191	6809 Cycles
Third Turbine Disk	3036113 6D640	14000	2511 9/22/89	7191	6809 Cycles
High Turbine Blades	3028601	3500	1816.0 10/24/12	2774.3	725.7 Eng Hrs

AIRWORTHINESS DIRECTIVES (AD's)

Ref	Description	INTERVAL	C/W	DUE	REMAINING
73-26-09	Flight Compartment side Window	N/A	Due to S/N of Aircraft		
74-26-05	Fuel Control Units	L/H	N/A	P/N not installed per Overhaul sheet	
74-26-05	Fuel Control Units	R/H	N/A	P/N not installed per Overhaul sheet	

79-12-06	Upper & Lower Spar Cap Stems	N/A	Due to S/N & Unit number
80-09-09	Dual Flight Director Installation	N/A	Due to S/N of Aircraft
83-01-06		N/A	8/3/07 6815.8 Equipment not installed
87-10-01	Fan blades L/H	C/W	8/22/08 Found embodied at O/H
87-10-01	Fan blades R/H	C/W	4/23/87 C/W at overhaul by Volvo Fly
87-20-05	Seat belts	N/A	6/1/88 3171
87-17-06	Seat belts	N/A	6/1/88 3171
89-06-01	Switlik Life Jackets	N/A	5/7/89 Type not installed
90-03-02	Vertical Gyro	N/A	3/12/90 3668
90-07-01	Keith Air conditioner	N/A	5/16/90 3719
93-05-15	Thrust Reveerser Throttle Load Limiter	N/A	Thrust Reversers not installed
93-18-08	High pressure turbine assembly L/H	C/W	8/22/08 Found embodied at O/H
93-18-08	High pressure turbine assembly R/H	N/A	9/12/96 5283.6
94-19-06	Puritian Oxygen Masks	C/W	2/6/95 4821.2
95-25-10	Outflow / safety Valve	N/A	7/20/96 Due to P/N installed
98-04-38	AFM - Limitations Section - icing	C/W	5/2/98 5631.3 Blue logbook, yellow section
98-25-02	BF Goodrich skywatch	C/W	8/17/99 5698.2 Blue logbook, yellow section
98-25-10	Aircraft Belts INC	C/W	8/17/99 5698.2 Blue logbook, yellow section
99-08-21	Puritian Bennett	C/W	8/17/99 5698.2 Blue logbook, yellow section
001-23-17	Garmin GNS430	N/A	6/9/02 GNS 430 not installed
003-13-08	Goodrich Avionics systems	N/A	1/19/04 6387.4 Equipment not installed
004-04-09	Impellers L/H	C/W	8/22/08 Found embodied at O/H
004-04-09	Impellers R/H	N/A	4/13/04 6416 Impeller P/N not installed
004-08-15	TAWS 8000 Terrain	N/A	5/4/04 6431.4 Equipment not installed
004-09-05	Brake Stator Disks	N/A	7/5/04 6441.7
005-01-05		N/A	8/15/08 Software 4.06 is installed
005-01-19	Garmin GTX330	N/A	8/15/08 Verified that software 4.06 in installed
005-25-08	Shadin ADC 2000	N/A	4/26/06 6674.4 Equipment not installed
006-04-10	Incorrect wires engine fire bottles	C/W	4/26/06 6674.4 SB 26-02 C/W on 6/10/05
006-06-03	Airplane Flight Manual (AFM)	C/W	5/10/06 6674
006-16-18	Sandel TAWS ST3400	C/W	9/14/06 6757.4
06-16-18R1	Sandel TAWS ST3400	C/W	9/14/06 6757.4 Per this log entry Software 3.07 has been loaded
007-11-17	Wires for positive & negative terminal fire bottles	C/W	4/26/06 6674.4 SB 26-02 C/W on 6/10/05
010-01-03	Fire Fighting Enterprises Halon fire extinguishers	N/A	1/5/10 Verified by CH Manufacturer not installed
011-01-09	BE Aerospace PBEs	N/A	1/5/11 Equipment not installed

011-04-09	Oxygen Generators	N/A		Oxygen generators not installed
012-11-09	R1 Oxygen Generators	N/A	8/14/15	8020.3 Equipment not installed
013-09-11	Air conditioner compressor motor P/N 1134104-1,-5	N/A	7/1/13	Keith Products installed P/N ES61108-1
015-08-07	Crew oxygen masks	N/A	6/1/15	Type not installed
015-10-51	Avidyne Integrated Flight Displays	N/A	6/1/15	Avidyne equipment not installed
015-17-12	Air conditioner compressor motor	N/A	8/26/15	8020.3 STC & P/N of motor not installed
015-23-09	Zodiac oxygen masks	N/A	12/4/15	8081.2 MFG & P/N not installed
016-11-20	BE Aerospace PBEs	N/A	12/23/16	8219.2 Equip not installed
018-21-14	Zodiac Aerotechnics MC10 series oxygen masks	N/A	3/26/19	8450.5 Do to P/N installed

SERVICE BULLETINS (SB's)

Ref		Description	INTERVAL	C/W	DUE	REMAINING
SB	11-4 R5	Model 500 conversion to 501	C/W	12/14/01	5964.5	
SL	21-20	Compressor drive motor brush inspect/replacement	C/W	3/8/94	4531.9	
SB	21-23	Outflow valve	C/W	5/31/95	4901.3	
SB	23-18	VLF noise filter	C/W	11/8/00	5841.4	Blue logbook yellow section
SB	23-22	Sunstrand CVR	N/A	12/12/94	4795.1	
SB	24-18	Wing tip wire bundle	C/W	11/8/00	5841.4	Blue logbook yellow section
SL	500-25-3	Inspect / Modification of personel flotation devices				
SL	25-08	Replace CO2 cartridge in life vests	C/W	1/28/97	5364.8	
SB	25-09	Glareshield	C/W	11/8/00	5841.4	Blue logbook yellow section
SB	26-02	Engine fire bottle wiring	C/W	6/10/05	6608.4	
SB	27-9	Speed brake switch	C/W	11/25/88	3348	
SB	27-14	Flap motor connector	C/W	3/20/07	6798.1	
SB	27-15	L & R flap gear box	C/W	5/6/02	6026.5	
SB	27-16	Elevator electric trim	C/W	11/8/00	5841.4	Blue logbook yellow section
SB	28-7 R5	Motive Flow Fuel press switch removal	C/W	12/14/01	5964.5	
SB	28-08	Fuel cell inspection	C/W	3/14/96	5152.2	
SB	28-09	Airborne fuel pump	C/W	9/11/96	5283.5	
SB	28-10	Fuel cell foam block	C/W	6/21/01	5916.2	Black binder WO SE-DVA
SB	28-12	Wing boost pump wiring	C/W	5/10/06	6674	Installed kit #SB500-12-0

SB	32-38	Brakes	N/A	1/22/90	3652
SB	32-42	MLG wheel well hyd lines grommet replacement	C/W	3/8/94	4531.9
SB	32-45	Power brake screw	C/W	11/10/00	5841.4 Cessna log book
SB	32-47	Goodrich brakes	C/W	11/8/00	5841.4 Blue logbook yellow section
SB	32-48	Goodrich brakes	C/W	11/8/00	5814.4 Blue logbook yellow section
SL	32-53	NLG Uplock line inspection	C/W	3/8/94	4531.9
SL	32-54	Landing gear locking solenoid inspection	C/W	3/8/94	4531.9
SL	32-56	Cleveland brake bolt replacment	N/A	10/25/93	4394.5 Equipment not installed
SL	32-57	NLG down and lock switch inspection	C/W	3/8/94	4531.9
SL	32-62	MLG actuator stud inspection	C/W	10/25/93	4394.5
SL	32-66	NLG wheel hardware inspection	C/W	11/10/94	4773.3
SB	32-85	Emergency air bottle replace	C/W	1/28/97	5364.8

SERVICE BULLETINS (SB's)

Ref		Description	INTERVAL	C/W	DUE	REMAINING
SL	33-04	Landing light switch replace	C/W	10/25/93	4394.5	
SB	33-13	Emergency light battery upgrade	C/W	5/16/16	8112.2	
SB	34-15	9500 lb Zero fuel	C/W	3/17/97	5416	
SB	34-57	Starter/Generator & GCU filter installation	C/W	3/8/94	4531.9	
SB	34-58	Vertical gyro	N/A	11/9/89	3603	
SI	430-100	Glareshield mod	C/W	4/30/07	6804.6	
SB	35-06	Eros mask	C/W	11/11/16	8198.0	
SB	52-15	Cabin door hinge pin	C/W	1/12/88	3025.0	
SB	52-16	Entry step improvement installation	C/W	3/8/94	4531.9	
SB	52-18	Baggage door safety lock installation	N/A	8/3/07	6815.8	Equipment not installed
SB	52-19	Door step catch cover	C/W	11/8/00	5841.4	Blue logbook yellow section
SB	56-6 R4	Windshield replacement L/H	C/W	12/14/01	5964.5	
SL	57-04	Wire bundle route improvement	C/W	3/8/94	4531.9	
SB	57-05	Wing carry-thru spar fitting inspection	C/W	9/15/95	5038.3	
SL	500-72-10	Inspection of Impeller L/H	C/W	8/22/08	SB 7590 was found embodied at O/H	
SL	500-72-10	Inspection of Impeller R/H	N/A	P/N of Impeller not installed		

SL	74-04	Igniter box grounding		C/W	2/22/01	5874.3
SB	7136R4	Oil Pump	L/H	C/W	7/16/09	5934.8 Eng TT
SB	7185R2	Oil Pump	L/H	C/W	7/16/09	5934.8 Eng TT
SB	7193		L/H	C/W	8/18/94	
SB	7193		R/H	C/W	9/22/81	
	7281		L/H			
	7281		R/H			
	7288		L/H	C/W	8/18/94	
	7288		R/H	C/W	3/28/00	
	7297		L/H			
	7297		R/H	C/W	10/25/93	
	7306		L/H	C/W	8/22/08	
	7306		R/H			
	7317		L/H	C/W	8/18/94	
	7317		R/H	C/W	3/28/00	
	7476		L/H			
	7476		R/H			
	7581					
	7581					

