

~~TH 1848 RH~~
TH 1848 2H



McCAULEY

PROPELLER LOGBOOK

REG NO N2348Q LT **CHANDLER AVIATION INC**
MODEL 58 CHANDLER MUNICIPAL
S/N TH1848 CHANDLER, AZ
ENG MOD IO550C (480) 732-9118
ENG S/N 824335R

DATE 11/21/03
WO# 22077
HOBBS 2272
TACH XXX
TOTAL XXX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND
AIRWORTHY FOR RETURN TO SERVICE ON THE DATE 11/21/04 ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE [Signature]

AUTH. NO. 2307335 A&P

Dressed and repainted faces of prop blades. I certify that this propeller has been
inspected in accordance with a Beechcraft 100 hour inspection and was determined
to be in airworthy condition.

END

NOTE

Having work performed at a facility other than
Approved Service Station

| | | | | |
|---------|----------------|---------------------------------|-------|-----------------|
| REG NO | <u>N2348Q</u> | LT CHANDLER AVIATION INC | DATE | <u>02/17/04</u> |
| MODEL | <u>58</u> | CHANDLER MUNICIPAL | WO# | <u>25043</u> |
| S/N | <u>TH1848</u> | CHANDLER, AZ | HOBBS | <u>2370</u> |
| ENG MOD | <u>IO550C</u> | (480) 732-9118 | TACH | <u>XXX</u> |
| ENG S/N | <u>824335R</u> | | TOTAL | <u>XXX</u> |

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE  11/17/04 AUTH. NO. 2307335 A&P

Dressed and repainted faces of prop blades. I certify that this propeller has been inspected in accordance with a Beechcraft 100 hour short form #98-39097B inspection and was determined to be in airworthy condition.

END

| | | | | |
|---------|----------------|---------------------------------|-------|-----------------|
| REG NO | <u>N2348Q</u> | LT CHANDLER AVIATION INC | DATE | <u>06/25/04</u> |
| MODEL | <u>58</u> | CHANDLER MUNICIPAL | WO# | <u>25531</u> |
| S/N | <u>TH1848</u> | CHANDLER, AZ | HOBBS | <u>2370</u> |
| ENG MOD | <u>IO550C</u> | (480) 732-9118 | TACH | <u>XXX</u> |
| ENG S/N | <u>824335R</u> | | TOTAL | <u>XXX</u> |

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.


SIGNATURE

AUTH. NO. 299827544 A&P

Dressed and repainted faces of prop blades. I certify that this propeller has been inspected in accordance with a Beechcraft 100 hour short form #98-39097B inspection and was determined to be in airworthy condition.

END

INSTALLATION HISTORY

| Date | Aircraft Model & Registration No. | Engine Serial Number & Position |
|-------------|---|---|
| JAN 31 1998 | THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE. |  |
| 3-21-98 | 58 N2348Q | 683718 LH |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

MAINTENANCE & SERVICE HISTORY

C DATE: 2/18/99 Prop: 3AF32C512-C W/O: 33430 Page 1 of
AC : TH-1848 S/N : 980195 TSN: 302.7 HOBBS : 302.7
REG#: N2348Q Loc.: LH TSO:

INSPECTIONS:

1. C/W ANNUAL INSPECTION I/A/W BEEHCRAFT BARON 55, 56TC AND 58
100 HOUR OR ANNUAL LONG FORM INSPECTION GUIDE P/N 118662H.

MAINTENANCE NOTES:

1. SECURED PROP DOME SCREWS WITH .032 SAFETY WIRE.
2. SANDED, PRIMED AND PAINTED RH PROP.

AIRWORTHINESS DIRECTIVES THROUGH BI-WEEKLY 99-03 HAVE BEEN VERIFIED
FOR COMPLIANCE.

I certify that this propeller has been inspected in accordance with
inspections and procedures for an inspection program required by
FAR 91.409 (a)(1) and has been found to be in airworthy condition
and is approved for return to service. Pertinent details are on file at
this repair station under work order # 33430 dated 2/18/99

INSPECTION : ANNUAL

Authorized Signature



RAYTHEON AIRCRAFT SERVICES, INC. CRS# VG4R595M
2450 N. WESTSHORE BLVD. TAMPA, FL. 33607

res
ion
rs

NC

12

MAINTENANCE & SERVICE HISTORY

DATE: 8/26/99

REG: N2348Q

AFTT: 347.5

S/N: TH-1848

HOBBS: 347.5

W/O: 34882

PROP:

3AF32C512C

(LEFT)

TSN: 347.5

DATE OF OVHL: N/A

PAGE 1 OF 1

S/N: 980195

TSO:

natures
Station
mbers

INSPECTIONS:

1. PERFORMED ANNUAL INSPECTION I/A/W BEECHCRAFT BARON 55, 56TC AND 58 100 HOUR OR ANNUAL LONG FORM INSPECTION GUIDE P/N 118662H.
ALL AIRWORTHINESS DIRECTIVES THRU BI-WEEKLY 99-17, HAVE BEEN VERIFIED FOR COMPLIANCE.

I certify that this PROPELLER has been inspected in accordance with inspections and procedures for an inspection program required by FAR 91.409 (a)(1) and has been found to be in airworthy condition and is approved for return to service. Pertinent details are on file at this repair station under work order # 34882 dated 8/26/99.

INSPECTION : ANNUAL.

Authorized Signature



RAYTHEON AIRCRAFT SERVICES, INC. CRS# VG4R595M

2450 N. WESTSHORE BLVD. TAMPA, FL. 33607

1 & 12

PRICE & SERVICE HISTORY

| Date | Total Propeller Time | Time Since Overhaul | Description Of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|--|----------------------|---------------------|---------------------|---|
| <p>REG NO <u>N-2348Q</u> LT CHANDLER AVIATION INC DATE <u>10/08/02</u></p> <p>MODEL <u>58</u> CHANDLER MUNICIPAL WO# <u>18893</u></p> <p>S/N <u>TH1848</u> CHANDLER, AZ HOBBS <u>1700</u></p> <p>ENG MOD <u>IO550C30B</u> (480) 732-9118 TACH <u>XXX</u></p> <p>ENG S/N <u>824335-R</u> TOTAL <u>XXX</u></p> <p><small>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.</small></p> <p>SIGNATURE <u></u> AUTHORIZED NO. <u>316866035</u> A&P</p> <p>Removed, repaired, and re-installed left engine prop, S/N 980195</p> <p>END</p> | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

SERVICEABLE

MFGR. NAME Woodward

COMPONENT NAME Governor

MODEL B210800

SERIAL 12025601

Remarks: Bench Test

and Reset Probe.

MAINTENANCE RELEASE

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency, and was found to be in an airworthy condition for return to service.

Pertinent details of the repair are on file at this agency.

Work Order No. 64421

Date 10/10/00

Signed [Signature]

FAA APPROVED REPAIR STATION NO. ZR2R355L
PROPELLER, POWER PLAN AND ACCESSORIES
CLASS 1 AND 2 LIMITED

OTTOSEN

Propeller & Accessories, Inc.

105 SOUTH 28th STREET • PHOENIX, ARIZONA 85034
(602) 275-8514

HISTORY

Authorized Signatures
Repairman and Station
Certificate Numbers

0/08/02

8893

700

XX

XXX

TIONS AND WAS FOUND

035 A&P

35

END

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

(602) 275-8514

HISTORY

| Authorized Signatures Repairman and Station Certificate Numbers | |
|---|--|
| 10/08/02 | |
| 8893 | |
| 700 | |
| XXX | |
| XXX | |
| ATIONS AND WAS FOUND | |
| 035 A&P | |
| 95 | |
| | |
| | |
| | |
| e Bulletins On Pages 11 & 12 | |

MAINTENANCE & SERVICE HISTORY

| | | | | Signatures and Station Numbers |
|---|-----------|------------------------------|------------------------------|--------------------------------------|
| REG NO | N-2348Q | LT | CHANDLER AVIATION INC | DATE 04/06/02 |
| MODEL | 58 | | CHANDLER MUNICIPAL | WO# 18323 |
| S/N | TH1848 | | CHANDLER, AZ | HOBBS 1497 |
| ENG MOD | IO550C30B | | (480) 732-9118 | TACH XXX |
| ENG S/N | 824335-R | | | TOTAL XXXXXXXX |
| <small>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.</small> | | | | |
| SIGNATURE | | AUTHORIZED NO. 316866035 A&P | | |
| R&R propeller for overhaul, see Ottosen's propeller and accessories | | | | |
| yellow tag dated 0205/02. Torqued prop belts. | | | | |
| END | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12 | | | | |

MAINTENANCE & SERVICE HISTORY

| Date | Total Propeller Time | Time Since Overhaul | Description Of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|------|----------------------|---------------------|---------------------|---|
|------|----------------------|---------------------|---------------------|---|




HOBBS 3345.1
TOTAL -----
TSOH -----
DATE 1/9/06

AIRCRAFT MAINTENANCE & REPAIR
FALCON FIELD – MESA, AZ

REG # N2348Q
A/C # TH-1848
PROP # 980195

REMOVE PROPELLER FOR OVERHAUL BY OTTOSEN, WORK ORDER # 85279 AND REINSTALL AFTER OVERHAUL. OPS TEST SATISFACTORY. THIS PROPELLER IS APPROVED FOR RETURN TO SERVICE.

 A/P 527825638

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

1575 East Ryan Rd.
Chandler, AZ 85249
Phone: (480) 785-7722
Cell (480) 296-3305



N Number: 2348Q LH
Hobbs Time: 1689.7
TSMOH: 149.1
Date: 7/27/2011

I certify that this propeller has been inspected in accordance with a 100 hr/annual long form inspection P/N 118662Q and was found to be in airworthy condition.

Chad Thomas
Signature

---END---

AP 341 7648
Certificate Number

1575 East Ryan Rd.
Chandler, AZ 85249
Phone: (480) 785-7722
Cell: (480) 296-3305



N Number: 2348Q LH
Hobbs Time: 1984.1
TSMOH: 443.5
Date: 6/8/2012

I certify that this propeller has been inspected in accordance with a 100 hr/annual long form inspection P/N 118662Q and was found to be in airworthy condition.

Chad Thomas
Signature

---END---

AP 341 7648 IA
Certificate Number

| | | | | | |
|----------|------------|----|-----------------------|------------|----------|
| REG NO | N2348Q | LT | CHANDLER AVIATION INC | DATE | 04/03/13 |
| MODEL | 58 | | CHANDLER MUNICIPAL | WO# | 50150 |
| S/N | TH1848 | | CHANDLER, AZ | HOBBS | 2283.8 |
| PROP M/N | 3AF32C512C | | (480) 732-9118 | TACH | XXX |
| PROP S/N | 980195 | | | TOTAL SMOH | 743.2 |

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS FACILITY.

SIGNATURE [Signature] AUTH. NO. 2307335 IA

Perform minor dressing of leading edge. I certify that this propeller has been inspected in accordance with a Hawker Beechcraft Long / Annual Inspection form P/N 118662Q dated April 1/11 and was determined to be in airworthy condition.

END

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2377.0
TSMOH: 836.4
Date: 07/12/2013

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

—END—


Signature

A7P2727343 IA
Certificate Number


Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2461.3
TSMOH: 920.7
Date: 09/30/2013

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

—END—


Signature

A7P2727343 IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2559.2
TSMOH: 1018.6
Date: 02/17/2014

- This propeller has been inspected in accordance with Hawker Beechcraft 100 hour long / annual inspection form P/N: 118662Q dated: 04/01/2011 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

—END—


Signature

A7P2727343 IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2638.6
TSMOH: 1098.0
Date: 05/12/2014

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

—END—


Signature

A7P2727343 IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2729.9
TSMOH: 1189.3
Date: 07/22/2014

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

—END—


Signature

A7P2727343 IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2826.7
TSMOH: 1286.1
Date: 09/30/2014

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

--END--

Signature 

A7P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 2926.0
TSMOH: 1385.4
Date: 02/02/2015

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N: 118662Q dated: 04/01/2011 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

--END--

Signature 

A7P 2727343IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3024.6
TSMOH: 1484.0
Date: 05/06/2015

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

--END--

Signature 

A7P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3114.1
TSMOH: 1573.5
Date: 08/03/2015

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---


Signature

AP3016498
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3213.1
TSMOH: 1672.5
Date: 10/19/2015

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097J dated 04/01/2011 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---


Signature

AP3016498
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3312.0
TSMOH: 1771.4
Date: 01/27/2016

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N: 118662Q dated: 04/01/2011 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

---END---


Signature

A772727343IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 3411.5
TSMOH 1870.9
Date 04/21/2016

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

—END—


Signature

A7P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1675 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 3511.3
TSMOH 1941.1
Date 07/14/2016

- Removed propeller and sent to Warner Propeller and governor inc for overhaul. Installed propeller Model # 3AF32C512-C S/N 901304 for temporary use.

—END—


Signature

A7P 2727343
Certificate Number


Southwest Aircraft Charter
Maintenance Operations
1675 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 3521.4
TSMOH 0.0
Date 07/25/2016

- Received overhauled propeller from Warner propeller and governor co see 8130-3 # 36590 and installed in the L/H position on Baron 58 S/N TH-1848 Per McCauley installation instructions. Operational and leak check good

—END—


Signature

A7P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 3608.6
TSMOH 87.2
Date 10/11/2016

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

—END—


Signature

A7P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 3689.3
TSMOH 167.9
Date 02/09/2017

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N11862R dated 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance


—END—


Signature

A7P 2727243IA
Certificate Number

21 JUL 2016 TSN Not Reported TSO 0.0
Overhauled, functional tested and
static balanced. Refer to WO # 12171
and 8130-3 # 36590 for details.




Brooke Warner
Warner Propeller & Governor Co., LLC
FAA CRS # W59R659N

Southwest Aircraft Charter
Maintenance Operations
1575 E Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3788.5
TSMOH: 267.1
Date: 05/23/2017

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see propeller S/N 980195 listing for all AD compliance

---END---

Signature 

A4P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3887.8
TSMOH: 366.4
Date: 09/05/2017

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see propeller S/N 980195 listing for all AD compliance

---END---

Signature 

A4P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 3980.7
TSMOH: 459.3
Date: 12/20/2017

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N11862R dated 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance

---END---

Signature 

A4P 2727343IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4072.8
TSMOH: 551.4
Date: 04/15/2018

- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014 and is in airworthy condition. All ADs complied with as of this date see propeller S/N 980195 listing for all AD compliance

---END---

Signature 

A4P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4089.8
TSMOH: 568.4
Date: 05/18/2018

- Removed L/H Propeller assembly P/N: 3AF32C512-C S/N: 980195 due to damaged blade and sent to Ottosen Propeller & accessories for repair. Received repaired propeller assembly P/N: 3AF32C512-C S/N: 980195 and installed in L/H position in reference to placard A-2230-9 and McCauley owner/operator manual ch 61-00-06 dated 08/18/2014. Operational and leak check good

---END---

Signature 

A4P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4168.1
TSMOH: 646.7
Date: 08/15/2018

- This propeller has been inspected in accordance with a **Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014** and is in airworthy condition. All ADs complied with as of this date see propeller S/N 980195 listing for all AD compliance.

---END---


Signature

A1P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4262.0
TSMOH: 740.6
Date: 01/01/2019

- This propeller has been inspected in accordance with Beechcraft **100 hour long / annual inspection** form P/N11862R: dated: 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---


Signature

A1P 2727343 IA
Certificate Number


Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4333.2
TSMOH: 811.8
Date: 04/30/2019

- This propeller has been inspected in accordance with Beechcraft **100 hour long / annual inspection** form P/N11862R: dated: 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---


Signature

A1P 2727343 IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4428.1
TSMOH: 906.7
Date: 08/05/2019

- This propeller has been inspected in accordance with a **Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014** and is in airworthy condition. All ADs complied with as of this date see propeller S/N: 980195 listing for all AD compliance.

---END---


Signature

A1P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail #: N2348Q LT
Aircraft Serial #: TH-1848
Propeller Serial #: 980195
Hour Meter: 4502.1
TSMOH: 980.7
Date: 11/06/2019

- This propeller has been inspected in accordance with a **Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014** and is in airworthy condition. All ADs complied with as of this date see propeller S/N: 980195 listing for all AD compliance.

---END---


Signature

A1P 2727343
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 4593.5
TSMOH 1072.1
Date 03/27/2020

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N11862R dated 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---

Signature

AIP 2727343IA
Certificate Number

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 4689.4
TSMOH 1168.0
Date 01/22/2021

- This propeller has been inspected in accordance with Beechcraft 100 hour long / annual inspection form P/N11862R dated 04/01/2014 and was found to be in airworthy condition. All ADs complied with as of this date see listing for all AD compliance.

---END---

Signature

Certificate Number

AIP 2727343JA

Southwest Aircraft Charter
Maintenance Operations
1575 E. Ryan Road
Chandler, AZ 85286



Aircraft Tail # N2348Q LT
Aircraft Serial # TH-1848
Propeller Serial # 980195
Hour Meter 49.6
TSMOH 1264.1
Date 07/26/2021


- This propeller has been inspected in accordance with a Beechcraft 100-hour short form inspection P/N: 98-39097K dated 04/01/2014 and is in airworthy condition.

---END---

Signature

AIP 2727343
Certificate Number

1575 East Ryan Rd.
Chandler, AZ 85249
Phone: (480) 785-7722
Cell: (480) 296-3305



N Number: 2348Q RH
Hobbs Time: 1689.7
TSMOH: 149.1
Date: 7/27/2011


I certify that this propeller has been inspected in accordance with a 100 hr/annual long form inspection P/N 118662Q and was found to be in airworthy condition.

Chad Thomas
Signature

---END---

APP3417648 DA
Certificate Number

1575 East Ryan Rd.
Chandler, AZ 85249
Phone: (480) 785-7722
Cell: (480) 296-3305



N Number: 2348Q RH
Hobbs Time: 1984.1
TSMOH: 443.5
Date: 6/8/2012

I certify that this propeller has been inspected in accordance with a 100 hr/annual long form inspection P/N 118662Q and was found to be in airworthy condition.

Chad Thomas
Signature

---END---

APP3417648
Certificate Number

REG NO N2348Q RT **CHANDLER AVIATION INC** DATE 04/03/13
MODEL 58 CHANDLER MUNICIPAL WO# 50150
S/N TH1848 CHANDLER, AZ HOBBS 2283.8
PROP M/N 3AF32C512C (480) 732-9118 TACH XXX
PROP S/N 980485 TOTAL SMOH 743.2

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS FACILITY.

SIGNATURE [Signature] AUTH. NO. 2307335 IA

Remove propeller and install new prop shaft o-ring. Perform minor dressing of leading edge. I certify that this propeller has been inspected in accordance with a Hawker Beechcraft Long / Annual Inspection form P/N 118662Q dated April 1/11 and was determined to be in airworthy condition.

END

REG NO N2348Q RT **CHANDLER AVIATION INC** DATE 04/09/13
MODEL 58 CHANDLER MUNICIPAL WO# 50197
S/N TH1848 CHANDLER, AZ HOBBS XXXX
PROP M/N 3AF32C512C (480) 732-9118 TACH XXX
PROP S/N 980485 TOTAL SMOH XXXX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS FACILITY.

SIGNATURE [Signature] AUTH. NO. 565623722 IA

Re oriented prop to be same on both engines. Remove and re-install per service manual. Torque bolts to specs.

END