

# **AIRCRAFT MAINTENANCE RECORDS**

**N** 83003

LH

**PROP**  
**LOG BOOK**




9-24-2019  
Left Prop  
S/N AU-6732  
N83003

Hartzell  
HC-C2YR-2CEUF/FC7666A-2R

Tach 1109.9  
Prop TT 1109.9  
SMOH 508.6

- \* Completed 100hr Inspection IAW Piper PA-44-180T inspection guide.
- \* Serviced hub piston with nitrogen.
- \* Ground run-up completed, ops and leak check good.

I certify that this Propeller has been inspected IAW a 100hr Inspection and found to be in airworthy condition.

  
Zach Boyle – South Dakota State University  
A&P3420723IA

10-26-2020


Left Prop  
S/N AU-6732  
N83003

Hartzell  
HC-C2YR-2CEUF/FC7666A-2R

Tach 1132.4  
Prop TT 1132.4  
SMOH 531.1

- \* Completed 100hr Inspection IAW Piper PA-44-180T inspection guide.
- \* Serviced hub piston with nitrogen.
- \* Ground run-up completed, ops and leak check good.

I certify that this Propeller has been inspected IAW a 100hr Inspection and found to be in airworthy condition.

  
Zach Boyle – South Dakota State University  
A&P3420723IA

4-15-2021

Left Prop  
S/N AU-6732  
N83003

Hartzell  
HC-C2YR-2CEUF/FC7666A-2R

Tach 1235.9  
Prop TT 1235.9  
SMOH 635.6

- \* Completed 100hr Inspection IAW Piper PA-44-180T inspection guide.
- \* Serviced hub piston with nitrogen.
- \* Ground run-up completed, ops and leak check good.

I certify that this Propeller has been inspected IAW a 100hr Inspection and found to be in airworthy condition.

  
Zach Boyle – South Dakota State University  
A&P3420723IA

**SUB-TOTAL** THIS PAGE

**TOTAL** - CARRY FORWARD TO NEXT PAGE