N4323Q



The Standard

M4323Q

OPENED 9-5-14



ASA-SP-L

The Standard Propeller Log SP-L

© 1994-2000 Aviation Supplies & Academics, Inc.

ISBN 1-56027-418-2 978-1-56027-418-6

ASA-SP-L

All rights reserved.

Reproduction or use, without expressed permission, in any manner, is prohibited.

in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE

Newcastle, WA 98059-3153 Website: www.asa2fly.com Email: asa@asa2fly.com

Printed in the United States of America





Type FIXED PI+CH
Type FIXED PITCH
Serial # 17260223

□ HUB & BL	ADE INSPECT	IONS, REPAIRS	AND ALTERATIONS						IIIIn A Ni		AND ALTERATIONS
Next Insi Due: Ta	ertify that this prop worthy	TTProp 2115.9 hour inspection in peller has been ins	EPIX AVIATION, LLC 2802 Airport Drive, Suite 1 Chesapeake, Virginia 23323 157-421-4973 EpiXAviation.com accordance with FAR 43 appd D. pected in accordance with a 100 h	N4323Q wo 9926 Date 9/5/14 Repainted face. Checked track. hour inspection was found to be		Nex Due Complie Cortify airworth	that this propel hy.	2802 Air Chessape 7 7 Ep	in accordance with a 100	N4323Q wo 13571 Date 9/10/15 Repainted face. Checked track. hour inspection was found to be	
Year:					10	Year:	in Service	Description			<i>J.</i>
Next Inspection Due:	Time Since Overhaul	1				Next Inspection Due:	Time Since Overhaul				
		Mech. Cert. # or Re	epair Station #					Mech. Cert. # or Repai	ir Station #		

Year: Date: Next Inspection Due:	Total Tim in Service Time Sine Overhaul	CONRAD AERO 1200 Flight Line Dr. Three Rivers, MI 49093 Phone: (269) 279-6000 Propeller Log Entry	Year:	Total T in Serv	CONRAD AERO 1200 Flight Line Dr. Three Rivers, MI 49093 Phone: (269) 279-6000 Propeller Log Entry N4323Q
Year:	Total Tim in Service Time Sin- Overhaul	Inspected propeller & spinner, dressed blades as needed, painted prop face, I certify that this propeller has been inspected in accordance with an annual	Next Inspection	Total T Ren	ne: 9-14-2017 Tach Time: 323.4 Total Time: 2301.4 moved spinner and inspected spinner, spinner bulkhead, hub, and blades, istalled spinner. I certify that this propeller has been inspected in accordance in an annual inspection, & found to be in airworthy condition at this time A&P 3142013 IA
Year:	Total Time in Service	Description	Year:	Total Time in Service	Description
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #	Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #

ADE INS	CONRAD AERO			HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS [
Total Tim in Service Time Sine Overhaul	Date: 9-11-18 Tach Time: 371.0 Total Time: 2349.0	Total Time in Service Time Since Overhaul	CONRAD AERO 1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093 Phone: (269) 279-6000 Aircraft log entry	
Total Tim in Service Time Sinc Overhaul	I certify that this propeller has been inspected in accordance with an annual inspection, & found to be in airworthy condition at this time A&P 3657290 IA	Year:	Total Time in Service Time Since Overhaul	N4323Q Date: 10-2-2019 Tach Time: 400.1 Total Time: 2378.1 Performed annual inspection of propeller by removing spinner, inspection of
Total Time	Mech. Cert. # or Repair Station #		Total Time	spinner, spinner back plate, blades and bolts. Dressed small nicks in blades, and painted the backs flat black. Reinstalled spinner. I certify this propeller was inspected in accordance with an annual inspection and found to be in airworthy
in Service	Description	Year:	in Service	condition at this time.
Time Since Overhaul	Mech. Cert. # or Repair Station #	Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #
	Total Tim in Service Time Sinc Overhaul Total Tim in Service Time Sinc Overhaul	Total Tim in Service Total Time Sind Overhaul Total Time Since Overhaul Time Since Overhaul	Time Sinc Overhaul Total Time Sinc Overhaul Time Sinc Overhaul Total Time Sinc Overhaul Tota	Total Time in Service Time Since Overhaul Total Time in Service Total Time in Service

☐ HUB & BLA	DE INSPECT	TIONS, REPAIRS AND ALTERATIONS			
Year: 2020 Date: 9/21	Total Time in Service TAC. 426.0	in accordance with an annual inspected	Year:	Total Time in Service	CONRAD AERO 1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093 Phone: (269) 279-6000 Aircraft log entry
Next Inspection Due:	Time Since Overhaul 2464.0	Mech. Cert. # or Repair Station # Coned All 2073766 TA	Next Inspection Due:	Time Since Overhaul	N4323Q
Year:	Total Time in Service	Description	Year:	Total Time in Service	Date: 9-16-2021 Tach Time: 450.7 Total Time: 2428.7 Performed annual inspection of propeller by removing spinner, inspection of spinner, spinner back plate, blades and bolts. Dressed small nicks in blades, and painted the backs flat black. Peinterlied and painted the backs flat black.
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #	Next Inspection Due:	Time Since Overhaul	painted the backs flat black. Reinstalled spinner. I certify this propeller was inspected in accordance with an annual inspection and found to be in airworthy condition at this time.
Year:	Total Time in Service	Description	Year:	Total Time in Service	A&P 3142013 IA
Next Inspection Due:	Time Since Overhaul		Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #			Mech. Cert. # or Repair Station #

☐ HUB & BLA	DE INSPECTIONS, REPAIRS AND ALTERATIONS			CONRAD AERO	AND ALTERATIONS
Year:	Total Time	Year:	Ti	1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093 Phone: (269) 279-6000	
Date:		Date:		Aircraft log entry	
Next Inspection Due:	CONRAD AERO 1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093 Phone: (269) 279-6000	Next Inspection Due:	Date: 9-1	N4323Q 9-2023 Tach Time: 480.3 Total Time: 2458.3	
	Prop log entry	1	Performed	d annual inspection of propeller by removing spinner, inspection of spinner back plate, blades and bolts. Dressed blades as required, and	
Year:	Tr N4323Q	Year:	painted the	he backs flat black. Reinstalled spinner. I certify this propeller was	
Date:	Ti Date: 10-05-2022 Tach Time: 465.0 Total Time: 2443.0	Date: Next Inspection	condition	Jared Eichorn A&P 4099632 IA	
Next Inspection Due:	On Performed annual inspection of propeller by removing spinner, inspection of Performed annual inspection of propeller by removing spinner, inspection of propeller by removing spinner.	Due:	d-commun.	Mech. Cert. # or Repair Station #	
Year:	spinner, spinner back plate, blades and boits. Diesset the blades are painted the backs flat black. Reinstalled spinner. I certify this propeller was inspected in accordance with an annual inspection and found to be in airworthy condition at this time.	Year:	Total Time in Service	Description	
Date:	CONDITION At this time.	Date:			
Next Inspection	Til One	Next Inspection Due:	Time Since Overhaul		
	A&P 3142013 IA			Mech. Cert. # or Repair Station #	

					AIRWORTHINESS DIRECTIVES
AIRWOR		CONRAD AERO 1200 Flight Line Dr. Unit 516 Three Rivers, MI 49093	Year:	Total Hours	Complied by the following:
Year:		Phone: (269) 279-8000	Date:		
Date:		Prop log Entry N4323Q	A.D. #		
A.D. #	Date	9-06-2024 Tach Time: 498.9 Total Time: 2476.9 ual inspection of propeller by removing spinner, inspection of spinner, spinner back the despeed blades as required. Reinstalled spinner. I certify this propeller was			
	Performed anni plate, blades a	and inspection of propeller by removing spinner, inspection of spinner, aparticle and inspection of propeller by removing spinner, inspection of spinner, aparticle and bolts; dressed blades as required. Reinstalled spinner. I certify this propeller was cordance with an annual inspection and found to be in airworthy condition at this time.	Next Inspection Due:		
Next Inspection	inspected in accordance with all almutations are the second and the second accordance with all almutations are the second accordance with a second a			Mech. Cert. #	or Repair Station #
			Year:	Total Hours	Complied by the following:
Year:	Total Hours	Complied by the following:	Date:		
Date:			A.D. #		
A.D. #					
			Next Inspection Due:		
Next Inspection	n			Mech. Cert. #	or Repair Station #
	Mach Cort #	or Repair Station #			