

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J34F-121F

PROPELLER S/N FP4574B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-J34F-1RF

High/Feather _____

Propeller S/N FP4574B

Start Lock _____

Blade Design F76930FB

Low _____

Blade S/N's

Reverse _____

No. 1 K37015

No. 2 K37018

Aircraft Manufacturer Cirrus Design

No. 3 K37025

Aircraft Model SR-22

No. 4 _____

S/N 1931

No. 5 _____

Registration _____

No. 6 _____

Spinner Assembly Part No. _____

[illegible]

PROP MODEL:
PDC-J3YF-1RF
PROP S/N: FP4574B
REG. NO: N363SD
WORK ORDER:
26956-03-2007



Commander Aero, Inc.

Repair Station No. GA5R-876M
10570 Springboro Pike
Miamisburg, Ohio 45342 USA
Phone: 888-881-5580

DATE: 4/10/2007
A/C TSN: 178.8
PROP TT: 178.8
HOBBS: 178.8

Prop Entries

(3) Complied with 100 Hour Propeller Inspection.

I certify that this propeller was inspected in accordance with a 100 hour inspection and found to be airworthy. The aircraft and/or component(s) on N363SD was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 26956-03-2007, Dated 4/10/2007.

DATE: 4/10/2007

SIGNED:

Kromer, Gary
Certified Repair Station No. GA5R-876M

Work Order: 26956-03-2007

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF/F7693DFB
PROP S/N: FP4574B
REG. NO: N541WP
WORK ORDER: 23535



American Aircraft Maintenance, Inc.

Repair Station No. Z5SR421Y
19711-B Campus Drive
Santa Ana, CA 92707
Phone: (949) 852-8420

DATE: 3/28/2008
A/C TSN: 281.8
PROP TT: 281.8
HOBBS: 281.8

Prop Entries

Complied with an Annual/100 HR inspection as per Manufacturer's Service and/or Maintenance Manual. All Airworthiness Directives are in compliance at this time through bi-weekly issue 2008-06.... Dressed leading edge and painted propeller face.



THIS AIRCRAFT OR COMPONENT HAS BEEN REPAIRED AND/OR INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CFR, IT IS FOUND AIRWORTHY AND IS APPROVED RETURN TO SERVICE.



DATE: 3/28/2008

SIGNED:

Work Order: 23535

Printed by EBis 3 (datcomedia.com)

Date	Prop TSN	Advanced Aircraft Services	DATE: 7/2/2012 A/C TSN: 497.7 PROP TT: 497.7 FLIGHTTIME:	Directives, and Inspections.
		PROP MODEL: PHC-J3YF-1RF PROP S/N: FP4574B REG. NO. N541WP WORK ORDER: 2307-06-2012 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179		
		Prop Entries Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2012-12. Run up and ops check good. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
		DATE: 7/2/2012 SIGNED:  Richard A. Barnhart II, IA: 3124994AP Work Order: 2307-06-2012 Printed by EBis 3 (datcomedia.com)		
		PROP MODEL: PHC-J3YF-1RF PROP S/N: FP4574B REG. NO. N541WP WORK ORDER: 2985-07-2013 ADVANCED Advanced Lancaster LP 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179	DATE: 8/8/2013 A/C TSN: 551.3 PROP TT: 551.3 FLIGHTTIME:	
		Prop Entries Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2013-15. Ops check good. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
		DATE: 8/8/2013 SIGNED:  Joel A. Glover, IA: 2849196AP Work Order: 2985-07-2013 Printed by EBis 3 (datcomedia.com)		

		PROP MODEL: PHC-J3YF-1RF PROP S/N: FP4574B REG. NO. N541WP WORK ORDER: 3602-10-2014 ADVANCED Advanced Lancaster LP 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179	DATE: 10/14/2014 A/C TSN: 597.7 PROP TT: 597.7 FLIGHTTIME:	
		Prop Entries Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2014-20. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
		DATE: 10/14/2014 SIGNED:  Milan Jovanovic, IA: 3164111AP Work Order: 3602-10-2014 Printed by EBis 3 (datcomedia.com)		
		PROP MODEL: PHC-J3YF-1RF PROP S/N: FP4574B REG. NO. N541WP WORK ORDER: 4240-11-2015 ADVANCED Advanced Lancaster LP 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179	DATE: 11/20/2015 A/C TSN: 663.1 PROP TT: 663.1 HOBBS:	
		Prop Entries Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2015-23. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
		DATE: 11/20/2015 SIGNED:  Richard A. Barnhart II, IA: 3124994AP Work Order: 4240-11-2015 Printed by EBis 3 (datcomedia.com)		

[illegible]