

CC11-00408





Propeller Record	General Information	
Propeller Manufacture Model <u>SOX5</u> Hub Series # Date of Manufacture	NLE DAIE	Blade # 2 DESIGNED \$ /1. Ho Compt ASTM F25
Aircraft Installed On:	Make/Model <u>STOL</u> <u>Aircraft</u> , LLC. <u>model</u> : <u>CCX-1865-0010</u> <u>5/N</u> <u>CCX-1865-0010</u>	CATTOPRO 209-754-3553 or c Glass/2XCarbon Compo Diameter: 80" Pitch: 50 Engn:CC-340 170+ HP Red Line RPM Torque: 35 ft lbs. 7" Cri Manufacture Date: D

ANUFACTURED PELLERS attoprops.com osite 2-B #11154623

^a NLE Carbon Cub Design RPM 2700 max. 3100 ush Plate Required December 2015

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

21

Year: Date:	Total Time in Service	Propeller serial number 11154623 was removed off serial number - CCX-1865-0010.	
Next Inspection Due:	Time Since Overhaul	Concession 199 3367272 2-25-16 (Date)	
 Year:	Total Time in Service	Propeller serial number 11154623 was	
Date:		installed on serial number CC11-00408.	
Next Inspection Due:	Time Since Overhaul	A&P (Date)	
Year:	Total Time in Service	Reg. Number: N155CC CC11-00408	
Date:		Dynamically Balanced Propeller ACES Systems.	
Next Inspection Due:	Time Since Overhaul	Weight: <u>0</u> Angle: <u>47</u> IPS: .03	
		- A&P James Bean APP 3367262 (Date) 7-8-16-	

				'IONS 🗆
		LEMAC AVIATION, LLC	SERVICE #:	1267
Year:	adjerented for anti-	- 4550 EAST MCKELLIPS ROAD, SUITE 10	1 DATE:	7/13/16
Date:		MESA, ARIZONA 85215	REGISTRATION:	N155CC
Next Insp Due:	MAKE: CUB CRAFTERS	PROP: HARTZELL CATO HOBBS: 21.7	TSMOH:	
Due	MODEL: CC11-160	MODEL: PHC-JOYF-IN 90 150 JLE FLIGHT: 18.9	TOP END:	N/A
1	SERIAL: CC11-00408	SERIAL: FP7654B_1154623 TOTAL: 18.9		
		PROPELLER LOG		
Year:			a h halte	
Date:	 Removed propeller, sent to C. 	ATO for repaint. Installed after repainting, torqued and safetied att	cach bons.	
Next Insp	MATTHEW EVJEN 3168041 A&P	IA		
Due:				
	ircraft Maintenance, LLC	8/9/2017 N155		
Daniel W Sta 12405 SW Ri			CC11-00408 DCB007	
Hillsboro, OF		Catto		
	oaksaircraft.com			
Tach: 153.2 &	& PTSNEW: 153.2			
	Other condition increation on this n	roneller		
-	00hr condition inspection on this p			
l certify that and was foun	this propeller has been inspected on the design of the des	n 8/9/2017 IAW the manufacturer's maintenance and institution.	spection procedures per a	100hr condition inspection

Twin Oaks Aircraft Maintenance, LLC Daniel W Stark 12405 SW River Road Hillsboro, OR. 97123	9/7/2018 Cub Crafters CC11-160 Titan OX-340CC-B3J3N4 Catto 80 X 50 NLE	N155CC S/N: CC11-00408 S/N: DCB007 S/N: 11154623
danny@twinoaksaircraft.com Tech: 170.1 & PTSNEW: 170.1 Completed a 100hr condition inspection on this propeller.	1	
certify that this propeller has been inspected on 9/7/2018 IAW t and was found to be in condition for safe operation.	he manufacturer's maintenance Daniel W Stark 2708377 1A	
Twin Oaks Aircraft Maintenance, LLC Daniel W Stark	10/9/2019 Cub Crathere CC11 1/0	N155CC
12405 SW River Road	Cub Crafters CC11-160 Titan OX-340CC-B3J3N4	S/N: CC11-00408 S/N: DCB007
Hillsboro, OR. 97123 danny@twinoaksaircraft.com	Catto 80 X 50 NLE	S/N: 11154623
Tach: 202.5 & PTSNEW: 202.5		
Completed a 100hr condition inspection on this propeller.		
I certify that this propeller has been inspected on 10/9/2019 IAW and was found to be in condition for safe operation.	the manufacturer's maintenance Daniel W Stark 2708377 IA	and inspection procedures per a 100hr condition inspection
Mech. Cert. # or Repair Sta	tion #	

Twin Oaks Aircraft Maintenance, LLC	11/9/2020	N155CC
Daniel W Stark	Cub Crafters CC11-160	S/N: CC11-00408
12405 SW River Road	Titan OX-340CC-B3J3N4	S/N: DCB007
Hillsboro, OR. 97123	Catto 80 X 50 NLE	S/N: 11154623
danny@twinoaksaircraft.com		
Tach: 216.8 & PTSNEW: 216.8		
Completed a 100hr condition inspection on this propeller.		
I certify that this propeller has been inspected on 11/9/2020 IAW and was found to be in condition for safe operation.		
	Daniel W Stark 2708377 Ad	&P
	11/15/2021	, NUMEROO
Twin Oaks Aircraft Maintenance, LLC	11/17/2021	N155CC
Daniel W Stark	Cub Crafters CC11-160	S/N: CC11-00408
12405 SW River Road	Titan OX-340CC-B3J3N4	S/N: DCB007
Hillsboro, OR. 97123	Catto 80 X 50 NLE	S/N: 11154623
danny@twinoaksaircraft.com		
Tach: 245.8 & PTSNEW: 245.8		
Completed a 100hr condition inspection on this propeller.		
I certify that this propeller has been inspected on 11/17/2021 1/ and was found to be in condition for safe operation.	AW the manufacturer's maintena Danie/W Stark 2708377 A	nce and inspection procedures per a 100hr condition inspection
Mech. Cert. # or Repa	ir Station #	

Twin Oaks Aircraft Maintenance, LLC	11/15/2022	N155CC
Daniel W Stark	Cub Crafters CC11-160	S/N: CC11-00408
12405 SW River Road	Titan OX-340CC-B3J3N4	S/N: DCB007
Hillsboro, OR. 97123	Catto 80 X 50 NLE	S/N: 11154623
danny@twinoaksaircraft.com		
Tach: 302.5 & PTSNEW: 302.5		
Completed a 100hr condition inspection on this propeller.		
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	I the manufacturer's maintenan	ce and inspection procedures per a 100hr condition inspection
I certify that this propeller has been inspected on 11/15/2022 IAV	v the manufacturer's maintenan	ce and inspection procedures per a room condition inspection
and was found to be in condition for safe operation.	Daniel W Stark 2708377 Ad	2 D
	Dallow Stark 2706577 Ac	
Twin Oaks Aircraft Maintenance, LLC	9/29/2023	N155CC
Daniel W Stark	Cub Crafters CC11-160	S/N: CC11-00408
12405 SW River Road	Titan OX-340CC-B3J3N4	S/N: DCB007
Hillsboro, OR. 97123	Catto 80 X 50 NLE	S/N: 11154623
danny@twinoaksaircraft.com		
Tach: 306.6 & ETSNEW: 306.6		-
Completed a 100hr condition inspection on this engine, service	and lube as needed. Check com	pression: $\#1 = 77/80 \ \#2 = 78/80 \ \#3 = 76/80 \ \#4 = 78/80$.
	1	
I certify that this engine has been inspected on 9/29/2023 IAW	the manufacturer's maintenance	e and inspection procedures per a 100hr condition inspection and
was found to be in condition for safe operation.		
	Daniel W Stark 2708377	A&P
		•
Mech. Cert. # or Repair S	tation #	

	Twin Oaks Aircraft M	aintenance, LLC	9/5/2024	N155CC
	Daniel W Stark		Cub Crafters CC11-160	S/N: CC11-00408
	12405 SW River Road	ł	Titan OX-340CC-B3J3N4	S/N: DCB007
	Hillshoro OR. 97123		Catto 80 X 50 NLE	S/N: 11154623
	danny@twinoaksaircr	aft.com		
	Tach: 308.7 & PTSNE	EW: 308.7		
	Completed a 100hr co			
ondition inspection	I certify that this prop	eller has been ins	pected on 9/5/2024 IAW the manufacturer's maintenanc	e and inspection proc
	and was found to be in	n condition for sa		0.0
			Daniel W Stark 2708377 A	λ&Ρ
	Year:	in Service		and the second s
	Date:			
	Next Inspection Due:	Time Since Overhaul		
			Mech. Cert. # or Repair Station #	
4= 78/80.	Year:	Total Time in Service	Description	
dition inspection an	d			
	Date:			
	Next Inspection Due:	Time Since Overhaul		
			Mech. Cert. # or Repair Station #	

ocedures per a 100hr condition inspection

