

AIRCRAFT MAINTENANCE RECORDS

N 5813F

PROP LOG BOOK



AIRCRAFT MAINTENANCE RECORDS

Owner _____


Aircraft Registration **N** 5813F

Manufacturer McCawley

Model B2D34214-B 90DHB-16E


Serial No. 931922 1E6093
2E6096

Position Sc1




AIRCRAFT MAINTENANCE RECORD

Page No. _____

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
 Western Aircraft Propeller Service 42313 SE Oral Hull Road #2 Sandy, OR 97055 Repair Station FQ6R544N WO#28833 McCauley Propeller B2D34C214-B/90DHB-16E Hub Serial – 931922 Blade Serials – 1.EB093 2.EB096 Overhaul and Recondition Propeller in accordance with MPC200 Repairman  DATE <u>03/5/24</u> FAA Repair Station FQ6R544N TSO- 0000 TT - component identified above was inspected or repaired in accordance with Current FAA Regulations and found airworthy for return to service. Pertinent Details are on file at this agency under work order number.		


Reliant Aircraft Services LLC 14209 SW Tewkesbury Dr. Portland, OR 97224 503-799-9834		Logbook Insert Propeller
Model: Mooney M20 J	Airframe	Date: 03/12/2024
Reg #: N5813F	SERIAL #24-1563	Tach time 3824.1 Hobbs
PROP PTT 3824.1 TSPO 00	PROP MODEL # B2D34C214	PROP SERIAL # 931922

At the request of the owner/operator, installed propeller after overhaul. (See log entry and 8130 tracking form (#28833) from Western Aircraft Propeller Service.) Ground ran engine and inspected for leaks. No discrepancies noted. This propeller and airframe are returned to service in an airworthy condition with respect to the work performed this date.

DeLynn R Elrod  A&P 3508347 IA

Reliant Aircraft Services LLC 14209 SW Tewkesbury Dr. Portland, OR 97224 503-799-9834		Logbook Insert Propeller
Model: Mooney M20 J	Airframe	Date: 05/02/2024
Reg #: N5813F	SERIAL #24-1563	Tach time 3834.1 Hobbs
PROP PTT 3834.1 TSPO 10	PROP MODEL # B2D34C214	PROP SERIAL # 931922

Completed a propeller inspection IAW Mooney aircraft annual inspection guide form # 0100(B) dated Aug 2018 and FAR 43 App. D. Inspected spinner and backplate. Inspected propeller installation. No defects noted. Dressed leading edge and cleaned back side of blades. I certify this propeller was inspected IAW an annual inspection and was found to be in an airworthy condition as of this date.

DeLynn R Elrod  A&P 3508347 IA

SUB-TOTAL THIS PAGE

TOTAL - CARRY FORWARD TO NEXT PAGE

Page No.

PROP SERIAL # 931922

DeLynn R Elrod

A&P 3508347 1A

TOTAL - CARRY FORWARD TO NEXT PAGE

