

Left



The Standard

PROPELLER LOG

ANCA 6724

Year: _____ N1618T June 10, 2021 Hobbs: 1194.3 SPOH: 743.3
Date: _____
Next Inspection Due: _____
1. Dressed small nicks from blades.
I certify that this propeller has been inspected in accordance with an Annual Inspection and found to be in an airworthy condition. Airworthiness Directives are listed in the AD Compliance Report.

Year: _____
Date: _____
Next inspection _____

Scott Gerken
3211721 A&P/IA

Mech. Cert. # or Repair Station #

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____