

AIRCRAFT MAINTENANCE RECORDS

N 1618+

PROP LOG BOOK



AIRCRAFT MAINTENANCE RECORDS

Owner _____


Aircraft Registration **N** _____

Manufacturer _____


Model _____

Serial No. _____

Position _____



AIRCRAFT MAINTENANCE RECORD Page No. _____

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK	
CARRIED FORWARD →			
 PROPELLER 1525 NW 56TH STREET, FT LAUDERDALE, FL 33309 (954)667-2527			
W.O# 1003 MAKE: MCCAULEY	AIRCRAFT: N1618T MODEL : 3AF32C93-N	HOBBS 1232.3 S/N 731444	DATE: 06/05/2022 SPOH: 781.3
PERFORMED THE FOLLOWING INSPECTIONS: 100 HR INSPECTION IAW MCCAULEY SERVICE MANUAL AS A GUIDE & PART 43 APPENDIX D - DRESSED BLADES AS NEEDED. - AD'S CHECKED AT THIS DATE. SEE COMPLIANCE LIST			
The Propeller identified above was repaired and/or inspected in accordance with current regulations of the Federal Aviation Administration and has been determined to be in an Airworthy condition. Pertinent details are on file at this repair shop under WO: 1003			
 Eduardo Alejandro Perez Gonzalez / A&P 4232749 IA			
 PROPELLER LH 17700 SW 107TH AVE APT 203 MIAMI FL 33157 (954)667-2527			
W.O# 1113 MAKE: MCCAULEY	AIRCRAFT: N1618T MODEL : 3AF32C93-N	HOBBS 1256.3 S/N 731444	DATE: 07/22/2023 SPOH: 805.3
PERFORMED THE FOLLOWING INSPECTIONS: 100 HR INSPECTION IAW MCCAULEY SERVICE MANUAL AS A GUIDE & PART 43 APPENDIX D - DRESSED BLADES AS NEEDED. - AD'S CHECKED AT THIS DATE. SEE COMPLIANCE LIST			
I Certify that this Propeller has been inspected in accordance with a 100 Hr. inspection and was determined to be in Airworthy Condition			
 Jesus Perez A&P 4519731			
 PROPELLER LH 17700 SW 107TH AVE APT 203 MIAMI FL 33157 (954)667-2527			
W.O# 1197 MAKE: MCCAULEY	AIRCRAFT: N1618T MODEL : 3AF32C93-N	HOBBS: 1266.2 S/N 731444	DATE: 10/30/2024 SPOH: 815.2
PERFORMED THE FOLLOWING INSPECTIONS: 100 HR INSPECTION IAW MCCAULEY SERVICE MANUAL AS A GUIDE & PART 43 APPENDIX D - DRESSED BLADES AS NEEDED. - AD'S CHECKED AT THIS DATE. SEE COMPLIANCE LIST			
I Certify that this Propeller has been inspected in accordance with a 100 Hr. inspection and was determined to be in Airworthy Condition			
 Jesus Perez A&P 4519731			